1985475

# REMEDIAL ACTION AND OPERATIONS & MAINTENANCE STATUS REPORT JULY THROUGH DECEMBER 2021 LOWRY LANDFILL SUPERFUND SITE

**Prepared for**:

**CITY AND COUNTY OF DENVER**
**CHEMICAL WASTE MANAGEMENT, INC.**
**WASTE MANAGEMENT OF COLORADO, INC.**

**MARCH 31, 2022**

**PREPARED BY:**

**PARSONS**
**1776 LINCOLN ST., SUITE 600**
**DENVER, COLORADO 80203**
**(303) 831-8100**

**REVIEWED AND APPROVED BY:**

Lead Author: _____ Date: 3/28/22

Program Manager: _____ Date: 3/28/22

QA Manager: _____ Date: 3/28/22

# TABLE OF CONTENTS

**Page**

TABLE OF CONTENTS ..... I

LIST OF TABLES ..... III

LIST OF FIGURES ..... IV

LIST OF APPENDICES ..... V

LIST OF ACRONYMS AND ABBREVIATIONS ..... VIII

EXECUTIVE SUMMARY ..... 1

**1.0 INTRODUCTION ..... 1**

1.1 Purpose and Scope ..... 1
1.2 General Site Description ..... 1
1.3 Report Organization ..... 2

**2.0 WATER TREATMENT PLANT ..... 3**

2.1 Operations and Maintenance ..... 3
- 2.1.1 NBBW System ..... 4
- 2.1.2 North End Extraction System ..... 4
- 2.1.3 Liquid Volumes and Flow Rates ..... 4
- 2.1.4 pH System ..... 5
- 2.1.5 Removal of Volatile Organic Compounds ..... 5
- 2.1.6 Sludge Production ..... 7
- 2.1.7 Maintenance and Calibration ..... 7

2.2 Monitoring ..... 8
- 2.2.1 Summary of Activities ..... 8
- 2.2.5 Monitoring Results ..... 10

2.3 Treatability ..... 12

**3.0 WASTE MANAGEMENT ..... 13**

3.1 Drill Cuttings and Well Abandonment Wastes ..... 13
3.2 NTES Recovery Wastes ..... 13
3.3 Treatment Plant Wastes ..... 13
3.4 Decontamination Pad Wastes ..... 13
3.5 Site Monitoring Waste ..... 13

**4.0 GROUNDWATER MONITORING ..... 14**

4.1 Well Inspections, Maintenance, Installation and Development ..... 14
- 4.1.1 Well Inspections and Maintenance ..... 14
- 4.1.2 Well Installation and Development ..... 15

4.2 Sitewide Groundwater Elevations ..... 15

4.2.1 Alluvium/Weathered Dawson Formation Groundwater Elevations ..... 16
4.2.2 Unweathered Dawson Formation Groundwater Elevations ..... 17
4.2.3 Upper Denver Groundwater Elevations ..... 17
4.2.4 Lignite Layer Groundwater Elevations ..... 18
4.2.5 Vertical Hydraulic Gradients ..... 18
4.3 Groundwater Sampling ..... 19
4.3.1 Laboratory Analyses ..... 19
4.3.2 Data Validation ..... 20
4.4 Compliance Evaluation ..... 20
4.4.1 Procedures Used to Assess Compliance ..... 20
4.4.2 Results of Compliance Evaluations ..... 21
4.5 Effectiveness Evaluation ..... 29
4.5.1 Perimeter Slurry Wall ..... 30
4.5.2 North Toe Extraction System ..... 32
4.5.3 North Boundary Barrier Wall ..... 32
4.5.4 MW38 Channel ..... 36
4.5.5 Vertical Migration Assessment in Deep Groundwater (OU6) ..... 38
4.6 Voluntary Actions – MW38 and Perimeter Systems ..... 40
4.6.1 MW38 Source Control ..... 41
4.6.2 PM-11 ..... 42
4.6.3 MW51-WD ..... 42
4.6.4 PM-15 ..... 43
4.7 NTES Area NAPL Skimming ..... 43
4.8 North End Response Actions and Investigations ..... 44
4.8.1 North End Monitoring Results ..... 44
4.8.2 Groundwater Extraction in the North End, NBBW and GTEP Area ..... 45
4.8.3 Progress from Response Actions and Investigations ..... 45
4.9 GTEP Area Response Actions ..... 49

**5.0 LANDFILL GAS REMEDY ..... 52**

5.1 LFG Extraction, Collection, and Treatment System Operations 52
5.1.1 Extraction Wells and Collection System ..... 52
5.1.2 GTEP and Blower/Flare Stations ..... 54
5.2 LFG Extraction, Collection, and Treatment System Monitoring ..... 56
5.2.1 Flare Sampling ..... 56
5.2.2 GTEP Inlet Sampling ..... 56
5.2.3 GTEP Outlet Sampling ..... 56
5.2.4 POC Probe Sampling ..... 56

**6.0 STORMWATER ..... 57**

6.1 Surface Water Removal Action ..... 57
6.2 Stormwater Monitoring ..... 57
6.2.1 Sampling ..... 57
6.2.2 Stormwater Discharge Rate ..... 57

**7.0 COVER MONITORING ..... 58**

7.1 Landfill Cover ..... 58
7.1.1 Site and Landfill Cover Inspection ..... 58
7.1.2 Landfill Cover Maintenance Activities ..... 58
7.2 Buffer Zones ..... 58
7.2.1 Buffer Zone Inspections ..... 58
7.2.2 Buffer Zone Maintenance Activities ..... 59

**8.0 REMEDIAL ACTION ..... 60**

**9.0 PROBLEMS ENCOUNTERED, RECOMMENDATIONS, AND MASTER SCHEDULE ..... 61**

9.1 Problems Encountered ..... 61
9.2 Recommendations ..... 63
9.2.1 Recommendations for Slurry Wall Areas ..... 63
9.2.2 Recommendations for NTES, NBBW, and MW38 Areas 63
9.2.3 Recommendations for Off-Site North End Response Actions ..... 63
9.2.4 Recommendations for Sitewide Monitoring Plan – Compliance Monitoring ..... 63
9.3 Schedule of Planned Activities ..... 66

**10.0 REFERENCES ..... 67**

## LIST OF TABLES

**No.** **Title**

2.1 Water Treatment Plant Sampling Schedule
4.1 Summary of Drilling Activities Completed
4.2 Water Level Elevations
4.3 Summary of Vertical Hydraulic Gradient Calculations
4.4 Groundwater Sampling Activities
4.5 Summary of Detected Constituents
4.6 Summary of Compliance Monitoring Evaluations
4.7 Summary of Slurry Wall Gradient Calculations
4.8 North End Monitoring – Nitrate and 1,4-Dioxane (New Data Only)
4.9 NBBW & North End Extraction Systems – Volume and Mass Removed
4.10 Summary of GTEP Area Analytical Results Since 2010 VOCs and Nitrate

# LIST OF FIGURES


| No. | Title |
|---|---|
| 4.1 | Sitewide Potentiometric Surface – Alluvium/Weathered Dawson July 2021 |
| 4.2 | Sitewide Potentiometric Surface – Alluvium/Weathered Dawson October 2021 |
| 4.3 | Sitewide Potentiometric Surface – Unweathered Dawson July 2021 |
| 4.4 | Sitewide Potentiometric Surface – Unweathered Dawson October 2021 |
| 4.5 | Sitewide Potentiometric Levels – Upper Denver Formation July 2021 |
| 4.6 | Sitewide Potentiometric Levels – Upper Denver Formation October 2021 |
| 4.7 | Sitewide Potentiometric Levels – Lignite Layer July 2021 |
| 4.8 | Sitewide Potentiometric Levels – Lignite Layer October 2021 |
| 4.9 | Groundwater Sampling Locations – 2nd Half 2021 |
| 4.10 | Groundwater North End Sampling Locations – 2nd Half 2021 |
| 4.11 | Groundwater Compliance with Performance Standards |
| 4.12 | Perimeter Slurry Wall Well Pair Hydrographs |
| 4.13 | NTES Trench Water Levels and Pumping Rates |
| 4.14 | North Toe Extraction System Area Potentiometric Surface – Alluvium/Weathered Dawson July 2021 |
| 4.15 | North Toe Extraction System Area Potentiometric Surface – Alluvium/Weathered Dawson October 2021 |
| 4.16 | NBBW Area Weathered Dawson Potentiometric Surface – July 2021 |
| 4.17 | NBBW Area Weathered Dawson Potentiometric Surface – October 2021 |
| 4.18 | B-326-WD and MW113-EW-1 Water Elevations and Molybdenum Concentrations |
| 4.19 | MW113 Area - Water Elevations and MW113-EW-1 and NBBW-IW-3 Extraction Rate |
| 4.20 | 1,4-Dioxane Concentrations – B-326 / MW113 Area |
| 4.21 | 1,4-Dioxane Concentrations – B-321 (Extraction Well) / B-313 (Compliance Well) |
| 4.22 | NBBW Area Potentiometric Surface – Unweathered Dawson – July 2021 |
| 4.23 | NBBW Area Potentiometric Surface – Unweathered Dawson – October 2021 |
| 4.24 | MW38 Area Weathered Dawson Potentiometric Surface – July 2021 |
| 4.25 | MW38 Area Weathered Dawson Potentiometric Surface – October 2021 |
| 4.26 | B-326-WD and B-326-UD Water Elevation and NBBW-IW-3, MW113-EW-1 and MW133-UD Extraction Rate |
| 4.27 | PM-15 Area Potentiometric Surface – Weathered Dawson – July 2021 |
| 4.28 | PM-15 Area Potentiometric Surface – Weathered Dawson – October 2021 |
| 4.29 | Section 31 Weathered Dawson Potentiometric Surface – July 2021 |
| 4.30 | Section 31 Weathered Dawson Potentiometric Surface – October 2021 |
| 4.31 | Sections 19 and 30 Weathered Dawson/Weathered Upper Denver Potentiometric Surface – July 2021 |
| 4.32 | Section 31 1,4-Dioxane Results – Third Quarter 2021 |
| 4.33 | Section 31 1,4-Dioxane Results – Fourth Quarter 2021 |
| 4.34 | Sections 19 and 30 1,4-Dioxane Most Recent Results |
| 4.35 | North End Trend Analysis Plots – Area 1 |
| 4.36 | North End Trend Analysis Plots – Area 2 |
| 4.37 | North End Trend Analysis Plots – Area 3 |
| 4.38 | North End Trend Analysis Plots – Area 4 |
| 4.39 | North End Trend Analysis Plots – Sections 30 and 19 |
| 4.40 | North End Trend Analysis Plots – Yale Ave |

4.41 Progress from Response Actions – Last Sampling Date
4.42 North End Trend Analysis Plots – Area 5
5.1 Gas Monitoring Probe Location Map
6.1 Stormwater Sample Location
9.1 Master Schedule

## LIST OF APPENDICES

**No.** **Title**

**APPENDIX A WATER TREATMENT PLANT**

A-1 WTP Weekly Summaries and Standard Operations Checklists
A-2 NBBW Sump Graph
A-3 Sludge Analysis Data
A-4 WTP Water Quality Data
A-4.1 Summary of Water Treatment Plant Effluent (MP-001) Water Quality
A-4.1.1 Compliance Summary of Water Treatment Plant Effluent (MP-001) Water Quality – 1,4-Dioxane
A-4.1.2 Compliance Summary of Water Treatment Plant Effluent (MP-001) Water Quality – Volatile Organic Compounds and Nonylphenol
A-4.1.3 Compliance Summary of Water Treatment Plant Effluent (MP-001) Water Quality – Metals, pH and Semivolatile Volatile Organic Compounds
A-4.1.4 Compliance Summary of Water Treatment Plant Effluent (MP-001) Water Quality – Radionuclides
A-4.2 Summary of Treatment Plant Early Warning Influent Water Quality
A-4.2.1 Summary of Treatment Plant Early Warning Influent Water Quality (Volatile Organic Compounds) Individual And Composite Data
A-4.2.2 Summary of Treatment Plant Early Warning Influent Water Quality (1,4-Dioxane)
A-4.2.2.1 Summary of Treatment Plant Early Warning Influent Water Quality (1,4-Dioxane) Individual And Composite Data
A-4.2.2.2 Summary of Treatment Plant Early Warning Influent Water Quality (1,4-Dioxane) Trend Analysis
A-4.2.3 Summary of Treatment Plant Early Warning Influent Water Quality (Molybdenum)
A-4.2.3.1 Summary of Treatment Plant Early Warning Influent Water Quality (Molybdenum) Individual And Composite Data
A-4.2.3.2 Summary of Treatment Plant Early Warning Influent Water Quality (Molybdenum) Trend Analysis
A-5 Technical Memorandum – Anion Exchange Operational Performance At Lowry Landfill Superfund Site

## LIST OF APPENDICES (continued)

**No. Title**


**APPENDIX B WASTE DISPOSAL RECORDS**

B-1 Summary of Waste Disposed

B-2 Waste Manifests

**APPENDIX C GROUNDWATER**

C-1 New Monitoring Well Logs
C-2 Monitoring Well Hydrographs
C-3 Compliance Evaluation Statistical Testing and Analyte Statistical Trend Analysis Plots
C-3.1 Data Summary Table
C-3.2 Mann-Kendall Trend Analysis
C-3.3 Goodness-of-Fit Testing
C-3.4 Outlier Testing
C-3.5 Linear Regression Analysis
C-3.6 Upper Control Limit Analysis for Data Without Trend
C-4 Effectiveness Assessment
C-4.1 Determination of Hydraulic Gradients
C-4.2 Data Summary Table for Wells with Outward Gradient
C-4.3 Trend Analysis for Wells with Outward Gradients
C-4.4 Shewhart-CUSUM Test for Wells with Outward Gradients
C-5 Vertical Migration Assessment
C-5.1 Vertical Migration Well Data
C-5.2 Mann-Kendall Trend Analysis
C-5.3 Dixon's Test for Outliers
C-6 North End Monitoring and Response Actions
C-6.1 North End – All Organics and Nitrate Data
C-6.2 MW77 Area – All Organics and Nitrate Data

**APPENDIX D LANDFILL GAS**

D-1 LFG Quality and Extraction Well Pressures
D-2 Flare/Gas-to-Energy Plant Station Monitoring
D-2.1 Flare Station Monitoring – Lowry Inlet
D-2.2 Flare Station Monitoring - DADS Blower Flare
D-2.3 Flare Station Monitoring – Flare Station 3
D-2.4 Flare Station Monitoring – Combined Sources at Gas-to-Energy Plant
D-2.5 Flare Station Monitoring – Daily Field Notes
D-3 Landfill Gas Monitoring Probes – Methane

**APPENDIX E COVER MONITORING – FIELD INSPECTION AND MAINTENANCE REPORTS**

E-1 Site and Landfill Cover Inspections

## LIST OF APPENDICES (continued)

**No. Title**

E-2 Buffer Zone Inspections
E-2.1 August 2021 Buffer Zone Inspection
E-2.2 November 2021 Buffer Zone Inspection

**APPENDIX F ANALYTICAL DATA PACKAGES, DATA VALIDATION REPORTS, AND DATA QUALITY ASSESSMENT**

F-1 Sample Location Cross Reference Table
F-2 Analytical Data Packages and Data Validation Reports
F-3 Data Quality Assessment

**APPENDIX G ELECTRONIC DATABASE**

## LIST OF ACRONYMS AND ABBREVIATIONS

| | |
|---|---|
| % | Percent |
| Δh | Change in head |
| µg/L | Micrograms per liter |
| 14X | 1,4-Dioxane |
| 3DVA | 3-Dimensional Data Visualization and Analysis |
| 5YRR | Five Year Review Report |
| amsl | Above mean sea level |
| ARARs | Applicable or Relevant and Appropriate Requirements |
| bgs | Below ground surface |
| BTS | Biological Treatment System |
| °C | Degrees Centigrade |
| CD | Consent Decree |
| CDPHE | Colorado Department of Public Health and Environment |
| CFM | Chloroform |
| Chem Rec | Chemical recovery |
| CSE | Containment System Evaluation |
| CSM | Conceptual Site Model |
| cy | Cubic yards |
| d | Distance |
| DADS | Denver-Arapahoe Disposal Site |
| DBF | DADS Blower/Flare |
| DCA | Dichloroethane |
| DCE | Dichloroethene |
| Denver | City and County of Denver |
| DNAPL | Dense non-aqueous-phase liquid |
| DQA | Data Quality Assessment |
| DQO | Data quality objective |
| DVR | Data Validation Report |
| EB | Equipment blank |
| EBEW | East boundary extraction well |
| EMSI | Engineering Management Support, Inc. |
| ESW | East/South/West |
| EW | Extraction well |
| EWMP | Early Warning Monitoring Plan |
| ºF | Degrees Fahrenheit |
| Fm | Formation |
| FS3 | Flare Station 3 |
| Ft | Feet |
| ft/ft | Foot per foot |
| GAC | Granular activated carbon |
| GC | Gas chromatograph |
| gpd | Gallons per day |

## LIST OF ACRONYMS AND ABBREVIATIONS

| | |
|---|---|
| gpm | Gallons per minute |
| GTEP | Gas-to-Energy Plant |
| GWMP | Groundwater Monitoring Plan |
| H | Hour |
| HMI | Human-machine interface |
| in wc | Inches of water column |
| IRA | Initial Response Action |
| IX | Ion exchange |
| $L_c$ | Critical value |
| LBF | Lowry Blower/Flare |
| LCL | Lower confidence limit |
| LCS | Laboratory control sample |
| LEL | Lower explosive limit |
| LFG | Landfill gas |
| LNAPL | Light non-aqueous-phase liquid |
| MARLAP | Multi-Agency Radiological Laboratory Analytical Protocols |
| MB | Method blank |
| MDL | Method detection limit |
| Metro | Metro Wastewater Reclamation District (now Metro Water Recovery) |
| M-K | Mann-Kendall |
| mS/cm | micro-Siemens per centimeter |
| M | minute |
| mg/L | Milligrams per liter |
| MS/MSD | Matrix spike/matrix spike duplicate |
| mV | Millivolt |
| NA | Not applicable |
| NAPL | Non-aqueous-phase liquid |
| NBBW | North Boundary Barrier Wall |
| ND | Non-detect/not detected |
| NGVD | National Geodetic Vertical Datum |
| NTES | North Toe Extraction System |
| NV | Not validated |
| O&M | Operations and maintenance |
| OS | Optimization Study |
| PARCC | Precision, accuracy, representativeness, comparability, completeness |
| PCR | Periodic Compliance Report |
| PCE | Tetrachloroethene |
| PID | Photo-ionization detector |
| PLC | Programmable logic controller |
| POC | Point of compliance |
| POTW | Publicly-owned treatment works |
| Ppb | Parts per billion |
| PPE | Personal protective equipment |
| Ppm | Parts per million |
| PS | Performance standard |

## LIST OF ACRONYMS AND ABBREVIATIONS

| | |
|---|---|
| psi | Pounds per square inch |
| PWI | Potable water injection |
| QAPP | Quality Assurance Project Plan |
| RA | Remedial action |
| RAWP | Response Action Work Plan |
| RI | Remedial investigation |
| ROD | Record of Decision |
| RPD | Relative percent difference |
| RWST | Raw water storage tank |
| scfm | Standard cubic feet per minute |
| SDG | Sample delivery group |
| SIM | Selected Ion Monitoring |
| Site | Lowry Landfill Superfund Site |
| SOW | Statement of Work |
| Surr | Surrogate |
| SVOC | Semi-volatile organic compound |
| SWRA | Surface Water Removal Action |
| TB | Trip blank |
| TCA | Trichloroethane |
| TCE | Trichloroethene |
| TCHD | Tri County Health Department |
| TCLP | Toxicity characteristic leaching procedure |
| TDS | Total dissolved solids |
| TENORM | Technologically Enhanced Naturally Occurring Radioactive Material |
| THF | Tetrahydrofuran |
| THM | Trihalomethane |
| TM | Technical Memorandum |
| tpy | Tons per year |
| TSDF | Treatment, Storage and Disposal Facility |
| TSS | Total suspended solids |
| U | Non-detect |
| UCL | Upper confidence limit |
| UD | Unweathered Dawson formation |
| UPS | Uninterruptable power supply |
| USEPA | United States Environmental Protection Agency |
| USGS | United States Geological Survey |
| UV-Ox | Ultraviolet Oxidation |
| VFD | Variable frequency drive |
| VOC | Volatile organic compound |
| WAP | Water Augmentation Plan |
| WD | Weathered Dawson formation |
| WM | Waste Management |
| WMP | Waste Management Plan |
| WSDs | Work Settling Defendants |
| WTP | Water treatment plant |

LOWRY LANDFILL

www.lowrylandfill.com

# Executive Summary: Status of Operations, Maintenance and Remedial Actions

*March 31, 2022*

## INTRODUCTION

**Since the last report six months ago, EPA has published a Fifth Five-Year Review (2022) that determined the remedy at the site is protective in the long term. Just prior to the release of the 5th FYR, EPA also amended the Fourth Five-Year Review with a short-term protectiveness finding. These determinations were made as a result of the routine operations and maintenance (O&M) activities at and north of the Superfund Site completed by the City and County of Denver, Waste Management of Colorado, Inc., and Chemical Waste Management Inc.,(collectively referred to as the Work Settling Defendants (WSDs.) This work allowed for the WSDs to resolve all of the Fourth Five-Year Review deferred protectiveness findings in collaboration with EPA, CDPHE, and the Tri-County Health Department. Further, the remaining studies were finalized and incorporated by EPA into the 5th FYR which found the remedy protective in the long term. A brief summary of the protectiveness finding of the Fifth Five-Year Review and details of the O&M activities are presented in this Status Report.**

The Fifth Five-Year Review (2022) determined that the remedy is protective of human health and the environment and that no other information has come to light that could call this into question. Specifically, EPA has determined that the remedy is functioning as intended by the decision documents, and that the exposure assumptions, toxicity data, and cleanup levels and Remedial Action Objectives used at the time of the remedy selection are still valid. Therefore, the remedy for Lowry Landfill is protective of human health and the environment.

The O&M activities that allowed for EPA to resolve all Fourth Five-Year Review issues as well as issue a determination of protectiveness for the Fifth Five-Year Review consisted of extracting and treating approximately 9.1 million gallons of groundwater

from several onsite and offsite extraction systems in full compliance with the Industrial Discharge Permit from Metro Water Recovery; collection and analyses of 122 samples from 75 groundwater monitoring wells; continuous operations of the Landfill Gas Extraction and Treatment system in full compliance with decision documents; collection and analyses of soil gas samples from 64 subsurface gas monitoring probes surrounding the Lowry Landfill; maintenance of stormwater conveyance ditches; and inspection and maintenance of landfill covers and buffer properties contiguous to the Superfund Site.

During the reporting period all Fourth Five-Year review issues were resolved including 1) EPA approval of the North End Groundwater Monitoring Plan (added additional monitoring wells); 2) publication and EPA approval of the Containment System Evaluation (CSE) for the fifth groundwater remedy component that concluded the NBBW which was demonstrated to achieve containment along the Target Zone of Containment; and 3) EPA published the Final Updated Conceptual Site Model to describe the current understanding of site conditions. The Fourth Five Year Review determined that Operable Unit 1 (OU1) (Shallow Groundwater and Subsurface Liquids) and OU6 (Deep Groundwater) were short-term protective and protective, respectively, because there are no completed exposure pathways for 1,4-dioxane in shallow groundwater and the deep groundwater plume is delineated. In September of 2020 EPA determined that the North End 1,4-dioxane plume does not pose an unacceptable risk to human health, and that no additional institutional controls are necessary north of the Superfund Site. However, WSDs will continue to voluntarily extract groundwater from the North End to accelerate 1,4-dioxane mass removal.


As part of the WSDs ongoing commitment to transparency and community engagement, several outreach opportunities were provided. During this reporting period, the WSDs provided


community outreach by participating in five meetings with the Lowry Landfill Community Advisory Group with presentations given regarding stratigraphy, groundwater flow direction and dewatered areas of the weathered Dawson in the area north of the NBBW.

## Progress at Lowry

- ✔ Upgrading the WTP and POTW discharge line: **DONE**
- ✔ Obtain approval from the State Engineer's Office to allow higher flow rates through the plant and new locations for release of augmentation water on a permanent basis: **DONE**
- ✓ Sampling private wells within/adjacent to the 1,4-dioxane plume and confirming they are not impacted, **DONE**
- ✓ Evaluating effectiveness of five groundwater remedy components: **DONE**
- ✔ Updating the Groundwater Monitoring Plan to add 1,4-dioxane, delete iron, and incorporate the most recent Colorado Basic Standards for Groundwater : **DONE**
- ✔ Identifying and sampling potentially at-risk off-site private wells in the vicinity of the 1,4-dioxane plume and updating the North End Groundwater Monitoring Plan: **DONE**
- ✔ Confirming the lateral and vertical extent of the off-site 1,4-dioxane plume: **DONE**
- ✔ Updating performance standards for landfill gas in subsurface soils: **DONE**

# LOCATION & CONTAINMENT REMEDY MAPS



## GROUNDWATER MONITORING

More than 500 monitoring wells extending into both shallow and deep aquifers have been installed within and outside the site to ensure the community is protected. Well inspections are a routine part of the monitoring program. Data shows that the monitoring system continues to be effective.

Groundwater remedy component effectiveness evaluations conducted in 2021 as part of the fourth five-year review determined that the remedial components are effective and achieve objectives. Specifically, the slurry wall – a vertical barrier wall made of clay that prevents groundwater flow – continues to effectively contain contamination inside the eastern, southern and western limits of the landfill as designed. The North Toe Extraction System, which collects and pumps water to the treatment plant at less than 1 gallon per minute, continues to capture the most contaminated groundwater emanating from the landfill. The 960-foot long North Boundary Barrier Wall (NBBW) located at the north end of the site is the most significant groundwater extraction feature, removing 6 to 10 gallons per minute, which effectively prevents contamination from migrating offsite. Finally, groundwater extraction in the northwest corner of the site, known as the MW38 area, captures contaminated groundwater flowing through this area and prevents offsite migration.

Vertical migration monitoring shows vertical migration wells are in compliance with groundwater performance standards and that contaminated groundwater has not migrated to the deeper aquifers.

There are 60 compliance wells in the network, which are monitored for 29 different chemicals. There are 52 wells in compliance or potentially in compliance, and 8 wells are out of compliance or potentially out of compliance for chemicals such as 1,4-dioxane, PCE, nitrate, nitrite, and chloroform. The 8 wells that are out, or potentially out of, compliance are being addressed by continuing to pump contaminated water to the treatment plant, as discussed above. This method has proven to be effective at stopping groundwater flow in these areas and reducing the chemical concentrations.

## FACTORS AFFECTING CONTAMINANTS IN GROUNDWATER

### *1,4-dioxane and the North End*

In 2005, the Colorado Water Quality Control Commission established a new groundwater standard for 1,4-dioxane. At that time, new technological advancements capable of detecting and measuring 1,4-dioxane at the new standards found 1,4-dioxane north of the site. That standard has been revised over the past 13 years, and the current standard is now 0.35 parts per billion (ppb). Current best available analytical technology is not able to reliably detect 1,4-dioxane at this concentration in site groundwater so a site-specific standard for Lowry Landfill is set at 0.9 ppb.


Numerous response action work plans have been implemented that have effectively reduced the extent of 1,4-dioxane in the North End Area, and




Water Treatment

1.5 million gallons per month

In compliance with discharge standards






1,4-dioxane

- Synthetic industrial chemical sometimes added to solvents to prolong their useful life
- Used in some consumer products such as cosmetics, deodorants, soaps, toothpaste, anti-freeze and paint

- Site groundwater standard = .9 ppb

there is a comprehensive monitoring program in place. Of the 37 current North End monitoring wells, 36 have sufficient data to determine 1,4-dioxane trends. Of those, 86% are decreasing, 11% are flat, and 1,4-dioxane concentrations at one well (3%) are increasing. The observed concentration declines in all areas shows the effectiveness of the ongoing response actions and demonstrates that groundwater quality in this area is improving. Data shows that the groundwater extraction response at the site continues to significantly decrease the 1,4-dioxane concentrations, as well as the width and length of the contamination to the north. An animation of the North End plume over time is available at www.lowrylandfillinfo.com.

### *MW38 Sand Channel*

Remedial actions to contain groundwater and reduce contaminant concentrations in the sand channel have also been successful. Water is pumped out of the sand channel to maintain inward groundwater flow directions and prevent offsite migration of contaminants and the extracted water is sent to the treatment plant ensuring the surrounding groundwater is always flowing inward. Levels of 1,4-dioxane have been reduced by 98% since May 2005 in this area. Chloroform and trichloroethene concentrations have also been reduced by 94%. See graph at right.

### *Nitrate in the NBBW Area*

One well is exceeding the nitrite and nitrate standards and another exceeds nitrate only in an area where sewage sludge was historically land farmed to cultivate and enhance microbial degradation of the sludge. These wells are located along the northern boundary of the Site. There does not appear to be a potential for significant off-Site migration of nitrate or nitrite at concentrations greater than the performance standard and monitoring is ongoing. Additionally, groundwater extraction from the North End wells further downgradient would capture any potential migration of these compounds if it were to occur.

## WATER TREATMENT PLANT

The water treatment plant uses a natural biological process and advanced oxidation treatment to destroy more than 92% of the organic compounds coming into the plant. An ion-exchange system is used to reduce molybdenum by an average of 99%. The pretreated water is then discharged to a publicly-owned wastewater treatment plant for further treatment. The on-site treatment plant removes all site chemicals to safe standards and leaves a minimal environmental foot-print. It treats approximately 1.5 million gallons of contaminated groundwater every month. The data show the plant continues to operate as designed in compliance with discharge standards.




### At Lowry

- Extraction and treatment continues to decrease concentrations.
- North End Area: 38 Wells

**86%** *show declining concentrations*

**11%** *remain flat*

- MW38 Channel:


**98%** *reduction of 1,4 dioxane since May 2005*

## LANDFILL GAS REMEDY

Landfill gas—made up of methane, carbon dioxide, nitrogen and other gases—is created naturally by the biological decomposition of organic matter in landfills under low-oxygen conditions. The Site's landfill gas extraction, collection and treatment system continues to be effective and in compliance, including the gas-to-energy treatment plant, which removes roughly 5,000 tons of methane annually. This equates to removing more than 22,000 cars from the road each year. The on-site power plant, constructed in 2008, uses landfill gas to fuel four internal combustion engines that generate electricity for a local utility company. The electrical power generated is enough to supply 2,500 to 3,000 households.

## LANDFILL COVER

The former landfill is covered by 4 to 12 feet of compacted clay and soil. The "cap" reduces infiltration of rain and snow into the soil, which minimizes further groundwater contamination. The cover continues to effectively drain rain and snow, keeping it from penetrating the soil. The cap is routinely monitored for any depressions that may form due to settlement that would cause rainwater to pond, among other issues. No cap settlement issues were identified in this report.




LOWRY LANDFILL

**Visit the Lowry Landfill website for detailed information and contact information.**
**www.lowrylandfill.com**

## 1.0 INTRODUCTION

This Remedial Action (RA) and Operations & Maintenance (O&M) Status Report was prepared on behalf of the City and County of Denver (Denver), Chemical Waste Management, Inc., and Waste Management of Colorado, Inc. (WM), collectively Work Settling Defendants (WSDs), pursuant to Subsection 2.1 of the Statement of Work (SOW) attached as Exhibit C to the Consent Decree (CD) entered by the U.S. District Court for the District of Colorado on 28 September 2005 (and reentered on 16 November 2005) in Civil Action No. 02-CV-01341-EWN-MJW regarding the Lowry Landfill Superfund Site (the Site).

No RA activities were performed during the reporting period.

O&M activities consisted of operations, maintenance, and monitoring associated with the Site Water Treatment Plant (WTP), groundwater, surface water, landfill gas (LFG), and landfill covers. These activities were performed in accordance with *Addendum 7, Operation and Maintenance Manual, Water Treatment Plant* (Parsons/Engineering Management Support, Inc [EMSI], 2021); *Revision 3, Operations and Maintenance Manual, Groundwater Extraction* (Parsons, 2021a); *Revision 2 Groundwater Monitoring Plan* (GWMP) (EMSI/Parsons, 2018); the *Stormwater Monitoring Plan* (EMSI, 2008a); *Revision 3, Operations and Maintenance Manual, LFG Remedy* (EMSI, 2021); *Revision 4, Updated Compliance Monitoring Plan LFG Remedy* (EMSI, 2020a); and the *Final Operations and Maintenance Manual, Covers and Stormwater* (EMSI, 2007a). In addition, groundwater extraction from North End and MW77 Area response actions and monitoring of North End groundwater were implemented in accordance with the *Revised North End Initial Response Action (IRA) Work Plan Addendum* (EMSI, 2008b) as conditionally approved by United States Environmental Protection Agency (USEPA) on March 24, 2008; the *North End Groundwater Monitoring Plan* (EMSI, 2007b); the *North End Groundwater Monitoring Plan Update No.2* (EMSI, 2020b); the *North End Groundwater Monitoring Plan Update No. 3* (Parsons, 2021b); the *Response Action Work Plan to Extract Additional Groundwater from Upgradient of MW77-WD* (EMSI, 2011); the *Response Action Workplan for the B-326-UD and B-313 Areas* (EMSI, 2013); and the *Revised Work Plan to Further Assess the North End 1,4-Dioxane Plume and Update Conceptual Model for North End Area* (EMSI, 2018a). The status of North End activities is described in Subsections 4.8 and 4.9.

### 1.1 Purpose and Scope

This report summarizes results of O&M activities performed from 01 July 2021 through 31 December 2021 (reporting period).

### 1.2 General Site Description

The Site is located in Section 6, Township 5 South, Range 65 West, and in the southern portion of Section 31, Township 4 South, Range 65 West in west central Arapahoe County, approximately 15 miles east of downtown Denver, Colorado. The Site occupies approximately 508 acres within an unnamed north-south trending valley located west of Murphy Creek and east of East Toll Gate Creek. The North End study area extends for approximately three miles north of the Site and is coincident with the unnamed creek and Murphy Creek drainages.

## 1.3 Report Organization

This report contains ten sections and seven appendices. The remainder of this report is organized as follows:

- Section 2 and Appendix A contain a summary of WTP operations and monitoring. Appendices F and G contain electronic analytical data packages and data validation reports (DVRs) for the WTP, the Data Quality Assessment (DQA), and the database. The database has been updated for routine database checks and should replace any previous versions still in use.
- Section 3 and Appendix B contain a summary of waste management activities, including: waste storage, treatment, disposal, and maintenance.
- Section 4 and Appendix C contain a summary of groundwater monitoring activities and evaluations of monitoring results, including: well inspections, sitewide groundwater level data, analytical results, and statistical evaluations. Appendices F and G contain electronic analytical data packages, DVRs, the DQA, and the database for groundwater. The database has been updated for routine database checks and should replace any previous versions still in use.
- Section 5 and Appendix D contain a summary of LFG monitoring, extraction, collection, and treatment activities performed during the reporting period, and an evaluation of gas monitoring results and collection system performance. Appendix G contains the database for landfill gas, the Gas-to-Energy Plant (GTEP), and flare gas.
- Section 6 contains a summary of stormwater sampling activities and results. Appendix G contains the database for storm and surface water.
- Section 7 and Appendix E present activities and results related to cover monitoring and maintenance.
- Section 8 presents the status of RA activities.
- Section 9 presents problems encountered and recommendations for each component of this Status Report.
- Section 10 presents the references cited in this report.

## 2.0 WATER TREATMENT PLANT

This section summarizes WTP O&M activities for the reporting period.

### 2.1 Operations and Maintenance

Operations of the WTP during the reporting period were limited to treatment of Site waters originating from the North Boundary Barrier Wall (NBBW), North Toe Extraction System (NTES) sump, east boundary extraction wells (EBEWs – PM-11, PM-15 and MW-51 areas), MW38 area extraction wells, on- and off-Site North End Response Action wells, the decontamination pad at the GTEP complex, LFG condensate, and miscellaneous sources such as well sampling purge waters and potable water used for plant wash-down. Following treatment, all of these waters were discharged to the publicly-owned treatment works (POTW) pipeline.

The treatment protocols, process monitoring, and effluent quality monitoring were performed in accordance with Industrial Discharge Permit No. 2360-6, effective January 5, 2020.

Throughout the reporting period, the WTP was discharging to the POTW 99 percent (%) of the calendar time. Downtime was caused by the reasons listed below, in order of decreasing significance. No discharge occurred during these downtimes.

- Power interruption: Plant discharge stopped on seven occasions for power grid interruptions. Plant discharge was interrupted for a scheduled outage on August 4 for a high voltage line relocate near Denver-Arapahoe Disposal Site's (DADS) Scale house (9 hours 47 minutes). Other outages occurred on August 30 (1 hour 22 minutes), September 7 (2 hours 43 minutes), September 13 (2 hours 43 minutes), September 23 (2 hours 50 minutes), October 7 (2 hours 55 minutes) and November 7 (3 hours 57 minutes) for a total of 26 hours 17 minutes.
- Annual device calibrations: Plant operations were stopped on one occasion while the calibrations of critical devices were confirmed [scheduled - November 15 (1 hour and 23 minutes)].
- Routine O&M: Effluent pH probe calibration, quarterly POTW discharge line valve exercising and granular activated carbon (GAC) vessel back-flushing (scheduled – all less than one day).
- Automatic shutdown tests of auto-alarm sensors and shutdown circuits (scheduled – all less than one day).
- Main WTP programmable logic controller (PLC) network switch upgrade: Plant operations were stopped on one occasion while the network switch linking the main PLC to other PLCs and Human-Machine Interface (HMI) computers was upgraded (scheduled – 35 minutes).
- Main WTP PLC logic fault: Plant operations stopped when the Main PLC faulted when an out-of-range setpoint was input for the newly programmed P-114 Ion Exchange feed pump and resulted in a logic error. Plant operations stopped automatically until the fault could be cleared [September 21 (17 minutes)]. Changes were made to the programming to prevent this occurrence in the future.

- Daylight savings time to standard time adjustment: Plant operations were stopped while the PLC and plant computers were adjusted to standard time [November 8 (15 minutes)].
- Main WTP PLC uninterruptable power source (UPS) replacement: Plant operations were stopped on one occasion to replace an eight-year-old UPS on its second set of batteries (scheduled – 7 minutes).

All O&M activities were documented on checklists, in the daily operator logs, and/or electronic logs entered automatically into the WTP databases by the operating software. Completed daily operator logs and weekly checklists of pertinent information are provided in Appendix A-1.

### 2.1.1 NBBW System

As shown in Appendix A-2, groundwater elevations in the NBBW sump fluctuated between 5685.4 feet (ft) above mean sea level (amsl) and 5685.6 ft amsl. The average groundwater elevation was 5685.5 ft amsl, which is the set-point water level in the sump. Throughout the reporting period, groundwater was extracted from the NBBW sump at an average rate of 7.1 gallons per minute (gpm) while pumping.

The significance of groundwater elevations at the extraction sump and in the overall vicinity of the NBBW system relative to hydraulic containment is evaluated in Subsection 4.5.3 of this report.

### 2.1.2 North End Extraction System

Extraction wells in the North End include on-Site wells located near the northern boundary of the Site and off-Site wells located north of the Site in Section 31 (Figure 4.34). North End on-Site and off-Site extracted groundwater was conveyed to the main WTP through dedicated North End pipelines. On-Site and off-Site North End groundwaters are introduced to the WTP at the feed surge tank where they are blended with pre-treated on-Site waters, treated by GAC, then discharged to the POTW pipeline. Rates of North End on-Site and off-Site groundwater extraction are presented in more detail in Subsection 4.8.

### 2.1.3 Liquid Volumes and Flow Rates

The following table summarizes the types, flow rates, and volumes of waters treated during the reporting period.

| Water Source | Average Flow Rates (gpm) | Total Volume (gallons) |
|---|---|---|
| NBBW Water [total of volume sent directly to WTP plus volume temporarily routed to raw water storage tanks (RWSTs)] | 7.1 | 1,888,320 |
| MW38 area (includes automatic pumping from the sand channel wells and the source-control well) | 2.2 (calendar) | 582,728 |
| NTES Water | 0.5 (calendar) | 135,364 |
| LFG Condensate from Tank 530 (treated in WTP from July 1 through December 31, 2021) | 0.02 (calendar) | 5,399 |
| PM-11 Area | NA[a/] | 50,536 |
| MW51 Area | NA | 64,690 |
| PM-15 Area | NA | 3,600 |

| Water Source | Average Flow Rates (gpm) | Total Volume (gallons) |
|---|---|---|
| Decontamination Water and Precipitation | NA | 2,563 |
| North End On-Site Water[b/] | 15.9 (calendar) | 4,207,147 |
| North End Off-Site Water[b/] | 8.3 (calendar) | 2,169,008 |
| Potable Water [for plant wash-down, pipeline flushing and Gas Chromatographs (GCs)] | NA | 22,005 |
| Total Influent[c/] | 34.5 (calendar) | 9,131,360 |
| Discharge to POTW[c/] | 34.5 (calendar) | 9,126,699 |

calendar - timeframe used to derive average flow rate. For example, total volume during the reporting period (gallons) divided by number of calendar-minutes during the reporting period equals average flow rate in gpm.

a/ Not applicable – batch transfer to RWSTs, feed surge tank, or clear well, then treatment in WTP.

b/ See Subsection 4.8 for extraction rates from individual North End wells.

c/ The difference between the total influent volume and the volume discharged to the POTW is accounted for in total tank storage capacity associated with the WTP (including temporary storage in external tanks) and in measurement error of the totalizers. Totalizer error is as much as +/-0.5% on each totalizer (10 totalizers are used to generate the volumes above). For example, the effluent totalizer range of error is +/- 45,657 gallons over the reporting period.

### 2.1.4 pH System

During the reporting period, the pH of WTP effluent was measured every minute at the last pH monitoring probe in the plant (probe pH-740 located in the effluent surge tank). Average, minimum, and maximum pH readings during plant operations for the reporting period are summarized below. These represent normal pH readings.

| Month | Control pH Set-Point | Average pH Reading | Minimum pH Reading | Maximum pH Reading |
|---|---|---|---|---|
| July | 7.0 | 6.8 | 6.5 | 7.3 |
| August | 7.0 | 6.7 | 6.5 | 7.2 |
| September | 7.0 | 6.7 | 6.0 | 7.6 |
| October | 7.0 | 6.7 | 6.5 | 7.0 |
| November | 7.0 | 6.7 | 6.5 | 7.0 |
| December | 7.0 | 6.8 | 6.7 | 7.1 |

### 2.1.5 Removal of Volatile Organic Compounds

Removal of volatile organic compounds (VOCs) within the WTP is accomplished by biological treatment, UV-Oxidation (UV-Ox), and GAC. Biological treatment occurred in the Biological Treatment System (BTS) when treating a blend of approximately 6% NTES water, 21% MW38 area groundwater, 5% LFG condensate (when processing), and 68% softened water from the chemical precipitation process. The operating temperature of the BTS was maintained at 23.5 degrees Centigrade (°C).

While the BTS remained the primary process for VOC removal this reporting period, a parallel slip-stream of approximately 7.5 to 8.3 gpm of softened, non-NTES water was treated with UV-Ox to increase BTS removal efficiencies and biosolids handling by increasing the retention time within the BTS. The longer retention time in the BTS also allowed for increased flow from the MW38 Source well through the BTS.

The on-line GCs monitor eight target VOCs at least once per day for real-time monitoring at TP-3350 (BTS effluent) and TP-730 (UV-Ox effluent). The following compounds are monitored:

- 1,1-Dichloroethene (DCE)
- trans-1,2-DCE
- 1,1-Dichloroethane (DCA)
- Chloroform (CFM)
- Tetrahydrofuran (THF)
- Benzene
- 1,2-DCA
- 1,4-Dioxane

GC monitoring of GAC efficiencies at TP-710, TP-740, and TP-750 occurs once per week. Due to the large volume of data produced by the three GCs, those data are not included here but are available upon request.

Destruction efficiencies of the VOC compounds that have exceeded their discharge limits in **plant influent** in at least one sampling event since monitoring began are calculated below. Although the permit no longer includes discharge limits for these compounds (except 1,4-dioxane), they are routinely monitored in plant influent per the *Updated Early Warning Monitoring Plan* (EWMP) (EMSI, 2008c) and in plant effluent per the discharge permit (Metro Wastewater Reclamation District [Metro], 2020)]. Approximate destruction efficiencies for these compounds for the WTP as a whole are summarized below. These destruction efficiencies were calculated based on differences between mass loading to the plant from all influent streams and mass remaining in plant effluent.

**Organic Destruction Efficiencies across Entire WTP**

| Compound | Average Efficiency (%) July through December 2021 |
|---|---|
| 1,1-DCE | 92% |
| 1,2-DCA | 99% |
| 1,4-dioxane | 97% |
| Benzene | 100% |
| Vinyl Chloride | 100% |

Analytical results from MP-001 (plant effluent, Appendix A-4.1.1 and A-4.1.2) and influent composite sampling (Appendix A-4.2.1) indicate that some breakthrough of target

compounds through GAC contactors occurred during the reporting period (as shown in the table above). 1,4-Dioxane showed breakthrough over the entire reporting period. Note: GAC is not intended to remove 1,4-dioxane. However, 1,4-dioxane breakthrough concentrations were less than 85% of the discharge limit at all times (85% criterion is used as a trigger level to change out carbon, per Section 3.11 of the WTP O&M Manual).

### 2.1.6 Sludge Production

During the reporting period, approximately 25 cubic yards (cy) of dry sludge was produced and placed into a lined roll-off box located adjacent to the WTP. Fifteen cy each of the sludge were disposed at DADS in August and in November in accordance with the *Updated Waste Management Plan* (WMP) (EMSI, 2020c). The remaining sludge will be disposed of in the first half of 2022. The non-hazardous waste manifests for the sludge are presented in Appendix B-2. Analytical results for radiological and toxicity characteristic leaching procedure (TCLP) analyses of the sludge are presented in Appendix A-3. Analytical and screening results confirmed the sludge remains a non-hazardous, solid waste.

WTP sludge was also sampled for technologically enhanced naturally occurring radioactive material (TENORM) according to 6 CCR 1007-1 Part 20. The goal of the regulation is to determine if naturally occurring radioactive material concentrations are increased by, or as a result of, past or present human practices i.e., the processes within the WTP. The sludge was sampled in triplicate for Radium-226, Radium-228, Polonium-210, and Lead-210 (Appendix A-3). All sample results were below the exemption limit (5 pCi/g for each isotope) therefore Lowry WTP sludge material is exempted from the rule.

### 2.1.7 Maintenance and Calibration

Routine servicing and maintenance of plant equipment included the following:

- Serviced liquid transfer pumps, chemical feed pumps, and mixers;
- Quarterly bag filter inspections;
- Replenished chemical storage totes;
- Added and mixed chemical polymer;
- Serviced the HMR-30 mixing, flocculation, settling, and clear-well chambers;
- Serviced the sludge thickener and holding tanks;
- Serviced the plate and frame filter press;
- Back-flushed the GAC contactors to prevent fines accumulation and hydraulic packing of the carbon;
- Serviced air compressors (Ingersoll Rand);
- Cleaned pump strainers;
- Serviced BTS air blowers; and
- Quarterly UV-Ox unit inspection and test run (when on standby).

Routine maintenance and calibration of plant instrumentation included the following:

- Daily cleaning of pH probe at TP-315;

- Weekly calibration (and cleaning as necessary) of pH probes at TP-315, TP-365, TP-670, and TP-740;
- Weekly cleaning and monthly calibration of pH probes in the BTS;
- Weekly servicing, data backup, and calibration of on-line GCs;
- Weekly data backup and archiving of WTP operating database;
- Annual flow and level device calibration checks; and
- Monthly calibration of lower explosive limit (LEL) meter (LEL-740).

All maintenance and calibration activities were documented on checklists and in the daily operator logs provided in Appendix A-1.

## 2.2 Monitoring

### 2.2.1 Summary of Activities

Compliance monitoring during the reporting period consisted of sampling WTP effluent (MP-001) per the discharge permit (Metro, 2020). Other monitoring included sampling the molybdenum IX system to measure efficiencies; monitoring of NBBW-IW-3 for molybdenum and 1,4-dioxane; performance monitoring of the BTS; and Early Warning monitoring per the EWMP (EMSI, 2008c) to measure performance of the WTP treatment systems.

#### 2.2.1.1 WTP Effluent Compliance Monitoring

All WTP effluent (MP-001) analytical results for the reporting period were reported in monthly Periodic Compliance Reports (PCRs) that are submitted to Metro, Aurora, USEPA, Colorado Department of Public Health and Environment (CDPHE), and Tri County Health Department (TCHD). Analytical results for MP-001 monitoring are reported in Appendix A-4.1.


#### 2.2.1.2 Ion Exchange Monitoring for Molybdenum

Performance monitoring for the molybdenum ion exchange (IX) treatment system included weekly monitoring (while pumping) of MW113-EW-1 influent at plant sampling port TP-170 plus multiple sample ports located on the IX treatment system. The IX treatment system is used to manage the molybdenum in the WTP effluent (MP-001). The rate of extraction at MW113-EW-1 at the beginning of the period was approximately 2 gpm until it was increased from 2 gpm to 4 gpm on August 18, 2021. As the level of the alluvium in the MW113 area dropped, so did the extraction rate. The steady decline in both level and extraction rate continued throughout the period to near the base of the MW113-EW-1 well screen. The extraction rate was approximately 2 gpm by the end of the period. A high percentage of molybdenum continues to be efficiently removed by the IX system as the molybdenum concentration entering the IX treatment system remained relatively stable throughout the period.

#### 2.2.1.3 Monitoring of NBBW-IW-3

Performance monitoring at extraction well NBBW-IW-3 was also performed to monitor molybdenum concentrations and mass removal of 1,4-dioxane. On May 25, 2020 WSDs began pumping NBBW-IW-3 at 2 gpm into temporary tanks with weekly sampling of molybdenum and 1,4-dioxane to monitor their concentrations before pumping to the WTP. Only low-level concentrations (<45 micrograms per liter [µg/L]) of molybdenum have

been detected in well NBBW-IW-3 since extraction began while 1,4-dioxane concentrations ranged from 100 to 170 µg/L. On July 8, 2020 WSDs began pumping groundwater from NBBW-IW-3 directly to the WTP via the North End On-Site conveyance pipeline. Analysis frequency for molybdenum was increased to every other day using a field colorimeter to monitor for changes in molybdenum concentrations at this well. Field monitoring (with confirmation through weekly lab analysis) continued until April 27, 2021. As IX treatment of MW113-EW-1 groundwater allowed for higher extraction rates (2 gpm), the potential for molybdenum migration to NBBW-IW-3 from the MW113 area was reduced. As a result, field monitoring for molybdenum and weekly lab analysis from well NBBW-IW-3 was discontinued on March 31, 2021. Instead, monitoring for molybdenum was performed from North End On-Site sample port TP-150 where NBBW-IW-3 along with other On-Site North End groundwater enters the plant. Sampling molybdenum from TP-150 transitioned from daily to weekly early second half 2021 as NBBW-IW-3 groundwater production continued to decline. Sampling of TP-150 has returned to monthly as part of the EWMP. The 1,4-dioxane results from well NBBW-IW-3 indicate that the rate of 1,4-dioxane removal from the B-326-WD area continues to be enhanced while extracting. As shown in the graph below, water elevations in the area lowered due to increased extraction from MW113-EW-1. The effectiveness of NBBW-IW-3 1,4-dioxane removal declined due to lower extraction rates at this well (from 0.5 gpm in June 2021 to 0 gpm in September). The effect of MW113-EW-1 extraction continued to impact the extraction rate at NBBW-IW-3 and eventually groundwater production at NBBW-IW-3 ceased in September 2021.




### 2.2.1.4 BTS Performance Monitoring

Performance monitoring of the BTS involved collection of samples for 1,4-dioxane, VOCs, total phosphorus, total volatile suspended solids, nitrate, and nitrite. Analytical results are used to measure organic loading, biomass and efficiency of the biological system. BTS performance monitoring data may be found in the Access© database in Appendix G.

#### 2.2.1.5 Early Warning Monitoring

Early Warning monitoring for this reporting period involved monthly sampling of WTP influent according to the EWMP (EMSI, 2008c) and *Metro Letter of Understanding* (EMSI, 2015). Influent samples from TP-110 (RWSTs), TP-120 (NBBW), TP-150 (North End on-Site and NBBW-IW-3), TP-170 (MW113 Area), TP-160 (North End off-Site and MW77 area) and TP-3310 (BTS influent) were collected for analysis of VOCs, 1,4-dioxane, and molybdenum (Appendix A-4.2).

### 2.2.2 Sampling

WTP effluent (MP-001) and Early Warning influent samples were collected according to the schedule and analytical protocol presented in Table 2.1. A sampling schedule for the next reporting period for compliance and Early Warning is also provided in the table.

Performance monitoring for molybdenum in the IX system was performed weekly. Performance monitoring for molybdenum and 1,4-dioxane at NBBW-IW-3 was performed once in third quarter 2021 and ceased when the well stopped producing groundwater in fourth quarter 2021. Performance monitoring for the BTS was performed weekly. Appendix F-1 lists the samples collected for performance and compliance monitoring and Appendix F-2 contains the data packages from the laboratories.

### 2.2.3 Laboratory Analyses

Eurofins/TestAmerica (Denver) analyzed the samples collected from the WTP for non-radiological parameters. Eberline Services (Oak Ridge, Tennessee) analyzed the radiological samples. Analytical data packages and DVRs for the reporting period are presented in Appendix F-2.

### 2.2.4 Data Validation

All effluent (MP-001) sample results were validated according to USEPA *National Functional Guidelines for Organic and Inorganic Data Review* (USEPA, 1994a and b) as amended, by SW-846 guidelines specific to the method or as directed by USEPA. All radionuclide results that were less than the critical value ($L_C$) were qualified as non-detects (U). Radionuclides were validated according to the guidelines and criteria specified in the *Multi-Agency Radiological Laboratory Analytical Protocols* (MARLAP) *Manual* (USEPA, 2004).

Validation is complete for all July through December 2021 compliance sampling events. All compliance data packages were received with no major quality issues except for recurring matrix spike failure of benzidine due to the inadequacy of method 625 to extract this compound without oxidative losses. This problem is discussed in more detail in the DQA report (Appendix F-3). Performance and Early Warning samples are not validated.

### 2.2.5 Monitoring Results

Compliance, Early Warning, and performance monitoring for the WTP were performed in this period as detailed below.

#### 2.2.5.1 Compliance Monitoring

WTP effluent (sample port MP-001) was sampled according to the schedule in Section E.1 of the discharge permit (Metro, 2020) and results are presented in Appendix A-4.1. All validated results from WTP effluent sample port MP-001 were below the industrial wastewater discharge permit limits.

### 2.2.5.2 Early Warning Monitoring

The Updated EWMP (EMSI, 2008c) requires annual sampling for a comprehensive list of parameters from Section E.1 of the discharge permit per the *Metro Letter of Understanding* (EMSI, 2015). Any compound in the **influent** whose concentration exceeds the discharge limit requires periodic follow-up sampling to monitor for statistical trends. An annual influent sampling event for the parameters listed below is required to determine if influent concentrations are less than discharge limits.

- VOCs (E624) (including 1,4-dioxane),
- 1,4-dioxane (8260B Selected Ion Monitoring [SIM])
- Semi-Volatile Organic Compounds (SVOCs) (E625),
- Metals (E200.7 and E200.8),
- Mercury (E245.1),
- Nonylphenol (D7065),
- Gross Alpha/Beta (E900.0),
- Radium-226 and total (SM 7500-RA-B)
- Radium-228 (EPA-RA-05),
- Plutonium-238, -239, -240 (EPA 600/7-79-081), and
- Americium-241 (ER110 LANL).

The annual influent sampling event was performed on April 5, 2021 and indicated 1,4-dioxane and molybdenum were the only **influent** compounds exceeding **discharge** limits. Consequently, these compounds were selected as compounds of concern for monthly influent monitoring. These compounds were collected as grab samples to monitor the concentration in each influent source. Influent sampling involved collecting grab samples from each of seven sources (RWSTs, NBBW, MW38, North End on-Site water, North End off-Site water, MW113 water and BTS influent) and compositing the results based on flow-weighted percentages. VOCs are sampled quarterly for performance monitoring. Appendix A-4.2 presents the individual results for each influent grab, the percentage of total flow, and the flow-weighted total concentrations for VOCs (A-4.2.1), 1,4-dioxane (A-4.2.2), and molybdenum (A-4.2.3).

As mentioned above, two compounds exceeded the discharge limit in the influent (1,4-dioxane and molybdenum). Statistical trending analyses (Sen's test) for 1,4-dioxane is presented in Appendix A-4.2.2.2 and for molybdenum in Appendix A-4.2.3.2. There were no statistically significant increasing trends for these analytes. The WTP can readily treat 1,4-dioxane to below discharge limits. Molybdenum treatability is discussed in Section 2.3.

### 2.2.5.3 Performance Monitoring

Performance monitoring results for molybdenum and BTS testing may be found in the database in Appendix G.

## 2.3 Treatability

As discussed in Section 2.2.1.2, an IX system for molybdenum removal from MW113-EW-1 groundwater was brought online to manage the molybdenum in the WTP effluent (MP-001). At 1.9 gpm to 4.0 gpm extraction rates, influent molybdenum concentrations to the IX system ranged between 3,300 and 7,200 µg/L and discharge from the IX treatment system ranged from 120 to 400 µg/L during the reporting period.

An evaluation of the operational performance of the IX system for molybdenum treatment was performed in the reporting period and is presented in *Anion Exchange Operational Performance at Lowry Landfill Superfund Site* (Parsons, 2021c), included in this report as Appendix A-5.

## 3.0 WASTE MANAGEMENT

Waste management activities during the reporting period were performed in accordance with the *Updated Waste Management Plan* (EMSI, 2020c) and are described below.

### 3.1 Drill Cuttings and Well Abandonment Wastes

No drill cuttings or well abandonment wastes were generated during the reporting period.

### 3.2 NTES Recovery Wastes

Non-liquid wastes were generated by activities at the NTES totaling less than one drum of non-liquid waste, personal protective equipment (PPE), absorbent pads, and paper. The partially filled drum of non-liquid waste is temporarily stored in a satellite accumulation area at the NTES.

No liquid skimming wastes were generated from the NTES during the reporting period. Partially filled drums of liquid waste are temporarily stored in satellite accumulation areas at the NTES and will be disposed when the drums are full.

Decontamination liquids and solids that originate from NTES activities are managed as a potentially hazardous substance. No decontamination liquids or solids were generated during the reporting period.

### 3.3 Treatment Plant Wastes

WTP waste typically consists of spent carbon, chemical precipitation sludge, general trash, and PPE.

Approximately 25 cy of dry chemical precipitation sludge was produced and placed into a lined roll-off box next to the WTP. Approximately 15 cy each of the sludge were disposed at DADS in August 2021 and November 2021 (Appendix B-1). The non-hazardous waste manifests for these shipments are presented in Appendix B-2.

Trash and PPE that were visually clean were managed as non-hazardous debris and accumulated in the roll-off adjacent to the WTP. No trash was disposed of during the reporting period.

### 3.4 Decontamination Pad Wastes

Approximately 564 gallons of decontamination liquids from the decontamination pad sump were transported to and pumped into the RWSTs for processing through the WTP. This liquid was generated by storm events and decontamination activities. No decontamination solids were generated or disposed during the reporting period.

### 3.5 Site Monitoring Waste

Purge liquids from groundwater sampling were transported to and pumped into the WTP wet well for processing through the WTP.

## 4.0 GROUNDWATER MONITORING

This section summarizes groundwater characterization, compliance, and effectiveness activities conducted during the second half of 2021.

### 4.1 Well Inspections, Maintenance, Installation and Development

Well inspections, maintenance, installation, and development activities performed during the reporting period are discussed below.

#### 4.1.1 Well Inspections and Maintenance

Well inspections are completed as a routine part of the monitoring program. The general condition of each well and any necessary repairs are recorded in a comment field on the water level measurement form and electronically transferred to a separate data table stored in the Site database. The following items were identified:

| Location | Comments | State of Repair |
|---|---|---|
| BM-4X-10S | Needs new pad - cracked, does not affect well integrity | New pad was installed on 9/22/2021 |
| MW38-100S-195W | Needs new outer flush mount casing | New pad and casing installed on 9/29/2021 |
| MW38-1100N-326E | Needs new outer flush mount casing | New pad installed on 9/29/2021 |
| MW38-1175N-300E | Needs new outer flush mount casing | New pad and casing installed on 9/21/2021 |
| MW38-200S-195W | Needs new outer flush mount casing | New casing installed on 9/21/2021 |
| MW38-275S-195W | Needs new outer flush mount casing | New pad installed on 9/21/2021 |
| MW38-325S-195W | Needs new outer flush mount casing | New casing installed on 9/21/2021 |
| MW38-400S-195W | Needs new outer flush mount casing | New casing installed on 9/29/2021 |
| MW38-840S-325E | Needs new pad due to landfill cover repairs in that area | Well pad replacement on hold, awaiting further precipitation before finalizing pad repair |
| MW38-995N-475E | Needs new outer flush mount casing | New sprinkler box and pad installed on 9/29/2021 |
| MW120-WD | Needs new pad - cracked, does not affect well integrity | New pad was installed on 9/22/2021 |
| MW135-WD | Loose pad, locking bolts stripped, needs new outer flush mount casing, well lid not lockable, locked at J plug | New pad and casing were installed on 9/15/2021 |
| MW136-WD | Loose pad, locking bolts stripped, needs new outer flush mount casing, well lid not lockable, locked at J plug | New pad and casing were installed on 9/20/2021 |
| MW137-WD | Locking bolts rusting, needs new outer flush mount casing | New bolts and threads were installed on 9/20/2021 |
| MW138-WD | Locking bolts rusting, needs new outer flush mount casing | New pad and casing were installed on 9/20/2021 |

| Location | Comments | State of Repair |
|---|---|---|
| MW139-WD | Locking bolts rusting, needs new outer flush mount casing | New bolts and threads were installed on 9/20/2021 |
| MW140-WD | Locking bolts rusting, needs new outer flush mount casing, well lid not lockable, locked at J plug | New pad and casing were installed on 9/20/2021 |
| MW141-WD | Locking bolts rusting, needs new outer flush mount casing and new pad (cracked), well lid not lockable, locked at J plug | New pad and casing were installed on 9/20/2021 |
| MW177-DEN | Needs new pad - Driven over and now cracked, does not affect well integrity | New pad installed on 9/22/2021 |
| NTES-EW-2 | Well needs repair as the well casing is settling into the ground and the well lid does not close anymore, removal of section of casing will be required, locked at J plug | To be repaired |
| PTP-26 | Bailer stuck in well, retrieval attempt recovered pipe nipple (bailer weight) | Not repairable but will continue use as quarterly water level measurement point |
| PZ-101A | Pad broken, does not affect well integrity | New pad installed on 9/22/2021 |

Labels were replaced on 51 wells. The labels on five more wells need replacing due to wearing. Well caps were replaced on seven wells with in-house inventory; five more wells still require new well caps. Due to schedule, inventory, and weather limitations some of these repairs were delayed and will be performed in the next reporting period.

### 4.1.2 Well Installation and Development

No new wells were installed, and no existing wells were abandoned during this reporting period, as indicated on Table 4.1.

## 4.2 Sitewide Groundwater Elevations

Groundwater elevations were measured in both the third and fourth quarters of 2021. Due to the number of water elevations recorded, Table 4.2 presents only one record for each location per quarter, with measurements taken in July and October 2021. Water level measurements were recorded on a PC tablet containing water level data from previous quarters. Data entry screens prompted the field technician to recheck the measurement if the reading was <0.25 or >0.25 ft from the previous quarter's measurement. Data from the tablet were then downloaded to a desktop computer and appended to the main database.

Hydrographs for the majority of the wells/piezometers in which water levels were gauged are presented in Appendix C-2. Due to the density of monitoring wells in the MW38 area, hydrographs were developed only for representative wells in that portion of the Site.

Discussion of potentiometric surfaces for the alluvium/weathered Dawson (WD), unweathered Dawson (UD), upper Denver, and lignite layer formations are presented in the following subsections. Lateral and vertical hydraulic gradients are also discussed (Subsection 4.2.5).

### 4.2.1 Alluvium/Weathered Dawson Formation Groundwater Elevations

The sitewide alluvium/weathered Dawson groundwater potentiometric surfaces for the third and fourth quarters of 2021 are shown on Figures 4.1 and 4.2, respectively. Groundwater at the Site occurs under water table conditions within the alluvial deposits along the Unnamed Creek drainage and within the weathered portion of the Dawson Formation (Fm.). Groundwater generally occurs at relatively shallow depths beneath drainages and at greater depths beneath topographic highs. The depth to groundwater in the alluvium and weathered Dawson ranges from approximately 2.2 ft below ground surface (bgs) in the detention basin along the T1 transect and MW132-WD in Section 31, to greater than 40 ft bgs along the unnamed creek drainage in the NBBW area (B-319), to approximately 62 ft bgs in the southwestern corner of the Site (RDPZ-102 area). The depth to groundwater has increased in areas of groundwater extraction such as the MW38 area where pumping in the MW38 sand channel has lowered the water table at the southern end of the sand channel (at pumping well MW38-170S-140W) by approximately 11.7 ft below the original static level, and by about 20 ft below the original water table at the northern sand-channel pumping well (MW38-1028N-256E). Continued groundwater extraction and cessation of potable water injection at the NBBW has contributed to declining groundwater elevations in the NBBW area as demonstrated by the absence of saturated weathered Dawson at B-305WD, B-307, B-311, B-312, B-318, B-319, B-319-25S, B-319-26W, B-319-50S, B-319-50W, B-319-75S, B-323-WD, GW-109, NBBW-IW-1, MW-1000, PTP-14, PTP-15, PTP-15S, PTP-16, PTP-17S, PTP-18, PTP-19, PTP-20, PTP-20S, PTP-22S, TR-1, and U-701-WD during this reporting period.

In general, groundwater associated with the alluvium and weathered Dawson moves from south to north beneath the Site (Figures 4.1 and 4.2). However, the direction of groundwater movement may deviate locally near drainages and ridgelines as a consequence of the movement of groundwater away from topographic ridges; convergent flow toward drainages; variations in stratigraphy such as depositional sand channels; and/or groundwater extraction and voluntary actions. Groundwater extraction from wells along the perimeter slurry wall (PM-11, PM-15, and MW51-WD areas), NTES, NBBW, and MW38 channel areas also influences local potentiometric surfaces as discussed in Subsections 4.5.1 through 4.5.4, respectively. Details of pumping from the MW38, PM-11, PM-15, and MW51-WD areas are also discussed in Subsection 4.6. Pumping for response actions in the North End, NBBW, and GTEP areas are discussed in Subsections 4.8. and 4.9.

In some instances, water level data from some wells were not used for potentiometric surface interpretations. For example, the water level for MW38-320N-305E was not used because the sandy zone in the screened interval is deeper and does not correlate to sandy zones screened in nearby wells. A similar situation occurs at MW38-1373N-180W. Cross Section H-H' in the *Final MW38 Area Pilot Test Report* (Parsons, 2005; Figure 2.10) shows there is no saturated weathered Dawson sand that correlates to the MW38 channel sand.

Overall, the lateral hydraulic gradient within the alluvium/weathered Dawson beneath the Site is approximately 0.021 foot per foot (ft/ft) directed generally to the north-northeast (between PM-8I and A-115 [change in head, $\Delta h$ = 119.69 ft; distance, d = 5580 ft] in October 2021). The depth to groundwater, groundwater flow directions, and lateral hydraulic gradients observed during this reporting period are similar to those recorded in previous reporting periods.

### 4.2.2 Unweathered Dawson Formation Groundwater Elevations

The sitewide unweathered Dawson groundwater potentiometric surfaces for the third and fourth quarters of 2021 are shown on Figures 4.3 and 4.4, respectively. The depth to the unweathered Dawson potentiometric surface ranges from approximately 16 ft bgs in the NBBW area (B-306) and along the unnamed creek drainage, to approximately 77 ft bgs in the MW38 area (MW38-410N-180W), to approximately 89 ft below the landfill mass (B-708). In general, the groundwater gradient associated with the unweathered Dawson trends from south-southwest to north-northeast beneath the Site. The lateral hydraulic gradient within the unweathered Dawson beneath the Site is approximately 0.017 ft/ft directed generally to the northeast (between PM-6X-UD and MW-EW-2LC [$\Delta h$ = 97.17 ft; d = 5,720 ft]) (using October 2021 water levels). The depths to groundwater, groundwater flow direction, and lateral hydraulic gradient observed during the second half of 2021 in the unweathered Dawson are similar to those recorded in previous reporting periods.

Examination of hydrographs (Appendix C-2) for several wells along the western boundary of the Site indicates groundwater levels that are not stable due to slow recovery since installation development or from sample purging. Similarly, the hydrograph for MW37-UD in the NBBW area (Appendix C-2) shows a steadily increasing trend through January 2020 from a sampling event that occurred in January 2005. Groundwater in the well now appears to be in equilibrium with the unweathered Dawson. This slow recovery is not uncommon for a well completed in claystone. In addition, well MW-1 shows a steadily increasing (rising) trend since 1982 probably due to the low hydraulic properties of the screened interval, while other wells (MW-2 and MW-3) show no trend. For these reasons, groundwater levels measured at MW-1 and MW-2 were not used to interpret the potentiometric surfaces shown on Figures 4.3 or 4.4, as noted on the figures. The groundwater elevation for MW-3 was honored for contouring but may not be completely representative due to long screen intervals.

Several well pairs exist with both wells screened in the unweathered Dawson. The water level in MW38-1064N-655E is utilized for the potentiometric surface, but the level in MW38-1064N-660E is not honored because the sand unit in the shallower well (MW38-1064N-655E) is more closely related stratigraphically to adjacent wells than the sand unit in the deeper MW38-1064N-660E well. The weathered and unweathered sand units in the MW38-1064N area are interpreted to be part of the west to east trending "C"-sand (see *Final Remedial Investigation Report for the Shallow Groundwater and Subsurface Liquids and Deep Groundwater Operable Units [Harding Lawson Associates, 1992]*; Section 4.3.2.2.1, Channel Deposits within the Dawson Formation, p. 4-28). The potentiometric "trough" trending east-northeast from MW38-410N-180W is interpreted to be a result of this stratigraphic condition. Similarly, wells B-712-UD and B-712-LD, situated near the east end of the NTES, are both completed in the unweathered Dawson. However, only B-712-UD was honored for contouring the unweathered potentiometric surface because it is screened in the uppermost sandstone unit of the unweathered Dawson, which is the criterion used for contour-well selection, whereas B-712-LD is screened in a lower portion of the unweathered Dawson.

### 4.2.3 Upper Denver Groundwater Elevations

Potentiometric data from monitoring wells screened in the upper Denver are shown on Figures 4.5 and 4.6 for the July and October 2021 measurements, respectively. It should

be recognized that the design criteria for constructing wells in the upper Denver was to set the screen in the first clean sand (i.e., minimal fines) below the clay separation unit. Because of geologic heterogeneity, the screen intervals are not always completed at the same stratigraphic level. As a result, the potentiometric contours shown on Figures 4.5 and 4.6 should be considered approximate, as variations in the elevations of screen intervals (shown on the figures) can introduce potentiometric variability. Stabilized water levels from the second half of 2021 are consistent with those measured in previous reporting periods.

The potentiometric level in monitoring well MW112-DEN, located in the southwest corner of the Site, has been slowly rising, consistent with the rest of the Denver Basin, since its installation in June 2005. However, interpretation of the potentiometric levels continues to suggest a northeast trending potentiometric trough. This well is screened in a thick, coarse-grained, porous sand unit. The hydraulic gradient along the trough is relatively flat (0.0046 ft/ft between MW112-DEN and MW71-DENR [$\Delta h$ = 27.72 ft; d = 5,975 ft]) (using October 2021 water levels).

### 4.2.4 Lignite Layer Groundwater Elevations

Figures 4.7 and 4.8 show the locations of the 12 wells completed in the Lignite layer and their potentiometric levels for July and October 2021, respectively. The levels indicate that the potentiometric surface is nearly flat with a very low hydraulic gradient of 0.00133 ft/ft between B-506 and MW71-LIG ($\Delta h$ = 6.85 ft; d = 5,160 ft) (using October 2021 water levels) to the east-northeast, similar to previous reporting periods. Hydrographs of lignite wells GW-120, GW-121, GW-122, and C-702Q1 (Appendix C-2) installed at least 15 years ago indicate that the potentiometric surface of the lignite layer had gradually and steadily dropped 13 to 22 ft, until mid-2006 when the levels stabilized or even rebounded by approximately one to two feet.

Unlike the Upper Denver, the elevation and stratigraphy of the lignite layer is fairly consistent and predictable across the Site. Except for B-506, all lignite wells are screened across the full saturated thickness of this layer. Monitoring well B-506, located hydraulically upgradient southwest of the Site, has a 40-foot screen that spans the lignite layer and the underlying shale and sandstones of the Lower Denver hydrostratigraphic unit. Consequently, the potentiometric data from this well should be used with caution. Nonetheless, taken as a whole, the potentiometric contours illustrated on Figures 4.7 and 4.8 may be viewed with a relatively high degree of confidence.

### 4.2.5 Vertical Hydraulic Gradients

Vertical hydraulic gradients between the weathered and unweathered Dawson hydrostratigraphic units were calculated by dividing the head difference between the midpoints of the saturated well screens associated with weathered and unweathered Dawson well pairs. To the extent that they are available, measured water levels and calculated vertical gradients are summarized in Table 4.3.

Upward hydraulic gradients, indicated by positive values (pink highlight) on Table 4.3, occur in 30.4% of the well pairs (not including well pairs where the WD was dry) during the fourth quarter 2021.

Areas of upward potential occur around the NBBW groundwater extraction trench and the GTEP extraction well where groundwater is extracted from the weathered Dawson. Other areas with upward gradients are in the vicinity of the PM-15 and MW51 pumping

systems where groundwater extraction has lowered the weathered Dawson potentiometric surface. Downward potential occurs along the MW38 sand channel.

The upward and downward vertical gradient directions observed during the second half of 2021 are generally consistent with those previously observed. However, as extraction from the NBBW and GTEP areas continue, additional wells in these areas may become dry.

## 4.3 Groundwater Sampling

Table 4.4 and Figures 4.9 and 4.10 present the 75 compliance, North End Monitoring, effectiveness, and investigation monitoring wells and 122 samples collected during the reporting period. One sample was from an upper Denver well, 111 samples were from weathered Dawson wells, and 9 samples were from unweathered Dawson wells with one sample from an unweathered Denver well. Table 4.4 presents the wells sampled during the reporting period and their classifications, i.e., compliance (18 wells), compliance/effectiveness (8 wells), effectiveness (5 wells), North End Monitoring (34 wells), and investigation (10 wells). Water bearing units, sampling dates, and frequency of sampling are also included in the table. The table also shows sampling scheduled for the next two quarters in conformance with the updated GWMP and North End GWMP. Table 4.5 presents a summary of detected constituents at each location.

### 4.3.1 Laboratory Analyses

Analyte lists for groundwater compliance and performance monitoring are presented below.

| Classification | Analytical Methods | Analytes |
|---|---|---|
| Compliance, Vertical Migration, and NTES, NBBW & MW38 Effectiveness | 8260B<br>8260SIM<br>6010B<br>300.0A | (25) VOCs<br>1,4-Dioxane<br>(2) Dissolved metals<br>Nitrate and Nitrite |
| Perimeter Effectiveness | 8260B<br>8260SIM | (4) VOCs<br>1,4-Dioxane |
| North End Monitoring/Investigation | 8260SIM | 1,4-Dioxane |
| MW77 Response Action | 8260B<br>8260SIM<br>300.0A | 1,1-DCE (VOCs)<br>1,4-Dioxane<br>Nitrate |
| B-313/B-326-UD Response Action | 8260SIM<br>300.0A | 1,4-Dioxane<br>Nitrate |
| NBBW-IW-3 Response Action | 8260SIM<br>6010B | 1,4-Dioxane<br>Molybdenum |

Indicator chemicals for the compliance wells are listed below:

- 1,1,1-Trichloroethane
- 1,1,2,2-Tetrachloroethane
- 1,1,2-Trichloroethane
- 1,1-Dichloroethane
- 1,1-Dichloroethene
- 1,2-Dichloroethane
- Chlorobenzene
- Chloroform
- cis-1,2-Dichloroethene
- Dibromochloromethane
- Ethylbenzene
- Methylene Chloride

- 1,2-Dichloropropane
- 1,4-Dioxane
- Acetone
- Arsenic
- Benzene
- Bromodichloromethane
- Bromoform
- Cadmium
- Carbon Tetrachloride
- Naphthalene
- Nitrogen, Nitrate
- Nitrogen, Nitrite
- Tetrachloroethene
- Toluene
- Trans-1,2-Dichloroethene
- Trichloroethene
- Vinyl Chloride

Perimeter effectiveness wells are sampled for 1,1,1-trichloroethane (TCA), 1,1-DCA, trichloroethene (TCE), and tetrachloroethene (PCE) plus low-level 1,4-dioxane. Wells in the NBBW, NTES and MW38 areas are being sampled for all the compliance analytes listed above in the event that indicator chemicals for effectiveness need to be determined.

Sample and data tracking information including the dates of sample collection, sample delivery group (SDG) number, laboratory, and validation reference, are summarized in Appendix F-1. Analytical data packages and DVRs for the reporting period are presented in Appendix F-2. The DQA report is presented in Appendix F-3. The analytical database is presented in Appendix G.

### 4.3.2 Data Validation

Validation results are presented in the DQA report in Appendix F-3. Data quality was acceptable, and no major issues were encountered except for holding time violations for nitrate.

## 4.4 Compliance Evaluation

This subsection presents an assessment of compliance with groundwater performance standards along the point of compliance (POC). Sixty monitoring wells are included in the compliance monitoring network (EMSI/Parsons, 2018). Compliance evaluations are performed using the procedures set forth in Appendix C of the updated GWMP (EMSI/Parsons, 2018).

### 4.4.1 Procedures Used to Assess Compliance

Compliance with groundwater performance standards is assessed at each compliance well for each chemical identified in the updated GWMP as an "indicator of compliance" (listed in Section 4.3.1). Evaluation of compliance at a well is performed by comparing the 90% upper confidence limit (UCL) and, if necessary, the 90% lower confidence limit (LCL) of the chemical concentration in groundwater to its performance standard. A well is statistically in compliance if the 90% UCL is less than its performance standard and a well is out of compliance if the 90% LCL is greater than its performance standard. If the performance standard lies within the confidence interval (i.e., between the UCL and LCL), it is unknown whether the well is in or out of compliance. In some cases (i.e., where a trend is present in the data), a determination may be made as to potentially in or out of compliance based on empirical evidence such as concentration and trend (see Step 9 of Section 7.3.1 of the revised GWMP (EMSI/Parsons, 2018).

The data evaluation procedures consist of a number of statistical tests (Mann-Kendall [M-K] trend analysis, outlier test, goodness-of-fit test, regression analysis, and calculation of UCLs) which are performed using USEPA's ProUCL software package (version 5.1) or manually in the case of regression analysis. In order to minimize the impact of potential

temporal trends, calculation of the 90% LCL and 90% UCL is based on the results of the ten most recent sampling events (with the additional caveat that only samples obtained no more frequently than quarterly intervals will be considered in the identification of the ten most recent sample results). The UCL and LCL are then used to evaluate compliance with the groundwater performance standards. The data evaluation procedures described in the updated GWMP (EMSI/Parsons, 2018) result in calculation of long term (ten most recent events) average concentrations as well as the upper and lower confidence limits. A summary of the data used for the evaluation procedures is presented in Appendix C-3.1.

The sampling results for each compliance monitoring well for each indicator chemical with a reported result greater than the performance standard are analyzed using the M-K test for the presence of temporal trends. If no trend is present, the UCL and mean are determined using the ProUCL software. If an increasing or decreasing trend is determined to be present, compliance is evaluated using linear regression to estimate the mean value and the 90% upper and lower confidence levels for the most recent sample date. This result is a mean value for the most recent sampling date and is not the same as, and should not be confused with, an overall arithmetic or geometric mean of all sampling results.

At least four sample results are necessary to evaluate the long-term average, UCL, and LCL concentrations in a well relative to performance standards. At least four samples have been collected from each well and analyzed for all the 29 indicator chemicals of compliance.

### 4.4.2 Results of Compliance Evaluations

Tabular and graphical summaries of the results of the compliance monitoring evaluations are presented in Table 4.6 and on Figure 4.11, respectively. Complete copies of the results of the statistical evaluations are contained in Appendix C-3.

Based on the statistical tests, water quality for one or more compliance monitoring parameters at six of the 60 compliance monitoring locations exceeded performance standards (Table 4.6). The locations and the parameters found to exceed performance standards consist of the following:

| Well | Compound |
|---|---|
| **B-313** | Nitrate |
| B-313 | 1,4-Dioxane |
| B-326-UD | 1,4-Dioxane |
| B-326-WD | 1,4-Dioxane |
| BM-11X-100N | Tetrachloroethene |
| MW62-WDR | 1,4-Dioxane |
| MW62-WDR | Nitrate |
| MW77-WD | 1,4-Dioxane |

Statistically-based compliance determinations could not be made for some indicator chemicals in the following monitoring wells although subjective determinations may be possible, and are discussed below:

| Well | Compound |
|---|---|
| B-326-UD | Nitrate |
| BM-11X-100N | Trichloroethene |
| BM-15N6 | Nitrate |
| GW-109 | 1,4-Dioxane |

| Well | Compound |
|---|---|
| GW-109 | Chloroform |
| GW-109 | Bromodichloromethane |
| MW23-C-SD | 1,4-Dioxane |
| MW38-830N-230E | 1,4-Dioxane |
| MW38-830N-230E | Chloroform |
| MW62-WDR | Nitrite |
| MW106-UD | 1,4-Dioxane |

**B-326-UD Nitrate**: A statistically-based compliance determination could not be made for nitrate in B-326-UD because the data displayed a decreasing trend and the requirements for use of linear regression to estimate the confidence limits were not met. Procedures to be used when this condition occurs are included in Step 9 of Section 7.3.1 of the updated GWMP (EMSI/Parsons, 2018). B-326-UD is considered to be potentially in compliance for nitrate because it had a decreasing trend and the last six results were less than the performance standard (28,000 µg/L) including the last two samples that did not contain detectable levels of nitrate. WSDs will continue monitoring at B-326-UD and attempt to determine compliance for this constituent.

**BM-11X-100N TCE:** A statistically-based compliance determination could not be made for TCE in BM-11X-100N because the groundwater performance standard for this chemical (5 µg/L) falls between the 90% UCL and the 90% LCL values. As per Step 8, Section 7.3.1 of the GWMP, no conclusion can be reached regarding compliance with the groundwater performance standard because the ten most recent results, which range from 3.6 to 5.7 µg/L, are all very near the groundwater performance standard (5 µg/L). WSDs will continue monitoring at BM-11X-100N and attempt to determine compliance for this constituent.

**BM-15N6 Nitrate:** A statistically-based compliance determination could not be made for nitrate in BM-15N6 because the data displayed a decreasing trend and the requirements for use of linear regression to estimate the confidence limits were not met. Procedures to be used when this condition occurs are included in Step 9 of Section 7.3.1 of the updated GWMP (EMSI/Parsons, 2018). BM-15N6 is considered to be potentially out of compliance for nitrate because all results were greater than the performance standard (28000 µg/L). The last statistically-based compliance determination (second half 2020) determined that nitrate was out of compliance in this well. WSDs will continue monitoring at BM-15N6 and attempt to determine compliance for this constituent.

**GW-109 1,4-Dioxane**: The water levels in this well have dropped to the point that there was not enough water available to collect a sample from this well since 6/1/20. Consequently, a formal statistical-based compliance determination could not be made; however, because the measured water level is below the base of the screened interval, the well is considered to be dry and GW-109 is considered to be in compliance. Previous determinations in this well indicated that 1,4-dioxane was indeterminant with a high degree of variability in the 1,4-dioxane results. The most recent concentrations in this well (41 µg/L, 3/2/20 and 20 µg/L, 6/1/20), may be caused by variations in groundwater levels and/or flow directions in the vicinity of this well resulting from historical cessation of potable water injection and historical or ongoing changes in pumping rates in nearby

extraction wells affecting the data set. WSDs will continue monitoring at GW-109 and attempt to determine compliance for this constituent.

**GW-109 Chloroform and Bromodichloromethane**: As stated above the water levels in this well have dropped to the point that there was not enough water available to collect a sample from this well since 6/1/20. Consequently, a formal statistical-based compliance determination could not be made; however, because the measured water level is below the base of the screened interval, the well is considered to be dry and GW-109 is considered to be in compliance. Furthermore, the last time that these parameters were detected at levels above their respective performance standards (1.0 µg/L for bromodichloromethane and 3.5 µg/L for chloroform) was November 2015. In addition, the eight most recent results for bromodichloromethane and the seven most recent results for chloroform were not detected in this well. WSDs will continue monitoring at GW-109 and continue to evaluate this wells compliance with the performance standards

**MW23-C-SD 1,4-Dioxane:** A compliance determination could not be made for 1,4-dioxane in MW23-C-SD because 90% of the results were not detected. The single detected value of 1.4 µg/L (9/15/20) is an outlier, but data validation could not find a reason to exclude this value from the statistics. If the outlier value is removed and replaced with an earlier value (0.5 U, 9/15/05) to have ten results, all ten results are not detected; therefore, the well would be in compliance with the performance standard for 1,4-dioxane. A confirmation sample was collected in 1$^{st}$ quarter 2021 that did not contain a detectable level of 1,4-dioxane (MDL = 0.09 µg/L). Although formal statistical testing could not be performed, this well is considered to be potentially in compliance with the 1,4-dioxane standard based on the preponderance of non-detect results from this well and because the single detect was not confirmed by a sample collected in first quarter 2021 (0.9 U µg/L).

**MW38-830N-230E 1,4-Dioxane**: A statistically-based compliance determination could not be made for 1,4-dioxane in MW38-830N-230E because the data displayed a decreasing trend and the requirements for use of linear regression to estimate the confidence limits were not met. Procedures to be used when this condition occurs are included in Step 9 of Section 7.3.1 of the updated GWMP (EMSI/Parsons, 2018). MW38-830N-230E is considered to be potentially out of compliance for 1,4-dioxane because all results were greater than the performance standard (0.9 µg/L). The last statistically-based compliance determination (first half 2020) determined that 1,4-dioxane was out of compliance in this well. WSDs will continue monitoring at MW38-830N-230E and attempt to determine its statistical compliance, but for practical purposes, this well is considered to be potentially out of compliance.

**MW38-830N-230E Chloroform:** A statistically-based compliance determination could not be made for chloroform in MW38-830N-230E because the data displayed a decreasing trend and the requirements for use of linear regression to estimate the confidence limits were not met. Procedures to be used when this condition occurs are included in Step 9 of Section 7.3.1 of the updated GWMP (EMSI/Parsons, 2018). MW38-830N-230E is considered to be potentially out of compliance for chloroform because, although it had a decreasing trend, seven of ten results were greater than the performance standard (3.5 µg/L) including the last two samples. The last statistically-based compliance determination (second half 2020) determined that chloroform was out of compliance in this

well. WSDs will continue monitoring at MW38-830N-230E and attempt to determine its statistical compliance, but for practical purposes, this well is considered to be potentially out of compliance.

**MW62-WDR Nitrite**: A statistically-based compliance determination could not be made for nitrite in MW62-WDR because the data displayed a decreasing trend and the requirements for use of linear regression to estimate the confidence limits were not met. Procedures to be used when this condition occurs are included in Step 9 of Section 7.3.1 of the updated GWMP (EMSI/Parsons, 2018). Although the results displayed a decreasing trend, MW62-WDR is considered to be potentially out of compliance for nitrite because eight of 10 results were greater than the performance standard (1000 µg/L). The high degree of variability in the nitrite results for well MW62-WDR, which range from not detected to 5,400 µg/L, may be caused by variations in groundwater levels and/or flow directions in the vicinity of this well resulting from percolation of precipitation through the shallow layer of nitrite impacted soils, historical cessation of potable water injection, and changes in pumping rates in nearby extraction wells. WSDs will continue monitoring at MW62-WDR and attempt to determine compliance for this constituent, but for practical purposes, this well is considered to be potentially out of compliance.

**MW106-UD 1,4-Dioxane**: A statistically-based compliance determination could not be made for 1,4-dioxane in MW106-UD because 90% of the results were not detected. The single detected value of 6.5 µg/L (2/28/07) is an outlier, but data validation could not find a reason to exclude this value from the statistics. If the outlier value is removed and replaced with an earlier value (0.5 U, 7/21/06) to have ten results, all ten results are not detected; therefore, the well would be in compliance with the performance standard for 1,4-dioxane. Although formal statistical testing could not be performed, this well is considered to be potentially in compliance with the 1,4-dioxane standard based on the preponderance of non-detect results from this well.

The eight wells determined to be statistically out of compliance or potentially out of compliance are summarized below. Recommendations relative to non-compliance with performance standards at these locations follow the summary.

| Well | Compound | Compliance Decision | Trend |
|---|---|---|---|
| B-313 | 1,4-Dioxane | Out of compliance | No trend |
| B-313 | Nitrate | Out of compliance | No trend |
| B-326-UD | 1,4-Dioxane | Out of compliance | Decreasing |
| B-326-WD | 1,4-Dioxane | Out of compliance | No trend |
| BM-11X-100N | PCE | Out of compliance | No trend |
| BM-15N6 | Nitrate | Potentially Out of compliance | Decreasing |
| MW38-830N-230E | 1,4-Dioxane | Potentially Out of compliance | Decreasing |
| MW38-830N-230E | Chloroform | Potentially Out of compliance | Decreasing |
| MW62-WDR | 1,4-Dioxane | Out of compliance | Decreasing |
| MW62-WDR | Nitrate | Out of compliance | No trend |
| MW62-WDR | Nitrite | Potentially Out of compliance | Decreasing |
| MW77-WD | 1,4-Dioxane | Out of compliance | No trend |

The above compliance determination summary list is the same as that from the first half of 2021, with exception of three wells: well B-313 nitrate was previously indeterminant

and is now out of compliance; BM-11X-100N tetrachloroethene was previously potentially out of compliance and is now out of compliance; well MW62-WDR, which was potentially out of compliance but is now determined to be out of compliance for 1,4-dioxane. Also note that MW74-WD and BM-15E2 nitrate are now in compliance because the last ten sample results were less than the performance standard (28000 µg/L). Wells can change their compliance determination from one reporting period to the next because the 10 most-recent sample dataset moves over time and new data are always being incorporated. If the data are trending or fluctuating over time as some of these wells are, the compliance statistics will also change.

Based on the current findings, the necessity and scope of potential corrective actions for the eight monitoring locations identified above are assessed below in accordance with the procedures established in the updated GWMP.

#### 4.4.2.1 1,4-Dioxane in the NBBW Area

Based on the results of the statistical tests, 1,4-dioxane occurs in excess or potentially in excess of its performance standard in five NBBW-area compliance monitoring wells (B-313, B-326-UD, B-326-WD, MW62-WDR, and MW77-WD) (Figure 4.11).

In accordance with the Response Action Work Plan (RAWP) in the B-326-UD and B-313 areas (EMSI, 2013), the WSDs initiated groundwater extraction from well B-321 in the area of compliance well B-313 in June 2013 to address occurrences of nitrate and 1,4-dioxane in well B-313. The concentration of 1,4-dioxane at compliance well B-313 was 39 µg/L on May 7, 2013, before the response action began. The most recent (November 2021) 1,4-dioxane concentration in this well was 17 µg/L.

With regard to B-326-UD, groundwater extraction has been ongoing from nearby unweathered Dawson well MW113-UD since July 11, 2013 in accordance with the same RAWP. Groundwater extraction at MW113-UD along with groundwater extraction from adjacent weathered zone wells MW113-WD and MW113-EW-1 which began in 2007, resulted in a long-term downward trend in the water level in B-326-UD over the period from 2007 through 2018. Cessation of potable water injection in October 2018, resulted in a further significant decline in water levels in this well (approximately 21 feet between October 2018 through October 2021) and development of a steep cone of depression in the unweathered zone potentiometric surface around the MW113-UD extraction well and B-326-UD (see Figure 4.23). During this same timeframe (October 2018 through October 2021), concentrations of 1,4-dioxane increased slightly to 7.7 µg/L (2/12/20) then declined to 5 µg/L (10/12/21). Relationships between the groundwater level declines and 1,4-dioxane concentration changes were addressed in the Revised Final Cessation Report (EMSI/CDM-Smith, 2020a).

The presence of 1,4-dioxane in B-326-WD at concentrations greater than the groundwater performance standard was the basis for previous determinations that a Case 3 condition (the presence of an out-of-compliance condition with the potential for migration beyond the site boundary) exists in this area. To address this condition, the WSDs have been extracting groundwater from MW113-EW-1 (alluvial/weathered Dawson groundwater) and MW113-UD (unweathered Dawson groundwater) in accordance with USEPA-approved work plans.

The table below shows the changing concentrations of 1,4-dioxane in B-326-WD. These changes of 1,4-dioxane in B-326-WD most likely reflect the effects of cessation and extraction at nearby wells.

| Well | Date | Conc (µg/L) |
|---|---|---|
| B-326-WD | 8/26/2019 | 10 |
| B-326-WD | 12/11/2019 | 8.8 |
| B-326-WD | 2/12/2020 | 10 |
| B-326-WD | 5/28/2020 | 11 |
| B-326-WD | 8/26/2020 | 3.5 |
| B-326-WD | 11/23/2020 | 3.9 |
| B-326-WD | 2/3/2021 | 17 |
| B-326-WD | 6/1/2021 | 7.5 |
| B-326-WD | 8/30/21 | 0.77 J |
| B-326-WD | 10/12/21 | 1.0 |

The changing concentrations of 1,4-dioxane in B-326-WD are believed to be affected by changes in groundwater extraction in nearby MW113-EW-1. With the continued absence of injection water, presumably this extraction well is pulling water from a different area when pumping, likely from the east, which contains lower levels of 1,4-dioxane. When extraction from MW113-EW-1 was temporarily suspended on November 4, 2020 and restarted on January 27, 2021 to allow for treatment of water contained in temporary storage tanks, 1,4-dioxane concentration in B-326-WD increased to 17 µg/L on February 3, 2021. This may be the result of less flushing of residual 1,4-dioxane contained in the capillary fringe/vadose zone. After extraction of MW113-EW-1 resumed (March 11, 2021), the 1,4-dioxane concentration in B-326-WD dropped to below the performance standard (0.9 µg/L) in August 2021 (0.77 µg/L). The latest sampling result (October 2021) was slightly above the performance standard at 1 µg/L.

Like B-326-UD, relationships between the groundwater level declines and changes in 1,4-dioxane concentrations in well B-326-WD were addressed in the Revised Final Cessation Report (EMSI/CDM-Smith, 2020a). The WSDs will continue to monitor both the 1,4-dioxane concentrations and the water level in these wells and continue to evaluate conditions in this area.

With regard to MW62-WDR and MW77-WD, a Case 3 condition exists in the vicinity of these wells. WSDs have implemented four RAWPs (EMSI, 2006a, 2007c, 2008b, and 2010a) to reduce the levels of 1,4-dioxane in these areas and are currently implementing the *Response Action Work Plan to Extract Additional Groundwater from Upgradient of MW77-WD* (EMSI, 2011) to bring these wells into compliance. Visually declining trends in 1,4-dioxane, 1,1-DCE, and nitrate are apparent in compliance well MW77-WD since the start of response action implementation in 2008. 1,4-Dioxane has decreased from 120 µg/L in May 2008 to 11 µg/L in October 2021. Similar trends are apparent for nitrate (160,000 µg/L to 12,000 µg/L) and 1,1-DCE (22 µg/L to 1.7 µg/L) for the same sampling dates.

In MW62-WDR, 1,4-dioxane is out of compliance and exceeds the performance standard in all of the ten most recent samples (3.2 µg/L to 4.6 µg/L) with a decreasing trend. Although the trend is decreasing, the slow decline indicates that 1,4-dioxane will potentially continue to be out of compliance in this area. The well lies within the zone of containment caused by groundwater extraction from the NBBW and Response Actions

north and east of the NBBW (see Figures 4.16 and 4.17). Consequently, the exceedances may be a Case 2 condition, which require only long-term monitoring. As required by the Fourth Five-Year Review Report (5YRR) (USEPA, 2017), the WSDs conducted additional evaluations of the effectiveness of the NBBW containment system and the Response Actions in the NBBW area as part of the NBBW Containment System Evaluation (CSE) Plan (EMSI/CDM/Parsons, 2019). That evaluation (EMSI/CDM/Parsons, 2021) determined that the NBBW effectively contains flow of contaminated groundwater within the alluvium/weathered bedrock groundwater unit. Any residual 1,4-dioxane remaining north of the containment zone will be captured by ongoing Response Action pumping north of the containment zone.

#### 4.4.2.2 Nitrate and Nitrite in the NBBW Area

Nitrate is out of compliance in monitoring wells B-313 and MW62-WDR (Figure 4.11). Nitrite is potentially out of compliance in well MW62-WDR. These wells are located along the northern boundary of the Site, in an area where sewage sludge was historically land farmed. Statistical testing of potential temporal trends in the results (Appendix C-3.2) indicates that there is no trend in the nitrate concentrations in B-313 and MW62-WDR and a decreasing trend in nitrite concentrations in MW62-WDR. Based on the decision rules established in the GWMP, occurrences of nitrate and nitrite in these wells may be classified as a Case 3 condition. As discussed below and in Subsection 4.9, response actions are being implemented in this area. Other wells located in Section 31 north of the NBBW area were previously sampled in 2006 and analyzed for nitrate, nitrite, and VOCs. These compounds were not detected at concentrations greater than performance standards in any of the wells located along unnamed creek, immediately upgradient of the confluence with Murphy Creek (MW115-WD, MW116-WD, MW117-WD, MW118-WD, MW119-WD, and MW120-WD), or in any of the DADS wells located along unnamed creek or Murphy Creek (MW02-AD, MW05-WD, MW07-AD, MW08-WD, MW09-WD, and MW80-WD). Wells located south of the Yale Avenue extension along the northern boundary of Section 31 (MW121-WDR, MW122-WDR, MW123-WD, MW124-WD, MW125-WD, MW126-WD, MW127-WD, MW129-WD, MW130-WD and MW131-WD) were sampled for VOCs and nitrate in 2006 and were resampled in 2016 as part of the *Work Plan to Sample North End Wells, Piezometers and Surface Water* (EMSI, 2016) or *Work Plan for 3DVA Synoptic Sampling Event* (EMSI, 2018b, as amended in EMSI, 2018c), and again no nitrate, nitrite, or VOCs were detected above performance standards in any of these wells. Based on these results, the extent of nitrate and nitrite exceedances has been determined to be limited to the area immediately to the north of the NBBW (i.e., in the immediate vicinity of compliance monitoring wells B-313 and MW62-WDR. Based on the results of the prior sampling and the limited area of nitrate exceedance, there does not appear to be a potential for significant off-Site migration of nitrate or nitrite at concentrations greater than the performance standard.

As discussed above, the WSDs prepared, implemented, and updated various RAWPs to address 1,4-dioxane occurrences east and downgradient of the NBBW. To the extent that the nitrate and nitrite occurrences do not result from a source in the immediate vicinity of these wells (i.e., impacts from prior land farming of sewage sludge in this area), implementation of response actions for 1,4-dioxane should also address nitrate occurrences in these areas. To the extent that the cause of the nitrate and nitrite occurrences in these wells is due to impacts from prior land farming of sewage sludge in this area, the response actions being undertaken in this area may or may not reduce their concentrations in

groundwater. Nonetheless, groundwater extraction from North End wells further downgradient should capture any potential migration of nitrate and nitrite from the NBBW area if northern migration were to occur.

#### 4.4.2.3 Chloroform and 1,4-Dioxane MW38-830N-230E

Chloroform and 1,4-dioxane concentrations in monitoring well MW38-830N-230E potentially exceed the groundwater performance standard. Decreasing trends in the concentrations of these chemicals were identified in this well. This well is located along the POC at the north end of the MW38 channel. The hydraulic gradient within the channel at this location is to the north so migration of these chemicals crosses the POC. As part of the groundwater containment remedy for the Site, groundwater extraction is conducted from the MW38 channel at two locations, including a location approximately 200 ft north of well MW38-830N-230E, which is downgradient from and beyond the POC relative to the compliance monitoring well. Therefore, although chloroform or 1,4-dioxane may migrate across the POC, impacted groundwater is hydraulically contained within, and removed from, the sand channel in the area immediately north of well MW38-830N-230E as depicted on Figures 4-24 and 4-25. Consequently, no action other than continued extraction from the MW38 channel and monitoring of the compliance well is required for these occurrences.

#### 4.4.2.4 Nitrate in BM-15N6

Nitrate occurs in well BM-15N6 at concentrations greater than its performance standard. Statistical testing of potential temporal trends (Appendix C-3.2) indicates that there is a decreasing trend in nitrate concentrations in well BM-15N6. Each of the last 10 results for nitrate in this well are above the performance standard (28,000 µg/L). Therefore, although the trend is decreasing, the compound is considered potentially out of compliance in this well.

This well is located in an area where sewage sludge had historically been land-farmed. USEPA positioned the compliance boundary within the land farming area such that it straddles the land farming area. That, coupled with an absence of 1,4-dioxane and only low-level detections of VOCs below performance standards since 2003 in this well, would indicate the source of nitrates is not from landfill mass or waste pit contaminant migration; rather, it is likely from the past land farming activities inside and outside the compliance boundary. Groundwater sampling conducted in June 2017 and October 2018 indicated that nitrate has been observed in surrounding wells BM-15N2 (43,000 µg/L), BM-15NE1 (26,000 µg/L), BM-15N5 (68,000 µg/L), BM-15N1 (25,000 µg/L), BM-15I-15N (54,000 µg/L), BM-15I-50S (9,300 µg/L), and BM-15X-50S (38,000 µg/L).

The spatial randomness of nitrate detections in and around well BM-15N6 as compared to other compliance wells in this vicinity is similar to that observed near the NBBW where sewage sludge was land farmed. The randomness is likely attributable to a number of hydrogeochemical variables associated with the leaching, transport, and attenuation of nitrates that can differ significantly from location to location. Nitrate concentrations can also fluctuate with precipitation and rate of groundwater pumping from the PM-15 Area wells.

Because 1) the source of the nitrate in well BM-15N6 is most likely a result of sewage sludge land farming in this area, 2) the presence of active groundwater extraction in this area, and 3) the distance between this well and the Site boundary is approximately 200 feet,

(see Figure 4.11), the occurrence of nitrate in well BM-15N6 is considered to be a Case 2 condition as defined in the GWMP (EMSI/Parsons, 2018). Consequently, no action other than continued groundwater monitoring is recommended.

#### 4.4.2.5 BM-11X-100N Tetrachloroethene

PCE in BM-11X-100N is out of compliance with an no statistical trend. The ten most recent PCE concentrations in this well range from 4.6 µg/L to 7.2 µg/L with the most recent sample containing a PCE concentration of 5.4 µg/L (October 28, 2021). PCE levels appeared to slowly increase from October 2017 to November 2020 but have dropped in the last two sampling events. The variation in PCE concentrations appears to be related to changes in the water level in this well. Prior to the summer of 2015, the water level in this well was relatively stable ranging from approximately 5,790 to 5,795 ft amsl. Beginning in the summer of 2015, the water level in this well increased, peaking at a high of just over 5,800 ft amsl in July 2017. Since that time, the water level in this well has declined back below 5,792 ft amsl. Consequently, it is likely that the increase in PCE levels in this well may be the result of flushing of residual PCE contained in the capillary fringe/vadose zone. If this is the case, then the PCE level in this well should decline over time which has been observed in the most recent PCE results (7.2 µg/L in November 2020 to 5.4 µg/L in October 2021). The well is located outside of the perimeter slurry wall in an area where the hydraulic gradient across the slurry wall is inward due to groundwater extraction along the interior of the slurry wall, but with increasing distance away from the slurry wall the hydraulic gradient becomes outward to the northeast toward the Site boundary (Figures 4.1 and 4.2). Well MW50-WD, a weathered Dawson well positioned approximately 150 ft north of well BM-11X-150N and outside the slurry wall, has never contained PCE at concentrations above the method detection limit. Similarly, wells located further to the north and northeast have always been in compliance with the PCE groundwater performance standard (see Figure 4.11). The overall low concentration of PCE in well BM-11X-100N, in addition to an inward gradient across the wall at this location, and no or very low PCE detections in groundwater to the north and northeast of the well indicate that the PCE occurrences in this area represent a Case 2 condition (little or no downward trend with a low potential for off-Site migration) as defined in the GWMP (EMSI/Parsons, 2018). The WSDs previously completed a Case 2 evaluation for this well (EMSI, 2006b). Results indicated that it is unlikely that the PCE occurrences above the performance standard in this area will migrate to the Site boundary. Rather, PCE occurrences in this area will likely attenuate naturally over time. Consequently, the recommended action is to continue monitoring.

## 4.5 Effectiveness Evaluation

Four components of the groundwater containment remedy (perimeter slurry wall, NTES, NBBW, and MW38 channel) are intended to provide hydraulic control and contaminant containment in the shallow (alluvium/weathered Dawson) groundwater at the Site. The effectiveness of these features is demonstrated either by hydraulic (water level) monitoring or water quality monitoring, in accordance with Sections 3.2, 4.2, 5.2, and 7.3 of the Revised GWMP (EMSI/Parsons, 2018). The effectiveness of these remedial components was assessed in detail in 2021 and continues to be monitored regularly (EMSI/Parsons, 2021a and b). The four components are discussed below.

### 4.5.1 Perimeter Slurry Wall

The primary criterion for assessment of the effectiveness of the perimeter slurry wall is the presence of an inward hydraulic gradient across the slurry wall. In the event an outward hydraulic gradient is determined to be present at a particular location along the wall, water quality data obtained from outside the wall are used to assess the effectiveness of the slurry wall at containing Site contaminants.

The presence of an inward hydraulic gradient is determined by reviewing the water level measurements from the weathered Dawson wells located in a paired configuration inside and outside of the perimeter slurry wall. Fifteen well pairs (PM-1 through PM-15) are used for this assessment. Results of the evaluations of the hydraulic gradients across the perimeter slurry wall are summarized in Table 4.7. Hydrographs for the fifteen well pairs are presented on Figure 4.12. A complete set of hydrographs along with results of statistical testing of the water level data are presented in Appendix C-4.1.

Water level data indicate the presence of inward hydraulic gradients across the perimeter slurry wall at eleven of the fifteen well pairs. Outward hydraulic gradients exist across the slurry wall along the southern part of the western portion of the wall in the PM-3 and PM-6 areas and along the northern part of the eastern portion of the slurry wall in the PM-14 area. The gradient calculation for the PM-13 well pair could not be performed because PM-13I was dry, likely due to purging associated with attempts to sample this well. This well was part of the 2018 Synoptic sampling event (EMSI, 2018b and 2018c) and was dewatered during purging before a sample could be collected. The last 13 attempts to measure the water level in PM-13I revealed no recharge at this well since the October 2018 sampling event. PM-13X has been intermittently dry since the 2018 synoptic sampling event including in July 2021.

Where the water level data indicate the presence of an outward gradient, the effectiveness of the perimeter slurry wall is assessed using water quality data for five indicator compounds (1,1,1-TCA, 1,1-DCA, TCE, PCE, and 1,4-dioxane) obtained from wells located outside of the slurry wall in these areas. The presence of no trend or decreasing trend in water quality data indicates the slurry wall is effective at containing Site contaminants, while the presence of an increasing trend indicates the slurry wall may not be effectively containing Site contaminants.

In accordance with the updated GWMP, a minimum of four sample results is necessary to evaluate water quality trends for the effectiveness evaluation when inward gradients cannot be demonstrated (gradient data for each well is presented in Appendix C-4.1). For wells with 4 to 8 sample results (Appendix C-4.2), Sen's test is used to assess trends (Appendix C-4.3) for the compounds. A minimum of nine sample results is required to perform more rigorous statistical testing including calculation of Shewhart-CUSUM control limits (Appendix C-4.4). Sen's test is performed on the background data sets used to calculate the Shewhart-CUSUM control limits to verify that no temporal trends exist in the background data.

PM-3X has been sampled 36 times for VOCs and nine times for 1,4-dioxane (Appendix C-4.2). 1,4-Dioxane has never been detected in this well. TCE, 1,1,1-TCA and 1,1-DCA have never been detected above their RLs in this well. PCE has been detected in this well at concentrations substantially below its groundwater performance standard of 5 µg/L. The background data set for 1,1,1-TCA and TCE includes 32 samples. The background data set for 1,1-DCA and PCE includes 12 and 20 samples, respectively. The data sets for 1,1-

DCA and PCE were adjusted because they indicated trending data when the number of samples was increased in the baseline data set. No increasing trends were identified in the background data sets and the most recent results for 1,1,1-TCA, 1,1-DCA, TCE, and PCE are below the Shewhart-CUSUM control limit (Appendix C-4.4). These VOC results, plus the 1,4-dioxane non-detect results, indicate the slurry wall is effective at this location.

PM-6X has been sampled 38 times for VOCs and nine times for 1,4-dioxane (Appendix C-4.2). None of the five indicator compounds have ever been detected in this well. These results indicate the slurry wall is effective in this area.

PM-13X has been sampled 37 times for VOCs and nine times for 1,4-dioxane (Appendix C-4.2). 1,4-Dioxane has only been detected once in PM-13X (0.35J). It was not detected in the three most recent samples. The other four indicator VOCs have been detected in this well during each of these sampling events, but concentrations have always been less than performance standards. When the background VOC data set is set to more than 16 sampling events, 1,1,1-TCA shows a decreasing trend in the background data set. When the background VOC data set is set to more than 20 sampling events, 1,1-DCA shows a decreasing trend in the background data set. Therefore, it was necessary to revert to the prior background data for these compounds in order to not include trending data in the background data sets. The other two detected VOC compounds had no trend in the background set of 32 results. No increasing trends were identified in the background data sets and the 21 most recent results for 1,1,1-TCA, the 17 most recent results for 1,1-DCA, and the five most recent samples for PCE and TCE are below the Shewhart-CUSUM control limit (Appendix C-4.4). These VOC results, plus the 1,4-dioxane results of less than the RL, indicate the perimeter slurry wall is effective at this location.

PM-14X has been sampled 39 times for 1,1,1-TCA, 1,1-DCA, TCE, and PCE and 36 times for 1,4-dioxane (Appendix C-4.2). PCE has never been detected at this location. 1,4-Dioxane was detected once at a trace detect of 0.1 J µg/L (12/15/20). 1,1,1-TCA, 1,1-DCA, and TCE have been detected in this well at concentrations substantially below their respective groundwater performance standards. When the background VOC data set is set to more than 24 sampling events, 1,1-DCA shows a decreasing trend in the background data set. Therefore, the background data set included 24 samples for 1,1-DCA. The most recent 15 samples for 1,1-DCA are below the Shewhart-CUSUM control limit. No increasing or decreasing trends in the background data set of 36 samples were identified for 1,1,1-TCA, TCE and PCE and the three most recent results for each compound are below the Shewhart-CUSUM control limit. 1,4-Dioxane background set is 32 samples with no trends and the most recent four samples are below the Shewhart-CUSUM control limit (Appendix C-4.4). Therefore, the analytical chemistry data indicate the perimeter slurry wall is effective at this location.

Based on evaluation of the water level and water quality data, the perimeter slurry wall is effective at containing contamination inside the eastern, southern, and western limits of the landfill footprint.

Effectiveness of the perimeter barrier wall (EMSI/Parsons, 2021a) surrounding the eastern, southern, and western sides of the Section 6 landfill at the Site was evaluated as it related to findings and recommendations in USEPA's Fourth 5YRR (USEPA, 2017). It was concluded that successful operation of the perimeter barrier wall in conjunction with operations of the other remedial components at the Site address the remedial action objectives for protection of human health and the environment.

### 4.5.2 North Toe Extraction System

Effectiveness of the NTES is demonstrated based on hydraulic monitoring alone if either of the following conditions occurs:

1. Pumping from the NTES results in continuous decline of trench water levels as demonstrated by the well hydrographs for MPZ-10R, NTES-180W, and MPZ-11; or
2. Trench water levels (as measured in MPZ-10R, NTES-180W, and MPZ-11) remain below the base of alluvium (elevation of 5,740 ft amsl).

Figure 4.13 shows the water level data from piezometers NTES-180W, MPZ-10R, MPZ-11 and the extraction sump, and indicates that trench water levels remained below the base of alluvium throughout the reporting period. This is displayed by the potentiometric surfaces for the alluvium/weathered Dawson in the NTES area (Figures 4.14 and 4.15 for the third and fourth quarters of 2021, respectively) showing convergent groundwater flow to the trench. As indicated by Figures 4.13, 4.14, and 4.15, the NTES is effective at capturing contaminated groundwater emanating from the toe of the landfill.

Effectiveness of the MW38 Area, NTES, and North End Response Actions, (EMSI/Parsons, 2021b) at the Site were evaluated as it related to findings and recommendations in USEPA's Fourth 5YRR (USEPA, 2017). The measure of effectiveness for the NTES prescribed in the GWMP is being met by ongoing groundwater extraction from NTES trench wells.

### 4.5.3 North Boundary Barrier Wall

The presence, location, and extent of the containment area created by the NBBW systems are defined by the weathered Dawson potentiometric surface in the NBBW area. Figures 4.16 and 4.17 present the potentiometric surfaces for the alluvium/weathered Dawson in the NBBW area for the third and fourth quarters of 2021, respectively.

The NBBW zone of containment is highlighted in yellow on Figures 4.16 and 4.17. After potable water injection ceased on October 2, 2018, the water table between the NBBW and MW113 area has been flattening and a clear groundwater divide cannot be definitely demonstrated. Instead, a larger containment area north of the NBBW caused by cessation of potable water injection in conjunction with Response Action extraction has developed as shown on Figures 4.16 and 4.17 and has encompassed compliance wells B-313, GW-109, and B-326-WD, plus monitoring wells PTP-14, PTP-15, PTP-16, PTP-17S, PTP-18, PTP-19, PTP-20, and TR-1. Directions of groundwater flow into cones of depression within the enhanced Containment Zone are shown on both figures.

Since potable water injection stopped north of the NBBW, capture of contaminated groundwater migrating from the Site does not appear to have been compromised and the NBBW continues to function as intended. Flattening of the water table north (downgradient) of the wall is expected to continue. VOC and 1,4-dioxane concentrations provide an additional line of evidence that the NBBW is effectively performing as intended and containing contamination within the alluvium/weathered Dawson Formation that might otherwise migrate across the POC along the northern boundary of the Site.

Extraction of groundwater north of the NBBW continued during the reporting period. The extraction rates (gpm) from the four extraction wells are shown below.

| Well | 7/1 – 7/13//21 | 7/14 – 8/12/21 | 8/13 – 9/15/21 | 9/16 – 10/14/21 | 10/15 – 11/11/21 | 11/12- 12/14/21 | 12/15 – 12/31/21 |
|---|---|---|---|---|---|---|---|
| MW113-EW-1 | 2.0 | 2.0 | 2.5 to 4 | 3.6 | 3.3 | 3.0 | 2.0 |
| B-321 | 0.1 | 0.08 | 0.08 | 0.08 | 0.0 | 0.0 | 0.0 |
| MW113-UD | 0.03 | 0.03 | 0.03 | 0.03 | 0.02 | 0.02 | 0.02 |
| NBBW-IW-3 | 0.5 | 0.4 | 0.3 | 0.01 | 0.0 | 0.0 | 0.0 |
| **Total Extraction** | **2.63** | **2.51** | **2.91 to 4.41** | **3.72** | **3.32** | **3.02** | **2.02** |

Fluctuations in groundwater levels and 1,4-dioxane concentrations were observed in most weathered and unweathered Dawson monitoring wells in the NBBW area. As the water levels declined in the area, from both seasonal water decline and cessation of injection, the ability of extraction wells to remove groundwater from the system was affected, as discussed below.

The saturated thickness (defined as the water present in a well between the top of the water column and bottom of the well screen) in MW113-EW-1 has decreased since cessation of potable water injection. Historically, this well was able to sustain extraction in the 3 to 4 gpm range. With decreasing saturated thicknesses, sustained yields from this well are expected to decline.

On November 18, 2019, total molybdenum was detected in WTP effluent above its permitted limit, which led to a temporary shut-down of the WTP. After sampling all waters entering the WTP, the source was determined to be from extraction well MW113-EW-1.

Flow from that well was decreased to 1 gpm on November 18, 2019 and the WTP was returned to service. Due to continued increases in molybdenum concentrations in that well, and to ensure no additional effluent exceedances occurred in WTP effluent, the extraction rate from MW113-EW-1 was reduced to 0.5 gpm, on June 16, 2020. On July 30, 2020 a recently installed packer in the well was adjusted to a depth of 5664 feet amsl and the extraction pump inlet was raised to 5664.5 feet amsl to increase groundwater extraction from the interval above the packer. The MW113-EW-1 extraction rate remained at 0.5 gpm through November 3, 2020. Extraction from MW113-EW-1 was terminated on November 4, 2020 to allow the WTP to treat groundwater stored in a Baker tank prior to freezing weather. No additional extraction from MW113-EW-1 occurred between November 9, 2020 through January 26, 2021 to allow for the installation of the IX system. Extraction from MW113-EW-1 resumed on January 27, 2021 (extraction rate between 0.5 and 1 gpm) and was increased on March 11, 2021 to 2 gpm to increase mass removal. Because of decreasing water levels in NBBW area, the packer in MW113-EW-1 was removed on June 7, 2021. The extraction pump inlet was lowered to 6 inches above the bottom of MW113-EW-1's 5-foot sump and extraction resumed on June 8, 2021. An investigation of the extent and possible sources of elevated molybdenum in groundwater was presented in a Technical Memorandum, *Evaluation of Potential Sources of Elevated Molybdenum in Wells MW113-WD and MW113-EW-1* (EMSI/CDM Smith, 2020b).

The evaluation found the source of molybdenum appears to be naturally-occurring, coincident with fine to coarse-grained sands and clay clasts, deposited at the top of the bedrock interface. Plausible sources are Pike's Peak Granite (primary source of Dawson Formation) and/or rhyolite from the Castle Rock Formation deposited as Eocene age alluvium. Molybdenum is not a compound of concern for the Site but is regulated in the WTP effluent by the Metro permit. On January 27, 2021, an IX treatment system was brought online to treat the molybdenum from well MW113-EW-1. Since January 27 the total molybdenum concentration has dropped from 17000 µg/L to 3400 µg/L (10/19/21). The decrease in concentration indicates that the source is limited and appears to be depleting.

Figure 4.18 shows water elevations at monitoring well MW113-WD and dissolved molybdenum concentrations in compliance wells B-326-WD and B-326-UD and monitoring wells MW113-EW-1, MW113-WD, MW113-UD, and MW113-LD. Extraction from MW113-EW-1 was increased to 4 gallon per minute on August 19, 2021. The additional extraction from the weathered Dawson resulted in an increased rate of dewatering of the MW113 area as shown by a steepening of MW113-WD water elevations on Figure 4.18. Dissolved molybdenum concentrations gradually increased in MW113-WD until the well's water elevations flattened in mid-November. Following stabilization of water elevation, the dissolved molybdenum concentration increased until stabilizing around 20,000 µg/L. Stabilization of both water elevation and groundwater extraction rate suggest the area has reached equilibration under the current precipitation conditions.

To continue, and possibly increase, removal of 1,4-dioxane mass from the MW113 and B-326 areas, former injection well NBBW-IW-3 was converted to an extraction well and groundwater extraction began at 2 gpm on May 25, 2020. Following additional modifications to the well and conveyance system, extraction was increased to 2.5 gpm on June 17, 2020. Groundwater extraction from NBBW-IW-3 ranged between 2.5 and 1.7 gpm until MW113-EW-1 extraction was increased on March 11, 2021. Following the increase in extraction at MW113-EW-1, NBBW-IW-3 became formation limited and the extraction rate decreased to 0.5 gpm. Varying extraction rates during this period are the result of pump cycling, groundwater sampling and mechanical improvements to the well or WTP. After September 2021, no water was available for extraction from NBBW-IW-3.

Figure 4.19 shows water elevations following cessation for extraction well and companion monitoring well pairs MW113-EW-1/MW113-WD and NBBW-IW-3/B-319. Since cessation began, water levels decreased while extracting at 3.7 gpm from well MW113-EW-1. When extraction was reduced to 1 gpm, water levels rebounded (raised) immediately and slowly approached a steady-state (not increasing or decreasing) over time. To increase mass removal, extraction was increased to 2 gpm on May 25, 2020 in NBBW-IW-3 and water levels rapidly declined. Review of the graph shows a steady and continuing water level decline following reduced extraction at 0.5 gpm in MW113-EW-1 and increased extraction to 2.5 gpm in NBBW-IW-3. Extraction from MW113-EW-1 was terminated on November 4, 2020 while extraction at NBBW-IW-3 became formation limited with an average extraction rate at 1.7 gpm. Increased extraction at MW113-EW-1 on March 11, 2021 resulted in decreased extraction at formation limited well NBBW-IW-3 at 0.5 gpm. Following this extraction modification, water level decreases were observed in B-319, MW113-WD and MW113-EW-1. From March 17, 2021 to August 19, 2021, the

water level in MW113-WD decreased at an average rate of approximately 0.15 feet per week. MW113-EW-1 extraction was increased to 4 gpm resulting in a water level in MW113-WD decreasing at approximately 0.41 feet per week (August 19, 2021 through November 19, 2021). The extraction rate at MW113-EW-1 steadily decreased and slowly approached a steady-state of 1.9 gpm at the end of the reporting period. During this period, November 19, 2021 through December 22, 2021, the water level in MW113-WD declined at a rate of approximately 0.05 feet per week. As previously mentioned, stabilization of water elevation and groundwater extraction rate suggest the area has reached equilibrium (i.e., pumping rate and current precipitation conditions).

Future extraction rates will be dictated by the ability of the wells to maintain yield, balanced against the ability of the WTP to meet its discharge limit for molybdenum (see Section 2.2.1 - Summary of Activities and Section 2.3 - Treatability).

Figure 4.20 shows the effect of the remedial action implemented in this area on 1,4-dioxane concentrations. The graph shows overall declining 1,4-dioxane trends for compliance wells B-326-WD and B-326-UD and nearby extraction wells MW113-EW-1 and MW113-UD prior to cessation of potable water injection. Since cessation began, concentrations in the compliance wells have generally remained constant, while concentrations in the nearby extraction wells have generally increased. Following identification of MW113-EW-1 as the source of the elevated molybdenum concentrations in the WTP effluent, extraction from this well was decreased to 1 gpm on November 18, 2019. Following reduced groundwater extraction from this well, the 1,4-dioxane concentration decreased. Extraction from NBBW-IW-3 beginning on May 28, 2020 and modifications to extraction at MW113-EW-1 did not appear to have any effect on concentrations in compliance wells B-326-WD and B-326-UD. Concentrations of 1,4-dioxane in MW113-UD have increased since cessation of potable water and are generally similar to concentrations prior to the start of extraction at MW113-UD on September 27, 2011. It is antipicated that concentrations in both MW113-WD and MW113-UD will gradually decrease as residual 1,4-dioxane present in the weathered Dawson is removed.

Groundwater levels north of the NBBW have declined since cessation began as shown on Figure 4.19. Correlations among groundwater levels, pumping rates, and 1,4-dioxane concentrations are further addressed in the *Revised Final Report on Pilot Test for Cessation of Potable Water Injection* (EMSI/CDM-Smith, 2020a).

As a result of cessation of injection, availability of water in B-321 is formation limited and the extraction rate is dictated by the groundwater flow rate into the well. Extraction at B-321 remained at 0.001 gpm until November 3, 2020 when extraction was stopped to allow groundwater to enter the well for the fourth quarter sampling event in 2020. Insufficient water entered the well for sampling. Following the attempted sampling, groundwater extraction from the well was no longer possible due to lack of enough water entering the well to allow pump cycling and no additional extraction has occurred since November 3, 2020. Lack of groundwater entering the well reflects continued dry conditions in this area until June 7, 2021 when the B-321 produced enough water to resume extraction and continued through October 14, 2021. To the extent that seasonal precipitation events raise the groundwater table in this area, extraction will continue as long as sufficient groundwater is present in the well for extraction.

Figure 4.21 shows an overall declining 1,4-dioxane trend for compliance well B-313 prior to and following the start of cessation. It also shows the duration and rates of groundwater extraction from nearby extraction well B-321, and concentrations of 1,4-dioxane in the extraction well over time. As shown, between 2010 and the start of cessation in 2018, 1,4-dioxane concentrations in the extraction well varied between 16 and 45 µg/L, with no apparent trend. Since the start of cessation, 1,4-dioxane concentrations became more variable ranging between 8.3 and 97 µg/L again with no apparent trend. The increased variability is believed to be attributed to changes in the direction and rate of groundwater movement caused by cessation of potable water injection, changes in groundwater pumping rates, and changes in groundwater levels. The extraction rate from well B-321 is formation limited and dictated by groundwater availability, so that 1,4-dioxane concentration variability is anticipated to continue. Lack of groundwater entering B-321 reflects continued dry conditions at this area until June 7, 2021 when the B-321 produced enough water to resume extraction, albeit at less than 0.10 gpm for only four months. Since 3rd quarter 2020, 1,4-dioxane concentrations in compliance well B-313 have stabilized to approximately 17 µg/L. Further discussion is provided in the Revised Final Cessation Report (EMSI/CDM-Smith, 2020a).

Figures 4.22 and 4.23 show the potentiometric surfaces of the unweathered Dawson in the NBBW area. As shown, there appear to be two potentiometric lows, sloped from south to north beneath the eastern, and to a lesser extent, western side of the NBBW. Both lows correspond to the presence of sandstones within the unweathered Dawson in the vicinity of the NBBW. An evaluation of the nature and extent of these sandstones and their influence on groundwater flow conditions are further evaluated as part of the NBBW CSE (EMSI/CDM-Smith/Parsons, 2021).

### 4.5.4 MW38 Channel


Groundwater extraction continued from wells MW38-170S-140E and MW38-1028N-256E located in the MW38 channel sand (Figures 4.24 and 4.25). Pumping from these two wells is performed to maintain an inward hydraulic gradient toward the sand channel. Pumping occurs on an intermittent basis because the sand channel has been essentially dewatered and it takes several days for sufficient water to accumulate in the areas of these two wells to activate pumping.

Hydraulic (water level) monitoring is used to demonstrate the effectiveness of the MW38 sand channel at containing groundwater in the MW38 area. These data were used to prepare potentiometric maps of the MW38 area (Figures 4.24 and 4.25). Review of these maps indicates the presence of convergent groundwater flow along the entire length of the MW38 channel, as indicated by the flow direction arrows on these two figures. The presence of convergent flow into the MW38 channel indicates that the channel effectively prevents shallow contaminated groundwater within the channel from migrating to the west, east, north, or south from the sand channel.

It should be noted that the northern extraction well (MW38-1028N-256E) is positioned 100 ft north of the Site boundary to take advantage of the thicker and deeper extent of porous channel sand at this location. As a result, groundwater quality from the compliance well (MW38-830N-230E), which is positioned within the sand channel near the Site boundary and south of MW38-1028N-256E, is representative of groundwater that will be

extracted by extraction well MW38-1028N-256E and will not migrate beyond the sand channel.

The concentration time-series graph below shows that hydraulic gradient control pumping at channel wells MW38-170S-140W and MW38-1028N-256E and source control pumping at MW38-825N-445E have successfully reduced contaminant concentrations in MW38-830N-230E where the 1,4-dioxane concentration has declined by 97.4% in this compliance well.




PCE = Tetrachloroethene TCE = Trichloroethene c12DCE = cis-1,2-Dichloroethene
12DCA = 1,2-Dichloroethane CFM –=Chloroform 14X = 1,4-Dioxane

It should be noted that on December 11, 2019, a leak from DADS' buried potable water supply pipe was identified near MW38-500N-396E. Potable water is believed to have preferentially flowed along the pipeline bedding and was observed in the pipeline trench 50 feet east of MW38-680N-419E. From this area the pipeline heads eastward, parallel to the DADS main access road. The pipeline is located about 40 feet south of MW76-WD and MW75-WD. Potable water was observed daylighting between MW75-WD and MW74-WD. DADS repaired the leak in January 2020. By April 2020, the higher groundwater elevation at MW38-680N-419E observed in January 2020 had declined to within a few feet of historical water elevations and during this reporting period water levels have returned to historical water elevations.

Effectiveness of the MW38 Area, NTES, and North End Response Actions, (EMSI/Parsons, 2021b) at the Site were evaluated as it related to findings and

recommendations in USEPA's Fourth 5YRR (USEPA, 2017). The measure of effectiveness for the MW38 area prescribed in GWMP is being met by ongoing groundwater extraction from the MW38 sand channel.

### 4.5.5 Vertical Migration Assessment in Deep Groundwater (OU6)

The presence of a downward component to the hydraulic gradient at the Site indicates that there is a potential for downward migration of contamination from source area(s) into the underlying unweathered Dawson and potentially the upper Denver and lignite layers (Table 4.3). Although there may be a downward component to the hydraulic gradient, this downward component is wholly or partially offset by the lower permeability of the deeper bedrock units compared to that of the alluvium and weathered bedrock. This section describes the vertical migration assessment performed using data from four specific non-compliance program wells and a review of deep groundwater compliance wells that are monitored for compounds of concern.

#### 4.5.5.1 Vertical Migration Wells

Monitoring of the 29 water quality parameters that are indicators of compliance with groundwater standards is performed in selected unweathered Dawson and upper Denver wells **inside of the POC**. Contaminant concentrations are monitored for trends and compared to performance standards to assess if contaminants are potentially migrating vertically. The goal for vertical migration monitoring is to show that groundwater contaminant concentrations will be below performance standards, and if present, will exhibit stable or decreasing concentration trends over time. These conditions would indicate no vertical migration of contamination is occurring.

Monitoring for potential vertical migration is separate and distinct from compliance monitoring and monitoring performed to demonstrate the effectiveness of the various remedy components. The purpose of monitoring for potential vertical migration is to allow for ongoing assessment of the well network and sampling frequency used for the deeper compliance monitoring wells at the Site. Water quality data obtained from the interior deeper monitoring wells will be used to identify any modifications to the compliance monitoring network and/or sampling frequencies for the deeper units, if any, that may be necessary to ensure detection of possible occurrences of contamination above performance standards in the deeper units that may be migrating towards either the horizontal or vertical POC.

Although not compliance wells, vertical migration wells (B-504A, B-712-LD, C-702P3, and GW-113) are subject to the same statistical tests used in Section 4.4.1 for comparison of UCLs and LCLs to performance standards. Upper Denver wells B-504A, C-702P3, and GW-113 are sampled every five years and unweathered Dawson well B-712-LD is sampled every two years. These wells were not sampled during the reporting period. The results and statistical analyses for these wells as previously reported in the first half 2021 Status Report are summarized below:

- For wells B-504A, C-702P3 and GW-113, the maximum concentrations for all compounds for each well were less than their respective performance standards; therefore, statistical analyses to determine the UCL and LCL for comparison to performance standards did not need to be performed (Appendix C-5.1).

- For well B-712-LD, the historical maximum concentrations of all compounds were also less than their respective performance standards except for one detect of 1,4-dioxane (0.95 µg/L) in 2007. The eight subsequent samples obtained from this well were all reported as not detected for 1,4-dioxane, down to a method detection limit (MDL) of 0.09 µg/L. A compliance determination could not be made for 1,4-dioxane because 90% of the results were not detected. The single detected value of 0.95 µg/L was determined to be an outlier (Appendix C-5.3). If the outlier is removed and replaced with an earlier value (0.5 U, 6/19/06) in order to have ten results, all ten results are not detected: therefore, the well would be in compliance with the groundwater performance standard for 1,4-dioxane.

No significant increasing trends were identified for any of the indicator chemicals of compliance in any of these wells (Appendix C-5.2). Based on evaluation of the results obtained from the last sampling event, there is no evidence of vertical migration of contamination beneath and north of the landfill. The WSDs recommend no changes in the frequency of monitoring of the vertical migration wells.

#### 4.5.5.2 Deep Groundwater Water Quality

Thirty-four deep wells (unweathered Dawson, Upper Denver, and Lignite layer) are part of the compliance monitoring network (EMSI/Parsons, 2018) and are sampled routinely for 29 compounds of concern. Although trace or low concentration detects of multiple compounds of concern have been detected over time, only three unweathered Dawson compliance wells have detections of compounds of concern at concentrations greater than performance standards.

- B-326-UD for 1,4-dioxane and nitrate,
- MW23-C-SD for 1,4-dioxane, and
- MW106-UD for 1,4-dioxane

Section 4.4 discusses compliance statistical testing for these wells and compounds and determined 1,4-dioxane in MW23-C-SD and MW106-UD were potentially in compliance due to the preponderance of nondetects and because each well had only one detect of 1,4-dioxane not confirmed by subsequent samples.

B-326-UD nitrate is potentially in compliance because it displays a decreasing trend and the last six results were less than the performance standard. The decrease in nitrate in the deeper monitoring well B-326-UD correlates with the declining water level observed post-cessation and could suggest a change in flow path with non-nitrate impacted water now being monitored by this well.

1,4-Dioxane is out of compliance in B-326-UD with a decreasing trend. This unweathered Dawson well is paired with B-326-WD allowing calculation of vertical gradients. There is an upward gradient at this location meaning that vertical migration in this area is currently upward. B-326-WD is also out of compliance for 1,4-dioxane although no trend is indicated. Water elevations in the B-326-WD/B-326-UD well pair generally mirror each other. As water levels in both wells declined following cessation, an upward vertical gradient developed at the end of May 2019 that continued through October 2021. Therefore, if vertical migration is occurring, the direction of migration is upward from the unweathered bedrock in the B-326 area as shown in Figure 4.26.

In contrast, vertical downward gradients were identified at other locations in the NBBW area. Each of the following well pairs displayed vertical gradients with a downward hydraulic gradient indicating a potential for downward migration of groundwater and contaminants; however, water quality monitoring has not detected the presence of site-related contaminants in the deeper well while at least one compound was out of compliance in the paired weathered Dawson well.

- **B-313/B-313-UD**: B-313 is out of compliance for 1,4-dioxane (17 µg/L on the last sampling date of 11/16/21) and nitrate (55000 µg/L, 8/12/21). 1,4-dioxane has never been detected in B-313-UD and nitrate has only been detected at 100 J µg/L (7/27/20).
- **MW62-WDR/MW62-UD**: MW62-WDR is out of compliance for 1,4-dioxane (3.2 µg/L, 10/27/21) and nitrate (110,000 µg/L, 10/27/21). 1,4-dioxane has never been detected in MW62-UD and nitrate has only been detected once at 110 J µg/L. 1,4-Dioxane has never been detected in MW62-DENR or MW62-LIG also. Nitrate has been detected in MW62-DENR ranging from 57 J (8/14/18) to 180 J µg/L (9/2/05).
- **MW77-WD/MW77-UD**: MW77-WD is out of compliance for 1,4-dioxane (11 µg/L, 10/27/21) and has only been detected once in MW77-UD at 0.38 J µg/L (8/20/18).

Outside of the NBBW area, there are two weathered Dawson compliance wells paired with unweathered wells that have detected compounds at concentrations above performance standards in the past; however, those compounds are not present or are present at low concentrations in their associated deeper unweathered Dawson well. GW-114A has a downward gradient and the well's last exceedance was methylene chloride at 12 µg/L (11/5/02). This chemical was not detected ( reporting limit of 1 U µg/L) in the associated deep well GW-108A (a compliance well) when this well last sampled on 8/19/20. MW74-WD has a downward gradient and the most recent exceedance is nitrate at 30,000 µg/L (5/17/17). Nitrate was not detected in the associated unweathered bedrock well (MW74-UD) the last time it was sampled on 8/6/20. Most unweathered Dawson wells that are located in a paired configuration with a weathered Dawson compliance well have never detected chemicals at levels above the performance standards.

The low or not detected concentrations in the deeper (unweathered Dawson) compliance wells in areas of downward vertical gradient where elevated concentrations of site-related chemicals are present in the paired weathered Dawson well indicate there is little or no downward migration of contaminants in this area.

In conclusion, with the exception of B-326-UD, monitoring of deeper groundwater at Lowry demonstrates that deeper groundwater meets the groundwater performance standards in compliance wells and that significant vertical migration of site contaminants is not occurring. 1,4-Dioxane in the B-326-UD area is out of compliance but located in an area where both weathered and unweathered Dawson groundwater are captured by groundwater extraction at MW113-EW-1 and MW113-UD and cessation. Overall, the evidence indicates that vertical migration of contaminants to deeper groundwater is not occurring.

### 4.6 Voluntary Actions – MW38 and Perimeter Systems

Voluntary measures are being implemented at the Site 1) for source control associated with the MW38 sand channel; 2) to induce inward hydraulic gradients across the perimeter

slurry wall; and 3) to remove VOCs from groundwater outside the slurry wall. The systems are located in the following areas, starting on the west side and progressing counterclockwise around the Site:

- MW38-WD - groundwater extraction from an upgradient (source-control) well;
- PM-11 - groundwater extraction from two internal wells (gradient control);
- MW51-WD - groundwater extraction from three internal wells (gradient control) and air sparge at one well (VOC removal outside the wall); and
- PM-15 - groundwater extraction from six internal or northern wells (gradient control) and air sparge at one well (VOC removal outside the wall).


The status of each of these voluntary actions is discussed below.

### 4.6.1 MW38 Source Control


Voluntary pumping of the source well (MW38-825S-445E) resumed in the first half of 2019 following completion of upgrades to the WTP and installation of the new POTW pipeline. In the second half of 2021, total extracted groundwater from the source well was 69,302 gallons and reflects six months of continuous pumping.

The primary constituents detected in the November 8, 2021 sample were 1,2-DCA at 36,000 µg/L; 1,1-DCA at 2,200 µg/L; and 1,4-dioxane at 2,500 µg/L. Continued extraction resulted in contaminant mass removal of 20.78 pounds of 1,2-DCA; 1.27 pounds of 1,1-DCA; and 1.44 pounds of 1,4-dioxane during the second half of 2021. Cumulative mass removed from this well since pumping began in October 2004 is 2,999.5 pounds of 1,2-DCA; 155.0 pounds of 1,1-DCA; and 153.1 pounds of 1,4-dioxane.

The source well time-series graphs below show volume of groundwater extracted and mass removed semi-annually for 1,1-DCA, 1,2-DCA, and 1,4-dioxane as well as



cumulative volume and mass removed semi-annually. The response action at MW38-825S-445E has been successful at reducing contaminant mass in this area.




### 4.6.2 PM-11

Groundwater extraction from wells PM-11I and BM-11I-100N (see Figure 4.2) was conducted to induce an inward hydraulic gradient by lowering the water table inside the slurry wall relative to outside of the wall. The combined extraction rate from the two PM-11 area wells was 276 gallons per day (gpd). Approximately 50,536 gallons of water were transferred to the WTP during the reporting period. Well BM-11I-100N produces approximately 60% of the combined volume, which has remained fairly consistent over the past several years.

### 4.6.3 MW51-WD

Voluntary measures in the MW51-WD area (see Figure 4.2) include groundwater extraction from three interior wells and air sparging from one well outside the wall. Groundwater extraction has been on-going since February 2003 and air sparging has been intermittent since 2002. Both measures are discussed below.

#### 4.6.3.1 Groundwater Extraction

Groundwater extraction continued from wells MW51I-WD-15N, MW51I-WD, and MW51I-WD-35S, which are all positioned inside the slurry wall. The cumulative second half of 2021 production from these three wells was 64,690 gallons or 352 gpd. Based on totalizer logs, approximately 72% was from well MW51I-WD-35S and 27% was from well MW51I-WD-15N. Less than one percent was from the middle extraction well MW51I-WD where only saturated clays are present.

#### 4.6.3.2 Air Sparge

Air sparging from MW70-WD, which began in May 2002, was terminated in March 2013 because four quarterly sampling events following cessation of sparging confirmed no VOC detections above performance standards in this well. However, the concentration of PCE in MW70-WD increased to 5.1 µg/L on November 19, 2014, so air sparging was resumed on December 15, 2014. MW70-WD showed a decreased concentration of PCE (0.5 J µg/L) and TCE (0.26 J µg/L) in the May 14, 2020 groundwater sample and neither compound was detected in the groundwater sampled on December 8, 2020, May 27, 2021 or November 9, 2021. Compliance well MW60-WD, located downgradient from MW70-WD is also sampled semi-annually. Neither PCE nor TCE have been detected in MW60-WD since April 17, 2000.

### 4.6.4 PM-15

Voluntary measures in the PM-15 area (see Figures 4.27 and 4.28) included groundwater extraction from six wells and air sparging from one well. Groundwater extraction has been on-going since February 2000, and air sparging has been ongoing since June 2003. Both measures are discussed below.

#### 4.6.4.1 Groundwater Extraction

Six extraction wells were pumped during the reporting period: five interior wells (PM-15I, BM-15I-25S, BM-15I-50S, BM-15I-100S, and BM-15I-150S) and one well positioned 15 ft north of the end of the slurry wall (BM-15I-15N). A total volume of 3,783 gallons or 21 gpd was transferred from PM-15 area storage tank to the RWST at the WTP during the second half of 2021. Based on totalizer logs, BM-15I-25S and BM-15I-15N produce the majority of the groundwater.

Groundwater extraction has maintained an inward hydraulic gradient across the northeast end of the slurry wall ranging from 0.29 ft/ft at the extraction pairs to 0.001 ft/ft at the non-extraction well pairs, as can be checked by comparison of paired wells on Figure 4.12, Figure 4.27, and Table 4.2. At non-extraction well pairs, the hydraulic gradient is small, but inward.

#### 4.6.4.2 Air Sparge

Well BM-15N5 has been air sparged since June 2003 and throughout the reporting period to remove low-level residual VOCs from groundwater north of the slurry wall in the PM-15 area. The air sparge well BM-15N5 is positioned downgradient from PM-15X. Ongoing groundwater extraction from wells inside the slurry wall is inducing inward gradients across the wall that will further minimize the potential for migration of residual VOCs outside the wall.

## 4.7 NTES Area NAPL Skimming

During the reporting period, no light non-aqueous phase liquid (LNAPL) extraction was necessary from the sump riser, MPZ-10R or MPZ-11 based on monitoring of the thickness of the LNAPL layer. A measured product thickness of greater than six inches is used to trigger non-aqueous phase liquid (NAPL) extraction. The last LNAPL extraction from the NTES took place September 13, 2011.

Visual inspection of the groundwater pumped from the NTES to the WTP indicated no LNAPL or dense non-aqueous phase liquid (DNAPL) were present in the extracted groundwater, as there were no visible globules present in the pumped groundwater.

A discussion on the effectiveness and operations at the NTES was provided in Subsection 4.5.2.

## 4.8 North End Response Actions and Investigations

The following sections describe the monitoring and extraction response actions for the North End (land sections 31, 30, 19, 18, and 24) and progress made to date.

### 4.8.1 North End Monitoring Results

North End groundwater levels and groundwater quality were monitored during the reporting period in accordance with the *North End Groundwater Monitoring Plan* (EMSI, 2007b and updates EMSI, 2020b and Parsons, 2021b) (collectively, North End GWMP). Depths to groundwater are measured quarterly from all North End investigation wells installed in Section 31. Water levels in North End wells in Sections 30, 19, and 24 are measured semiannually during the first and third quarters of each year. Figures 4.29 and 4.30 show the potentiometric surface in Section 31 for July and October 2021, respectively. Although well control is sparse in Sections 19 and 30, Figure 4.31 shows the interpreted potentiometric surface in the vicinity of Murphy Creek Golf Course during July 2021.

Available nitrate and 1,4-dioxane analytical results from existing North End investigation wells are presented in Table 4.8. Table C-6.1 (Appendix C-6) presents all organic and nitrate data collected from the north end wells in the reporting period. Table C-6.2 (Appendix C-6) presents all organic and nitrate data collected in Area 3 during the reporting period. Section 31 1,4-dioxane concentrations are shown on Figures 4.32 and 4.33 for the third and fourth quarters of 2021, respectively. Section 31 wells are sampled quarterly. Figure 4.34 shows the spatial distribution of 1,4-dioxane in shallow groundwater in Sections 19 and 30 in the third quarter of 2021; wells are sampled semi-annually in this area. No data are available in Section 19 and 30 for the fourth quarter 2021.

Two private domestic wells located along East Jewel Avenue, have been sampled annually each spring (second quarter) since 2006 for 1,4-dioxane and were last sampled on May 19, 2021. The wells are perforated from depths of 357 to 600 ft bgs. Sampling of these wells is intended to provide assurances to the well owners that are proximal to the shallow groundwater plume that their drinking water does not contain 1,4-dioxane at concentrations above acceptable levels. Sampling of these wells is not for compliance monitoring purposes. 1,4-Dioxane has never been detected in either of these wells above an MDL of 0.5 µg/L (from March 28, 2006 through July 16, 2015), above an MDL of 0.15 µg/L (July 16, 2015 to May 23, 2019), or above an MDL of 0.09 µg/L (June 25, 2020). The two domestic wells were also sampled on May 19, 2021 for total dissolved solids, alkalinity, metals, VOCs, SVOCs, sulfate, chloride, nitrate, nitrite, and fecal coliform to update the assessment of groundwater quality in the wells and determine if shallow groundwater is potentially being drawn down into the well screens. Fecal coliform was not detected in the wells and groundwater geochemistry was similar to historical deep groundwater conditions. These results indicate that these wells are unlikely to draw shallow groundwater down into the well screens and that the groundwater being extracted by the wells is coming from the screened intervals (e.g., deeper than 350 feet bgs).

### 4.8.2 Groundwater Extraction in the North End, NBBW and GTEP Area

Groundwater was extracted from the four areas illustrated on Figures 4.32 and 4.33, and described below:

- In Area 1, groundwater extraction is ongoing at three wells (MW153-EW-1, MW154-EW-1, and MW155-EW-1) at a combined rate of between 6.8 and 7.3 gpm during the reporting period. Extraction from MW156-EW-1 was suspended on March 22, 2012 because the 1,4-dioxane concentration dropped to below the performance standard in effect at that time (5 µg/L). 1,4-Dioxane was detected at 1.1 µg/L in groundwater sampled on July 21, 2021 and at an estimated concentration of 0.48 J µg/L in the most recent groundwater sample collected on November 22, 2021.
- In Area 2, pumping from one well (MW160-WD) was conducted. Groundwater extraction from this well is limited by the formation and pumping was limited to 0.5 gpm. The most recent (fourth quarter 2021) 1,4-dioxane concentrations detected at this well and adjacent well MW132-WD were 3.3 µg/L and 14 µg/L, respectively – both above the current performance standard. No extraction occurred from MW118-WD (extraction suspended on 3/19/11). The most recent (November 2021) 1,4-dioxane concentration in this well is 0.26 J µg/L.
- In Area 3 (MW77 area), three wells (MW102-WD, MW77-EW-1 and MW98-WD) were pumped at a combined rate of 0.65 to 1.09 gpm during the reporting period. Extraction was stopped at MW77-EW-2 on June 24, 2011 because the 1,4-dioxane concentration decreased to below the previous 5.0 µg/L performance standard. The most recent (November 2021) concentration detected at this well was 0.12 J µg/L. Pumping was also suspended at MW114-WD on October 7, 2009 for the same reason. The most recent (November 2021) concentration in this well is 0.96 µg/L – slightly above the current performance standard. Pumping from well MW114-WD was not initiated during this reporting period because of its low concentration and low mass removal potential.
- Groundwater extraction in Area 4 (NBBW area) was discussed in Subsections 4.4.2.1 and 4.4.2.2 relative to compliance with groundwater standards and in effectiveness at reducing 1,4-dioxane and nitrate concentrations. WSDs will continue to optimize pumping from the weathered and unweathered Dawson wells in accordance with the RAWP protocols to meet the removal action objectives (Section 4.5.3).
- Area 5 (GTEP Area) activities are discussed in Subsection 4.9.

### 4.8.3 Progress from Response Actions and Investigations

Approximately 6.5 million gallons of groundwater were pumped from twelve active North End response action wells during the reporting period. Based on the number of gallons pumped and the concentrations at each extraction well, approximately 490 grams (1.08 pounds) of 1,4-dioxane were removed during the reporting period as shown in Table 4.9. The cumulative volume removed since inception of the response actions is about 154.4 million gallons, with a cumulative mass removal of 9,589 grams (21.1 pounds) of 1,4-dioxane. Table 4.9 lists the groundwater volume removed and the 1,4-dioxane mass removed from each north end extraction well.

Trend analyses for the 37 wells being monitored in the North End Area are illustrated in Figures 4.35 through 4.40. Trend analysis was performed on four compliance wells and presented in Appendix C-3.2. Two of these compliance wells are not listed in the North End GWMP Update No. 3 (Parsons, 2021b) but are included here (B-313 and MW77-WD) because they are good indicators of 1,4-dioxane mass removal occurring over time. One well recently added to North End GWMP (MW179-UDEN) does not have enough samples to perform trend analysis (requires a minimum of four samples).

All trend results are summarized in the table below. Of the 39 wells where trend analysis was performed, 32 (82%) are showing declining trends and 6 (15%) are showing no trends. PTP-14 is showing an increasing trend for 1,4-dioxane through June 2020 and has been dry since that date. The decreasing trends in all four Areas are evidence that the ongoing response actions are effective at removing mass from within Section 31. Extraction well B-321 is showing an increasing trend in nitrate. This increase may be caused by variations in groundwater levels and/or flow directions in the vicinity of this extraction well resulting from cessation of potable water injection.

**Results of 1,4-Dioxane and Nitrate Trend Analysis in North End Wells**

| Well | Trend[1/] | Extraction Well? | Well | Trend | Extraction Well? |
|---|---|---|---|---|---|
| **1,4-Dioxane** | | | | | |
| B-321 | Decreasing | Yes | MW142-WD | Decreasing | No |
| B-326-UD* | Decreasing | No | MW144-WD | Decreasing | No |
| B-326-WD* | No trend | No | MW151-WD | Decreasing | No |
| MW05-WD | Decreasing | No | MW153-EW-1 | Decreasing | Yes |
| MW102-WD | Decreasing | Yes | MW154-EW-1 | Decreasing | Yes |
| MW103-WD | No Trend | No | MW155-EW-1 | Decreasing | Yes |
| MW113-UD | Decreasing | Yes | MW156-EW-1 | Decreasing | Yes |
| MW113-EW-1 | Decreasing | Yes | MW156-WD | Decreasing | No |
| MW114-WD | Decreasing | Yes | MW157-WD | Decreasing | No |
| MW117-WD | Decreasing | No | MW160-WD | Decreasing | Yes |
| MW118-WD | Decreasing | Yes | MW176-DEN | No trend | No |
| MW121-WDR | Decreasing | No | MW179-UDEN | Insufficient Data | No |
| MW122-WDR | Decreasing | No | MW77-EW-1 | Decreasing | Yes |
| MW123-WD | Decreasing | No | MW77-EW-2 | Decreasing | Yes |
| MW124-WD | Decreasing | No | MW77-WD* | No trend | No |
| MW125-WD | Decreasing | No | MW98-WD | Decreasing | Yes |
| MW129-WD | Decreasing | No | PTP-12 | No Trend | No |
| MW132-WD | Decreasing | No | PTP-13 | Decreasing | No |
| MW135-WD | Decreasing | No | PTP-14 | Increasing | No |
| MW141-WD | Decreasing | No | B-313* | No trend | No |
| **Nitrate** | | | | | |
| B-321 | Increasing* | Yes | MW113-EW-1 | No trend | Yes |

1/ Trend for the compliance wells uses the last ten sampling events. Trend for all other wells uses all sampling events. Compliance wells are indicated by a *. Trend is determined by Mann-Kendall trend test for compliance wells only, remaining well trends determined by Sen's test. MW77-WD and B-313 are not North End Monitoring wells but are listed here for additional information only.

Figure 4.41 depicts the concentration trends spatially with the use of different colored dots to signify increasing, decreasing, and no trend. Inset graphs for wells MW103-WD and B-326-WD which exhibit no trend, are shown on the figure. B-326-WD is a compliance well with no trend over the last 10 samples. An inset on Figure 4.41 displays all data for B-326-WD to demonstrate how 1,4-dioxane has decreased over time. MW77-WD and B-313 have no trend also but display similar results as B-326-WD. Figure 4.41 shows the lateral extent of the 1,4-dioxane plume in Sections 31, 30, and 19.

The following table summarizes the status of each task specified in the ongoing RAWPs and Monitoring Plans.

**Summary of Progress to Date**

| **Revised North End IRA Work Plan Addendum** (EMSI, 2008b) | **Status** |
|---|---|
| Continue pumping from extraction wells in Areas 1, 2, 3, and 4. | Ongoing. |

| **Work Plans for Area 4 Response Action** (EMSI, 2008b and 2010b) | **Status** |
|---|---|
| Extraction coupled with potable water injection upgradient of extraction well MW113-EW-1 is intended to mobilize and recover mass from this otherwise "stagnant zone" of groundwater contamination.<br><br>Continue pumping from extraction well MW113-EW-1 as deemed appropriate to achieve objectives. | Potable water injection was discontinued on October 2, 2018. Extraction from MW113-EW-1 is ongoing. NBBW-IW-3 was converted to an extraction well and was initially pumping at a rate of about 2 gpm to enhance mass removal from this Area. Water levels continue to decrease in the area and NBBW-IW-3 has become formation limited resulting in an extraction rate of 0.5 gpm through the first half of 2021. Extraction rates continued to decline and the well became dry in September 2021. |

| **Work Plans to Extract Additional Groundwater from Area 3 and 5 of the North End Response Action** (EMSI, 2010a and 2011) | **Status** |
|---|---|
| Assess the presence (or absence) of a preferential pathway beneath the GTEP pad toward MW77-WD, the lateral limits of the pathway (if present), the direction and rate of groundwater movement, and potential yield from an extraction well. Design and install a new extraction well and collection system to best intercept the flow of contaminated groundwater toward MW77-WD. | Initial investigation work complete. Extraction from MW170-EW-1 is ongoing - see Subsection 4.9, below. |

| **North End Groundwater Monitoring Plan and Update No. 3**<br>(EMSI, 2007b and Parsons, 2021b) | **Status** |
|---|---|
| Assess results and modify plan as appropriate. | Ongoing. quarterly and semiannual monitoring of North End wells will continue in accordance with *Update No. 3.* |

| **Response Action Work Plan for B-326-UD and B-313 Area**<br>(EMSI, 2013) | **Status** |
|---|---|
| Extract groundwater from MW113-UD to remediate contamination in the vicinity of B-326-UD. Extract groundwater from B-321 to remediate contamination in the vicinity of B-313. | Ongoing. An unweathered Dawson monitoring well MW115-UD was sampled for 1,4-dioxane on August 20, 2013 and March 4, 2014. No 1,4-dioxane was detected in either sample. Groundwater extraction from wells MW113-UD and B-321 commenced in June and July 2013, respectively, in accordance with the RAWP. |

| **Work Plan to Assess Northern Extent of 1,4-Dioxane in Shallow Groundwater (North of Well MW144-WD)**<br>(EMSI, 2014) | **Status** |
|---|---|
| Install four piezometers along western extension of Mississippi Avenue. Sample groundwater and collect confirmation samples. Recommend location for permanent sentry well. Install additional piezometers to delineate lateral extent if 1,4-dioxane concentrations are greater than the performance standard. | Piezometers NEPZ-100 through NEPZ-103 were installed and sampled for 1,4-dioxane. Initial and confirmation sampling results were less than the performance standard of 0.9 µg/L. A sentry well location was recommended. |

| **Work Plan to Sample North End Wells, Piezometers, and Surface Water**<br>(EMSI, 2016) | **Status** |
|---|---|
| Sample existing monitoring wells, piezometers, and surface water stations for 1,4-dioxane, VOCs, metals, nitrate, and nitrite beginning at the Yale Avenue extension well transect and extending northward up to and including the recently-installed piezometers along Mississippi Avenue. | Field investigation work complete. Analytical results have been validated and are consistent with previous sampling results. |

| | |
|---|---|
| In addition, one surface water sampling station (SW-3) is located south of the Yale Avenue extension. | |

| **Revision 1, Addendum to Work Plan to Assess Northern Extent of 1,4-Dioxane** (EMSI, 2017) | **Status** |
|---|---|
| The second phase of the work to delineate lateral extent of 1,4-dioxane concentrations across the NEPZ transect involved extending the Mississippi transect to the east and west and sampling for 1,4-dioxane and VOCs. A location for a permanent sentry well was determined in accordance with the Work Plan. | Additional piezometers to the east and west were installed in 2nd half 2017. Based on assessment of geological and chemical results from the piezometers, a permanent sentry well was installed, developed, and ultimately added to the North End GWMP. |

| **Work Plan to Cease Potable Water Injection at North Boundary Barrier Wall** (EMSI, 2018d) | **Status** |
|---|---|
| Cease potable water injection to evaluate the effectiveness of the NBBW without Potable Water Injection (PWI), as directed by USEPA in the fourth five-year review (USEPA, 2017). | WSDs began baseline sampling in June 2018 and continued sampling and collection of water levels through the first half of 2020. The cessation pilot-test was terminated in July 2019. |

| **Revised Work Plan to Further Assess the North End 1,4-Dioxane Plume** (EMSI, 2018a) | **Status** |
|---|---|
| Assess the northern and vertical extent of the 1,4-dioxane plume and update the Conceptual Site Model (CSM) of the North End area. Work scope includes Installing six wells (shallow and deep), collecting samples, and performing slug tests. | The Work Plan was implemented in 2018 and 2019 and a final report was prepared in 2020. The final report was approved by USEPA in September 2020. |


Effectiveness of the MW38 Area, NTES, and North End Response Actions, (EMSI/Parsons, 2021b) at the Site were evaluated as it related to findings and recommendations in USEPA's Fourth 5YRR (USEPA, 2017). Response Action objectives prescribed in work plans and notification documents for the North End are being met by ongoing groundwater extraction from the Response Actions and ongoing monitoring and sampling programs. System optimization is an ongoing component of operations and includes, but is not limited to, maximizing pumping from wells with the highest 1,4-dioxane concentrations; and cyclical pumping from wells whose concentrations meet the performance standard then rebound to above the performance standard.

## 4.9 GTEP Area Response Actions

Pumping from the GTEP extraction well (MW170-EW-1, Figure 4.33, Area 5) was initiated on January 9, 2012 and continued throughout the reporting period. During this reporting period, the pumping rate ranged between 12.8 gpm and 13.3 gpm, with

approximately 3.4 million gallons pumped during the period. Approximately 64.2 million gallons have been extracted since the start of pumping.

Figures 4.16 and 4.17 show the potentiometric surface configuration of the GTEP area during July and October 2021, respectively. In the center of the GTEP area, groundwater levels at MW170-WD (adjacent to extraction well MW170-EW-1) have been lowered by approximately 16 ft, compared to the January 2012 pre-pumping groundwater elevation of 5703.12 ft amsl. A hydrograph of MW170-WD (below) shows that hydraulic equilibrium was established at a pumping rate of about 13 gpm.




Figures 4.16 and 4.17 indicate that a cone of depression beneath the GTEP area remained throughout the reporting period. The 360-degree capture zone continued to prevent contaminants from migrating toward MW77-WD and MW62-WDR. Pumping rates were sustained during this reporting period.

MW171-WD located along the surface water diversion ditch east of the GTEP area shows a rise of 5 feet in groundwater level in response to March 2021 precipitation events. This well generally has a rapid rise in groundwater levels following precipitation events greater than ¾ of inch. Groundwater level response to is due to location of the well adjacent to diversion ditch, a 4-foot thick fine to very coarse sand interval intersected by the well screen, and surface water present in the diversion ditch. Groundwater levels in MW171-WD generally return to 5700 ft amsl following seasonal reduction of precipitation in the 3rd quarter of each year and does not stabilize until fourth quarter. For these reasons, groundwater level measured at MW171-WD in third quarter of 2021 was not used to interpret the potentiometric surface shown on Figure 4.16 and noted on the figure.

The inferred flow lines on Figure 4.17 indicate inward flow toward extraction well MW170-EW-1 from all directions. This hydraulic condition is meeting the specific response action objective of the RAWP (EMSI, 2011) "…to cease the potential seepage of contaminated groundwater from the sand channel toward well MW77-WD". The 1,4-dioxane concentration at compliance well MW77-WD has steadily decreased from 41 µg/L just prior to GTEP pumping to 11 µg/L on October 27, 2021. Baseline/initial and subsequent analytical results for all GTEP area wells are shown in Table 4.10. These results indicate that groundwater quality within and adjacent to the GTEP sand channel has improved since pumping began.

With regard to MW62-WDR, the well lies within the NBBW zone of containment shown on Figures 4.16 and 4.17. The NBBW CSE (EMSI/CDM/Parsons, 2021) determined that the NBBW effectively contains flow of contaminated groundwater within the alluvium/weathered bedrock groundwater unit. Any residual 1,4-dioxane remaining north of the containment zone will be captured by ongoing Response Action pumping north of the containment zone.

Statistical trend analyses of VOCs, 1,4-dioxane, and nitrate in well MW170-EW-1 are presented in Figure 4.42 and in the table below. 1,1-DCA, 1,1-DCE, 1,4-dioxane, PCE, and TCE showed statistically significant decreasing trends while cis-1,2-dichloroethene (cis-1,2-DCE) is showing an increasing trend; all other analytes were not trending.

**Trends in MW170-EW-1**

| Compound | Trend |
|---|---|
| 1,4-Dioxane | Decreasing |
| 1,1-DCA | Decreasing |
| 1,1-DCE | Decreasing |
| cis-1,2-DCE | Increasing |
| TCE | Decreasing |
| PCE | Decreasing |

## 5.0 LANDFILL GAS REMEDY

The current LFG extraction, collection and treatment system consists of the following components: 64 vertical gas extraction wells (EWs), header and lateral piping, three automatic and nine manual condensate traps, two flares, and the GTEP.

The original system began operation in October 1996. All LFG was treated by the Lowry Blower/Flare (LBF) station, which burned LFG in an enclosed flare. Since then, the system has been expanded to include additional extraction wells in both the Lowry and DADS landfills. Additional treatment devices have also been added to treat the combined gas flows from Lowry and DADS landfills.

The GTEP began operation in July 2008 and is a beneficial use treatment system that uses LFG to produce electricity. The DADS Blower/Flare (DBF) station, installed in 2010, burns LFG in an open flare. It began operation in August 2010.

In March 2015, the Lowry/DADS treatment system was updated with the installation of large capacity candlestick flare, referred to as Flare Station 3 (FS3). At that time, FS3 replaced the LBF station, which is currently decommissioned.

On June 4, 2019 the CDPHE approved a Title V Permit modification request to allow operation of the GTEP, DBF, and FS3 at full capacity, full time. The combined capacity of the three treatment units is approximately 3,800 standard cubic feet per minute (scfm). The modification was necessary to accommodate increasing gas volume generated from the DADS Section 32 landfill. This operational change is a departure from the previous routine of operating the DBF on an as needed basis only.

### 5.1 LFG Extraction, Collection, and Treatment System Operations

The current LFG extraction, collection and treatment system consists of vertical gas extraction wells and condensate traps and the GTEP and blower/flare stations.

#### 5.1.1 Extraction Wells and Collection System

The Lowry LFG extraction and collection system was monitored monthly (Appendix D-1). Of the sixty-four EWs at Lowry, sixty-one were online and three were shut down due to lack of gas production. Adjustments were made to wellhead valves as needed to compensate for changing methane, oxygen, carbon dioxide, and balance gas levels. Gas temperatures at the extraction wells remained stable during the reporting period with no initial gas temperature exceeding 101 degrees Fahrenheit (°F).

##### 5.1.1.1 Wellhead Vacuums

LFG extraction vacuums were monitored at both the wellhead and the collection system piping. Measurements and adjustments made to maintain system balance were recorded on the LFG Extraction Well Monitoring forms (summarized as Appendix D-1).

##### 5.1.1.2 Wellhead Gas Quality

LFG quality measurements (including methane, carbon dioxide, oxygen, and balance gas [mostly nitrogen]) were collected monthly from the 64 EWs. The overall gas quality remained stable within the well field and at the GTEP, DBF, and FS3 stations, as shown in Appendices D-1 and D-2.

### 5.1.1.3 Collection Piping

The table below shows the LFG oxygen concentrations measured at the Lowry Header Pipe and at each treatment device during the reporting period.

| LFG Oxygen Concentrations (% Volume) | | | |
|---|---|---|---|
| **Sample Point** | **Minimum** | **Average** | **Maximum** |
| Lowry Header Pipe | 0.8 | 2.2 | 3.5 |
| GTEP | 0.1 | 0.4 | 0.9 |
| DBF | 0.4 | 0.7 | 1.2 |
| FS3 | 0.1 | 0.5 | 0.9 |

Generally, oxygen readings up to 3% indicate integrity of the gas collection network. Monitoring data are provided in Appendices D-2.1 through D-2.4.

### 5.1.1.4 Condensate Traps

Automatic condensate traps were inspected weekly. Pulse counter and totalizing flow meter readings were recorded on the Weekly Service Records on file at the WTP. Monthly automatic condensate volumes measured at the T505 flow meter in the WTP are summarized below:

| Period | Condensate Processed (Gallons) |
|---|---|
| July | 948 |
| August | 1,035 |
| September | 755 |
| October | 1,562 |
| November | 666 |
| December | 430 |
| **Total** | **5,396** |

The integrity of the automatic traps and conveyance line to the WTP was monitored approximately weekly for volume production and pressure changes. All inspections and testing were documented on WTP checklists and/or in the daily operator logs. Completed checklists are provided in Appendix A-1. No operational problems were observed.

Manual condensate traps were inspected monthly. All manual traps appeared to be collecting condensate. No condensate was removed from the manual traps during the reporting period.

#### 5.1.1.5 Gas Collection System Maintenance

During the reporting period, minor maintenance was performed such as refreshing gas well ID markings.

### 5.1.2 GTEP and Blower/Flare Stations

During the reporting period, the GTEP, DBF, and FS3 stations provided treatment of extracted LFG. The GTEP, DBF, and FS3 operated for approximately 4,196 hours, 4,087 hours, and 4,180 hours, respectively.

During the reporting period, routine preventive maintenance such as fluid changes and engine overhauls were performed. On July 13, 2021, RKA performed a field calibration of the ABB flow meter at the GTEP. The flow meter was found to be in good working order with only minor adjustments needed to maintain accurate flow readings.

While the DBF and FS3 stations were operating, flare temperature, flow rate, methane content, and maintenance activities were recorded and are discussed below. Similar data were collected for the GTEP in accordance with the *Modified Construction Permit No. 06AR1264* issued by the CDPHE Air Pollution Control Division. Those data are retained at the GTEP and are available for inspection by USEPA and CDPHE.

#### 5.1.2.1 Flare Temperature

While combustion temperature was recorded, DBF and FS3 are open flares and not subject to combustion temperature requirements - only visual presence of a flame.

#### 5.1.2.2 Gas Flow Rate

For the reporting period, the combined average LFG flow from both Lowry and DADS Landfills was approximately 2,729 scfm. The combined average LFG flow was calculated by first summing the volume of LFG consumed by the GTEP, DBF, and FS3 stations. The sum was then divided by the difference between the total time during the reporting period and the total time that no treatment device was operating. Volume data for each treatment device were collected by fixed instruments on the discharge side of the blower or compressor.

The Lowry well field contributed approximately 5.7% of this flow and 94.3% was contributed by the DADS well field, as described in the Daily Status Reports in Appendix D-2.5. For the reporting period, the average flows for Lowry and DADS were 156 and 2,573 scfm, respectively.

#### 5.1.2.3 Methane Content

Methane content at the Lowry Header Pipe and at each treatment device was measured at least twice weekly when the treatment device was operating during regular business hours. The table below shows the LFG methane concentrations measured at the Lowry Header Pipe and at each treatment device during the reporting period.

**LFG Methane Concentrations (% Volume)**

| Sample Point | Minimum | Average | Maximum |
|---|---|---|---|
| Lowry Header Pipe | 23.9 | 28.4 | 39.4 |

| Sample Point | Minimum | Average | Maximum |
|---|---|---|---|
| GTEP | 50.8 | 53.5 | 57.4 |
| DBF | 32.6 | 39.2 | 48.4 |
| FS3 | 45.7 | 49.8 | 55.7 |

Monitoring data are provided in Appendices D-2.1 through D-2.4.

### 5.1.2.4 Blower/Flare Station Maintenance

Routine preventive maintenance such as blower rotations and lubrication were performed throughout the reporting period.

### 5.1.2.5 Additional Reporting Requirements

**(1) Value and length of time for exceedance of parameter(s) being monitored.** There were no events during the reporting period where vacuum was not observed at an extraction well.

In March 2013, a new operating procedure was approved for EWs-09, -10, and -23 due to oxygen concentrations exceeding 5.0%. The new operating procedure allows the wells to remain fully closed unless a gas concentration of greater than 30% methane and less than 2.0% oxygen are detected. The wells are temporarily opened to collect the gas readings each month. During the reporting period, EWs-09, -10, and -23 remained closed because they did not meet these operating criteria. The wells were turned on only to collect readings.

**(2) Description and duration of all periods when the gas stream is diverted from the treatment device through a bypass line or the indication of bypass flow as specified under §60.756.** There were no diversions during the reporting period.

**(3) Description and duration of all periods when the treatment device was not operating for a period exceeding 1 hour and length of time the treatment device was not operating.** There were three occurrence when all treatment devices were simultaneously offline (total system shutdown) for one hour or more during the reporting period.

**Treatment Device Shutdown Time**

| Date | Total Shutdown Time (hours) | Description |
|---|---|---|
| 9/7/21 | 5.17 | Power interruption |
| 9/6/21 | 19.58 | Power interruption |
| 8/30/21 | 1.08 | Power interruption |

**(4) All periods when the collection system was not operating in excess of 5 days.** There were no periods where the collection system was not operational in excess of 5 days during the reporting period.

**(5) The location of each exceedance of the 500 parts per million methane concentration as provided in §60.753(d) and the concentration recorded at each location for which an exceedance was recorded in the previous quarter.** This requirement is not applicable to Lowry.

**(6) The date of installation and the location of each well or collection system expansion added pursuant to paragraphs (a)(3), (b), and (c)(4) of §60.755.** No collection system expansion activities occurred during the reporting period.

### 5.2 LFG Extraction, Collection, and Treatment System Monitoring

Monitoring activities during the reporting period consisted of collecting gas composition samples at the GTEP, DBF, and FS3 as well as POC probes as discussed in the following subsections.

#### 5.2.1 Flare Sampling

Methane, carbon dioxide, oxygen, and balance gas monitoring at the Lowry header pipe, DBF and FS3 stations was performed at least once weekly during regular business hours while the treatment devices were operating and a technician was available. Results are summarized in Appendices D-2.1 through D-2.4. Monitored parameters were generally within normal historical ranges.

No other gas sampling was performed during the reporting period. No odor evaluation was performed at the flares during the reporting period.

#### 5.2.2 GTEP Inlet Sampling

Methane, carbon dioxide, oxygen, and balance gas monitoring were performed at the GTEP at least twice weekly during regular business hours while the treatment device was operating, and a technician was available. A summary of GTEP monitoring results is provided in Appendix D-2. Monitored parameters were within normal historical ranges.

No inlet gas sampling was performed during the reporting period. No odor evaluation was performed at the GTEP during the reporting period.

#### 5.2.3 GTEP Outlet Sampling

No outlet sampling at the GTEP exhaust was performed during the reporting period.

#### 5.2.4 POC Probe Sampling

POC probe locations are shown in Figure 5.1. The last biennial sampling event for VOCs was performed in May 2021. POC probes were not sampled for VOCs this reporting period.

The POC probes were sampled quarterly for methane (Appendix D-3). All concentrations were below the methane performance standard of 5% by volume.

## 6.0 STORMWATER

The following subsections discuss performance monitoring of the Surface Water Removal Action (SWRA) and stormwater monitoring.

### 6.1 Surface Water Removal Action

As discussed in Subsection 4.2.1, the depth to groundwater within the alluvium/weathered Dawson beneath the SWRA (which extends between the NTES and WTP access road) is approximately 10 ft bgs. The SWRA blanket drain typically lies between two and four ft bgs. Consequently, the water table is beneath the base of the SWRA blanket drain, so clogging of the drain is not a concern.

### 6.2 Stormwater Monitoring

Annual stormwater sampling in accordance with the *Stormwater Monitoring Plan* (EMSI, 2008a) was not performed during the reporting period. Stormwater will be sampled in the next reporting period if sufficient flow is available to activate the stormwater sampler. The stormwater sampling location (SWMP-1) is shown on Figure 6.1.

#### 6.2.1 Sampling

Stormwater sampling was not performed during this reporting period.

#### 6.2.2 Stormwater Discharge Rate

A stormwater discharge rate was not estimated because sampling was not performed during this reporting period.

## 7.0 COVER MONITORING

Inspection and maintenance of the Site is required by the *Final Operations and Maintenance Manual, Covers and Stormwater* (EMSI, 2007a). Inspections are conducted to identify and repair problems arising from nuisance conditions, settlement, cover or ditch erosion, ditch sedimentation, and damage to security fences and gates. The following sections discuss the Site and buffer zone inspections and maintenance performed during this reporting period.

### 7.1 Landfill Cover

#### 7.1.1 Site and Landfill Cover Inspection

A Site-wide inspection is required annually and after any event that may cause release of waste material. The following remedial components are inspected:

- The landfill prism;
- The traffic cap covering the East/South/West (ESW) slurry wall;
- The SWRA collection system cover (including surface features of the NTES trench);
- The waste pit area; and
- The stormwater conveyance ditches.

No formal inspections were warranted in the second half of 2021, as the site experienced dry and warm drought conditions during the reporting period. However, some preventive maintenance was performed and is discussed in more detail below. Larger areas of thistle noted on the June 21, 2021 formal cover inspection were treated with herbicide in August 2021.

#### 7.1.2 Landfill Cover Maintenance Activities

Cover maintenance during the second half 2021 was performed to fill shallow areas noted as near flat or possibly low in the form of importing approximately 930 cy of clean topsoil to fill shallow areas with the greatest potential for ponding. Weed mitigation in the form of spot spraying was performed as necessary in accordance with the *Integrated Weed Management Plan for Lowry Landfill Superfund Site and Buffer Properties* (Parsons, 2009).

Due to a noticeable decline in the prairie dog population due to control measures performed in November 2020 in surrounding areas and within Section 6, mitigation was not required during the reporting period.

### 7.2 Buffer Zones

#### 7.2.1 Buffer Zone Inspections

Formal quarterly inspections of the buffer zones surrounding the Site were conducted in August and November 2021 (Appendices E-2.1 and E-2.2, respectively). Inspections focused on the integrity of security fencing, removal of trash and debris, potential soil erosion, wildlife management, and noxious weed management. Items of concern included areas of damaged barbed wire fencing.

Inspection reports provide photographs of items of concern and their locations on a property map (Appendices E-2.1 and E-2.2).

### 7.2.2 Buffer Zone Maintenance Activities

Fence repairs in areas of concern were successfully performed during the reporting period.

A noticeable increase in the prairie dog population within the buffer zone property warrants mitigation to resume in the Spring of 2022.

## 8.0 REMEDIAL ACTION

Remedial actions have been completed for all remedy components except for groundwater, which has received Interim Completion for the groundwater monitoring program. Groundwater monitoring is continuing in accordance with the USEPA-approved GWMP (EMSI/Parsons, 2018).

## 9.0 PROBLEMS ENCOUNTERED, RECOMMENDATIONS, AND MASTER SCHEDULE

Problems and recommendations associated with ongoing O&M activities are presented in this section, as well as an updated Master Schedule for Site activities and action items associated with USEPA's 2017 5YRR. The master schedule is presented as Figure 9.1.

### 9.1 Problems Encountered

The status of issues and recommendations identified in USEPA's Fourth Five Year Review is summarized below:

| Issue Number | Recommendation | Status |
|---|---|---|
| 1 | Cease potable water injection and evaluate effectiveness of NBBW groundwater extraction system. | WSDs submitted the *Revised Final Report on Pilot Test for Cessation of Potable Water Injection* (EMSI/CDM-Smith, 2020a). USEPA approved the document on June 26, 2020.<br>WSDs submitted the *NBBW Containment System Evaluation* (EMSI/CDM-Smith/Parsons, 2021). USEPA approved the document on October 11, 2021. |
| 2 | Increase capacity of WTP. | Completed on February 1, 2019. |
| 3 | Evaluate effectiveness of groundwater remedy components on-site and off-site and optimize, as necessary | Effectiveness Evaluations for the MW38 Area, NTES, North End Response Actions, and Perimeter Barrier Wall were prepared during the reporting period. USEPA approval was achieved in January 2021.<br>WSDs submitted the *NBBW Containment System Evaluation* (EMSI/CDM-Smith/Parsons, 2021). USEPA approved the document on October 11, 2021. |
| 4 | Sample and analyze four wells located within and immediately adjacent to the 1,4-dioxane plume and implement appropriate remedial actions. Clarify if closure of abandoned wells was performed in accordance with Rule 16 of the 2CCR 402-2. Provide a Work Plan for detailing how potential at-risk-receptors will be | WSDs submitted the *Final Technical Memorandum, Identification and Sampling of Water Supply Wells Within and Immediately Adjacent to Off-Site 1,4-Dioxane Plume* (EMSI, 2020d). USEPA approved the document on June 26, 2020. |

| Issue Number | Recommendation | Status |
|---|---|---|
| | effectively identified and addressed. | |
| 5 and 6 | Add 1,4-dioxane to the COC list for groundwater remedy effectiveness monitoring and remove iron from the COC list for groundwater compliance monitoring. | WSDs submitted *Groundwater Monitoring Plan, Revision 2 (*EMSI/Parsons, 2018). USEPA approved the document on September 6, 2018. |
| 7 and 9 | Develop an updated map and conceptual site model of the off-site 1,4-dioxane plume. Evaluate need for and scope of additional monitoring and additional institutional controls for the plume area. | WSDs submitted *Technical Memorandum, Updated 1,4-Dioxane Plume Map and North End Conceptual Model, 2017 Five-Year Review Issues #7 and #9* (EMSI/CDM-Smith, 2020c). The memorandum included a Risk Summary prepared by USEPA that concluded the plume posed no unacceptable risk to human health. USEPA approved the document.<br><br>WSDs also submitted *North End Groundwater Monitoring Plan – Update No.2* (EMSI, 2020b). USEPA approved the document on October 16, 2020.<br><br>WSDs also submitted *North End Groundwater Monitoring Plan – Update No. 3* (Parsons, 2021b). USEPA approved the document on September 22, 2021.<br><br>USEPA, with support and concurrence from CDPHE, TCHD, and WSDs, prepared a Conceptual Site Model Update document to augment the response to Item 7. The CSM Update was finalized October 12, 2021.<br><br>USEPA determined that no additional institutional controls are necessary. |
| 8 | Reevaluate subsurface gas performance standards utilizing updated toxicity values and Site-specific input data. | WSDs submitted *Revision 3, Updated Compliance Monitoring Plan, Landfill Gas Remedy* (EMSI, 2018e). USEPA approved the document on August 2, 2018 |

Thus, as of the end of this reporting period all Fourth FYR issues have been addressed.

During previous reporting periods, WSDs assessed vertical and lateral limits of elevated molybdenum in the B326/MW113 area, determined the source to be naturally-occurring, added a second extraction well to the B-326/MW113 groundwater area so that 1,4-dioxane mass from this area could continue to be removed, and conducted treatability studies to remove molybdenum from MW113-EW-1 water before it enters the main treatment train of the WTP. WSDs prepared *Technical Memorandum – Molybdenum in NBBW Groundwater, Evaluation of Potential Sources of Elevated Molybdenum in Wells MW113-WD and MW113-EW-1* (EMSI/CDM Smith, 2020b) documenting the extent and possible sources of molybdenum. The memorandum concluded that the source was naturally occurring. Monitoring and testing of the molybdenum pretreatment system were performed during the reporting period.

## 9.2 Recommendations

### 9.2.1 Recommendations for Slurry Wall Areas

Continue to monitor groundwater levels in all effectiveness monitoring well pairs. For well pairs that do not demonstrate inward gradients across the wall, collect water quality samples from the external well (PM-X series well) to assess the effectiveness of the perimeter slurry wall in these areas.

### 9.2.2 Recommendations for NTES, NBBW, and MW38 Areas

Continue to pump and treat groundwater from these areas. For the NTES, continue to operate the product skimming system when product thickness greater than six inches is observed in the trench.

For the NBBW area, continue to collect, evaluate, and report potentiometric and water quality data, per the *Final Technical Memorandum: Post-Cessation Pilot Test Monitoring* Plan (EMSI/CDM-Smith, 2020d)

### 9.2.3 Recommendations for Off-Site North End Response Actions

Continue to optimize ongoing groundwater extraction in off-Site Areas 1, 2, and 3 in accordance with their respective RAWPs. This may include increasing extraction rates, as discussed above.

### 9.2.4 Recommendations for Sitewide Monitoring Plan – Compliance Monitoring

As discussed in Subsections 4.4.2, eight monitoring locations were found to contain one or more compliance parameters in excess of a performance standard. The eight wells determined to be statistically out of compliance or potentially out of compliance are summarized below.

| Well | Compound | Compliance Decision |
|---|---|---|
| B-313 | 1,4-Dioxane | Out of compliance |
| B-313 | Nitrate | Out of compliance |
| B-326-UD | 1,4-Dioxane | Out of compliance |
| B-326-WD | 1,4-Dioxane | Out of compliance |
| BM-11X-100N | PCE | Potentially Out of compliance |
| BM-15N6 | Nitrate | Potentially Out of compliance |

| Well | Compound | Compliance Decision |
|---|---|---|
| MW38-830N-230E | 1,4-Dioxane | Potentially Out of compliance |
| MW38-830N-230E | Chloroform | Potentially Out of compliance |
| MW62-WDR | 1,4-Dioxane | Potentially Out of compliance |
| MW62-WDR | Nitrate | Out of compliance |
| MW62-WDR | Nitrite | Potentially Out of compliance |
| MW77-WD | 1,4-Dioxane | Out of compliance |

Recommendations relative to non-compliance with performance standards at these locations are discussed in the following sections.

#### 9.2.4.1 1,4-Dioxane in the NBBW Area

1,4-Dioxane occurs in excess or potentially in excess of its performance standard in five NBBW-area compliance monitoring wells (B-313, B-326-UD, B-326-WD, MW62-WDR, and MW77-WD).

The WSDs will continue to monitor both the 1,4-dioxane concentrations and the water level in these wells and continue to evaluate conditions in this area. Continued pumping from extraction wells MW113-EW-1, NBBW-IW-3, MW113-UD, B-321, MW170-EW-1, and MW-77 area wells is recommended.

With regard to the MW62-WDR area, this well lies within the zone of containment caused by groundwater extraction from the NBBW and Response Actions north and east of the NBBW (see Figures 4.16 and 4.17). Consequently, the exceedances may be a Case 2 condition, which requires only long-term monitoring. As required by the Fourth 5YRR (USEPA, 2017), the WSDs conducted additional evaluations of the effectiveness of the NBBW containment system and the Response Actions in the NBBW area as part of the CSE. That evaluation (EMSI/CDM-Smith/Parsons, 2021) determined that the NBBW effectively contains flow of contaminated groundwater within the alluvium/weathered bedrock groundwater unit. In the meantime, 1,4-dioxane that might have migrated north of the containment zone will be captured by ongoing Response Action pumping north of the containment zone.

#### 9.2.4.2 Nitrate and Nitrite in the NBBW Area

Nitrate is out of compliance in monitoring wells B-313 and MW62-WDR (Figure 4.11). Nitrite is potentially out of compliance in well MW62-WDR. These wells are located along the northern boundary of the Site, in an area where sewage sludge was historically land farmed.

The extent of nitrate and nitrite exceedances has been determined to be limited to the eastern portion of the NBBW area (i.e., in the immediate vicinity of compliance monitoring wells B-313 and MW62-WDR). Therefore, there does not appear to be a potential for significant off-Site migration of nitrate or nitrite at concentrations greater than the performance standard.

To the extent that the nitrate and nitrite occurrences do not result from a source in the immediate vicinity of these wells (i.e., impacts from prior land farming of sewage sludge in this area), implementation of response actions for 1,4-dioxane should also address these compounds in this area. To the extent that the cause of the nitrate and nitrite occurrences in these wells is due to impacts from prior land farming of sewage sludge in this area, the

response actions being undertaken in this area may or may not reduce their concentrations in groundwater. Nonetheless, groundwater extraction from North End wells further downgradient should capture any potential migration of nitrate and nitrite from the NBBW area if northern migration were to occur.

#### 9.2.4.3 MW38-830N-230E

Chloroform and 1,4-dioxane concentrations in monitoring well MW38-830N-230E potentially exceed their respective groundwater performance standards. Decreasing trends in the concentrations of these chemicals were identified in this well. This well is located along the POC at the north end of the MW38 channel. The hydraulic gradient within the channel at this location is to the north so migration of these chemicals crosses the POC. As part of the groundwater containment remedy for the Site, groundwater extraction is conducted from the MW38 channel at two locations, including a location approximately 200 ft north of well MW38-830N-230E, which is downgradient from and beyond the POC relative to the compliance monitoring well. Therefore, although these chemicals may migrate across the POC, impacted groundwater is hydraulically contained within the sand channel in the area immediately north of well MW38-830N-230E. No action other than continued extraction and monitoring of the compliance well is required for these occurrences.

#### 9.2.4.4 Nitrate in BM-15N6

Nitrate occurs in well BM-15N6 at concentrations greater than its performance standard. Statistical testing indicates that there is a decreasing trend in nitrate concentrations in this well. As discussed in Subsection 4.4.2.4 of this report, this well is located in an area where sewage sludge had historically been land-farmed. USEPA positioned the compliance boundary within the land farming area such that it straddles the land farming area. That, coupled with an absence of 1,4-dioxane and only low-level detections of VOCs below performance standards since 2003 in this well, would indicate the source of nitrates is not from landfill mass or waste pit contaminant migration; rather, it is likely from the past land farming activities inside and outside the compliance boundary. Nitrate has been observed in surrounding wells BM-15N2 (43,000 µg/L), BM-15NE1 (26,000 µg/L), BM-15N5 (68,000 µg/L) and BM-15N1 (25,000 µg/L) (1$^{st}$ Half 2017) and BM-15I-15N (54000 µg/L), BM-15I-50S (9,300 µg/L), and BM-15X-50S (38,000 µg/L) (October 2018) The spatial randomness of nitrate detections in and around well BM-15N6 as compared to other compliance wells in this vicinity is similar to that observed near the NBBW where sewage sludge was land farmed.

Because 1) the source of the nitrate occurrences in well BM-15N6 is most likely a result of sewage sludge land farming in this area, 2) groundwater is actively being extracted from this area, and 3) the distance between this well and the Site boundary is approximately 200 feet, the occurrence of nitrate in well BM-15N6 is considered to be a Case 2 condition as defined in the GWMP (EMSI/Parsons, 2018). No action other than continued groundwater monitoring is recommended.

#### 9.2.4.5 Tetrachloroethene in BM-11X-100N

PCE in BM-11X-100N is potentially out of compliance with an increasing trend. The ten most recent PCE concentrations in this well range from a low of 4.6 µg/L in October 2017 to a high of 7.2 µg/L (October 2020) with the most recent sample containing a PCE concentration of 5.4 µg/L (October 28, 2021). PCE levels appeared to slowly increase

from October 2017 to November 2020 but have dropped in the last two sampling events. The variation in PCE concentrations appears to be related to changes in the water level in this well. Prior to the summer of 2015, the water level in this well was relatively stable ranging from approximately 5,790 to 5,795 ft amsl. Beginning in the summer of 2015, the water level in this well increased, peaking at a high of just over 5,800 ft amsl in July 2017. Since that time, the water level in this well has declined back below 5,792 ft amsl. Consequently, it is likely that the increase in PCE levels in this well may be the result of flushing of residual PCE contained in the capillary fringe/vadose zone. If this is the case, then the PCE level in this well should decline over time as evidenced by the drop in concentration of the most recent PCE result from 7.2 µg/L in November 2020 to 5.4 µg/L in October 2021.

The overall low concentration of PCE in well BM-11X-100N, in addition to an inward gradient across the wall at this location, and no or very low PCE detections in groundwater to the north and northeast of the well indicate that the PCE occurrences in this area represent a Case 2 condition (little or no downward trend with a low potential for off-Site migration) as defined in the GWMP (EMSI/Parsons, 2018). The WSDs previously completed a Case 2 evaluation for this well (EMSI, 2006b). Results indicated that it is unlikely that the PCE occurrences above the performance standard in this area will migrate to the Site boundary. Rather, PCE occurrences in this area will likely attenuate naturally over time. Consequently, the recommended action is to continue monitoring.

### 9.2.5 Recommendations to Voluntary Actions

As discussed in Subsection 4.6 of this report, the following voluntary measures will continue to be implemented by the WSDs during the next reporting period:

1. Continue pumping of the MW38 Area source well (MW38-825S-445E).
2. Continue to operate groundwater extraction systems for gradient control in the PM-11, PM-15, and MW51 areas, as appropriate. In addition, continue to operate air sparging operations in the PM-15 and MW51 areas.
3. Continue to skim LNAPL from the surface of groundwater in the NTES trench, if present.
4. Continue to optimize removal of 1,4-dioxane within the WTP.

## 9.3 Schedule of Planned Activities

See Figure 9.1 Master Schedule for an update of planned activities. Please note that the timelines and milestone list in Gantt chart for the 5YRR are subject to change based on agency review timeframes and level of effort needed to respond to agency comments. The schedule reflects USEPA-approved revised 5YRR milestone dates.

## 10.0 REFERENCES


EMSI, 2006a. Memorandum – North End Work Plan for Initial Response Action (Installation of Two Extraction Wells), Lowry Landfill Superfund Site. October 19.

EMSI, 2006b. Memo to Evaluate Potential TCE Migration in PM-11 Area, Lowry Landfill Superfund Site. June 6.

EMSI, 2007a. Final Operations and Maintenance Manual, Covers and Stormwater, Lowry Landfill Superfund Site. January 25.

EMSI, 2007b. North End Groundwater Monitoring Plan, Lowry Landfill Superfund Site. July 6.

EMSI, 2007c. Memorandum – Work Plan for MW77 Area Response Action, Lowry Landfill Superfund Site. March 5.

EMSI, 2008a. Stormwater Monitoring Plan, Lowry Landfill Superfund Site, April 30.

EMSI, 2008b. Revised North End Initial Response Action (IRA) Work Plan Addendum, Lowry Landfill Superfund Site. February 22.EMSI, 2008c. Updated Early Warning Monitoring Plan, Lowry Landfill Superfund Site. December 22.

EMSI, 2008c. Updated Early Warning Monitoring Plan, Lowry Landfill Superfund Site. December 22.

EMSI, 2010a. Notification of Work to Extract Additional Groundwater from Area 3 for the North End Response Action. November 19.

EMSI, 2010b. Proposed Voluntary Action to More Efficiently Manage and Maintain the North Boundary Barrier Wall Containment Zone in Conjunction with Mass Removal of 1,4-Dioxane Immediately North of the Containment Zone. July 27.

EMSI, 2011. Response Action Work Plan to Extract Additional Groundwater from Upgradient of MW77-WD, Lowry Landfill Superfund Site. November 1.

EMSI, 2013. Response Action Work Plan, B-326-UD and B-313 Areas, Lowry Landfill Superfund Site. April 4.

EMSI, 2014. Work Plan to Assess Northern Extent of 1,4-Dioxane in Shallow Groundwater (North of Well MW144-WD), Lowry Landfill Superfund Site. November 10.

EMSI, 2015. Metro Letter of Understanding, Early Warning Monitoring Plan, Table B.1, Lowry Landfill Superfund Site. January 8.

EMSI, 2016. Work Plan to Sample North End Wells, Piezometers and Surface Water Lowry Landfill Superfund Site. January 22.

EMSI, 2017. Revision 1, Addendum to Work Plan to Assess Northern Extent of 1,4-Dioxane. July 27.

EMSI, 2018a. Revised Work Plan to Further Assess the North End 1,4-Dioxane Plume and Update Conceptual Model for North End Area, Lowry Landfill Superfund Site. November 8.

EMSI, 2018b. Work Plan for 3DVA Synoptic Sampling Event, Lowry Landfill Superfund Site. July 13.

EMSI, 2018c. Addendum 1 to Work Plan for 3DVA Synoptic Sampling Event, Lowry Landfill Superfund Site. September 12.

EMSI, 2018d. Final Pilot Test Work Plan to Temporarily Cease Potable Water Injection North of the North Boundary Barrier Wall, Lowry Landfill Superfund Site, Arapahoe County, Colorado. October 1.

EMSI, 2018e. Revision 3, Updated Compliance Monitoring Plan, Landfill Gas Remedy, Lowry Landfill Superfund Site. July 27.

EMSI, 2020a. Revision 4, Updated Compliance Monitoring Plan, Landfill Gas Remedy, Lowry Landfill Superfund Site. February 10.

EMSI, 2020b. North End Groundwater Monitoring Plan – Update No. 2, Lowry Landfill Superfund Site. October 16.

EMSI, 2020c. Updated Waste Management Plan, Lowry Landfill Superfund Site. October 14.

EMSI, 2020d. Final Technical Memorandum, Identification and Sampling of Water Supply Wells Within and Immediately Adjacent to Off-Site 1,4-Dioxane Plume, Lowry Landfill Superfund Site. June 3.

EMSI, 2021. Revision 3, Operations and Maintenance Manual, Landfill Gas Remedy Lowry Landfill Superfund Site (with addendum). February 9.

EMSI/CDM-Smith, 2019. Updated 1,4-Dioxane Plume Map and North End Conceptual Model, 2017 Five-Year Review Issue #6, Lowry Landfill Superfund Site. October 16.

EMSI/CDM-Smith, 2020a. Revised Final Report on Pilot Test for Cessation of Potable Water Injection, Lowry Landfill Superfund Site, Arapahoe County, Colorado. May 15.

EMSI/CDM-Smith, 2020b. Technical Memorandum – Molybdenum in NBBW Groundwater, Evaluation of Potential Sources of Elevated Molybdenum in Wells MW113-WD and MW113-EW-1, July 23.

EMSI/CDM-Smith, 2020c. Technical Memorandum, Updated 1,4-Dioxane Plume Map and North End Conceptual Model, 2017 Five-Year Review Issues #7 and #9, Lowry Landfill Superfund Site. October 16, 2019; Revision September 2, 2020

EMSI/CDM-Smith, 2020d. Final Technical Memorandum: Post-Cessation Pilot Test Monitoring Plan, Lowry Landfill Superfund Site, March 31.

EMSI/CDM-Smith/Parsons, 2019. North Boundary Barrier Wall Containment System Evaluation Plan, Lowry Landfill Superfund Site.

EMSI/CDM-Smith/Parsons, 2021. North Boundary Barrier Wall, Containment System Evaluation, Lowry Landfill Superfund Site. September 21.

EMSI/Parsons, 2018. Revision 2, Groundwater Monitoring Plan, Lowry Landfill Superfund Site. August 16.

EMSI/Parsons, 2021a. Technical Memorandum, Effectiveness Evaluation for Perimeter Barrier Wall, 2017 Five-Year Review Issue #3, Lowry Landfill Superfund Site. January 20.

EMSI/Parsons, 2021b. Technical Memorandum, Effectiveness Evaluations for MW38 Area, North Toe Extraction System, and North End Response Actions, 2017 Five-Year Review Issue #3, Lowry Landfill Superfund Site. January 22.

USEPA, 1994a. EPA Contract Laboratory Program National Functional Guidelines for Organic Data Review (as amended). December.

USEPA, 1994b. EPA Contract Laboratory Program National Functional Guidelines for Inorganic Data Review (as amended). February.

USEPA, 1994c. Record of Decision Lowry Landfill Superfund Site, Arapahoe County, Colorado. March.

USEPA, 2002. Minor Modification of the March 10, 1994 Record of Decision, Lowry Landfill Superfund Site, Arapahoe County, Colorado. September.

USEPA, 2004. Multi-Agency Radiological Laboratory Analytical Protocols Manual, Center for Environmental Assessment, Office of Research and Development. July.

USEPA, 2017. Fourth Five-Year Review Report for Lowry Landfill Superfund Site Arapahoe County, Colorado. September 28.

Harding Lawson Associates, 1992. Final Remedial Investigation Report for the Shallow Groundwater and Subsurface Liquids and Deep Groundwater Operable Units, Lowry Landfill, Arapahoe County, Colorado. March 25.

Metro, 2020. Metro Wastewater Reclamation District and Industrial Wastewater Discharge Permit No. 2360-6, issued to City and County of Denver and Chemical Waste Management, Inc/Waste Management of Colorado, Inc., for the Lowry Landfill Superfund Site. Effective January 5, 2020. January 3.

Parsons, 2005. Final MW38 Area Pilot Test Report Lowry Landfill Superfund Site. April 15.

Parsons, 2009. Integrated Weed Management Plan for Lowry Landfill Superfund Site and Buffer Properties. November.

Parsons, 2020a. Technical Memorandum – Molybdenum Removal at Lowry Landfill Superfund Site. July 17.

Parsons, 2021a. Revision 3, Operations and Maintenance Manual Groundwater Extraction, Lowry Landfill Superfund Site. August 23.

Parsons, 2021b. North End Groundwater Monitoring Plan – Update No. 3, Lowry Landfill Superfund Site. August 23.

Parsons, 2021c. Technical Memorandum - Anion Exchange Operational Performance at Lowry Landfill Superfund Site. September 24.

Parsons/EMSI, 2021. Addendum No. 7 to Operations and Maintenance Manual, Water Treatment Plant, Lowry Landfill Superfund Site. March 26.

# TABLE 2.1
# WATER TREATMENT PLANT SAMPLING SCHEDULE
## JULY THROUGH DECEMBER 2021 OPERATIONS AND MAINTENANCE STATUS REPORT
## LOWRY LANDFILL SUPERFUND SITE

| | MP-001 (WTP Effluent) | | | | | Early Warning Influent (grab) TP-110, TP-120, TP-140, TP-150, TP-160, TP-170, TP3310 | Early Warning Influent (grab) TP-110, TP-120, TP-140, TP-150, TP-160, TP-170, TP3310 | Early Warning Influent (grab) TP-110, TP-120, TP-140, TP-150, TP-160, TP-170, TP3310 | Early Warning Influent (composite) |
|---|---|---|---|---|---|---|---|---|---|
| **Sampling Date** | **Monthly 24-Hour Grabs[a/]** | **Monthly Composite[b/]** | **Quarterly 24-Hour Grabs[a/]** | **Quarterly Composite[a/]** | **Yearly Composite[a/]** | **Monthly** | **Quarterly[c/]** | **Yearly** | **Yearly[d/]** |
| **July 6, 7 2021** | X | | X | X | | X | X | | |
| **August 2, 3 2021** | X | X | | | | X | | | |
| **September 7, 8 2021** | X | X | | | | X | | | |
| **October 4, 5 2021** | X | | X | X | | X | X | | |
| **November 2, 3 2021** | X | X | | | | X | | | |
| **December 6, 7 2021** | X | X | | | | X | | | |
| **January 2022** | X | | X | X | | X | X | | |
| **February 2022** | X | X | | | | X | | | |
| **March 2022** | X | X | | | | X | | | |
| **April 2022** | X | | X | X | X | X | X | X | X |
| **May 2022** | X | X | | | | X | | | |
| **June 2022** | X | X | | | | X | | | |
| **Analytical Methods** | 1,4-Dioxane (8260 SIM)<br>pH (pH-740 one time at start of 24 hours) | Molybdenum (200.8) | VOCs (EPA 624.1)<br>Nonylphenols, Total (ASTM D7065_11) | SVOCs (EPA 625.1)<br>Metals[e/] (200.7, 200.8)<br>Gross alpha/beta<br>Plutonium-238,239,240<br>Americium-241<br>Radium - 226,228,Total | Metals[e/] (200.7, 200.8)<br>Mercury (245.1) | 1,4-Dioxane (8260 SIM)<br>Molybdenum (200.8) | VOCs (EPA 624.1) | Nonylphenols Total (ASTM D7065_11) | SVOCs (EPA 625.1)<br>Metals[f/] (200.7, 200.8)<br>Mercury (7470)<br>Gross alpha/beta<br>Americium-241<br>Plutonium-238,239,240<br>Radium - 226,228,Total |

a/ Individual compounds and frequency are listed in Industrial Discharge Permit No. 2360-6, issued by the Metro Wastewater Reclamation District (Metro), effective January 5, 2020 to January 4, 2025

b/ monthly sampling of molybdenum performed for performance monitoring, not required by the Discharge Permit

c/ equivalent to MP-001 VOC quarterly list

d/ equivalent to MP-001 yearly list

e/ Quarterly Metals - Molybdenum, Zinc and Selenium

f/ Yearly Metals - Arsenic, Cadmium, Chromium, Copper, Lead, Nickel and Silver

**TABLE 4.1**
**SUMMARY OF DRILLING ACTIVITIES COMPLETED**
**JULY THROUGH DECEMBER 2021 OPERATIONS AND MAINTENANCE STATUS REPORT**
**LOWRY LANDFILL SUPERFUND SITE**

| Well/Boring ID | Date of Installation | Date Abandoned | Type[a/] of Well/Boring | Northing[b/] | Easting[b/] | Ground Surface Elevation | Measuring Point Elevation | Screened Interval | Total Depth |
|---|---|---|---|---|---|---|---|---|---|
| | | | | (feet) | (feet) | (ft NGVD)[c/] | (ft NGVD) | (ft bgs)[d/] | (ft bgs) |
| **Installed Wells** | | | | | | | | | |
| None | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| **Abandoned Wells** | | | | | | | | | |
| None | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |

a/ Type: BH = borehole, MW = monitoring well, TMW = temporary monitoring well, PZ = piezometer, EW = extraction well, MPE = multiphase extraction well

b/ Locations referenced to Modified State Plane Coordinate System (in feet).

c/ ft NGVD = elevation (in feet) referenced to the National Geodetic Vertical Datum of 1929.

d/ ft bgs = feet below ground surface.

**TABLE 4.2**
**WATER LEVEL ELEVATIONS**
**JULY THROUGH DECEMBER 2021 OPERATIONS AND MAINTENANCE STATUS REPORT**
**LOWRY LANDFILL SUPERFUND SITE**

| Well ID | Date of Measurement | Water-Surface Elevation (ft NGVD)[a/] | Measured Depth to Water (ft below MP)[b/] | Depth to Water (ft bgs)[c/] | Measuring Point Elevation (ft NGVD) | Stickup (ft)[d/] | Screened Interval (ft bgs) | Total Depth (ft bgs) | Base of Weathering (ft bgs) | Formation[e/] |
|---|---|---|---|---|---|---|---|---|---|---|
| A-102 | 7/8/2021 | 5,703.43 | 20.18 | 17.59 | 5,723.61 | 2.59 | 10.4-30.3 | 35 | 32 | ALLUVIUM/WD |
| A-102 | 10/4/2021 | 5,703.42 | 20.19 | 17.6 | 5,723.61 | 2.59 | 10.4-30.3 | 35 | 32 | ALLUVIUM/WD |
| A-115 | 7/7/2021 | 5,697.26 | 13.49 | 11.27 | 5,710.75 | 2.22 | 6.9-13.5 | 21 | NE[f/], >21 | ALLUVIUM/WD |
| A-115 | 10/4/2021 | 5,696.60 | 14.15 | 11.93 | 5,710.75 | 2.22 | 6.9-13.5 | 21 | NE, >21 | ALLUVIUM/WD |
| B-215-WD | 7/7/2021 | 5,702.04 | 33.88 | 31.46 | 5,735.92 | 2.42 | 34-36 | 39 | 36.5 | WD |
| B-215-WD | 10/4/2021 | 5,701.99 | 33.93 | 31.51 | 5,735.92 | 2.42 | 34-36 | 39 | 36.5 | WD |
| B-304 | 7/7/2021 | 5,699.20 | 27.59 | 27 | 5,726.79 | 0.59 | 24-34 | 39 | 37 | WD |
| B-304 | 10/4/2021 | 5,697.00 | 29.79 | 29.2 | 5,726.79 | 0.59 | 24-34 | 39 | 37 | WD |
| B-304-UD | 7/7/2021 | 5,688.91 | 39.73 | 37.59 | 5,728.64 | 2.14 | 58-78 | 80 | 36.5 | UNWD |
| B-304-UD | 10/4/2021 | 5,687.91 | 40.73 | 38.59 | 5,728.64 | 2.14 | 58-78 | 80 | 36.5 | UNWD |
| B-305R | 7/7/2021 | 5,691.83 | 32.9 | 30.47 | 5,724.73 | 2.43 | 28-38 | 41 | 27 | UNWD |
| B-305R | 10/4/2021 | 5,691.76 | 32.97 | 30.54 | 5,724.73 | 2.43 | 28-38 | 41 | 27 | UNWD |
| B-305WD | 7/7/2021 | Dry | Dry | Dry | 5,723.77 | 1.87 | 13-23 | 28 | 23 | WD |
| B-305WD | 10/4/2021 | Dry | Dry | Dry | 5,723.77 | 1.87 | 13-23 | 28 | 23 | WD |
| B-306 | 7/8/2021 | 5,690.82 | 18.75 | 15.88 | 5,709.57 | 2.87 | 28.5-38.5 | 43.5 | 22 | UNWD |
| B-306 | 10/4/2021 | 5,690.23 | 19.34 | 16.47 | 5,709.57 | 2.87 | 28.5-38.5 | 43.5 | 22 | UNWD |
| B-307 | 7/8/2021 | Dry | Dry | Dry | 5,708.83 | 1.34 | 15-20 | 22 | NE, >22 | WD |
| B-307 | 10/4/2021 | Dry | Dry | Dry | 5,708.83 | 1.34 | 15-20 | 22 | NE, >22 | WD |
| B-308 | 7/7/2021 | 5,693.70 | 28.86 | 26.8 | 5,722.56 | 2.06 | 23-33 | 37 | 33 | WD |
| B-308 | 10/4/2021 | 5,692.74 | 29.82 | 27.76 | 5,722.56 | 2.06 | 23-33 | 37 | 33 | WD |
| B-309 | 7/7/2021 | 5,687.02 | 29.39 | 26.48 | 5,716.41 | 2.91 | 17-27 | 31 | 26.5 | WD |
| B-309 | 10/4/2021 | 5,687.02 | 29.39 | 26.48 | 5,716.41 | 2.91 | 17-27 | 31 | 26.5 | WD |
| B-310 | 7/7/2021 | 5,687.33 | 29.82 | 27.47 | 5,717.15 | 2.35 | 21.5-31.5 | 34 | 31.3 | WD |
| B-310 | 10/4/2021 | 5,687.53 | 29.62 | 27.27 | 5,717.15 | 2.35 | 21.5-31.5 | 34 | 31.3 | WD |
| B-311 | 7/8/2021 | Dry | Dry | Dry | 5,718.56 | 2.66 | 18-23 | 25.7 | 23 | WD |
| B-311 | 10/4/2021 | Dry | Dry | Dry | 5,718.56 | 2.66 | 18-23 | 25.7 | 23 | WD |
| B-312 | 7/8/2021 | Dry | Dry | Dry | 5,711.24 | 2.64 | 21-31 | 35 | 31 | WD |
| B-312 | 10/4/2021 | Dry | Dry | Dry | 5,711.24 | 2.64 | 21-31 | 35 | 31 | WD |
| B-313 | 7/7/2021 | 5,691.88 | 24.04 | 21.52 | 5,715.92 | 2.52 | 20-27 | 30.1 | 26.5 | WD |
| B-313 | 10/4/2021 | 5,689.53 | 26.39 | 23.87 | 5,715.92 | 2.52 | 20-27 | 30.1 | 26.5 | WD |
| B-313-UD | 7/7/2021 | 5,682.83 | 32.62 | 29.97 | 5,715.45 | 2.65 | 48-63 | 65 | 27 | UNWD |
| B-313-UD | 10/4/2021 | 5,681.71 | 33.74 | 31.09 | 5,715.45 | 2.65 | 48-63 | 65 | 27 | UNWD |
| B-314 | 7/8/2021 | 5,696.45 | 45.68 | 43.15 | 5,742.13 | 2.53 | 32.5-47.5 | 51 | 47.5 | WD |
| B-314 | 10/4/2021 | 5,696.45 | 45.68 | 43.15 | 5,742.13 | 2.53 | 32.5-47.5 | 51 | 47.5 | WD |
| B-314-UD | 7/8/2021 | 5,689.76 | 52.24 | 49.84 | 5,742.00 | 2.40 | 67-87 | 89 | 48.5 | UNWD |
| B-314-UD | 10/4/2021 | 5,689.08 | 52.92 | 50.52 | 5,742.00 | 2.40 | 67-87 | 89 | 48.5 | UNWD |
| B-315 | 7/8/2021 | 5,697.16 | 40.8 | 38.24 | 5,737.96 | 2.56 | 28-43 | 46 | 43 | WD |
| B-315 | 10/4/2021 | 5,697.01 | 40.95 | 38.39 | 5,737.96 | 2.56 | 28-43 | 46 | 43 | WD |
| B-316 | 7/7/2021 | 5,696.08 | 22.58 | 20.02 | 5,718.66 | 2.56 | 20.5-30.5 | 34 | 30.5 | WD |
| B-316 | 10/4/2021 | 5,695.84 | 22.82 | 20.26 | 5,718.66 | 2.56 | 20.5-30.5 | 34 | 30.5 | WD |
| B-316-UD | 7/7/2021 | 5,691.20 | 27.64 | 25.4 | 5,718.84 | 2.24 | 41-56 | 59 | 33 | UNWD |
| B-316-UD | 10/4/2021 | 5,691.43 | 27.41 | 25.17 | 5,718.84 | 2.24 | 41-56 | 59 | 33 | UNWD |
| B-317 | 7/7/2021 | 5,689.79 | 21.03 | 18.51 | 5,710.82 | 2.52 | 18-24 | 28.1 | 24 | WD |
| B-317 | 10/4/2021 | 5,690.34 | 20.48 | 17.96 | 5,710.82 | 2.52 | 18-24 | 28.1 | 24 | WD |
| B-317-UD | 7/7/2021 | 5,691.52 | 18.41 | 16.58 | 5,709.93 | 1.83 | 37-52 | 54.5 | 23.5 | UNWD |
| B-317-UD | 10/4/2021 | 5,691.01 | 18.92 | 17.09 | 5,709.93 | 1.83 | 37-52 | 54.5 | 23.5 | UNWD |
| B-318 | 7/7/2021 | Dry | Dry | Dry | 5,728.49 | 2.59 | 18-25 | 28 | 25 | WD |
| B-318 | 10/4/2021 | Dry | Dry | Dry | 5,728.49 | 2.59 | 18-25 | 28 | 25 | WD |
| B-319 | 7/8/2021 | 5,670.26 | 43.14 | 40.22 | 5,713.40 | 2.80 | 21.5-41.5 | 44.1 | 42 | WD |
| B-319 | 10/4/2021 | Dry | Dry | Dry | 5,713.40 | 2.80 | 21.5-41.5 | 44.1 | 42 | WD |
| B-319-25S | 7/8/2021 | Dry | Dry | Dry | 5,712.73 | 2.23 | 14-24 | 24 | NE, >24 | WD |
| B-319-25S | 10/4/2021 | Dry | Dry | Dry | 5,712.73 | 2.23 | 14-24 | 24 | NE, >24 | WD |
| B-319-26W | 7/8/2021 | Dry | Dry | Dry | 5,712.60 | 2.60 | 12.4-22.4 | 22.4 | NE, >22.4 | WD |
| B-319-26W | 10/4/2021 | Dry | Dry | Dry | 5,712.60 | 2.60 | 12.4-22.4 | 22.4 | NE, >22.4 | WD |
| B-319-50S | 7/8/2021 | Dry | Dry | Dry | 5,713.85 | 2.55 | 14-24 | 24 | NE, >24 | WD |
| B-319-50S | 10/4/2021 | Dry | Dry | Dry | 5,713.85 | 2.55 | 14-24 | 24 | NE, >24 | WD |
| B-319-50W | 7/8/2021 | Dry | Dry | Dry | 5,711.78 | 2.28 | 14-24 | 24 | NE, >24 | WD |
| B-319-50W | 10/4/2021 | Dry | Dry | Dry | 5,711.78 | 2.28 | 14-24 | 24 | NE, >24 | WD |
| B-319-75S | 7/8/2021 | Dry | Dry | Dry | 5,714.00 | 2.00 | 14-24 | 24 | NE, >24 | WD |
| B-319-75S | 10/4/2021 | Dry | Dry | Dry | 5,714.00 | 2.00 | 14-24 | 24 | NE, >24 | WD |
| B-320 | 7/7/2021 | 5,695.13 | 27.89 | 25.47 | 5,723.02 | 2.42 | 19-34 | 38.5 | 34 | WD |
| B-320 | 10/4/2021 | 5,693.64 | 29.38 | 26.96 | 5,723.02 | 2.42 | 19-34 | 38.5 | 34 | WD |
| B-321 | 7/8/2021 | 5,686.47 | 26.42 | 24.63 | 5,712.89 | 1.79 | 12-27 | 30.5 | 27 | WD |
| B-321 | 10/4/2021 | 5,686.27 | 26.62 | 24.83 | 5,712.89 | 1.79 | 12-27 | 30.5 | 27 | WD |
| B-322 | 7/7/2021 | 5,688.43 | 31.51 | 28.73 | 5,719.94 | 2.78 | 15-30 | 33.5 | 30 | WD |
| B-322 | 10/4/2021 | 5,688.35 | 31.59 | 28.81 | 5,719.94 | 2.78 | 15-30 | 33.5 | 30 | WD |

**TABLE 4.2**
**WATER LEVEL ELEVATIONS**
**JULY THROUGH DECEMBER 2021 OPERATIONS AND MAINTENANCE STATUS REPORT**
**LOWRY LANDFILL SUPERFUND SITE**

| Well ID | Date of Measurement | Water-Surface Elevation (ft NGVD)[a/] | Measured Depth to Water (ft below MP)[b/] | Depth to Water (ft bgs)[c/] | Measuring Point Elevation (ft NGVD) | Stickup (ft)[d/] | Screened Interval (ft bgs) | Total Depth (ft bgs) | Base of Weathering (ft bgs) | Formation[e/] |
|---|---|---|---|---|---|---|---|---|---|---|
| B-323-WD | 7/7/2021 | Dry | Dry | Dry | 5,732.01 | 2.01 | 23-33 | 35 | 33 | WD |
| B-323-WD | 10/4/2021 | Dry | Dry | Dry | 5,732.01 | 2.01 | 23-33 | 35 | 33 | WD |
| B-324-WD | 7/8/2021 | 5,703.83 | 31.18 | 27.67 | 5,735.01 | 3.51 | 28.5-43.5 | 46 | 43.5 | WD |
| B-324-WD | 10/4/2021 | 5,701.72 | 33.29 | 29.78 | 5,735.01 | 3.51 | 28.5-43.5 | 46 | 43.5 | WD |
| B-325-WD | 7/7/2021 | 5,696.17 | 37.79 | 35.13 | 5,733.96 | 2.66 | 29.5-39.5 | 43 | 39.5 | WD |
| B-325-WD | 10/4/2021 | 5,696.15 | 37.81 | 35.15 | 5,733.96 | 2.66 | 29.5-39.5 | 43 | 39.5 | WD |
| B-326-UD | 7/8/2021 | 5,672.35 | 42.11 | 39.45 | 5,714.46 | 2.66 | 60-80 | 83 | 48.5 | UNWD |
| B-326-UD | 10/4/2021 | 5,669.54 | 44.92 | 42.26 | 5,714.46 | 2.66 | 60-80 | 83 | 48.5 | UNWD |
| B-326-WD | 7/8/2021 | 5,670.17 | 43.41 | 41.23 | 5,713.58 | 2.18 | 24-49 | 51 | 49 | WD |
| B-326-WD | 10/4/2021 | 5,666.31 | 47.27 | 45.09 | 5,713.58 | 2.18 | 24-49 | 51 | 49 | WD |
| B-327-UD | 7/7/2021 | 5,692.79 | 30.74 | 28.71 | 5,723.53 | 2.03 | 50-65 | 67 | 19 | UNWD |
| B-327-UD | 10/4/2021 | 5,692.08 | 31.45 | 29.42 | 5,723.53 | 2.03 | 50-65 | 67 | 19 | UNWD |
| B-327-WD | 7/7/2021 | 5,697.30 | 26.09 | 23.6 | 5,723.39 | 2.49 | 18-28 | 30 | 28 | WD |
| B-327-WD | 10/4/2021 | 5,695.68 | 27.71 | 25.22 | 5,723.39 | 2.49 | 18-28 | 30 | 28 | WD |
| B-502 | 7/15/2021 | 5,748.98 | 30.74 | 26.92 | 5,779.72 | 3.82 | 95-105 | 120 | 23 | UNWD |
| B-502 | 10/11/2021 | 5,748.70 | 31.02 | 27.2 | 5,779.72 | 3.82 | 95-105 | 120 | 23 | UNWD |
| B-504A | 7/15/2021 | 5,717.53 | 34.65 | 34.27 | 5,752.18 | 0.38 | 105-125 | 126.5 | 36 | UPPER DENVER |
| B-504A | 10/11/2021 | 5,717.34 | 34.84 | 34.46 | 5,752.18 | 0.38 | 105-125 | 126.5 | 36 | UPPER DENVER |
| B-506 | 7/6/2021 | 5,687.17 | 146.22 | 143.83 | 5,833.39 | 2.39 | 310-350 | 355 | 55 | LIGNITE |
| B-506 | 10/1/2021 | 5,686.94 | 146.45 | 144.06 | 5,833.39 | 2.39 | 310-350 | 355 | 55 | LIGNITE |
| B-518 | 7/9/2021 | 5,759.38 | 38.36 | 36.02 | 5,797.74 | 2.34 | 75-95 | 100 | 50 | UNWD |
| B-518 | 10/5/2021 | 5,759.15 | 38.59 | 36.25 | 5,797.74 | 2.34 | 75-95 | 100 | 50 | UNWD |
| B-519 | 7/8/2021 | 5,808.85 | 18.29 | 18.15 | 5,827.14 | 0.14 | 60-80 | 85 | 50 | UNWD |
| B-519 | 10/1/2021 | 5,807.99 | 19.15 | 19.01 | 5,827.14 | 0.14 | 60-80 | 85 | 50 | UNWD |
| B-520 | 7/8/2021 | 5,762.43 | 63.66 | 61.77 | 5,826.09 | 1.89 | 125-145 | 155 | 50 | UPPER DENVER |
| B-520 | 10/1/2021 | 5,762.19 | 63.9 | 62.01 | 5,826.09 | 1.89 | 125-145 | 155 | 50 | UPPER DENVER |
| B-706 | 7/21/2021 | 5,785.40 | 78.84 | 76.1 | 5,864.24 | 2.74 | 105-115 | 115 | 87.6 | UNWD |
| B-706 | 10/1/2021 | 5,785.33 | 78.91 | 76.17 | 5,864.24 | 2.74 | 105-115 | 115 | 87.6 | UNWD |
| B-708 | 7/8/2021 | 5,774.10 | 91.91 | 88.9 | 5,866.01 | 3.01 | 122-132 | 132 | 101 | UNWD |
| B-708 | 10/1/2021 | 5,774.02 | 91.99 | 88.98 | 5,866.01 | 3.01 | 122-132 | 132 | 101 | UNWD |
| B-712-25S-UD | 7/15/2021 | 5,748.25 | 25.53 | 22.65 | 5,773.78 | 2.88 | 65-80 | 82 | 35.5 | UNWD |
| B-712-25S-UD | 10/11/2021 | 5,748.04 | 25.74 | 22.86 | 5,773.78 | 2.88 | 65-80 | 82 | 35.5 | UNWD |
| B-712-LD | 7/15/2021 | 5,741.42 | 31.44 | 28.98 | 5,772.86 | 2.46 | 100-115 | 119 | 36.5 | UNWD |
| B-712-LD | 10/11/2021 | 5,741.32 | 31.54 | 29.08 | 5,772.86 | 2.46 | 100-115 | 119 | 36.5 | UNWD |
| B-712-UD | 7/15/2021 | 5,747.92 | 24.62 | 22.38 | 5,772.54 | 2.24 | 56.5-71.5 | 74 | 36 | UNWD |
| B-712-UD | 10/11/2021 | 5,747.72 | 24.82 | 22.58 | 5,772.54 | 2.24 | 56.5-71.5 | 74 | 36 | UNWD |
| BKGD-1WD | 7/12/2021 | 5,842.85 | 32.33 | 30.1 | 5,875.18 | 2.23 | 44.5-54.5 | 55 | 54 | WD |
| BKGD-1WD | 10/8/2021 | 5,842.45 | 32.73 | 30.5 | 5,875.18 | 2.23 | 44.5-54.5 | 55 | 54 | WD |
| BKGD-2UD | 7/12/2021 | 5,801.49 | 50.01 | 48.06 | 5,851.50 | 1.95 | 58-68 | 68.5 | 47.6 | UNWD |
| BKGD-2UD | 10/8/2021 | 5,801.40 | 50.1 | 48.15 | 5,851.50 | 1.95 | 58-68 | 68.5 | 47.6 | UNWD |
| BKGD-2WD | 7/12/2021 | 5,840.28 | 11.14 | 9.24 | 5,851.42 | 1.90 | 33.6-48.6 | 48.6 | 47.6 | WD |
| BKGD-2WD | 10/8/2021 | 5,841.49 | 9.93 | 8.03 | 5,851.42 | 1.90 | 33.6-48.6 | 48.6 | 47.6 | WD |
| BKGD-3UD | 7/12/2021 | 5,785.54 | 56.63 | 54.57 | 5,842.17 | 2.06 | 94-104 | 105 | 70 | UNWD |
| BKGD-3UD | 10/8/2021 | 5,785.70 | 56.47 | 54.41 | 5,842.17 | 2.06 | 94-104 | 105 | 70 | UNWD |
| BKGD-3WD | 7/12/2021 | 5,785.08 | 57.5 | 54.57 | 5,842.58 | 2.93 | 55.5-70.5 | 71 | 70 | WD |
| BKGD-3WD | 10/8/2021 | 5,785.28 | 57.3 | 54.37 | 5,842.58 | 2.93 | 55.5-70.5 | 71 | 70 | WD |
| BKGD-4UD | 7/12/2021 | 5,822.65 | 29.05 | 26.99 | 5,851.70 | 2.06 | 60-75 | 75 | 30 | UNWD |
| BKGD-4UD | 10/8/2021 | 5,822.71 | 28.99 | 26.93 | 5,851.70 | 2.06 | 60-75 | 75 | 30 | UNWD |
| BKGD-4WD | 7/12/2021 | 5,832.56 | 19.33 | 17.08 | 5,851.89 | 2.25 | 21-30 | 31 | 30 | WD |
| BKGD-4WD | 10/8/2021 | 5,832.69 | 19.2 | 16.95 | 5,851.89 | 2.25 | 21-30 | 31 | 30 | WD |
| BM-11I-100N | 7/9/2021 | 5,773.92 | 43.26 | 40.26 | 5,817.18 | 3.00 | 18.5-50.5 | 56 | 50.5 | WD |
| BM-11I-100N | 10/5/2021 | 5,773.74 | 43.44 | 40.44 | 5,817.18 | 3.00 | 18.5-50.5 | 56 | 50.5 | WD |
| BM-11I-100S | 7/9/2021 | 5,797.50 | 24.73 | 22.23 | 5,822.23 | 2.50 | 19.2-51.2 | 57 | 51.2 | WD |
| BM-11I-100S | 10/5/2021 | 5,797.47 | 24.76 | 22.26 | 5,822.23 | 2.50 | 19.2-51.2 | 57 | 51.2 | WD |
| BM-11I-150N | 7/9/2021 | 5,790.13 | 25.78 | 23.67 | 5,815.91 | 2.11 | 17.5-47.5 | 54 | 46.5 | WD |
| BM-11I-150N | 10/5/2021 | 5,790.04 | 25.87 | 23.76 | 5,815.91 | 2.11 | 17.5-47.5 | 54 | 46.5 | WD |
| BM-11I-200N | 7/9/2021 | 5,790.82 | 24.13 | 21.54 | 5,814.95 | 2.59 | 19-44 | 49 | 44 | WD |
| BM-11I-200N | 10/5/2021 | 5,790.76 | 24.19 | 21.6 | 5,814.95 | 2.59 | 19-44 | 49 | 44 | WD |
| BM-11I-50N | 7/9/2021 | 5,792.24 | 26.75 | 23.75 | 5,818.99 | 3.00 | 17.5-47.5 | 53 | 47.5 | WD |
| BM-11I-50N | 10/5/2021 | 5,792.16 | 26.83 | 23.83 | 5,818.99 | 3.00 | 17.5-47.5 | 53 | 47.5 | WD |
| BM-11I-50S | 7/9/2021 | 5,794.65 | 26.91 | 23.91 | 5,821.56 | 3.00 | 18-48 | 53 | 47.7 | WD |
| BM-11I-50S | 10/5/2021 | 5,794.57 | 26.99 | 23.99 | 5,821.56 | 3.00 | 18-48 | 53 | 47.7 | WD |
| BM-11X-100N | 7/9/2021 | 5,792.73 | 22.78 | 20.28 | 5,815.51 | 2.50 | 19-46 | 50 | 46 | WD |
| BM-11X-100N | 10/5/2021 | 5,792.20 | 23.31 | 20.81 | 5,815.51 | 2.50 | 19-46 | 50 | 46 | WD |
| BM-11X-100S | 7/9/2021 | 5,805.15 | 14.6 | 12.1 | 5,819.75 | 2.50 | 18.5-48.5 | 53 | 47.5 | WD |
| BM-11X-100S | 10/5/2021 | 5,804.07 | 15.68 | 13.18 | 5,819.75 | 2.50 | 18.5-48.5 | 53 | 47.5 | WD |

**TABLE 4.2**
**WATER LEVEL ELEVATIONS**
**JULY THROUGH DECEMBER 2021 OPERATIONS AND MAINTENANCE STATUS REPORT**
**LOWRY LANDFILL SUPERFUND SITE**

| Well ID | Date of Measurement | Water-Surface Elevation (ft NGVD)[a/] | Measured Depth to Water (ft below MP)[b/] | Depth to Water (ft bgs)[c/] | Measuring Point Elevation (ft NGVD) | Stickup (ft)[d/] | Screened Interval (ft bgs) | Total Depth (ft bgs) | Base of Weathering (ft bgs) | Formation[e/] |
|---|---|---|---|---|---|---|---|---|---|---|
| BM-11X-150N | 7/9/2021 | 5,792.30 | 22.16 | 19.75 | 5,814.46 | 2.41 | 19.5-44.5 | 49.5 | 44.5 | WD |
| BM-11X-150N | 10/5/2021 | 5,791.86 | 22.6 | 20.19 | 5,814.46 | 2.41 | 19.5-44.5 | 49.5 | 44.5 | WD |
| BM-11X-200N | 7/9/2021 | 5,791.90 | 21.09 | 18.65 | 5,812.99 | 2.44 | 19.5-44.5 | 50.5 | 44.5 | WD |
| BM-11X-200N | 10/5/2021 | 5,791.54 | 21.45 | 19.01 | 5,812.99 | 2.44 | 19.5-44.5 | 50.5 | 44.5 | WD |
| BM-11X-50N | 7/9/2021 | 5,795.17 | 22.11 | 19.61 | 5,817.28 | 2.50 | 17-47 | 50 | 47.5 | WD |
| BM-11X-50N | 10/5/2021 | 5,794.52 | 22.76 | 20.26 | 5,817.28 | 2.50 | 17-47 | 50 | 47.5 | WD |
| BM-11X-50S | 7/9/2021 | 5,804.16 | 15.08 | 12.58 | 5,819.24 | 2.50 | 19-46 | 50 | 44.5 | WD |
| BM-11X-50S | 10/5/2021 | 5,802.94 | 16.3 | 13.8 | 5,819.24 | 2.50 | 19-46 | 50 | 44.5 | WD |
| BM-15E1 | 7/9/2021 | 5,731.51 | 33.44 | 31.86 | 5,764.95 | 1.58 | 20-40 | 45 | 40 | WD |
| BM-15E1 | 10/5/2021 | 5,731.86 | 33.09 | 31.51 | 5,764.95 | 1.58 | 20-40 | 45 | 40 | WD |
| BM-15E2 | 7/9/2021 | 5,731.33 | 36.4 | 34.07 | 5,767.73 | 2.33 | 31-43 | 46.8 | 43 | WD |
| BM-15E2 | 10/5/2021 | 5,731.44 | 36.29 | 33.96 | 5,767.73 | 2.33 | 31-43 | 46.8 | 43 | WD |
| BM-15E3 | 7/9/2021 | 5,731.33 | 37.82 | 35.27 | 5,769.15 | 2.55 | 31.5-46.5 | 49.6 | 46.7 | WD |
| BM-15E3 | 10/5/2021 | 5,731.42 | 37.73 | 35.18 | 5,769.15 | 2.55 | 31.5-46.5 | 49.6 | 46.7 | WD |
| BM-15E4 | 7/9/2021 | 5,736.11 | 36.08 | 33.39 | 5,772.19 | 2.69 | 34-49 | 54 | 49 | WD |
| BM-15E4 | 10/5/2021 | 5,736.31 | 35.88 | 33.19 | 5,772.19 | 2.69 | 34-49 | 54 | 49 | WD |
| BM-15E5 | 7/9/2021 | 5,737.60 | 32.97 | 30.2 | 5,770.57 | 2.77 | 31.5-46.5 | 53 | 46.5 | WD |
| BM-15E5 | 10/5/2021 | 5,736.93 | 33.64 | 30.87 | 5,770.57 | 2.77 | 31.5-46.5 | 53 | 46.5 | WD |
| BM-15E6 | 7/9/2021 | 5,737.56 | 35.56 | 32.74 | 5,773.12 | 2.82 | 29.5-49.5 | 52.7 | 49.5 | WD |
| BM-15E6 | 10/5/2021 | 5,737.84 | 35.28 | 32.46 | 5,773.12 | 2.82 | 29.5-49.5 | 52.7 | 49.5 | WD |
| BM-15I-100S | 7/9/2021 | 5,725.99 | 52.56 | 49.2 | 5,778.55 | 3.36 | 19-51 | 56.8 | 50.8 | WD |
| BM-15I-100S | 10/5/2021 | 5,725.57 | 52.98 | 49.62 | 5,778.55 | 3.36 | 19-51 | 56.8 | 50.8 | WD |
| BM-15I-125S | 7/9/2021 | 5,739.26 | 39.39 | 37.28 | 5,778.65 | 2.11 | 19.5-50.5 | 53 | 49.8 | WD |
| BM-15I-125S | 10/5/2021 | 5,739.21 | 39.44 | 37.33 | 5,778.65 | 2.11 | 19.5-50.5 | 53 | 49.8 | WD |
| BM-15I-150S | 7/9/2021 | 5,725.57 | 54.78 | 51.55 | 5,780.35 | 3.23 | 20.5-50.5 | 55.5 | 50.5 | WD |
| BM-15I-150S | 10/5/2021 | 5,725.21 | 55.14 | 51.91 | 5,780.35 | 3.23 | 20.5-50.5 | 55.5 | 50.5 | WD |
| BM-15I-15N | 7/9/2021 | 5,725.22 | 50.27 | 47.48 | 5,775.49 | 2.79 | 17-47 | 52 | 47 | WD |
| BM-15I-15N | 10/5/2021 | 5,725.02 | 50.47 | 47.68 | 5,775.49 | 2.79 | 17-47 | 52 | 47 | WD |
| BM-15I-175S | 7/9/2021 | 5,741.33 | 39.34 | 37.48 | 5,780.67 | 1.86 | 19-51 | 55 | 50.8 | WD |
| BM-15I-175S | 10/5/2021 | 5,741.19 | 39.48 | 37.62 | 5,780.67 | 1.86 | 19-51 | 55 | 50.8 | WD |
| BM-15I-200S | 7/9/2021 | 5,745.49 | 36.17 | 33.9 | 5,781.66 | 2.27 | 20-50 | 55.5 | 48.2 | WD |
| BM-15I-200S | 10/5/2021 | 5,745.34 | 36.32 | 34.05 | 5,781.66 | 2.27 | 20-50 | 55.5 | 48.2 | WD |
| BM-15I-25S | 7/9/2021 | 5,720.97 | 56.59 | 52.73 | 5,777.56 | 3.86 | 21-51 | 56 | 52 | WD |
| BM-15I-25S | 10/5/2021 | 5,720.40 | 57.16 | 53.3 | 5,777.56 | 3.86 | 21-51 | 56 | 52 | WD |
| BM-15I-37.5S | 7/9/2021 | 5,723.05 | 52.63 | 50.25 | 5,775.68 | 2.38 | 24-54 | 59 | 54 | WD |
| BM-15I-37.5S | 10/5/2021 | 5,723.04 | 52.64 | 50.26 | 5,775.68 | 2.38 | 24-54 | 59 | 54 | WD |
| BM-15I-50S | 7/9/2021 | 5,723.76 | 53.73 | 50.37 | 5,777.49 | 3.36 | 17.7-52.7 | 59 | 53 | WD |
| BM-15I-50S | 10/5/2021 | 5,723.62 | 53.87 | 50.51 | 5,777.49 | 3.36 | 17.7-52.7 | 59 | 53 | WD |
| BM-15I-75S | 7/9/2021 | 5,738.09 | 38.86 | 37.42 | 5,776.95 | 1.44 | 19-51 | 55 | 51 | WD |
| BM-15I-75S | 10/5/2021 | 5,738.05 | 38.9 | 37.46 | 5,776.95 | 1.44 | 19-51 | 55 | 51 | WD |
| BM-15N1 | 7/9/2021 | 5,736.95 | 34.13 | 32.25 | 5,771.08 | 1.88 | 22.3-52.3 | 60 | 52.3 | WD |
| BM-15N1 | 10/5/2021 | 5,736.66 | 34.42 | 32.54 | 5,771.08 | 1.88 | 22.3-52.3 | 60 | 52.3 | WD |
| BM-15N2 | 7/9/2021 | 5,743.72 | 25.94 | 23.47 | 5,769.66 | 2.47 | 19-39 | 45 | 39.2 | WD |
| BM-15N2 | 10/5/2021 | 5,739.21 | 30.45 | 27.98 | 5,769.66 | 2.47 | 19-39 | 45 | 39.2 | WD |
| BM-15N3 | 7/9/2021 | 5,741.61 | 24.97 | 22.57 | 5,766.58 | 2.40 | 19.5-39.5 | 45 | 39.5 | WD |
| BM-15N3 | 10/5/2021 | 5,738.70 | 27.88 | 25.48 | 5,766.58 | 2.40 | 19.5-39.5 | 45 | 39.5 | WD |
| BM-15N4 | 7/9/2021 | 5,734.79 | 30.77 | 28.06 | 5,765.56 | 2.71 | 17-37 | 44 | 37 | WD |
| BM-15N4 | 10/5/2021 | 5,735.50 | 30.06 | 27.35 | 5,765.56 | 2.71 | 17-37 | 44 | 37 | WD |
| BM-15N5 | 7/9/2021 | 5,735.98 | 36.72 | 34.42 | 5,772.70 | 2.30 | 31-56 | 62 | 56 | WD |
| BM-15N5 | 10/5/2021 | 5,736.00 | 36.7 | 34.4 | 5,772.70 | 2.30 | 31-56 | 62 | 56 | WD |
| BM-15N6 | 7/9/2021 | 5,737.37 | 35.22 | 30.63 | 5,772.59 | 4.59 | 16-46 | 51 | 47 | WD |
| BM-15N6 | 10/5/2021 | 5,737.42 | 35.17 | 30.58 | 5,772.59 | 4.59 | 16-46 | 51 | 47 | WD |
| BM-15NE1 | 7/9/2021 | 5,730.38 | 33.82 | 31.32 | 5,764.20 | 2.50 | 17.5-42.5 | 45 | 42.5 | WD |
| BM-15NE1 | 10/5/2021 | 5,730.27 | 33.93 | 31.43 | 5,764.20 | 2.50 | 17.5-42.5 | 45 | 42.5 | WD |
| BM-15NE2 | 7/9/2021 | 5,729.82 | 31.79 | 30.17 | 5,761.61 | 1.62 | 19-39 | 42.8 | 39 | WD |
| BM-15NE2 | 10/5/2021 | 5,729.59 | 32.02 | 30.4 | 5,761.61 | 1.62 | 19-39 | 42.8 | 39 | WD |
| BM-15NW1 | 7/9/2021 | 5,752.72 | 19.84 | 18.52 | 5,772.56 | 1.32 | 12-22 | 47 | 43.8 | WD |
| BM-15NW1 | 10/5/2021 | 5,753.02 | 19.54 | 18.22 | 5,772.56 | 1.32 | 12-22 | 47 | 43.8 | WD |
| BM-15NW2 | 7/9/2021 | 5,752.59 | 20.58 | 17.28 | 5,773.17 | 3.30 | 22-32 | 34.5 | NE, >34.5 | WD |
| BM-15NW2 | 10/5/2021 | 5,752.70 | 20.47 | 17.17 | 5,773.17 | 3.30 | 22-32 | 34.5 | NE, >34.5 | WD |
| BM-15X-100S | 7/9/2021 | 5,738.47 | 37.38 | 34.88 | 5,775.85 | 2.50 | 18.5-52.5 | 55 | 52.6 | WD |
| BM-15X-100S | 10/5/2021 | 5,738.26 | 37.59 | 35.09 | 5,775.85 | 2.50 | 18.5-52.5 | 55 | 52.6 | WD |
| BM-15X-125S | 7/9/2021 | 5,739.10 | 37.65 | 35.56 | 5,776.75 | 2.09 | 19-50 | 55 | 49.9 | WD |
| BM-15X-125S | 10/5/2021 | 5,739.16 | 37.59 | 35.5 | 5,776.75 | 2.09 | 19-50 | 55 | 49.9 | WD |
| BM-15X-150S | 7/9/2021 | 5,739.95 | 37.69 | 35.19 | 5,777.64 | 2.50 | 20-50 | 54 | 50 | WD |
| BM-15X-150S | 10/5/2021 | 5,739.94 | 37.7 | 35.2 | 5,777.64 | 2.50 | 20-50 | 54 | 50 | WD |

**TABLE 4.2**
**WATER LEVEL ELEVATIONS**
**JULY THROUGH DECEMBER 2021 OPERATIONS AND MAINTENANCE STATUS REPORT**
**LOWRY LANDFILL SUPERFUND SITE**

| Well ID | Date of Measurement | Water-Surface Elevation (ft NGVD)[a/] | Measured Depth to Water (ft below MP)[b/] | Depth to Water (ft bgs)[c/] | Measuring Point Elevation (ft NGVD) | Stickup (ft)[d/] | Screened Interval (ft bgs) | Total Depth (ft bgs) | Base of Weathering (ft bgs) | Formation[e/] |
|---|---|---|---|---|---|---|---|---|---|---|
| BM-15X-175S | 7/9/2021 | 5,742.23 | 36.72 | 34.63 | 5,778.95 | 2.09 | 19-50 | 53 | 49.9 | WD |
| BM-15X-175S | 10/5/2021 | 5,741.99 | 36.96 | 34.87 | 5,778.95 | 2.09 | 19-50 | 53 | 49.9 | WD |
| BM-15X-200S | 7/9/2021 | 5,743.81 | 36.51 | 34.03 | 5,780.32 | 2.48 | 19.5-51.5 | 54.5 | 51.5 | WD |
| BM-15X-200S | 10/5/2021 | 5,743.44 | 36.88 | 34.4 | 5,780.32 | 2.48 | 19.5-51.5 | 54.5 | 51.5 | WD |
| BM-15X-37.5S | 7/9/2021 | 5,736.01 | 38.51 | 35.89 | 5,774.52 | 2.62 | 25-55 | 60 | 55 | WD |
| BM-15X-37.5S | 10/5/2021 | 5,736.37 | 38.15 | 35.53 | 5,774.52 | 2.62 | 25-55 | 60 | 55 | WD |
| BM-15X-50S | 7/9/2021 | 5,737.21 | 37.4 | 34.9 | 5,774.61 | 2.50 | 19-51 | 54 | 51.4 | WD |
| BM-15X-50S | 10/5/2021 | 5,737.66 | 36.95 | 34.45 | 5,774.61 | 2.50 | 19-51 | 54 | 51.4 | WD |
| BM-15X-75S | 7/9/2021 | 5,738.11 | 36.23 | 34.53 | 5,774.34 | 1.70 | 19-51 | 55 | 51 | WD |
| BM-15X-75S | 10/5/2021 | 5,738.44 | 35.9 | 34.2 | 5,774.34 | 1.70 | 19-51 | 55 | 51 | WD |
| BM-4I-100N | 7/6/2021 | 5,793.11 | 43.28 | 40.53 | 5,836.39 | 2.75 | 34-54 | 60 | 53.7 | WD |
| BM-4I-100N | 10/1/2021 | 5,792.98 | 43.41 | 40.66 | 5,836.39 | 2.75 | 34-54 | 60 | 53.7 | WD |
| BM-4I-100S | 7/6/2021 | 5,793.51 | 43.05 | 40.69 | 5,836.56 | 2.36 | 34-49 | 55 | 48.6 | WD |
| BM-4I-100S | 10/1/2021 | 5,793.48 | 43.08 | 40.72 | 5,836.56 | 2.36 | 34-49 | 55 | 48.6 | WD |
| BM-4I-10S | 7/6/2021 | 5,793.30 | 43.06 | 40.8 | 5,836.36 | 2.26 | 34-54 | 59.5 | 53.5 | WD |
| BM-4I-10S | 10/1/2021 | 5,793.26 | 43.1 | 40.84 | 5,836.36 | 2.26 | 34-54 | 59.5 | 53.5 | WD |
| BM-4I-50N | 7/6/2021 | 5,793.34 | 42.63 | 39.93 | 5,835.97 | 2.70 | 32-47 | 52.5 | 46.8 | WD |
| BM-4I-50N | 10/1/2021 | 5,793.24 | 42.73 | 40.03 | 5,835.97 | 2.70 | 32-47 | 52.5 | 46.8 | WD |
| BM-4I-50S | 7/6/2021 | 5,793.22 | 44.11 | 41.08 | 5,837.33 | 3.03 | 30.5-50.5 | 56 | 50.2 | WD |
| BM-4I-50S | 10/1/2021 | 5,793.15 | 44.18 | 41.15 | 5,837.33 | 3.03 | 30.5-50.5 | 56 | 50.2 | WD |
| BM-4X-100N | 7/6/2021 | 5,793.74 | 42.35 | 39.63 | 5,836.09 | 2.72 | 31-51 | 54 | 50.6 | WD |
| BM-4X-100N | 10/1/2021 | 5,793.69 | 42.4 | 39.68 | 5,836.09 | 2.72 | 31-51 | 54 | 50.6 | WD |
| BM-4X-100S | 7/6/2021 | 5,793.12 | 43.56 | 41.55 | 5,836.68 | 2.01 | 34-49 | 53 | 48.7 | WD |
| BM-4X-100S | 10/1/2021 | 5,793.27 | 43.41 | 41.4 | 5,836.68 | 2.01 | 34-49 | 53 | 48.7 | WD |
| BM-4X-10S | 7/6/2021 | 5,793.18 | 43.59 | 41.12 | 5,836.77 | 2.47 | 33.5-56.5 | 59 | 56.3 | WD |
| BM-4X-10S | 10/1/2021 | 5,793.16 | 43.61 | 41.14 | 5,836.77 | 2.47 | 33.5-56.5 | 59 | 56.3 | WD |
| BM-4X-40S | 7/6/2021 | 5,785.95 | 50.72 | 48.35 | 5,836.67 | 2.37 | 68-83 | 87 | 52 | UNWD |
| BM-4X-40S | 10/1/2021 | 5,785.94 | 50.73 | 48.36 | 5,836.67 | 2.37 | 68-83 | 87 | 52 | UNWD |
| BM-4X-50N | 7/6/2021 | 5,793.35 | 43.1 | 40.28 | 5,836.45 | 2.82 | 34-49 | 54 | 49 | WD |
| BM-4X-50N | 10/1/2021 | 5,793.28 | 43.17 | 40.35 | 5,836.45 | 2.82 | 34-49 | 54 | 49 | WD |
| BM-4X-50S | 7/6/2021 | 5,793.53 | 43.59 | 40.97 | 5,837.12 | 2.62 | 32.5-52.5 | 55 | 52.5 | WD |
| BM-4X-50S | 10/1/2021 | 5,793.52 | 43.6 | 40.98 | 5,837.12 | 2.62 | 32.5-52.5 | 55 | 52.5 | WD |
| BW-PZ-1 | 7/7/2021 | 5,692.87 | 31.6 | 29.44 | 5,724.47 | 2.16 | 23-33 | 33 | 33 | WD |
| BW-PZ-1 | 10/4/2021 | 5,692.86 | 31.61 | 29.45 | 5,724.47 | 2.16 | 23-33 | 33 | 33 | WD |
| BW-PZ-1LC | 7/7/2021 | 5,689.20 | 35.98 | 33.55 | 5,725.18 | 2.43 | 43-53 | 53 | 33 | UNWD |
| BW-PZ-1LC | 10/4/2021 | 5,688.64 | 36.54 | 34.11 | 5,725.18 | 2.43 | 43-53 | 53 | 33 | UNWD |
| C-702P1 | 7/15/2021 | 5,688.67 | 41.71 | 39.33 | 5,730.38 | 2.38 | 196-201 | 237 | 31.5 | UPPER DENVER |
| C-702P1 | 10/11/2021 | 5,688.44 | 41.94 | 39.56 | 5,730.38 | 2.38 | 196-201 | 237 | 31.5 | UPPER DENVER |
| C-702P3 | 7/15/2021 | 5,711.89 | 17.48 | 15.21 | 5,729.37 | 2.27 | 90-100 | 102 | 60 | UPPER DENVER |
| C-702P3 | 10/11/2021 | 5,711.83 | 17.54 | 15.27 | 5,729.37 | 2.27 | 90-100 | 102 | 60 | UPPER DENVER |
| C-702P4 | 7/15/2021 | 5,713.95 | 15.92 | 13.85 | 5,729.87 | 2.07 | 47-52 | 53 | NE, >37 | UNWD |
| C-702P4 | 10/11/2021 | 5,714.22 | 15.65 | 13.58 | 5,729.87 | 2.07 | 47-52 | 53 | NE, >37 | UNWD |
| C-702Q1 | 7/15/2021 | 5,678.01 | 53.75 | 51.09 | 5,731.76 | 2.66 | 219-229 | 230 | 35 | LIGNITE |
| C-702Q1 | 10/11/2021 | 5,677.92 | 53.84 | 51.18 | 5,731.76 | 2.66 | 219-229 | 230 | 35 | LIGNITE |
| C-702Q3 | 7/15/2021 | 5,713.89 | 17.25 | 15.01 | 5,731.14 | 2.24 | 30-35 | 36 | 32.5 | WD |
| C-702Q3 | 10/11/2021 | 5,713.67 | 17.47 | 15.23 | 5,731.14 | 2.24 | 30-35 | 36 | 32.5 | WD |
| EAST CLEANOUT | 7/15/2021 | 5,734.49 | 32.62 | NA[/g] | 5,767.11 | -- | -- | -- | -- | NO GEOLOGIC LOG |
| EAST CLEANOUT | 10/11/2021 | 5,734.60 | 32.51 | NA | 5,767.11 | -- | -- | -- | -- | NO GEOLOGIC LOG |
| GW-101 | 7/9/2021 | 5,729.32 | 49.68 | 48.38 | 5,779.00 | 1.30 | 78.6-98.6 | 98.9 | 42 | UNWD |
| GW-101 | 10/5/2021 | 5,729.15 | 49.85 | 48.55 | 5,779.00 | 1.30 | 78.6-98.6 | 98.9 | 42 | UNWD |
| GW-101-DEN | 7/9/2021 | 5,720.80 | 59.74 | 57.24 | 5,780.54 | 2.50 | 134 - 148.6 | 154 | 50 | UPPER DENVER |
| GW-101-DEN | 10/5/2021 | 5,720.49 | 60.05 | 57.55 | 5,780.54 | 2.50 | 134 - 148.6 | 154 | 50 | UPPER DENVER |
| GW-103 | 7/6/2021 | 5,739.75 | 58.53 | 49.55 | 5,798.28 | 8.98 | 136-155.9 | 157 | 40 | UPPER DENVER |
| GW-103 | 10/1/2021 | 5,739.55 | 58.73 | 49.75 | 5,798.28 | 8.98 | 136-155.9 | 157 | 40 | UPPER DENVER |
| GW-104 | 7/6/2021 | 5,751.68 | 48.88 | 39.22 | 5,800.56 | 9.66 | 44.4-69.3 | 69.5 | 36.3 | UNWD |
| GW-104 | 10/1/2021 | 5,751.65 | 48.91 | 39.25 | 5,800.56 | 9.66 | 44.4-69.3 | 69.5 | 36.3 | UNWD |
| GW-106 | 7/8/2021 | 5,716.96 | 21.88 | 20.44 | 5,738.84 | 1.44 | 24.5-49.5 | 50.8 | 43 | WD |
| GW-106 | 10/4/2021 | 5,716.46 | 22.38 | 20.94 | 5,738.84 | 1.44 | 24.5-49.5 | 50.8 | 43 | WD |
| GW-106-DEN | 7/8/2021 | 5,711.68 | 27.88 | 25.32 | 5,739.56 | 2.56 | 100.6 - 125 | 135 | 43 | UPPER DENVER |
| GW-106-DEN | 10/4/2021 | 5,711.53 | 28.03 | 25.47 | 5,739.56 | 2.56 | 100.6 - 125 | 135 | 43 | UPPER DENVER |
| GW-106-LIG | 7/8/2021 | 5,691.04 | 49.74 | 46.76 | 5,740.78 | 2.98 | 235-250 | 258 | 43.4 | LIGNITE |
| GW-106-LIG | 10/4/2021 | 5,690.88 | 49.9 | 46.92 | 5,740.78 | 2.98 | 235-250 | 258 | 43.4 | LIGNITE |
| GW-107A | 7/7/2021 | 5,699.80 | 26.59 | 25.1 | 5,726.39 | 1.49 | 15-35 | 59 | 32 | WD |
| GW-107A | 10/4/2021 | 5,698.54 | 27.85 | 26.36 | 5,726.39 | 1.49 | 15-35 | 59 | 32 | WD |
| GW-107UD | 7/7/2021 | 5,699.50 | 27.95 | 26.13 | 5,727.45 | 1.82 | 48.5-58.5 | 58.5 | 31.6 | UNWD |
| GW-107UD | 10/4/2021 | 5,701.19 | 26.26 | 24.44 | 5,727.45 | 1.82 | 48.5-58.5 | 58.5 | 31.6 | UNWD |

**TABLE 4.2**
**WATER LEVEL ELEVATIONS**
**JULY THROUGH DECEMBER 2021 OPERATIONS AND MAINTENANCE STATUS REPORT**
**LOWRY LANDFILL SUPERFUND SITE**

| Well ID | Date of Measurement | Water-Surface Elevation (ft NGVD)[a/] | Measured Depth to Water (ft below MP)[b/] | Depth to Water (ft bgs)[c/] | Measuring Point Elevation (ft NGVD) | Stickup (ft)[d/] | Screened Interval (ft bgs) | Total Depth (ft bgs) | Base of Weathering (ft bgs) | Formation[e/] |
|---|---|---|---|---|---|---|---|---|---|---|
| GW-107UDR | 7/7/2021 | 5,677.11 | 50.18 | 47.89 | 5,727.29 | 2.29 | 47-62 | 64.5 | 34 | UNWD |
| GW-107UDR | 10/4/2021 | 5,678.65 | 48.64 | 46.35 | 5,727.29 | 2.29 | 47-62 | 64.5 | 34 | UNWD |
| GW-108A | 7/7/2021 | 5,688.70 | 43.79 | 41.1 | 5,732.49 | 2.69 | 52.6-87.6 | 99 | 42 | UNWD |
| GW-108A | 10/4/2021 | 5,687.98 | 44.51 | 41.82 | 5,732.49 | 2.69 | 52.6-87.6 | 99 | 42 | UNWD |
| GW-109 | 7/8/2021 | Dry | Dry | Dry | 5,707.99 | 1.49 | 8.6-28.6 | 29 | NE, >29 | ALLUVIUM |
| GW-109 | 10/4/2021 | Dry | Dry | Dry | 5,707.99 | 1.49 | 8.6-28.6 | 29 | NE, >29 | ALLUVIUM |
| GW-112 | 7/15/2021 | 5,735.92 | 34.03 | 24.08 | 5,769.95 | 9.95 | 9.2-29.2 | 34.2 | 30.5 | WD |
| GW-112 | 10/11/2021 | 5,736.11 | 33.84 | 23.89 | 5,769.95 | 9.95 | 9.2-29.2 | 34.2 | 30.5 | WD |
| GW-113 | 7/15/2021 | 5,719.58 | 54.28 | 51.82 | 5,773.86 | 2.46 | 149.8-174.8 | 175.5 | 38 | UPPER DENVER |
| GW-113 | 10/11/2021 | 5,719.46 | 54.4 | 51.94 | 5,773.86 | 2.46 | 149.8-174.8 | 175.5 | 38 | UPPER DENVER |
| GW-114A | 7/7/2021 | 5,695.99 | 36.31 | 34.31 | 5,732.30 | 2.00 | 29.5-39.5 | 40 | NE, >40 | WD |
| GW-114A | 10/4/2021 | 5,695.97 | 36.33 | 34.33 | 5,732.30 | 2.00 | 29.5-39.5 | 40 | NE, >40 | WD |
| GW-120 | 7/15/2021 | 5,681.89 | 109.1 | 100.91 | 5,790.99 | 8.19 | 287.8-297.8 | 310 | 65 | LIGNITE |
| GW-120 | 10/11/2021 | 5,681.38 | 109.61 | 101.42 | 5,790.99 | 8.19 | 287.8-297.8 | 310 | 65 | LIGNITE |
| GW-121 | 7/15/2021 | 5,681.86 | 92.83 | 90.84 | 5,774.69 | 1.99 | 266.7-291.7 | 298 | 32 | LIGNITE |
| GW-121 | 10/11/2021 | 5,680.98 | 93.71 | 91.72 | 5,774.69 | 1.99 | 266.7-291.7 | 298 | 32 | LIGNITE |
| GW-122 | 7/9/2021 | 5,681.94 | 143.32 | 139.66 | 5,825.26 | 3.66 | 312.8-332.8 | 343 | 84 | LIGNITE |
| GW-122 | 10/5/2021 | 5,681.03 | 144.23 | 140.57 | 5,825.26 | 3.66 | 312.8-332.8 | 343 | 84 | LIGNITE |
| GW-POA1 | 7/14/2021 | 5,751.04 | 33.55 | 31.16 | 5,784.59 | 2.39 | 21.1-41.1 | 43.75 | 41.1 | WD |
| GW-POA1 | 10/7/2021 | 5,751.04 | 33.55 | 31.16 | 5,784.59 | 2.39 | 21.1-41.1 | 43.75 | 41.1 | WD |
| GW-POA-1N | 7/14/2021 | 5,751.63 | 25.94 | 23.76 | 5,777.57 | 2.18 | 19.5-32 | 35 | 32.5 | WD |
| GW-POA-1N | 10/7/2021 | 5,751.60 | 25.97 | 23.79 | 5,777.57 | 2.18 | 19.5-32 | 35 | 32.5 | WD |
| GW-POA-1NE | 7/14/2021 | 5,749.00 | 24.08 | 21.44 | 5,773.08 | 2.08 | 17-32 | 34.5 | 32.6 | WD |
| GW-POA-1NE | 10/7/2021 | 5,749.33 | 23.75 | 21.11 | 5,773.08 | 2.08 | 17-32 | 34.5 | 32.6 | WD |
| GW-POA2 | 7/15/2021 | 5,747.72 | 33.98 | 31.98 | 5,781.70 | 2.00 | 17.3-37.3 | 40.7 | 37.3 | WD |
| GW-POA2 | 10/11/2021 | 5,747.70 | 34 | 32 | 5,781.70 | 2.00 | 17.3-37.3 | 40.7 | 37.3 | WD |
| GW-POA3 | 7/15/2021 | Dry | Dry | Dry | 5,752.77 | 2.77 | 14.7-29.7 | 33 | 29.7 | WD |
| GW-POA3 | 10/11/2021 | Dry | Dry | Dry | 5,752.77 | 2.77 | 14.7-29.7 | 33 | 29.7 | WD |
| GW-POA4 | 7/15/2021 | 5,715.94 | 26.6 | 23.86 | 5,742.54 | 2.74 | 13.2-38.2 | 41.2 | 38.2 | WD |
| GW-POA4 | 10/11/2021 | 5,716.21 | 26.33 | 23.59 | 5,742.54 | 2.74 | 13.2-38.2 | 41.2 | 38.2 | WD |
| MNA-01 | 7/15/2021 | 5,737.67 | 23.98 | 21.23 | 5,761.65 | 2.75 | 15-35 | 37 | 33 | WD |
| MNA-01 | 10/11/2021 | 5,738.00 | 23.65 | 20.9 | 5,761.65 | 2.75 | 15-35 | 37 | 33 | WD |
| MNA-02 | 7/15/2021 | 5,739.14 | 20.19 | 17.66 | 5,759.33 | 2.53 | 12-32 | 34 | 32 | WD |
| MNA-02 | 10/11/2021 | 5,739.52 | 19.81 | 17.28 | 5,759.33 | 2.53 | 12-32 | 34 | 32 | WD |
| MNA-03 | 7/15/2021 | 5,739.31 | 18.72 | 15.99 | 5,758.03 | 2.73 | 10-35 | 37 | 35 | WD |
| MNA-03 | 10/11/2021 | 5,739.56 | 18.47 | 15.74 | 5,758.03 | 2.73 | 10-35 | 37 | 35 | WD |
| MNA-04 | 7/15/2021 | 5,739.07 | 17.56 | 14.83 | 5,756.63 | 2.73 | 14-34 | 39 | 34 | WD |
| MNA-04 | 10/11/2021 | 5,739.20 | 17.43 | 14.7 | 5,756.63 | 2.73 | 14-34 | 39 | 34 | WD |
| MNA-05 | 7/15/2021 | 5,738.19 | 16.49 | 14.21 | 5,754.68 | 2.28 | 9-34 | 37 | 34 | WD |
| MNA-05 | 10/11/2021 | 5,738.32 | 16.36 | 14.08 | 5,754.68 | 2.28 | 9-34 | 37 | 34 | WD |
| MNA-06 | 7/15/2021 | 5,742.82 | 22.57 | 19.88 | 5,765.39 | 2.69 | 13-28 | 30 | 28 | WD |
| MNA-06 | 10/11/2021 | 5,743.36 | 22.03 | 19.34 | 5,765.39 | 2.69 | 13-28 | 30 | 28 | WD |
| MNA-07 | 7/15/2021 | 5,743.00 | 22.06 | 19.6 | 5,765.06 | 2.46 | 17-37 | 39 | 37 | WD |
| MNA-07 | 10/11/2021 | 5,743.10 | 21.96 | 19.5 | 5,765.06 | 2.46 | 17-37 | 39 | 37 | WD |
| MNA-08 | 7/15/2021 | 5,722.63 | 17.02 | 14.67 | 5,739.65 | 2.35 | 12-32 | 34 | 32 | WD |
| MNA-08 | 10/11/2021 | 5,722.24 | 17.41 | 15.06 | 5,739.65 | 2.35 | 12-32 | 34 | 32 | WD |
| MNA-09 | 7/15/2021 | 5,717.49 | 15.95 | 13.11 | 5,733.44 | 2.84 | 8.5-38.5 | 41.5 | 38.5 | WD |
| MNA-09 | 10/11/2021 | 5,716.09 | 17.35 | 14.51 | 5,733.44 | 2.84 | 8.5-38.5 | 41.5 | 38.5 | WD |
| MNA-10 | 7/15/2021 | 5,713.49 | 14.46 | 11.71 | 5,727.95 | 2.75 | 9-34 | 39 | 34 | WD |
| MNA-10 | 10/11/2021 | 5,713.33 | 14.62 | 11.87 | 5,727.95 | 2.75 | 9-34 | 39 | 34 | WD |
| MNA-11 | 7/15/2021 | 5,706.83 | 17.89 | 14.87 | 5,724.72 | 3.02 | 9.5-29.5 | 33 | 29.5 | WD |
| MNA-11 | 10/11/2021 | 5,706.93 | 17.79 | 14.77 | 5,724.72 | 3.02 | 9.5-29.5 | 33 | 29.5 | WD |
| MNA-12 | 7/15/2021 | 5,704.23 | 15.66 | 13.07 | 5,719.89 | 2.59 | 8.5-28.5 | 31 | 28.5 | WD |
| MNA-12 | 10/11/2021 | 5,704.30 | 15.59 | 13 | 5,719.89 | 2.59 | 8.5-28.5 | 31 | 28.5 | WD |
| MNA-13 | 7/15/2021 | 5,699.27 | 17.74 | 15.63 | 5,717.01 | 2.11 | 10-25 | 29 | 25 | WD |
| MNA-13 | 10/11/2021 | 5,698.91 | 18.1 | 15.99 | 5,717.01 | 2.11 | 10-25 | 29 | 25 | WD |
| MPZ-1 | 7/15/2021 | Dry | Dry | Dry | 5,722.55 | 2.08 | 3.2-13.2 | 13.5 | NE, >13.5 | ALLUVIUM |
| MPZ-1 | 10/11/2021 | Dry | Dry | Dry | 5,722.55 | 2.08 | 3.2-13.2 | 13.5 | NE, >13.5 | ALLUVIUM |
| MPZ-10R | 7/15/2021 | 5,729.01 | 33.64 | 32.59 | 5,762.65 | 1.05 | 16.8-36.8 | 37 | NE, > | FILL |
| MPZ-10R | 10/11/2021 | 5,728.67 | 33.98 | 32.93 | 5,762.65 | 1.05 | 16.8-36.8 | 37 | NE, > | FILL |
| MPZ-11 | 7/15/2021 | 5,734.33 | 32.1 | 28.32 | 5,766.43 | 3.78 | 11-36 | 36 | NE | FILL |
| MPZ-11 | 10/11/2021 | 5,734.45 | 31.98 | 28.2 | 5,766.43 | 3.78 | 11-36 | 36 | NE | FILL |
| MPZ-12 | 7/15/2021 | 5,738.96 | 24.13 | 21.34 | 5,763.09 | 2.79 | 7-32 | 35 | NE, >35 | ALLUVIUM |
| MPZ-12 | 10/11/2021 | 5,739.30 | 23.79 | 21 | 5,763.09 | 2.79 | 7-32 | 35 | NE, >35 | ALLUVIUM |
| MPZ-13 | 7/15/2021 | 5,739.05 | 24.3 | 22.05 | 5,763.35 | 2.25 | 7.3-32.3 | 35 | NE, >35 | WD |
| MPZ-13 | 10/11/2021 | 5,739.72 | 23.63 | 21.38 | 5,763.35 | 2.25 | 7.3-32.3 | 35 | NE, >35 | WD |

**TABLE 4.2**
**WATER LEVEL ELEVATIONS**
**JULY THROUGH DECEMBER 2021 OPERATIONS AND MAINTENANCE STATUS REPORT**
**LOWRY LANDFILL SUPERFUND SITE**

| Well ID | Date of Measurement | Water-Surface Elevation (ft NGVD)[a/] | Measured Depth to Water (ft below MP)[b/] | Depth to Water (ft bgs)[c/] | Measuring Point Elevation (ft NGVD) | Stickup (ft)[d/] | Screened Interval (ft bgs) | Total Depth (ft bgs) | Base of Weathering (ft bgs) | Formation[e/] |
|---|---|---|---|---|---|---|---|---|---|---|
| MPZ-2 | 7/15/2021 | 5,711.94 | 13.68 | 11.57 | 5,725.62 | 2.11 | 3.2-13.2 | 13.5 | NE, >13.5 | ALLUVIUM |
| MPZ-2 | 10/11/2021 | 5,711.82 | 13.8 | 11.69 | 5,725.62 | 2.11 | 3.2-13.2 | 13.5 | NE, >13.5 | ALLUVIUM |
| MPZ-3 | 7/15/2021 | 5,716.98 | 14.44 | 12.68 | 5,731.42 | 1.76 | 3.5-13.5 | 13.5 | NE, >13.5 | ALLUVIUM |
| MPZ-3 | 10/11/2021 | 5,716.64 | 14.78 | 13.02 | 5,731.42 | 1.76 | 3.5-13.5 | 13.5 | NE, >13.5 | ALLUVIUM |
| MPZ-4 | 7/15/2021 | Dry | Dry | Dry | 5,738.70 | 1.77 | 3.5-13.5 | 13.5 | NE, >13.5 | ALLUVIUM |
| MPZ-4 | 10/11/2021 | Dry | Dry | Dry | 5,738.70 | 1.77 | 3.5-13.5 | 13.5 | NE, >13.5 | ALLUVIUM |
| MPZ-5 | 7/15/2021 | Dry | Dry | Dry | 5,744.26 | 1.63 | 3.7-13.65 | 13.65 | NE, >13.5 | ALLUVIUM |
| MPZ-5 | 10/11/2021 | Dry | Dry | Dry | 5,744.26 | 1.63 | 3.7-13.65 | 13.65 | NE, >13.5 | ALLUVIUM |
| MPZ-6 | 7/15/2021 | Dry | Dry | Dry | 5,749.51 | 1.95 | 3.3-13.3 | 13.5 | NE, >13.5 | ALLUVIUM |
| MPZ-6 | 10/11/2021 | Dry | Dry | Dry | 5,749.51 | 1.95 | 3.3-13.3 | 13.5 | NE, >13.5 | ALLUVIUM |
| MPZ-7 | 7/15/2021 | Dry | Dry | Dry | 5,756.19 | 1.45 | 3.4-13.4 | 13.5 | NE, >13.5 | ALLUVIUM |
| MPZ-7 | 10/11/2021 | Dry | Dry | Dry | 5,756.19 | 1.45 | 3.4-13.4 | 13.5 | NE, >13.5 | ALLUVIUM |
| MPZ-8 | 7/15/2021 | Dry | Dry | Dry | 5,771.19 | 8.87 | 3.4-13.4 | 13.5 | NE, >13.5 | ALLUVIUM |
| MPZ-8 | 10/11/2021 | Dry | Dry | Dry | 5,771.19 | 8.87 | 3.4-13.4 | 13.5 | NE, >13.5 | ALLUVIUM |
| MPZ-9 | 7/15/2021 | Dry | Dry | Dry | 5,769.92 | 6.30 | 3.5-13.5 | 13.54 | NE, >13.5 | ALLUVIUM |
| MPZ-9 | 10/11/2021 | Dry | Dry | Dry | 5,769.92 | 6.30 | 3.5-13.5 | 13.54 | NE, >13.5 | ALLUVIUM |
| MW-1 | 7/12/2021 | 5,745.10 | 72.07 | 70 | 5,817.17 | 2.07 | 106-156 | 156 | 45 | UNWD |
| MW-1 | 10/8/2021 | 5,744.91 | 72.26 | 70.19 | 5,817.17 | 2.07 | 106-156 | 156 | 45 | UNWD |
| MW-1000 | 7/7/2021 | Dry | Dry | Dry | 5,717.68 | 2.34 | 18-28 | 28 | 26.5 | WD |
| MW-1000 | 10/4/2021 | 5,687.60 | 30.08 | 27.74 | 5,717.68 | 2.34 | 18-28 | 28 | 26.5 | WD |
| MW-1000LC | 7/7/2021 | 5,686.87 | 30.5 | 28.07 | 5,717.37 | 2.43 | 37.5-47.5 | 47.5 | 26.5 | UNWD |
| MW-1000LC | 10/4/2021 | 5,686.26 | 31.11 | 28.68 | 5,717.37 | 2.43 | 37.5-47.5 | 47.5 | 26.5 | UNWD |
| MW100-WD | 7/2/2021 | 5,701.17 | 26.4 | 23.83 | 5,727.57 | 2.57 | 30-35 | 38.5 | 35 | WD |
| MW100-WD | 10/4/2021 | 5,700.76 | 26.81 | 24.24 | 5,727.57 | 2.57 | 30-35 | 38.5 | 35 | WD |
| MW101-WD | 7/2/2021 | 5,698.11 | 23.58 | 21.19 | 5,721.69 | 2.39 | 22.5-32.5 | 34 | 32 | WD |
| MW101-WD | 10/4/2021 | 5,697.75 | 23.94 | 21.55 | 5,721.69 | 2.39 | 22.5-32.5 | 34 | 32 | WD |
| MW102-WD | 7/2/2021 | 5,696.39 | 26.76 | 24.41 | 5,723.15 | 2.35 | 24-36 | 38.5 | 36 | WD |
| MW102-WD | 10/4/2021 | 5,695.91 | 27.24 | 24.89 | 5,723.15 | 2.35 | 24-36 | 38.5 | 36 | WD |
| MW103-WD | 7/2/2021 | 5,693.38 | 26.1 | 23.67 | 5,719.48 | 2.43 | 21.7 - 36.7 | 39 | 37 | WD |
| MW103-WD | 10/4/2021 | 5,693.08 | 26.4 | 23.97 | 5,719.48 | 2.43 | 21.7 - 36.7 | 39 | 37 | WD |
| MW104-WD | 7/2/2021 | 5,686.99 | 22.11 | 18.88 | 5,709.10 | 3.23 | 13.7 - 33.7 | 36 | 33.7 | WD |
| MW104-WD | 10/4/2021 | 5,686.38 | 22.72 | 19.49 | 5,709.10 | 3.23 | 13.7 - 33.7 | 36 | 33.7 | WD |
| MW105-WD | 7/9/2021 | 5,723.13 | 21.74 | 19.28 | 5,744.87 | 2.46 | 22 - 32 | 34.3 | 32 | WD |
| MW105-WD | 10/5/2021 | 5,722.43 | 22.44 | 19.98 | 5,744.87 | 2.46 | 22 - 32 | 34.3 | 32 | WD |
| MW106-UD | 7/9/2021 | 5,750.80 | 35.48 | 32.75 | 5,786.28 | 2.73 | 41 - 51 | 54 | 36 | UNWD |
| MW106-UD | 10/5/2021 | 5,750.88 | 35.4 | 32.67 | 5,786.28 | 2.73 | 41 - 51 | 54 | 36 | UNWD |
| MW107-UD | 7/9/2021 | 5,752.01 | 53.74 | 51.54 | 5,805.75 | 2.20 | 61.9 - 76.9 | 79.3 | 47 | UNWD |
| MW107-UD | 10/5/2021 | 5,751.96 | 53.79 | 51.59 | 5,805.75 | 2.20 | 61.9 - 76.9 | 79.3 | 47 | UNWD |
| MW107-WD | 7/9/2021 | 5,765.49 | 40.46 | 38.05 | 5,805.95 | 2.41 | 36 - 46 | 48.5 | 45 | WD |
| MW107-WD | 10/5/2021 | 5,765.26 | 40.69 | 38.28 | 5,805.95 | 2.41 | 36 - 46 | 48.5 | 45 | WD |
| MW108-WD | 7/8/2021 | 5,808.19 | 18.03 | 15.51 | 5,826.22 | 2.52 | 30 - 45 | 50 | 47.5 | WD |
| MW108-WD | 10/1/2021 | 5,807.34 | 18.88 | 16.36 | 5,826.22 | 2.52 | 30 - 45 | 50 | 47.5 | WD |
| MW109-WD | 7/6/2021 | 5,793.64 | 40.63 | 38.91 | 5,834.27 | 1.72 | 36 - 51 | 54 | 50.8 | WD |
| MW109-WD | 10/1/2021 | 5,793.55 | 40.72 | 39 | 5,834.27 | 1.72 | 36 - 51 | 54 | 50.8 | WD |
| MW110-WD | 7/6/2021 | 5,782.29 | 48.04 | 45.52 | 5,830.33 | 2.52 | 41.5 - 56.5 | 58.8 | 56.5 | WD |
| MW110-WD | 10/1/2021 | 5,782.25 | 48.08 | 45.56 | 5,830.33 | 2.52 | 41.5 - 56.5 | 58.8 | 56.5 | WD |
| MW111-UD | 7/6/2021 | 5,766.81 | 50 | 47.79 | 5,816.81 | 2.21 | 69 - 74 | 79.5 | 61 | UNWD |
| MW111-UD | 10/1/2021 | 5,766.58 | 50.23 | 48.02 | 5,816.81 | 2.21 | 69 - 74 | 79.5 | 61 | UNWD |
| MW112-DEN | 7/6/2021 | 5,737.88 | 105.13 | 102.64 | 5,843.01 | 2.49 | 174.6 - 204 | 209 | 50 | UPPER DENVER |
| MW112-DEN | 10/1/2021 | 5,737.53 | 105.48 | 102.99 | 5,843.01 | 2.49 | 174.6 - 204 | 209 | 50 | UPPER DENVER |
| MW112-UD | 7/6/2021 | 5,792.15 | 50.2 | 47.65 | 5,842.35 | 2.55 | 60 - 75 | 79 | 49 | UNWD |
| MW112-UD | 10/1/2021 | 5,791.90 | 50.45 | 47.9 | 5,842.35 | 2.55 | 60 - 75 | 79 | 49 | UNWD |
| MW112-WD | 7/6/2021 | 5,806.39 | 36.2 | 33.68 | 5,842.59 | 2.52 | 28.5 - 48.5 | 51 | 48.5 | WD |
| MW112-WD | 10/1/2021 | 5,806.45 | 36.14 | 33.62 | 5,842.59 | 2.52 | 28.5 - 48.5 | 51 | 48.5 | WD |
| MW113-EW-1 | 7/8/2021 | 5,669.92 | 41.35 | 40.38 | 5,711.27 | 0.97 | 20-50 | 55.3 | 46 | WD |
| MW113-EW-1 | 10/4/2021 | 5,663.83 | 47.44 | 46.47 | 5,711.27 | 0.97 | 20-50 | 55.3 | 46 | WD |
| MW113-LD | 7/8/2021 | 5,678.36 | 33.99 | 31.64 | 5,712.35 | 2.35 | 77.2-97.2 | 100 | 35.1 | UNWD |
| MW113-LD | 10/4/2021 | 5,676.69 | 35.66 | 33.31 | 5,712.35 | 2.35 | 77.2-97.2 | 100 | 35.1 | UNWD |
| MW113-UD | 7/8/2021 | 5,631.69 | 80.59 | 78.31 | 5,712.28 | 2.28 | 59-79 | 84 | 51.7 | UNWD |
| MW113-UD | 10/4/2021 | 5,631.71 | 80.57 | 78.29 | 5,712.28 | 2.28 | 59-79 | 84 | 51.7 | UNWD |
| MW113-WD | 7/8/2021 | 5,670.01 | 43.43 | 39.89 | 5,713.44 | 3.54 | 20-50 | 55 | 51.7 | WD |
| MW113-WD | 10/4/2021 | 5,666.00 | 47.44 | 43.9 | 5,713.44 | 3.54 | 20-50 | 55 | 51.7 | WD |
| MW114-WD | 7/2/2021 | 5,689.09 | 24.25 | 21.41 | 5,713.34 | 3.00 | 22-32 | 38 | 32 | WD |
| MW114-WD | 10/4/2021 | 5,688.73 | 24.61 | 21.77 | 5,713.34 | 3.00 | 22-32 | 38 | 32 | WD |
| MW115-UD | 7/2/2021 | 5,687.65 | 14.7 | 12.17 | 5,702.35 | 2.53 | 46.6-56.6 | -- | 24 | UNWD |
| MW115-UD | 10/4/2021 | 5,687.17 | 15.18 | 12.65 | 5,702.35 | 2.53 | 46.6-56.6 | -- | 24 | UNWD |

**TABLE 4.2**
**WATER LEVEL ELEVATIONS**
**JULY THROUGH DECEMBER 2021 OPERATIONS AND MAINTENANCE STATUS REPORT**
**LOWRY LANDFILL SUPERFUND SITE**

| Well ID | Date of Measurement | Water-Surface Elevation (ft NGVD)[a/] | Measured Depth to Water (ft below MP)[b/] | Depth to Water (ft bgs)[c/] | Measuring Point Elevation (ft NGVD) | Stickup (ft)[d/] | Screened Interval (ft bgs) | Total Depth (ft bgs) | Base of Weathering (ft bgs) | Formation[e/] |
|---|---|---|---|---|---|---|---|---|---|---|
| MW115-WD | 7/2/2021 | 5,687.51 | 20.86 | 13.52 | 5,708.37 | 2.25 | 11.3-26.3 | 30 | 26.3 | WD |
| MW115-WD | 10/4/2021 | 5,687.00 | 21.37 | 14.03 | 5,708.37 | 2.25 | 11.3-26.3 | 30 | 26.3 | WD |
| MW116-WD | 7/2/2021 | 5,687.74 | 26.73 | 24.08 | 5,714.47 | 2.65 | 24.9-39.9 | 45 | 39.9 | WD |
| MW116-WD | 10/4/2021 | 5,687.21 | 27.26 | 24.61 | 5,714.47 | 2.65 | 24.9-39.9 | 45 | 39.9 | WD |
| MW117-WD | 7/2/2021 | 5,686.14 | 14.18 | 11.76 | 5,700.32 | 2.42 | 10.5-30.5 | 33 | 30.5 | WD |
| MW117-WD | 10/4/2021 | 5,685.48 | 14.84 | 12.42 | 5,700.32 | 2.42 | 10.5-30.5 | 33 | 30.5 | WD |
| MW118-UD | 7/2/2021 | 5,687.50 | 17.66 | 15.1 | 5,705.16 | 2.56 | 62-77 | 80 | 34.9 | UNWD |
| MW118-UD | 10/4/2021 | 5,686.96 | 18.2 | 15.64 | 5,705.16 | 2.56 | 62-77 | 80 | 34.9 | UNWD |
| MW118-WD | 7/2/2021 | 5,685.29 | 20.05 | 17.45 | 5,705.34 | 2.60 | 20.1-35.1 | 37.5 | 35.1 | WD |
| MW118-WD | 10/4/2021 | 5,684.61 | 20.73 | 18.13 | 5,705.34 | 2.60 | 20.1-35.1 | 37.5 | 35.1 | WD |
| MW119-WD | 7/2/2021 | 5,688.23 | 16 | 14.17 | 5,704.23 | 1.83 | 18-28 | 31.5 | 29 | WD |
| MW119-WD | 10/4/2021 | 5,687.72 | 16.51 | 14.68 | 5,704.23 | 1.83 | 18-28 | 31.5 | 29 | WD |
| MW120-WD | 7/2/2021 | 5,687.15 | 15.02 | 12.75 | 5,702.17 | 2.27 | 18-28 | 32 | 30 | WD |
| MW120-WD | 10/4/2021 | 5,686.55 | 15.62 | 13.35 | 5,702.17 | 2.27 | 18-28 | 32 | 30 | WD |
| MW121-WDR | 7/1/2021 | 5,652.44 | 22.98 | 20.46 | 5,675.42 | 2.52 | 23.5-33.5 | 36 | 36.5 | WD |
| MW121-WDR | 10/6/2021 | 5,651.74 | 23.68 | 21.16 | 5,675.42 | 2.52 | 23.5-33.5 | 36 | 36.5 | WD |
| MW122-WDR | 7/1/2021 | 5,652.68 | 19.95 | 17.32 | 5,672.63 | 2.63 | 20.5-30.5 | 36 | 33 | WD |
| MW122-WDR | 10/6/2021 | 5,651.86 | 20.77 | 18.14 | 5,672.63 | 2.63 | 20.5-30.5 | 36 | 33 | WD |
| MW123-WD | 7/1/2021 | 5,653.16 | 18.88 | 16.14 | 5,672.04 | 2.74 | 22-32 | 36 | 33 | WD |
| MW123-WD | 10/6/2021 | 5,652.13 | 19.91 | 17.17 | 5,672.04 | 2.74 | 22-32 | 36 | 33 | WD |
| MW124-WD | 7/1/2021 | 5,653.72 | 18.31 | 16.08 | 5,672.03 | 2.23 | 23-33 | 39 | 34.5 | WD |
| MW124-WD | 10/6/2021 | 5,652.41 | 19.62 | 17.39 | 5,672.03 | 2.23 | 23-33 | 39 | 34.5 | WD |
| MW125-WD | 7/1/2021 | 5,654.83 | 18.07 | 14.87 | 5,672.90 | 3.20 | 22-32 | 37 | 36 | WD |
| MW125-WD | 10/6/2021 | 5,653.15 | 19.75 | 16.55 | 5,672.90 | 3.20 | 22-32 | 37 | 36 | WD |
| MW126-WD | 7/1/2021 | 5,655.54 | 17.61 | 14.66 | 5,673.15 | 2.95 | 20-30 | 34 | 33 | WD |
| MW126-WD | 10/6/2021 | 5,653.82 | 19.33 | 16.38 | 5,673.15 | 2.95 | 20-30 | 34 | 33 | WD |
| MW127-WD | 7/1/2021 | 5,655.98 | 16.38 | 14.02 | 5,672.36 | 2.36 | 20-30 | 34 | 32.5 | WD |
| MW127-WD | 10/6/2021 | 5,654.25 | 18.11 | 15.75 | 5,672.36 | 2.36 | 20-30 | 34 | 32.5 | WD |
| MW129-WD | 7/1/2021 | 5,649.91 | 21.2 | 18.89 | 5,671.11 | 2.31 | 20.8-30.5 | 34 | 31 | WD |
| MW129-WD | 10/6/2021 | 5,649.73 | 21.38 | 19.07 | 5,671.11 | 2.31 | 20.8-30.5 | 34 | 31 | WD |
| MW130-WD | 7/1/2021 | 5,649.60 | 23.43 | 21.2 | 5,673.03 | 2.23 | 21.3-31 | 37.5 | 32.4 | WD |
| MW130-WD | 10/6/2021 | 5,649.66 | 23.37 | 21.14 | 5,673.03 | 2.23 | 21.3-31 | 37.5 | 32.4 | WD |
| MW131-WD | 7/1/2021 | 5,649.40 | 26.85 | 24.9 | 5,676.25 | 1.95 | 23.3-33 | 36 | 34.3 | WD |
| MW131-WD | 10/6/2021 | 5,649.83 | 26.42 | 24.47 | 5,676.25 | 1.95 | 23.3-33 | 36 | 34.3 | WD |
| MW132-WD | 7/1/2021 | 5,674.88 | 3.76 | 1.42 | 5,678.64 | 2.34 | 4-14 | 24 | 21.5 | WD |
| MW132-WD | 10/6/2021 | 5,674.13 | 4.51 | 2.17 | 5,678.64 | 2.34 | 4-14 | 24 | 21.5 | WD |
| MW133-WD | 7/1/2021 | 5,636.10 | 12.5 | 12.4 | 5,648.60 | 0.10 | 14-24 | 27 | 24.5 | WD |
| MW133-WD | 10/6/2021 | 5,636.02 | 12.58 | 12.48 | 5,648.60 | 0.10 | 14-24 | 27 | 24.5 | WD |
| MW134-WD | 7/1/2021 | 5,637.68 | 18.89 | 16.42 | 5,656.57 | 2.47 | 15-30 | 33 | 30.5 | WD |
| MW134-WD | 10/6/2021 | 5,637.59 | 18.98 | 16.51 | 5,656.57 | 2.47 | 15-30 | 33 | 30.5 | WD |
| MW135-WD | 7/1/2021 | 5,638.95 | 19.08 | 19.5 | 5,658.03 | -0.42 | 18-38 | 41.5 | 39 | WD |
| MW135-WD | 10/6/2021 | 5,638.88 | 19.15 | 19.57 | 5,658.03 | -0.42 | 18-38 | 41.5 | 39 | WD |
| MW136-WD | 7/1/2021 | 5,638.69 | 20.61 | 21.01 | 5,659.30 | -0.40 | 21-46 | 49 | 46.5 | WD |
| MW136-WD | 10/6/2021 | 5,638.49 | 20.81 | 21.21 | 5,659.30 | -0.40 | 21-46 | 49 | 46.5 | WD |
| MW137-WD | 7/1/2021 | 5,638.46 | 16.42 | 16.8 | 5,654.88 | -0.38 | 21-41 | 44 | 39.5 | WD |
| MW137-WD | 10/6/2021 | 5,638.22 | 16.66 | 17.04 | 5,654.88 | -0.38 | 21-41 | 44 | 39.5 | WD |
| MW138-WD | 7/1/2021 | 5,638.29 | 15.51 | 15.81 | 5,653.80 | -0.30 | 19-39 | 43 | 39.5 | WD |
| MW138-WD | 10/6/2021 | 5,637.89 | 15.91 | 16.21 | 5,653.80 | -0.30 | 19-39 | 43 | 39.5 | WD |
| MW139-WD | 7/1/2021 | 5,638.77 | 10.93 | 11.13 | 5,649.70 | -0.20 | 17-37 | 44 | 39.8 | WD |
| MW139-WD | 10/6/2021 | 5,638.16 | 11.54 | 11.74 | 5,649.70 | -0.20 | 17-37 | 44 | 39.8 | WD |
| MW140-WD | 7/1/2021 | 5,607.51 | 18.06 | 18.39 | 5,625.57 | -0.33 | 21-36 | 44 | 42.5 | WD |
| MW140-WD | 10/6/2021 | 5,607.05 | 18.52 | 18.85 | 5,625.57 | -0.33 | 21-36 | 44 | 42.5 | WD |
| MW141-UDEN | 7/1/2021 | 5,605.32 | 18.2 | 18.66 | 5,623.52 | -0.46 | 57-77 | 79 | 37.5 | UNWEATHERED DENVER |
| MW141-UDEN | 10/6/2021 | 5,604.83 | 18.69 | 19.15 | 5,623.52 | -0.46 | 57-77 | 79 | 37.5 | UNWEATHERED DENVER |
| MW141-WD | 7/1/2021 | 5,607.33 | 17.4 | 17.67 | 5,624.73 | -0.27 | 21-31 | 44 | 42 | WD |
| MW141-WD | 10/6/2021 | 5,606.81 | 17.92 | 18.19 | 5,624.73 | -0.27 | 21-31 | 44 | 42 | WD |
| MW142-WD | 7/1/2021 | 5,589.62 | 8.98 | 9.38 | 5,598.60 | -0.40 | 10-20 | 34 | 33.5 | WD |
| MW142-WD | 10/6/2021 | 5,589.46 | 9.14 | 9.54 | 5,598.60 | -0.40 | 10-20 | 34 | 33.5 | WD |
| MW144-WD | 7/1/2021 | 5,568.43 | 13.94 | 14.11 | 5,582.37 | -0.17 | 16.5-31.5 | 36 | 35.5 | WD |
| MW144-WD | 10/6/2021 | 5,567.79 | 14.58 | 14.75 | 5,582.37 | -0.17 | 16.5-31.5 | 36 | 35.5 | WD |
| MW145-WD | 7/1/2021 | 5,568.45 | 11.39 | 11.66 | 5,579.84 | -0.27 | 13-38 | 40.9 | 38 | WD |
| MW145-WD | 10/6/2021 | 5,567.85 | 11.99 | 12.26 | 5,579.84 | -0.27 | 13-38 | 40.9 | 38 | WD |
| MW151-WD | 7/1/2021 | 5,662.98 | 16.52 | 14.02 | 5,679.50 | 2.50 | 17-27 | 39 | 36.6 | WD |
| MW151-WD | 10/6/2021 | 5,659.29 | 20.21 | 17.71 | 5,679.50 | 2.50 | 17-27 | 39 | 36.6 | WD |
| MW153-EW-1 | 7/1/2021 | 5,663.44 | 10.95 | 8.76 | 5,674.39 | 2.19 | 13-23 | 29.5 | 28.7 | WD |
| MW153-EW-1 | 10/6/2021 | 5,659.41 | 14.98 | 12.79 | 5,674.39 | 2.19 | 13-23 | 29.5 | 28.7 | WD |

**TABLE 4.2**
**WATER LEVEL ELEVATIONS**
**JULY THROUGH DECEMBER 2021 OPERATIONS AND MAINTENANCE STATUS REPORT**
**LOWRY LANDFILL SUPERFUND SITE**

| Well ID | Date of Measurement | Water-Surface Elevation (ft NGVD)[a/] | Measured Depth to Water (ft below MP)[b/] | Depth to Water (ft bgs)[c/] | Measuring Point Elevation (ft NGVD) | Stickup (ft)[d/] | Screened Interval (ft bgs) | Total Depth (ft bgs) | Base of Weathering (ft bgs) | Formation[e/] |
|---|---|---|---|---|---|---|---|---|---|---|
| MW153-WD | 7/1/2021 | 5,663.57 | 9.66 | 7.23 | 5,673.23 | 2.43 | 10-20 | 32 | 29.7 | WD |
| MW153-WD | 10/6/2021 | 5,659.37 | 13.86 | 11.43 | 5,673.23 | 2.43 | 10-20 | 32 | 29.7 | WD |
| MW154-EW-1 | 7/1/2021 | 5,663.47 | 11 | 8.83 | 5,674.47 | 2.17 | 11.5-21.5 | 28 | -- | WD |
| MW154-EW-1 | 10/6/2021 | 5,659.56 | 14.91 | 12.74 | 5,674.47 | 2.17 | 11.5-21.5 | 28 | -- | WD |
| MW154-WD | 7/1/2021 | 5,663.73 | 9.98 | 7.77 | 5,673.71 | 2.21 | 7-22 | 32 | 28.5 | WD |
| MW154-WD | 10/6/2021 | 5,659.59 | 14.12 | 11.91 | 5,673.71 | 2.21 | 7-22 | 32 | 28.5 | WD |
| MW155-EW-1 | 7/1/2021 | 5,663.81 | 10.51 | 8.09 | 5,674.32 | 2.42 | 9.5-19.5 | 25 | -- | WD |
| MW155-EW-1 | 10/6/2021 | 5,659.47 | 14.85 | 12.43 | 5,674.32 | 2.42 | 9.5-19.5 | 25 | -- | WD |
| MW155-WD | 7/1/2021 | 5,663.73 | 10.71 | 7.17 | 5,674.44 | 3.54 | 9-19 | 34 | 32.3 | WD |
| MW155-WD | 10/6/2021 | 5,659.38 | 15.06 | 11.52 | 5,674.44 | 3.54 | 9-19 | 34 | 32.3 | WD |
| MW156-EW-1 | 7/1/2021 | 5,663.81 | 9.54 | 7.09 | 5,673.35 | 2.45 | 11-21 | 29 | -- | WD |
| MW156-EW-1 | 10/6/2021 | 5,659.31 | 14.04 | 11.59 | 5,673.35 | 2.45 | 11-21 | 29 | -- | WD |
| MW156-WD | 7/1/2021 | 5,663.46 | 9.34 | 6.94 | 5,672.80 | 2.40 | 14-24 | 34 | 33 | WD |
| MW156-WD | 10/6/2021 | 5,658.83 | 13.97 | 11.57 | 5,672.80 | 2.40 | 14-24 | 34 | 33 | WD |
| MW157-WD | 7/1/2021 | 5,662.99 | 9.59 | 7.31 | 5,672.58 | 2.28 | 14-24 | 33.3 | 31.5 | WD |
| MW157-WD | 10/6/2021 | 5,658.29 | 14.29 | 12.01 | 5,672.58 | 2.28 | 14-24 | 33.3 | 31.5 | WD |
| MW158-WD | 7/1/2021 | 5,661.31 | 11.95 | 9.69 | 5,673.26 | 2.26 | 15-25 | 39 | 34 | WD |
| MW158-WD | 10/6/2021 | 5,657.74 | 15.52 | 13.26 | 5,673.26 | 2.26 | 15-25 | 39 | 34 | WD |
| MW160-WD | 7/1/2021 | 5,655.09 | 35.38 | 31.21 | 5,690.47 | 4.17 | 15-30 | 36 | 31 | WD |
| MW160-WD | 10/6/2021 | 5,654.32 | 36.15 | 31.98 | 5,690.47 | 4.17 | 15-30 | 36 | 31 | WD |
| MW170-EW-1 | 7/2/2021 | 5,676.18 | 55.62 | 54 | 5,731.80 | 1.62 | 25-60 | 65 | 60 | WD |
| MW170-EW-1 | 10/4/2021 | 5,676.43 | 55.37 | 53.75 | 5,731.80 | 1.62 | 25-60 | 65 | 60 | WD |
| MW170-WD | 7/2/2021 | 5,687.17 | 42.74 | 42.84 | 5,729.91 | -0.10 | 20-55 | 58 | 55.5 | WD |
| MW170-WD | 10/4/2021 | 5,687.00 | 42.91 | 43.01 | 5,729.91 | -0.10 | 20-55 | 58 | 55.5 | WD |
| MW171-WD | 7/2/2021 | 5,702.88 | 27.8 | 25.4 | 5,730.68 | 2.40 | 17.5-32.5 | 35 | 32.5 | WD |
| MW171-WD | 10/4/2021 | 5,700.50 | 30.18 | 27.78 | 5,730.68 | 2.40 | 17.5-32.5 | 35 | 32.5 | WD |
| MW172-WD | 7/2/2021 | 5,700.14 | 30.35 | 28.23 | 5,730.49 | 2.12 | 18-38 | 43 | 38 | WD |
| MW172-WD | 10/4/2021 | 5,699.80 | 30.69 | 28.57 | 5,730.49 | 2.12 | 18-38 | 43 | 38 | WD |
| MW173-WD | 7/2/2021 | 5,701.55 | 29.24 | 26.99 | 5,730.79 | 2.25 | 18-33 | 38 | 35.5 | WD |
| MW173-WD | 10/4/2021 | 5,701.21 | 29.58 | 27.33 | 5,730.79 | 2.25 | 18-33 | 38 | 35.5 | WD |
| MW174-WD | 7/2/2021 | 5,702.08 | 31.47 | 28.8 | 5,733.55 | 2.67 | 20.7-35.7 | 38 | 36 | WD |
| MW174-WD | 10/4/2021 | 5,701.77 | 31.78 | 29.11 | 5,733.55 | 2.67 | 20.7-35.7 | 38 | 36 | WD |
| MW175-WD | 7/2/2021 | 5,689.38 | 44.03 | 41.48 | 5,733.41 | 2.55 | 25.5-45.5 | 49 | 46 | WD |
| MW175-WD | 10/4/2021 | 5,688.92 | 44.49 | 41.94 | 5,733.41 | 2.55 | 25.5-45.5 | 49 | 46 | WD |
| MW176-DEN | 7/1/2021 | 5,558.58 | 15.55 | 15.88 | 5,574.13 | -0.23 | 12-52 | 55 | 55 | Upper Denver |
| MW176-DEN | 10/6/2021 | 5,557.51 | 16.62 | 16.95 | 5,574.13 | -0.23 | 12-52 | 55 | 55 | Upper Denver |
| MW176-UDEN | 7/1/2021 | 5,557.89 | 17.33 | 17.86 | 5,575.22 | -0.53 | 74-94 | 109 | 51 | UNWEATHERED DENVER |
| MW176-UDEN | 10/6/2021 | 5,557.48 | 17.74 | 18.27 | 5,575.22 | -0.53 | 74-94 | 109 | 51 | UNWEATHERED DENVER |
| MW177-DEN | 7/1/2021 | 5,569.35 | 12.85 | 13.29 | 5,582.20 | -0.44 | 17.5-27.5 | 33 | 27.5 | UPPER DENVER |
| MW177-DEN | 10/6/2021 | 5,568.79 | 13.41 | 13.85 | 5,582.20 | -0.44 | 17.5-27.5 | 33 | 27.5 | UPPER DENVER |
| MW177-UDEN | 7/1/2021 | 5,565.27 | 16.65 | 17.02 | 5,581.92 | -0.37 | 47-62 | 69 | 27.5 | UNWEATHERED DENVER |
| MW177-UDEN | 10/6/2021 | 5,564.80 | 17.12 | 17.49 | 5,581.92 | -0.37 | 47-62 | 69 | 27.5 | UNWEATHERED DENVER |
| MW178-DEN | 7/1/2021 | 5,559.89 | 17.6 | 17.96 | 5,577.49 | -0.36 | 16-36 | 43 | 36 | UPPER DENVER |
| MW178-DEN | 10/6/2021 | 5,558.98 | 18.51 | 18.87 | 5,577.49 | -0.36 | 16-36 | 43 | 36 | UPPER DENVER |
| MW178-UDEN | 7/1/2021 | 5,536.74 | 39.9 | 40.75 | 5,576.64 | -0.85 | 67-97 | 99 | 36.5 | UNWEATHERED DENVER |
| MW178-UDEN | 10/6/2021 | 5,536.53 | 40.11 | 40.96 | 5,576.64 | -0.85 | 67-97 | 99 | 36.5 | UNWEATHERED DENVER |
| MW179-UDEN | 7/1/2021 | 5,649.18 | 22.68 | 20.92 | 5,671.86 | 1.85 | 56-81 | 84 | 29 | UNWEATHERED DENVER |
| MW179-UDEN | 10/6/2021 | 5,648.79 | 23.07 | 21.31 | 5,671.86 | 1.85 | 56-81 | 84 | 29 | UNWEATHERED DENVER |
| MW180-WD | 7/1/2021 | 5,678.21 | 16.63 | 14.49 | 5,694.84 | 2.14 | 17-27 | 30 | 27 | WD |
| MW180-WD | 10/6/2021 | 5,677.86 | 16.98 | 14.84 | 5,694.84 | 2.14 | 17-27 | 30 | 27 | WD |
| MW-2 | 7/12/2021 | 5,757.83 | 78.74 | 76.77 | 5,836.57 | 1.97 | 64-119 | 142 | 60 | UNWD |
| MW-2 | 10/8/2021 | 5,757.75 | 78.82 | 76.85 | 5,836.57 | 1.97 | 64-119 | 142 | 60 | UNWD |
| MW23-C-SD | 7/2/2021 | 5,699.09 | 29.58 | 27.21 | 5,728.67 | 2.37 | 56-71 | 73 | 38 | UNWD |
| MW23-C-SD | 10/4/2021 | 5,698.56 | 30.11 | 27.74 | 5,728.67 | 2.37 | 56-71 | 73 | 38 | UNWD |
| MW23-UPPER-C | 7/2/2021 | 5,702.43 | 26.5 | 24.17 | 5,728.93 | 2.33 | 25-35 | 38 | 37 | WD |
| MW23-UPPER-C | 10/4/2021 | 5,702.03 | 26.9 | 24.57 | 5,728.93 | 2.33 | 25-35 | 38 | 37 | WD |
| MW23-WD | 7/2/2021 | 5,701.54 | 28.44 | 25.43 | 5,729.98 | 3.01 | 35-55 | 56.5 | NE, >56.5 | UNWD |
| MW23-WD | 10/4/2021 | 5,701.18 | 28.8 | 25.79 | 5,729.98 | 3.01 | 35-55 | 56.5 | NE, >56.5 | UNWD |
| MW-3 | 7/12/2021 | 5,788.31 | 42.95 | 40.59 | 5,831.26 | 2.36 | 47-97 | 102 | 55 | UNWD |
| MW-3 | 10/8/2021 | 5,787.34 | 43.92 | 41.56 | 5,831.26 | 2.36 | 47-97 | 102 | 55 | UNWD |
| MW30-BU | 7/9/2021 | 5,718.13 | 78.82 | 76.11 | 5,796.95 | 2.71 | 150-180 | 183 | 48 | UPPER DENVER |
| MW30-BU | 10/5/2021 | 5,717.81 | 79.14 | 76.43 | 5,796.95 | 2.71 | 150-180 | 183 | 48 | UPPER DENVER |
| MW32-UD | 7/6/2021 | 5,787.98 | 46.18 | 44.42 | 5,834.16 | 1.76 | 59.5-69.5 | 69.8 | 49 | UNWD |
| MW32-UD | 10/1/2021 | 5,787.26 | 46.9 | 45.14 | 5,834.16 | 1.76 | 59.5-69.5 | 69.8 | 49 | UNWD |
| MW32-WD | 7/6/2021 | 5,802.02 | 32.4 | 29.96 | 5,834.42 | 2.44 | 32.7 - 47.7 | 50 | 47.5 | WD |
| MW32-WD | 10/1/2021 | 5,803.19 | 31.23 | 28.79 | 5,834.42 | 2.44 | 32.7 - 47.7 | 50 | 47.5 | WD |

**TABLE 4.2**
**WATER LEVEL ELEVATIONS**
**JULY THROUGH DECEMBER 2021 OPERATIONS AND MAINTENANCE STATUS REPORT**
**LOWRY LANDFILL SUPERFUND SITE**

| Well ID | Date of Measurement | Water-Surface Elevation (ft NGVD)[a/] | Measured Depth to Water (ft below MP)[b/] | Depth to Water (ft bgs)[c/] | Measuring Point Elevation (ft NGVD) | Stickup (ft)[d/] | Screened Interval (ft bgs) | Total Depth (ft bgs) | Base of Weathering (ft bgs) | Formation[e/] |
|---|---|---|---|---|---|---|---|---|---|---|
| MW33-UD | 7/6/2021 | 5,788.72 | 56.16 | 54.18 | 5,844.88 | 1.98 | 62.5-72.5 | 75 | 51.5 | UNWD |
| MW33-UD | 10/1/2021 | 5,788.67 | 56.21 | 54.23 | 5,844.88 | 1.98 | 62.5-72.5 | 75 | 51.5 | UNWD |
| MW33-WDR | 7/6/2021 | Dry | Dry | Dry | 5,844.27 | 1.97 | 31.5-43.2 | -- | 50.6 | WD |
| MW33-WDR | 10/1/2021 | Dry | Dry | Dry | 5,844.27 | 1.97 | 31.5-43.2 | -- | 50.6 | WD |
| MW34-UD | 7/6/2021 | 5,787.22 | 48.99 | 46.58 | 5,836.21 | 2.41 | 64-74 | 74 | 54.5 | UNWD |
| MW34-UD | 10/1/2021 | 5,787.40 | 48.81 | 46.4 | 5,836.21 | 2.41 | 64-74 | 74 | 54.5 | UNWD |
| MW34-WDR | 7/6/2021 | 5,790.13 | 46.09 | 43.37 | 5,836.22 | 2.72 | 43 - 53 | 56 | 53.5 | WD |
| MW34-WDR | 10/1/2021 | 5,790.64 | 45.58 | 42.86 | 5,836.22 | 2.72 | 43 - 53 | 56 | 53.5 | WD |
| MW35-UD | 7/6/2021 | 5,759.34 | 58.91 | 56.76 | 5,818.25 | 2.15 | 69.79 | 79 | 59 | UNWD |
| MW35-UD | 10/1/2021 | 5,759.34 | 58.91 | 56.76 | 5,818.25 | 2.15 | 69.79 | 79 | 59 | UNWD |
| MW35-WDR | 7/6/2021 | 5,778.83 | 39.16 | 36.47 | 5,817.99 | 2.69 | 36.7 - 56.7 | 59 | 58 | WD |
| MW35-WDR | 10/1/2021 | 5,778.70 | 39.29 | 36.6 | 5,817.99 | 2.69 | 36.7 - 56.7 | 59 | 58 | WD |
| MW36-UD | 7/6/2021 | 5,767.32 | 33.74 | 31.78 | 5,801.06 | 1.96 | 56.5-66.5 | 66.5 | 46.1 | UNWD |
| MW36-UD | 10/1/2021 | 5,767.25 | 33.81 | 31.85 | 5,801.06 | 1.96 | 56.5-66.5 | 66.5 | 46.1 | UNWD |
| MW36-WDR | 7/6/2021 | 5,771.46 | 29.75 | 27.34 | 5,801.21 | 2.41 | 30.5-42.5 | 48.6 | 42.5 | WD |
| MW36-WDR | 10/1/2021 | 5,771.37 | 29.84 | 27.43 | 5,801.21 | 2.41 | 30.5-42.5 | 48.6 | 42.5 | WD |
| MW37-UD | 7/7/2021 | 5,699.23 | 28.11 | 26.17 | 5,727.34 | 1.94 | 38-53 | 59 | 32.5 | UNWD |
| MW37-UD | 10/4/2021 | 5,699.24 | 28.1 | 26.16 | 5,727.34 | 1.94 | 38-53 | 59 | 32.5 | UNWD |
| MW37-WD | 7/7/2021 | 5,695.85 | 32.56 | 29.56 | 5,728.41 | 3.00 | 22-32 | 35 | 32 | WD |
| MW37-WD | 10/4/2021 | 5,695.80 | 32.61 | 29.61 | 5,728.41 | 3.00 | 22-32 | 35 | 32 | WD |
| MW38-0N-140W | 7/13/2021 | 5,745.65 | 62.23 | 59.95 | 5,807.88 | 2.28 | 48-63 | 79 | 63 | WD |
| MW38-0N-140W | 10/8/2021 | 5,745.74 | 62.14 | 59.86 | 5,807.88 | 2.28 | 48-63 | 79 | 63 | WD |
| MW38-1005N-150E | 7/12/2021 | 5,734.36 | 41.92 | 39.44 | 5,776.28 | 2.48 | 36.5-56.5 | 61.4 | 56.5 | WD |
| MW38-1005N-150E | 10/8/2021 | 5,733.37 | 42.91 | 40.43 | 5,776.28 | 2.48 | 36.5-56.5 | 61.4 | 56.5 | WD |
| MW38-100N-200E | 7/13/2021 | 5,747.34 | 43.68 | 41.16 | 5,791.02 | 2.52 | 33-48 | 50.5 | 48 | WD |
| MW38-100N-200E | 10/8/2021 | 5,747.36 | 43.66 | 41.14 | 5,791.02 | 2.52 | 33-48 | 50.5 | 48 | WD |
| MW38-100N-53W | 7/13/2021 | Dry | Dry | Dry | 5,804.53 | 2.03 | 48-58 | 69 | 58 | WD |
| MW38-100N-53W | 10/8/2021 | Dry | Dry | Dry | 5,804.53 | 2.03 | 48-58 | 69 | 58 | WD |
| MW38-100N-60E | 7/13/2021 | 5,736.84 | 60.69 | 58.16 | 5,797.53 | 2.53 | 40-60 | 64.5 | 61.5 | WD |
| MW38-100N-60E | 10/8/2021 | 5,736.60 | 60.93 | 58.4 | 5,797.53 | 2.53 | 40-60 | 64.5 | 61.5 | WD |
| MW38-100S-140W | 7/14/2021 | Dry | Dry | Dry | 5,807.35 | 1.55 | 48.5-68.5 | 74 | 68.5 | WD |
| MW38-100S-140W | 10/7/2021 | Dry | Dry | Dry | 5,807.35 | 1.55 | 48.5-68.5 | 74 | 68.5 | WD |
| MW38-100S-195W | 7/13/2021 | 5,736.84 | 70.38 | 70.73 | 5,807.22 | -0.35 | 51-71 | 73.5 | 71 | WD |
| MW38-100S-195W | 10/8/2021 | Dry | Dry | Dry | 5,807.22 | -0.35 | 51-71 | 73.5 | 71 | WD |
| MW38-100S-200E | 7/14/2021 | 5,748.58 | 43.48 | 41.02 | 5,792.06 | 2.46 | 34-49 | 51.5 | 49 | WD |
| MW38-100S-200E | 10/7/2021 | 5,748.54 | 43.52 | 41.06 | 5,792.06 | 2.46 | 34-49 | 51.5 | 49 | WD |
| MW38-100S-53W | 7/14/2021 | Dry | Dry | Dry | 5,806.51 | 3.71 | 46-66 | 79 | 66 | WD |
| MW38-100S-53W | 10/7/2021 | Dry | Dry | Dry | 5,806.51 | 3.71 | 46-66 | 79 | 66 | WD |
| MW38-1028N-256E | 7/12/2021 | 5,719.67 | 52.13 | 50.03 | 5,771.80 | 2.10 | 28-53 | 56 | NE, > 56 | WD |
| MW38-1028N-256E | 10/8/2021 | 5,719.68 | 52.12 | 50.02 | 5,771.80 | 2.10 | 28-53 | 56 | NE, > 56 | WD |
| MW38-1064N-650E | 7/12/2021 | 5,739.20 | 21.68 | 19.2 | 5,760.88 | 2.48 | 20-35 | 39 | 35 | WD |
| MW38-1064N-650E | 10/8/2021 | 5,737.04 | 23.84 | 21.36 | 5,760.88 | 2.48 | 20-35 | 39 | 35 | WD |
| MW38-1064N-655E | 7/12/2021 | 5,726.88 | 33.72 | 31.52 | 5,760.60 | 2.20 | 40-55 | 57.5 | 35.5 | UNWD |
| MW38-1064N-655E | 10/8/2021 | 5,727.28 | 33.32 | 31.12 | 5,760.60 | 2.20 | 40-55 | 57.5 | 35.5 | UNWD |
| MW38-1064N-660E | 7/12/2021 | 5,717.37 | 43.17 | 40.93 | 5,760.54 | 2.24 | 60-75 | 77.5 | 35 | UNWD |
| MW38-1064N-660E | 10/8/2021 | 5,717.29 | 43.25 | 41.01 | 5,760.54 | 2.24 | 60-75 | 77.5 | 35 | UNWD |
| MW38-1095N-226E | 7/12/2021 | 5,720.74 | 50.57 | 48.76 | 5,771.31 | 1.81 | 23-53 | 69 | 52.5 | WD |
| MW38-1095N-226E | 10/8/2021 | 5,720.62 | 50.69 | 48.88 | 5,771.31 | 1.81 | 23-53 | 69 | 52.5 | WD |
| MW38-1100N-0E | 7/12/2021 | 5,745.20 | 34.56 | 32.1 | 5,779.76 | 2.46 | 32-47 | 54 | 47 | WD |
| MW38-1100N-0E | 10/8/2021 | 5,745.30 | 34.46 | 32 | 5,779.76 | 2.46 | 32-47 | 54 | 47 | WD |
| MW38-1100N-326E | 7/12/2021 | 5,728.17 | 38.22 | 38.23 | 5,766.39 | -0.01 | 34.5-49.5 | 52.5 | 49.5 | WD |
| MW38-1100N-326E | 10/8/2021 | 5,728.61 | 37.78 | 37.79 | 5,766.39 | -0.01 | 34.5-49.5 | 52.5 | 49.5 | WD |
| MW38-1120N-1000E | 7/13/2021 | 5,716.75 | 33.46 | 32.75 | 5,750.21 | 0.71 | 50-70 | 72.5 | 44 | UNWD |
| MW38-1120N-1000E | 10/8/2021 | 5,716.65 | 33.56 | 32.85 | 5,750.21 | 0.71 | 50-70 | 72.5 | 44 | UNWD |
| MW38-1175N-300E | 7/12/2021 | Dry | Dry | Dry | 5,767.86 | -0.42 | 25.5-45.5 | 48.5 | 45.5 | WD |
| MW38-1175N-300E | 10/8/2021 | 5,723.06 | 44.8 | 45.22 | 5,767.86 | -0.42 | 25.5-45.5 | 48.5 | 45.5 | WD |
| MW38-1175N-518E | 7/12/2021 | 5,736.51 | 29.9 | 30.09 | 5,766.41 | -0.19 | 25.5-45.5 | 48 | 45.5 | WD |
| MW38-1175N-518E | 10/8/2021 | 5,735.76 | 30.65 | 30.84 | 5,766.41 | -0.19 | 25.5-45.5 | 48 | 45.5 | WD |
| MW38-1200N-226E | 7/12/2021 | 5,709.85 | 62.24 | 60.65 | 5,772.09 | 1.59 | 45-70 | 74 | 69.5 | UNWD |
| MW38-1200N-226E | 10/8/2021 | 5,709.85 | 62.24 | 60.65 | 5,772.09 | 1.59 | 45-70 | 74 | 69.5 | UNWD |
| MW38-1363N-180W | 7/13/2021 | 5,724.73 | 46.11 | 46.37 | 5,770.84 | -0.26 | 70-90 | 94.5 | 58 | UNWD |
| MW38-1363N-180W | 10/8/2021 | 5,724.61 | 46.23 | 46.49 | 5,770.84 | -0.26 | 70-90 | 94.5 | 58 | UNWD |
| MW38-1373N-180W | 7/13/2021 | 5,722.91 | 49.18 | 46.39 | 5,772.09 | 2.79 | 36-51 | 54 | 51 | WD |
| MW38-1373N-180W | 10/8/2021 | 5,723.17 | 48.92 | 46.13 | 5,772.09 | 2.79 | 36-51 | 54 | 51 | WD |
| MW38-150S-320W | 7/12/2021 | 5,759.74 | 53.86 | 51.36 | 5,813.60 | 2.50 | 47-57 | 59.5 | 57 | WD |
| MW38-150S-320W | 10/8/2021 | 5,759.69 | 53.91 | 51.41 | 5,813.60 | 2.50 | 47-57 | 59.5 | 57 | WD |

**TABLE 4.2**
**WATER LEVEL ELEVATIONS**
**JULY THROUGH DECEMBER 2021 OPERATIONS AND MAINTENANCE STATUS REPORT**
**LOWRY LANDFILL SUPERFUND SITE**

| Well ID | Date of Measurement | Water-Surface Elevation (ft NGVD)[a/] | Measured Depth to Water (ft below MP)[b/] | Depth to Water (ft bgs)[c/] | Measuring Point Elevation (ft NGVD) | Stickup (ft)[d/] | Screened Interval (ft bgs) | Total Depth (ft bgs) | Base of Weathering (ft bgs) | Formation[e/] |
|---|---|---|---|---|---|---|---|---|---|---|
| MW38-170S-140W | 7/14/2021 | 5,734.59 | 72.17 | 69.91 | 5,806.76 | 2.26 | 58-73 | 78.5 | 74 | WD |
| MW38-170S-140W | 10/7/2021 | 5,734.57 | 72.19 | 69.93 | 5,806.76 | 2.26 | 58-73 | 78.5 | 74 | WD |
| MW38-200N-425E | 7/13/2021 | 5,731.41 | 49.44 | 47.29 | 5,780.85 | 2.15 | 33-58 | 69 | 40 | UNWD |
| MW38-200N-425E | 10/8/2021 | 5,731.77 | 49.08 | 46.93 | 5,780.85 | 2.15 | 33-58 | 69 | 40 | UNWD |
| MW38-200N-60E | 7/13/2021 | 5,737.18 | 58.24 | 55.72 | 5,795.42 | 2.52 | 38.5-58.5 | 61.6 | 58.5 | WD |
| MW38-200N-60E | 10/8/2021 | 5,736.96 | 58.46 | 55.94 | 5,795.42 | 2.52 | 38.5-58.5 | 61.6 | 58.5 | WD |
| MW38-200S-140W | 7/14/2021 | 5,735.67 | 70.89 | 68.63 | 5,806.56 | 2.26 | 53-73 | 77 | 72 | WD |
| MW38-200S-140W | 10/7/2021 | 5,735.54 | 71.02 | 68.76 | 5,806.56 | 2.26 | 53-73 | 77 | 72 | WD |
| MW38-200S-180W | 7/14/2021 | 5,735.99 | 72.17 | 70.31 | 5,808.16 | 1.86 | 55-75 | 78.8 | 75 | WD |
| MW38-200S-180W | 10/7/2021 | 5,735.81 | 72.35 | 70.49 | 5,808.16 | 1.86 | 55-75 | 78.8 | 75 | WD |
| MW38-200S-195W | 7/13/2021 | 5,736.17 | 70.42 | 70.9 | 5,806.59 | -0.48 | 53-73 | 76.5 | 73 | WD |
| MW38-200S-195W | 10/8/2021 | 5,735.99 | 70.6 | 71.08 | 5,806.59 | -0.48 | 53-73 | 76.5 | 73 | WD |
| MW38-250S-160W | 7/14/2021 | 5,743.40 | 62.91 | 60.3 | 5,806.31 | 2.61 | 51-63 | 68 | 63 | WD |
| MW38-250S-160W | 10/7/2021 | 5,743.35 | 62.96 | 60.35 | 5,806.31 | 2.61 | 51-63 | 68 | 63 | WD |
| MW38-250S-320W | 7/12/2021 | 5,759.32 | 55.07 | 52.58 | 5,814.39 | 2.49 | 45-60 | 64 | 60 | WD |
| MW38-250S-320W | 10/8/2021 | 5,759.28 | 55.11 | 52.62 | 5,814.39 | 2.49 | 45-60 | 64 | 60 | WD |
| MW38-250S-50W | 7/14/2021 | Dry | Dry | Dry | 5,803.99 | 3.09 | 34-49 | 54 | 49 | WD |
| MW38-250S-50W | 10/7/2021 | Dry | Dry | Dry | 5,803.99 | 3.09 | 34-49 | 54 | 49 | WD |
| MW38-275S-195W | 7/13/2021 | 5,738.04 | 67.89 | 68.06 | 5,805.93 | -0.17 | 50-70 | 72.5 | 69 | WD |
| MW38-275S-195W | 10/8/2021 | 5,738.01 | 67.92 | 68.09 | 5,805.93 | -0.17 | 50-70 | 72.5 | 69 | WD |
| MW38-300S-180W | 7/14/2021 | 5,745.42 | 62.22 | 59.38 | 5,807.64 | 2.84 | 56-61 | 64 | 61 | WD |
| MW38-300S-180W | 10/7/2021 | 5,745.40 | 62.24 | 59.4 | 5,807.64 | 2.84 | 56-61 | 64 | 61 | WD |
| MW38-300S-315W | 7/12/2021 | 5,745.08 | 68.81 | 66.62 | 5,813.89 | 2.19 | 53.7-68.7 | 87 | 68 | WD |
| MW38-300S-315W | 10/8/2021 | 5,745.09 | 68.8 | 66.61 | 5,813.89 | 2.19 | 53.7-68.7 | 87 | 68 | WD |
| MW38-300S-60E | 7/14/2021 | 5,748.41 | 47.71 | 45.99 | 5,796.12 | 1.72 | 40-50 | 58 | 50 | WD |
| MW38-300S-60E | 10/7/2021 | 5,748.44 | 47.68 | 45.96 | 5,796.12 | 1.72 | 40-50 | 58 | 50 | WD |
| MW38-302S-50W | 7/14/2021 | 5,743.90 | 58.78 | 56.3 | 5,802.68 | 2.48 | 50-70 | 79 | 55 | UNWD |
| MW38-302S-50W | 10/7/2021 | 5,743.78 | 58.9 | 56.42 | 5,802.68 | 2.48 | 50-70 | 79 | 55 | UNWD |
| MW38-320N-305E | 7/13/2021 | 5,728.88 | 55.31 | 52.22 | 5,784.19 | 3.09 | 40-55 | 64 | NE, >64 | WD |
| MW38-320N-305E | 10/8/2021 | 5,728.97 | 55.22 | 52.13 | 5,784.19 | 3.09 | 40-55 | 64 | NE, >64 | WD |
| MW38-325S-195W | 7/13/2021 | 5,746.55 | 58.88 | 59.04 | 5,805.43 | -0.16 | 48.5-63.5 | 66 | 62.5 | WD |
| MW38-325S-195W | 10/8/2021 | 5,746.55 | 58.88 | 59.04 | 5,805.43 | -0.16 | 48.5-63.5 | 66 | 62.5 | WD |
| MW38-350N-175E | 7/13/2021 | 5,739.10 | 49.48 | 46.5 | 5,788.58 | 2.98 | 27-47 | 49.5 | 47 | WD |
| MW38-350N-175E | 10/8/2021 | 5,739.10 | 49.48 | 46.5 | 5,788.58 | 2.98 | 27-47 | 49.5 | 47 | WD |
| MW38-350S-200E | 7/14/2021 | 5,748.67 | 40.57 | 38.13 | 5,789.24 | 2.44 | 37.5-44.5 | 53.8 | 44.5 | WD |
| MW38-350S-200E | 10/7/2021 | 5,748.72 | 40.52 | 38.08 | 5,789.24 | 2.44 | 37.5-44.5 | 53.8 | 44.5 | WD |
| MW38-350S-320W | 7/12/2021 | 5,747.53 | 66.63 | 64.17 | 5,814.16 | 2.46 | 54-74 | 77 | 74 | WD |
| MW38-350S-320W | 10/8/2021 | 5,747.51 | 66.65 | 64.19 | 5,814.16 | 2.46 | 54-74 | 77 | 74 | WD |
| MW38-350S-50W | 7/14/2021 | 5,747.81 | 54.24 | 51.69 | 5,802.05 | 2.55 | 36-56 | 58.5 | 57 | WD |
| MW38-350S-50W | 10/7/2021 | 5,747.85 | 54.2 | 51.65 | 5,802.05 | 2.55 | 36-56 | 58.5 | 57 | WD |
| MW38-350S-60E | 7/14/2021 | 5,748.35 | 47.89 | 45.35 | 5,796.24 | 2.54 | 33.5-53.5 | 57.2 | 53.5 | WD |
| MW38-350S-60E | 10/7/2021 | 5,748.36 | 47.88 | 45.34 | 5,796.24 | 2.54 | 33.5-53.5 | 57.2 | 53.5 | WD |
| MW38-360N-405E | 7/13/2021 | Dry | Dry | Dry | 5,779.52 | 2.44 | 40-55 | 59 | 49 | WD/UNWD |
| MW38-360N-405E | 10/8/2021 | Dry | Dry | Dry | 5,779.52 | 2.44 | 40-55 | 59 | 49 | WD/UNWD |
| MW38-390S-60E | 7/14/2021 | 5,748.38 | 46.55 | 44.02 | 5,794.93 | 2.53 | 30.5-50.5 | 73 | 50.5 | WD |
| MW38-390S-60E | 10/7/2021 | 5,748.42 | 46.51 | 43.98 | 5,794.93 | 2.53 | 30.5-50.5 | 73 | 50.5 | WD |
| MW38-400N-100E | 7/13/2021 | 5,738.88 | 50.06 | 47.72 | 5,788.94 | 2.34 | 40-55 | 62 | 55 | WD |
| MW38-400N-100E | 10/8/2021 | 5,738.80 | 50.14 | 47.8 | 5,788.94 | 2.34 | 40-55 | 62 | 55 | WD |
| MW38-400N-180W | 7/13/2021 | 5,756.75 | 42.01 | 38.85 | 5,798.76 | 3.16 | 41.5-56.5 | 59 | 57 | WD |
| MW38-400N-180W | 10/8/2021 | 5,756.58 | 42.18 | 39.02 | 5,798.76 | 3.16 | 41.5-56.5 | 59 | 57 | WD |
| MW38-400N-240E | 7/13/2021 | 5,738.87 | 45.84 | 43.13 | 5,784.71 | 2.71 | 31-46 | 49.2 | 46 | WD |
| MW38-400N-240E | 10/8/2021 | 5,738.78 | 45.93 | 43.22 | 5,784.71 | 2.71 | 31-46 | 49.2 | 46 | WD |
| MW38-400N-300E | 7/13/2021 | 5,718.29 | 64.82 | 62.31 | 5,783.11 | 2.51 | 65.6-85.6 | 89 | 45 | UNWD |
| MW38-400N-300E | 10/8/2021 | 5,718.26 | 64.85 | 62.34 | 5,783.11 | 2.51 | 65.6-85.6 | 89 | 45 | UNWD |
| MW38-400S-0W | 7/14/2021 | 5,747.97 | 50.83 | 47.73 | 5,798.80 | 3.10 | 37.5-51.5 | 54 | 51.7 | WD |
| MW38-400S-0W | 10/7/2021 | 5,748.05 | 50.75 | 47.65 | 5,798.80 | 3.10 | 37.5-51.5 | 54 | 51.7 | WD |
| MW38-400S-140W | 7/14/2021 | 5,747.39 | 57.02 | 54.61 | 5,804.41 | 2.41 | 38.5-58.5 | 61.5 | 58.5 | WD |
| MW38-400S-140W | 10/7/2021 | 5,747.43 | 56.98 | 54.57 | 5,804.41 | 2.41 | 38.5-58.5 | 61.5 | 58.5 | WD |
| MW38-400S-195W | 7/13/2021 | 5,746.96 | 57.42 | 57.34 | 5,804.38 | 0.08 | 43.5-58.5 | 64 | 58.5 | WD |
| MW38-400S-195W | 10/8/2021 | 5,746.96 | 57.42 | 57.34 | 5,804.38 | 0.08 | 43.5-58.5 | 64 | 58.5 | WD |
| MW38-400S-320W | 7/12/2021 | 5,747.82 | 65.78 | 63.48 | 5,813.60 | 2.30 | 59.5-74.5 | 87 | 74.2 | WD |
| MW38-400S-320W | 10/8/2021 | 5,748.04 | 65.56 | 63.26 | 5,813.60 | 2.30 | 59.5-74.5 | 87 | 74.2 | WD |
| MW38-400S-50W | 7/14/2021 | 5,747.71 | 53.51 | 51.39 | 5,801.22 | 2.12 | 42-57 | 59.5 | 57 | WD |
| MW38-400S-50W | 10/7/2021 | 5,747.80 | 53.42 | 51.3 | 5,801.22 | 2.12 | 42-57 | 59.5 | 57 | WD |
| MW38-410N-180W | 7/13/2021 | 5,718.18 | 79.23 | 76.52 | 5,797.41 | 2.71 | 71.5-91.5 | 94 | 56 | UNWD |
| MW38-410N-180W | 10/8/2021 | 5,718.21 | 79.2 | 76.49 | 5,797.41 | 2.71 | 71.5-91.5 | 94 | 56 | UNWD |

**TABLE 4.2**
**WATER LEVEL ELEVATIONS**
**JULY THROUGH DECEMBER 2021 OPERATIONS AND MAINTENANCE STATUS REPORT**
**LOWRY LANDFILL SUPERFUND SITE**

| Well ID | Date of Measurement | Water-Surface Elevation (ft NGVD)[a/] | Measured Depth to Water (ft below MP)[b/] | Depth to Water (ft bgs)[c/] | Measuring Point Elevation (ft NGVD) | Stickup (ft)[d/] | Screened Interval (ft bgs) | Total Depth (ft bgs) | Base of Weathering (ft bgs) | Formation[e/] |
|---|---|---|---|---|---|---|---|---|---|---|
| MW38-450S-200E | 7/14/2021 | 5,748.67 | 40.72 | 37.93 | 5,789.39 | 2.79 | 45.5-48.5 | 48.8 | 45.5 | WD/UNWD |
| MW38-450S-200E | 10/7/2021 | 5,748.67 | 40.72 | 37.93 | 5,789.39 | 2.79 | 45.5-48.5 | 48.8 | 45.5 | WD/UNWD |
| MW38-450S-320W | 7/12/2021 | 5,750.73 | 62.02 | 59.37 | 5,812.75 | 2.65 | 50-70 | 73.2 | 70 | WD |
| MW38-450S-320W | 10/8/2021 | 5,751.03 | 61.72 | 59.07 | 5,812.75 | 2.65 | 50-70 | 73.2 | 70 | WD |
| MW38-450S-60E | 7/14/2021 | 5,748.91 | 45.33 | 42.89 | 5,794.24 | 2.44 | 31.5-51.5 | 54 | 52.5 | WD |
| MW38-450S-60E | 10/7/2021 | 5,748.94 | 45.3 | 42.86 | 5,794.24 | 2.44 | 31.5-51.5 | 54 | 52.5 | WD |
| MW38-500N-396E | 7/13/2021 | 5,740.54 | 34.55 | 31.96 | 5,775.09 | 2.59 | 24-39 | 44 | 40 | WD |
| MW38-500N-396E | 10/8/2021 | 5,740.46 | 34.63 | 32.04 | 5,775.09 | 2.59 | 24-39 | 44 | 40 | WD |
| MW38-500S-320W | 7/12/2021 | 5,750.89 | 60.72 | 58.61 | 5,811.61 | 2.11 | 55-70 | 87 | 69.3 | WD |
| MW38-500S-320W | 10/8/2021 | 5,751.16 | 60.45 | 58.34 | 5,811.61 | 2.11 | 55-70 | 87 | 69.3 | WD |
| MW38-500S-50W | 7/14/2021 | 5,749.76 | 51.02 | 48.41 | 5,800.78 | 2.61 | 36.5-51.5 | 54 | 51.5 | WD |
| MW38-500S-50W | 10/7/2021 | 5,749.82 | 50.96 | 48.35 | 5,800.78 | 2.61 | 36.5-51.5 | 54 | 51.5 | WD |
| MW38-550S-200E | 7/14/2021 | 5,750.78 | 35.29 | 32.82 | 5,786.07 | 2.47 | 34-49 | 54 | 44.5 | WD |
| MW38-550S-200E | 10/7/2021 | 5,750.80 | 35.27 | 32.8 | 5,786.07 | 2.47 | 34-49 | 54 | 44.5 | WD |
| MW38-550S-320W | 7/12/2021 | 5,751.54 | 59.15 | 57.16 | 5,810.69 | 1.99 | 58-68 | 72 | 68 | WD |
| MW38-550S-320W | 10/8/2021 | 5,751.87 | 58.82 | 56.83 | 5,810.69 | 1.99 | 58-68 | 72 | 68 | WD |
| MW38-600N-250E | 7/13/2021 | 5,738.76 | 38.22 | 35.74 | 5,776.98 | 2.48 | 27.5-42.5 | 45.1 | 42.5 | WD |
| MW38-600N-250E | 10/8/2021 | 5,738.66 | 38.32 | 35.84 | 5,776.98 | 2.48 | 27.5-42.5 | 45.1 | 42.5 | WD |
| MW38-600S-320W | 7/12/2021 | 5,752.23 | 58.63 | 56.17 | 5,810.86 | 2.46 | 52-62 | 69 | 61.5 | WD |
| MW38-600S-320W | 10/8/2021 | 5,752.51 | 58.35 | 55.89 | 5,810.86 | 2.46 | 52-62 | 69 | 61.5 | WD |
| MW38-650S-200E | 7/14/2021 | 5,751.03 | 35.51 | 31.77 | 5,786.54 | 3.74 | 42-47 | 53 | 47 | WD |
| MW38-650S-200E | 10/7/2021 | 5,751.04 | 35.5 | 31.76 | 5,786.54 | 3.74 | 42-47 | 53 | 47 | WD |
| MW38-650S-400E | 7/14/2021 | 5,750.89 | 26.04 | 23.71 | 5,776.93 | 2.33 | 16-36 | 38.5 | 36 | WD |
| MW38-650S-400E | 10/7/2021 | 5,750.87 | 26.06 | 23.73 | 5,776.93 | 2.33 | 16-36 | 38.5 | 36 | WD |
| MW38-650S-50W | 7/14/2021 | 5,752.07 | 48.34 | 45.83 | 5,800.41 | 2.51 | 35-55 | 58.5 | 55 | WD |
| MW38-650S-50W | 10/7/2021 | 5,752.16 | 48.25 | 45.74 | 5,800.41 | 2.51 | 35-55 | 58.5 | 55 | WD |
| MW38-680N-419E | 7/12/2021 | 5,749.35 | 22.91 | 20.77 | 5,772.26 | 2.14 | 25-40 | 43 | 40 | WD |
| MW38-680N-419E | 10/8/2021 | 5,747.89 | 24.37 | 22.23 | 5,772.26 | 2.14 | 25-40 | 43 | 40 | WD |
| MW38-700S-320W | 7/12/2021 | 5,765.80 | 44.68 | 41.8 | 5,810.48 | 2.88 | 54-59 | 64 | 58.9 | WD |
| MW38-700S-320W | 10/8/2021 | 5,765.99 | 44.49 | 41.61 | 5,810.48 | 2.88 | 54-59 | 64 | 58.9 | WD |
| MW38-700S-400E | 7/14/2021 | 5,750.90 | 26.36 | 24 | 5,777.26 | 2.36 | 20-35 | 38.3 | 35 | WD |
| MW38-700S-400E | 10/7/2021 | 5,750.87 | 26.39 | 24.03 | 5,777.26 | 2.36 | 20-35 | 38.3 | 35 | WD |
| MW38-750S-400E | 7/14/2021 | 5,750.90 | 26.82 | 24.8 | 5,777.72 | 2.02 | 18-33 | 37.4 | 33 | WD |
| MW38-750S-400E | 10/7/2021 | 5,750.91 | 26.81 | 24.79 | 5,777.72 | 2.02 | 18-33 | 37.4 | 33 | WD |
| MW38-758N-277E | 7/12/2021 | 5,738.55 | 32.83 | 30.35 | 5,771.38 | 2.48 | 24-36 | 49 | 36 | WD |
| MW38-758N-277E | 10/8/2021 | 5,738.39 | 32.99 | 30.51 | 5,771.38 | 2.48 | 24-36 | 49 | 36 | WD |
| MW38-770S-60E | 7/14/2021 | 5,761.29 | 32.13 | 29.61 | 5,793.42 | 2.52 | 25-45 | 48 | 45 | WD |
| MW38-770S-60E | 10/7/2021 | 5,761.38 | 32.04 | 29.52 | 5,793.42 | 2.52 | 25-45 | 48 | 45 | WD |
| MW38-794N-383E | 7/12/2021 | 5,749.49 | 22.91 | 20.47 | 5,772.40 | 2.44 | 25-40 | 42.5 | 40 | WD |
| MW38-794N-383E | 10/8/2021 | 5,747.57 | 24.83 | 22.39 | 5,772.40 | 2.44 | 25-40 | 42.5 | 40 | WD |
| MW38-815S-445E | 7/14/2021 | 5,751.03 | 29.28 | 26.49 | 5,780.31 | 2.79 | 21.7 - 36.7 | 38 | 36 | WD |
| MW38-815S-445E | 10/7/2021 | 5,751.03 | 29.28 | 26.49 | 5,780.31 | 2.79 | 21.7 - 36.7 | 38 | 36 | WD |
| MW38-825S-445E | 7/14/2021 | 5,750.98 | 30.16 | 26.62 | 5,781.14 | 3.54 | 26-36 | 41 | 36 | WD |
| MW38-825S-445E | 10/7/2021 | 5,750.97 | 30.17 | 26.63 | 5,781.14 | 3.54 | 26-36 | 41 | 36 | WD |
| MW38-830N-230E | 7/12/2021 | 5,738.48 | 35.09 | 33.5 | 5,773.57 | 1.59 | 28 - 38 | 43.4 | 40 | WD |
| MW38-830N-230E | 10/8/2021 | 5,738.29 | 35.28 | 33.69 | 5,773.57 | 1.59 | 28 - 38 | 43.4 | 40 | WD |
| MW38-830S-380E | 7/14/2021 | 5,751.13 | 28.94 | 26.77 | 5,780.07 | 2.17 | 17.5 - 32.5 | 34.8 | 33 | WD |
| MW38-830S-380E | 10/7/2021 | 5,751.08 | 28.99 | 26.82 | 5,780.07 | 2.17 | 17.5 - 32.5 | 34.8 | 33 | WD |
| MW38-840S-325E | 7/14/2021 | 5,752.55 | 27.88 | 25.38 | 5,780.43 | 2.50 | 19 - 34 | 39 | 36 | WD |
| MW38-840S-325E | 10/7/2021 | 5,752.72 | 27.71 | 25.21 | 5,780.43 | 2.50 | 19 - 34 | 39 | 36 | WD |
| MW38-890S-385E | 7/14/2021 | 5,751.62 | 32.03 | 29.43 | 5,783.65 | 2.60 | 21.3 - 36.3 | 39 | 37 | WD |
| MW38-890S-385E | 10/7/2021 | 5,751.62 | 32.03 | 29.43 | 5,783.65 | 2.60 | 21.3 - 36.3 | 39 | 37 | WD |
| MW38-995N-228E | 7/12/2021 | 5,720.79 | 53.63 | 50.91 | 5,774.42 | 2.72 | 24-64 | 74 | 64 | WD |
| MW38-995N-228E | 10/8/2021 | 5,720.68 | 53.74 | 51.02 | 5,774.42 | 2.72 | 24-64 | 74 | 64 | WD |
| MW38-995N-300E | 7/12/2021 | 5,720.75 | 50.66 | 48.15 | 5,771.41 | 2.51 | 27.5-57.5 | 60 | 57.5 | WD |
| MW38-995N-300E | 10/8/2021 | 5,720.69 | 50.72 | 48.21 | 5,771.41 | 2.51 | 27.5-57.5 | 60 | 57.5 | WD |
| MW38-995N-375E | 7/12/2021 | 5,735.00 | 33.89 | 30.7 | 5,768.89 | 3.19 | 29-49 | 51.5 | 49 | WD |
| MW38-995N-375E | 10/8/2021 | 5,734.27 | 34.62 | 31.43 | 5,768.89 | 3.19 | 29-49 | 51.5 | 49 | WD |
| MW38-995N-475E | 7/13/2021 | 5,738.51 | 21.97 | 22.49 | 5,760.48 | -0.52 | 31-51 | 53.9 | 51 | WD |
| MW38-995N-475E | 10/8/2021 | 5,736.76 | 23.72 | 24.24 | 5,760.48 | -0.52 | 31-51 | 53.9 | 51 | WD |
| MW38-WD | 7/14/2021 | 5,736.20 | 68.22 | 64.9 | 5,804.42 | 3.32 | 39.5-69.5 | 75 | 69.5 | WD |
| MW38-WD | 10/7/2021 | 5,735.91 | 68.51 | 65.19 | 5,804.42 | 3.32 | 39.5-69.5 | 75 | 69.5 | WD |
| MW39I-WD | 7/6/2021 | 5,772.17 | 33.51 | 30.73 | 5,805.68 | 2.78 | 31.1-41 | 48.8 | 41 | WD |
| MW39I-WD | 10/1/2021 | 5,772.49 | 33.19 | 30.41 | 5,805.68 | 2.78 | 31.1-41 | 48.8 | 41 | WD |
| MW39-UD | 7/6/2021 | 5,751.70 | 52.85 | 49.8 | 5,804.55 | 3.05 | 56-76 | 79 | 42.8 | UNWD |
| MW39-UD | 10/1/2021 | 5,751.69 | 52.86 | 49.81 | 5,804.55 | 3.05 | 56-76 | 79 | 42.8 | UNWD |

**TABLE 4.2**
**WATER LEVEL ELEVATIONS**
**JULY THROUGH DECEMBER 2021 OPERATIONS AND MAINTENANCE STATUS REPORT**
**LOWRY LANDFILL SUPERFUND SITE**

| Well ID | Date of Measurement | Water-Surface Elevation (ft NGVD)[a/] | Measured Depth to Water (ft below MP)[b/] | Depth to Water (ft bgs)[c/] | Measuring Point Elevation (ft NGVD) | Stickup (ft)[d/] | Screened Interval (ft bgs) | Total Depth (ft bgs) | Base of Weathering (ft bgs) | Formation[e/] |
|---|---|---|---|---|---|---|---|---|---|---|
| MW39-WD | 7/6/2021 | 5,773.33 | 31.92 | 29.17 | 5,805.25 | 2.75 | 24.1-44.1 | 48.7 | 44.1 | WD |
| MW39-WD | 10/1/2021 | 5,773.31 | 31.94 | 29.19 | 5,805.25 | 2.75 | 24.1-44.1 | 48.7 | 44.1 | WD |
| MW40-WD | 7/6/2021 | 5,777.60 | 43.06 | 40.4 | 5,820.66 | 2.66 | 31.7-61.7 | 65 | 61.8 | WD |
| MW40-WD | 10/1/2021 | 5,777.58 | 43.08 | 40.42 | 5,820.66 | 2.66 | 31.7-61.7 | 65 | 61.8 | WD |
| MW41-WD | 7/6/2021 | 5,787.73 | 45.19 | 42.77 | 5,832.92 | 2.42 | 25.3-55.3 | 61 | 55.3 | WD |
| MW41-WD | 10/1/2021 | 5,787.68 | 45.24 | 42.82 | 5,832.92 | 2.42 | 25.3-55.3 | 61 | 55.3 | WD |
| MW42-UD | 7/6/2021 | 5,788.06 | 47.74 | 45.34 | 5,835.80 | 2.40 | 70-90 | 92.5 | 60 | UNWD |
| MW42-UD | 10/1/2021 | 5,786.84 | 48.96 | 46.56 | 5,835.80 | 2.40 | 70-90 | 92.5 | 60 | UNWD |
| MW42-WD | 7/6/2021 | 5,789.27 | 46.94 | 44.33 | 5,836.21 | 2.61 | 23.3-48.3 | 52 | 48.3 | WD |
| MW42-WD | 10/1/2021 | 5,789.66 | 46.55 | 43.94 | 5,836.21 | 2.61 | 23.3-48.3 | 52 | 48.3 | WD |
| MW43-WD | 7/6/2021 | 5,791.22 | 51.55 | 49.08 | 5,842.77 | 2.47 | 19.5-54.5 | 60.5 | 55.1 | WD |
| MW43-WD | 10/1/2021 | 5,791.26 | 51.51 | 49.04 | 5,842.77 | 2.47 | 19.5-54.5 | 60.5 | 55.1 | WD |
| MW44-WD | 7/21/2021 | 5,788.89 | 60.36 | 57.81 | 5,849.25 | 2.55 | 26.4-66.4 | 69.7 | 66.4 | WD |
| MW44-WD | 10/1/2021 | 5,788.77 | 60.48 | 57.93 | 5,849.25 | 2.55 | 26.4-66.4 | 69.7 | 66.4 | WD |
| MW45-WD | 7/8/2021 | 5,806.42 | 49.12 | 46.98 | 5,855.54 | 2.14 | 35-65 | 70 | 65 | WD |
| MW45-WD | 10/1/2021 | 5,806.76 | 48.78 | 46.64 | 5,855.54 | 2.14 | 35-65 | 70 | 65 | WD |
| MW46-WD | 7/8/2021 | 5,825.88 | 22.57 | 19.92 | 5,848.45 | 2.65 | 15-65 | 70 | 65 | WD |
| MW46-WD | 10/1/2021 | 5,825.12 | 23.33 | 20.68 | 5,848.45 | 2.65 | 15-65 | 70 | 65 | WD |
| MW47-WD | 7/8/2021 | 5,827.13 | 14.88 | 12.37 | 5,842.01 | 2.51 | 10-45 | 45.3 | NE, >45.3 | WD |
| MW47-WD | 10/1/2021 | 5,825.82 | 16.19 | 13.68 | 5,842.01 | 2.51 | 10-45 | 45.3 | NE, >45.3 | WD |
| MW48-WD | 7/8/2021 | 5,826.04 | 11.82 | 9.56 | 5,837.86 | 2.26 | 9.7-49.7 | 55 | 49.7 | WD |
| MW48-WD | 10/1/2021 | 5,824.23 | 13.63 | 11.37 | 5,837.86 | 2.26 | 9.7-49.7 | 55 | 49.7 | WD |
| MW49-WD | 7/8/2021 | 5,808.22 | 16.72 | 14.48 | 5,824.94 | 2.24 | 19-54 | 58.5 | 54 | WD |
| MW49-WD | 10/1/2021 | 5,807.49 | 17.45 | 15.21 | 5,824.94 | 2.24 | 19-54 | 58.5 | 54 | WD |
| MW50-WD | 7/9/2021 | 5,790.79 | 20.16 | 17.61 | 5,810.95 | 2.55 | 15.2-45.2 | 50 | 45.2 | WD |
| MW50-WD | 10/5/2021 | 5,790.72 | 20.23 | 17.68 | 5,810.95 | 2.55 | 15.2-45.2 | 50 | 45.2 | WD |
| MW51-10S | 7/9/2021 | 5,753.00 | 43.32 | 40.9 | 5,796.32 | 2.42 | 51-61 | 64 | 44 | UNWD |
| MW51-10S | 10/5/2021 | 5,752.91 | 43.41 | 40.99 | 5,796.32 | 2.42 | 51-61 | 64 | 44 | UNWD |
| MW51I-WD | 7/9/2021 | 5,749.68 | 48.35 | 45.32 | 5,798.03 | 3.03 | 34-44 | 49 | 44 | WD |
| MW51I-WD | 10/5/2021 | 5,751.63 | 46.4 | 43.37 | 5,798.03 | 3.03 | 34-44 | 49 | 44 | WD |
| MW51I-WD-10S | 7/9/2021 | 5,756.49 | 41.42 | 38.71 | 5,797.91 | 2.71 | 40.5-41.5 | 44 | NE, >44 | WD |
| MW51I-WD-10S | 10/5/2021 | 5,756.44 | 41.47 | 38.76 | 5,797.91 | 2.71 | 40.5-41.5 | 44 | NE, >44 | WD |
| MW51I-WD-15N | 7/9/2021 | 5,747.34 | 49.27 | 47.23 | 5,796.61 | 2.04 | 29-44 | 49 | 44 | WD |
| MW51I-WD-15N | 10/5/2021 | 5,747.20 | 49.41 | 47.37 | 5,796.61 | 2.04 | 29-44 | 49 | 44 | WD |
| MW51I-WD-35S | 7/9/2021 | 5,746.30 | 51.64 | 49.28 | 5,797.94 | 2.36 | 26-46 | 51 | 46 | WD |
| MW51I-WD-35S | 10/5/2021 | 5,746.09 | 51.85 | 49.49 | 5,797.94 | 2.36 | 26-46 | 51 | 46 | WD |
| MW51I-WD-65N | 7/9/2021 | 5,752.04 | 43.18 | 41.46 | 5,795.22 | 1.72 | 28.5-43.5 | 50.5 | 44 | WD |
| MW51I-WD-65N | 10/5/2021 | 5,752.02 | 43.2 | 41.48 | 5,795.22 | 1.72 | 28.5-43.5 | 50.5 | 44 | WD |
| MW51I-WD-80S | 7/9/2021 | 5,756.73 | 41.71 | 39.77 | 5,798.44 | 1.94 | 39-54 | 59 | 52 | WD |
| MW51I-WD-80S | 10/5/2021 | 5,756.66 | 41.78 | 39.84 | 5,798.44 | 1.94 | 39-54 | 59 | 52 | WD |
| MW51-WD | 7/9/2021 | 5,753.69 | 42.71 | 40.41 | 5,796.40 | 2.30 | 16.2-41.2 | 45.1 | 41.2 | WD |
| MW51-WD | 10/5/2021 | 5,753.64 | 42.76 | 40.46 | 5,796.40 | 2.30 | 16.2-41.2 | 45.1 | 41.2 | WD |
| MW51X-WD-100S | 7/9/2021 | 5,751.73 | 46.9 | 44.17 | 5,798.63 | 2.73 | 46.5-48.5 | 51 | 52 | WD |
| MW51X-WD-100S | 10/5/2021 | 5,751.72 | 46.91 | 44.18 | 5,798.63 | 2.73 | 46.5-48.5 | 51 | 52 | WD |
| MW51X-WD-35S | 7/9/2021 | 5,751.98 | 44.07 | 42.06 | 5,796.05 | 2.01 | 28-43 | 45.5 | 43.5 | WD |
| MW51X-WD-35S | 10/5/2021 | 5,751.93 | 44.12 | 42.11 | 5,796.05 | 2.01 | 28-43 | 45.5 | 43.5 | WD |
| MW51X-WD-65N | 7/9/2021 | 5,751.98 | 43.27 | 39.93 | 5,795.25 | 3.34 | 21-41 | 44.5 | 41 | WD |
| MW51X-WD-65N | 10/5/2021 | 5,751.96 | 43.29 | 39.95 | 5,795.25 | 3.34 | 21-41 | 44.5 | 41 | WD |
| MW51X-WD-90S | 7/9/2021 | 5,751.80 | 46.03 | 44.1 | 5,797.83 | 1.93 | 38-53 | 56.5 | 52 | WD |
| MW51X-WD-90S | 10/5/2021 | 5,751.80 | 46.03 | 44.1 | 5,797.83 | 1.93 | 38-53 | 56.5 | 52 | WD |
| MW52-DEN | 7/9/2021 | 5,728.83 | 54.7 | 52.59 | 5,783.53 | 2.11 | 155-175 | 180 | 45 | UPPER DENVER |
| MW52-DEN | 10/5/2021 | 5,728.47 | 55.06 | 52.95 | 5,783.53 | 2.11 | 155-175 | 180 | 45 | UPPER DENVER |
| MW52-LIG | 7/9/2021 | 5,681.29 | 102.25 | 99.41 | 5,783.54 | 2.84 | 285-300 | 307 | 45 | LIGNITE |
| MW52-LIG | 10/5/2021 | 5,680.93 | 102.61 | 99.77 | 5,783.54 | 2.84 | 285-300 | 307 | 45 | LIGNITE |
| MW52-UD | 7/9/2021 | 5,748.40 | 35.74 | 32.9 | 5,784.14 | 2.84 | 65-85 | 88 | 45 | UNWD |
| MW52-UD | 10/5/2021 | 5,748.02 | 36.12 | 33.28 | 5,784.14 | 2.84 | 65-85 | 88 | 45 | UNWD |
| MW52-WD | 7/9/2021 | 5,751.43 | 33.44 | 30.57 | 5,784.87 | 2.87 | 25-45 | 50 | 45 | WD |
| MW52-WD | 10/5/2021 | 5,751.52 | 33.35 | 30.48 | 5,784.87 | 2.87 | 25-45 | 50 | 45 | WD |
| MW53-WD | 7/9/2021 | 5,748.32 | 36.39 | 34.88 | 5,784.71 | 1.51 | 17.5-52.5 | 55.5 | 52.5 | WD |
| MW53-WD | 10/5/2021 | 5,748.11 | 36.6 | 35.09 | 5,784.71 | 1.51 | 17.5-52.5 | 55.5 | 52.5 | WD |
| MW54-UDR | 7/9/2021 | 5,719.96 | 25.91 | 23.44 | 5,745.87 | 2.47 | 54-64 | 67 | 37 | UNWD |
| MW54-UDR | 10/5/2021 | 5,719.86 | 26.01 | 23.54 | 5,745.87 | 2.47 | 54-64 | 67 | 37 | UNWD |
| MW54-WD | 7/9/2021 | 5,720.24 | 25.03 | 22.41 | 5,745.27 | 2.62 | 16.8-36.8 | 40 | 36.8 | WD |
| MW54-WD | 10/5/2021 | 5,719.62 | 25.65 | 23.03 | 5,745.27 | 2.62 | 16.8-36.8 | 40 | 36.8 | WD |
| MW55-WD | 7/13/2021 | 5,754.14 | 37.13 | 34.26 | 5,791.27 | 2.87 | 28.4-48.4 | 54 | 48.4 | WD |
| MW55-WD | 10/8/2021 | 5,753.95 | 37.32 | 34.45 | 5,791.27 | 2.87 | 28.4-48.4 | 54 | 48.4 | WD |

**TABLE 4.2**
**WATER LEVEL ELEVATIONS**
**JULY THROUGH DECEMBER 2021 OPERATIONS AND MAINTENANCE STATUS REPORT**
**LOWRY LANDFILL SUPERFUND SITE**

| Well ID | Date of Measurement | Water-Surface Elevation (ft NGVD)[a/] | Measured Depth to Water (ft below MP)[b/] | Depth to Water (ft bgs)[c/] | Measuring Point Elevation (ft NGVD) | Stickup (ft)[d/] | Screened Interval (ft bgs) | Total Depth (ft bgs) | Base of Weathering (ft bgs) | Formation[e/] |
|---|---|---|---|---|---|---|---|---|---|---|
| MW56-WD | 7/14/2021 | 5,750.27 | 47.97 | 44.93 | 5,798.24 | 3.04 | 25-50 | 54 | 50 | WD |
| MW56-WD | 10/7/2021 | 5,750.32 | 47.92 | 44.88 | 5,798.24 | 3.04 | 25-50 | 54 | 50 | WD |
| MW57-WD | 7/14/2021 | 5,740.19 | 36.96 | 34.81 | 5,777.15 | 2.15 | 24-39 | 44 | 39 | WD |
| MW57-WD | 10/7/2021 | 5,740.06 | 37.09 | 34.94 | 5,777.15 | 2.15 | 24-39 | 44 | 39 | WD |
| MW58-WD | 7/13/2021 | 5,756.18 | 53.83 | 50.72 | 5,810.01 | 3.11 | 26-56 | 59 | 56 | WD |
| MW58-WD | 10/8/2021 | 5,756.61 | 53.4 | 50.29 | 5,810.01 | 3.11 | 26-56 | 59 | 56 | WD |
| MW59-WD | 7/13/2021 | 5,755.93 | 47.17 | 45.58 | 5,803.10 | 1.59 | 39.5-57 | 60 | 57 | WD |
| MW59-WD | 10/8/2021 | 5,756.00 | 47.1 | 45.51 | 5,803.10 | 1.59 | 39.5-57 | 60 | 57 | WD |
| MW60-WD | 7/9/2021 | 5,751.66 | 35.23 | 32.58 | 5,786.89 | 2.65 | 19-44 | 49 | 44 | WD |
| MW60-WD | 10/5/2021 | 5,751.68 | 35.21 | 32.56 | 5,786.89 | 2.65 | 19-44 | 49 | 44 | WD |
| MW61-WD | 7/9/2021 | 5,751.67 | 34.37 | 32.23 | 5,786.04 | 2.14 | 27-39 | 44 | 39 | WD |
| MW61-WD | 10/5/2021 | 5,751.68 | 34.36 | 32.22 | 5,786.04 | 2.14 | 27-39 | 44 | 39 | WD |
| MW62-DENR | 7/7/2021 | 5,698.83 | 29.52 | 27.52 | 5,728.35 | 2.00 | 124-144 | 149 | 35 | UPPER DENVER |
| MW62-DENR | 10/4/2021 | 5,698.43 | 29.92 | 27.92 | 5,728.35 | 2.00 | 124-144 | 149 | 35 | UPPER DENVER |
| MW62-LIG | 7/7/2021 | 5,674.58 | 52.72 | 51.02 | 5,727.30 | 1.70 | 208-223 | 227 | 30.5 | LIGNITE |
| MW62-LIG | 10/4/2021 | 5,674.28 | 53.02 | 51.32 | 5,727.30 | 1.70 | 208-223 | 227 | 30.5 | LIGNITE |
| MW62-UD | 7/7/2021 | 5,690.74 | 36.92 | 34.86 | 5,727.66 | 2.06 | 53.5-68.5 | 71 | 32 | UNWD |
| MW62-UD | 10/4/2021 | 5,690.44 | 37.22 | 35.16 | 5,727.66 | 2.06 | 53.5-68.5 | 71 | 32 | UNWD |
| MW62-WDR | 7/7/2021 | 5,697.12 | 31.13 | 28.81 | 5,728.25 | 2.32 | 20.4-30.4 | 33.5 | 30 | WD |
| MW62-WDR | 10/4/2021 | 5,697.08 | 31.17 | 28.85 | 5,728.25 | 2.32 | 20.4-30.4 | 33.5 | 30 | WD |
| MW63-WD | 7/6/2021 | 5,772.87 | 35.62 | 33.73 | 5,808.49 | 1.89 | 33-53 | 57.9 | 53 | WD |
| MW63-WD | 10/1/2021 | 5,772.96 | 35.53 | 33.64 | 5,808.49 | 1.89 | 33-53 | 57.9 | 53 | WD |
| MW64-WD | 7/6/2021 | 5,775.20 | 30.83 | 28.1 | 5,806.03 | 2.73 | 31-46 | 49 | 45.4 | WD |
| MW64-WD | 10/1/2021 | 5,775.32 | 30.71 | 27.98 | 5,806.03 | 2.73 | 31-46 | 49 | 45.4 | WD |
| MW65-WD | 7/6/2021 | 5,772.10 | 27.49 | 25.1 | 5,799.59 | 2.39 | 26-38 | 42 | 37.7 | WD |
| MW65-WD | 10/1/2021 | 5,772.03 | 27.56 | 25.17 | 5,799.59 | 2.39 | 26-38 | 42 | 37.7 | WD |
| MW66-WD | 7/9/2021 | 5,751.66 | 39.78 | 37.14 | 5,791.44 | 2.64 | 31.8-41.8 | 49 | 41 | WD |
| MW66-WD | 10/5/2021 | 5,751.66 | 39.78 | 37.14 | 5,791.44 | 2.64 | 31.8-41.8 | 49 | 41 | WD |
| MW67-WD | 7/6/2021 | 5,772.71 | 28.9 | 26.39 | 5,801.61 | 2.51 | 31-43 | 49 | 43 | WD |
| MW67-WD | 10/1/2021 | 5,772.77 | 28.84 | 26.33 | 5,801.61 | 2.51 | 31-43 | 49 | 43 | WD |
| MW68-WD | 7/6/2021 | 5,773.74 | 32.67 | 30.06 | 5,806.41 | 2.61 | 29-44 | 52.8 | 44 | WD |
| MW68-WD | 10/1/2021 | 5,773.69 | 32.72 | 30.11 | 5,806.41 | 2.61 | 29-44 | 52.8 | 44 | WD |
| MW70-WD | 7/9/2021 | 5,751.68 | 39.47 | 37.32 | 5,791.15 | 2.15 | 34.5-49.5 | 52.3 | 49 | WD |
| MW70-WD | 10/5/2021 | 5,751.65 | 39.5 | 37.35 | 5,791.15 | 2.15 | 34.5-49.5 | 52.3 | 49 | WD |
| MW71-DENR | 7/9/2021 | 5,710.05 | 22.86 | 20.4 | 5,732.91 | 2.46 | 102.1 - | 130 | 41.5 | UPPER DENVER |
| MW71-DENR | 10/5/2021 | 5,709.81 | 23.1 | 20.64 | 5,732.91 | 2.46 | 102.1 - | 130 | 41.5 | UPPER DENVER |
| MW71-LIG | 7/9/2021 | 5,680.24 | 52.45 | 49.76 | 5,732.69 | 2.69 | 208-223 | 228 | 33 | LIGNITE |
| MW71-LIG | 10/5/2021 | 5,680.09 | 52.6 | 49.91 | 5,732.69 | 2.69 | 208-223 | 228 | 33 | LIGNITE |
| MW71-UD | 7/9/2021 | 5,710.25 | 22.89 | 20.45 | 5,733.14 | 2.44 | 67.5-82.5 | 84 | 37 | UNWD |
| MW71-UD | 10/5/2021 | 5,709.84 | 23.3 | 20.86 | 5,733.14 | 2.44 | 67.5-82.5 | 84 | 37 | UNWD |
| MW71-WD | 7/9/2021 | 5,709.80 | 23.26 | 20.5 | 5,733.06 | 2.76 | 20.5-35.5 | 39.2 | 35.5 | WD |
| MW71-WD | 10/5/2021 | 5,709.21 | 23.85 | 21.09 | 5,733.06 | 2.76 | 20.5-35.5 | 39.2 | 35.5 | WD |
| MW72-DEN | 7/9/2021 | 5,716.32 | 40.41 | 37.83 | 5,756.73 | 2.58 | 109.4 - 124 | 128 | 42 | UPPER DENVER |
| MW72-DEN | 10/5/2021 | 5,716.04 | 40.69 | 38.11 | 5,756.73 | 2.58 | 109.4 - 124 | 128 | 42 | UPPER DENVER |
| MW72-LIGR | 7/9/2021 | 5,682.00 | 77.07 | 74.67 | 5,759.07 | 2.40 | 253-263 | 268 | 42 | LIGNITE |
| MW72-LIGR | 10/5/2021 | 5,681.03 | 78.04 | 75.64 | 5,759.07 | 2.40 | 253-263 | 268 | 42 | LIGNITE |
| MW72-UD | 7/9/2021 | 5,721.51 | 35.15 | 32.69 | 5,756.66 | 2.46 | 66-81 | 84 | 43 | UNWD |
| MW72-UD | 10/5/2021 | 5,721.06 | 35.6 | 33.14 | 5,756.66 | 2.46 | 66-81 | 84 | 43 | UNWD |
| MW72-WD | 7/9/2021 | 5,725.31 | 31.97 | 28.99 | 5,757.28 | 2.98 | 32.5-42.5 | 45 | 42.5 | WD |
| MW72-WD | 10/5/2021 | 5,724.66 | 32.62 | 29.64 | 5,757.28 | 2.98 | 32.5-42.5 | 45 | 42.5 | WD |
| MW73-UD | 7/8/2021 | 5,711.16 | 25.04 | 22.54 | 5,736.20 | 2.50 | 57.7-77.7 | 80 | 35 | UNWD |
| MW73-UD | 10/4/2021 | 5,710.97 | 25.23 | 22.73 | 5,736.20 | 2.50 | 57.7-77.7 | 80 | 35 | UNWD |
| MW73-WD | 7/8/2021 | 5,715.81 | 21.01 | 18.45 | 5,736.82 | 2.56 | 15.7-35.7 | 38 | 34.5 | WD |
| MW73-WD | 10/4/2021 | 5,715.26 | 21.56 | 19 | 5,736.82 | 2.56 | 15.7-35.7 | 38 | 34.5 | WD |
| MW74-UD | 7/13/2021 | 5,713.25 | 36.11 | 33.75 | 5,749.36 | 2.36 | 72.7-92.7 | 95 | 54 | UNWD |
| MW74-UD | 10/8/2021 | 5,713.15 | 36.21 | 33.85 | 5,749.36 | 2.36 | 72.7-92.7 | 95 | 54 | UNWD |
| MW74-WD | 7/13/2021 | 5,717.20 | 32.18 | 29.8 | 5,749.38 | 2.38 | 38-58 | 62 | 54 | WD |
| MW74-WD | 10/8/2021 | 5,716.73 | 32.65 | 30.27 | 5,749.38 | 2.38 | 38-58 | 62 | 54 | WD |
| MW75-UD | 7/12/2021 | 5,717.04 | 39.79 | 37.17 | 5,756.83 | 2.62 | 71.5-91.5 | 94 | 51 | UNWD |
| MW75-UD | 10/8/2021 | 5,716.98 | 39.85 | 37.23 | 5,756.83 | 2.62 | 71.5-91.5 | 94 | 51 | UNWD |
| MW75-WD | 7/12/2021 | 5,735.03 | 22.14 | 19.27 | 5,757.17 | 2.87 | 25-50 | 52.5 | 50 | WD |
| MW75-WD | 10/8/2021 | 5,732.29 | 24.88 | 22.01 | 5,757.17 | 2.87 | 25-50 | 52.5 | 50 | WD |
| MW76-UD | 7/12/2021 | 5,717.53 | 45.01 | 42.67 | 5,762.54 | -0.16 | 60-80 | 83 | 34.5 | UNWD |
| MW76-UD | 10/8/2021 | 5,717.48 | 42.56 | 42.72 | 5,760.04 | -0.16 | 60-80 | 83 | 34.5 | UNWD |
| MW76-WD | 7/12/2021 | 5,743.92 | 18.32 | 15.78 | 5,762.24 | -0.06 | 20-35 | 38 | 34.5 | WD |
| MW76-WD | 10/8/2021 | 5,741.02 | 18.62 | 18.68 | 5,759.64 | -0.06 | 20-35 | 38 | 34.5 | WD |

**TABLE 4.2**
**WATER LEVEL ELEVATIONS**
**JULY THROUGH DECEMBER 2021 OPERATIONS AND MAINTENANCE STATUS REPORT**
**LOWRY LANDFILL SUPERFUND SITE**

| Well ID | Date of Measurement | Water-Surface Elevation (ft NGVD)[a/] | Measured Depth to Water (ft below MP)[b/] | Depth to Water (ft bgs)[c/] | Measuring Point Elevation (ft NGVD) | Stickup (ft)[d/] | Screened Interval (ft bgs) | Total Depth (ft bgs) | Base of Weathering (ft bgs) | Formation[e/] |
|---|---|---|---|---|---|---|---|---|---|---|
| MW77-EW-1 | 7/2/2021 | 5,688.41 | 36.82 | 34.19 | 5,725.23 | 2.63 | 25-35 | 39 | 37.6 | WD |
| MW77-EW-1 | 10/4/2021 | 5,688.38 | 36.85 | 34.22 | 5,725.23 | 2.63 | 25-35 | 39 | 37.6 | WD |
| MW77-EW-2 | 7/2/2021 | 5,696.19 | 24.79 | 22.31 | 5,720.98 | 2.48 | 22-32 | 39 | 34.9 | WD |
| MW77-EW-2 | 10/4/2021 | 5,695.87 | 25.11 | 22.63 | 5,720.98 | 2.48 | 22-32 | 39 | 34.9 | WD |
| MW77-UD | 7/2/2021 | 5,696.00 | 31.56 | 29.33 | 5,727.56 | 2.22 | 57-72 | 75 | 35 | UNWD |
| MW77-UD | 10/4/2021 | 5,695.35 | 32.21 | 29.98 | 5,727.56 | 2.22 | 57-72 | 75 | 35 | UNWD |
| MW77-WD | 7/2/2021 | 5,701.25 | 27 | 24.15 | 5,728.25 | 2.85 | 19.7-34.7 | 37 | 34.5 | WD |
| MW77-WD | 10/4/2021 | 5,700.00 | 28.25 | 25.4 | 5,728.25 | 2.85 | 19.7-34.7 | 37 | 34.5 | WD |
| MW78-UD | 7/9/2021 | 5,706.00 | 25.54 | 23.2 | 5,731.54 | 2.34 | 57-77 | 79.5 | 42.5 | UNWD |
| MW78-UD | 10/5/2021 | 5,705.34 | 26.2 | 23.86 | 5,731.54 | 2.34 | 57-77 | 79.5 | 42.5 | UNWD |
| MW78-WD | 7/9/2021 | 5,705.17 | 26.41 | 23.93 | 5,731.58 | 2.48 | 24-44 | 47.5 | 42.5 | WD |
| MW78-WD | 10/5/2021 | 5,704.70 | 26.88 | 24.4 | 5,731.58 | 2.48 | 24-44 | 47.5 | 42.5 | WD |
| MW79-UD | 7/9/2021 | 5,712.71 | 14.59 | 12.29 | 5,727.30 | 2.30 | 52-72 | 75 | 35 | UNWD |
| MW79-UD | 10/5/2021 | 5,712.80 | 14.5 | 12.2 | 5,727.30 | 2.30 | 52-72 | 75 | 35 | UNWD |
| MW79-WD | 7/9/2021 | 5,713.20 | 14.83 | 12 | 5,728.03 | 2.83 | 20-35 | 38 | 35 | WD |
| MW79-WD | 10/5/2021 | 5,712.74 | 15.29 | 12.46 | 5,728.03 | 2.83 | 20-35 | 38 | 35 | WD |
| MW90-UD | 7/9/2021 | 5,731.96 | 27.99 | 24.74 | 5,759.95 | 3.25 | 44-64 | 66.5 | 41 | UNWD |
| MW90-UD | 10/5/2021 | 5,731.23 | 28.72 | 25.47 | 5,759.95 | 3.25 | 44-64 | 66.5 | 41 | UNWD |
| MW90-WD | 7/9/2021 | 5,731.93 | 28.12 | 25.17 | 5,760.05 | 2.95 | 26-41 | 43.5 | 41 | WD |
| MW90-WD | 10/5/2021 | 5,731.21 | 28.84 | 25.89 | 5,760.05 | 2.95 | 26-41 | 43.5 | 41 | WD |
| MW91-UD | 7/9/2021 | 5,716.32 | 19.52 | 17.28 | 5,735.84 | 2.24 | 60-80 | 82.5 | 31.5 | UNWD |
| MW91-UD | 10/5/2021 | 5,716.03 | 19.81 | 17.57 | 5,735.84 | 2.24 | 60-80 | 82.5 | 31.5 | UNWD |
| MW91-WD | 7/9/2021 | 5,717.66 | 17.93 | 15.94 | 5,735.59 | 1.99 | 21.5-31.5 | 34 | 31.5 | WD |
| MW91-WD | 10/5/2021 | 5,717.18 | 18.41 | 16.42 | 5,735.59 | 1.99 | 21.5-31.5 | 34 | 31.5 | WD |
| MW92-WD | 7/9/2021 | 5,724.35 | 23.66 | 21.05 | 5,748.01 | 2.61 | 19.5-39.5 | 42 | 39.5 | WD |
| MW92-WD | 10/5/2021 | 5,723.66 | 24.35 | 21.74 | 5,748.01 | 2.61 | 19.5-39.5 | 42 | 39.5 | WD |
| MW93-UD | 7/9/2021 | 5,732.05 | 25.32 | 22.75 | 5,757.37 | 2.57 | 42-62 | 75 | 35 | UNWD |
| MW93-UD | 10/5/2021 | 5,731.29 | 26.08 | 23.51 | 5,757.37 | 2.57 | 42-62 | 75 | 35 | UNWD |
| MW93-WD | 7/9/2021 | 5,729.79 | 27.69 | 25.21 | 5,757.48 | 2.48 | 15-35 | 37.5 | 35 | WD |
| MW93-WD | 10/5/2021 | 5,729.37 | 28.11 | 25.63 | 5,757.48 | 2.48 | 15-35 | 37.5 | 35 | WD |
| MW97-WD | 7/2/2021 | 5,698.98 | 28.68 | 25.82 | 5,727.66 | 2.86 | 29-31 | 34 | 30.5 | WD |
| MW97-WD | 10/4/2021 | 5,698.30 | 29.36 | 26.5 | 5,727.66 | 2.86 | 29-31 | 34 | 30.5 | WD |
| MW98-WD | 7/2/2021 | 5,690.98 | 34.75 | 32.42 | 5,725.73 | 2.33 | 25.5-33 | 36 | 33 | WD |
| MW98-WD | 10/4/2021 | 5,691.01 | 34.72 | 32.39 | 5,725.73 | 2.33 | 25.5-33 | 36 | 33 | WD |
| MW99-WD | 7/2/2021 | 5,700.10 | 25.4 | 22.9 | 5,725.50 | 2.50 | 25.5-33 | 35.5 | 31.5 | WD |
| MW99-WD | 10/4/2021 | 5,699.69 | 25.81 | 23.31 | 5,725.50 | 2.50 | 25.5-33 | 35.5 | 31.5 | WD |
| MW-EW-1 | 7/7/2021 | 5,697.61 | 15.91 | 12.99 | 5,713.52 | 2.92 | 7.8-17.8 | 17.8 | NE, >17.8 | ALLUVIUM |
| MW-EW-1 | 10/4/2021 | 5,697.14 | 16.38 | 13.46 | 5,713.52 | 2.92 | 7.8-17.8 | 17.8 | NE, >17.8 | ALLUVIUM |
| MW-EW-1LC | 7/7/2021 | 5,695.10 | 17.87 | 15.93 | 5,712.97 | 1.94 | 28-38 | 38.1 | 23 | UNWD |
| MW-EW-1LC | 10/4/2021 | 5,694.68 | 18.29 | 16.35 | 5,712.97 | 1.94 | 28-38 | 38.1 | 23 | UNWD |
| MW-EW-1LCRA | 7/7/2021 | 5,692.97 | 19.89 | 17.53 | 5,712.86 | 2.36 | 46.5-61.5 | 64 | 23 | UNWD |
| MW-EW-1LCRA | 10/4/2021 | 5,692.51 | 20.35 | 17.99 | 5,712.86 | 2.36 | 46.5-61.5 | 64 | 23 | UNWD |
| MW-EW-2 | 7/7/2021 | 5,697.64 | 16 | 12.98 | 5,713.64 | 3.02 | 8-18 | 18 | NE, >18 | ALLUVIUM |
| MW-EW-2 | 10/4/2021 | 5,697.00 | 16.64 | 13.62 | 5,713.64 | 3.02 | 8-18 | 18 | NE, >18 | ALLUVIUM |
| MW-EW-2LC | 7/7/2021 | 5,695.62 | 18.79 | 15.73 | 5,714.41 | 3.06 | 28-38 | 38 | 25 | UNWD |
| MW-EW-2LC | 10/4/2021 | 5,695.03 | 19.38 | 16.32 | 5,714.41 | 3.06 | 28-38 | 38 | 25 | UNWD |
| MW-EW-2LCR | 7/7/2021 | 5,695.32 | 20.62 | 17.68 | 5,715.94 | 2.94 | 46.5-56.5 | 59 | 24.5 | UNWD |
| MW-EW-2LCR | 10/4/2021 | 5,694.88 | 21.06 | 18.12 | 5,715.94 | 2.94 | 46.5-56.5 | 59 | 24.5 | UNWD |
| NBBW-IW-1 | 7/8/2021 | Dry | Dry | Dry | 5,709.43 | 2.61 | 10-20 | 27.5 | 22 | WD |
| NBBW-IW-1 | 10/4/2021 | Dry | Dry | Dry | 5,709.43 | 2.61 | 10-20 | 27.5 | 22 | WD |
| NBBW-IW-2 | 7/8/2021 | 5,686.48 | 22.62 | 19.46 | 5,709.10 | 3.16 | 12-22 | 28 | 23 | WD |
| NBBW-IW-2 | 10/4/2021 | 5,686.17 | 22.93 | 19.77 | 5,709.10 | 3.16 | 12-22 | 28 | 23 | WD |
| NBBW-IW-3 | 7/8/2021 | 5,668.38 | 43.36 | 41.09 | 5,711.74 | 2.27 | 11-41 | 47 | 42 | WD |
| NBBW-IW-3 | 10/4/2021 | 5,666.88 | 44.86 | 42.59 | 5,711.74 | 2.27 | 11-41 | 47 | 42 | WD |
| NEPZ-097 | 7/1/2021 | 5,553.88 | 24.61 | 24.81 | 5,578.49 | -0.20 | 23-43 | 47.3 | 43.5 | UPPER DENVER |
| NEPZ-097 | 10/6/2021 | 5,553.24 | 25.25 | 25.45 | 5,578.49 | -0.20 | 23-43 | 47.3 | 43.5 | UPPER DENVER |
| NEPZ-098 | 7/1/2021 | 5,554.88 | 21.75 | 21.74 | 5,576.63 | 0.01 | 16-46 | 49.5 | 45.5 | UPPER DENVER |
| NEPZ-098 | 10/6/2021 | 5,554.12 | 22.51 | 22.5 | 5,576.63 | 0.01 | 16-46 | 49.5 | 45.5 | UPPER DENVER |
| NEPZ-099 | 7/1/2021 | 5,556.66 | 18.8 | 18.76 | 5,575.46 | 0.04 | 12.5-42.5 | 48.5 | 43.5 | UPPER DENVER |
| NEPZ-099 | 10/6/2021 | 5,555.69 | 19.77 | 19.73 | 5,575.46 | 0.04 | 12.5-42.5 | 48.5 | 43.5 | UPPER DENVER |
| NEPZ-101 | 7/1/2021 | 5,560.75 | 11.65 | 12.33 | 5,572.40 | -0.68 | 19-44 | 49 | 43 | UPPER DENVER |
| NEPZ-101 | 10/6/2021 | 5,559.67 | 12.73 | 13.41 | 5,572.40 | -0.68 | 19-44 | 49 | 43 | UPPER DENVER |
| NEPZ-102 | 7/1/2021 | 5,563.38 | 10.22 | 10.66 | 5,573.60 | -0.44 | 27-42 | 49 | 43 | UPPER DENVER |
| NEPZ-102 | 10/6/2021 | 5,562.32 | 11.28 | 11.72 | 5,573.60 | -0.44 | 27-42 | 49 | 43 | UPPER DENVER |
| NEPZ-103 | 7/1/2021 | 5,564.66 | 9.62 | 10.16 | 5,574.28 | -0.54 | 24-44 | 46 | 43 | UPPER DENVER |
| NEPZ-103 | 10/6/2021 | 5,563.67 | 10.61 | 11.15 | 5,574.28 | -0.54 | 24-44 | 46 | 43 | UPPER DENVER |

**TABLE 4.2**
**WATER LEVEL ELEVATIONS**
**JULY THROUGH DECEMBER 2021 OPERATIONS AND MAINTENANCE STATUS REPORT**
**LOWRY LANDFILL SUPERFUND SITE**

| Well ID | Date of Measurement | Water-Surface Elevation (ft NGVD)[a/] | Measured Depth to Water (ft below MP)[b/] | Depth to Water (ft bgs)[c/] | Measuring Point Elevation (ft NGVD) | Stickup (ft)[d/] | Screened Interval (ft bgs) | Total Depth (ft bgs) | Base of Weathering (ft bgs) | Formation[e/] |
|---|---|---|---|---|---|---|---|---|---|---|
| NEPZ-104 | 7/1/2021 | 5,564.95 | 9.68 | 9.9 | 5,574.63 | -0.22 | 14.8-29.8 | 33 | 29.5 | UPPER DENVER |
| NEPZ-104 | 10/6/2021 | 5,564.01 | 10.62 | 10.84 | 5,574.63 | -0.22 | 14.8-29.8 | 33 | 29.5 | UPPER DENVER |
| NEPZ-105 | 7/1/2021 | 5,566.35 | 9.83 | 10.06 | 5,576.18 | -0.23 | 11.8-26.8 | 29.8 | 27.2 | UPPER DENVER |
| NEPZ-105 | 10/6/2021 | 5,565.60 | 10.58 | 10.81 | 5,576.18 | -0.23 | 11.8-26.8 | 29.8 | 27.2 | UPPER DENVER |
| NTES SUMP | 7/15/2021 | 5,729.16 | 28.77 | 32.64 | 5,757.93 | -3.87 | -- | -- | -- | -- |
| NTES SUMP | 10/11/2021 | 5,729.14 | 28.79 | 32.66 | 5,757.93 | -3.87 | -- | -- | -- | -- |
| NTES-180W | 7/15/2021 | 5,729.80 | 35.83 | 33.71 | 5,765.63 | 2.12 | 15-35 | 40.5 | 36 | Fill (tire shreds) |
| NTES-180W | 10/11/2021 | 5,729.80 | 35.83 | 33.71 | 5,765.63 | 2.12 | 15-35 | 40.5 | 36 | Fill (tire shreds) |
| NTES-EW1 | 7/15/2021 | 5,749.38 | 28.9 | 27.32 | 5,778.28 | 1.58 | 41-51 | 53.5 | 50.5 | WD |
| NTES-EW1 | 10/11/2021 | 5,749.50 | 28.78 | 27.2 | 5,778.28 | 1.58 | 41-51 | 53.5 | 50.5 | WD |
| NTES-EW2 | 7/15/2021 | 5,745.62 | 32.44 | 29.86 | 5,778.06 | 2.58 | 30-50 | 55 | 52 | WD |
| NTES-EW2 | 10/11/2021 | 5,745.72 | 32.34 | 29.76 | 5,778.06 | 2.58 | 30-50 | 55 | 52 | WD |
| NTES-EW3 | 7/15/2021 | 5,748.20 | 31.8 | 28.5 | 5,780.00 | 3.30 | 27.5-37.5 | 40 | 37.5 | WD |
| NTES-EW3 | 10/11/2021 | 5,748.45 | 31.55 | 28.25 | 5,780.00 | 3.30 | 27.5-37.5 | 40 | 37.5 | WD |
| PM-10I | 7/8/2021 | 5,815.01 | 19.47 | 16.89 | 5,834.48 | 2.58 | 11.7-49.2 | 55.25 | 49.2 | WD |
| PM-10I | 10/1/2021 | 5,814.28 | 20.2 | 17.62 | 5,834.48 | 2.58 | 11.7-49.2 | 55.25 | 49.2 | WD |
| PM-10X | 7/8/2021 | 5,820.68 | 13.71 | 10.92 | 5,834.39 | 2.79 | 11.7-41.7 | 45.6 | 41.7 | WD |
| PM-10X | 10/1/2021 | 5,818.97 | 15.42 | 12.63 | 5,834.39 | 2.79 | 11.7-41.7 | 45.6 | 41.7 | WD |
| PM-11I | 7/9/2021 | 5,773.53 | 46.49 | 44.07 | 5,820.02 | 2.42 | 12.5-52.5 | 58.5 | 52.5 | WD |
| PM-11I | 10/5/2021 | 5,773.39 | 46.63 | 44.21 | 5,820.02 | 2.42 | 12.5-52.5 | 58.5 | 52.5 | WD |
| PM-11X | 7/9/2021 | 5,795.56 | 21.91 | 20.14 | 5,817.47 | 2.44 | 16-51 | 55 | 50.8 | WD |
| PM-11X | 10/5/2021 | 5,794.85 | 22.62 | 20.85 | 5,817.47 | 2.44 | 16-51 | 55 | 50.8 | WD |
| PM-12I | 7/9/2021 | 5,762.86 | 41.77 | 39.04 | 5,804.63 | 2.73 | 23.2-43.2 | 49.2 | 43.2 | WD |
| PM-12I | 10/5/2021 | 5,762.69 | 41.94 | 39.21 | 5,804.63 | 2.73 | 23.2-43.2 | 49.2 | 43.2 | WD |
| PM-12X | 7/9/2021 | 5,767.15 | 36.36 | 33.85 | 5,803.51 | 2.51 | 17-47 | 50 | 44 | WD |
| PM-12X | 10/5/2021 | 5,767.00 | 36.51 | 34 | 5,803.51 | 2.51 | 17-47 | 50 | 44 | WD |
| PM-13I | 7/9/2021 | Dry | Dry | Dry | 5,791.09 | 2.89 | 14.5-34.5 | 41 | 34.5 | WD |
| PM-13I | 10/5/2021 | Dry | Dry | Dry | 5,791.09 | 2.89 | 14.5-34.5 | 41 | 34.5 | WD |
| PM-13X | 7/9/2021 | Dry | Dry | Dry | 5,789.76 | 2.86 | 15-35 | 35 | 35 | WD |
| PM-13X | 10/5/2021 | 5,752.11 | 37.65 | 34.79 | 5,789.76 | 2.86 | 15-35 | 35 | 35 | WD |
| PM-14I | 7/9/2021 | 5,748.97 | 33.47 | 30.94 | 5,782.44 | 2.53 | 11.6-56.6 | 62 | 56.6 | WD |
| PM-14I | 10/5/2021 | 5,749.09 | 33.35 | 30.82 | 5,782.44 | 2.53 | 11.6-56.6 | 62 | 56.6 | WD |
| PM-14ID | 7/9/2021 | 5,750.55 | 33.19 | 31.1 | 5,783.74 | 2.09 | 44.5-54.5 | 64 | 54.5 | WD |
| PM-14ID | 10/5/2021 | 5,750.68 | 33.06 | 30.97 | 5,783.74 | 2.09 | 44.5-54.5 | 64 | 54.5 | WD |
| PM-14X | 7/9/2021 | 5,747.90 | 33.28 | 30.62 | 5,781.18 | 2.66 | 26.3-51.3 | 55 | 51.3 | WD |
| PM-14X | 10/5/2021 | 5,748.11 | 33.07 | 30.41 | 5,781.18 | 2.66 | 26.3-51.3 | 55 | 51.3 | WD |
| PM-15I | 7/9/2021 | 5,723.61 | 53.31 | 49.79 | 5,776.92 | 3.52 | 18.6-48.6 | 54 | 48.6 | WD |
| PM-15I | 10/5/2021 | 5,723.20 | 53.72 | 50.2 | 5,776.92 | 3.52 | 18.6-48.6 | 54 | 48.6 | WD |
| PM-15I-UD | 7/9/2021 | 5,735.62 | 39.77 | 37.08 | 5,775.39 | 2.69 | 57.5-77.5 | 80 | 53.10 | UNWD |
| PM-15I-UD | 10/5/2021 | 5,735.55 | 39.84 | 37.15 | 5,775.39 | 2.69 | 57.5-77.5 | 80 | 53.10 | UNWD |
| PM-15W | 7/9/2021 | 5,746.24 | 34.11 | 31.19 | 5,780.35 | 2.92 | 22-32 | 54 | 53 | WD |
| PM-15W | 10/5/2021 | 5,746.19 | 34.16 | 31.24 | 5,780.35 | 2.92 | 22-32 | 54 | 53 | WD |
| PM-15WR | 7/9/2021 | 5,739.65 | 40.2 | 37.96 | 5,779.85 | 2.24 | 25-55 | 58 | 55.7 | WD |
| PM-15WR | 10/5/2021 | 5,739.62 | 40.23 | 37.99 | 5,779.85 | 2.24 | 25-55 | 58 | 55.7 | WD |
| PM-15X | 7/9/2021 | 5,736.91 | 37.73 | 34.89 | 5,774.64 | 2.84 | 29.3-49.3 | 52.5 | 49.4 | WD |
| PM-15X | 10/5/2021 | 5,737.04 | 37.6 | 34.76 | 5,774.64 | 2.84 | 29.3-49.3 | 52.5 | 49.4 | WD |
| PM-1I | 7/14/2021 | 5,771.24 | 22.82 | 19.86 | 5,794.06 | 2.96 | 15.5-35.5 | 41 | 35.5 | WD |
| PM-1I | 10/7/2021 | 5,771.72 | 22.34 | 19.38 | 5,794.06 | 2.96 | 15.5-35.5 | 41 | 35.5 | WD |
| PM-1X | 7/14/2021 | 5,774.02 | 17.91 | 15.28 | 5,791.93 | 2.63 | 14.5-34.5 | 38 | 34.5 | WD |
| PM-1X | 10/7/2021 | 5,773.19 | 18.74 | 16.11 | 5,791.93 | 2.63 | 14.5-34.5 | 38 | 34.5 | WD |
| PM-2I | 7/6/2021 | 5,769.95 | 46.95 | 44.15 | 5,816.90 | 2.80 | 30.2-65.2 | 71 | 65.2 | WD |
| PM-2I | 10/1/2021 | 5,769.92 | 46.98 | 44.18 | 5,816.90 | 2.80 | 30.2-65.2 | 71 | 65.2 | WD |
| PM-2X | 7/6/2021 | 5,776.96 | 38.26 | 36.14 | 5,815.22 | 2.12 | 28-63 | 68 | 63 | WD |
| PM-2X | 10/1/2021 | 5,776.91 | 38.31 | 36.19 | 5,815.22 | 2.12 | 28-63 | 68 | 63 | WD |
| PM-3I | 7/6/2021 | 5,778.64 | 48.9 | 46.26 | 5,827.54 | 2.64 | 29-64 | 70 | 64 | WD |
| PM-3I | 10/1/2021 | 5,778.60 | 48.94 | 46.3 | 5,827.54 | 2.64 | 29-64 | 70 | 64 | WD |
| PM-3X | 7/6/2021 | 5,778.07 | 48.95 | 46.43 | 5,827.02 | 2.52 | 28-68 | 71 | 68 | WD |
| PM-3X | 10/1/2021 | 5,778.13 | 48.89 | 46.37 | 5,827.02 | 2.52 | 28-68 | 71 | 68 | WD |
| PM-4EW1 | 7/6/2021 | 5,794.62 | 43.32 | 40.68 | 5,837.94 | 2.64 | 32-45 | 48 | 45 | WD |
| PM-4EW1 | 10/1/2021 | 5,794.49 | 43.45 | 40.81 | 5,837.94 | 2.64 | 32-45 | 48 | 45 | WD |
| PM-4EW2 | 7/6/2021 | 5,794.57 | 43.35 | 40.73 | 5,837.92 | 2.62 | 45-52 | 54.5 | 52 | WD |
| PM-4EW2 | 10/1/2021 | 5,794.43 | 43.49 | 40.87 | 5,837.92 | 2.62 | 45-52 | 54.5 | 52 | WD |
| PM-4I | 7/6/2021 | 5,793.20 | 43.52 | 40.9 | 5,836.72 | 2.62 | 22-57 | 62.9 | 57 | WD |
| PM-4I | 10/1/2021 | 5,793.14 | 43.58 | 40.96 | 5,836.72 | 2.62 | 22-57 | 62.9 | 57 | WD |
| PM-4X | 7/6/2021 | 5,793.59 | 43.6 | 41.01 | 5,837.19 | 2.59 | 28.8-48.8 | 51.9 | 48.8 | WD |
| PM-4X | 10/1/2021 | 5,793.52 | 43.67 | 41.08 | 5,837.19 | 2.59 | 28.8-48.8 | 51.9 | 48.8 | WD |

**TABLE 4.2**
**WATER LEVEL ELEVATIONS**
**JULY THROUGH DECEMBER 2021 OPERATIONS AND MAINTENANCE STATUS REPORT**
**LOWRY LANDFILL SUPERFUND SITE**

| Well ID | Date of Measurement | Water-Surface Elevation (ft NGVD)[a/] | Measured Depth to Water (ft below MP)[b/] | Depth to Water (ft bgs)[c/] | Measuring Point Elevation (ft NGVD) | Stickup (ft)[d/] | Screened Interval (ft bgs) | Total Depth (ft bgs) | Base of Weathering (ft bgs) | Formation[e/] |
|---|---|---|---|---|---|---|---|---|---|---|
| PM-5I | 7/6/2021 | 5,799.84 | 37.57 | 35.46 | 5,837.41 | 2.11 | 22.4-52.4 | 59 | 51.4 | WD |
| PM-5I | 10/1/2021 | 5,799.04 | 38.37 | 36.26 | 5,837.41 | 2.11 | 22.4-52.4 | 59 | 51.4 | WD |
| PM-5X | 7/6/2021 | 5,799.81 | 38.24 | 35.69 | 5,838.05 | 2.55 | 22.9-47.9 | 51.9 | 47.9 | WD |
| PM-5X | 10/1/2021 | 5,799.93 | 38.12 | 35.57 | 5,838.05 | 2.55 | 22.9-47.9 | 51.9 | 47.9 | WD |
| PM-6I | 7/8/2021 | 5,797.80 | 54.38 | 51.8 | 5,852.18 | 2.58 | 43.9-63.9 | 69.9 | 63.9 | WD |
| PM-6I | 10/1/2021 | 5,797.76 | 54.42 | 51.84 | 5,852.18 | 2.58 | 43.9-63.9 | 69.9 | 63.9 | WD |
| PM-6X | 7/8/2021 | 5,793.81 | 57.86 | 55.29 | 5,851.67 | 2.57 | 36.5-61.5 | 65 | 61.5 | WD |
| PM-6X | 10/1/2021 | 5,793.76 | 57.91 | 55.34 | 5,851.67 | 2.57 | 36.5-61.5 | 65 | 61.5 | WD |
| PM-6X-UD | 7/8/2021 | 5,792.58 | 59.45 | 56.94 | 5,852.03 | 2.51 | 85 - 109.5 | 112.5 | 75 | UNWD |
| PM-6X-UD | 10/1/2021 | 5,792.20 | 59.83 | 57.32 | 5,852.03 | 2.51 | 85 - 109.5 | 112.5 | 75 | UNWD |
| PM-7I | 7/8/2021 | 5,810.82 | 42.13 | 40.08 | 5,852.95 | 2.05 | 27.5-62.5 | 68.75 | 62.5 | WD |
| PM-7I | 10/1/2021 | 5,810.79 | 42.16 | 40.11 | 5,852.95 | 2.05 | 27.5-62.5 | 68.75 | 62.5 | WD |
| PM-7X | 7/8/2021 | 5,818.26 | 35.35 | 32.54 | 5,853.61 | 2.81 | 16.5-66.5 | 70 | 66.5 | WD |
| PM-7X | 10/1/2021 | 5,818.13 | 35.48 | 32.67 | 5,853.61 | 2.81 | 16.5-66.5 | 70 | 66.5 | WD |
| PM-8I | 7/8/2021 | 5,816.84 | 26.58 | 24.36 | 5,843.42 | 2.22 | 12.3-64.8 | 71.3 | 64.8 | WD |
| PM-8I | 10/1/2021 | 5,816.29 | 27.13 | 24.91 | 5,843.42 | 2.22 | 12.3-64.8 | 71.3 | 64.8 | WD |
| PM-8X | 7/8/2021 | 5,826.77 | 17.05 | 14.23 | 5,843.82 | 2.82 | 10.2-65.2 | 70 | 65.2 | WD |
| PM-8X | 10/1/2021 | 5,825.60 | 18.22 | 15.4 | 5,843.82 | 2.82 | 10.2-65.2 | 70 | 65.2 | WD |
| PM-9I | 7/8/2021 | 5,816.62 | 24.81 | 22.38 | 5,841.43 | 2.43 | 12-44.5 | 50.25 | 44.5 | WD |
| PM-9I | 10/1/2021 | 5,816.02 | 25.41 | 22.98 | 5,841.43 | 2.43 | 12-44.5 | 50.25 | 44.5 | WD |
| PM-9X | 7/8/2021 | 5,826.89 | 14 | 10.81 | 5,840.89 | 3.19 | 11.75-46.75 | 50 | 46.8 | WD |
| PM-9X | 10/1/2021 | 5,824.98 | 15.91 | 12.72 | 5,840.89 | 3.19 | 11.75-46.75 | 50 | 46.8 | WD |
| PTP-1 | 7/7/2021 | 5,695.74 | 36.93 | 33.16 | 5,732.67 | 3.77 | 25-40 | 40 | NE, >40 | WD |
| PTP-1 | 10/4/2021 | 5,695.74 | 36.93 | 33.16 | 5,732.67 | 3.77 | 25-40 | 40 | NE, >40 | WD |
| PTP-10C | 7/7/2021 | 5,694.00 | 32.5 | 28.2 | 5,726.50 | 4.30 | 19-34 | 34 | 32 | WD |
| PTP-10C | 10/4/2021 | 5,693.95 | 32.55 | 28.25 | 5,726.50 | 4.30 | 19-34 | 34 | 32 | WD |
| PTP-11 | 7/2/2021 | 5,687.52 | 22.66 | 19.08 | 5,710.18 | 3.58 | 12-22 | 23.9 | 22 | WD |
| PTP-11 | 10/4/2021 | 5,687.32 | 22.86 | 19.28 | 5,710.18 | 3.58 | 12-22 | 23.9 | 22 | WD |
| PTP-12 | 7/2/2021 | 5,688.73 | 24.4 | 21.57 | 5,713.13 | 2.83 | 12-27 | 27 | 26 | WD |
| PTP-12 | 10/4/2021 | 5,688.51 | 24.62 | 21.79 | 5,713.13 | 2.83 | 12-27 | 27 | 26 | WD |
| PTP-13 | 7/8/2021 | 5,688.25 | 25.31 | 23.15 | 5,713.56 | 2.16 | 12.5-27.5 | 27.5 | 27 | WD |
| PTP-13 | 10/4/2021 | 5,687.57 | 25.99 | 23.83 | 5,713.56 | 2.16 | 12.5-27.5 | 27.5 | 27 | WD |
| PTP-14 | 7/8/2021 | Dry | Dry | Dry | 5,709.05 | 2.25 | 12-27 | 27 | 26.5 | WD |
| PTP-14 | 10/4/2021 | Dry | Dry | Dry | 5,709.05 | 2.25 | 12-27 | 27 | 26.5 | WD |
| PTP-15 | 7/8/2021 | Dry | Dry | Dry | 5,704.94 | 2.84 | 7.5-22.5 | 23.7 | 22.5 | WD |
| PTP-15 | 10/4/2021 | Dry | Dry | Dry | 5,704.94 | 2.84 | 7.5-22.5 | 23.7 | 22.5 | WD |
| PTP-15S | 7/8/2021 | Dry | Dry | Dry | 5,704.55 | 2.35 | 7-12 | 12 | NE, >12 | WD |
| PTP-15S | 10/4/2021 | Dry | Dry | Dry | 5,704.55 | 2.35 | 7-12 | 12 | NE, >12 | WD |
| PTP-16 | 7/8/2021 | Dry | Dry | Dry | 5,703.46 | 0.36 | 4.5-14.5 | 17 | NE, >17 | WD |
| PTP-16 | 10/4/2021 | Dry | Dry | Dry | 5,703.46 | 0.36 | 4.5-14.5 | 17 | NE, >17 | WD |
| PTP-17S | 7/8/2021 | Dry | Dry | Dry | 5,711.50 | 4.50 | 10-15 | 15 | NE, >15 | WD |
| PTP-17S | 10/4/2021 | Dry | Dry | Dry | 5,711.50 | 4.50 | 10-15 | 15 | NE, >15 | WD |
| PTP-18 | 7/8/2021 | Dry | Dry | Dry | 5,712.55 | 3.85 | 15.5-30.5 | 30.5 | 30.5 | WD |
| PTP-18 | 10/4/2021 | Dry | Dry | Dry | 5,712.55 | 3.85 | 15.5-30.5 | 30.5 | 30.5 | WD |
| PTP-19 | 7/8/2021 | Dry | Dry | Dry | 5,715.56 | 3.86 | 9.5-24.5 | 39 | 38.8 | WD |
| PTP-19 | 10/4/2021 | Dry | Dry | Dry | 5,715.56 | 3.86 | 9.5-24.5 | 39 | 38.8 | WD |
| PTP-20 | 7/8/2021 | Dry | Dry | Dry | 5,707.16 | 3.66 | 6-21 | 23.5 | 21 | WD |
| PTP-20 | 10/4/2021 | Dry | Dry | Dry | 5,707.16 | 3.66 | 6-21 | 23.5 | 21 | WD |
| PTP-20S | 7/8/2021 | Dry | Dry | Dry | 5,706.15 | 2.65 | NA | -- | NA | WD |
| PTP-20S | 10/4/2021 | Dry | Dry | Dry | 5,706.15 | 2.65 | NA | -- | NA | WD |
| PTP-21 | 7/8/2021 | 5,688.86 | 21.75 | 19.34 | 5,710.61 | 2.41 | 7.5-22.5 | 22.5 | 21 | WD |
| PTP-21 | 10/4/2021 | 5,688.58 | 22.03 | 19.62 | 5,710.61 | 2.41 | 7.5-22.5 | 22.5 | 21 | WD |
| PTP-22 | 7/8/2021 | 5,688.75 | 23.42 | 20.55 | 5,712.17 | 2.87 | 6-21 | 21 | 21 | WD |
| PTP-22 | 10/4/2021 | 5,688.70 | 23.47 | 20.6 | 5,712.17 | 2.87 | 6-21 | 21 | 21 | WD |
| PTP-22S | 7/8/2021 | Dry | Dry | Dry | 5,711.50 | 2.20 | 7-12 | 12 | NE, >12 | WD |
| PTP-22S | 10/4/2021 | Dry | Dry | Dry | 5,711.50 | 2.20 | 7-12 | 12 | NE, >12 | WD |
| PTP-23 | 7/7/2021 | 5,693.25 | 32.08 | 28.27 | 5,725.33 | 3.81 | 23-33 | 33 | 32 | WD |
| PTP-23 | 10/4/2021 | 5,693.24 | 32.09 | 28.28 | 5,725.33 | 3.81 | 23-33 | 33 | 32 | WD |
| PTP-24 | 7/7/2021 | 5,692.55 | 28.68 | 25.48 | 5,721.23 | 3.20 | 22-32 | 32 | 29.5 | WD |
| PTP-24 | 10/4/2021 | 5,692.45 | 28.78 | 25.58 | 5,721.23 | 3.20 | 22-32 | 32 | 29.5 | WD |
| PTP-25 | 7/7/2021 | 5,688.11 | 25.28 | 23.31 | 5,713.39 | 1.97 | 18.3-28.3 | 28.29 | 27 | WD |
| PTP-25 | 10/4/2021 | 5,688.10 | 25.29 | 23.32 | 5,713.39 | 1.97 | 18.3-28.3 | 28.29 | 27 | WD |
| PTP-26 | 7/7/2021 | 5,689.15 | 35.44 | 32.54 | 5,724.59 | 2.90 | 24-34 | 34 | 34 | WD |
| PTP-26 | 10/4/2021 | 5,689.24 | 35.35 | 32.45 | 5,724.59 | 2.90 | 24-34 | 34 | 34 | WD |
| PTP-27 | 7/7/2021 | 5,693.90 | 33.64 | 30.94 | 5,727.54 | 2.70 | 24-34 | 34 | 34 | WD |
| PTP-27 | 10/4/2021 | 5,694.01 | 33.53 | 30.83 | 5,727.54 | 2.70 | 24-34 | 34 | 34 | WD |

**TABLE 4.2**
**WATER LEVEL ELEVATIONS**
**JULY THROUGH DECEMBER 2021 OPERATIONS AND MAINTENANCE STATUS REPORT**
**LOWRY LANDFILL SUPERFUND SITE**

| Well ID | Date of Measurement | Water-Surface Elevation (ft NGVD)[a/] | Measured Depth to Water (ft below MP)[b/] | Depth to Water (ft bgs)[c/] | Measuring Point Elevation (ft NGVD) | Stickup (ft)[d/] | Screened Interval (ft bgs) | Total Depth (ft bgs) | Base of Weathering (ft bgs) | Formation[e/] |
|---|---|---|---|---|---|---|---|---|---|---|
| PTP-2F | 7/7/2021 | 5,692.84 | 36.28 | 32.26 | 5,729.12 | 4.02 | 22.5-37.5 | 37.5 | 36 | WD |
| PTP-2F | 10/4/2021 | 5,692.86 | 36.26 | 32.24 | 5,729.12 | 4.02 | 22.5-37.5 | 37.5 | 36 | WD |
| PTP-3F | 7/7/2021 | 5,690.96 | 34.08 | 30.44 | 5,725.04 | 3.64 | 16.5-31.5 | 31.5 | NE, >31.5 | WD |
| PTP-3F | 10/4/2021 | 5,690.92 | 34.12 | 30.48 | 5,725.04 | 3.64 | 16.5-31.5 | 31.5 | NE, >31.5 | WD |
| PTP-4C | 7/7/2021 | 5,690.90 | 29.57 | 25.7 | 5,720.47 | 3.87 | 17-27 | 27.2 | NE, >27.2 | WD |
| PTP-4C | 10/4/2021 | 5,690.89 | 29.58 | 25.71 | 5,720.47 | 3.87 | 17-27 | 27.2 | NE, >27.2 | WD |
| PTP-5A | 7/7/2021 | Dry | Dry | Dry | 5,717.37 | 3.37 | 15-25 | 25 | NE, >25 | WD |
| PTP-5A | 10/4/2021 | Dry | Dry | Dry | 5,717.37 | 3.37 | 15-25 | 25 | NE, >25 | WD |
| PTP-6B | 7/7/2021 | 5,688.67 | 24.39 | 20.43 | 5,713.06 | 3.96 | 9-24 | 24 | NE, >24 | WD |
| PTP-6B | 10/4/2021 | 5,688.62 | 24.44 | 20.48 | 5,713.06 | 3.96 | 9-24 | 24 | NE, >24 | WD |
| PTP-7H | 7/7/2021 | 5,689.03 | 23.5 | 20.07 | 5,712.53 | 3.43 | 12.5-22.5 | 22.5 | NE, >22.5 | WD |
| PTP-7H | 10/4/2021 | 5,688.95 | 23.58 | 20.15 | 5,712.53 | 3.43 | 12.5-22.5 | 22.5 | NE, >22.5 | WD |
| PTP-8A | 7/7/2021 | 5,689.81 | 28.05 | 25.09 | 5,717.86 | 2.96 | 16-26 | 26 | NE, >26 | WD |
| PTP-8A | 10/4/2021 | 5,689.77 | 28.09 | 25.13 | 5,717.86 | 2.96 | 16-26 | 26 | NE, >26 | WD |
| PTP-9 | 7/7/2021 | Dry | Dry | Dry | 5,722.06 | 3.46 | 17-27 | 27 | NE, >27 | WD |
| PTP-9 | 10/4/2021 | Dry | Dry | Dry | 5,722.06 | 3.46 | 17-27 | 27 | NE, >27 | WD |
| PZ-101A | 7/8/2021 | 5,681.15 | 145.05 | 142.75 | 5,826.20 | 2.30 | 314.6-325.1 | 328 | 48 | LIGNITE |
| PZ-101A | 10/1/2021 | 5,677.87 | 148.33 | 146.03 | 5,826.20 | 2.30 | 314.6-325.1 | 328 | 48 | LIGNITE |
| PZ-103 | 7/6/2021 | 5,680.03 | 115.75 | 109.27 | 5,795.78 | 6.48 | 291.5-302 | 302.3 | 30 | LIGNITE |
| PZ-103 | 10/1/2021 | 5,679.75 | 116.03 | 109.55 | 5,795.78 | 6.48 | 291.5-302 | 302.3 | 30 | LIGNITE |
| RDPZ-102 | 7/6/2021 | 5,783.70 | 64.38 | 61.93 | 5,848.08 | 2.45 | 47.5-67 | 69.5 | 69.5 | WD |
| RDPZ-102 | 10/1/2021 | 5,783.69 | 64.39 | 61.94 | 5,848.08 | 2.45 | 47.5-67 | 69.5 | 69.5 | WD |
| SUMP | 7/7/2021 | 5,685.77 | 26.97 | 27.87 | 5,712.74 | -0.90 | 10-32.9 | 32.9 | -- | NO GEOLOGIC LOG |
| SUMP | 10/4/2021 | 5,685.68 | 27.06 | 27.96 | 5,712.74 | -0.90 | 10-32.9 | 32.9 | -- | NO GEOLOGIC LOG |
| T1-1 | 7/1/2021 | 5,674.97 | 3.3 | 1.23 | 5,678.27 | 2.07 | 7.5-17.5 | 17.5 | -- | ALLUVIUM |
| T1-1 | 10/6/2021 | 5,674.13 | 4.14 | 2.07 | 5,678.27 | 2.07 | 7.5-17.5 | 17.5 | -- | ALLUVIUM |
| T1-2 | 7/1/2021 | 5,675.89 | 9.13 | 5.81 | 5,685.02 | 3.32 | 10-20 | 20 | -- | WD |
| T1-2 | 10/6/2021 | 5,674.70 | 10.32 | 7 | 5,685.02 | 3.32 | 10-20 | 20 | -- | WD |
| T1-3 | 7/1/2021 | 5,675.74 | 3.72 | 0.26 | 5,679.46 | 3.46 | 6.4-16.4 | 16.4 | -- | WD |
| T1-3 | 10/6/2021 | 5,674.99 | 4.47 | 1.01 | 5,679.46 | 3.46 | 6.4-16.4 | 16.4 | -- | WD |
| T1-4 | 7/1/2021 | 5,676.25 | 3.84 | 0.45 | 5,680.09 | 3.39 | 4-14 | 14 | -- | WD |
| T1-4 | 10/6/2021 | 5,675.79 | 4.3 | 0.91 | 5,680.09 | 3.39 | 4-14 | 14 | -- | WD |
| T1-5 | 7/1/2021 | 5,677.82 | 14.88 | 11.48 | 5,692.70 | 3.40 | 14-24 | 24 | -- | WD |
| T1-5 | 10/6/2021 | 5,677.03 | 15.67 | 12.27 | 5,692.70 | 3.40 | 14-24 | 24 | -- | WD |
| TR-1 | 7/8/2021 | Dry | Dry | Dry | 5,706.65 | 1.72 | 8-18 | 18 | NE, >18 | WD |
| TR-1 | 10/4/2021 | Dry | Dry | Dry | 5,706.65 | 1.72 | 8-18 | 18 | NE, >18 | WD |
| U-518R-WD | 7/9/2021 | 5,751.83 | 46.88 | 44.67 | 5,798.71 | 2.21 | 39.5 - 49.5 | 52.7 | 50.5 | WD |
| U-518R-WD | 10/5/2021 | 5,751.96 | 46.75 | 44.54 | 5,798.71 | 2.21 | 39.5 - 49.5 | 52.7 | 50.5 | WD |
| U-701 | 7/7/2021 | 5,688.22 | 28.12 | 25.5 | 5,716.34 | 2.62 | 34-44 | 44 | 33.6 | UNWD |
| U-701 | 10/4/2021 | 5,688.26 | 28.08 | 25.46 | 5,716.34 | 2.62 | 34-44 | 44 | 33.6 | UNWD |
| U-701-WD | 7/7/2021 | Dry | Dry | Dry | 5,716.24 | 2.23 | 12.7-22.7 | 22.7 | 34.9 | WD |
| U-701-WD | 10/4/2021 | Dry | Dry | Dry | 5,716.24 | 2.23 | 12.7-22.7 | 22.7 | 34.9 | WD |
| WEST CLEANOUT | 7/15/2021 | Dry | Dry | Dry | 5,772.41 | -- | -- | -- | -- | NO GEOLOGIC LOG |
| WEST CLEANOUT | 10/11/2021 | Dry | Dry | Dry | 5,772.41 | -- | -- | -- | -- | NO GEOLOGIC LOG |

a/ ft NGVD = elevation in feet referenced to the National Geodetic Vertical Datum of 1929.

b/ ft below MP = feet below measuring point

c/ ft bgs = feet below ground surface

d/ ft = feet

e/ Formation = formation or zone in which well screen is located. Formation/zone designations are as follow:

ALLUVIUM = Alluvium of un-named creek.
FILL = imported soils - not native
LIGNITE = "Lignite zone" in Denver Formation
UNWD = Unweathered Dawson Formation
UPPER DENVER = Upper part of Denver Formation
WD = Weathered Dawson Formation

f/ NE = Base of weathering not encountered during drilling of boring

g/ -- or NA = Information not available at this time

# TABLE 4.3
## SUMMARY OF VERTICAL HYDRAULIC GRADIENT CALCULATIONS
### JULY THROUGH DECEMBER 2021 OPERATIONS AND MAINTENANCE STATUS REPORT
### LOWRY LANDFILL SUPERFUND SITE

| | | 3rd Quarter 2021 | | | | 4th Quarter 2021 | | | |
|---|---|---|---|---|---|---|---|---|---|
| Shallow Well | Deep Well | Measure Date | Head Difference [a/] (ft)[b/] | Diff. in Saturated Screen Elev. [c/] (ft) | Vertical Gradient[d/] (ft/ft) | Measure Date | Head Difference (ft) | Diff. in Saturated Screen Elev. (ft) | Vertical Gradient (ft/ft) |
| B-304 | B-304-UD | 7/7/2021 | -10.29 | 37.20 | -0.277 | 10/4/2021 | -9.09 | 36.10 | -0.252 |
| B-305WD | B-305-R | 7/7/2021 | B-305WD Dry | | | 10/4/2021 | B-305WD Dry | | |
| B-307 | B-306 | 7/8/2021 | B-307 Dry | | | 10/4/2021 | B-307 Dry | | |
| B-313 | B-313-UD | 7/7/2021 | -7.05 | 29.84 | -0.236 | 10/4/2021 | -5.82 | 28.67 | -0.203 |
| B-314 | B-314-UD | 7/8/2021 | -6.69 | 31.67 | -0.211 | 10/4/2021 | -7.37 | 31.67 | -0.233 |
| B-316 | B-316-UD | 7/7/2021 | -4.88 | 22.80 | -0.214 | 10/4/2021 | -4.41 | 22.80 | -0.193 |
| B-317 | B-317-UD | 7/7/2021 | 1.73 | 23.44 | 0.074 | 10/4/2021 | 0.67 | 23.70 | 0.028 |
| B-326-WD | B-326-UD | 7/8/2021 | 2.18 | 24.48 | 0.089 | 10/4/2021 | 3.23 | 22.55 | 0.143 |
| B-327-WD | B-327-UD | 7/7/2021 | -4.51 | 31.10 | -0.145 | 10/4/2021 | -3.60 | 30.29 | -0.119 |
| B-712-UD | B-712-LD | 7/15/2021 | -6.50 | 43.40 | -0.150 | 10/11/2021 | -6.40 | 43.40 | -0.147 |
| BKGD-2WD | BKGD-2UD | 7/12/2021 | -38.79 | 21.87 | -1.774 | 10/8/2021 | -40.09 | 21.87 | -1.833 |
| BM-4X-50S | BM-4X-40S | 7/6/2021 | -7.58 | 28.96 | -0.262 | 10/1/2021 | -7.58 | 28.96 | -0.262 |
| BW-PZ-1 | BW-PZ-1LC | 7/7/2021 | -3.67 | 16.34 | -0.225 | 10/4/2021 | -4.22 | 16.34 | -0.258 |
| C-702Q3 | C-702P4 | 7/15/2021 | 0.06 | 18.10 | 0.003 | 10/11/2021 | 0.55 | 18.10 | 0.030 |
| GW-107A | GW-107UD | 7/7/2021 | -0.30 | 22.72 | -0.013 | 10/4/2021 | 2.65 | 22.09 | 0.120 |
| GW-114A | GW-108A | 7/7/2021 | -7.29 | 33.70 | -0.216 | 10/4/2021 | -7.99 | 33.69 | -0.237 |
| MW-1000 | MW-1000LC | 7/7/2021 | MW-1000 Dry | | | 10/4/2021 | -1.34 | 42.63 | -0.031 |
| MW33-WDR | MW33-UD | 7/6/2021 | MW33-WDR Dry | | | 10/1/2021 | MW33-WDR Dry | | |
| MW36-WDR | MW36-UD | 7/6/2021 | -4.14 | 24.70 | -0.168 | 10/1/2021 | -4.12 | 24.70 | -0.167 |
| MW37-WD | MW37-UD | 7/7/2021 | 3.39 | 14.72 | 0.230 | 10/4/2021 | 3.45 | 14.69 | 0.235 |
| MW38-1064N-650E | MW38-1064N-655E | 7/12/2021 | -12.32 | 20.00 | -0.616 | 10/8/2021 | -9.76 | 19.32 | -0.505 |
| MW38-1373N-180W | MW38-1363N-180W | 7/13/2021 | 1.82 | 29.50 | 0.062 | 10/8/2021 | 1.44 | 29.64 | 0.049 |
| MW38-350S-50W | MW38-302S-50W | 7/14/2021 | -3.91 | 8.61 | -0.454 | 10/7/2021 | -4.07 | 8.69 | -0.469 |
| MW38-400N-180W | MW38-410N-180W | 7/13/2021 | -38.57 | 35.91 | -1.074 | 10/8/2021 | -38.37 | 35.90 | -1.069 |
| MW38-400N-240E | MW38-400N-300E | 7/13/2021 | -20.58 | 32.43 | -0.634 | 10/8/2021 | -20.52 | 32.39 | -0.634 |
| MW39-WD | MW39-UD | 7/6/2021 | -21.63 | 30.36 | -0.712 | 10/1/2021 | -21.62 | 30.35 | -0.712 |
| MW42-WD | MW42-UD | 7/6/2021 | -1.21 | 33.89 | -0.036 | 10/1/2021 | -2.82 | 34.08 | -0.083 |
| MW49-WD | B-519 | 7/8/2021 | 0.63 | 29.20 | 0.022 | 10/1/2021 | 0.50 | 29.20 | 0.017 |
| MW51-WD | MW51-10S | 7/9/2021 | -0.69 | 15.40 | -0.045 | 10/5/2021 | -0.73 | 15.37 | -0.047 |
| MW51X-WD-100S | B-518 | 7/9/2021 | 7.65 | 38.00 | 0.201 | 10/5/2021 | 7.43 | 38.00 | 0.196 |
| MW52-WD | MW52-UD | 7/9/2021 | -3.03 | 37.92 | -0.080 | 10/5/2021 | -3.50 | 37.96 | -0.092 |
| MW54-WD | MW54-UDR | 7/9/2021 | -0.28 | 28.65 | -0.010 | 10/5/2021 | 0.24 | 28.34 | 0.008 |
| MW62-WDR | MW62-UD | 7/7/2021 | -6.38 | 31.73 | -0.201 | 10/4/2021 | -6.64 | 31.70 | -0.209 |
| MW71-WD | MW71-UD | 7/9/2021 | 0.45 | 46.60 | 0.010 | 10/5/2021 | 0.63 | 46.31 | 0.014 |
| MW72-WD | MW72-UD | 7/9/2021 | -3.80 | 36.10 | -0.105 | 10/5/2021 | -3.60 | 36.10 | -0.100 |
| MW73-WD | MW73-UD | 7/8/2021 | -4.65 | 41.18 | -0.113 | 10/4/2021 | -4.29 | 40.91 | -0.105 |

# TABLE 4.3
## SUMMARY OF VERTICAL HYDRAULIC GRADIENT CALCULATIONS
### JULY THROUGH DECEMBER 2021 OPERATIONS AND MAINTENANCE STATUS REPORT
### LOWRY LANDFILL SUPERFUND SITE

| | | 3rd Quarter 2021 | | | | 4th Quarter 2021 | | | |
|---|---|---|---|---|---|---|---|---|---|
| Shallow Well | Deep Well | Measure Date | Head Difference [a/] (ft)[b/] | Diff. in Saturated Screen Elev. [c/] (ft) | Vertical Gradient[d/] (ft/ft) | Measure Date | Head Difference (ft) | Diff. in Saturated Screen Elev. (ft) | Vertical Gradient (ft/ft) |
| MW74-WD | MW74-UD | 7/13/2021 | -3.95 | 34.70 | -0.114 | 10/8/2021 | -3.58 | 34.70 | -0.103 |
| MW75-WD | MW75-UD | 7/12/2021 | -17.99 | 44.09 | -0.408 | 10/8/2021 | -15.31 | 44.09 | -0.347 |
| MW76-WD | MW76-UD | 7/12/2021 | -26.39 | 42.00 | -0.628 | 10/8/2021 | -23.64 | 42.00 | -0.563 |
| MW77-WD | MW77-UD | 7/2/2021 | -5.25 | 35.15 | -0.149 | 10/4/2021 | -4.65 | 34.52 | -0.135 |
| MW78-WD | MW78-UD | 7/9/2021 | 0.83 | 32.90 | 0.025 | 10/5/2021 | 0.64 | 32.70 | 0.020 |
| MW79-WD | MW79-UD | 7/9/2021 | -0.49 | 34.70 | -0.014 | 10/5/2021 | 0.06 | 34.70 | 0.002 |
| MW91-WD | MW91-UD | 7/9/2021 | -1.34 | 43.50 | -0.031 | 10/5/2021 | -1.15 | 43.50 | -0.026 |
| MW93-WD | MW93-UD | 7/9/2021 | 2.26 | 22.10 | 0.102 | 10/5/2021 | 1.92 | 21.88 | 0.088 |
| MW-EW-1 | MW-EW-1LC | 7/7/2021 | -2.51 | 17.60 | -0.143 | 10/4/2021 | -2.46 | 17.37 | -0.142 |
| MW-EW-1 | MW-EW-1LCRA | 7/7/2021 | -7.00 | 38.70 | -0.181 | 10/4/2021 | -6.99 | 38.47 | -0.182 |
| MW-EW-2 | MW-EW-2LC | 7/7/2021 | -2.02 | 16.77 | -0.120 | 10/4/2021 | -1.97 | 16.45 | -0.120 |
| NTES-EW1 | B-712-UD | 7/15/2021 | -1.46 | 24.40 | -0.060 | 10/11/2021 | -1.78 | 24.40 | -0.073 |
| BM-15I-15N | PM-15I-UD | 7/9/2021 | 10.40 | 20.26 | 0.513 | 10/5/2021 | 10.53 | 20.16 | 0.522 |
| U-701-WD | U-701 | 7/7/2021 | U-701-WD Dry | | | 10/4/2021 | U-701-WD Dry | | |

a/ The midpoint of the saturated portion of the screen interval is used to calculate the vertical distance between well pairs.

b/ ft = feet

c/ Groundwater elevations are presented in Table 4.2.

d/ A negative value indicates a downward gradient and a positive value indicates an upward gradients.

Highlighted cells indicate upward gradients

**TABLE 4.4**
**GROUNDWATER SAMPLING ACTIVITIES**
**JULY THROUGH DECEMBER 2021 OPERATIONS AND MAINTENANCE STATUS REPORT**
**LOWRY LANDFILL SUPERFUND SITE**

| Sample ID | Sample Type | Location [a/] | Water-Bearing Unit[b/] | Sampling Frequency[c/] | Date of Last Sample Collection[d/] | 3rd Quarter 2021 | 4th Quarter 2021 | 1st Quarter 2022[e/] | 2nd Quarter 2022[e/] |
|---|---|---|---|---|---|---|---|---|---|
| B-313 | Compliance/Effectiveness/B-326-UD & B-313 RAWP[f/]/1,4-Dioxane Resampling Event | NB | WD | Semi-annual (Compliance)/Quarterly (RAWP & North End Monitoring) | 11/16/2021 | 8/12/2021<br>DRY[i/] | 11/16/2021 | X | X |
| B-314 | Compliance/Effectiveness | NB | WD | Semi-annual | 10/27/2021 | | 10/27/2021 | | X |
| B-321 | B-326-UD & B-313 RAWP/1,4-Dioxane Resampling Event | NB | WD | Quarterly | 8/30/2021 | 8/11/2021<br>8/30/2021 | DRY | X | X |
| B-326-UD | Compliance/B-326-UD & B-313 RAWP/North End Monitoring/Molybdenum Investigation/1,4-Dioxane Resampling Events | NB | UNWD | Biennial (Compliance)/Quarterly (RAWP, North End Monitoring & Molybdenum Investigation) | 10/12/2021 | 8/12/2021<br>8/23/2021[h/]<br>8/30/2021 | 10/12/2021 | X | X |
| B-326-WD | Compliance/Effectiveness/North End Monitoring/Molybdenum Investigation/1,4-Dioxane Resampling Events/1,4-Dioxane Confirmation Sample | NB | WD | Semi-annual (Compliance)/Quarterly (North End Monitoring & Molybdenum Investigation) | 10/12/2021 | 8/12/2021<br>8/23/2021[h/]<br>8/30/2021<br>9/27/2021 | 10/12/2021 | X | X |
| BKGD-3WD | Performance Evaluation Sample | EXT-S | WD | Annual | 8/16/2021 | 8/16/2021 | | | |
| BM-11X-100N | Compliance/Effectiveness | EB | WD | Semi-annual | 10/28/2021 | | 10/28/2021 | | X |
| BM-11X-100S | Compliance/Effectiveness | EB | WD | Semi-annual | 10/28/2021 | | 10/28/2021 | | X |
| BM-15E2 | Compliance | EB | WD | Semi-annual | 11/16/2021 | | 11/16/2021 | | X |
| BM-15N6 | Compliance/Effectiveness | EB | WD | Semi-annual | 10/13/2021 | | 10/13/2021 | | X |
| GW-106 | Compliance | NB | WD | Semi-annual | 10/13/2021 | | 10/13/2021 | | X |
| GW-109 | Compliance | NB | WD | Semi-annual | 6/1/2020 | | DRY | | X |
| MNA-01 | Effectiveness | INT | WD | Semi-annual | 11/23/2021 | | 11/23/2021 | | X |
| MNA-03 | Effectiveness | INT | WD | Semi-annual | 11/23/2021 | | 11/23/2021 | | X |
| MW05-WD | North End Monitoring | NE | WD | Semi-annual | 8/18/2021 | 8/18/2021 | | X | |
| MW102-WD | North End Monitoring | NB | WD | Quarterly | 11/18/2021 | 8/31/2021 | 11/18/2021 | X | X |
| MW103-WD | North End Monitoring/1,4-Dioxane Resampling Event | NE | WD | Quarterly | 11/2/2021 | 7/22/2021<br>8/5/2021 | 11/2/2021 | X | X |
| MW105-WD | Compliance | EB | WD | Semi-annual | 10/19/2021 | | 10/19/2021 | | X |
| MW108-WD | Compliance | EB | WD | Semi-annual | 11/1/2021 | | 11/1/2021 | | X |
| MW113-EW-1 | North End Monitoring/Molybdenum Investigation | NE | WD | Quarterly | 10/19/2021 | 7/29/2021 | 10/19/2021 | X | X |
| MW113-UD | North End Monitoring/Molybdenum Investigation | NE | UNWD | Quarterly (RAWP & North End Monitoring)/Monthly (Molybdenum Investigation) | 12/15/2021 | 7/29/2021<br>8/25/2021<br>9/9/2021 | 10/19/2021<br>11/17/2021<br>12/15/2021 | X | X |
| MW113-WD | Molybdenum Investigation | NE | WD | Bi-weekly | 12/28/2021 | Sampled 6 times | Sampled 7 times | X | X |
| MW114-WD | North End Monitoring/1,4-Dioxane Resampling Event | NE | WD | Quarterly | 11/17/2021 | 7/22/2021<br>8/5/2021 | 11/17/2021 | X | X |

**TABLE 4.4**
**GROUNDWATER SAMPLING ACTIVITIES**
**JULY THROUGH DECEMBER 2021 OPERATIONS AND MAINTENANCE STATUS REPORT**
**LOWRY LANDFILL SUPERFUND SITE**

| Sample ID | Sample Type | Location [a/] | Water-Bearing Unit[b/] | Sampling Frequency[c/] | Date of Last Sample Collection[d/] | 3rd Quarter 2021 | 4th Quarter 2021 | 1st Quarter 2022[e/] | 2nd Quarter 2022[e/] |
|---|---|---|---|---|---|---|---|---|---|
| MW117-WD | North End Monitoring/1,4-Dioxane Resampling Event | NE | WD | Quarterly | 11/17/2021 | 7/22/2021<br>8/5/2021 | 11/17/2021 | X | X |
| MW118-WD | North End Monitoring | NE | WD | Quarterly | 11/17/2021 | 8/9/2021 | 11/17/2021 | X | X |
| MW121-WDR | North End Monitoring | NE | WD | Semi-annual | 8/18/2021 | 8/18/2021 | | X | |
| MW122-WDR | North End Monitoring | NE | WD | Semi-annual | 8/18/2021 | 8/18/2021 | | X | |
| MW123-WD | North End Monitoring | NE | WD | Semi-annual | 8/18/2021 | 8/18/2021 | | X | |
| MW124-WD | North End Monitoring | NE | WD | Semi-annual | 8/18/2021 | 8/18/2021 | | X | |
| MW125-WD | North End Monitoring/1,4-Dioxane Resampling Event | NE | WD | Semi-annual | 8/30/2021 | 8/23/2021<br>8/30/2021 | | X | |
| MW129-WD | North End Monitoring | NE | WD | Semi-annual | 9/7/2021 | 9/7/2021 | | X | |
| MW132-WD | North End Monitoring | NE | WD | Quarterly | 11/2/2021 | 7/21/2021 | 11/2/2021 | X | X |
| MW135-WD | North End Monitoring | NE | WD | Semi-annual | 7/28/2021 | 7/28/2021 | | X | |
| MW141-WD | North End Monitoring | NE | WD | Semi-annual | 7/28/2021 | 7/28/2021 | | X | |
| MW142-WD | North End Monitoring | NE | WD | Semi-annual | 7/28/2021 | 7/28/2021 | | X | |
| MW144-WD | North End Monitoring | NE | WD | Semi-annual | 8/4/2021 | 8/4/2021 | | X | |
| MW151-WD | North End Monitoring | NE | WD | Quarterly | 11/11/2021 | 7/19/2021 | 11/11/2021 | X | X |
| MW153-EW-1 | North End Monitoring | NE | WD | Quarterly | 11/8/2021 | 7/21/2021 | 11/8/2021 | X | X |
| MW154-EW-1 | North End Monitoring | NE | WD | Quarterly | 11/11/2021 | 7/21/2021 | 11/11/2021 | X | X |
| MW155-EW-1 | North End Monitoring | NE | WD | Quarterly | 11/22/2021 | 7/21/2021 | 11/22/2021 | X | X |
| MW156-EW-1 | North End Monitoring | NE | WD | Quarterly | 11/22/2021 | 7/21/2021 | 11/22/2021 | X | X |
| MW156-WD | North End Monitoring | NE | WD | Quarterly | 11/11/2021 | 7/19/2021 | 11/11/2021 | X | X |
| MW157-WD | North End Monitoring | NE | WD | Quarterly | 11/11/2021 | 7/19/2021 | 11/11/2021 | X | X |
| MW160-WD | North End Monitoring | NE | WD | Quarterly | 11/8/2021 | 7/19/2021 | 11/8/2021 | X | X |
| MW170-EW-1 | RAWP/MW77 Response Action/Molybdenum Investigation | EB | WD | Quarterly | 10/27/2021 | 8/9/2021 | 10/27/2021 | X | X |
| MW176-DEN | North End Monitoring | NE | DEN | Semi-annual | 8/4/2021 | 8/4/2021 | | X | |
| MW179-UDEN | North End Monitoring | NE | UDEN | Semi-annual | 9/8/2021 | 9/8/2021 | | X | |
| MW23-UPPER-C | Compliance | EB | WD | Semi-annual | 10/18/2021 | | 10/18/2021 | | X |
| MW36-WDR | Compliance | WB | WD | Semi-annual | 11/2/2021 | | 11/2/2021 | | X |
| MW38-1028N-256E | MW38 Source Control | WB | WD | Semi-annual | 11/10/2021 | | 11/10/2021 | | X |
| MW38-170S-140W | MW38 Source Control | WB | WD | Semi-annual | 11/9/2021 | | 11/9/2021 | | X |
| MW38-825S-445E | MW38 Source Control | WB | WD | Semi-annual | 11/8/2021 | | 11/8/2021 | | X |
| MW38-830N-230E | Compliance | WB | WD | Semi-annual | 10/14/2021 | | 10/14/2021 | | X |
| MW43-WD | Compliance | WB | WD | Semi-annual | 11/16/2021 | | 11/16/2021 | | X |
| MW54-WD | Compliance | EB | WD | Semi-annual | 10/14/2021 | | 10/14/2021 | | X |
| MW60-WD | Compliance | EB | WD | Semi-annual | 10/28/2021 | | 10/28/2021 | | X |
| MW62-WDR | Compliance/Effectiveness | NB | WD | Semi-annual | 10/27/2021 | | 10/27/2021 | | X |
| MW70-WD | VES Performance | EB | WD | Semi-annual | 11/9/2021 | | 11/9/2021 | | X |
| MW71-WD | Compliance | EB | WD | Semi-annual | 11/1/2021 | | 11/1/2021 | | X |
| MW74-WD | Compliance | NB | WD | Semi-annual | 10/14/2021 | | 10/14/2021 | | X |
| MW77-EW-1 | North End Monitoring | EB | WD | Quarterly | 11/18/2021 | 8/31/2021 | 11/18/2021 | X | X |

# TABLE 4.4
# GROUNDWATER SAMPLING ACTIVITIES
## JULY THROUGH DECEMBER 2021 OPERATIONS AND MAINTENANCE STATUS REPORT
## LOWRY LANDFILL SUPERFUND SITE

| Sample ID | Sample Type | Location [a/] | Water-Bearing Unit[b/] | Sampling Frequency[c/] | Date of Last Sample Collection[d/] | 3rd Quarter 2021 | 4th Quarter 2021 | 1st Quarter 2022[e/] | 2nd Quarter 2022[e/] |
|---|---|---|---|---|---|---|---|---|---|
| MW77-EW-2 | 1,4-Dioxane Confirmation Sample/North End Monitoring | EB | WD | Quarterly | 11/18/2021 | 9/1/2021<br>9/14/2021 | 11/18/2021 | X | X |
| MW77-WD | Compliance | EB | WD | Semi-annual | 10/27/2021 | | 10/27/2021 | | X |
| MW78-WD | Compliance | EB | WD | Semi-annual | 11/1/2021 | | 11/1/2021 | | X |
| MW90-WD | Compliance | EB | WD | Semi-annual | 10/13/2021 | | 10/13/2021 | | X |
| MW91-WD | Compliance | EB | WD | Semi-annual | 10/18/2021 | | 10/18/2021 | | X |
| MW98-WD | North End Monitoring | NB | WD | Quarterly | 11/18/2021 | 8/31/2021 | 11/18/2021 | X | X |
| NBBW-IW-3[g/] | Molybdenum Investigation | NB | WD | Quarterly | 8/5/2021 | 8/5/2021 | DRY | X | X |
| Private Well 1 | Residential Well | NE | DEN | Annual | 5/19/2021 | | | | X |
| PM-13X | Effectiveness | EB | WD | Semi-annual | 11/3/2021 | | 11/3/2021 | | X |
| PM-14X | Compliance/Effectiveness | EB | WD | Semi-annual | 10/26/2021 | | 10/26/2021 | | X |
| PM-3X | Effectiveness | WB | WD | Semi-annual | 11/3/2021 | | 11/3/2021 | | X |
| PM-6X | Effectiveness | SB | WD | Semi-annual | 11/3/2021 | | 11/3/2021 | | X |
| PTP-11 | Molybdenum Investigation | NB | WD | Quarterly | 11/4/2021 | 8/26/2021 | 11/4/2021 | X | X |
| PTP-12 | Molybdenum Investigation | NB | WD | Quarterly | 11/4/2021 | 8/26/2021 | 11/4/2021 | X | X |
| PTP-13 | North End Monitoring/Molybdenum Investigation | NB | WD | Quarterly | 11/10/2021 | 8/25/2021 | 11/10/2021 | X | X |
| PTP-14 | Molybdenum Investigation | NB | WD | Quarterly | 6/2/2020 | DRY | DRY | X | X |
| Private Well 2 | Residential Well | NE | DEN | Annual | 5/19/2021 | | | | X |
| U-518R-WD | Compliance | EB | WD | Semi-annual | 10/26/2021 | | 10/26/2021 | | X |

a/ Location = geographic location at the site
- EB = East Boundary
- WB = West Boundary
- SB = South Boundary
- INT = Interior
- NB = North Boundary
- NE = North End
- NT = North Toe
- EXT-S = Exterior South

b/ Water-bearing unit = formation or zone in which well screen is located
Formation/zone designations are as follow:
- Alluvium = Alluvium
- WD = Weathered Dawson Formation
- UNWD = Unweathered Dawson Formation
- DEN = Upper part of Denver Formation
- UDEN = Unweathered Denver Formation
- Lignite = "Lignite zone" in Denver Formation

c/ Represents frequency for long term monitoring.

d/ Last sampling date - may be for 1,4-dioxane only or for full contaminant of concern list

e/ An "x" indicates that the well is scheduled to be sampled during the 1st and/or 2nd quarter of 2022

f/ RAWP = Response Action Work Plan

g/ Weekly Molybdenum sampling was suspended after 1Q 2021 when sampling began at WTP sampling port

h/ Resample was attempted, but shipment to lab was delayed by air carrier and samples were cancelled due to high cooler temperatures, no sample data for this event

i/ Resample was attempted on 9/7/2021, but well was dry during resampling attempt, no sample data for this event

**TABLE 4.5**
**SUMMARY OF DETECTED CONSTITUENTS**
**JULY THROUGH DECEMBER 2021 OPERATIONS AND MAINTENANCE STATUS REPORT**
**LOWRY LANDFILL SUPERFUND SITE**

| Well ID | Constituent/Parameter | Date Sampled | Result | Qualifier[a/] | Units[b/] | Reporting Limit |
|---|---|---|---|---|---|---|
| B-313 | 1,4-Dioxane | 11/16/2021 | 17 | | µg/L | 0.9 |
| B-313 | Nitrogen, Nitrate | 8/12/2021 | 55000 | J | µg/L | 2500 |
| B-314 | 1,1-Dichloroethane | 10/27/2021 | 1.5 | | µg/L | 1 |
| B-314 | Nitrogen, Nitrate | 10/27/2021 | 160 | J | µg/L | 500 |
| B-321 | 1,4-Dioxane | 8/30/2021 | 9.7 | | µg/L | 0.9 |
| B-321 | Nitrogen, Nitrate | 8/11/2021 | 43000 | | µg/L | 2500 |
| B-326-UD | 1,4-Dioxane | 8/30/2021 | 6.1 | | µg/L | 0.9 |
| B-326-UD | 1,4-Dioxane | 10/12/2021 | 5 | | µg/L | 0.9 |
| B-326-UD | Molybdenum, Dissolved | 8/12/2021 | 3 | J | µg/L | 20 |
| B-326-UD | Molybdenum, Dissolved | 10/12/2021 | 2.9 | J | µg/L | 20 |
| B-326-WD | 1,4-Dioxane | 8/30/2021 | 0.77 | J | µg/L | 0.9 |
| B-326-WD | 1,4-Dioxane | 9/27/2021 | 0.69 | J | µg/L | 0.9 |
| B-326-WD | 1,4-Dioxane | 10/12/2021 | 1 | | µg/L | 0.9 |
| B-326-WD | Molybdenum, Dissolved | 8/12/2021 | 54 | | µg/L | 20 |
| B-326-WD | Molybdenum, Dissolved | 10/12/2021 | 30 | | µg/L | 20 |
| B-326-WD | Nitrogen, Nitrate | 10/12/2021 | 9900 | | µg/L | 2500 |
| B-326-WD | Nitrogen, Nitrite | 10/12/2021 | 150 | J- | µg/L | 500 |
| BKGD-3WD | Nitrogen, Nitrate | 8/16/2021 | 660 | | µg/L | 500 |
| BM-11X-100N | 1,1,1-Trichloroethane | 10/28/2021 | 0.71 | J | µg/L | 1 |
| BM-11X-100N | 1,1-Dichloroethane | 10/28/2021 | 33 | | µg/L | 1 |
| BM-11X-100N | 1,1-Dichloroethene | 10/28/2021 | 1.2 | | µg/L | 1 |
| BM-11X-100N | Chloroform | 10/28/2021 | 1.4 | | µg/L | 1 |
| BM-11X-100N | Nitrogen, Nitrate | 10/28/2021 | 12000 | | µg/L | 2500 |
| BM-11X-100N | Tetrachloroethene | 10/28/2021 | 5.4 | | µg/L | 1 |
| BM-11X-100N | Trichloroethene | 10/28/2021 | 4.8 | | µg/L | 1 |
| BM-11X-100S | 1,1-Dichloroethane | 10/28/2021 | 4.8 | | µg/L | 1 |
| BM-11X-100S | Chloroform | 10/28/2021 | 1.3 | | µg/L | 1 |
| BM-11X-100S | Nitrogen, Nitrate | 10/28/2021 | 10000 | | µg/L | 2500 |
| BM-11X-100S | Tetrachloroethene | 10/28/2021 | 1.2 | | µg/L | 1 |
| BM-11X-100S | Trichloroethene | 10/28/2021 | 1.3 | | µg/L | 1 |
| BM-15E2 | 1,1-Dichloroethane | 11/16/2021 | 1.5 | | µg/L | 1 |
| BM-15E2 | 1,1-Dichloroethene | 11/16/2021 | 0.34 | J | µg/L | 1 |
| BM-15E2 | Nitrogen, Nitrate | 11/16/2021 | 19000 | | µg/L | 2500 |
| BM-15E2 | Tetrachloroethene | 11/16/2021 | 0.34 | J | µg/L | 1 |
| BM-15E2 | Trichloroethene | 11/16/2021 | 0.31 | J | µg/L | 1 |
| BM-15N6 | 1,1-Dichloroethane | 10/13/2021 | 2.6 | | µg/L | 1 |
| BM-15N6 | Nitrogen, Nitrate | 10/13/2021 | 30000 | | µg/L | 5000 |
| BM-15N6 | Tetrachloroethene | 10/13/2021 | 2.7 | | µg/L | 1 |
| BM-15N6 | Trichloroethene | 10/13/2021 | 0.71 | J | µg/L | 1 |
| GW-106 | Arsenic | 10/13/2021 | 5 | J | µg/L | 15 |
| GW-106 | Nitrogen, Nitrate | 10/13/2021 | 1400 | | µg/L | 500 |
| MNA-01 | 1,1-Dichloroethane | 11/23/2021 | 59 | | µg/L | 10 |
| MNA-01 | 1,2-Dichloroethane | 11/23/2021 | 30 | | µg/L | 10 |
| MNA-01 | 1,4-Dioxane | 11/23/2021 | 10000 | | µg/L | 2000 |
| MNA-01 | Benzene | 11/23/2021 | 20 | | µg/L | 10 |
| MNA-01 | cis-1,2-Dichloroethene | 11/23/2021 | 1.6 | J | µg/L | 10 |

**TABLE 4.5**
**SUMMARY OF DETECTED CONSTITUENTS**
**JULY THROUGH DECEMBER 2021 OPERATIONS AND MAINTENANCE STATUS REPORT**
**LOWRY LANDFILL SUPERFUND SITE**

| Well ID | Constituent/Parameter | Date Sampled | Result | Qualifier[a/] | Units[b/] | Reporting Limit |
|---|---|---|---|---|---|---|
| MNA-03 | 1,1-Dichloroethane | 11/23/2021 | 110 | | µg/L | 10 |
| MNA-03 | 1,4-Dioxane | 11/23/2021 | 5300 | | µg/L | 2000 |
| MNA-03 | Arsenic | 11/23/2021 | 8.9 | J | µg/L | 15 |
| MNA-03 | Benzene | 11/23/2021 | 100 | | µg/L | 10 |
| MW05-WD | 1,4-Dioxane | 8/18/2021 | 4.4 | | µg/L | 0.9 |
| MW102-WD | 1,4-Dioxane | 8/31/2021 | 1.7 | | µg/L | 0.9 |
| MW102-WD | 1,4-Dioxane | 11/18/2021 | 1.1 | | µg/L | 0.9 |
| MW103-WD | 1,4-Dioxane | 8/5/2021 | 0.45 | J | µg/L | 0.9 |
| MW103-WD | 1,4-Dioxane | 11/2/2021 | 0.41 | J | µg/L | 0.9 |
| MW105-WD | Arsenic | 10/19/2021 | 4.9 | J | µg/L | 15 |
| MW105-WD | Nitrogen, Nitrate | 10/19/2021 | 130 | J | µg/L | 500 |
| MW108-WD | Chloroform | 11/1/2021 | 0.4 | J | µg/L | 1 |
| MW108-WD | Nitrogen, Nitrate | 11/1/2021 | 9700 | | µg/L | 500 |
| MW108-WD | Nitrogen, Nitrite | 11/1/2021 | 330 | J | µg/L | 500 |
| MW113-EW-1 | 1,4-Dioxane | 7/29/2021 | 92 | | µg/L | 0.9 |
| MW113-EW-1 | 1,4-Dioxane | 10/19/2021 | 120 | | µg/L | 0.9 |
| MW113-EW-1 | Molybdenum, Dissolved | 7/29/2021 | 6600 | | µg/L | 20 |
| MW113-EW-1 | Molybdenum, Dissolved | 10/19/2021 | 3300 | | µg/L | 20 |
| MW113-EW-1 | Molybdenum, Total | 7/29/2021 | 6500 | | µg/L | 20 |
| MW113-EW-1 | Molybdenum, Total | 10/19/2021 | 3400 | | µg/L | 20 |
| MW113-EW-1 | Nitrogen, Nitrate | 7/29/2021 | 1100 | | µg/L | 500 |
| MW113-EW-1 | Nitrogen, Nitrate | 10/19/2021 | 2000 | | µg/L | 500 |
| MW113-UD | 1,4-Dioxane | 7/29/2021 | 120 | | µg/L | 0.9 |
| MW113-UD | 1,4-Dioxane | 10/19/2021 | 94 | | µg/L | 0.9 |
| MW113-UD | Molybdenum, Dissolved | 7/29/2021 | 970 | | µg/L | 20 |
| MW113-UD | Molybdenum, Dissolved | 8/25/2021 | 830 | | µg/L | 20 |
| MW113-UD | Molybdenum, Dissolved | 9/9/2021 | 730 | | µg/L | 20 |
| MW113-UD | Molybdenum, Dissolved | 10/19/2021 | 720 | | µg/L | 20 |
| MW113-UD | Molybdenum, Dissolved | 11/17/2021 | 730 | | µg/L | 20 |
| MW113-UD | Molybdenum, Dissolved | 12/15/2021 | 870 | | µg/L | 20 |
| MW113-UD | Molybdenum, Total | 7/29/2021 | 960 | | µg/L | 20 |
| MW113-UD | Molybdenum, Total | 8/25/2021 | 890 | | µg/L | 20 |
| MW113-UD | Molybdenum, Total | 9/9/2021 | 770 | | µg/L | 20 |
| MW113-UD | Molybdenum, Total | 10/19/2021 | 740 | | µg/L | 20 |
| MW113-UD | Molybdenum, Total | 11/17/2021 | 730 | | µg/L | 20 |
| MW113-UD | Molybdenum, Total | 12/15/2021 | 900 | | µg/L | 20 |
| MW113-WD | Molybdenum, Dissolved | 7/13/2021 | 18000 | | µg/L | 20 |
| MW113-WD | Molybdenum, Dissolved | 7/29/2021 | 15000 | | µg/L | 20 |
| MW113-WD | Molybdenum, Dissolved | 8/11/2021 | 14000 | | µg/L | 20 |
| MW113-WD | Molybdenum, Dissolved | 8/25/2021 | 8700 | | µg/L | 20 |
| MW113-WD | Molybdenum, Dissolved | 9/8/2021 | 2400 | | µg/L | 20 |
| MW113-WD | Molybdenum, Dissolved | 9/23/2021 | 1600 | | µg/L | 20 |
| MW113-WD | Molybdenum, Dissolved | 10/5/2021 | 2900 | | µg/L | 20 |
| MW113-WD | Molybdenum, Dissolved | 10/19/2021 | 3500 | | µg/L | 20 |
| MW113-WD | Molybdenum, Dissolved | 11/2/2021 | 5500 | | µg/L | 20 |
| MW113-WD | Molybdenum, Dissolved | 11/17/2021 | 12000 | | µg/L | 20 |

**TABLE 4.5**
**SUMMARY OF DETECTED CONSTITUENTS**
**JULY THROUGH DECEMBER 2021 OPERATIONS AND MAINTENANCE STATUS REPORT**
**LOWRY LANDFILL SUPERFUND SITE**

| Well ID | Constituent/Parameter | Date Sampled | Result | Qualifier[a/] | Units[b/] | Reporting Limit |
|---|---|---|---|---|---|---|
| MW113-WD | Molybdenum, Dissolved | 11/30/2021 | 15000 | | µg/L | 20 |
| MW113-WD | Molybdenum, Dissolved | 12/15/2021 | 20000 | | µg/L | 200 |
| MW113-WD | Molybdenum, Dissolved | 12/28/2021 | 19000 | | µg/L | 20 |
| MW113-WD | Molybdenum, Total | 7/13/2021 | 18000 | | µg/L | 20 |
| MW113-WD | Molybdenum, Total | 7/29/2021 | 15000 | | µg/L | 20 |
| MW113-WD | Molybdenum, Total | 8/11/2021 | 13000 | | µg/L | 20 |
| MW113-WD | Molybdenum, Total | 8/25/2021 | 8800 | | µg/L | 20 |
| MW113-WD | Molybdenum, Total | 9/8/2021 | 2400 | | µg/L | 20 |
| MW113-WD | Molybdenum, Total | 9/23/2021 | 1600 | | µg/L | 20 |
| MW113-WD | Molybdenum, Total | 10/5/2021 | 2800 | | µg/L | 20 |
| MW113-WD | Molybdenum, Total | 10/19/2021 | 3500 | | µg/L | 20 |
| MW113-WD | Molybdenum, Total | 11/2/2021 | 5500 | | µg/L | 20 |
| MW113-WD | Molybdenum, Total | 11/17/2021 | 12000 | | µg/L | 20 |
| MW113-WD | Molybdenum, Total | 11/30/2021 | 15000 | | µg/L | 20 |
| MW113-WD | Molybdenum, Total | 12/15/2021 | 20000 | | µg/L | 200 |
| MW113-WD | Molybdenum, Total | 12/28/2021 | 19000 | | µg/L | 20 |
| MW114-WD | 1,4-Dioxane | 8/5/2021 | 0.93 | | µg/L | 0.9 |
| MW114-WD | 1,4-Dioxane | 11/17/2021 | 0.96 | | µg/L | 0.9 |
| MW117-WD | 1,4-Dioxane | 8/5/2021 | 1.8 | | µg/L | 0.9 |
| MW117-WD | 1,4-Dioxane | 11/17/2021 | 1.5 | | µg/L | 0.9 |
| MW118-WD | 1,4-Dioxane | 8/9/2021 | 0.28 | J | µg/L | 0.9 |
| MW118-WD | 1,4-Dioxane | 11/17/2021 | 0.26 | J | µg/L | 0.9 |
| MW121-WDR | 1,4-Dioxane | 8/18/2021 | 2 | | µg/L | 0.9 |
| MW122-WDR | 1,4-Dioxane | 8/18/2021 | 2 | | µg/L | 0.9 |
| MW123-WD | 1,4-Dioxane | 8/18/2021 | 1.5 | | µg/L | 0.9 |
| MW124-WD | 1,4-Dioxane | 8/18/2021 | 0.49 | J | µg/L | 0.9 |
| MW125-WD | 1,4-Dioxane | 8/30/2021 | 0.41 | J | µg/L | 0.9 |
| MW129-WD | 1,4-Dioxane | 9/7/2021 | 5.3 | | µg/L | 0.9 |
| MW132-WD | 1,4-Dioxane | 7/21/2021 | 11 | | µg/L | 0.9 |
| MW132-WD | 1,4-Dioxane | 11/2/2021 | 14 | | µg/L | 0.9 |
| MW135-WD | 1,4-Dioxane | 7/28/2021 | 4.5 | | µg/L | 0.9 |
| MW141-WD | 1,4-Dioxane | 7/28/2021 | 2.3 | | µg/L | 0.9 |
| MW142-WD | 1,4-Dioxane | 7/28/2021 | 1.7 | | µg/L | 0.9 |
| MW151-WD | 1,4-Dioxane | 7/19/2021 | 1.7 | | µg/L | 0.9 |
| MW151-WD | 1,4-Dioxane | 11/11/2021 | 5.1 | | µg/L | 0.9 |
| MW153-EW-1 | 1,4-Dioxane | 7/21/2021 | 1.5 | | µg/L | 0.9 |
| MW153-EW-1 | 1,4-Dioxane | 11/8/2021 | 2 | | µg/L | 0.9 |
| MW154-EW-1 | 1,4-Dioxane | 7/21/2021 | 1.2 | | µg/L | 0.9 |
| MW154-EW-1 | 1,4-Dioxane | 11/11/2021 | 0.63 | J | µg/L | 0.9 |
| MW155-EW-1 | 1,4-Dioxane | 7/21/2021 | 1.1 | | µg/L | 0.9 |
| MW155-EW-1 | 1,4-Dioxane | 11/22/2021 | 0.27 | J | µg/L | 0.9 |
| MW156-EW-1 | 1,4-Dioxane | 7/21/2021 | 1.1 | | µg/L | 0.9 |
| MW156-EW-1 | 1,4-Dioxane | 11/22/2021 | 0.48 | J | µg/L | 0.9 |
| MW156-WD | 1,4-Dioxane | 7/19/2021 | 0.88 | J | µg/L | 0.9 |
| MW156-WD | 1,4-Dioxane | 11/11/2021 | 0.25 | J | µg/L | 0.9 |
| MW157-WD | 1,4-Dioxane | 7/19/2021 | 0.19 | J | µg/L | 0.9 |

**TABLE 4.5**
**SUMMARY OF DETECTED CONSTITUENTS**
**JULY THROUGH DECEMBER 2021 OPERATIONS AND MAINTENANCE STATUS REPORT**
**LOWRY LANDFILL SUPERFUND SITE**

| Well ID | Constituent/Parameter | Date Sampled | Result | Qualifier[a/] | Units[b/] | Reporting Limit |
|---|---|---|---|---|---|---|
| MW157-WD | 1,4-Dioxane | 11/11/2021 | 0.1 | J | µg/L | 0.9 |
| MW160-WD | 1,4-Dioxane | 7/19/2021 | 2.3 | | µg/L | 0.9 |
| MW160-WD | 1,4-Dioxane | 11/8/2021 | 3.3 | | µg/L | 0.9 |
| MW170-EW-1 | 1,1,1-Trichloroethane | 8/9/2021 | 1.8 | | µg/L | 1 |
| MW170-EW-1 | 1,1,1-Trichloroethane | 10/27/2021 | 2 | | µg/L | 1 |
| MW170-EW-1 | 1,1-Dichloroethane | 8/9/2021 | 4 | | µg/L | 1 |
| MW170-EW-1 | 1,1-Dichloroethane | 10/27/2021 | 4.6 | | µg/L | 1 |
| MW170-EW-1 | 1,1-Dichloroethene | 8/9/2021 | 2.8 | | µg/L | 1 |
| MW170-EW-1 | 1,1-Dichloroethene | 10/27/2021 | 3.4 | | µg/L | 1 |
| MW170-EW-1 | 1,4-Dioxane | 8/9/2021 | 14 | | µg/L | 0.9 |
| MW170-EW-1 | 1,4-Dioxane | 10/27/2021 | 12 | | µg/L | 0.9 |
| MW170-EW-1 | cis-1,2-Dichloroethene | 8/9/2021 | 9.5 | | µg/L | 1 |
| MW170-EW-1 | cis-1,2-Dichloroethene | 10/27/2021 | 11 | | µg/L | 1 |
| MW170-EW-1 | Molybdenum, Dissolved | 8/9/2021 | 2 | J | µg/L | 20 |
| MW170-EW-1 | Molybdenum, Total | 8/9/2021 | 4.5 | J | µg/L | 20 |
| MW170-EW-1 | Molybdenum, Total | 10/27/2021 | 6.3 | J | µg/L | 20 |
| MW170-EW-1 | Nitrogen, Nitrate | 8/9/2021 | 9800 | | µg/L | 500 |
| MW170-EW-1 | Nitrogen, Nitrate | 10/27/2021 | 9900 | | µg/L | 500 |
| MW170-EW-1 | Tetrachloroethene | 8/9/2021 | 1 | | µg/L | 1 |
| MW170-EW-1 | Tetrachloroethene | 10/27/2021 | 0.93 | J | µg/L | 1 |
| MW170-EW-1 | Trichloroethene | 8/9/2021 | 0.45 | J | µg/L | 1 |
| MW170-EW-1 | Trichloroethene | 10/27/2021 | 0.33 | J | µg/L | 1 |
| MW176-DEN | 1,4-Dioxane | 8/4/2021 | 0.49 | J | µg/L | 0.9 |
| MW23-UPPER-C | Nitrogen, Nitrate | 10/18/2021 | 100 | J | µg/L | 500 |
| MW36-WDR | Arsenic | 11/2/2021 | 5.9 | J | µg/L | 15 |
| MW36-WDR | Cadmium | 11/2/2021 | 0.83 | J | µg/L | 5 |
| MW36-WDR | Nitrogen, Nitrate | 11/2/2021 | 19000 | | µg/L | 2500 |
| MW38-1028N-256E | 1,1-Dichloroethane | 11/10/2021 | 1.5 | | µg/L | 1 |
| MW38-1028N-256E | 1,2-Dichloroethene | 11/10/2021 | 0.45 | J | µg/L | 1 |
| MW38-1028N-256E | 1,4-Dioxane | 11/10/2021 | 2.1 | | µg/L | 0.9 |
| MW38-1028N-256E | Bromodichloromethane | 11/10/2021 | 0.37 | J | µg/L | 1 |
| MW38-1028N-256E | Chloroform | 11/10/2021 | 1.9 | | µg/L | 1 |
| MW38-1028N-256E | cis-1,2-Dichloroethene | 11/10/2021 | 0.45 | J | µg/L | 1 |
| MW38-1028N-256E | Tetrachloroethene | 11/10/2021 | 0.63 | J | µg/L | 1 |
| MW38-1028N-256E | Trichloroethene | 11/10/2021 | 0.99 | J | µg/L | 1 |
| MW38-170S-140W | 1,1-Dichloroethane | 11/9/2021 | 10 | | µg/L | 1 |
| MW38-170S-140W | 1,2-Dichloroethene | 11/9/2021 | 2.6 | | µg/L | 1 |
| MW38-170S-140W | 1,4-Dioxane | 11/9/2021 | 14 | | µg/L | 0.9 |
| MW38-170S-140W | 1,4-Dioxane | 11/9/2021 | 15 | J | µg/L | 20 |
| MW38-170S-140W | Carbon Disulfide | 11/9/2021 | 0.32 | J | µg/L | 2 |
| MW38-170S-140W | Chloroform | 11/9/2021 | 1.7 | | µg/L | 1 |
| MW38-170S-140W | cis-1,2-Dichloroethene | 11/9/2021 | 2.6 | | µg/L | 1 |
| MW38-170S-140W | Dichlorodifluoromethane | 11/9/2021 | 1.5 | J | µg/L | 2 |
| MW38-170S-140W | Tetrachloroethene | 11/9/2021 | 0.95 | J | µg/L | 1 |
| MW38-170S-140W | Tetrahydrofuran | 11/9/2021 | 51 | | µg/L | 7 |
| MW38-170S-140W | Trichloroethene | 11/9/2021 | 2.4 | | µg/L | 1 |

**TABLE 4.5**
**SUMMARY OF DETECTED CONSTITUENTS**
**JULY THROUGH DECEMBER 2021 OPERATIONS AND MAINTENANCE STATUS REPORT**
**LOWRY LANDFILL SUPERFUND SITE**

| Well ID | Constituent/Parameter | Date Sampled | Result | Qualifier[a/] | Units[b/] | Reporting Limit |
|---|---|---|---|---|---|---|
| MW38-825S-445E | 1,1-Dichloroethane | 11/8/2021 | 2200 | | µg/L | 400 |
| MW38-825S-445E | 1,1-Dichloroethene | 11/8/2021 | 420 | | µg/L | 400 |
| MW38-825S-445E | 1,2-Dichloroethane | 11/8/2021 | 36000 | | µg/L | 400 |
| MW38-825S-445E | 1,2-Dichloroethene | 11/8/2021 | 410 | | µg/L | 400 |
| MW38-825S-445E | 1,3-Dichlorobenzene | 11/8/2021 | 100 | J | µg/L | 400 |
| MW38-825S-445E | 1,4-Dichlorobenzene | 11/8/2021 | 710 | | µg/L | 400 |
| MW38-825S-445E | 1,4-Dioxane | 11/8/2021 | 2500 | | µg/L | 9 |
| MW38-825S-445E | Benzene | 11/8/2021 | 170 | J | µg/L | 400 |
| MW38-825S-445E | Chloroform | 11/8/2021 | 140 | J | µg/L | 400 |
| MW38-825S-445E | cis-1,2-Dichloroethene | 11/8/2021 | 410 | | µg/L | 400 |
| MW38-825S-445E | m-Xylene & p-Xylene | 11/8/2021 | 140 | J | µg/L | 800 |
| MW38-825S-445E | o-Xylene | 11/8/2021 | 96 | J | µg/L | 400 |
| MW38-825S-445E | Tetrahydrofuran | 11/8/2021 | 1300 | J | µg/L | 2800 |
| MW38-825S-445E | Trichloroethene | 11/8/2021 | 96 | J | µg/L | 400 |
| MW38-825S-445E | Vinyl Chloride | 11/8/2021 | 810 | | µg/L | 400 |
| MW38-825S-445E | Xylenes, Total | 11/8/2021 | 240 | J | µg/L | 800 |
| MW38-830N-230E | 1,1-Dichloroethane | 10/14/2021 | 3.5 | | µg/L | 1 |
| MW38-830N-230E | 1,4-Dioxane | 10/14/2021 | 4.6 | | µg/L | 0.9 |
| MW38-830N-230E | Bromodichloromethane | 10/14/2021 | 0.75 | J | µg/L | 1 |
| MW38-830N-230E | Chloroform | 10/14/2021 | 3.7 | | µg/L | 1 |
| MW38-830N-230E | cis-1,2-Dichloroethene | 10/14/2021 | 1.4 | | µg/L | 1 |
| MW38-830N-230E | Nitrogen, Nitrate | 10/14/2021 | 7700 | | µg/L | 500 |
| MW38-830N-230E | Trichloroethene | 10/14/2021 | 1.6 | | µg/L | 1 |
| MW43-WD | Nitrogen, Nitrate | 11/16/2021 | 8600 | | µg/L | 500 |
| MW54-WD | Nitrogen, Nitrate | 10/14/2021 | 2600 | | µg/L | 500 |
| MW62-WDR | 1,4-Dioxane | 10/27/2021 | 3.2 | | µg/L | 0.9 |
| MW62-WDR | Nitrogen, Nitrate | 10/27/2021 | 110000 | | µg/L | 25000 |
| MW62-WDR | Nitrogen, Nitrite | 10/27/2021 | 2200 | | µg/L | 500 |
| MW70-WD | 1,1-Dichloroethane | 11/9/2021 | 1.5 | | µg/L | 1 |
| MW71-WD | Nitrogen, Nitrate | 11/1/2021 | 2200 | | µg/L | 500 |
| MW71-WD | Nitrogen, Nitrite | 11/1/2021 | 150 | J | µg/L | 500 |
| MW74-WD | Nitrogen, Nitrate | 10/14/2021 | 5600 | | µg/L | 500 |
| MW77-EW-1 | 1,4-Dioxane | 8/31/2021 | 3.7 | | µg/L | 0.9 |
| MW77-EW-1 | 1,4-Dioxane | 11/18/2021 | 3 | | µg/L | 0.9 |
| MW77-EW-2 | 1,4-Dioxane | 9/14/2021 | 0.13 | J | µg/L | 0.9 |
| MW77-EW-2 | 1,4-Dioxane | 11/18/2021 | 0.12 | J | µg/L | 0.9 |
| MW77-WD | 1,1-Dichloroethane | 10/27/2021 | 0.99 | J | µg/L | 1 |
| MW77-WD | 1,1-Dichloroethene | 10/27/2021 | 1.7 | | µg/L | 1 |
| MW77-WD | 1,4-Dioxane | 10/27/2021 | 11 | | µg/L | 0.9 |
| MW77-WD | Nitrogen, Nitrate | 10/27/2021 | 12000 | | µg/L | 2500 |
| MW77-WD | Tetrachloroethene | 10/27/2021 | 1.1 | | µg/L | 1 |
| MW78-WD | Nitrogen, Nitrate | 11/1/2021 | 180 | J | µg/L | 500 |
| MW78-WD | Nitrogen, Nitrite | 11/1/2021 | 320 | J | µg/L | 500 |
| MW90-WD | Cadmium | 10/13/2021 | 0.45 | J | µg/L | 5 |
| MW90-WD | Nitrogen, Nitrate | 10/13/2021 | 840 | | µg/L | 500 |
| MW98-WD | 1,4-Dioxane | 8/31/2021 | 11 | | µg/L | 0.9 |

# TABLE 4.5
## SUMMARY OF DETECTED CONSTITUENTS
### JULY THROUGH DECEMBER 2021 OPERATIONS AND MAINTENANCE STATUS REPORT
### LOWRY LANDFILL SUPERFUND SITE

| Well ID | Constituent/Parameter | Date Sampled | Result | Qualifier[a/] | Units[b/] | Reporting Limit |
|---|---|---|---|---|---|---|
| MW98-WD | 1,4-Dioxane | 11/18/2021 | 11 | | µg/L | 0.9 |
| NBBW-IW-3 | 1,4-Dioxane | 8/5/2021 | 140 | | µg/L | 5.6 |
| NBBW-IW-3 | Molybdenum, Dissolved | 8/5/2021 | 32 | | µg/L | 20 |
| NBBW-IW-3 | Molybdenum, Total | 8/5/2021 | 33 | | µg/L | 20 |
| PM-13X | 1,1-Dichloroethane | 11/3/2021 | 22 | | µg/L | 1 |
| PM-13X | Chloroform | 11/3/2021 | 0.65 | J | µg/L | 1 |
| PM-13X | Tetrachloroethene | 11/3/2021 | 0.3 | J | µg/L | 1 |
| PM-13X | Trichloroethene | 11/3/2021 | 0.66 | J | µg/L | 1 |
| PM-14X | 1,1-Dichloroethane | 10/26/2021 | 4 | | µg/L | 1 |
| PM-14X | Chloroform | 10/26/2021 | 0.29 | J | µg/L | 1 |
| PM-14X | Nitrogen, Nitrate | 10/26/2021 | 9100 | | µg/L | 500 |
| PM-3X | 1,1-Dichloroethane | 11/3/2021 | 0.37 | J | µg/L | 1 |
| PTP-11 | Molybdenum, Dissolved | 8/26/2021 | 8 | J | µg/L | 20 |
| PTP-11 | Molybdenum, Dissolved | 11/4/2021 | 8.2 | J | µg/L | 20 |
| PTP-11 | Molybdenum, Total | 8/26/2021 | 9.4 | J | µg/L | 20 |
| PTP-11 | Molybdenum, Total | 11/4/2021 | 9.1 | J | µg/L | 20 |
| PTP-12 | 1,4-Dioxane | 11/4/2021 | 9.1 | | µg/L | 0.9 |
| PTP-12 | Molybdenum, Dissolved | 8/26/2021 | 11 | J | µg/L | 20 |
| PTP-12 | Molybdenum, Dissolved | 11/4/2021 | 11 | J | µg/L | 20 |
| PTP-12 | Molybdenum, Total | 8/26/2021 | 12 | J | µg/L | 20 |
| PTP-12 | Molybdenum, Total | 11/4/2021 | 12 | J | µg/L | 20 |
| PTP-13 | 1,4-Dioxane | 8/25/2021 | 4.8 | | µg/L | 0.9 |
| PTP-13 | 1,4-Dioxane | 11/10/2021 | 6.9 | | µg/L | 0.9 |
| PTP-13 | Molybdenum, Dissolved | 8/25/2021 | 490 | | µg/L | 20 |
| PTP-13 | Molybdenum, Dissolved | 11/10/2021 | 620 | | µg/L | 20 |
| PTP-13 | Molybdenum, Total | 8/25/2021 | 570 | | µg/L | 20 |
| PTP-13 | Molybdenum, Total | 11/10/2021 | 630 | | µg/L | 20 |
| U-518R-WD | 1,1-Dichloroethane | 10/26/2021 | 4.4 | | µg/L | 1 |
| U-518R-WD | Tetrachloroethene | 10/26/2021 | 0.38 | J | µg/L | 1 |
| U-518R-WD | Trichloroethene | 10/26/2021 | 0.8 | J | µg/L | 1 |

Shaded wells are compliance wells.

a/ Qualifiers:
- J= The analyte was analyzed for, and was positively identified, but the associated numerical value may not be consistent with the amount actually present in the environmental sample.
- J-= Same as J qualification but with an indication of negative bias in the sample concentration.
- J+= Same as J qualification but with an indication of positive bias in the sample concentration.

b/ Units
- µg/L = micrograms per liter
- pCi/L = picocuries per liter

**TABLE 4.6**
**SUMMARY OF COMPLIANCE MONITORING EVALUATIONS**
**JULY THROUGH DECEMBER 2021 OPERATIONS AND MAINTENANCE STATUS REPORT**
**LOWRY LANDFILL SUPERFUND SITE**

| Well | Compound | Date Range | | Trend[a/] | Distribution | 90% UCL[b/] | Mean | 90% LCL[c/] | Performance Standard | Compliance Decision |
|---|---|---|---|---|---|---|---|---|---|---|
| B-313 | 1,4-Dioxane | 4/16/2019 | 11/16/2021 | No trend | Normal | 17.28 | 16.5 | 15.72 | 0.9 | Out of Compliance |
| B-313 | Nitrate | 1/3/2019 | 8/12/2021 | No trend | Normal | 38613 | 33600 | 28587 | 28000 | Out of Compliance |
| B-326-UD | 1,4-Dioxane | 8/26/2019 | 10/12/2021 | Decreasing | NA[d/] | 6.13 | 5.698 | 5.267 | 0.9 | Out of Compliance |
| B-326-UD | Nitrate | 4/28/2015 | 2/4/2021 | Decreasing | NC[e/] | NC | NC | NC | 28000 | Not determined - Did not meet linear regression requirements, Potentially in compliance[f/] |
| B-326-WD | 1,4-Dioxane | 8/26/2019 | 10/12/2021 | No trend | Normal | 9.572 | 7.35 | 5.128 | 0.9 | Out of Compliance |
| BM-11X-100N | Tetrachloroethene | 4/20/2017 | 10/28/2021 | No trend | Normal | 6.437 | 6.07 | 5.703 | 5 | Out of Compliance |
| BM-11X-100N | Trichloroethene | 4/20/2017 | 10/28/2021 | Increasing | NA | 5.86 | 5.379 | 4.898 | 5 | Indeterminant[g/] |
| BM-15N6 | Nitrate | 4/25/2017 | 10/13/2021 | Decreasing | NC | NC | NC | NC | 28000 | Not determined - Did not meet linear regression requirements, Potentially out of compliance[h/] |
| GW-109 | 1,4-Dioxane | NA | NA | NC | NC | NC | NC | NC | 0.9 | Well was dry -no samples collected this period, statistical evaluation could not be performed, considered in compliance |
| GW-109 | Chloroform | NA | NA | NC | NC | NC | NC | NC | 3.5 | Well was dry -no samples collected this period, statistical evaluation could not be performed, considered in compliance |
| GW-109 | Bromodichloromethane | NA | NA | NC | NC | NC | NC | NC | 1 | Well was dry -no samples collected this period, statistical evaluation could not be performed, considered in compliance |
| MW23-C-SD | 1,4-Dioxane | 3/15/2006 | 2/18/2021 | No trend | NC | NC | NC | NC | 0.9 | Potentially in compliance[f/], 90% Nondetects - data not processed - 4th quarter 2020 results > GWPS but not verified by comfirmation sample that was non detect. |
| MW38-830N-230E | 1,4-Dioxane | 4/26/2017 | 10/14/2021 | Decreasing | NA | NC | NC | NC | 0.9 | Not determined - Did not meet linear regression requirements, Potentially out of compliance[h/] |
| MW38-830N-230E | Chloroform | 4/26/2017 | 10/14/2021 | Decreasing | NA | NC | NC | NC | 3.5 | Not determined - Did not meet linear regression requirements, Potentially out of compliance[h/] |
| MW62-WDR | 1,4-Dioxane | 10/13/2017 | 10/27/2021 | Decreasing | NA | 3.275 | 3.054 | 2.621 | 0.9 | Out of Compliance |
| MW62-WDR | Nitrate | 10/13/2017 | 10/27/2021 | No trend | Nonparametric | 123865 | 120000 | 116135 | 28000 | Out of Compliance |
| MW62-WDR | Nitrite | 10/13/2017 | 10/27/2021 | Decreasing | NA | NC | NC | NC | 1000 | Not determined - Did not meet linear regression requirements, Potentially out of compliance[h/] |
| MW77-WD | 1,4-Dioxane | 4/24/2017 | 10/27/2021 | No trend | Normal | 11.39 | 8.82 | 6.25 | 0.9 | Out of Compliance |
| MW106-UD | 1,4-Dioxane | 11/21/2006 | 8/26/2020 | Decreasing | NC | NC | NC | NC | 0.9 | Not determined - Did not meet linear regression requirements, Potentially in compliance[f/], 90% Nondetects (decreasing trend due to decreasing MDL over time). |

a/ Trend determined by Mann-Kendall trend test analysis. When there is an increasing or decreasing trend, least squares regression analysis is used to determine the UCL and LCL

b/ Upper Confidence Limit

c/ Lower Confidence Limit

d/ NA - Not applicable

e/ NC - Not calculated

f/ Potentially in compliance - a statistical determination could not be made but the preponderance of evidence (i.e., decreasing trend and recent results < performance standard) suggests the parameter is in compliance at this well.

g/ UCL above performance standard and LCL below performance standard - cannot determine potential for compliance

h/ Potentially out of compliance - a statistical determination could not be made but the preponderance of evidence (i.e., increasing trend and recent results > performance standard or all results > performance standard) suggests the parameter is out of compliance at this well.

**Note:** * Statistics performed per the 2018 GWMP

* For all other parameters for the above listed 11 wells and all 29 parameters in the other compliance monitoring wells, the maximum detection for any compound did not exceed the performance standard. Compliance statistics were not performed.

**TABLE 4.7**
**SUMMARY OF SLURRY WALL GRADIENT CALCULATIONS**
**JULY THROUGH DECEMBER 2021 OPERATIONS AND MAINTENANCE STATUS REPORT**
**LOWRY LANDFILL SUPERFUND SITE**

| Well Pair | Range of Head Differences (ft) | | Mean of Differences | 80% Lower Confidence Limit | 95% Upper Confidence Limit | Gradient | Conclusion |
|---|---|---|---|---|---|---|---|
| | Minimum | Maximum | (ft) | (ft) | (ft) | | |
| PM-1 | -2.78 | -0.31 | -1.07 | -1.38 | -0.41 | Inward Gradient exists | Wall is effective |
| PM-2 | -7.70 | -6.98 | -7.10 | -7.21 | -6.86 | Inward Gradient exists | Wall is effective |
| PM-3 | 0.47 | 0.78 | 0.67 | 0.54 | 0.95 | Outward Gradient exists | Review water quality data |
| PM-4 | -0.39 | -0.21 | -0.31 | -0.43 | -0.06 | Inward Gradient exists | Wall is effective |
| PM-5 | -1.22 | 0.03 | -0.85 | -1.06 | -0.41 | Inward Gradient exists | Wall is effective |
| PM-6 | 3.69 | 4.09 | 3.94 | 3.89 | 4.04 | Outward Gradient exists | Review water quality data |
| PM-7 | -7.44 | -6.54 | -7.10 | -7.26 | -6.77 | Inward Gradient exists | Wall is effective |
| PM-8 | -10.17 | -8.51 | -9.27 | -9.59 | -8.60 | Inward Gradient exists | Wall is effective |
| PM-9 | -10.90 | -7.77 | -9.22 | -9.64 | -8.33 | Inward Gradient exists | Wall is effective |
| PM-10 | -5.67 | -3.36 | -4.79 | -5.19 | -3.95 | Inward Gradient exists | Wall is effective |
| PM-11 | -22.03 | -20.01 | -21.45 | -21.68 | -20.95 | Inward Gradient exists | Wall is effective |
| PM-12 | -6.25 | -4.29 | -5.01 | -5.23 | -4.53 | Inward Gradient exists | Wall is effective |
| PM-13 | Not calculated | Not calculated | Not calculated | Not calculated | Not calculated | PM-13I was dry | Continue to review water quality data |
| PM-14 | 0.98 | 1.16 | 1.05 | 0.95 | 1.27 | Outward Gradient exists | Review water quality data |
| PM-15 | -13.84 | -11.87 | -12.58 | -12.78 | -12.18 | Inward Gradient exists | Wall is effective |

ft = feet

**TABLE 4.8**
**NORTH END MONITORING - NITRATE AND 1,4-DIOXANE (NEW DATA ONLY)**
**JULY THROUGH DECEMBER 2021 OPERATIONS AND MAINTENANCE STATUS REPORT**
**LOWRY LANDFILL SUPERFUND SITE**

| Section | Well ID | Sample Date | 1,4-Dioxane (µg/L)[a/] | Nitrogen, Nitrate (µg/L) | VOCs[b/] | Anions | Metals |
|---|---|---|---|---|---|---|---|
| 31 | B-313 | 8/12/2021 | | 55000 J | | | |
| 31 | B-313 | 11/16/2021 | 17 | | | | |
| 31 | B-314 | 10/27/2021 | 0.9 U | 160 J | X[c/] | X | X |
| 31 | B-321 | 8/11/2021 | | 43000 | | | |
| 31 | B-321 | 8/30/2021 | 9.7 | | | | |
| 31 | B-326-UD | 8/30/2021 | 6.1 | | | | X |
| 31 | B-326-UD | 10/12/2021 | 5 | | | | X |
| 31 | B-326-WD | 8/30/2021 | 0.77 J | | | | |
| 31 | B-326-WD | 9/27/2021 | 0.69 J | | | | |
| 31 | B-326-WD | 10/12/2021 | 200 U | 9900 | X | X | X |
| 31 | MW05-WD | 8/18/2021 | 4.4 | | | | |
| 31 | MW113-EW-1 | 7/29/2021 | 92 | 1100 | | | X |
| 31 | MW113-EW-1 | 10/19/2021 | 120 | 2000 | | | X |
| 31 | MW113-UD | 7/29/2021 | 120 | | | | X |
| 31 | MW113-UD | 10/19/2021 | 94 | | | | X |
| 31 | MW114-WD | 8/5/2021 | 0.93 | | | | |
| 31 | MW114-WD | 11/17/2021 | 0.96 | | | | |
| 31 | MW117-WD | 8/5/2021 | 1.8 | | | | |
| 31 | MW117-WD | 11/17/2021 | 1.5 | | | | |
| 31 | MW118-WD | 8/9/2021 | 0.28 J | | | | |
| 31 | MW118-WD | 11/17/2021 | 0.26 J | | | | |
| 31 | MW121-WDR | 8/18/2021 | 2 | | | | |
| 31 | MW122-WDR | 8/18/2021 | 2 | | | | |
| 31 | MW123-WD | 8/18/2021 | 1.5 | | | | |
| 31 | MW124-WD | 8/18/2021 | 0.49 J | | | | |
| 31 | MW125-WD | 8/30/2021 | 0.41 J | | | | |
| 31 | MW129-WD | 9/7/2021 | 5.3 | | | | |
| 31 | MW132-WD | 7/21/2021 | 11 | | | | |
| 31 | MW132-WD | 11/2/2021 | 14 | | | | |
| 30 | MW135-WD | 7/28/2021 | 4.5 | | | | |
| 30 | MW141-WD | 7/28/2021 | 2.3 | | | | |
| 19 | MW142-WD | 7/28/2021 | 1.7 | | | | |
| 24 | MW144-WD | 8/4/2021 | 0.9 U | | | | |
| 31 | MW151-WD | 7/19/2021 | 1.7 | | | | |
| 31 | MW151-WD | 11/11/2021 | 5.1 | | | | |
| 31 | MW153-EW-1 | 7/21/2021 | 1.5 | | | | |
| 31 | MW153-EW-1 | 11/8/2021 | 2 | | | | |
| 31 | MW154-EW-1 | 7/21/2021 | 1.2 | | | | |
| 31 | MW154-EW-1 | 11/11/2021 | 0.63 J | | | | |
| 31 | MW155-EW-1 | 7/21/2021 | 1.1 | | | | |
| 31 | MW155-EW-1 | 11/22/2021 | 0.27 J | | | | |
| 31 | MW156-EW-1 | 7/21/2021 | 1.1 | | | | |
| 31 | MW156-EW-1 | 11/22/2021 | 0.48 J | | | | |
| 31 | MW156-WD | 7/19/2021 | 0.88 J | | | | |
| 31 | MW156-WD | 11/11/2021 | 0.25 J | | | | |
| 31 | MW157-WD | 7/19/2021 | 0.19 J | | | | |
| 31 | MW157-WD | 11/11/2021 | 0.1 J | | | | |
| 31 | MW160-WD | 7/19/2021 | 2.3 | | | | |
| 31 | MW160-WD | 11/8/2021 | 3.3 | | | | |
| 13 | MW176-DEN | 8/4/2021 | 0.49 J | | | | |

**TABLE 4.8**
**NORTH END MONITORING - NITRATE AND 1,4-DIOXANE (NEW DATA ONLY)**
**JULY THROUGH DECEMBER 2021 OPERATIONS AND MAINTENANCE STATUS REPORT**
**LOWRY LANDFILL SUPERFUND SITE**

| Section | Well ID | Sample Date | 1,4-Dioxane (µg/L)[a/] | Nitrogen, Nitrate (µg/L) | VOCs[b/] | Anions | Metals |
|---|---|---|---|---|---|---|---|
| 31 | MW179-UDEN | 9/8/2021 | 0.9 U | | | | |
| 31 | NBBW-IW-3 | 8/5/2021 | 140 | | | | X |
| 31 | PTP-12 | 11/4/2021 | 9.1 | | | | X |
| 31 | PTP-13 | 8/25/2021 | 4.8 | | | | X |
| 31 | PTP-13 | 11/10/2021 | 6.9 | | | | X |

a/ µg/L = micrograms per liter

b/ VOCs = volatile organic compounds

c/ X = indicates the sample was analyzed for at least one compound within the group.

Final Q definitions:

J+ = a "J" qualifier indicating positive bias in the associated result

J=The analyte was analyzed for, and was positively identified, but the associated numerical value may not be consistent with the amount actually present in the environmental sample.

U= The analyte was analyzed for and is not present above the level of the associated value. The associated numerical value indicates the approximate concentration necessary to detect the analyte in the sample.

UJ=The analyte analyzed for was not present above the level of the associated value. The associated numerical value may not accurately represent the concentration necessary to detect the analyte in the s

**TABLE 4.9**
**NBBW & NORTH END EXTRACTION SYSTEMS - VOLUME AND MASS REMOVED**
**JULY THROUGH DECEMBER 2021 OPERATIONS AND MAINTENANCE STATUS REPORT**
**LOWRY LANDFILL SUPERFUND SITE**

| Mass Removal of 1,4-Dioxane from North End Groundwater Extraction<br>July through December 2021 (2H21) | | | |
|---|---|---|---|
| **Extraction Well** | **Volume Removed (gallons)** | **Mass (grams)** | **Mass (pounds)** |
| MW153-EW-1 | 1,094,544 | 6.78 | 0.015 |
| MW154-EW-1 | 333,360 | 1.46 | 0.003 |
| MW155-EW-1 | 450,864 | 1.75 | 0.004 |
| MW156-EW-1 | 0 | 0.00 | 0.000 |
| MW160-WD | 132,480 | 1.33 | 0.003 |
| MW118-WD | 0 | 0.00 | 0.000 |
| MW114-WD | 0 | 0.00 | 0.000 |
| MW77-EW-2 | 0 | 0.00 | 0.000 |
| MW102-WD | 237,888 | 1.43 | 0.003 |
| MW77-EW-1 | 12,442 | 0.16 | 0.000 |
| MW98-WD | 9,317 | 0.37 | 0.001 |
| MW170-EW-1 * | 3,449,808 | 176.48 | 0.389 |
| MW113-EW-1 * | 721,152 | 288.89 | 0.637 |
| MW113-UD * | 6,840 | 3.04 | 0.007 |
| B-321 * | 12,730 | 0.44 | 0.001 |
| NBBW-IW-3* | 16,618 | 7.85 | 0.017 |
| TOTAL | 6,478,042 | 489.99 | 1.080 |

| Total Mass Removal of 1,4-Dioxane from North End Groundwater Extraction<br>Cumulative through 12/31/21 | | | |
|---|---|---|---|
| **Extraction Well** | **Volume Removed (gallons)** | **Mass (grams)** | **Mass (pounds)** |
| MW153-EW-1 | 21,536,472 | 415.6 | 0.916 |
| MW154-EW-1 | 14,849,429 | 344.3 | 0.759 |
| MW155-EW-1 | 13,751,344 | 212.4 | 0.468 |
| MW156-EW-1 | 6,103,619 | 174.0 | 0.384 |
| MW160-WD | 6,082,354 | 257.5 | 0.568 |
| MW118-WD | 1,490,372 | 123.7 | 0.273 |
| MW114-WD | 805,136 | 58.4 | 0.129 |
| MW77-EW-2 | 149,192 | 8.6 | 0.019 |
| MW102-WD | 7,268,780 | 256.5 | 0.566 |
| MW77-EW-1 | 280,704 | 14.6 | 0.032 |
| MW98-WD | 754,257 | 119.1 | 0.263 |
| MW170-EW-1 * | 64,198,656 | 5381.2 | 11.864 |
| MW113-EW-1 * | 14,231,599 | 1544.1 | 3.404 |
| MW113-UD * | 161,658 | 40.8 | 0.090 |
| B-321 * | 1,777,661 | 158.4 | 0.349 |
| NBBW-IW-3* | 936,922 | 480.0 | 1.058 |
| TOTAL | 154,378,155 | 9,589.1 | 21.1 |

**TABLE 4.10**
**SUMMARY OF GTEP AREA ANALYTICAL RESULTS SINCE 2010 VOCs AND NITRATE**
**JULY THROUGH DECEMBER 2021 OPERATIONS AND MAINTENANCE STATUS REPORT**
**LOWRY LANDFILL SUPERFUND SITE**

| | | Compounds[a/] | | | | | | | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| **Well** | **Sample Date** | **PCE** | **Q[b/]** | **TCE** | **Q** | **cis-1,2-DCE** | **Q** | **1,1-DCE** | **Q** | **1,1,1-TCA** | **Q** | **1,2-DCA** | **Q** | **1,1-DCA** | **Q** | **1,4-Dioxane** | **Q** | **NO3** | **Q** |
| **Performance Standard→** | | **5** | | **5** | | **70** | | **7** | | **200** | | **5** | | **990** | | **0.9** | | **28** | |
| MW62-WDR | 7/25/2016 | 0.2 | U | 0.16 | U | 0.15 | U | 0.23 | U | 0.16 | U | 0.13 | U | 0.22 | U | 5.6 | | 130 | |
| MW62-WDR | 11/9/2016 | 0.2 | U | 0.16 | U | 0.15 | U | 0.23 | U | 0.16 | U | 0.13 | U | 0.22 | U | 4.4 | | 150 | |
| MW62-WDR | 2/7/2017 | 0.2 | U | 0.16 | U | 0.15 | U | 0.23 | U | 0.16 | U | 0.13 | U | 0.22 | U | 5.2 | | 140 | |
| MW62-WDR | 5/17/2017 | 0.2 | U | 0.16 | U | 0.15 | U | 0.23 | U | 0.16 | U | 0.13 | U | 0.22 | U | 5.3 | | 110 | |
| MW62-WDR | 8/1/2017 | 0.2 | U | 0.16 | U | 0.15 | U | 0.23 | U | 0.16 | U | 0.13 | U | 0.22 | U | 5.8 | | 110 | |
| MW62-WDR | 10/13/2017 | 0.2 | U | 0.16 | U | 0.15 | U | 0.23 | U | 0.16 | U | 0.13 | U | 0.22 | U | 4.6 | | 120 | |
| MW62-WDR | 3/7/2018 | 0.2 | U | 0.16 | U | 0.15 | U | 0.23 | U | 0.16 | U | 0.13 | U | 0.22 | U | 3.9 | | 110 | |
| MW62-WDR | 5/10/2018 | 0.2 | U | 0.16 | U | 0.15 | U | 0.23 | U | 0.16 | U | 0.13 | U | 0.22 | U | 4.2 | | 120 | |
| MW62-WDR | 7/31/2018 | 0.2 | U | 0.16 | U | 0.15 | U | 0.23 | U | 0.16 | U | 0.13 | U | 0.22 | U | 3.8 | | 120 | |
| MW62-WDR | 5/14/2019 | 0.2 | U | 0.16 | U | 0.15 | U | 0.23 | U | 0.16 | U | 0.13 | U | 0.22 | U | 3.9 | | 120 | |
| MW62-WDR | 12/17/2019 | 0.2 | U | 0.16 | U | 0.15 | U | 0.23 | U | 0.16 | U | 0.13 | U | 0.22 | U | 3.5 | | 120 | |
| MW62-WDR | 5/14/2020 | 0.2 | U | 0.16 | U | 0.15 | U | 0.23 | U | 0.16 | U | 0.13 | U | 0.22 | U | 3.4 | | 130 | |
| MW62-WDR | 11/11/2020 | 0.2 | U | 0.16 | U | 0.15 | U | 0.23 | U | 0.16 | U | 0.13 | U | 0.22 | U | 3.4 | | 130 | J |
| MW62-WDR | 4/27/2021 | 0.2 | U | 0.16 | U | 0.15 | U | 0.23 | U | 0.16 | U | 0.13 | U | 0.22 | U | 3.3 | | 120 | |
| MW62-WDR | 10/27/2021 | 0.2 | U | 0.16 | U | 0.15 | U | 0.23 | U | 0.16 | U | 0.13 | U | 0.22 | U | 3.2 | | 110 | |
| B-323-WD | 3/4/2011 | 1.5 | | 0.85 | J | 0.98 | J | 2.5 | | 2.2 | | 0.13 | U | 3.7 | | 53 | | | |
| MW170-WD | 3/7/2011 | 5.4 | | 2.1 | | 3.8 | | 11 | | 6.9 | | 0.13 | U | 8.3 | | 72 | | | |
| MW170-EW-1 | 1/5/2012 | 11 | | 3.6 | | 8 | | 26 | | 11 | | 0.55 | J | 15 | | 150 | | 110 | |
| MW170-EW-1 | 8/22/2012 | 5 | | 2 | | 3.4 | | 11 | | 2.7 | | 0.33 | J | 10 | | 77 | | 33 | |
| MW170-EW-1 | 9/19/2012 | 4.5 | | 2.2 | | 3 | | 11 | | 3.1 | | 0.35 | J | 9.3 | | 72 | | 27 | |
| MW170-EW-1 | 10/22/2012 | 4.3 | | 1.5 | | 2.2 | | 9.2 | | 2 | | 0.19 | J | 6.2 | | 56 | | 24 | |
| MW170-EW-1 | 11/13/2012 | 3.8 | | 1.5 | | 2.2 | | 8.7 | | 1.9 | | 0.13 | U | 5.9 | | 46 | | 19 | |
| MW170-EW-1 | 12/10/2012 | 4.2 | | 1.6 | | 2 | | 8 | | 2.1 | | 0.13 | U | 6.2 | | 40 | | 17 | |
| MW170-EW-1 | 1/30/2013 | 5.2 | | 1.8 | | 1.9 | | 11 | | 2.7 | | 0.17 | J | 6.9 | | 45 | | 13 | |
| MW170-EW-1 | 2/20/2013 | 5.4 | | 2.4 | | 3.2 | | 14 | | 3.1 | | 0.13 | U | 10 | | 71 | | 12 | |
| MW170-EW-1 | 3/14/2013 | 8.3 | | 3.5 | | 4.6 | | 21 | | 4 | | 0.34 | J | 15 | | 79 | | 8.8 | |
| MW170-EW-1 | 4/22/2013 | 5.8 | | 2.2 | | 2.5 | | 11 | | 1.6 | | 0.13 | J | 7.9 | | 64 | | 5.5 | |
| MW170-EW-1 | 5/15/2013 | 5.2 | | 2.1 | | 2.7 | | 9 | | 1.6 | | 0.13 | U | 8.1 | | 50 | | 5.5 | |
| MW170-EW-1 | 6/17/2013 | 4.9 | | 1.9 | | 2.7 | | 8 | | 1.6 | | 0.13 | U | 6.5 | | 39 | | 5.3 | |
| MW170-EW-1 | 7/29/2013 | 4 | | 1.4 | | 2.1 | | 6.2 | | 1.2 | | 0.13 | U | 5.1 | | 32 | | 5.3 | |
| MW170-EW-1 | 8/21/2013 | 4.8 | | 1.5 | | 2 | | 6.8 | | 1.7 | | 0.13 | U | 5.4 | | 29 | | 5 | |
| MW170-EW-1 | 9/18/2013 | 3.3 | | 1.1 | | 1.6 | | 4.4 | | 0.93 | | 0.13 | U | 3.7 | | 32 | | 5.3 | |
| MW170-EW-1 | 11/11/2013 | 2.7 | | 1.1 | | 1.4 | | 4.6 | | 1 | | 0.13 | U | 3.7 | | 27 | | 5.8 | |
| MW170-EW-1 | 2/20/2014 | 1.7 | | 0.64 | J | 0.8 | J | 2.5 | | 0.72 | J | 0.13 | U | 2.6 | | 15 | | 5.1 | |
| MW170-EW-1 | 5/28/2014 | 2.1 | | 0.87 | J | 1 | | 3.2 | | 0.88 | J | 0.13 | U | 3.1 | | 18 | | 6.2 | |
| MW170-EW-1 | 9/4/2014 | 2.3 | | 0.86 | J | 1.9 | | 4.3 | | 1.1 | | 0.13 | U | 3.1 | | 22 | | 14 | |
| MW170-EW-1 | 12/3/2014 | 1.5 | | 0.56 | J | 2 | | 3.1 | | 1.1 | | 0.13 | U | 2.6 | | 17 | | 13 | |
| MW170-EW-1 | 3/5/2015 | 1.7 | | 0.59 | J | 2.3 | | 2.9 | | 1.3 | | 0.13 | U | 2.2 | | 12 | | 14 | |
| MW170-EW-1 | 6/18/2015 | 1.2 | | 0.4 | J | 1.9 | | 2.3 | | 1.2 | | 0.13 | U | 1.9 | | 9.9 | | 19 | |

**TABLE 4.10**
**SUMMARY OF GTEP AREA ANALYTICAL RESULTS SINCE 2010 VOCs AND NITRATE**
**JULY THROUGH DECEMBER 2021 OPERATIONS AND MAINTENANCE STATUS REPORT**
**LOWRY LANDFILL SUPERFUND SITE**

| | | Compounds[a/] | | | | | | | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| **Well** | **Sample Date** | **PCE** | **Q[b/]** | **TCE** | **Q** | **cis-1,2-DCE** | **Q** | **1,1-DCE** | **Q** | **1,1,1-TCA** | **Q** | **1,2-DCA** | **Q** | **1,1-DCA** | **Q** | **1,4-Dioxane** | **Q** | **NO3** | **Q** |
| **Performance Standard→** | | **5** | | **5** | | **70** | | **7** | | **200** | | **5** | | **990** | | **0.9** | | **28** | |
| MW170-EW-1 | 9/16/2015 | 1.1 | | 0.43 | J | 1.4 | | 1.8 | | 0.98 | J | 0.13 | U | 1.6 | | 8.8 | | 22 | |
| MW170-EW-1 | 12/10/2015 | 0.87 | J | 0.3 | J | 0.82 | J | 1.1 | | 0.49 | J | 0.13 | U | 0.99 | J | 6.7 | | 22 | |
| MW170-EW-1 | 2/24/2016 | 0.76 | J | 0.23 | J | 0.8 | J | 0.94 | J | 0.48 | J | 0.13 | U | 0.82 | J | 5.3 | | 18 | |
| MW170-EW-1 | 6/23/2016 | 0.7 | J | 0.26 | J | 1.4 | | 1.3 | | 0.73 | J | 0.13 | U | 1.2 | | 6 | | 24 | |
| MW170-EW-1 | 12/19/2016 | 0.56 | J | 0.19 | J | 0.69 | J | 0.79 | J | 0.42 | J | 0.13 | U | 0.69 | J | 3.9 | | 21 | |
| MW170-EW-1 | 3/13/2017 | 0.74 | J | 0.29 | J | 1.3 | | 1.3 | | 0.77 | J | 0.13 | U | 1.2 | | 3.7 | | 18 | |
| MW170-EW-1 | 6/26/2017 | 0.61 | J | 0.21 | J | 0.98 | J | 1.2 | | 0.55 | J | 0.13 | U | 0.92 | J | 4.6 | | 15 | |
| MW170-EW-1 | 9/11/2017 | 0.76 | J | 0.21 | J | 1.2 | | 1.3 | | 0.73 | J | 0.13 | U | 1.1 | | 4.7 | | 13 | |
| MW170-EW-1 | 12/4/2017 | 0.67 | J | 0.26 | J | 2.7 | | 1.6 | | 0.98 | J | 0.13 | U | 1.4 | | 5.5 | | 11 | |
| MW170-EW-1 | 3/7/2018 | 0.78 | J | 0.3 | J | 5.6 | | 2.1 | | 1.9 | | 0.13 | U | 2.8 | | 8.6 | | 19 | |
| MW170-EW-1 | 6/11/2018 | 1.3 | | 0.53 | J | 17 | | 5.4 | | 5.1 | | 0.16 | J | 6.8 | | 15 | | 12 | |
| MW170-EW-1 | 9/5/2018 | 1.4 | | 0.5 | J | 14 | | 4.3 | | 4.3 | | 0.13 | U | 5.6 | | 17 | | 8.7 | |
| MW170-EW-1 | 11/19/2018 | 1.7 | | 0.65 | J | 17 | | 5.5 | | 5.5 | | 0.2 | J | 7.1 | | 20 | | 7.7 | |
| MW170-EW-1 | 2/8/2019 | 1.1 | | 0.44 | J | 13 | | 3.4 | | 3.4 | | 0.13 | U | 5.3 | | 16 | | 8.8 | |
| MW170-EW-1 | 3/18/2019 | 1.6 | | 0.63 | J | 13 | | 4.4 | | 3.1 | | 0.13 | U | 5.6 | | 18 | | 8 | |
| MW170-EW-1 | 4/18/2019 | 1.2 | | 0.52 | J | 10 | | 2.7 | | 2.9 | | 0.13 | U | 4.4 | | 15 | | 7.8 | |
| MW170-EW-1 | 5/17/2019 | 1.2 | | 0.49 | J | 10 | | 2.8 | | 2.8 | | 0.13 | U | 4.6 | | 15 | | 8.4 | |
| MW170-EW-1 | 6/14/2019 | 1 | | 0.42 | J | 11 | | 3.5 | | 2.2 | | 0.13 | U | 4 | | 15 | | 8.9 | |
| MW170-EW-1 | 7/17/2019 | 1.4 | | 0.62 | J | 14 | | 4.7 | | 3.8 | | 0.13 | U | 6 | | 30 | J | 7.8 | |
| MW170-EW-1 | 8/19/2019 | 1.6 | | 0.73 | J | 15 | | 4.7 | | 3.7 | | 0.13 | U | 6.3 | | 29 | J | 7.5 | |
| MW170-EW-1 | 9/17/2019 | 1.1 | | 0.43 | J | 12 | | 3.5 | | 2.5 | | 0.13 | U | 4.8 | | 17 | | 7.4 | |
| MW170-EW-1 | 10/15/2019 | 1.3 | | 0.51 | J | 13 | | 2.8 | | 3.2 | | 0.13 | U | 5.6 | | 18 | | 7.7 | |
| MW170-EW-1 | 11/12/2019 | 1.2 | | 0.48 | J | 12 | | 3.4 | | 2.6 | | 0.13 | U | 4.8 | | 19 | | 7.8 | |
| MW170-EW-1 | 12/10/2019 | 1.6 | | 0.62 | J | 15 | | 5 | | 3.6 | | 0.13 | U | 6.5 | | 21 | | 8.3 | |
| MW170-EW-1 | 2/11/2020 | 1.3 | | 0.5 | J | 13 | | 4.3 | | 2.8 | | 0.14 | J | 5.1 | | 18 | | 8.1 | |
| MW170-EW-1 | 5/12/2020 | 1.4 | | 0.48 | J | 13 | | 4.1 | | 3.2 | | 0.13 | U | 5.6 | | 16 | | 8.7 | |
| MW170-EW-1 | 8/10/2020 | 1.1 | | 0.42 | J | 11 | | 3.7 | | 2.4 | | 0.28 | J | 4.9 | | 19 | U | 9.2 | |
| MW170-EW-1 | 8/20/2020 | | | | | | | | | | | | | | | 16 | | | |
| MW170-EW-1 | 11/10/2020 | 1.6 | | 0.64 | J | 12 | | 3.6 | | 2.6 | | 0.13 | U | 4.7 | | 16 | | 8.8 | |
| MW170-EW-1 | 2/4/2021 | 1.1 | | 0.35 | J | 12 | | 3.7 | | 2.6 | | 0.13 | U | 5.1 | | 16 | | 9.2 | |
| MW170-EW-1 | 5/12/2021 | 0.95 | J | 0.38 | J | 9.8 | | 2.8 | | 1.8 | | 0.13 | U | 4.1 | | 15 | | 11 | J |
| MW170-EW-1 | 8/9/2021 | 1 | | 0.45 | J | 9.5 | | 2.8 | | 1.8 | | 0.13 | U | 4 | | 14 | | 9.8 | |
| MW170-EW-1 | 10/27/2021 | 0.93 | J | 0.33 | J | 11 | | 3.4 | | 2 | | 0.13 | U | 4.6 | | 12 | | 9.9 | |
| MW171-WD | 3/3/2011 | 1 | | 0.65 | J | 0.36 | J | 2.1 | | 1.1 | | 0.13 | U | 2.8 | | 21 | | | |
| MW171-WD | 1/4/2012 | 0.2 | U | 0.16 | U | 0.15 | U | 0.64 | J | 0.16 | U | 0.13 | U | 0.77 | J | 6.6 | | 18 | |
| MW171-WD | 8/28/2012 | 0.3 | J | 0.21 | J | 0.15 | U | 0.71 | J | 0.24 | J | 0.13 | U | 0.93 | J | 8.4 | | 15 | |
| MW171-WD | 1/31/2013 | 0.25 | J | 0.18 | J | 0.15 | U | 0.63 | J | 0.25 | J | 0.13 | U | 0.82 | J | 9.5 | | 16 | |
| MW171-WD | 8/21/2018 | 0.2 | U | 0.16 | U | 0.15 | U | 0.23 | U | 0.16 | U | 0.13 | U | 0.22 | U | 3 | | 10 | |

**TABLE 4.10**
**SUMMARY OF GTEP AREA ANALYTICAL RESULTS SINCE 2010 VOCs AND NITRATE**
**JULY THROUGH DECEMBER 2021 OPERATIONS AND MAINTENANCE STATUS REPORT**
**LOWRY LANDFILL SUPERFUND SITE**

| | | Compounds[a/] | | | | | | | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| **Well** | **Sample Date** | **PCE** | **Q[b/]** | **TCE** | **Q** | **cis-1,2-DCE** | **Q** | **1,1-DCE** | **Q** | **1,1,1-TCA** | **Q** | **1,2-DCA** | **Q** | **1,1-DCA** | **Q** | **1,4-Dioxane** | **Q** | **NO3** | **Q** |
| **Performance Standard→** | | **5** | | **5** | | **70** | | **7** | | **200** | | **5** | | **990** | | **0.9** | | **28** | |
| MW172-WD | 3/1/2011 | 1.7 | | 0.83 | J | 0.86 | J | 6 | | 1.3 | | 0.13 | U | 6 | | 51 | | | |
| MW172-WD | 1/4/2012 | 2.3 | | 1.2 | | 0.95 | J | 4.9 | | 0.94 | J | 0.13 | U | 5.8 | | 68 | | 28 | |
| MW172-WD | 8/28/2012 | 0.2 | U | 0.16 | U | 0.15 | U | 0.23 | U | 0.16 | U | 0.13 | U | 0.22 | U | 0.82 | J | 1.3 | |
| MW172-WD | 1/30/2013 | 0.62 | J | 0.26 | J | 0.15 | U | 1.1 | | 0.26 | J | 0.13 | U | 1 | | 16 | | 8.1 | |
| MW172-WD | 9/19/2018 | 0.2 | U | 0.16 | U | 0.15 | U | 0.23 | U | 0.16 | U | 0.13 | U | 0.22 | U | 0.6 | J | 2.1 | |
| MW173-WD | 3/1/2011 | 0.2 | U | 0.16 | U | 0.15 | U | 0.23 | U | 0.16 | U | 0.13 | U | 0.22 | U | 0.5 | U | | |
| MW173-WD | 8/24/2018 | 0.2 | U | 0.16 | U | 0.15 | U | 0.23 | U | 0.16 | U | 0.13 | U | 0.22 | U | 0.15 | U | | |
| MW174-WD | 1/5/2012 | 0.2 | U | 0.16 | U | 0.15 | U | 0.23 | U | 0.16 | U | 0.13 | U | 0.22 | U | 0.5 | U | 10 | |
| MW174-WD | 9/6/2012 | 0.2 | U | 0.16 | U | 0.15 | U | 0.23 | U | 0.16 | U | 0.13 | U | 0.22 | U | 0.5 | U | 6.7 | |
| MW174-WD | 2/5/2013 | 0.2 | U | 0.16 | U | 0.15 | U | 0.23 | U | 0.16 | U | 0.13 | U | 0.22 | U | 0.5 | U | 5.3 | |
| MW174-WD | 9/25/2018 | 0.2 | U | 0.16 | U | 0.15 | U | 0.23 | U | 0.16 | U | 0.13 | U | 0.22 | U | 0.15 | U | 2.9 | |
| MW175-WD | 1/5/2012 | 3.5 | | 2.1 | | 3.5 | | 13 | | 0.42 | J | 0.27 | J | 12 | | 76 | | 62 | |
| MW175-WD | 9/6/2012 | 0.2 | J | 0.16 | U | 0.15 | U | 0.46 | J | 0.33 | J | 0.13 | U | 0.22 | U | 2.4 | J | 35 | |
| MW175-WD | 2/5/2013 | 0.2 | | 0.47 | J | 0.61 | J | 2.3 | | 0.24 | J | 0.13 | U | 2 | | 15 | | 19 | |
| MW175-WD | 9/19/2018 | 0.2 | | 0.16 | U | 0.15 | U | 0.23 | U | 0.16 | U | 0.13 | U | 0.22 | U | 0.53 | J | 28 | |
| MW77-WD | 12/19/2003 | 6.2 | | 2.6 | | 1.5 | | 11 | | 11 | | 0.32 | J | 11 | | 85 | J | 68 | |
| MW77-WD | 1/21/2004 | 6.7 | | 2.9 | | 1.6 | | 12 | | 11 | | 0.13 | U | 11 | | 76 | J | | |
| MW77-WD | 5/26/2010 | 3.3 | | 1.2 | | 0.82 | J | 7 | | 2.8 | | 0.13 | U | 4.7 | | 45 | | 160 | |
| MW77-WD | 11/18/2010 | 2.3 | | 0.9 | J | 0.66 | J | 4.2 | | 1.7 | | 0.13 | U | 3.5 | | 37 | | 120 | |
| MW77-WD | 3/2/2011 | 3 | | 1.1 | | 0.82 | J | 5.8 | | 2 | | 0.13 | U | 4.7 | | 41 | | | |
| MW77-WD | 5/25/2011 | 4.6 | | 2 | | 1.3 | | 10 | | 3.5 | | 0.13 | U | 7.2 | | 61 | | 170 | |
| MW77-WD | 11/15/2011 | 2.8 | | 1.1 | | 0.89 | J | 5.1 | | 1.6 | | 0.13 | U | 4.3 | | 41 | | 130 | |
| MW77-WD | 5/24/2012 | 1.6 | | 0.46 | J | 0.15 | U | 2.1 | | 0.76 | J | 0.13 | U | 1.6 | | 23 | | 42 | |
| MW77-WD | 11/8/2012 | 2.2 | | 0.68 | J | 0.37 | J | 1.9 | | 0.92 | J | 0.13 | U | 1.9 | | 29 | | 46 | |
| MW77-WD | 5/8/2013 | 2.1 | | 0.55 | J | 0.22 | J | 1.9 | | 0.67 | J | 0.13 | U | 1.3 | | 27 | | 65 | |
| MW77-WD | 11/12/2013 | 0.8 | | 0.21 | J | 0.15 | U | 0.56 | J | 0.32 | J | 0.13 | U | 0.67 | J | 11 | | 74 | |
| MW77-WD | 4/29/2014 | 1.6 | | 1.49 | J | 0.17 | J | 1.4 | | 0.58 | J | 0.13 | U | 1.1 | | 23 | | 63 | |
| MW77-WD | 11/18/2014 | 0.74 | J | 0.24 | J | 0.15 | U | 0.93 | J | 0.3 | J | 0.13 | U | 0.54 | J | 7.7 | | 59 | |
| MW77-WD | 4/23/2015 | 0.57 | J | 0.16 | U | 0.15 | U | 0.37 | J | 0.17 | J | 0.13 | U | 0.28 | J | 5.8 | | 53 | |
| MW77-WD | 11/12/2015 | 1.4 | | 0.42 | J | 0.16 | J | 1.7 | | 0.5 | J | 0.13 | U | 1.2 | | 15 | | 23 | |
| MW77-WD | 5/16/2016 | 0.36 | J | 0.16 | U | 0.15 | U | 0.24 | J | 0.16 | U | 0.13 | U | 0.22 | U | 3.5 | | 35 | |
| MW77-WD | 10/31/2016 | 1.4 | | 0.38 | J | 0.16 | J | 1.5 | | 0.32 | J | 0.13 | U | 1 | | 14 | | 16 | |
| MW77-WD | 4/24/2017 | 1.3 | | 0.51 | J | 0.19 | J | 1.9 | | 0.44 | J | 0.13 | U | 1.7 | | 20 | | 24 | |
| MW77-WD | 10/26/2017 | 0.61 | J | 0.17 | J | 0.15 | U | 0.52 | J | 0.16 | U | 0.13 | U | 0.36 | J | 5.3 | | 27 | |
| MW77-WD | 5/3/2018 | 0.98 | J | 0.22 | J | 0.15 | U | 0.75 | J | 0.16 | U | 0.13 | U | 0.51 | J | 9 | | 26 | |
| MW77-WD | 8/2/2018 | 0.27 | J | 0.16 | U | 0.15 | U | 0.23 | U | 0.16 | U | 0.13 | U | 0.22 | U | 2.6 | | 9.7 | |
| MW77-WD | 5/2/2019 | 0.48 | J | 0.16 | U | 0.15 | U | 0.26 | J | 0.16 | U | 0.13 | U | 0.22 | U | 3 | | 17 | |
| MW77-WD | 10/22/2019 | 1.3 | | 0.18 | J | 0.15 | U | 1.7 | | 0.16 | U | 0.28 | J | 0.91 | J | 12 | | 17 | |
| MW77-WD | 5/4/2020 | 0.61 | J | 0.18 | J | 0.15 | U | 0.43 | J | 0.16 | U | 0.13 | U | 0.22 | U | 5 | | 18 | |

**TABLE 4.10**
**SUMMARY OF GTEP AREA ANALYTICAL RESULTS SINCE 2010 VOCs AND NITRATE**
**JULY THROUGH DECEMBER 2021 OPERATIONS AND MAINTENANCE STATUS REPORT**
**LOWRY LANDFILL SUPERFUND SITE**

| | | Compounds[a/] | | | | | | | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| **Well** | **Sample Date** | **PCE** | **Q[b/]** | **TCE** | **Q** | **cis-1,2-DCE** | **Q** | **1,1-DCE** | **Q** | **1,1,1-TCA** | **Q** | **1,2-DCA** | **Q** | **1,1-DCA** | **Q** | **1,4-Dioxane** | **Q** | **NO3** | **Q** |
| **Performance Standard→** | | **5** | | **5** | | **70** | | **7** | | **200** | | **5** | | **990** | | **0.9** | | **28** | |
| MW77-WD | 10/28/2020 | 1.7 | | 0.47 | J | 0.15 | U | 2.1 | | 0.31 | J | 0.13 | U | 1.1 | | 16 | | 12 | |
| MW77-WD | 4/21/2021 | 0.56 | J | 0.16 | U | 0.15 | U | 0.52 | J | 0.16 | U | 0.13 | U | 0.22 | U | 4.3 | | 15 | |
| MW77-WD | 10/27/2021 | 1.1 | | 0.16 | U | 0.15 | U | 1.7 | | 0.16 | U | 0.13 | U | 0.99 | J | 11 | | 12 | |
| MW98-WD | 3/8/2010 | | | | | | | | | | | | | | | 44 | | | |
| MW98-WD | 6/10/2010 | | | | | | | | | | | | | | | 42 | | | |
| MW98-WD | 9/7/2010 | | | | | | | | | | | | | | | 38 | | | |
| MW98-WD | 12/1/2010 | | | | | | | | | | | | | | | 34 | | | |
| MW98-WD | 3/9/2011 | | | | | | | | | | | | | | | 36 | | | |
| MW98-WD | 6/14/2011 | | | | | | | | | | | | | | | 35 | | | |
| MW98-WD | 8/30/2011 | | | | | | | | | | | | | | | 40 | | | |
| MW98-WD | 12/13/2011 | | | | | | | | | | | | | | | 29 | | | |
| MW98-WD | 3/20/2012 | | | | | | | | | | | | | | | 26 | | | |
| MW98-WD | 6/13/2012 | | | | | | | | | | | | | | | 24 | | | |
| MW98-WD | 9/5/2012 | | | | | | | | | | | | | | | 23 | | | |
| MW98-WD | 12/6/2012 | | | | | | | | | | | | | | | 22 | | | |
| MW98-WD | 3/6/2013 | | | | | | | | | | | | | | | 19 | | | |
| MW98-WD | 6/4/2013 | | | | | | | | | | | | | | | 20 | | | |
| MW98-WD | 9/10/2013 | | | | | | | | | | | | | | | 21 | | | |
| MW98-WD | 11/4/2013 | | | | | | | | | | | | | | | 17 | J | | |
| MW98-WD | 2/13/2014 | | | | | | | | | | | | | | | 17 | | | |
| MW98-WD | 5/14/2014 | | | | | | | | | | | | | | | 18 | | | |
| MW98-WD | 8/13/2014 | | | | | | | | | | | | | | | 22 | | | |
| MW98-WD | 12/2/2014 | | | | | | | | | | | | | | | 19 | | | |
| MW98-WD | 2/9/2015 | | | | | | | | | | | | | | | 16 | | | |
| MW98-WD | 6/11/2015 | | | | | | | | | | | | | | | 21 | | | |
| MW98-WD | 9/3/2015 | | | | | | | | | | | | | | | 16 | | | |
| MW98-WD | 12/28/2015 | | | | | | | | | | | | | | | 16 | | | |
| MW98-WD | 3/1/2016 | | | | | | | | | | | | | | | 15 | | | |
| MW98-WD | 6/20/2016 | | | | | | | | | | | | | | | 16 | | | |
| MW98-WD | 12/28/2016 | | | | | | | | | | | | | | | 14 | | | |
| MW98-WD | 3/2/2017 | | | | | | | | | | | | | | | 13 | | | |
| MW98-WD | 6/27/2017 | | | | | | | | | | | | | | | 14 | | | |
| MW98-WD | 7/27/2017 | | | | | | | | | | | | | | | 14 | | | |
| MW98-WD | 11/30/2017 | | | | | | | | | | | | | | | 12 | | | |
| MW98-WD | 3/21/2018 | | | | | | | | | | | | | | | 12 | | | |
| MW98-WD | 5/24/2018 | | | | | | | | | | | | | | | 11 | | | |
| MW98-WD | 9/4/2018 | 0.82 | J | 0.24 | J | 0.15 | U | 0.69 | J | 0.29 | J | 0.13 | U | 0.83 | J | 11 | | 4.40 | |
| MW98-WD | 11/20/2018 | | | | | | | | | | | | | | | 12 | | | |
| MW98-WD | 2/22/2019 | | | | | | | | | | | | | | | 11 | | | |

**TABLE 4.10**
**SUMMARY OF GTEP AREA ANALYTICAL RESULTS SINCE 2010 VOCs AND NITRATE**
**JULY THROUGH DECEMBER 2021 OPERATIONS AND MAINTENANCE STATUS REPORT**
**LOWRY LANDFILL SUPERFUND SITE**

| | | Compounds[a/] | | | | | | | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| **Well** | **Sample Date** | **PCE** | **Q[b/]** | **TCE** | **Q** | **cis-1,2-DCE** | **Q** | **1,1-DCE** | **Q** | **1,1,1-TCA** | **Q** | **1,2-DCA** | **Q** | **1,1-DCA** | **Q** | **1,4-Dioxane** | **Q** | **NO3** | **Q** |
| **Performance Standard→** | | **5** | | **5** | | **70** | | **7** | | **200** | | **5** | | **990** | | **0.9** | | **28** | |
| MW98-WD | 5/16/2019 | | | | | | | | | | | | | | | 10 | | | |
| MW98-WD | 7/24/2019 | | | | | | | | | | | | | | | 11 | | | |
| MW98-WD | 10/23/2019 | | | | | | | | | | | | | | | 12 | | | |
| MW98-WD | 2/13/2020 | | | | | | | | | | | | | | | 11 | | | |
| MW98-WD | 5/21/2020 | | | | | | | | | | | | | | | 8.6 | | | |
| MW98-WD | 8/24/2020 | | | | | | | | | | | | | | | 9.8 | | | |
| MW98-WD | 11/18/2020 | | | | | | | | | | | | | | | 11 | | | |
| MW98-WD | 2/11/2021 | | | | | | | | | | | | | | | 6.3 | | | |
| MW98-WD | 6/7/2021 | | | | | | | | | | | | | | | 9.8 | | | |
| MW98-WD | 8/31/2021 | | | | | | | | | | | | | | | 11 | | | |
| MW98-WD | 11/18/2021 | | | | | | | | | | | | | | | 11 | | | |
| MW102-WD | 3/8/2010 | | | | | | | | | | | | | | | 29 | | | |
| MW102-WD | 6/10/2010 | | | | | | | | | | | | | | | 29 | | | |
| MW102-WD | 9/7/2010 | | | | | | | | | | | | | | | 25 | | | |
| MW102-WD | 12/1/2010 | | | | | | | | | | | | | | | 19 | | | |
| MW102-WD | 3/9/2011 | | | | | | | | | | | | | | | 20 | | | |
| MW102-WD | 6/14/2011 | | | | | | | | | | | | | | | 21 | | | |
| MW102-WD | 8/30/2011 | | | | | | | | | | | | | | | 21 | | | |
| MW102-WD | 12/13/2011 | | | | | | | | | | | | | | | 12 | | | |
| MW102-WD | 3/20/2012 | | | | | | | | | | | | | | | 9.7 | | | |
| MW102-WD | 6/13/2012 | | | | | | | | | | | | | | | 6.4 | | | |
| MW102-WD | 9/5/2012 | | | | | | | | | | | | | | | 5.8 | | | |
| MW102-WD | 12/6/2012 | | | | | | | | | | | | | | | 4 | J | | |
| MW102-WD | 3/6/2013 | | | | | | | | | | | | | | | 3.3 | J | | |
| MW102-WD | 6/4/2013 | | | | | | | | | | | | | | | 3.2 | J | | |
| MW102-WD | 9/10/2013 | | | | | | | | | | | | | | | 2.8 | J | | |
| MW102-WD | 11/4/2013 | | | | | | | | | | | | | | | 2.8 | J | | |
| MW102-WD | 2/13/2014 | | | | | | | | | | | | | | | 2.4 | J | | |
| MW102-WD | 5/14/2014 | | | | | | | | | | | | | | | 2.7 | J | | |
| MW102-WD | 8/13/2014 | | | | | | | | | | | | | | | 5.2 | | | |
| MW102-WD | 12/2/2014 | | | | | | | | | | | | | | | 3.6 | J | | |
| MW102-WD | 2/9/2015 | | | | | | | | | | | | | | | 2.8 | J | | |
| MW102-WD | 6/11/2015 | | | | | | | | | | | | | | | 4.4 | J | | |
| MW102-WD | 9/3/2015 | | | | | | | | | | | | | | | 3.3 | | | |
| MW102-WD | 12/28/2015 | | | | | | | | | | | | | | | 2.9 | | | |
| MW102-WD | 3/1/2016 | | | | | | | | | | | | | | | 2.2 | | | |
| MW102-WD | 6/20/2016 | | | | | | | | | | | | | | | 3.3 | | | |
| MW102-WD | 12/28/2016 | | | | | | | | | | | | | | | 2.5 | | | |
| MW102-WD | 3/2/2017 | | | | | | | | | | | | | | | 2.9 | | | |

**TABLE 4.10**
**SUMMARY OF GTEP AREA ANALYTICAL RESULTS SINCE 2010 VOCs AND NITRATE**
**JULY THROUGH DECEMBER 2021 OPERATIONS AND MAINTENANCE STATUS REPORT**
**LOWRY LANDFILL SUPERFUND SITE**

| | | Compounds[a/] | | | | | | | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| **Well** | **Sample Date** | **PCE** | **Q[b/]** | **TCE** | **Q** | **cis-1,2-DCE** | **Q** | **1,1-DCE** | **Q** | **1,1,1-TCA** | **Q** | **1,2-DCA** | **Q** | **1,1-DCA** | **Q** | **1,4-Dioxane** | **Q** | **NO3** | **Q** |
| **Performance Standard→** | | **5** | | **5** | | **70** | | **7** | | **200** | | **5** | | **990** | | **0.9** | | **28** | |
| MW102-WD | 6/27/2017 | | | | | | | | | | | | | | | 2.5 | | | |
| MW102-WD | 7/27/2017 | | | | | | | | | | | | | | | 2.5 | | | |
| MW102-WD | 11/30/2017 | | | | | | | | | | | | | | | 1.3 | | | |
| MW102-WD | 3/21/2018 | | | | | | | | | | | | | | | 1.4 | | | |
| MW102-WD | 5/24/2018 | | | | | | | | | | | | | | | 0.81 | J | | |
| MW102-WD | 9/4/2018 | 0.24 | J | 0.16 | U | 0.15 | U | 0.23 | U | 0.16 | U | 0.13 | U | 0.22 | U | 1.8 | | 2.9 | |
| MW102-WD | 11/20/2018 | | | | | | | | | | | | | | | 1.8 | | | |
| MW102-WD | 2/22/2019 | | | | | | | | | | | | | | | 1.5 | | | |
| MW102-WD | 5/16/2019 | | | | | | | | | | | | | | | 1.5 | | | |
| MW102-WD | 7/24/2019 | | | | | | | | | | | | | | | 1.7 | | | |
| MW102-WD | 10/23/2019 | | | | | | | | | | | | | | | 1.5 | | | |
| MW102-WD | 2/13/2020 | | | | | | | | | | | | | | | 1.1 | | | |
| MW102-WD | 5/21/2020 | | | | | | | | | | | | | | | 1.3 | | | |
| MW102-WD | 8/24/2020 | | | | | | | | | | | | | | | 1.1 | | | |
| MW102-WD | 11/18/2020 | | | | | | | | | | | | | | | 0.99 | | | |
| MW102-WD | 2/11/2021 | | | | | | | | | | | | | | | 0.9 | | | |
| MW102-WD | 6/7/2021 | | | | | | | | | | | | | | | 1.8 | | | |
| MW102-WD | 8/31/2021 | | | | | | | | | | | | | | | 1.7 | | | |
| MW102-WD | 11/18/2021 | | | | | | | | | | | | | | | 1.1 | | | |
| MW77-EW-1 | 3/8/2010 | | | | | | | | | | | | | | | 32 | | | |
| MW77-EW-1 | 6/10/2010 | | | | | | | | | | | | | | | 33 | | | |
| MW77-EW-1 | 9/7/2010 | | | | | | | | | | | | | | | 27 | | | |
| MW77-EW-1 | 12/1/2010 | | | | | | | | | | | | | | | 24 | | | |
| MW77-EW-1 | 3/9/2011 | | | | | | | | | | | | | | | 22 | | | |
| MW77-EW-1 | 6/14/2011 | | | | | | | | | | | | | | | 23 | | | |
| MW77-EW-1 | 8/30/2011 | | | | | | | | | | | | | | | 30 | | | |
| MW77-EW-1 | 12/13/2011 | | | | | | | | | | | | | | | 18 | | | |
| MW77-EW-1 | 3/20/2012 | | | | | | | | | | | | | | | 16 | | | |
| MW77-EW-1 | 6/13/2012 | | | | | | | | | | | | | | | 12 | | | |
| MW77-EW-1 | 9/5/2012 | | | | | | | | | | | | | | | 12 | | | |
| MW77-EW-1 | 12/6/2012 | | | | | | | | | | | | | | | 10 | | | |
| MW77-EW-1 | 3/6/2013 | | | | | | | | | | | | | | | 9.7 | | | |
| MW77-EW-1 | 6/4/2013 | | | | | | | | | | | | | | | 8.6 | | | |
| MW77-EW-1 | 9/10/2013 | | | | | | | | | | | | | | | 9.1 | | | |
| MW77-EW-1 | 12/17/2013 | | | | | | | | | | | | | | | 7.6 | | | |
| MW77-EW-1 | 2/13/2014 | | | | | | | | | | | | | | | 7.6 | | | |
| MW77-EW-1 | 5/14/2014 | | | | | | | | | | | | | | | 7.1 | | | |
| MW77-EW-1 | 8/13/2014 | | | | | | | | | | | | | | | 10 | | | |
| MW77-EW-1 | 12/2/2014 | | | | | | | | | | | | | | | 7.5 | | | |

**TABLE 4.10**
**SUMMARY OF GTEP AREA ANALYTICAL RESULTS SINCE 2010 VOCs AND NITRATE**
**JULY THROUGH DECEMBER 2021 OPERATIONS AND MAINTENANCE STATUS REPORT**
**LOWRY LANDFILL SUPERFUND SITE**

| | | Compounds[a/] | | | | | | | | | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| **Well** | **Sample Date** | **PCE** | **Q[b/]** | **TCE** | **Q** | **cis-1,2-DCE** | **Q** | **1,1-DCE** | **Q** | **1,1,1-TCA** | **Q** | **1,2-DCA** | **Q** | **1,1-DCA** | **Q** | **1,4-Dioxane** | **Q** | **NO3** | **Q** |
| **Performance Standard→** | | **5** | | **5** | | **70** | | **7** | | **200** | | **5** | | **990** | | **0.9** | | **28** | |
| MW77-EW-1 | 2/9/2015 | | | | | | | | | | | | | | | 6.6 | | | |
| MW77-EW-1 | 6/11/2015 | | | | | | | | | | | | | | | 9.5 | | | |
| MW77-EW-1 | 9/3/2015 | | | | | | | | | | | | | | | 6.5 | | | |
| MW77-EW-1 | 12/28/2015 | | | | | | | | | | | | | | | 8.4 | | | |
| MW77-EW-1 | 3/1/2016 | | | | | | | | | | | | | | | 4.8 | | | |
| MW77-EW-1 | 6/20/2016 | | | | | | | | | | | | | | | 5.8 | | | |
| MW77-EW-1 | 12/28/2016 | | | | | | | | | | | | | | | 4.5 | | | |
| MW77-EW-1 | 3/2/2017 | | | | | | | | | | | | | | | 11 | | | |
| MW77-EW-1 | 6/27/2017 | | | | | | | | | | | | | | | 11 | | | |
| MW77-EW-1 | 7/27/2017 | | | | | | | | | | | | | | | 5.4 | | | |
| MW77-EW-1 | 11/30/2017 | | | | | | | | | | | | | | | 3.7 | | | |
| MW77-EW-1 | 3/21/2018 | | | | | | | | | | | | | | | 3.5 | | | |
| MW77-EW-1 | 5/24/2018 | | | | | | | | | | | | | | | 2.5 | | | |
| MW77-EW-1 | 9/4/2018 | 0.43 | J | 0.16 | U | 0.15 | U | 0.23 | J | 0.16 | J | 0.13 | U | 0.55 | J | 10 | | 3 | |
| MW77-EW-1 | 11/20/2018 | | | | | | | | | | | | | | | 3.3 | | | |
| MW77-EW-1 | 2/22/2019 | | | | | | | | | | | | | | | 2.9 | | | |
| MW77-EW-1 | 5/16/2019 | | | | | | | | | | | | | | | 2.9 | | | |
| MW77-EW-1 | 7/24/2019 | | | | | | | | | | | | | | | 3.3 | | | |
| MW77-EW-1 | 10/23/2019 | | | | | | | | | | | | | | | 4.5 | | | |
| MW77-EW-1 | 2/13/2020 | | | | | | | | | | | | | | | 3 | | | |
| MW77-EW-1 | 5/21/2020 | | | | | | | | | | | | | | | 2.8 | | | |
| MW77-EW-1 | 8/24/2020 | | | | | | | | | | | | | | | 3 | | | |
| MW77-EW-1 | 11/18/2020 | | | | | | | | | | | | | | | 3.4 | | | |
| MW77-EW-1 | 2/11/2021 | | | | | | | | | | | | | | | 2.7 | | | |
| MW77-EW-1 | 6/7/2021 | | | | | | | | | | | | | | | 3.2 | | | |
| MW77-EW-1 | 8/31/2021 | | | | | | | | | | | | | | | 3.7 | | | |
| MW77-EW-1 | 11/18/2021 | | | | | | | | | | | | | | | 3 | | | |
| MW77-EW-2 | 3/8/2010 | | | | | | | | | | | | | | | 9.4 | | | |
| MW77-EW-2 | 6/10/2010 | | | | | | | | | | | | | | | 8.9 | | | |
| MW77-EW-2 | 9/7/2010 | | | | | | | | | | | | | | | 8.6 | | | |
| MW77-EW-2 | 12/1/2010 | | | | | | | | | | | | | | | 11 | | | |
| MW77-EW-2 | 3/9/2011 | | | | | | | | | | | | | | | 6.3 | | | |
| MW77-EW-2 | 6/14/2011 | | | | | | | | | | | | | | | 1.7 | J | | |
| MW77-EW-2 | 8/30/2011 | | | | | | | | | | | | | | | 1.5 | J | | |
| MW77-EW-2 | 12/13/2011 | | | | | | | | | | | | | | | 0.82 | J | | |
| MW77-EW-2 | 3/20/2012 | | | | | | | | | | | | | | | 0.7 | J | | |
| MW77-EW-2 | 6/13/2012 | | | | | | | | | | | | | | | 0.58 | J | | |
| MW77-EW-2 | 9/5/2012 | | | | | | | | | | | | | | | 0.85 | J | | |
| MW77-EW-2 | 12/6/2012 | | | | | | | | | | | | | | | 0.52 | J | | |

**TABLE 4.10**
**SUMMARY OF GTEP AREA ANALYTICAL RESULTS SINCE 2010 VOCs AND NITRATE**
**JULY THROUGH DECEMBER 2021 OPERATIONS AND MAINTENANCE STATUS REPORT**
**LOWRY LANDFILL SUPERFUND SITE**

| | | Compounds[a/] | | | | | | | | | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| **Well** | **Sample Date** | **PCE** | **Q[b/]** | **TCE** | **Q** | **cis-1,2-DCE** | **Q** | **1,1-DCE** | **Q** | **1,1,1-TCA** | **Q** | **1,2-DCA** | **Q** | **1,1-DCA** | **Q** | **1,4-Dioxane** | **Q** | **NO3** | **Q** |
| **Performance Standard→** | | **5** | | **5** | | **70** | | **7** | | **200** | | **5** | | **990** | | **0.9** | | **28** | |
| MW77-EW-2 | 3/6/2013 | | | | | | | | | | | | | | | 0.5 | U | | |
| MW77-EW-2 | 6/4/2013 | | | | | | | | | | | | | | | 0.5 | U | | |
| MW77-EW-2 | 9/10/2013 | | | | | | | | | | | | | | | 0.5 | U | | |
| MW77-EW-2 | 12/17/2013 | | | | | | | | | | | | | | | 0.5 | U | | |
| MW77-EW-2 | 2/13/2014 | | | | | | | | | | | | | | | 0.5 | U | | |
| MW77-EW-2 | 5/14/2014 | | | | | | | | | | | | | | | 0.5 | U | | |
| MW77-EW-2 | 8/13/2014 | | | | | | | | | | | | | | | 0.5 | U | | |
| MW77-EW-2 | 12/2/2014 | | | | | | | | | | | | | | | 0.5 | U | | |
| MW77-EW-2 | 2/9/2015 | | | | | | | | | | | | | | | 0.68 | J | | |
| MW77-EW-2 | 6/11/2015 | | | | | | | | | | | | | | | 0.94 | J | | |
| MW77-EW-2 | 9/3/2015 | | | | | | | | | | | | | | | 0.65 | J | | |
| MW77-EW-2 | 12/28/2015 | | | | | | | | | | | | | | | 0.53 | J | | |
| MW77-EW-2 | 3/1/2016 | | | | | | | | | | | | | | | 0.5 | J | | |
| MW77-EW-2 | 6/20/2016 | | | | | | | | | | | | | | | 0.3 | J | | |
| MW77-EW-2 | 12/28/2016 | | | | | | | | | | | | | | | 0.6 | J | | |
| MW77-EW-2 | 3/2/2017 | | | | | | | | | | | | | | | 0.81 | J | | |
| MW77-EW-2 | 6/27/2017 | | | | | | | | | | | | | | | 0.44 | J | | |
| MW77-EW-2 | 7/27/2017 | | | | | | | | | | | | | | | 0.18 | J | | |
| MW77-EW-2 | 11/30/2017 | | | | | | | | | | | | | | | 0.15 | U | | |
| MW77-EW-2 | 3/21/2018 | | | | | | | | | | | | | | | 0.37 | J | | |
| MW77-EW-2 | 5/24/2018 | | | | | | | | | | | | | | | 0.15 | U | | |
| MW77-EW-2 | 9/4/2018 | 0.20 | U | 0.16 | U | 0.15 | U | 0.23 | U | 0.16 | U | 0.13 | U | 0.22 | U | 0.15 | U | 0.55 | |
| MW77-EW-2 | 11/20/2018 | | | | | | | | | | | | | | | 0.15 | U | | |
| MW77-EW-2 | 2/22/2019 | | | | | | | | | | | | | | | 0.17 | J | | |
| MW77-EW-2 | 5/16/2019 | | | | | | | | | | | | | | | 0.15 | J | | |
| MW77-EW-2 | 7/24/2019 | | | | | | | | | | | | | | | 0.4 | U | | |
| MW77-EW-2 | 10/23/2019 | | | | | | | | | | | | | | | 0.4 | U | | |
| MW77-EW-2 | 2/13/2020 | | | | | | | | | | | | | | | 0.12 | J | | |
| MW77-EW-2 | 5/21/2020 | | | | | | | | | | | | | | | 0.17 | J | | |
| MW77-EW-2 | 8/24/2020 | | | | | | | | | | | | | | | 0.19 | J | | |
| MW77-EW-2 | 11/18/2020 | | | | | | | | | | | | | | | 0.19 | J | | |
| MW77-EW-2 | 2/11/2021 | | | | | | | | | | | | | | | 0.18 | J | | |
| MW77-EW-2 | 6/7/2021 | | | | | | | | | | | | | | | 2 | | | |
| MW77-EW-2 | 9/14/2021 | | | | | | | | | | | | | | | 0.13 | J | | |
| MW77-EW-2 | 11/18/2021 | | | | | | | | | | | | | | | 0.12 | J | | |
| MW77-UD | 1/4/2012 | 0.2 | U | 0.16 | U | 0.15 | U | 0.23 | U | 0.16 | U | 0.13 | U | 0.22 | U | 0.5 | U | 0.5 | U |
| MW77-UD | 2/7/2012 | 0.2 | U | 0.16 | U | 0.15 | U | 0.23 | U | 0.16 | U | 0.13 | U | 0.22 | U | 0.5 | U | 0.5 | U |
| MW77-UD | 9/6/2012 | 0.2 | U | 0.16 | U | 0.15 | U | 0.23 | U | 0.16 | U | 0.13 | U | 0.22 | U | 0.5 | U | 0.31 | J |

**TABLE 4.10**
**SUMMARY OF GTEP AREA ANALYTICAL RESULTS SINCE 2010 VOCs AND NITRATE**
**JULY THROUGH DECEMBER 2021 OPERATIONS AND MAINTENANCE STATUS REPORT**
**LOWRY LANDFILL SUPERFUND SITE**


| | | Compounds[a/] | | | | | | | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| **Well** | **Sample Date** | **PCE** | **Q[b/]** | **TCE** | **Q** | **cis-1,2-DCE** | **Q** | **1,1-DCE** | **Q** | **1,1,1-TCA** | **Q** | **1,2-DCA** | **Q** | **1,1-DCA** | **Q** | **1,4-Dioxane** | **Q** | **NO3** | **Q** |
| **Performance Standard→** | | **5** | | **5** | | **70** | | **7** | | **200** | | **5** | | **990** | | **0.9** | | **28** | |
| MW77-UD | 8/20/2018 | 0.2 | U | 0.16 | U | 0.15 | U | 0.23 | U | 0.16 | U | 0.13 | U | 0.22 | U | 0.38 | J | 0.047 | J |

**All concentrations listed in µg/L, except nitrate ($NO_3$), which is listed in mg/L

**Yellow shaded cells indicate the concentration exceeds the performance standard

a/ PCE = tetrachloroethene
TCE = trichloroethene
cis-1,2-DCE = cis-1,2-dichloroethene
1,1-DCE = 1,1-dichloroethene
1,1,1-TCA = 1,1,1-trichloroethane
1,2-DCA = 1,2-dichloroethane
1,1-DCA = 1,1-dichloroethane
NO3 = Nitrate

b/ Q = Final qualifier
Qualifiers J = estimated concentration below the reporting limit
U = undetected concentration below the method detection limit




## Legend

- Weathered Dawson Well Location
- Dry area
- Water Elevation Contour (10-foot interval) (Dashed where inferred, queried where uncertain)
- Dry Area or Well labeled dry – Water Level Below Base of Well Screen
- (5790.09) Water levels recorded week of July 1, 2021

**FIGURE 4.1**

**SITEWIDE POTENTIOMETRIC SURFACE ALLUVIUM/WEATHERED DAWSON July 2021**

**O&M Status Report - 2nd Half 2021 Lowry Landfill Superfund Site**

**PARSONS**

**Denver, Colorado**

S:\ES\Mal\Proj\LWRYLNFL\QUARTERLY REPORTS\2ND HALF 2021\GIS\Fig4-1 WDWaterLevels3Q2021.mxd lxh 3/11/2022



Injection Trench
North Boundary Barrier Wall
See Figure 4.25
See Figure 4.17
See Figure 4.15
See Figure 4.28
Slurry Wall
North Toe
Extraction System
Slurry Wall
WEST CLEANOUT
Dry
5700
5690
5740
5730
5670
5680
5710
5720
5750
5760
5770
5780
5790
5800
5810
5820
5830
PTP-16 Dry
B-319-26W Dry
MW114-WD 5688.73
NBBW-IW-3 5666.88
PTP-15 Dry
PTP-11 5687.32
MW102-425N-105W
PTP-20 Dry
PTP-15S Dry
TR-1 Dry
PTP-12 5688.51
PTP-17S Dry
MW103-WD 5693.08
PTP-20S Dry
B-319-50W Dry
GW-109 Dry
PTP-14 Dry
PTP-13 5687.57
MW102-320N-75E
PTP-21 5688.53
MW113-EW 5663.83
MW77-EW-2 5695.87
NBBW-IW-2 5686.17
PTP-22S Dry
B-304 5697
B-324-WD 5701.72
PTP-19 Dry
MW102-WD 5695.91
B-313 5688.77
B-326-WD 5666.31
B-320 5693.64
NBBW-IW-1 Dry
PTP-18 Dry
B-318
B-311 Dry
MW101-WD 5697.75
B-314 5696.45
B-308 5692.74
B-319-25S Dry
MW77-EW-1 5688.38
B-312 Dry
B-319-75S Dry
B-319-50S Dry
B-309 5687.02
B-307 Dry
B-310 5687.53
B305-WD Dry
B-327-WD 5695.68
MW97-WD 5698.1
MW98-WD 5691.01
MW62-WDR 5697.08
PTP-5A Dry
B-322 5688.35
MW99-WD 5699.69
MW77-WD 5700
B-316 Dry
MW171-WD 5700.50
MW100-WD 5700.76
A-115 5696.6
U-701-WD Dry
MW172-WD 5699.80
MW-EW-1 5697.14
PTP-9 Dry
MW23-UPPER-C 5701.03
B-315 5697.01
B-323-WD Dry
MW-EW-2 5697
GW-107A 5698.54
MW170-WD 5687.00
MW173-WD 5701.21
MNA-13 5698.91
MW175-WD 5688.92
MW174-WD 5701.77
MW170-EW-1 5676.43
GW-106 5716.16
MW74-WD 5716.73
A-102 5703.42
B-215-WD 5701.99
MW78-WD 5704.7
MW73-WD 5715.26
MNA-12 5704.3
MPZ-1 Dry
MW71-WD 5709.21
MNA-11 5706.93
MPZ-2 5711.82
C-702Q3 5713.67
MW79-WD 5712.74
MNA-10 5713.33
GW-POA3 Dry
GW-POA4 5716.21
MPZ-3 5716.64
MNA-09 5716.09
MW91-WD 5717.18
MNA-08 5722.24
MPZ-4 Dry
MW54-WD 5719.62
MW105-WD 5722.46
MW92-WD 5723.66
GW-POA2 5747.7
MPZ-5 Dry
MW72-WD 5724.66
MPZ-6 Dry
MNA-05 5738.32
MNA-04 5739.2
MPZ-7 Dry
MNA-07 5743.1
MNA-03 5739.56
MNA-06 5743.36
MPZ-12 5739.3
MNA-02 5739.52
MNA-01 5738
MPZ-13 5739.72
NTES-EW3 5748.45
MPZ-8 Dry
MPZ-11 5734.45
MPZ-10R 5728.67
NTES-EW2 5749.72
MPZ-9 Dry
GW-112 5736.11
NTES-EW1 5749.5
MW53-WD 5748.11
PM-14I 5749.09
PM-14X 5748.11
MW52-WD 5751.52
PM-13I Dry
PM-13X 5752.11
MW51I-WD-65N 5752.02
MW51X-WD-65N 5751.96
MW60-WD 5751.68
MW66-WD 5751.66
MW51I-WD-15N 5747.2
MW51I-WD 5753.64
MW70-WD 5751.65
MW51I-WD 5751.63
MW51I-WD-10S 5756.44
MW61-WD 5751.68
MW51X-WD-35S 5751.93
MW51I-WD-35S 5746.09
MW51X-WD-100S 5751.72
MW51I-WD-80S 5756.66
U-518R-WD 5751.96
MW51I-WD-90S
PM-12I 5762.69
PM-12X 5767
MW107-WD 5765.26
MW50-WD 5790.72
BM-11I-200N 5790.76
BM-11X-200N 5791.54
BM-11X-150N 5791.86
BM-11I-100N 5793.74
BM-11I-150N 5790.04
BM-11X-100N 5792.2
BM-11I-50N 5792.16
BM-11X-50N 5794.52
PM-11X 5794.85
PM-11I 5773.39
BM-11X-50S 5802.94
BM-11I-10S 5797.47
BM-11X-100S 5804.07
MW49-WD 5807.49
MW108-WD 580
PM-10I 5814.28
PM-10X 5818.97
PM-9X 5824.98
MW48-WD 5824.23
PM-9I 5816.02
MW47-WD 5825.82
PM-8X 5825.6
PM-8I 5816.29
MW46-WD 5825.12
PM-7X 5818.13
PM-7I 5810.79
MW45-WD 5806.76
PM-6X 5793.76
PM-6I 5797.76
MW112-WD 5806.45
MW33-WDR Dry
MW44-WD 5788.77
MW43-WD 5791.26
RDPZ-102 5783.68
MW32-WD 5803.19
PM-5X 5799.66
PM-5I 5799.04
MW42-WD 5789.66
MW41-WD 5787.68
MW109-WD 5793.55
BM-4X-100N 5793.69
BM-4I-100N 5792.98
BM-4I-50N 5793.24
BM-4X-50N 5793.23
PM-4I 5793.14
PM-4X 5793.52
BM-4X-10S 5793.16
BM-4I-50S 5793.15
BM-4I-10S 5793.26
BM-4X-50S 5793.52
BM-4X-100S 5793.27
BM-4I-100S 5793.48
MW34-WDR 5790.64
MW110-WD 5782.25
PM-3X 5778.13
PM-3I 5778.6
MW40-WD 5777.58
MW35-WDR 5778.7
PM-2X 5776.91
PM-2I 5769.92
MW64-WD 5775.12
MW63-WD 5772.96
MW68-WD 5773.69
MW39-WD 5773.31
MW39-WD-5W
MW39I-WD 5772.49
MW67-WD 5772.77
MW65-WD 5772.03
MW36-WDR 5771.37
PM-1X 5773.19
PM-1I 5771.72
GW-POA1 5751.04
MW38-830S-380E 5751.08
MW38-815S-445E 5751.03
MW38-825S-445E 5750.97
MW38-750S-400E 5750.91
MW38-770S-60E 5761.38
MW38-810S-325E 5752.72
MW38-790S-385E 575 62
MW38-700S-400E 5750.87
GW-POA-1N 5751.6
MW38-650S-400E 5750.87
MW38-650S-200E 5751.04
MW38-650S-50W 5752.16
GW-POA-1NE 5749.33
MW38-550S-200E 5750.8
MW38-600S-320W 5752.57
MW38-550S-320W 5751.87
MW38-700S-320W 5765.99
MW38-480S-60E 5748.94
MW56-WD 5750.32
MW38-450S-320W 5751.03
MW38-400S-140W 5747.43
MW38-350S-320W 5747.51
MW38-300S-160W 5745.4
MW38-250S-320W 5759.28
MW38-250S-50W Dry
MW38-350S-200E 5748.72
MW38-150S-320W 5759.09
MW38-100S-195W Dry
MW38-100S-140W Dry
MW38-100S-53W Dry
MW38-100S-200E 5748.54
MW38-170S-140W 5734.57
MW38-200S-140W 5735.54
MW38-0N-140W 5745.74
MW58-WD 5756.61
MW38-WD 5735.91
MW38-100N-200E 5747.36
MW59-WD 5756
MW38-200N-60E 5736.96
MW38-100N-60E 5736.6
MW38-100N-53W Dry
MW38-400N-180W 5756.58
MW38-350N-175E 5739.1
MW38-320N-305E 5728.97 Not Used
MW38-400N-240E 5738.78
MW55-WD 5753.95
MW38-360N-405E Dry
MW38-500N-396E 5740.46
MW38-600N-250E 5738.66
MW38-680N-419E 5747.89
MW38-794N-277E 5747.57
MW38-738N-277E 5738.39
MW38-830N-230E 5738.29
MW38-1064N-650E 5737.04
MW38-995N-475E 5736.76
MW38-1005N-150E 5733.37
MW38-1100N-0E 5745.3
MW38-1100N-326E 5728.61
MW38-1028N-256E 5728.88
MW38-1175N-300E 5723.06
MW38-1175N-5[illegible]E 5735.76
MW38-1373N-180W 5723.17 Not Used
MW76-WD 5741.02
MW75-WD 5742.29
GW-106 5716.16
MW74-WD 5716.73
MW73-WD 5715.26
MW-095N-226E 572[illegible]
MW-1028N-256E [illegible]
BKGD-1WD 5842.45
BKGD-2WD 5841.49
N
Feet
0
250
500
1 inch = 500 feet
Legend
Weathered Dawson Well Location
Dry area
Water Elevation Contour (10-foot interval)
(Dashed where inferred, queried where uncertain)
Dry Area or Well labeled dry –
Water Level Below Base of Well Screen
(5790.09) Water levels recorded week of October 01, 2021
FIGURE 4.2
SITEWIDE POTENTIOMETRIC SURFACE
ALLUVIUM/WEATHERED DAWSON
October 2021
O&M Status Report - 2nd Half 2021
Lowry Landfill Superfund Site
PARSONS
Denver, Colorado
S:\ES\Maj\Proj\LWRYLNFL\QUARTERLY REPORTS\2ND HALF 2021\GIS\Fig4-2_WDWaterLevels4Q2021.mxd lxh 3/11/2022

Figure 4.22

Injection Trench

North Boundary Barrier Wall

MW113-LD 5678.36 Not Used
MW113-UD 5631.69
B-326-UD 5672.35
B-304-UD 5688.91
B-313-UD 5682.83
B-314-UD 5689.76
GW-108A 5688.7
MW-1000 5686.8
B-306 5690.82
B-327-UD 5692.79
BW-PZ-1LC 5689.2
B-317-UD 5691.52
U-701 5688.22
B-305R 5691.83
MW62-UD 5690.74
MW77-UD 5696.00
MW-EW-1LC 5695.1
MW-EW-1LCRA 5692.97 Not Used
B-316-UD 5691.2
MW23-C-SD 5699.09
MW37-UD 5699.23
MW23-WD 5701.54
MW-EW-2LC 5695.62
GW-107UD 5699.5
GW-107UDR 5677.11 Not Used
MW38-1363N-180W 5724.73
MW38-1200N-226E 5709.85
MW38-1120N-1000E 5716.75
MW38-1064N-660E 5717.37 Not Used
MW38-1064N-655E 5726.88
MW76-UD 5717.53
MW75-UD 5717.04
MW74-UD 5713.25
MW73-UD 5711.19
MW78-UD 5706
MW71-UD 5710.25
MW38-410N-180W 5718.18
MW38-400N-300E 5718.29
MW38-360N-405E Dry
MW38-200N-425E 5731.41
C-702P4 5713.95
MW79-UD 5712.71
MW91-UD 5716.32
MW38-302S-50W 5743.9
MW38-450S-200E 5748.67
MW54-UDR 5719.96
MW72-UD 5721.51
MW36-UD 5767.32
MW39-UD 5751.7
North Toe Extraction System
MW93-UD 5732.05
MW90-UD 5731.96
MW-1 5745.1 Not Used
MW35-UD 5759.34
GW-104 5751.68
B-502 5748.98
PM-15-UD 5735.52
MW111-UD 5766.81
B-712-LD 5741.42 Not Used
B-712-UD 5747.92
B-712-25S-UD 5748.25
GW-101 5729.32
MW-2 5757.83 Not Used
MW34-UD 5787.22
MW52-UD 5748.4
MW106-UD 5750.80
BM-4X-40S 5785.95
MW42-UD 5788.06
B-706 5785.4
MW-3 5788.31
MW32-UD 5787.98
MW51-10S 5753
B-518 5759.38
B-708 5774.1
MW107-UD 5752.01
Slurry Wall
MW33-UD 5788.72
MW112-UD 5792.15
PM-6X-UD 5792.58
B-519 5808.85
BKGD-2UD 5801.49 Not Used
5700
5710
5720
5730
5740
5750
5760
5770
5780
5790
5800
5810

## Legend

- Unweathered Dawson Well Location
- Water Elevation Contour (10-foot interval) (Dashed where inferred)
- (5790.09) Water levels recorded week of July 01, 2021
- Dry — Water Level Below Base of Screen

N

0 250 500 Feet

1 inch = 500 feet

**FIGURE 4.3**

**SITEWIDE POTENTIOMETRIC SURFACE UNWEATHERED DAWSON**
**July 2021**
**O&M Status Report - 2nd Half 2021**
**Lowry Landfill Superfund Site**

**PARSONS**

**Denver, Colorado**

S:\ES\MajProj\LWRYLNFL\QUARTERLY REPORTS\2ND HALF 2021\GIS\Fig4-3_UNWDWaterLevels3Q2021.mxd lxh 3/25/2022

Figure 4.23

Injection Trench

North Boundary Barrier Wall

MW113-LD 5676.69
MW113-UD 5631.71
B-326-UD 5669.54
B-313-UD 5681.71
B-304-UD 5687.91
B-314-UD 5689.08
GW-108A 5687.98
BW-PZ-1LC 5688.64
MW-1000 5686.27
B-306 5690.23
B-327-UD 5692.08
B-317-UD 5691.01
U-701 5688.26
B-305R 5691.76
MW62-UD 5690.44
MW77-UD 5695.35
MW-EW-1LC 5694.88
B-316-UD 5691.43
MW37-UD 5699.24
MW-EW-1LCRA 5692.51 Not Used
MW-EW-2LC 5695.03
GW-107UD 5701.19
GW-107UDR 5678.65 Not Used
MW23-C-SD 5698.56
MW23-WD 5701.18

MW38-1363N-180W 5724.61
MW38-1200N-226E 5709.85
MW38-1120N-1000E 5716.65
MW38-1064N-660E 5717.29 Not Used
MW38-1064N-655E 5727.26
MW76-UD 5717.48
MW75-UD 5716.98
MW74-UD 5713.15
MW73-UD 5710.97
MW78-UD 5705.34
MW71-UD 5709.84
MW38-410N-180W 5718.21
MW38-400N-300E 5718.26
MW38-360N-405E Dry
MW38-200N-425E 5731.77
C-702P4 5714.22
MW79-UD 5712.8
MW91-UD 5716.03
MW38-302S-50W 5743.78
MW38-450S-200E 5748.67
MW54-UDR 5719.86
MW72-UD 5731.06
MW36-UD 5767.25
MW39-UD 5751.69
North Toe Extraction System
MW93-UD 5731.29
MW90-UD 5731.23
MW-1 5744.91 Not Used
B-502 5748.7
GW-104 5751.65
PM-15-UD 5735.55
MW35-UD 5759.34
MW111-UD 5766.58
B-712-LD 5741.32 Not Used
B-712-UD 5747.72
B-712-25S-UD 5748.04
GW-101 5729.15
MW-2 5757.75 Not Used
MW34-UD 5787.4
MW52-UD 5748.02
MW106-UD 5750.88
BM-4X-40S 5785.94
MW42-UD 5786.84
B-706 5785.33
MW51-10S 5752.91
B-518 5759.15
MW-3 5787.34
MW32-UD 5787.26
B-708 5774.02
MW107-UD 5751.96
Slurry Wall
MW33-UD 5788.67
MW112-UD 5791.9
PM-6X-UD 5792.20
B-519 5807.99

5700 5710 5720 5730 5740 5750 5760 5770 5780 5790 5800 5810

BKGD-2UD 5801.4 Not Used

N

0 250 500 Feet

1 inch = 500 feet

## Legend

- Unweathered Dawson Well Location
- Water Elevation Contour (10-foot interval) (Dashed where inferred)
- (5790.09) Water levels recorded week of October 01, 2021
- Dry — Water Level Below Base of Screen


**FIGURE 4.4**

**SITEWIDE POTENTIOMETRIC SURFACE UNWEATHERED DAWSON**
**October 2021**
**O&M Status Report - 2nd Half 2021**
**Lowry Landfill Superfund Site**

**PARSONS**

**Denver, Colorado**

S:\ES\Maj\Proj\LWRY\NEL\QUARTERLY REPORTS\2ND HALF 2021\GIS\Fig4-4_UNWDWaterLevels4Q2021.mxd lxh 3/25/2022




## Legend

MW112-DEN Well location,
5737.88 Water Elevation, and
5665.92 - 5636.52 Elevation of Screen Interval (feet above mean sea level)
Water elevation contour
(dashed where inferred, queried where uncertain)

N

0 250 500
Feet

1 inch = 500 feet

**Figure 4.5**
**Sitewide Potentiometric Levels**
**Upper Denver Formation**
**July 2021**

O&M Status Report - 2nd Half 2021
Lowry Landfill Superfund Site, Colorado

**PARSONS**
**Denver, Colorado**

S:\ES\Maj\Proj\LWRYLNFL\QUARTERLY REPORTS\2ND HALF 2021\GIS\Fig4-5_SitewideDenWaterLevel3Q2021.mxd lxh 2/21/2022

North Boundary
Barrier Wall

MW62-DENR
5698.43
5602-5582

5710

5700

GW-106-DEN
5711.53
5636.40-5612.00

MW71-DENR
5709.81
5628.35-5603.95

C-702P3
5711.83
5637-5627

B-504A
5717.34
5647-5627

MW72-DEN
5716.04
5644.75-5630.15

North Toe
Extraction System

GW-103
5739.55
5653-5633

GW-113
5719.46
5622-5597

MW30-BU
5717.81
5644-5614

5720

GW-101-DEN
5720.49
5644.20-5629.60

MW52-DEN
5728.47
5626-5606

5740

5730

5740

5750

5760

MW112-DEN
5737.53
5665.92-5636.52

Slurry Wall

B-520
5762.19

5699-5679

## Legend

MW112-DEN Well location,
5737.53 Water Elevation, and
5665.92 - 5636.52 Elevation of Screen Interval (feet above mean sea level)
Water elevation contour
(dashed where inferred, queried where uncertain)

N

0 250 500
Feet

1 inch = 500 feet


**Figure 4.6**
**Sitewide Potentiometric Levels**
**Upper Denver Formation**
**October 2021**

O&M Status Report - 2nd Half 2021
Lowry Landfill Superfund Site, Colorado

PARSONS

Denver, Colorado

S:\ES\MajProj\LWRYLNFL\QUARTERLY REPORTS\2ND HALF 2021\GIS\Fig4-6_SitewideDenWaterLevel4Q2021.mxd lxh 2/21/2022




## Legend

MW52-LIG 5681.29 — Well location and water elevation

Water elevation contour (dashed where inferred)

N

0 250 500 Feet

1 inch = 500 feet

**Figure 4.7**
**Sitewide Potentiometric Levels**
**Lignite Layer**
**July 2021**

O&M Status Report- 2nd Half 2021
Lowry Landfill Superfund Site, Colorado

**PARSONS**

**Denver, Colorado**

North Boundary
Barrier Wall

MW62-LIG
5674.28

GW-106-LIG
5690.88

MW71-LIG
5680.09

C-702Q1
5677.92

5675

5685

5690

MW72-LIGR
5681.03

North Toe
Extraction System

PZ-103
5679.75

GW-122
5681.03

GW-121
5680.98

GW-120
5681.38

MW52-LIG
5680.93

B-506
5686.94
(Screen interval
includes 30 ft
of Lower Denver)

5690

Slurry Wall

5680

PZ-101A
5677.87

S:\ES\Mail Proj\LWRY\LNFL\QUARTERLY REPORTS\2ND HALF 2021\GIS\Fig4-8_SitewideLigWaterLevel4Q2021.mxd lxh 2/21/2022

## Legend

MW52-LIG 5680.93 — Well location and water elevation

Water elevation contour (dashed where inferred)

N

0 250 500 Feet

1 inch = 500 feet

**Figure 4.8**
**Sitewide Potentiometric Levels**
**Lignite Layer**
**October 2021**

O&M Status Report- 2nd Half 2021
Lowry Landfill Superfund Site, Colorado

**PARSONS**

**Denver, Colorado**

MW114-WD
PTP-11
PTP-12
MW103-WD
MW113-UD
MW113-WD
PTP-13
MW113-EW-1
B-321
B-326-UD
MW77-EW-2
B-326-WD
B-314
B-313
MW102-WD
NBBW-IW-3
MW77-EW-1
MW98-WD
MW62-WDR
MW77-WD
North Boundary
Barrier Wall
MW23-UPPER-C
MW38-1028N-256E
MW170-EW-1
MW38-830N-230E
MW78-WD
MW74-WD
GW-106
MW71-WD
Asbestos
Monofill
MW91-WD
MW38-170S-140W
MW54-WD
MW105-WD
MW38-825S-445E
MW36-WDR
MW90-WD
North Toe
Extraction System
MNA-03
BM-15N6
MNA-01
BM-15E2
PM-3X
PM-14X
PM-13X
MW60-WD
MW70-WD
U-518R-WD
MW43-WD
Slurry Wall
BM-11X-100N
BM-11X-100S
MW108-WD
PM-6X

## Legend

**FORMATION**

- ALLUVIUM
- ALLUVIUM/WD
- LIGNITE
- Unweathered Dawson
- UPPER DENVER
- Weathered Dawson
- NO GEOLOGIC LOG
- Groundwater Compliance Well

N

Feet
0 250 500

1 inch = 500 feet

**FIGURE 4.9**
**GROUNDWATER SAMPLING LOCATIONS**
**2nd Half 2021**

O&M Status Report - 2nd Half 2021
Lowry Landfill Superfund Site, Colorado

**PARSONS**

**Denver, Colorado**

S:\ES\MajProj\LWRYLNFL\QUARTERLY REPORTS\2ND HALF 2021\GIS\Fig4-9_Sample Locs_2ndHalf_34Q21.mxd lxh 2/2/2022

13
18
24
19
25
30
MW176-DEN
MW144-WD
MW142-WD
Residence 1
MW141-WD
Residence 2
MW135-WD
MW05-WD
MW122-WDR
MW123-WD
MW124-WD
MW179-UDEN
MW129-WD
MW125-WD
MW121-WDR
MW156-WD
MW153-EW-1
MW157-WD
MW156-EW-1
MW151-WD
MW155-EW-1
MW154-EW-1
MW132-WD
MW118-WD
MW160-WD
MW117-WD
PTP-11
MW113-EW-1
MW113-WD
MW113-UD
PTP-12
NBBW-IW-3
MW114-WD
PTP-13
MW103-WD
B-321
B-326-WD
B-326-UD
MW77-EW-2
MW102-WD
B-313
MW77-EW-1
MW98-WD
B-314
MW62-WDR
MW74-WD
MW77-WD
MW38-1028N-256E
MW23-UPPER-C
MW38-830N-230E
MW170-EW-1
MW78-WD
GW-106
MW71-WD
Mississippi Ave.
Coal Creek
Gun Club Road
Un-Named Murphy Creek Tributary
Murphy Creek
Un-Named Murphy Creek Tributary
Yale Ave.
Murphy Creek Tributary
MURPHY CREEK
UNNAMED CREEK
STORMWAT

**Legend**

**FORMATION**

- ALLUVIUM
- LIGHNITE
- Unweathered Dawson
- UNWEATHERED DENVER
- DENVER
- UPPER DENVER
- Weathered Dawson
- Groundwater Compliance Well

N

Feet

0 600 1,200

1 inch = 1,200 feet

**FIGURE 4.10**


**GROUNDWATER**
**NORTH END SAMPLING LOCATIONS**
**2nd Half 2021**
O&M Status Report - 2nd Half 2021
Lowry Landfill Superfund Site, Colorado

**PARSONS**

**Denver, Colorado**

S:\ES\MajProj\LWRYLNFL\QUARTERLY REPORTS\2ND HALF 2021\GIS\Fig4-10 Sample Locs NE 2ndHalf 34Q21.mxd lxh 2/2/2022

M:\clients\EMSI\LOWRY\2021\Compliance-all_2nd-half-2021.dwg-11x17 02/14/2022 1:54PM




## Legend

- Out of Compliance or Potentially out of Compliance
- In Compliance or Potentially in Compliance

Note: Results for certain parameters of indeterminant compliance are not shown

NITRATE Compounds With Detections That Exceed Performance Standard

0 250 500
FEET

Figure 4.11

# Groundwater Compliance With Performance Standards

O&M Status Report 2nd Half 2021
Lowry Landfill Superfund Site

EMSI Engineering Management Support, Inc.

PM-1X
PM-1I
PM-1 Well Pair Hydrographs
PM-2 Well Pair Hydrographs
PM-2X
PM-2I
PM-3X
PM-3I
PM-3 Well Pair Hydrographs
PM-14 Well Pair Hydrographs
PM-15I
PM-15X
PM-15 Well Pair Hydrographs
PM-14I
PM-14X
PM-13 Well Pair Hydrographs
SLURRY WALL
PM-4 Well Pair Hydrographs
PM-4X
PM-4I
PM-5 Well Pair Hydrographs
PM-10 Well Pair Hydrographs
PM-13I
PM-13X
PM-12 Well Pair Hydrographs
PM-5X
PM-5I
PM-8 Well Pair Hydrographs
PM-9 Well Pair Hydrographs
PM-12I
PM-12X
PM-6 Well Pair Hydrographs
PM-11 Well Pair Hydrographs
PM-11I
PM-11X
PM-6I
PM-6X
PM-7I
PM-8I
PM-9I
PM-10I
PM-7 well Pair Hydrographs
PM-7X
PM-8X
PM-9X
PM-10X

Legend

PM-14X Hydraulic gradient monitoring well

Exterior well hydrograph

Interior well hydrograph

0 200 400

FEET

N

Figure 4.12

Perimeter Slurry Wall
Well Pair Hydrographs

O&M Status Report 2nd Half 2021
Lowry Landfill Superfund Site

EMSI Engineering Management Support, Inc.

M:\clients\EMSI\LOWRY\2021 Hydrographs\2nd-Half\Hydrographs_2nd-half-2021.dwg-11X17 02/14/2022 2:45PM






**FIGURE 4.13**

**NTES TRENCH WATER LEVELS AND PUMPING RATES**

**O&M Status Report**
**July Through December 2021**
**Lowry Landfill Superfund Site**

PARSONS
Denver, Colorado

S:\ES\MajProj\LWRYLNFL\QUARTERLY REPORTS\2ND HALF 2021\FIGURES\Fig4-13 NTES Trench_2ndHalf_2021.xlsx




S:\ES\Mal\Pro\LWRYLNFL\QUARTERLY REPORTS\2ND HALF 2021\GIS\Fig4-14 NT WDWaterLevels3Q2021.mxd lxh 3/16/2022

**FIGURE 4.14**

**NORTH TOE EXTRACTION SYSTEM AREA**
**POTENTIOMETRIC SURFACE**
**ALLUVIUM/WEATHERED DAWSON**
**July 2021**
**O&M Status Report - 2nd Half 2021**
**Lowry Landfill Superfund Site**

**PARSONS**

**Denver, Colorado**





**FIGURE 4.15**

**NORTH TOE EXTRACTION SYSTEM AREA**
**POTENTIOMETRIC SURFACE**
**ALLUVIUM/WEATHERED DAWSON**
**October 2021**
**O&M Status Report - 2nd Half 2021**
**Lowry Landfill Superfund Site**

**PARSONS**

**Denver, Colorado**

## Legend

- Potentiometric Surface (dashed where inferred)
- Injection Trench
- Groundwater Monitoring Well
- Compliance Wells highlighted with blue
- Groundwater Extraction Well
- Groundwater injection Well
- Groundwater Flow Direction
- Zone of Containment
- NBBW
- Area where the WD is dry

**Injection Wells**
**Operation suspended 10/2/18**

NBBW

Note: The water elevation value for the fully penetrating well when twinned by a partially penetrating piezometer was honored for contouring

Dry - Water Level Below Base of Screen (hatched contour line) Zone of Depression created by Groundwater Extraction

N

0 37.5 75 150 Feet

1 inch = 150 feet

**FIGURE 4.16**
**NBBW AREA**
**WEATHERED DAWSON**
**POTENTIOMETRIC SURFACE**

**July 2021**

**O&M Status Report - 1st Half 2021**
**Lowry Landfill Superfund Site**

**PARSONS**
**Denver, Colorado**

S:\ES\MapProj\LWRYLNFL\QUARTERLY REPORTS\2ND HALF 2021\GIS\Fig4-16_NBBWpotsurf_3Q2021.mxd kh 3/18/2022

## Legend

- Water Elevation Contour (2-foot interval) (dashed where inferred)
- Injection Trench
- Groundwater Monitoring Well
  Compliance Wells highlighted with blue
- Groundwater Extraction Well
- Groundwater injection Well
- Groundwater Flow Direction
- Zone of Containment caused by NBBW and Response Action Pumping
- NBBW
- Area where the WD is dry

**Injection Wells**
**Operation terminated 10/2/18**

NBBW

Note: The water elevation value for the fully penetrating well when twinned by a partially penetrating piezometer was honored for contouring

Dry - Water Level Below Base of Screen (hatched contour line) Zone of Depression created by Groundwater Extraction

N

0 37.5 75 150 Feet

1 inch = 150 feet

**FIGURE 4.17**
**NBBW AREA**
**WEATHERED DAWSON**
**POTENTIOMETRIC SURFACE**


**OCTOBER 2021**

**O&M Status Report - 2nd Half 2021**
**Lowry Landfill Superfund Site**


**PARSONS**
**Denver, Colorado**

S:\ES\MajProj\LWRYLNFL\QUARTERLY REPORTS\2ND HALF 2021\GIS\Fig4-17_NBBWpotsurf_4Q2021.mxd kh 3/18/2022

# Figure 4.18


B-326 and MW113 - Water Elevation/Dissolved Molybdenum
Total Molybdenum detected in MW113-EW-1. MW113-EW-1 extraction rate reduced
NBBW-IW-3 extraction commenced to increase mass removal
Packer installed (5664 feet amsl) and MW113-EW-1 inlet adusted on 7/30/20 (5664.5 feet amsl)
Packer removed and MW113-EW-1 inlet adusted on 6/7/21 (5659.8 feet amsl)
MW113-EW-1 Extraction
NBBW-IW-3 Extraction
MW113-UD Extraction
Extraction Rate (gallons per minute)
Water Elevation (ft amsl)
Dissolved Molybdenum (ug/L)
MW113-WD (Water Elevation)
B-326-WD (Dissolved Moly)
B-326-UD (Dissolved Moly)
MW113-WD (Dissolved Moly)
MW113-EW-1 (Dissolved Moly)
MW113-UD (Dissolved Moly)
MW113-LD (Moly Dissolved)
MW113-EW-1 Extraction Rate
NBBW-IW-3 Extration Rate
MW113-UD Extraction Rate

# Figure 4.19
# MW113 Area - Water Elevations and MW113-EW-1 and NBBW-IW-3 Extraction Rate





1 Transducer Water Levels 2 6 2022 for SSR

# Figure 4.20

## 1,4-Dioxane Concentrations

### B-326 / MW113 Area





B-326 and MW113 WD & UD 14X 2H2021 SDF


# Figure 4.21

## 1,4-Dioxane Concentrations

### B-321 (Extraction Well) / B-313 (Compliance Well)




B-313 and B-321 Extraction 14X 2H2021 SDF


North Boundary
Barrier Wall
MW113-LD
5678.36
Not Used
MW113-UD
5631.69
B-326-UD
5672.35
B-313-UD
5682.83
B-314-UD
5689.76
B-304-UD
5688.91
GW-108A
5688.70
MW-1000LC
5686.87
BW-PZ-1LC
5689.20
B-306
5690.82
B-317-UD
5691.52
U-701
5688.22
B-305R
5691.83
B-327-UD
5692.79
MW62-UD
5690.74
MW77-UD
5696.00
MW-EW-1LCRA
5692.97
Not Used
MW-EW-1LC
5695.10
MW-EW-2LC
5695.62
MW-EW-2LCR
5695.32
B-316-UD
5691.20
MW37-UD
5699.23
MW23-C-SD
5699.09
MW23-WD
5701.54
GW-107UD
5699.50
GW-107UDR
5677.11
Not Used
MW73-UD
5711.16
5681
5677
5671
5673
5675
5679
5683
5685
5687
5689
5691
5693
5695
5697
5699
5701
N
0
75
150
Feet
1 inch = 150 feet
Legend
Potentiometric Surface (dash where inferred)
Injection Trench
Groundwater Monitoring Well
Compliance Wells highlighted with blue
Groundwater Extraction Well
Dry
Water Level Below Base of Screen
FIGURE 4.22
NBBW AREA
POTENTIOMETRIC SURFACE
UNWEATHERED DAWSON
JULY 2021
O&M Status Report - 2nd Half 2021
Lowry Landfill Superfund Site
PARSONS
Denver, Colorado
S:\ES\MapProj\LWRY\LNFL\QUARTERLY REPORTS\2ND HALF 2021\GIS\Fig4-22_NBBWUNWDWatLev3Q2021.mxd lxh 3/25/2022

North Boundary
Barrier Wall

B-304-UD
5687.91

B-314-UD
5689.08

GW-108A
5687.98

BW-PZ-1LC
5688.64

MW-1000LC
5686.26

B-306
5690.23

B-317-UD
5691.01

B-313-UD
5681.71

MW113-LD
5676.69
Not Used

MW113-UD
5631.71

B-326-UD
5669.54

NBBW

U-701
5688.26

B-305R
5691.76

B-327-UD
5692.08

MW62-UD
5690.44

MW77-UD
5695.35

MW37-UD
5699.24

MW-EW-1LCRA
5692.51
Not Used

MW-EW-1LC
5694.68

B-316-UD
5691.43

MW-EW-2LCR
5694.88

MW-EW-2LC
5695.03

MW23-C-SD
5698.56

MW23-WD
5701.18

GW-107UD
5701.19

GW-107UDR
5678.65
Not Used

MW73-UD
5710.97

5679
5681
5685
5687
5691
5695
5697
5673
5667
5669
5671
5675
5677
5683
5689
5693
5699
5701

N

0 75 150 Feet

1 inch = 150 feet

## Legend

- Potentiometric Surface (dash where inferred)
- Injection Trench
- Groundwater Monitoring Well
  Compliance Wells highlighted with blue
- Groundwater Extraction Well
- Dry — Water Level Below Base of Screen


**FIGURE 4.23**

**NBBW AREA**
**POTENTIOMETRIC SURFACE**
**UNWEATHERED DAWSON**
**October 2021**
**O&M Status Report - 2nd Half 2021**
**Lowry Landfill Superfund Site**

**PARSONS**

**Denver, Colorado**

S:\ES\Maj Proj\LWRY\LNFL\QUARTERLY REPORTS\2ND HALF 2021\GIS\Fig4.23_NBBWUNWDWatLev4Q2021.mxd lkh 3/25/2022


MW38-1373N-180W
5722.91
Not Used
MW38-1005N-226E
5720.74
MW38-1175N-300E
Dry
MW38-1175N-518E
5736.51
MW38-1100N-326E
5728.17
MW38-1028N-256E
5719.67
MW38-1064N-650E
5739.2
MW38-1005N-150E
5734.36
MW38-995N-375E
MW38-995N-475E
5738.51
MW38-995N-278E
5720.79
MW38-830N-230E
5738.48
MW76-WD
5743.92
MW75-WD
MW74-WD
5717.2
GW-106
5716.96
MW73-WD
5715.81
MW38-794N-383E
MW38-758N-277E
5738.55
MW38-680N-419E
MW38-600N-250E
5738.76
MW55-WD
5754.14
MW38-500N-396E
5740.54
MW38-400N-180W
5756.75
MW38-400N-100E
5738.88
MW38-400N-240E
5738.87
MW38-360N-405E
Dry
MW38-350N-175E
5739.1
MW56-WD
MW38-320N-305E
5728.88
Not Used
MW38-200N-60E
5737.18
MW38-100N-53W
Dry
MW38-100N-200E
5747.34
MW38-100N-60E
MW38-0N-140W
MW38-WD
5736.2
MW56-WD
5756.18
MW51-WD
5740.19
MW38-100S-195W
5736.84
MW38-100S-140W
Dry
MW38-100S-200E
5748.58
MW38-150S-320W
5759.74
MW38-100S-53W
Dry
MW38-170S-140W
5744.69
MW38-200S-195W
MW38-200S-140W
5738.67
MW38-250S-320W
5759.32
MW38-250S-160W
MW38-250S-50W
Dry
MW38-275S-195W
MW38-300S-315W
5745.08
MW38-300S-60E
5748.41
MW38-300S-180W
MW38-350S-320W
MW38-350S-50W
5747.81
MW38-325S-195W
5746.55
MW38-350S-60E
5748.35
MW38-350S-200E
5748.67
MW38-400S-320W
MW38-400S-140W
MW38-390S-60E
5748.38
MW38-450S-200E
5748.67
MW38-400S-195W
5746.96
MW38-400S-50W
5747.71
MW38-400S-0W
5747.97
MW38-450S-320W
5750.73
MW38-500S-50W
5749.76
MW38-500S-320W
5750.89
MW38-450S-60E
5748.91
MW38-550S-200E
5750.78
MW38-550S-320W
5751.54
MW56-WD
5750.27
MW38-600S-320W
5752.23
MW38-650S-200E
5751.03
MW38-650S-50W
5752.07
MW38-650S-400E
5750.89
GW-POA-1NE
5749
GW-POA-1N
5751.63
MW38-700S-320W
5765.8
MW38-700S-400E
5750.9
MW38-770S-60E
5751.29
MW38-830S-380E
5751.13
MW38-750S-400E
MW38-815S-445E
5751.03
MW38-825S-445E
5750.98
MW38-890S-385E
5751.62
GW-POA1
5751.04
PM-1X
5774.02
PM-1I
5771.24
MW36-WDR
5771.46
MW65-WD
5772.1
MW67-WD
5772.71
MW39-WD
5773.33
MW39-WD-5W
MW39-WD
MW68-WD
5773.74
MW64-WD
5775.2
MW63-WD
PM-2X
5776.96
PM-2I
5769.95
5705
5710
5715
5720
5725
5730
5735
5740
5745
5750
5755
5760
5765
5770
5775
5780
Asbestos Monofill
Municipal
Solid Waste Landfill
Legend
Asbestos Monofill
Pumping Well
Compliance Monitoring Well
Potentiometric Surface
(dashed where inferred)
Sand Channel
Dry Area
Dry – Water Level Below Base of Screen
N
0 50 100 200
Feet
1 inch = 200 feet
FIGURE 4.24
MW38 AREA
WEATHERED DAWSON
POTENTIOMETRIC SURFACE
July 2021
O&M Status Report - 2nd Half 2021
Lowry Landfill Superfund Site, Colorado
PARSONS
Denver, Colorado
S:\ES\Maj\Proj\LWRY\LNFL\QUARTERLY REPORTS\2ND HALF 2021\GIS\Fig4-24_mw38wells3Q2021.mxd kh 3/8/2022




Legend
Asbestos Monofill
Pumping Well
Compliance Monitoring Well
Potentiometric Surface (dashed where inferred)
Sand Channel
Dry Area
Dry – Water Level Below Base of Screen
Asbestos Monofill
Municipal Solid Waste Landfill
MW38-1373N-180W 5723.17 Not Used
MW38-1175N-518E
MW38-1175N-300E 5723.06
MW38-1100N-326E 5728.61
MW38-1028N-250E
MW38-1064N-650E 5727.04
MW38-995N-375E 5734.27
MW38-995N-475E 5736.76
MW38-995N-300E 5720.69
MW38-1055N-150E 5733.37
MW38-1055N-226E 5720.62
MW38-996N-226E 5720.68
MW38-830N-230E 5738.29
MW38-794N-383E 5727.57
MW38-758N-277E
MW38-680N-419E
MW38-600N-250E 5738.66
MW38-500N-396E 5740.46
MW76-WD 5741.02
MW75-WD 5732.29
MW74-WD 5716.73
GW-106 5716.46
MW73-WD 5715.26
MW55-WD 5753.95
MW38-400N-180W 5756.58
MW38-400N-100E 5738.8
MW38-400N-240E 5738.78
MW38-360N-405E Dry
MW38-350N-175E 5730.1
MW38-320N-305E 5728.97 Not Used
MW38-200N-60E 5736.96
MW38-100N-200E 5747.36
MW38-100N-53W Dry
MW38-100N-60E 5736.6
MW38-0N-140W 5745.74
MW58-WD 5750.61
MW38-WD 5735.91
MW37-WD 5740.06
MW38-100S-195W Dry
MW38-100S-140W Dry
MW38-100S-53W Dry
MW38-100S-200E 5748.54
MW38-170S-140W 5724.57
MW38-200S-140W 5735.54
MW38-250S-150W 5747.35
MW38-250S-10W Dry
MW38-275S-195W 5738.01
MW38-300S-60E 5748.44
MW38-300S-180W 5745.4
MW38-350S-50W 5747.85
MW38-350S-60E 5748.36
MW38-350S-200E 5748.72
MW38-325S-195W 5746.55
MW38-400S-140W 5747.43
MW38-400S-0W 5748.05
MW38-390S-60E 5748.42
MW38-450S-200E 5748.67
MW38-400S-195W 5746.96
MW38-400S-50W 5747.8
MW38-450S-60E 5748.94
MW38-500S-50W 5749.82
MW50-WD 5750.32
MW38-500S-200E 5750.8
MW38-600S-320W 5752.51
MW38-650S-50W 5752.16
MW38-650S-200E 5751.04
MW38-650S-400E 5750.87
GW-POA-1NE 5749.33
GW-POA-1N 5751.6
MW38-700S-400E 5750.37
MW38-750S-400E 5750.31
MW38-770S-60E 5761.38
MW38-830S-380E 5751.08
MW38-815S-445E 5751.03
MW38-825S-445E 5750.97
MW38-890S-385E 5751.62
GW-POA1 5751.04
PM-1X 5773.19
PM-1I 5771.72
MW36-WDR 5771.37
MW65-WD 5772.03
MW67-WD 5772.77
MW39I-WD 5772.49
MW39-WD 5773.31
MW39-WD-5W
MW68-WD 5773.65
MW63-WD 5772.96
MW64-WD 5775.32
5705
5710
5715
5720
5725
5730
5735
5740
5745
5750
5755
5760
5765
5770
5775
5780
N
0 50 100 200
Feet
1 inch = 200 feet
FIGURE 4.25
MW38 AREA
WEATHERED DAWSON
POTENTIOMETRIC SURFACE
October 2021
O&M Status Report - 2nd Half 2021
Lowry Landfill Superfund Site, Colorado
PARSONS
Denver, Colorado
S:\ES\Maj\Proj\LWRYLNFL\QUARTERLY REPORTS\2ND HALF 2021\GIS\Fig4-25_mw38wells4Q2021_.mxd kh 3/8/2022

**FIGURE 4.26**

**B-326-WD and B-326-UD Water Elevation and NBBW-IW-3, MW113-EW-1 and MW133-UD Extraction Rate**







**FIGURE 4.27**

**PM-15 AREA**
**POTENTIOMETRIC SURFACE**
**WEATHERED DAWSON**
**July 2021**
**O&M Status Report - 2nd Half 2021**
**Lowry Landfill Superfund Site, Colorado**

**PARSONS**

**Denver, Colorado**

S:\ES\Maj\Proj\LWRY\LNFL\QUARTERLY REPORTS\2ND HALF 2021\GIS\Fig4-27_PM15_PotSurf3Q21.mxd lxh 3/8/2022

MW90-UD
5731.23
Not Used

MW90-WD
5731.21

BM-15N4
5735.50

BM-15N3
5738.70

BM-15NE2
5729.59

BM-15NW1
5753.02
Not Used

BM-15NW2
5752.70

BM-15N2
5739.21

BM-15NE1
5730.27

BM-15E5
5736.93

BM-15N1
5736.66

BM-15N6
5737.42

PM-15I-UD
5735.55
Not Used

BM-15N5
5736.00

BM-15I-15N
5725.02

BM-15E1
5731.86

PM-15X
5737.04

PM-15I
5723.20

BM-15E4
5736.31

BM-15I-25S
5720.40

PM-15W
5746.19
Not Used

BM-15E2
5731.44

BM-15X-37.5S
5736.37

BM-15I-37.5S
5723.04

PM-15WR
5739.62

BM-15X-50S
5737.66

BM-15I-50S
5723.62

BM-15I-75S
5738.05

BM-15E6
5737.84

BM-15X-75S
5738.44

BM-15I-100S
5725.57

BM-15E3
5731.42

BM-15X-100S
5738.26

BM-15I-125S
5739.21

BM-15X-125S
5739.16

BM-15X-150S
5739.94

BM-15I-150S
5725.21

BM-15I-175S
5741.19

BM-15X-175S
5741.99

BM-15I-200S
5745.34

BM-15X-200S
5743.44

5730
5735
5740
5745
5750
5725

N

0 30 60 Feet

1 inch = 30 feet

E/S/W Slurry Wall

## Legend

- Potentiometric Surface
- Groundwater Monitoring Well
- Groundwater Compliance Well
- Groundwater Extraction Well
- Air Sparge Well


**FIGURE 4.28**


**PM-15 AREA**
**POTENTIOMETRIC SURFACE**
**WEATHERED DAWSON**
**October 2021**
**O&M Status Report - 2nd Half 2021**
**Lowry Landfill Superfund Site, Colorado**

**PARSONS**

**Denver, Colorado**

S:\ES\Maj\Proj\LWRY\LNFL\QUARTERLY REPORTS\2ND HALF 2021\GIS\Fig4-28_PM15_PotSurf4Q21.mxd lxh 3/8/2022


MW131-WD
5649.4
MW130-WD
5649.6
MW129-WD
5649.91
MW122-WDR
5652.68
MW123-WD
5653.16
MW124-WD
5653.72
MW125-WD
5654.83
MW126-WD
5655.54
MW121-WDR
5652.44
MW127-WD
5655.98
5650
5655
5660
MW156-WD
5663.46
MW156-EW-1
5663.81
MW157-WD
5662.99
MW158-WD
5661.31
MW154-WD
5663.73
MW155-WD
5663.73
MW153-WD
5663.57
MW155-EW-1
5663.81
MW151-WD
5662.98
MW154-EW-1
5663.47
MW153-EW-1
5663.44
5665
5670
5675
5680
T1-1
5674.97
MW132-WD
5674.88
MW160-WD
T1-2
5675.89
T1-3
5675.74
T1-4
5676.25
T1-5
5677.82
MW180-WD
5678.21
MURPHY CREEK
UNNAMED CREEK
5685
MW118-WD
5685.29
MW117-WD
5686.14
MW120-WD
5687.15
MW104-WD
5686.99
MW119-WD
5688.23
MW116-WD
5687.74
MW115-WD
5687.51
5690
5695
5700
5705
5710
5725
5730
5735
5740
GW-109
Dry
PTP-15S
Dry
PTP-15
Dry
PTP-17S
Dry
TR-1
Dry
PTP-16
Dry
PTP-18
Dry
PTP-14
Dry
PTP-12
5688.73
PTP-13
5688.25
PTP-19
Dry
MW114-WD
5689.09
MW113-WD
5670.01
MW103-WD
5693.38
MW113-EW-1
5669.92
MW77-EW-2
5696.10
B-319-50W
Dry
PTP-20
Dry
PTP-20S
PTP-21
5688.86
NBBW-IW-2
5686.48
PTP-22S
Dry
B-320
5695.13
B-312
Dry
B-324-WD
5703.83
B-304
5699.2
B-321
5686.47
NBBW-IW-1
Dry
NBBW-IW-3
5688.38
B-309
5687.02
B-308
5693.7
B-314
5696.45
MW-1000
Dry
B-307
Dry
B-319-75S
Dry
B-310
5687.33
B-319-25S
Dry
B-319-50S
Dry
B-305WD
Dry
B-322
5688.43
B-318
B-326-WD
5670.17
B-319
5670.26
B-327-WD
5697.3
MW102-WD
5696.39
MW101-WD
5698.11
MW97-WD
5698.98
MW98-WD
5690.98
MW99-WD
5700.1
MW77-WD
5701.25
MW100-WD
5701.17
MW23-UPPER-C
5702.43
MW173-WD
5701.55
MW174-WD
5702.08
MW78-WD
5705.17
MW62-WDR
5697.12
MW171-WD
5702.88
MW172-WD
5700.14
STORMWATER DITCH
PTP-5A
Dry
SUMP
5685.77
A-115
5697.26
MW-EW-1
5697.61
LI-701-WD
Dry
PTP-9
Dry
B-329-WD
Dry
B-315
5697.16
MW-EW-2
5697.64
MNA-13
5699.27
GW-107A
5699.8
MW175-WD
5689.38
MW170-WD
5687.17
MW170-EW-1
5676.18
B-215-WD
5702.04
A-102
5703.43
North Boundary
Barrier Wall
MW38-1095N-226E
5720.74
MW38-1100N-326E
5728.17
MW38-1175N-300E
Dry
MW38-1175N-518E
5736.51
MW38-1064N-650E
5739.2
MW38-995N-475E
5738.51
MW38-800N
5738.0
MW75-WD
5735.03
MW76-WD
5743.92
MW74-WD
5717.2
GW-106
5716.96
MW73-WD
5715.81
MW38-794N-383E
5720
5715
5705
5695
5690
5685
5680
5670
5700
5725
5730
5735
5740
Legend
Extraction Well
Groundwater Monitoring Well
Potentiometric Contours
(dashed where inferred)
Area where Weathered Dawson is dry
Dry
Water Level Below Base of Screen
Zone of Containment
N
Feet
0
400
1 inch = 400 feet
FIGURE 4.29
SECTION 31 WEATHERED DAWSON
POTENTIOMETRIC SURFACE
July 2021
O&M Status Report - 2nd Half 2021
North End
Lowry Landfill Superfund Site, Colorado
PARSONS
Denver, Colorado
S:\ES\Maj\Proj\LWRY\LNFL\QUARTERLY REPORTS\2ND HALF 2021\GIS\Fig4-29_WD_Sec31_WaterLevels3Q21.mxd lxh 3/16/2022




## Legend

- Extraction Well
- Groundwater Monitoring Well
- Potentiometric Contours (dashed where inferred)
- Dry — Water Level Below Base of Screen
- Area where Weathered Dawson is dry
- Zone of Containment caused by NBBW and Response Action Pumping

N

0 400 Feet

1 inch = 400 feet

**FIGURE 4.30**

**SECTION 31 WEATHERED DAWSON POTENTIOMETRIC SURFACE**
**October 2021**
O&M Status Report - 2nd Half 2021
North End
Lowry Landfill Superfund Site, Colorado

**PARSONS**
**Denver, Colorado**

S:\ES\Maj\Proj\LWRY\LNFL\QUARTERLY REPORTS\2ND HALF 2021\GIS\Fig4-30_WD_Sec31_WaterLevels4Q21.mxd lxh 3/16/2022

13
18
24
19
25
30
31

MW178-UDEN 5536.74
MW178-DEN 5559.89
NEPZ-104 5564.95
MW176-UDEN 5557.89
MW176-DEN 5558.58
MW177-UDEN 5565.27
MW177-DEN 5569.35
NEPZ-098 5554.88
NEPZ-097 5553.88
NEPZ-103 5564.66
NEPZ-101 5560.75
NEPZ-099 5556.66
NEPZ-102 5563.38
NEPZ-105 5566.35
MW145-WD 5568.45
MW144-WD 5568.43
MW142-WD 5589.62
MW141-UDEN 5605.32
MW140-WD 5607.51
MW141-WD 5607.33
MW139-WD 5638.77
MW138-WD 5638.29
MW137-WD 5638.46
MW136-WD 5638.69
MW133-WD 5636.1
MW134-WD 5637.68
MW135-WD 5638.95
MW129-WD 5649.91
MW130-WD 5649.6
MW131-WD 5649.4
MW179-UDEN 5649.18
MW122-WDR 5652.68
MW124-WD 5653.72
MW126-WD 5655.54
MW127-WD 5655.98
MW121-WDR 5652.44
MW123-WD 5653.16
MW125-WD 5654.53
MW157-WD 5662.99
MW154-WD 5663.72
MW158-WD 5661.31
MW156-WD 5663.46
MW151-WD 5662.98
MW155-EW-1 5663.81
MW153-WD 5663.57
MW155-WD 5663.73
MW160-WD
MW132-WD 5674.88
T1-1 5674.97
T1-2 5675.89
T1-3 5675.74
T1-4 5676.25
T1-5 5677.82

SWMC-07
SWMC-06
SWMC-05
SWMC-04
SWMC-03
SWMC-02
SWMC-09
SWMC-08
SWMC-01
SW-5
SW-3

5555
5560
5565
5570
5575
5580
5585
5590
5595
5600
5605
5610
5615
5620
5625
5630
5635
5640
5645
5650
5655
5660
5665
5670
5675
5680
5685
5690

Mississippi Ave.
E. Jewell Ave.
Yale Ave.
Gun Club Road
Un-Named Murphy Creek Tributary
Un-Named Murphy Creek Tributary
Murphy Creek
Un-Named Murphy Creek Tributary
Murphy Creek

## Legend

- Groundwater Extraction Well
- Groundwater Monitoring Well
- Domestic Well Location
- Surface Water Sample Location
- Piezometer Location
- Dry — Water Level Below Base of Screen

N

0 500 1,000 Feet

1 inch = 1,000 feet


**FIGURE 4.31**

**SECTIONS 19 AND 30**
**WEATHERED DAWSON/**
**WEATHERED UPPER DENVER**
**POTENTIOMETRIC SURFACE**
**July 2021**

O&M Status Report - 2nd Half 2021
Lowry Landfill Superfund Site, Colorado

**PARSONS**
**Denver, Colorado**

S:\ES\Maj\Proj\LWRYLNFL\QUARTERLY REPORTS\2ND HALF 2021\GIS\Fig4-31_WD_Sec1930_WaterLevels3Q21.mxd lxh 3/8/2022




**Legend**

- NO 1,4-Dioxane (14X) DETECTED
- DETECTED 14X <= 0.9 ug/L PERFORMANCE STANDARD
- DETECTED 14X > 0.9 ug/L PERFORMANCE STANDARD
- EXTRACTION WELL

J = ESTIMATED VALUE
U = UNDETECTED

N

0 200 400 800 Feet

1 inch = 400 feet

**FIGURE 4.32**

**SECTION 31**
**1,4-DIOXANE RESULTS**
**THIRD QUARTER 2021**

O&M Status Report - 2nd Half 2021
Lowry Landfill Superfund Site, Colorado

**PARSONS**

**Denver, Colorado**

S:\ES\MalProj\LWRY\LNFL\QUARTERLY REPORTS\2ND HALF 2021\GIS\Fig4-32_14Diox_Sec31_3Q21.mxd lxh 3/8/2022

MW155-EW-1
0.27 J

MW156-EW-1
0.48 J

MW156-WD
0.25 J

MW154-EW-1
0.63 J

MW157-WD
0.1 J

MW153-EW-1
2

MW151-WD
5.1

AREA 1

MW160-WD
3.3

MW132-WD
14

MURPHY CREEK

AREA 2

MW118-WD
0.26 J

MW117-WD
1.5

UNNAMED CREEK

AREA 3

MW114-WD
0.96

MW113-UD
94

PTP-12
9.1

MW103-WD
0.41 J

MW113-EW-1
120

PTP-13
6.9

B-326-WD
1

MW77-EW-2
0.12 J

MW102-WD
1.1

B-313
17

B-326-UD
5

MW77-EW-1
3

B-314
0.9 U

NBBW-IW-3

AREA 4

MW98-WD
11

MW62-WDR
3.2

MW77-WD
11

MW23-UPPER-C
0.9 U

MW38-1028N-256E
2.1

MW170-EW-1
12

AREA 5

STORMWATER

MW38-830N-230E
4.6

MW74-WD
0.9 U

GW-106
0.9 U

North Boundary
Barrier Wall

MW78-WD
0.9 U

## Legend

- NO 1,4-Dioxane (14X) DETECTED
- DETECTED 14X <= 0.9 ug/L PERFORMANCE STANDARD
- DETECTED 14X > 0.9 ug/L PERFORMANCE STANDARD
- EXTRACTION WELL

J = ESTIMATED VALUE
U = UNDETECTED

N

0 200 400 800 Feet

1 inch = 400 feet

**FIGURE 4.33**

**SECTION 31**
**1,4-DIOXANE RESULTS**
**FOURTH QUARTER 2021**

O&M Status Report - 2nd Half 2021
Lowry Landfill Superfund Site, Colorado

**PARSONS**

**Denver, Colorado**

S:\ES\MajProj\LWRYLNFL\QUARTERLY REPORTS\2ND HALF 2021\GIS\Fig4-33_14Diox_Sec31_4Q21.mxd lxh 3/8/2022

MW176-DEN
0.49 J

MW144-WD
0.9 U

Mississippi Ave.

Gun Club Road

24

19

MW142-WD
1.7

Un-Named Murphy Creek Tributary

MW141-WD
2.3

E. Jewell Ave.

Un-Named Murphy Creek Tributary

Un-Named Murphy Creek Tributary

Murphy Creek

25

30

MW135-WD
4.5

MW122-WDR
2

MW121-WDR
2

MW123-WD
1.5

MW05-WD
4.4

MW124-WD
0.49 J

MW179-UDEN
0.9 U

MW125-WD
0.41 J

MW129-WD
5.3

Yale Ave.

MW156-WD
0.25 J

MW157-WD
0.1 J

MW156-EW-1
0.48 J

MW151-WD
5.1

MW155-EW-1
0.27 J

MW153-EW-1
2

MW154-EW-1
0.63 J

31

MW160-WD
3.3

MW132-WD
14

Murphy Creek

S:\ES\Maj\Proj\LWRYLNFL\QUARTERLY REPORTS\2ND HALF 2021\GIS\Fig4-34_14Diox_Sec1930_34Q21.mxd lxh 3/8/2022

**Legend**

- DETECTED 14X > 0.9 ug/L PERFORMANCE STANDARD
- DETECTED 14X <= 0.9 ug/L PERFORMANCE STANDARD
- NO 1,4-Dioxane (14X) DETECTED
- EXTRACTION WELL
- Domestic Well Location

J = ESTIMATED VALUE
U = UNDETECTED

N

Feet
0 1,000

1 inch = 1,000 feet

**FIGURE 4.34**


**SECTIONS 19 AND 30**
**1,4-DIOXANE**
**MOST RECENT RESULTS**

O&M Status Report - 2nd Half 2021
Lowry Landfill Superfund Site, Colorado


**PARSONS**

**Denver, Colorado**


# Figure 4.35
# North End Trend Analysis Plots - Area 1
# July through December 2021 Operations and Maintenance Status Report Lowry Landfill Superfund Site





Graph 1




Graph 2





Graph 3





Graph 4


# Figure 4.35
# North End Trend Analysis Plots - Area 1
# July through December 2021 Operations and Maintenance Status Report Lowry Landfill Superfund




Graph 5





Graph 6





Graph 7

Analysis prepared using Sen's Test for trend and DUMPSTAT®


# Figure 4.36
# North End Trend Analysis Plots - Area 2
# July through December 2021 Operations and Maintenance Status Report Lowry Landfill Superfund Site





**Graph 1**




**Graph 2**





**Graph 3**





**Graph 4**

Prepared by: Parsons
Analysis prepared using Sen's Test for trend and DUMPSTAT®


# Figure 4.37
# North End Trend Analysis Plots - Area 3
# July through December 2021 Operations and Maintenance Status Report Lowry Landfill Superfund Site





Graph 1




Graph 2





Graph 3





Graph 4

# Figure 4.37
# North End Trend Analysis Plots - Area 3
# July through December 2021 Operations and Maintenance Status Report Lowry Landfill Superfund Site





**Graph 5**





**Graph 6**

**Analysis prepared using Sen's Test for trend and DUMPSTAT®**


# Figure 4.38
# North End Trend Analysis Plots - Area 4
# July through December 2021 Operations and Maintenance Status Report Lowry Landfill Superfund Site





Graph 1




Graph 2





Graph 3





Graph 4


# Figure 4.38
# North End Trend Analysis Plots - Area 4
# July through December 2021 Operations and Maintenance Status Report Lowry Landfill Superfund Site





Graph 5




Graph 6





Graph 7





Graph 8

**Analysis prepared using Sen's Test for trend and DUMPSTAT®**


# Figure 4.39
# North End Trend Analysis Plots - Sections 30 and 19
# July through December 2021 Operations and Maintenance Status Report Lowry Landfill Superfund Site





Graph 1




Graph 2





Graph 3





Graph 4

# Figure 4.39
# North End Trend Analysis Plots - Sections 30 and 19
# July through December 2021 Operations and Maintenance Status Report Lowry Landfill Superfund Site





**Graph 5**





**Graph 6**

Analysis prepared using Sen's Test for trend and DUMPSTAT®


# Figure 4.40
# North End Trend Analysis Plots - Yale Area
# July through December 2021 Operations and Maintenance Status Report Lowry Landfill Superfund Site





Graph 1




Graph 2





Graph 3





Graph 4


# Figure 4.40
# North End Trend Analysis Plots - Yale Area
# July through December 2021 Operations and Maintenance Status Report Lowry Landfill Superfund Site




**Graph 5**




**Graph 6**




**Graph 7**

Analysis prepared using Sen's Test for trend and DUMPSTAT®

13
18
24
19
30
31
MW176-DEN
0.49 J
MW144-WD
0.9 U
MW142-WD
1.7
MW141-WD
2.3
MW135-WD
4.5
MW05-WD
4.4
MW122-WDR
2
MW179-UDEN
0.9 U
MW129-WD
5.3
MW121-WDR
2
MW155-EW-1
0.27 J
MW151-WD
5.1
B-326-WD
1
B-326-UD
5
MW153-EW-1
2
MW154-EW-1
0.63 J
MW132-WD
14
MW156-WD
0.25 J
MW157-WD
0.1 J
MW156-EW-1
0.48 J
MW160-WD
3.3
PTP-13
6.9
MW113-UD
94
MW62-WDR
3.2
MW113-EW-1
120
NBBW-IW-3
140
MW118-WD
0.26 J
MW117-WD
1.5
PTP-12
9.1
B-321
9.7
B-313
17
B-314
0.9 U
MW74-WD
0.9 U
GW-106
0.9 U
MW38-1028N-256E
2.1
MW38-830N-230E
4.6
MW38-170S-140W
14
MW170-EW-1
12
MW23-UPPER-C
0.9 U
MW38-825S-445E
2500
MW36-WDR
0.9 U
MW77-WD
11
MW78-WD
0.9 U
MW54-WD
0.9 U
MW123-WD
1.5
MW124-WD
0.49 J
MW125-WD
0.41 J
MW114-WD
0.96
MW103-WD
0.41 J
MW77-EW-1
3
MW77-EW-2
0.12 J
MW102-WD
1.1
MW98-WD
11
Mississippi Ave.
E. Jewell Ave.
Gun Club Road
Coal Creek
Un-Named Murphy Creek Tributary
Murphy Creek
UNNAMED CREEK
North Boundary Barrier Wall
North Toe
MURPHY CREEK
N
0 600 1,200 Feet
1 inch = 1,200 feet

**B-326-WD**
Compliance Monitoring Well
1,4-Dioxane Concentration (ug/L)
Start Injection at B-319 12/18/07
Start Extraction at MW113-EW-1 9/29/09
Start Injection at 3 IWs 11/8/10
Start Extraction at MW113-WD 7/2/07
1,4-D (ug/L)

**MW103-WD**
1,4-Dioxane Concentration (ug/L)

**B-313 (Compliance Well)**
1,4-DIOXANE
Concentration (ug/L)

**MW77-WD (Compliance Well)**
1,4-DIOXANE
Concentration (ug/L)

## Legend

- Increasing Trend
- No Trend; 1,4-Dioxane <= 0.9 µg/L
- Decreasing Trend; 1,4 Dioxane > 0.9 µg/L
- No Trend; 1,4 Dioxane > 0.9 µg/L
- Decreasing Trend; 1,4-Dioxane <= 0.9 µg/L
- Never Above Performance Standard

Note: 1,4-Dioxane values from last sampling date for 2nd half 2021

1,4 Dioxane > 0.9 µg/L in 2nd half 2021 (dashed where inferred)

**FIGURE 4.41**

**PROGRESS FROM RESPONSE ACTIONS**

**LAST SAMPLING DATE**


O&M Status Report - 2nd Half 2021
Lowry Landfill Superfund Site, Colorado

**PARSONS**


**Denver, Colorado**

S:\ES\Maj\Proj\LWRY\LNFL\QUARTERLY REPORTS\2ND HALF 2021\GIS\Fig4-41_14Diox_Sec1930_31_34Q21_MostRecent.mxd lxh 3/3/2022


# Figure 4.42
# North End Trend Analysis Plots - Area 5
# July through December 2021 Operations and Maintenance Status Report Lowry Landfill Superfund Site





**Graph 1**




**Graph 2**





**Graph 3**





**Graph 4**


# Figure 4.42
# North End Trend Analysis Plots - Area 5
# July through December 2021 Operations and Maintenance Status Report Lowry Landfill Superfund Site





Graph 5




Graph 6





Graph 7





Graph 8


# Figure 4.42
# North End Trend Analysis Plots - Area 5
# July through December 2021 Operations and Maintenance Status Report Lowry Landfill Superfund Site





**Graph 9**




**Graph 10**





**Graph 11**





**Graph 12**


# Figure 4.42
# North End Trend Analysis Plots - Area 5
# July through December 2021 Operations and Maintenance Status Report Lowry Landfill Superfund Site





**Graph 13**




**Graph 14**





**Graph 15**





**Graph 16**


# Figure 4.42
# North End Trend Analysis Plots - Area 5
# July through December 2021 Operations and Maintenance Status Report Lowry Landfill Superfund Site





**Graph 17**




**Graph 18**





**Graph 19**





**Graph 20**


# Figure 4.42
# North End Trend Analysis Plots - Area 5
# July through December 2021 Operations and Maintenance Status Report Lowry Landfill Superfund Site





**Graph 21**




**Graph 22**





**Graph 23**





**Graph 24**

# Figure 4.32
# North End Trend Analysis Plots - Area 5
# July through December 2021 Operations and Maintenance Status Report Lowry Landfill Superfund Site





**Graph 25**




**Graph 26**

**Analysis prepared using Sen's Test for trend and DUMPSTAT®**




LEGEND

MP-1 — LFG Monitoring Probe

5730 — Topographic Contour

N

0 300 600'

1"=600'

FIGURE 5.1


# GAS MONITORING PROBE LOCATION MAP

Lowry Landfill Superfund Site, Colorado

**PARSONS**

Denver, Colorado

S:\ES\CAD\LOWRYLF\727479\60030\02DN0036.dwg 02\27\14 SEH




LEGEND

SWMP-1 — STORMWATER SAMPLE LOCATION

5730 — TOPOGRAPHIC CONTOUR

NORTH BOUNDARY BARRIER WALL

STORMWATER DRAINAGEWAY AND FLOW DIRECTION

N

0 300 600

FEET

FIGURE 6.1

STORMWATER SAMPLE LOCATION

Lowry Landfill Superfund Site, Colorado


PARSONS

Denver, Colorado

S:\ES\MajProj\LWRYLNFL\QUARTERLY REPORTS\2ND HALF 2013\GIS\Fig6-1_09DN0046_StormWater.dwg- 01/28/2014 4:10PM jlh

Figure 9.1
Master Schedule

| ID | Task Name | Duration | Start | Finish |
|---|---|---|---|---|
| 1 | Update Site Management Plan | 136 edays | 2/26/21 | 7/12/21 |
| 2 | Agency Review/Comment Resolution/Approval | 292 edays | 7/12/21 | 4/30/22 |
| 3 | | | | |
| 4 | 2H 2021 O&M Status Report | 89 edays | 1/1/22 | 3/31/22 |
| 5 | 1H 2022 O&M Status Report | 91 edays | 7/1/22 | 9/30/22 |
| 6 | | | | |
| 7 | WTP Periodic Compliance Reports | 2000 edays | 1/1/21 | 6/24/26 |
| 8 | | | | |
| 9 | Update Contingency Plan | 171 edays | 6/25/21 | 12/13/21 |
| 10 | Agency Review/Comment Resolution/Approval | 169 edays | 12/13/21 | 5/31/22 |
| 11 | | | | |
| 12 | Update Records Management Plan | 29 edays | 6/1/22 | 6/30/22 |
| 13 | Agency Review/Comment Resolution/Approval | 31 edays | 6/30/22 | 7/31/22 |




Project: 2022 O&M Status Report
Date: 16 March 2022

Task | Milestone | Summary | Rolled Up Task

# APPENDIX A

# WATER TREATMENT PLANT

# APPENDIX A-1

# WTP WEEKLY SUMMARIES AND STANDARD OPERATIONS CHECKLISTS

# ABLE 3.19.1
# STANDARD OPERATIONS CHECKLIST
# MAIN WTP

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, July 01, 2021

**Inspection Performed by:** Mike Gelwick

### A. PERIMETER COLLECTION SYSTEMS

| Item | Status | Comments |
|---|---|---|
| LFG Cond Automatic Trap CT-1 | Sump Level: 12.79 ok | Counter: 175474 Cycles: 4 |
| LFG Cond Automatic Trap CT-2 | Sump Level: 8.76 ok | Counter: 272965 Cycles: 26 |
| LFG Cond Automatic Trap CT-3 | Sump Level: 7.55 ok | Counter: 293488 Cycles: 867 |
| CT-4 Containment/Vessel (LFG Cond) | ✓ Level: 70 % | Tank Level: 2.18 Counter: 191164 Cycles: 2 Sump: 8.90 ok |
| PM-15 Containment / Vessel | ✓ Level: 51 % | |
| MW-51 Containment / Vessel | ✓ Level: 65 % | |
| PM-11 Containment / Vessel | ✓ Level: 70 % | |
| MW-38 Systems | ✓ | |
| North Toe System | ✓ | |
| North End Systems (Weekly) | ✓ | |
| Full N. End Systems Check (Monthly) | ✓ | Last Done: 6-23-21 |
| North End Pipeline(s) Flushing (As Needed) | ✓ | Perform if suspended solids present Last Done: 11/15/15 |
| NTES line flush to T-530 (As needed) | ✓ | Perform if suspended solids present Last Done: 2/13/20 |
| NTES Piping Containment | ✓ | Monthly Sump Level: dry @ 16.07' Date: 6-17-21 |
| North Boundary System P-001: | CV 75.5% @ 7.5 gpm | 42.08 Hz / 2.11 Amps. / vault psi @ 18/Wolenes |
| T-101 & T-102 Containment / Tank | ✓ | Levels: 21 % & 21 % |
| Raw Water Storage Tanks Piping | ✓ | |
| RWST Building Temp. (TT-101) | 70.3 °F | Outside Temp.: ~ 69 °F |
| P-121 or P-122 | ✓ | 0.0 gpm / CV 58 % |
| RWST 2ndry Cont. High Level Switch | ✓ | (LSH-101) Last Test(monthly): 6-17-21 |
| RWST Back-Up Generator | ✓ | Last Test Run(monthly): 6-17-21 |

### B. CHEMICAL STORAGE BAYS

| Item | Status | Comments |
|---|---|---|
| Caustic Tote Levels | ✓ | ~590 Gallons Reserve = 0 |
| Caustic Bay Heater | ✓ | 58-celsius |
| Peroxide Tote Level | ✓ | ~ 200 Gallons Reserve = 1105 gal |
| HCL Tote Levels | ✓ | ~ 160 Gallons Reserve = ~300 gal |
| Chemical Totes and Piping Inspected | ✓ | Leaks observed: Y / (N) |
| Emergency Shower Inspected | ✓ | Checked and Flushed - All OK: (Y) / N |

### C. PRIMARY AND SECONDARY ACID FEED SYSTEM

| Item | Status | Comments |
|---|---|---|
| Primary Acid Feed Pump (P-631) | ✓ | |
| Ion Exchange Acid Feed Pump (P-632) | ✓ | PI-0632 PSI: 67 CV: 5 % |
| Primary Acid Retention Tank (T-510) | ✓ | |
| All Acid Feed Lines | ✓ | Leaks observed: Y / (N) |

### D. NBBW INJECTION TRENCH

| Item | Status | Comments |
|---|---|---|
| Injection Carbon (GAC-810) | OFFLINE | Date online: 7/20/18 |
| Injection Rate (FT-800) | 0.0 gpm | NBBW-IW-1= 0.0 NBBW-IW-2= 0.0 NBBW-IW-3= 0.0 gpm ea. |
| Totalizer Reading (FT-800) | 105,135,774 gal | INJ. STOPPED 10/02/18 @ 1545 |

# ABLE 3.19.1
# STANDARD OPERATIONS CHECKLIST
# MAIN WTP

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, July 01, 2021

**Inspection Performed by:** Mike Gelwick

### E. CHEMICAL PRECIPITATION SYSTEM (US FILTER HMR-30)

| Item | Status | Comment |
|---|---|---|
| T-300A Mixer | NA | |
| T-300B (Caustic Mixer) | ✓ | Last Cleaning (Qtrly): 6-3-21 |
| T-300A/B Water Level | ✓ | |
| T-300B (Caustic Mix Chamber) | ✓ | Last Cleaning (Qtrly): 6-3-21 |
| T-300A/B Overflow | ✓ | |
| pH Set-point for (pH 315) | Value: 10.8 | |
| pH 310 | Value: 6.82 | |
| pH 315 | Value: 10.87 | |
| Flocculation Chamber Paddle Wheel | ✓ | |
| Precipitate Floc Quality | ✓ | Good |
| Clarifier Water Quality | ✓ | Good Oil or sheen observed: Y / (N) |
| Clarifier Effluent Piping / Water Level | ✓ | |
| Clear-well Chamber and Water Level | ✓ | |
| HMR PLC Panel | ✓ | |
| Caustic Pump (P-270) | SB | |
| Caustic Pump (P-280) | ✓ | |
| Polymer Pump (P-310) | ✓ | |
| Polymer Tank Mixer | ✓ | |
| Polymer Tank Level | Gallons: ~ 550 | Just Refilled |
| Clear-well Transfer Pumps(P-371 /(372)) | ✓ | |
| Sludge Transfer Pump (P-330) | ✓ | Exercise Valves Weekly: Bottom or / Pull Suction to Side |
| Manual Sludge Lateral pumping | ✓ | Last done (As Needed): 5-2020 |
| Manual Sludge Lateral Ball Valves | ✓ | Exercise Weekly: All ok |
| Automatic Blow-down Operations | ✓ | |

### F. pH PROBES

| pH Probe Location | Calibration Date | Comments: (Time done) |
|---|---|---|
| pH-310 HMR-30 (T-300A) | 7-1-21-today | 1323 |
| pH-315 HMR-30 (T-300B) | | |
| pH-365 Primary Acid Ret. Tank | | |
| pH-113 Pre-Ion Exchange | | |
| pH-670 Pre-UV-OX | | 1359 |
| pH-740 Discharge Surge Tank | | Discharge suspended: 1315 ↔ 1322 |
| Out of Hold Double Check | ---------- | None in hold: ✓ ✓ ok |
| Valves Back to Normal Position | ---------- | All OK: ✓ ✓ ok |

### G. SLUDGE THICKENER, SLUDGE HOLDING TANKS, FILTER PRESS

| Item | Status | Comments |
|---|---|---|
| Verify Sludge Thickener Running | ✓ | Gauge Reading: 0 % |
| Sludge Thick. Transfer Pump (P-350) | ✓ | |
| Sludge Holding Tank (T-351) | ✓ | Level:~ 45 % |
| Sludge Holding Tank (T-352) | ✓ | Level: 41 % |
| Decant Transfer Pump (P-352) | ✓ | CV 44 % @0.8 gpm |
| Filter Press Pumps (P-381 / P-382) | ✓ | |
| Filter Press | ✓ | Stage: filling / stage 4 |

# ABLE 3.19.1
# STANDARD OPERATIONS CHECKLIST
# MAIN WTP

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, July 01, 2021

**Inspection Performed by:** Mike Gelwick

### H. ION EXCHANGE

| Item | Status | Comments |
|---|---|---|
| Feed Tank (T-113) | ✓ Level: 70 % | |
| Feed Pump (P-114) | ✓ Operating Press: 55.6 psi | CV@ 84 % @ 2.0 gpm |
| Retention Tank (T-114) | ✓ Operating Press: 54 psi | pH-113 @ 3.9 |
| Bag Filter (BF-113) | ✓ Operating Press: 52.5 psi | |
| Ion Exchange (Cage (1) or 2) + Guard | ✓ Operating Press: 54 psi | TP-1734 → TP-177A/9 cannisters + Guard |
| Post Ion Exchange | ✓ Operating Press: 3.5 psi | |

### I. FEED SURGE TANK

| Item | Status | Comments |
|---|---|---|
| Feed Surge Tank (T-520) | ✓ Level: 39 % | Last Cleaning (As Needed, if 4" of solids accumulate): 12/15/19 |
| Feed Surge Pump (P-521 or (P-522)) | Operating Press: 22 psi | CV@ 67 % @ 36.5 gpm |
| T-520 to GAC Total (FT-675) | 245564185 gal | Time: 1129 |
| North End On-Site Pumping | Operating Press: 2-3 psi | 13.2 gpm @ 1123 |
| North End Off-Site Pumping | Operating Press: 2-4 psi | 8.7 gpm @ 1123 |
| Peroxide Feed Pump (P-680) | ✓ | SPD 2.7 % / RATE 0.7 |
| Peroxide Conc. At (TP-710) | 1.0 PPM | |
| Peroxide Conc. At (TP-740) | 0.0 PPM | |

### J. HAZARDOUS WASTE STORAGE

| Item | Status | Comments |
|---|---|---|
| 180 Day storage area check | ✓ | Check sheet completed: NA/Empty |
| Satellite Haz. Waste Areas (BLDG #1) | ✓ | Condition: Good |
| Satellite Haz. Waste Area (BLDG #2) | ✓ | Condition: Good |

### K. UV-OXIDATION SYSTEM

| Item | Status | Comments |
|---|---|---|
| UV-Oxidation System | ✓ | |
| Annual Test Run (Calgon) | Date: 9-4-20 | Next: 8-2021 |
| Quarterly Test Run | Date: NA/Running | Next: NA/Running |
| Peroxide Feed Pump (P-650) | ✓ | Flow Rate: ~ 7.0 cc/min. |
| UV-Ox Power | ✓ | 25.7 kVA 26.52 Volts 9.8 Amps |
| Lamp Hours | 2629 Hrs | |
| Crystal Condition & Wiper Status | 6-27-21 | Oiler status: OK / Lubricated |
| UV-OX Bagfilters Status | Last change: 6-27-21 Cleaned: 6-27-21 | 11 psi In 11 psi Out |
| UV-OX Feed Pump ( P-600 or (P-601) ) | ✓ | CV@ 74 % @ 8.0 gpm |
| UV-OX Temperature | In(TT-670): 16.1 °C | Out(TT-710): 27.2 °C |
| PDU GAC (PDT-710) | ✓ | Δ Pressure: 3 psi |
| Peroxide Concentration Pre UV | 100 PPM | |
| Peroxide Concentration Post UV(TP-720) | 25 PPM | |
| Peroxide Conc. Post PDU (TP-730) | 0.0 PPM | |
| Secondary Acid Feed Pump (P-630) | ✓ | CV @ 1 % |
| Secondary Acid Retention Tank (T-645) | ✓ | |
| Pre – UV Oxidizer Total (FT-670) | 18833796 gal | Time: 1129 |
| Post UV-Ox / Pre PDU | ✓ | Pressure: 13 psi |
| Post PDU | ✓ | Pressure: 7 psi |

# ABLE 3.19.1
# STANDARD OPERATIONS CHECKLIST
# MAIN WTP

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, July 01, 2021

**Inspection Performed by:** Mike Gelwick

### L. PDU AND LIQUID –PHASE GRANULAR ACTIVATED CARBON

| Item | Status | Comments |
|---|---|---|
| PDT-720 | ✓ | Δ Pressure: 9 psi |
| PDT-730 | ✓ | Δ Pressure: 7 psi |

### M. EFFLUENT DISCHARGE

| Item | Status | Comments |
|---|---|---|
| Effluent Surge Pump (P751) or P752 ) | ✓ | CV@ 55.6 % |
| Effluent Surge Tank (T-740) | ✓ | Level: 40 % |
| Effluent Discharge Rate (FT-770) | ✓ | 36.2 gpm @ 1126 |
| POTW Line Pressure (PT-770) | ✓ | 32.6 psi |
| Effluent Totalizer Reading (FT-770) | 239635906 gal | Time: 1129 |
| POTW MH17S-078 Discharge Check (Monthly) | ✓ | Last Done: 5-18-21 |
| 4X8-Inch POTW Leak Detection Checks (Monthly) | ✓ | Last Done: ↓ |
| 4X8-Inch POTW Air Reliefs Checks (Monthly) | ✓ | Last Done: ↓ |
| 4X8-Inch POTW Isolation Valves Exercise (Qtrly) | ✓ | Last Done: 5-20-21 |
| 2-Inch POTW Backup Pressure Testing (Annual) | ✓ | Last Done: ~~5/19/20~~ 6-15-21 ok |
| 2-In POTW Backup Air Reliefs Checks (Annual) | ✓ | Last Done: 5/19/20 |
| 2-Inch POTW Isolation Valve Exercise (Annual) | ✓ | Last Done: 5/19/20 |
| Rotate Chiller Compressors | NA on Standby | ~~Now in Lead: 1 or 2~~ |

### N. LEL EFFLUENT TANK T-740

| Item | Status | Comments |
|---|---|---|
| LEL-740 Sensor | ✓ | Reading: 0 % |
| LEL Sensor Calibration / Automatic High LEL Shutdown Test (monthly) | Last Completed: 6-24-21 | Plant Effluent Suspended: 1255 ↔ 1315 |
| LEL Sensor Bridge Adjustment to 2.0 volts | Reading: 2.001 volts(monthly) | Adjustment Needed: Ⓨ or N |
| Verify Bridge Current between.300v-.360v | Reading: 0.331 volts(monthly) | 1.998→2.001 / 47% → 49% LEL |

### O. WTP INFLUENT TOTALIZERS Time : 1130-1135

| Source | Reading(Gallons) | Source | Reading(Gallons) |
|---|---|---|---|
| (FT-015) RWST Influent | 19535935 | (FT-505) LFG Cond. to T-530 | 214124 |
| (FT-025) NBBW Influent | 92832738 | (FT-056) Off - Site N. End Influent | 41796300 |
| (FT-012) MW-38 Inf. to HMR-30 | 7956045 | (FT-113) Ion Exchange Influent | 319391 |
| (FT-042 HMR30) MW-38 Source to HMR-30 | 35484 ~~35840~~ | (FT-810) Plant Potable Water In | 30046936 |
| (FT-043) MW-38 to RWST | 3061772 | (FT-026) NBBW Bypass to RWST | 4358374 |
| (FT-042 RWST) MW-38 Source to RWST | 72236 | (FT-014) Misc. Water to RWST | 8094579 |
| (FT-012T) MW-38 to T-540/541 | 8572115 | (FT-035) NTES Inf. to BIO | 6581370 |
| (FT-040T) MW-38N to T-540/541 | 1976318 | (FT-035T) NTES to T-530 | 457427 |
| (FT-041T) MW-38S to T-540/541 | 2694046 | (FT-017) BIO Inf. from T-530 | 645359 |
| (FT-042T) MW-38 Source to T-540/541 | 3973705 | (FT-018) T-540/541 Influent | 8617680 |
| (FT-055) On - Site N. End Influent | 95943505 | (FT-352) T-352 to HMR-30 | 1239498 |

# ABLE 3.19.1
# STANDARD OPERATIONS CHECKLIST
# MAIN WTP

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, July 01, 2021

**Inspection Performed by:** Mike Gelwick

### P. AIR COMPRESSORS

| Item | Status | Comments |
|---|---|---|
| Compressor Intake Temp. | 70 °F (Analog Gauge) | Outside Temp.: ~ 71 °F |
| Compressor Building Vent | ✓ | open-ended vent |
| Primary Air Compressor (IRN30H) | 2,000 Hour service date: 1-20-21 Serviced @ 58736 Hours | Coolant present in sight glass: (Y) / N Next service @ 60736 Hours Current Hours @ 60857 |
| IRN30H Motor Speed | 31 % | |
| IRN30H Pressure | 111 psi | |
| IRN30H Moisture purge valve chk(Weekly): | ✓ | |
| IRN30H Intake Filter | ✓ | Date Last Changed: 5-20-21 |
| Air Tanks Moisture Purge Valves | Manually Activate(weekly) ✓ | Excessive Moisture: Y / (N) |
| Backup Air Compressors (T-30 East and West) | ✓ | Both cool to touch: (Y) / N |
| Air Dryer | ✓ Eco on | Moisture at Receiver Tank: Y / (N) |
| Oil Moisture Prevention (Monthly) | Last Done: 6-24-21 | Run at max speed by bleeding air from filter canister above/after air dryer for 2 hrs |
| Air Receiver Tank | ✓ | 110 psi |

### Q. SUMPS

| Item | Status | Comments |
|---|---|---|
| Bag Filter Sump | ✓ | |
| Wet Well Sump | ✓ | |

### R. GAS CHROMATOGRAPH

| Item | Status | Comments |
|---|---|---|
| GC Operational | ✓ | GC # checking UV-Ox Effluent: 2 |
| Alarms Enabled | ✓ | |
| GC Influent Filters | ✓ | |

### S. SAFETY

| Item | Status | Comments |
|---|---|---|
| Building #1 Fire Extinguishers | ✓ | Date inspected: 6-23-21 |
| Building #1 Eye Wash/Shower | ✓ | Checked and Flushed- All OK: (Y) / N |

**Other Comments**:

| |
|---|
| Sludge Transfer Pump TDP valve vertical to open, levels replaced |
| |
| |
| |
| |

# TABLE 3.19.2
# STANDARD OPERATIONS CHECKLIST
# BIOLOGICAL TREATMENT SYSTEM

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, July 01, 2021

**Inspection Performed by:** Mike Gelwick

## A. PUMPS

| Item | Status | Flow Rate (gpm) | Pump Speed (CV%) | Discharge Pressure (psi) | Comments |
|---|---|---|---|---|---|
| **T-510 Pumps** | | | | | |
| P-3301 | SB | – | – % | – | |
| P-3301A | ✓ | 4.0 | 61.8 % | 14.0 | |
| **NTES Pump** P-002(Sump) / (P-002W(10R)) | ✓ | 0.51 | 49 % | P035 36-37 / P038 6.0 | Globules Observed at TP-130: Y / (N) Time: 1020 |
| **T-530** P-005 | ✓ | 0.21 | 33 % | 5 | |
| **T-540/541** P-006 | ✓ | 0.30 | 49 % | 3.5 | |
| **LFG COND Auto-Traps** | ✓ | 0.0 | NA | 4 | Between Cycles: (Y) / N |
| **Reactor Feed Pumps** | | | | | |
| P-3321 | ✓ | 2.62 | 59.0 % | 6.5 | |
| P-3322 | ✓ | 3.62 | 46.3 % | 5.0 | |
| P-3323 | ✓ | 2.58 | 67.8 % | 6.5 | |
| P-3324 | SB | – | – % | – | |
| **Reactor Effluent Pumps** | | | | | |
| P-3341 | ✓ | 4.32 | 70.5 % | 20 | |
| P-3341A | SB | – | – % | – | |

## B. BLOWERS

| Item | Status | Pressure (psi) | Temp (°F) | Next Scheduled Service (Qtrly) | Comments Last serviced on: 6-22-21 |
|---|---|---|---|---|---|
| B-3331 | ✓ | 4.26 | 150 | 9-2021 | Greased, Belt and Filter Checked: (Y) / N |
| B-3332 | SB | – | – | ↓ | Belt and Filter Checked: Y / (N) |
| B-3333 | ✓ | 4.47 | 156 | ↓ | Greased, Belt and Filter Checked: (Y) / N |
| B-3334 | ✓ | 4.24 | 148 | ↓ | Greased, Belt and Filter Checked: (Y) / N |

## C. REACTOR VENTILATION

| Item | Status | Comments |
|---|---|---|
| Vapor Carbon Contactor | ✓ | On-line: 2/10/18 |
| Reactor Vent Blower | ✓ | |
| Reactor Vent Booster | ✓ | |
| VTP-3350 | ✓ | PID Reading: 19.6 PPM |
| VTP-3360 | ✓ | PID Reading: 9.6 PPM |

# TABLE 3.19.2
# STANDARD OPERATIONS CHECKLIST
# BIOLOGICAL TREATMENT SYSTEM

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, July 01, 2021

**Inspection Performed by:** Mike Gelwick

## D. TANKS / REACTORS / SUMPS / CONTAINMENTS / PIPING / Chiller

| Item | Status | Comments |
|---|---|---|
| T-510 Post HMR-30 Mixing Tank | ✓ Level: 69 % | Last Cleaning (As needed, if 2" of solids accumulate): 12/15/19 |
| T-530 LFG Condensate / NTES Tank | ✓ Level: 34 % | |
| T-530 Mixer | ✓ | |
| LFG Condensate Conveyance Line | ✓ | Last Pressure Test: 8-10-20 Next: 8-2021 (Annual at a minimum or if flow drops off) |
| T-540/541 MW38 Tanks | Lvls: 66 % & 67% | |
| T-540/541 Mixers | ✓ | |
| Chiller | ✓ | Chiller Coolant Lvl: ~ 0.50" Below full mark |
| Chiller Cooling Fins (as needed) | ✓ | Last Cleaning: 4/20/18 (unit on Standby) |
| Secondary Containments | ✓ | Heat Trace: On OK / (Off Warm out) |
| Feed Piping to Sedimentation Tank | ✓ | Last Back Flushing (Quarterly): 6-14-21 |
| T-3310 Sedimentation Tank | Visual Level: OK | Last Cleaning (As Needed, use TSS info to determine): 12/2017 |
| T-3320 Blend Tank | ✓ Level: 73 % | Last Cleaning (Semi Annual): 5-7-20 |
| T-3331 Reactor No. 1 | ✓ | Digital Displays: (GOOD) / Needs Attn |
| T-3332 Reactor No. 2 | ✓ | Digital Displays: (GOOD) / Needs Attn |
| T-3333 Reactor No. 3 | ✓ | Digital Displays: (GOOD) / Needs Attn |
| T-3334 Settling Tank | ✓ | Last Cleaning (Semi Annual): 5-7-20 |
| P-3334 Biosolids Pump | ✓ | |
| T-3340 Overflow Tank | ✓ Level: 30 % | |
| Recycle Valve to Blend Tank | ✓ | 4.01 gpm @ 1142 |
| Building Containment Sump | ✓ | Last Alarm Test Date (Monthly): 6-17-21 |

## E. CHEMICAL FEED SYSTEM

| Item | Status | Comments |
|---|---|---|
| Phosphorous Supply | ✓ | Bags: 19.75 Gallons: ~ 75 |
| Phosphorous Pump (P-2221) | ✓ | |
| Caustic Supply | ✓ | ~ 40 Gallons |
| Caustic Pump (P-2211) | SB | Currently in acid addition mode |
| Acid Supply | ✓ | ~ 40 Gallons |
| Acid Pump (P-2211) | ✓ | |
| Caustic Pump (P-2231) | ✓ Leaks: Y / (N) | Last tubing tip cleaning (monthly): 6-17-21 |
| Caustic Pump (P-2232) | ✓ Leaks: Y / (N) | Last tubing tip cleaning (monthly): ↓ |
| Caustic Pump (P-2233) | ✓ Leaks: Y / (N) | Last tubing tip cleaning (monthly): |

# TABLE 3.19.2
# STANDARD OPERATIONS CHECKLIST
# BIOLOGICAL TREATMENT SYSTEM

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, July 01, 2021

**Inspection Performed by:** Mike Gelwick

### F. pH Probes

| pH Probe Location | Calibration Date (Monthly) | Comments |
|---|---|---|
| pH-3320 Blend Tank | 6-24-21 | Starting off Clean today |
| pH-3331 Reactor 1 | ↓ | ↓ |
| pH-3332 Reactor 2 | | |
| pH-3333 Reactor 3 | | |

### G. FILTER SYSTEM

| Item | Status | Comments |
|---|---|---|
| BF-3340 a/b Status | ✓ | |
| Automatic Backwash | Cycle Count: 59 | Auto |
| BF-3340 a/b Differential Pressure | PSI: 1 | 10/11 @ 4.5 gpm |
| 75-micron Bags Last Cleaning | Date: 11-14-19 | |
| 75-micron Bags Last Inspection | Date: ↓ | |
| 75-micron Bags Last Changed | Date: | |
| GACF-3340 Status | ✓ | |
| GACF-3340 Differential Pressure | PSI: 5 | 11/6 @ 3.9 gpm |
| Last Backwash Performed | Date: 6-17-21 | |

### H. ELECTRICAL AND INSTRUMENTATION

| Item | Status | Comments |
|---|---|---|
| "BIO" Backup Generator | ✓ | Block Heater: On OK / (Off Warm Out) |
| Electrical Surge Suppressor | ✓ | |
| Motor Control Center | ✓ | |
| PLC | ✓ | UPS @ 97 min / 71 Events |
| HMI's | ✓ | |
| BTS Process KWH Meter | 1776024 KWH | Time: 1212 |
| Building#2 KWH Meter | 5190989 KWH | Time: 1212 |

### I. GAS CHROMATOGRAPHY

| Item | Status | Comments |
|---|---|---|
| GC Operational | ✓ | GC # checking BIO: 3 |
| Alarms Enabled | ✓ | |
| GC Influent Filters | ✓ | |

# TABLE 3.19.2
# STANDARD OPERATIONS CHECKLIST
# BIOLOGICAL TREATMENT SYSTEM

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, July 01, 2021

**Inspection Performed by:** Mike Gelwick

## J. TOTALIZERS

| Item | Readings (gallons) | Comments |
|---|---|---|
| FT-3321 Feed to Reactor 1 | 5670946 | |
| FT-3324 Feed Spare | 45618 | |
| FT-3322 Feed to Reactor 2 | 10226436 | |
| FT-3323 Feed to Reactor 3 | 349091 | |
| FT-3301 T-510 to BIO | 51132798 | |
| FT-3341 BIO Effluent | 65811262 | |
| FT-3342 BIO Recycle | 54839734 | |

## K. SAFETY

| Item | Status | Comments |
|---|---|---|
| Building #2 Fire Extinguishers | ✓ | Inspection date: 6-23-21 |
| Building #2 Eye Wash/Shower | ✓ | Checked and Flushed- All OK: Ⓨ / N |

## L. OTHER COMMENTS:

| |
|---|
| |
| |
| |
| |

# ABLE 3.19.1
# STANDARD OPERATIONS CHECKLIST
# MAIN WTP

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, July 08, 2021

**Inspection Performed by:** Mike Gelwick

## A. PERIMETER COLLECTION SYSTEMS

| Item | Status | Comments |
|---|---|---|
| LFG Cond Automatic Trap CT-1 | Sump Level: 12.76 oz | Counter: 175944 Cycles: 470 |
| LFG Cond Automatic Trap CT-2 | Sump Level: 8.73 oz | Counter: 273036 Cycles: 71 |
| LFG Cond Automatic Trap CT-3 | Sump Level: 7.45 oz | Counter: 295259 Cycles: 1771 |
| CT-4 Containment/Vessel (LFG Cond) | ✓ Level: 70 % | Tank Level: 2.18 Counter: 191164 Cycles: 0 Sump: 9.01 oz |
| PM-15 Containment / Vessel | ✓ Level: 60 % | |
| MW-51 Containment / Vessel | ✓ Level: 30 % | |
| PM-11 Containment / Vessel | ✓ Level: 25 % | |
| MW-38 Systems | ✓ | |
| North Toe System | ✓ | |
| North End Systems (Weekly) | ✓ | |
| Full N. End Systems Check (Monthly) | ✓ | Last Done: 6-23-21 |
| North End Pipeline(s)Flushing (As Needed) | ✓ | Perform if suspended solids present Last Done: 11/15/15 |
| NTES line flush to T-530 (As needed) | ✓ | Perform if suspended solids present Last Done: 2/13/20 |
| NTES Piping Containment | ✓ | Monthly Sump Level: Dry = 16.07' Date: 6-17-21 |
| North Boundary System P-001: | CV 75.8 % @ 7.6 gpm | 42.38 Hz / 2.11 Amps. / vault psi @ 18/No leaks |
| T-101 & T-102 Containment / Tank | ✓ | Levels: 28 % & 26 % |
| Raw Water Storage Tanks Piping | ✓ | |
| RWST Building Temp. (TT-101) | 73.9 °F | Outside Temp.: ~ 81 °F |
| (P-121) or P-122 | ✓ | 0.6 gpm / CV 61 % |
| RWST 2ndry Cont. High Level Switch | ✓ | (LSH-101) Last Test(monthly): 6-17-21 |
| RWST Back-Up Generator | ✓ | Last Test Run(monthly): 6-17-21 |

## B. CHEMICAL STORAGE BAYS

| Item | Status | Comments |
|---|---|---|
| Caustic Tote Levels | ✓ | ~ 420 Gallons Reserve = 2 totes |
| Caustic Bay Heater | ✓ | 58-warmest |
| Peroxide Tote Level | ✓ | ~ 175 Gallons Reserve = ~105 gal |
| HCL Tote Levels | ✓ | ~ 115 Gallons Reserve = ~30 gal |
| Chemical Totes and Piping Inspected | ✓ | Leaks observed: Y / (N) |
| Emergency Shower Inspected | ✓ | Checked and Flushed - All OK: (Y) / N |

## C. PRIMARY AND SECONDARY ACID FEED SYSTEM

| Item | Status | Comments |
|---|---|---|
| Primary Acid Feed Pump (P-631) | ✓ | |
| Ion Exchange Acid Feed Pump (P-632) | ✓ | PI-0632 PSI: 66-68 CV: 5 % |
| Primary Acid Retention Tank (T-510) | ✓ | |
| All Acid Feed Lines | ✓ | Leaks observed: Y / (N) |

## D. NBBW INJECTION TRENCH

| Item | Status | Comments |
|---|---|---|
| Injection Carbon (GAC-810) | OFFLINE | Date online: 7/20/18 |
| Injection Rate (FT-800) | 0.0 gpm | NBBW-IW-1= 0.0 NBBW-IW-2= 0.0 NBBW-IW-3= 0.0 gpm ea. |
| Totalizer Reading (FT-800) | 105,135,774 gal | INJ. STOPPED 10/02/18 @ 1545 |

# ABLE 3.19.1
# STANDARD OPERATIONS CHECKLIST
# MAIN WTP

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, July 08, 2021

**Inspection Performed by:** Mike Gelwick

## E. CHEMICAL PRECIPITATION SYSTEM (US FILTER HMR-30)

| Item | Status | Comment |
|---|---|---|
| T-300A Mixer | NA | |
| T-300B (Caustic Mixer) | ✓ | Last Cleaning (Qtrly): 6-3-21 |
| T-300A/B Water Level | ✓ | |
| T-300B (Caustic Mix Chamber) | ✓ | Last Cleaning (Qtrly): 6-3-21 |
| T-300A/B Overflow | ✓ | |
| pH Set-point for (pH 315) | Value: 10.8 | |
| pH 310 | Value: 6.73 | |
| pH 315 | Value: 10.92 | |
| Flocculation Chamber Paddle Wheel | ✓ | |
| Precipitate Floc Quality | ✓ | Good |
| Clarifier Water Quality | ✓ | Good Oil or sheen observed: Y / (N) |
| Clarifier Effluent Piping / Water Level | ✓ | |
| Clear-well Chamber and Water Level | ✓ | |
| HMR PLC Panel | ✓ | |
| Caustic Pump (P-270) | SB | |
| Caustic Pump (P-280) | ✓ | |
| Polymer Pump (P-310) | ✓ | |
| Polymer Tank Mixer | ✓ | |
| Polymer Tank Level | Gallons: ~ 475 | |
| Clear-well Transfer Pumps(P-371 /(372)) | ✓ | |
| Sludge Transfer Pump (P-330) | ✓ | Exercise Valves Weekly: Bottom ok / TOP sized to open |
| Manual Sludge Lateral pumping | ✓ | Last done (As Needed): 3-2020 |
| Manual Sludge Lateral Ball Valves | ✓ | Exercise Weekly: All ok |
| Automatic Blow-down Operations | ✓ | |

## F. pH PROBES

| pH Probe Location | Calibration Date | Comments: (Time done) |
|---|---|---|
| pH-310 HMR-30 (T-300A) | 7-8-21 Today | 1300 |
| pH-315 HMR-30 (T-300B) | | |
| pH-365 Primary Acid Ret. Tank | | |
| pH-113 Pre-Ion Exchange | | |
| pH-670 Pre-UV-OX | | 1330 |
| pH-740 Discharge Surge Tank | | Discharge suspended: 1251 ↔ 1258 |
| Out of Hold Double Check | ---------- | None in hold: ✓✓ |
| Valves Back to Normal Position | ---------- | All OK: ✓✓ |

## G. SLUDGE THICKENER, SLUDGE HOLDING TANKS, FILTER PRESS

| Item | Status | Comments |
|---|---|---|
| Verify Sludge Thickener Running | ✓ | Gauge Reading: 0 % |
| Sludge Thick. Transfer Pump (P-350) | ✓ | |
| Sludge Holding Tank (T-351) | ✓ | Level: ~ 65 % |
| Sludge Holding Tank (T-352) | ✓ | Level: 57 % |
| Decant Transfer Pump (P-352) | ✓ | CV 31 % @ 0.6 gpm |
| Filter Press Pumps (P-381 / P-382) | ✓ | |
| Filter Press | ✓ | Stage: Full |

# ABLE 3.19.1
# STANDARD OPERATIONS CHECKLIST
# MAIN WTP

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, July 08, 2021

**Inspection Performed by:** Mike Gelwick

### H. ION EXCHANGE

| Item | Status | Comments |
|---|---|---|
| Feed Tank (T-113) | ✓ Level: 52 % | |
| Feed Pump (P-114) | Operating Press: 55.5 psi | CV@ 82 % @ 2.0 gpm |
| Retention Tank (T-114) | Operating Press: 54 psi | pH-113 @ 3.91 |
| Bag Filter (BF-113) | Operating Press: 56 psi | |
| Ion Exchange (Cage (1) or 2) + Guard | Operating Press: 54 psi | TP-123A → TP-177A / 9 canisters + Guard |
| Post Ion Exchange | Operating Press: 3.5 psi | |

### I. FEED SURGE TANK

| Item | Status | Comments |
|---|---|---|
| Feed Surge Tank (T-520) | ✓ Level: 38 % | Last Cleaning (As Needed, if 4" of solids accumulate): 12/15/19 |
| Feed Surge Pump (P-521 or (P-522)) | Operating Press: 24 psi | CV@ 68 % @ 35.7 gpm |
| T-520 to GAC Total (FT-675) | 24591727 gal | Time: 0929 |
| North End On-Site Pumping | Operating Press: 2-4 psi | 13.3 gpm @ 0918 |
| North End Off-Site Pumping | Operating Press: 2-6 psi | 8.8 gpm @ 0918 |
| Peroxide Feed Pump (P-680) | ✓ | SPD 2.7 % / RATE 0.7 |
| Peroxide Conc. At (TP-710) | 1.0 PPM | |
| Peroxide Conc. At (TP-740) | 0.0 PPM | |

### J. HAZARDOUS WASTE STORAGE

| Item | Status | Comments |
|---|---|---|
| 180 Day storage area check | ✓ | Check sheet completed: NA/Empty |
| Satellite Haz. Waste Areas (BLDG #1) | ✓ | Condition: Good |
| Satellite Haz. Waste Area (BLDG #2) | ✓ | Condition: Good |

### K. UV-OXIDATION SYSTEM

| Item | Status | Comments |
|---|---|---|
| UV-Oxidation System | ✓ | |
| Annual Test Run (Calgon) | Date: 8-4-20 | Next: 8-2021 |
| Quarterly Test Run | Date: NA/Annually | Next: NA/Annually |
| Peroxide Feed Pump (P-650) | ✓ | Flow Rate: ~ 7.0 cc/min. |
| UV-Ox Power | ✓ | 25.7 kVA 2628 Volts 9.8 Amps |
| Lamp Hours | 2794 Hrs | |
| Crystal Condition & Wiper Status | ✓ | Oiler status: OK |
| UV-OX Bagfilters Status | Last change: 6-27-21 Cleaned: 6-27-21 | 110 psi In 110 psi Out |
| UV-OX Feed Pump ( P-600 or (P-601) ) | ✓ | CV@ 76 % @ 8.0 gpm |
| UV-OX Temperature | In(TT-670): 16.1 °C | Out(TT-710): 27.1 °C |
| PDU GAC (PDT-710) | ✓ | Δ Pressure: 3 psi |
| Peroxide Concentration Pre UV | 100 PPM | |
| Peroxide Concentration Post UV(TP-720) | 20 PPM | |
| Peroxide Conc. Post PDU (TP-730) | 0.0 PPM | |
| Secondary Acid Feed Pump (P-630) | ✓ | CV @ 2 % |
| Secondary Acid Retention Tank (T-645) | ✓ | |
| Pre – UV Oxidizer Total (FT-670) | 18911032 gal | Time: 0930 |
| Post UV-Ox / Pre PDU | ✓ | Pressure: 13 psi |
| Post PDU | ✓ | Pressure: 7 psi |

# ABLE 3.19.1
# STANDARD OPERATIONS CHECKLIST
# MAIN WTP

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, July 08, 2021

**Inspection Performed by:** Mike Gelwick

### L. PDU AND LIQUID –PHASE GRANULAR ACTIVATED CARBON

| Item | Status | Comments |
|---|---|---|
| PDT-720 | ✓ | Δ Pressure: 10 psi |
| PDT-730 | ✓ | Δ Pressure: 8 psi |

### M. EFFLUENT DISCHARGE

| Item | Status | Comments |
|---|---|---|
| Effluent Surge Pump ((P751) or P752 ) | ✓ | CV@ 55.5 % |
| Effluent Surge Tank (T-740) | ✓ | Level: 40 % |
| Effluent Discharge Rate (FT-770) | ✓ | 35.7 gpm @ 0927 |
| POTW Line Pressure (PT-770) | ✓ | 32.5 psi |
| Effluent Totalizer Reading (FT-770) | 239988114 gal | Time: 0930 |
| POTW MH17S-078 Discharge Check (Monthly) | ✓ | Last Done: 7-8-21 |
| 4X8-Inch POTW Leak Detection Checks (Monthly) | ✓ | Last Done: |
| 4X8-Inch POTW Air Reliefs Checks (Monthly) | ✓ | Last Done: |
| 4X8-Inch POTW Isolation Valves Exercise (Qtrly) | ✓ | Last Done: |
| 2-Inch POTW Backup Pressure Testing (Annual) | ✓ | Last Done: ~~5/19/20~~ |
| 2-In POTW Backup Air Reliefs Checks (Annual) | ✓ | Last Done: ~~5/19/20~~ |
| 2-Inch POTW Isolation Valve Exercise (Annual) | ✓ | Last Done: ~~5/19/20~~ |
| Rotate Chiller Compressors | NA on Standby | ~~Now in Lead: 1 or 2~~ |

### N. LEL EFFLUENT TANK T-740

| Item | Status | Comments |
|---|---|---|
| LEL-740 Sensor | ✓ | Reading: 0 % |
| LEL Sensor Calibration / Automatic High LEL Shutdown Test (monthly) | Last Completed: 6-24-21 | Plant Effluent Suspended: 1255 ↔ 1315 |
| LEL Sensor Bridge Adjustment to 2.0 volts | Reading: 2.001 volts(monthly) | Adjustment Needed: (Y) or N |
| Verify Bridge Current between.300v-.360v | Reading: 0.331 volts(monthly) | 1.998→2.001 / 47% → 49% LEL |

### O. WTP INFLUENT TOTALIZERS Time : 0930- 0935

| Source | Reading(Gallons) | Source | Reading(Gallons) |
|---|---|---|---|
| (FT-015) RWST Influent | 19541777 | (FT-505) LFG Cond. to T-530 | 214276 |
| (FT-025) NBBW Influent | 92906687 | (FT-056) Off - Site N. End Influent | 41880576 |
| (FT-012) MW-38 Inf. to HMR-30 | 7979314 | (FT-113) Ion Exchange Influent | 338916 |
| (FT-042 HMR30) MW-38 Source to HMR-30 | 35484 | (FT-810) Plant Potable Water In | 30048320 |
| (FT-043) MW-38 to RWST | 3062136 | (FT-026) NBBW Bypass to RWST | 4359669 |
| (FT-042 RWST) MW-38 Source to RWST | 72236 | (FT-014) Misc. Water to RWST | 8099458 |
| (FT-012T) MW-38 to T-540/541 | 8572115 | (FT-035) NTES Inf. to BIO | 6586250 |
| (FT-040T) MW-38N to T-540/541 | 1976318 | (FT-035T) NTES to T-530 | 457555 |
| (FT-041T) MW-38S to T-540/541 | 2694046 | (FT-017) BIO Inf. from T-530 | 645871 |
| (FT-042T) MW-38 Source to T-540/541 | 3973705 | (FT-018) T-540/541 Influent | 8620591 |
| (FT-055) On - Site N. End Influent | 96075748 | (FT-352) T-352 to HMR-30 | 1241188 |

# ABLE 3.19.1
# STANDARD OPERATIONS CHECKLIST
# MAIN WTP

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, July 08, 2021

**Inspection Performed by:** Mike Gelwick

### P. AIR COMPRESSORS

| Item | Status | Comments |
|---|---|---|
| Compressor Intake Temp. | 79 °F (Analog Gauge) | Outside Temp.: ~ 85 °F |
| Compressor Building Vent | ✓ | open - all around |
| Primary Air Compressor (IRN30H) | 2,000 Hour service date: 7-8-21 today<br>Serviced @ 60952 Hours | Coolant present in sight glass: Ⓨ / N<br>Next service @ 62952 Hours<br>Current Hours @ 60952 |
| IRN30H Motor Speed | – % | Getting serviced currently off |
| IRN30H Pressure | – psi | |
| IRN30H Moisture purge valve chk(Weekly): | ✓ | |
| IRN30H Intake Filter | ✓ | Date Last Changed: 7-8-21 |
| Air Tanks Moisture Purge Valves | Manually Activate(weekly) ✓ | Excessive Moisture: Y / Ⓝ |
| Backup Air Compressors (T-30 East and West) | ✓ | Running during service<br>Both cool to touch: Y / Ⓝ |
| Air Dryer | ✓ Eco on | Moisture at Receiver Tank: Y / Ⓝ |
| Oil Moisture Prevention (Monthly) | Last Done: 6-24-21 | Run at max speed by bleeding air from filter canister above/after air dryer for 2 hrs |
| Air Receiver Tank | ✓ | 110 psi |

### Q. SUMPS

| Item | Status | Comments |
|---|---|---|
| Bag Filter Sump | ✓ | |
| Wet Well Sump | ✓ | |

### R. GAS CHROMATOGRAPH

| Item | Status | Comments |
|---|---|---|
| GC Operational | ✓ | GC # checking UV-Ox Effluent: # 2 |
| Alarms Enabled | ✓ | Calibration - Ethane 7-7-21 |
| GC Influent Filters | ✓ | ✓ |

### S. SAFETY

| Item | Status | Comments |
|---|---|---|
| Building #1 Fire Extinguishers | ✓ | Date inspected: 6-23-21 |
| Building #1 Eye Wash/Shower | ✓ | Checked and Flushed- All OK: Ⓨ / N |

**Other Comments:**

| |
|---|
| #M30 sludge transfer pump head & top valve replaced. Started to clean. |
| |
| |
| |
| |

# TABLE 3.19.2
# STANDARD OPERATIONS CHECKLIST
# BIOLOGICAL TREATMENT SYSTEM

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, July 08, 2021

**Inspection Performed by:** Mike Gelwick

## A. PUMPS

| Item | Status | Flow Rate (gpm) | Pump Speed (CV%) | Discharge Pressure (psi) | Comments |
|---|---|---|---|---|---|
| **T-510 Pumps** | | | | | |
| P-3301 | SB | – | – % | – | |
| P-3301A | ✓ | 4.0 | 52.7 % | 11.5 | |
| **NTES Pump** P-002(Sump) / (P-002W(10R)) | ✓ | 0.50 | 48 % | P035 3637 / P038 6.0 | Globules Observed at TP-130: Y / (N) Time: 0840 |
| **T-530** P-005 | ✓ | 0.20 | 32 % | 5.0 | |
| **T-540/541** P-006 | ✓ | 0.29 | 53 % | 3.5 | |
| **LFG COND Auto-Traps** | ✓ | 0.0 | NA | 4.0 | Between Cycles: (Y) / N |
| **Reactor Feed Pumps** | | | | | |
| P-3321 | ✓ | 2.66 | 65.9 % | 8.0 | |
| P-3322 | ✓ | 3.68 | 53.4 % | 6.0 | |
| P-3323 | & ✓ | 2.66 | 79.1 % | 8.0 | |
| P-3324 | SB | – | – % | – | |
| **Reactor Effluent Pumps** | | | | | |
| P-3341 | ✓ | 4.30 | 76.1 % | 26.0 | |
| P-3341A | SB | – | – % | – | |

## B. BLOWERS

| Item | Status | Pressure (psi) | Temp (°F) | Next Scheduled Service (Qtrly) | Comments Last serviced on: 6-22-21 |
|---|---|---|---|---|---|
| B-3331 | ✓ | 4.26 | 154 | 9-2021 | Greased, Belt and Filter Checked: (Y) / N |
| B-3332 | SB | – | – | ↓ | Belt and Filter Checked: Y / (N) |
| B-3333 | ✓ | 4.47 | 162 | | Greased, Belt and Filter Checked: (Y) / N |
| B-3334 | ✓ | 4.21 | 150 | | Greased, Belt and Filter Checked: (Y) / N |

## C. REACTOR VENTILATION

| Item | Status | Comments |
|---|---|---|
| Vapor Carbon Contactor | ✓ | On-line: 2/10/18 |
| Reactor Vent Blower | ✓ | |
| Reactor Vent Booster | ✓ | |
| VTP-3350 | ✓ | PID Reading: 3.1 PPM |
| VTP-3360 | ✓ | PID Reading: 0.6 PPM |

# TABLE 3.19.2
# STANDARD OPERATIONS CHECKLIST
# BIOLOGICAL TREATMENT SYSTEM

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, July 08, 2021

**Inspection Performed by:** Mike Gelwick

## D. TANKS / REACTORS / SUMPS / CONTAINMENTS / PIPING / Chiller

| Item | Status | Comments |
|---|---|---|
| T-510 Post HMR-30 Mixing Tank | ✓ Level: 70 % | Last Cleaning (As needed, if 2" of solids accumulate): 12/15/19 |
| T-530 LFG Condensate / NTES Tank | ✓ Level: 30 % | |
| T-530 Mixer | ✓ | |
| LFG Condensate Conveyance Line | ✓ | Last Pressure Test: 8-10-20 Next: 8-2021 (Annual at a minimum or if flow drops off) |
| T-540/541 MW38 Tanks | Lvls: 44 % & 45% | |
| T-540/541 Mixers | ✓ | |
| Chiller | ✓ | Chiller Coolant Lvl: ~.75 " Below full mark |
| Chiller Cooling Fins (as needed) | ✓ | Last Cleaning: 4/20/18 (unit on Standby) |
| Secondary Containments | ✓ | Heat Trace: On OK / (Off Warm out) |
| Feed Piping to Sedimentation Tank | ✓ | Last Back Flushing (Quarterly): 6-14-21 |
| T-3310 Sedimentation Tank | Visual Level: ok | Last Cleaning (As Needed, use TSS info to determine): 12/2017 |
| T-3320 Blend Tank | ✓ Level: 71 % | Last Cleaning (Semi Annual): 5-7-20 |
| T-3331 Reactor No. 1 | ✓ | Digital Displays: (GOOD) / Needs Attn |
| T-3332 Reactor No. 2 | ✓ | Digital Displays: (GOOD) / Needs Attn |
| T-3333 Reactor No. 3 | ✓ | Digital Displays: (GOOD) / Needs Attn |
| T-3334 Settling Tank | ✓ | Last Cleaning (Semi Annual): 5-7-20 |
| P-3334 Biosolids Pump | ✓ | |
| T-3340 Overflow Tank | ✓ Level: 30 % | |
| Recycle Valve to Blend Tank | ✓ | 3.99 gpm @ 0955 |
| Building Containment Sump | ✓ | Last Alarm Test Date (Monthly): 6-17-21 |

## E. CHEMICAL FEED SYSTEM

| Item | Status | Comments |
|---|---|---|
| Phosphorous Supply | ✓ | Bags: 19.75 Gallons: ~100 |
| Phosphorous Pump (P-2221) | ✓ | |
| Caustic Supply | ✓ | ~ 30 Gallons |
| Caustic Pump (P-2211) | SB | Currently in acid addition mode |
| Acid Supply | ✓ | ~ 40 Gallons |
| Acid Pump (P-2211) | ✓ | |
| Caustic Pump (P-2231) | ✓ Leaks: Y / (N) | Last tubing tip cleaning (monthly): 6-17-21 |
| Caustic Pump (P-2232) | ✓ Leaks: Y / (N) | Last tubing tip cleaning (monthly): |
| Caustic Pump (P-2233) | ✓ Leaks: Y / (N) | Last tubing tip cleaning (monthly): |

# TABLE 3.19.2
# STANDARD OPERATIONS CHECKLIST
# BIOLOGICAL TREATMENT SYSTEM

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, July 08, 2021

**Inspection Performed by:** Mike Gelwick

### F. pH Probes

| pH Probe Location | Calibration Date (Monthly) | Comments |
|---|---|---|
| pH-3320 Blend Tank | 6-24-21 | Spray off clean today |
| pH-3331 Reactor 1 | ↓ | ↓ |
| pH-3332 Reactor 2 | | |
| pH-3333 Reactor 3 | | |

### G. FILTER SYSTEM

| Item | Status | Comments |
|---|---|---|
| BF-3340 a/b Status | ✓ | |
| Automatic Backwash | Cycle Count: 40 | Reset |
| BF-3340 a/b Differential Pressure | PSI: 2 | 16/14 @ 2.6gpm |
| 75-micron Bags Last Cleaning | Date: 11-14-19 | |
| 75-micron Bags Last Inspection | Date: ↓ | |
| 75-micron Bags Last Changed | Date: | |
| GACF-3340 Status | ✓ | |
| GACF-3340 Differential Pressure | PSI: 8 | 14/6 @ 2.6gpm |
| Last Backwash Performed | Date: 6-17-21 | |

### H. ELECTRICAL AND INSTRUMENTATION

| Item | Status | Comments |
|---|---|---|
| "BIO" Backup Generator | ✓ | Block Heater: On OK / (Off Warm Out) |
| Electrical Surge Suppressor | ✓ | |
| Motor Control Center | ✓ | |
| PLC | ✓ | UPS @ 97 min / 71 Events |
| HMI's | ✓ | |
| BTS Process KWH Meter | 1777959 KWH | Time: 1038 |
| Building#2 KWH Meter | 5193815 KWH | Time: 1038 |

### I. GAS CHROMATOGRAPHY

| Item | Status | Comments |
|---|---|---|
| GC Operational | ✓ | GC # checking BIO: #3 |
| Alarms Enabled | ✓ | CC-Calibration & Maint 7-7-21 |
| GC Influent Filters | ✓ | |

# TABLE 3.19.2
# STANDARD OPERATIONS CHECKLIST
# BIOLOGICAL TREATMENT SYSTEM

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, July 08, 2021

**Inspection Performed by:** Mike Gelwick

## J. TOTALIZERS

| Item | Readings (gallons) | Comments |
|---|---|---|
| FT-3321 Feed to Reactor 1 | 5694148 | |
| FT-3324 Feed Spare | 45618 | |
| FT-3322 Feed to Reactor 2 | 10258656 | |
| FT-3323 Feed to Reactor 3 | 371970 | |
| FT-3301 T-510 to BIO | 51157745 | |
| FT-3341 BIO Effluent | 65844602 | |
| FT-3342 BIO Recycle | 54880493 | |

## K. SAFETY

| Item | Status | Comments |
|---|---|---|
| Building #2 Fire Extinguishers | ✓ | Inspection date: 6-23-21 |
| Building #2 Eye Wash/Shower | ✓ | Checked and Flushed- All OK: (Y) / N |

## L. OTHER COMMENTS:

| |
|---|
| |
| |
| |
| |

# ABLE 3.19.1
# STANDARD OPERATIONS CHECKLIST
# MAIN WTP

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, July 15, 2021

**Inspection Performed by:** Mike Gelwick

## A. PERIMETER COLLECTION SYSTEMS

| Item | Status | Comments |
|---|---|---|
| LFG Cond Automatic Trap CT-1 | Sump Level: 12.81 ok | Counter: 176464 Cycles: 520 |
| LFG Cond Automatic Trap CT-2 | Sump Level: 8.75 ok | Counter: 273046 Cycles: 10 |
| LFG Cond Automatic Trap CT-3 | Sump Level: 7.39 ok | Counter: 296353 Cycles: 1094 |
| CT-4 Containment/Vessel (LFG Cond) | ✓ Level: 70 % | Tank Level: 2.18 Counter: 19164 Cycles: 0 Sump: 8.92 ok |
| PM-15 Containment / Vessel | ✓ Level: 59 % | |
| MW-51 Containment / Vessel | ✓ Level: 70 % | |
| PM-11 Containment / Vessel | ✓ Level: 65 % | |
| MW-38 Systems | ✓ | |
| North Toe System | ✓ | |
| North End Systems (Weekly) | ✓ | |
| Full N. End Systems Check (Monthly) | ✓ | Last Done: 6-23-21 |
| North End Pipeline(s)Flushing (As Needed) | ✓ | Perform if suspended solids present Last Done: 11/15/15 |
| NTES line flush to T-530 (As needed) | ✓ | Perform if suspended solids present Last Done: 2/13/20 |
| NTES Piping Containment | ✓ | Monthly Sump Level: dry @ 16.07' Date: 6-17-21 |
| North Boundary System P-001: | CV 76.2 % @ 7.6 gpm | 42.71 Hz / 2.12 Amps. / vault psi @ 18/NO LEAKS |
| T-101 & T-102 Containment / Tank | ✓ | Levels: 22 % & 20 % |
| Raw Water Storage Tanks Piping | ✓ | |
| RWST Building Temp. (TT-101) | 70.1 °F | Outside Temp.: ~ 73 °F |
| (P-121) or P-122 | ✓ | 2.6 gpm / CV 25 % |
| RWST 2ndry Cont. High Level Switch | ✓ | (LSH-101) Last Test(monthly): 6-17-21 |
| RWST Back-Up Generator | ✓ | Last Test Run(monthly): 6-17-21 |

## B. CHEMICAL STORAGE BAYS

| Item | Status | Comments |
|---|---|---|
| Caustic Tote Levels | ✓ | ~ 560 Gallons Reserve = 1 tote |
| Caustic Bay Heater | ✓ | SB- WARM OUT |
| Peroxide Tote Level | ✓ | ~ 155 Gallons Reserve = ~105 gal |
| HCL Tote Levels | ✓ | ~ 100 Gallons Reserve = ~70 gal |
| Chemical Totes and Piping Inspected | ✓ | Leaks observed: Y / (N) |
| Emergency Shower Inspected | ✓ | Checked and Flushed - All OK: (Y) / N |

## C. PRIMARY AND SECONDARY ACID FEED SYSTEM

| Item | Status | Comments |
|---|---|---|
| Primary Acid Feed Pump (P-631) | ✓ | |
| Ion Exchange Acid Feed Pump (P-632) | ✓ | PI-0632 PSI: 70 CV: 5 % |
| Primary Acid Retention Tank (T-510) | ✓ | |
| All Acid Feed Lines | ✓ | Leaks observed: Y / (N) |

## D. NBBW INJECTION TRENCH

| Item | Status | Comments |
|---|---|---|
| Injection Carbon (GAC-810) | OFFLINE | Date online: 7/20/18 |
| Injection Rate (FT-800) | 0.0 gpm | NBBW-IW-1= 0.0 NBBW-IW-2= 0.0 NBBW-IW-3= 0.0 gpm ea. |
| Totalizer Reading (FT-800) | 105,135,774 gal | INJ. STOPPED 10/02/18 @ 1545 |

# ABLE 3.19.1
# STANDARD OPERATIONS CHECKLIST
# MAIN WTP

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, July 15, 2021

**Inspection Performed by:** Mike Gelwick

## E. CHEMICAL PRECIPITATION SYSTEM (US FILTER HMR-30)

| Item | Status | Comment |
|---|---|---|
| T-300A Mixer | NA | |
| T-300B (Caustic Mixer) | ✓ | Last Cleaning (Qtrly): 6-3-21 |
| T-300A/B Water Level | ✓ | |
| T-300B (Caustic Mix Chamber) | ✓ | Last Cleaning (Qtrly): 6-3-21 |
| T-300A/B Overflow | ✓ | |
| pH Set-point for (pH 315) | Value: 10.8 | |
| pH 310 | Value: 6.98 | |
| pH 315 | Value: 10.73 | |
| Flocculation Chamber Paddle Wheel | ✓ | |
| Precipitate Floc Quality | ✓ | Good |
| Clarifier Water Quality | ✓ | Good Oil or sheen observed: Y / (N) |
| Clarifier Effluent Piping / Water Level | ✓ | |
| Clear-well Chamber and Water Level | ✓ | |
| HMR PLC Panel | ✓ | |
| Caustic Pump (P-270) | SB | |
| Caustic Pump (P-280) | ✓ | |
| Polymer Pump (P-310) | ✓ | |
| Polymer Tank Mixer | ✓ | |
| Polymer Tank Level | Gallons: ~ 375 | |
| Clear-well Transfer Pumps(P-371 / (372)) | ✓ | |
| Sludge Transfer Pump (P-330) | ✓ | Exercise Valves Weekly: Bottom OK / Top Screw to Open |
| Manual Sludge Lateral pumping | ✓ | Last done (As Needed): #3-7-14-21 / 1+2 3-2020 |
| Manual Sludge Lateral Ball Valves | ✓ | Exercise Weekly: All of |
| Automatic Blow-down Operations | ✓ | |

## F. pH PROBES

| pH Probe Location | Calibration Date | Comments: (Time done) |
|---|---|---|
| pH-310 HMR-30 (T-300A) | 7-15-21 ~Today | 1341 |
| pH-315 HMR-30 (T-300B) | | |
| pH-365 Primary Acid Ret. Tank | | |
| pH-113 Pre-Ion Exchange | | |
| pH-670 Pre-UV-OX | | 1415 |
| pH-740 Discharge Surge Tank | | Discharge suspended: 1331 ↔ 1340 |
| Out of Hold Double Check | ---------- | None in hold: ✓✓ |
| Valves Back to Normal Position | ---------- | All OK: ✓✓ |

## G. SLUDGE THICKENER, SLUDGE HOLDING TANKS, FILTER PRESS

| Item | Status | Comments |
|---|---|---|
| Verify Sludge Thickener Running | ✓ | Gauge Reading: 0 % |
| Sludge Thick. Transfer Pump (P-350) | ✓ | |
| Sludge Holding Tank (T-351) | ✓ | Level: ~ 65 % |
| Sludge Holding Tank (T-352) | ✓ | Level: 50 % |
| Decant Transfer Pump (P-352) | ✓ | CV 36 % @ 0.6 gpm |
| Filter Press Pumps (P-381 / P-382) | ✓ | |
| Filter Press | ✓ | Stage: Full |

# ABLE 3.19.1
# STANDARD OPERATIONS CHECKLIST
# MAIN WTP

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, July 15, 2021

**Inspection Performed by:** Mike Gelwick

### H. ION EXCHANGE

| Item | Status | Comments |
|---|---|---|
| Feed Tank (T-113) | ✓ Level: 45 % | |
| Feed Pump (P-114) | ✓ Operating Press: 60.3psi | CV@ 83 % @ 2.0 gpm |
| Retention Tank (T-114) | ✓ Operating Press: 59 psi | pH-113 @ 3.63 |
| Bag Filter (BF-113) | ✓ Operating Press: 62 psi | |
| Ion Exchange (Cage 1 or 2) + Guard | ✓ Operating Press: 59 psi | TP-173A → TP-177A / 9 canisters + Guard |
| Post Ion Exchange | ✓ Operating Press: 3.5 psi | |

### I. FEED SURGE TANK

| Item | Status | Comments |
|---|---|---|
| Feed Surge Tank (T-520) | ✓ Level: 38 % | Last Cleaning (As Needed, if 4" of solids accumulate): 12/15/19 |
| Feed Surge Pump (P-521 or P-522) | Operating Press: 27 psi | CV@ 70 % @ 35.8 gpm |
| T-520 to GAC Total (FT-675) | 246276267 gal | Time: 0951 |
| North End On-Site Pumping | Operating Press: 2-3 psi | 13.4 gpm @ 0945 |
| North End Off-Site Pumping | Operating Press: 2-6 psi | 8.5 gpm @ 0945 |
| Peroxide Feed Pump (P-680) | ✓ | SPD 2.7 % / RATE 0.7 |
| Peroxide Conc. At (TP-710) | 1.0 PPM | |
| Peroxide Conc. At (TP-740) | 0.0 PPM | |

### J. HAZARDOUS WASTE STORAGE

| Item | Status | Comments |
|---|---|---|
| 180 Day storage area check | ✓ | Check sheet completed: NA/Empty |
| Satellite Haz. Waste Areas (BLDG #1) | ✓ | Condition: Good |
| Satellite Haz. Waste Area (BLDG #2) | ✓ | Condition: Good |

### K. UV-OXIDATION SYSTEM

| Item | Status | Comments |
|---|---|---|
| UV-Oxidation System | ✓ | |
| Annual Test Run (Calgon) | Date: 8-4-20 | Next: 8-2021 |
| Quarterly Test Run | Date: NA/Running | Next: NA/Running |
| Peroxide Feed Pump (P-650) | ✓ | Flow Rate: ~ 7.0 cc/min. |
| UV-Ox Power | ✓ | 25.7 kVA 2642 Volts 9.8 Amps |
| Lamp Hours | 2961 Hrs | |
| Crystal Condition & Wiper Status | ✓ | Oiler status: Ok |
| UV-OX Bagfilters Status | Last change: 7-13-21 Cleaned: 7-13-21 | 10.5 psi In 11.0 psi Out |
| UV-OX Feed Pump ( P-600 or P-601 ) | ✓ | CV@ 73 % @ 8.0 gpm |
| UV-OX Temperature | In(TT-670): 17.0 °C | Out(TT-710): 28.0 °C |
| PDU GAC (PDT-710) | ✓ | Δ Pressure: 3 psi |
| Peroxide Concentration Pre UV | 100 PPM | |
| Peroxide Concentration Post UV(TP-720) | 25 PPM | |
| Peroxide Conc. Post PDU (TP-730) | 0.0 PPM | |
| Secondary Acid Feed Pump (P-630) | ✓ | CV @ 2 % |
| Secondary Acid Retention Tank (T-645) | ✓ | |
| Pre – UV Oxidizer Total (FT-670) | 18988684 gal | Time: 0951 |
| Post UV-Ox / Pre PDU | ✓ | Pressure: 13 psi |
| Post PDU | ✓ | Pressure: 7 psi |

# ABLE 3.19.1
# STANDARD OPERATIONS CHECKLIST
# MAIN WTP

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, July 15, 2021

**Inspection Performed by:** Mike Gelwick

### L. PDU AND LIQUID –PHASE GRANULAR ACTIVATED CARBON

| Item | Status | Comments |
|---|---|---|
| PDT-720 | ✓ | Δ Pressure: 12 psi |
| PDT-730 | ✓ | Δ Pressure: 8 psi |

### M. EFFLUENT DISCHARGE

| Item | Status | Comments |
|---|---|---|
| Effluent Surge Pump (P751 or P752 ) | ✓ | CV@ 55.7 % |
| Effluent Surge Tank (T-740) | ✓ | Level: 40 % |
| Effluent Discharge Rate (FT-770) | ✓ | 36.1 gpm @ 0949 |
| POTW Line Pressure (PT-770) | ✓ | 32.7 psi |
| Effluent Totalizer Reading (FT-770) | 240346876 gal | Time: 0953 |
| POTW MH17S-078 Discharge Check (Monthly) | ✓ | Last Done: 7-8-21 |
| 4X8-Inch POTW Leak Detection Checks (Monthly) | ✓ | Last Done: |
| 4X8-Inch POTW Air Reliefs Checks (Monthly) | ✓ | Last Done: |
| 4X8-Inch POTW Isolation Valves Exercise (Qtrly) | ✓ | Last Done: |
| 2-Inch POTW Backup Pressure Testing (Annual) | ✓ | Last Done: ~~5/19/20~~ |
| 2-In POTW Backup Air Reliefs Checks (Annual) | ✓ | Last Done: ~~5/19/20~~ |
| 2-Inch POTW Isolation Valve Exercise (Annual) | ✓ | Last Done: ~~5/19/20~~ |
| Rotate Chiller Compressors | NA on Standby | ~~Now in Lead: 1 or 2~~ |

### N. LEL EFFLUENT TANK T-740

| Item | Status | Comments |
|---|---|---|
| LEL-740 Sensor | ✓ | Reading: 0 % |
| LEL Sensor Calibration / Automatic High LEL Shutdown Test (monthly) | Last Completed: 6-24-21 | Plant Effluent Suspended: 1255 ↔ 1315 |
| LEL Sensor Bridge Adjustment to 2.0 volts | Reading: 2.001 volts(monthly) | Adjustment Needed: (Y) or N |
| Verify Bridge Current between.300v-.360v | Reading: 0.331 volts(monthly) | 1.998→2.001 / 47%→49% LEL |

### O. WTP INFLUENT TOTALIZERS Time : 1003 - 1039

| Source | Reading(Gallons) | Source | Reading(Gallons) |
|---|---|---|---|
| (FT-015) RWST Influent | 195520679 | (FT-505) LFG Cond. to T-530 | 214516 |
| (FT-025) NBBW Influent | 9298682 | (FT-056) Off - Site N. End Influent | 41966092 |
| (FT-012) MW-38 Inf. to HMR-30 | 7998659 | (FT-113) Ion Exchange Influent | 358800 |
| (FT-042 HMR30) MW-38 Source to HMR-30 | 35484 | (FT-810) Plant Potable Water In | 30050220 |
| (FT-043) MW-38 to RWST | 3062560 | (FT-026) NBBW Bypass to RWST | 4361831 |
| (FT-042 RWST) MW-38 Source to RWST | 72236 | (FT-014) Misc. Water to RWST | 8103265 |
| (FT-012T) MW-38 to T-540/541 | 8578623 | (FT-035) NTES Inf. to BIO | 6591147 |
| (FT-040T) MW-38N to T-540/541 | 1976318 | (FT-035T) NTES to T-530 | 457756 |
| (FT-041T) MW-38S to T-540/541 | 2694046 | (FT-017) BIO Inf. from T-530 | 646405 |
| (FT-042T) MW-38 Source to T-540/541 | 3980265 | (FT-018) T-540/541 Influent | 8623514 |
| (FT-055) On - Site N. End Influent | 96210405 | (FT-352) T-352 to HMR-30 | 1245565 |

# ABLE 3.19.1
# STANDARD OPERATIONS CHECKLIST
# MAIN WTP

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, July 15, 2021

**Inspection Performed by:** Mike Gelwick

### P. AIR COMPRESSORS

| Item | Status | Comments |
|---|---|---|
| Compressor Intake Temp. | 68 °F (Analog Gauge) | Outside Temp.: ~ 87 °F |
| Compressor Building Vent | ✓ | open - observed |
| Primary Air Compressor (IRN30H) | 2,000 Hour service date: 7-8-21<br>Serviced @ 60952 Hours | Coolant present in sight glass: Y / N<br>Next service @ 62952 Hours<br>Current Hours @ 61047 |
| IRN30H Motor Speed | 31 % | |
| IRN30H Pressure | 116 psi | |
| IRN30H Moisture purge valve chk(Weekly): | ✓ | |
| IRN30H Intake Filter | ✓ | Date Last Changed: 7-8-21 |
| Air Tanks Moisture Purge Valves | Manually Activate(weekly) ✓ | Excessive Moisture: Y / N |
| Backup Air Compressors (T-30 East and West) | ✓ | Both cool to touch: Y / N |
| Air Dryer | ✓ ECO on | Moisture at Receiver Tank: Y / N |
| Oil Moisture Prevention (Monthly) | Last Done: 6-24-21 | Run at max speed by bleeding air from filter canister above/after air dryer for 2 hrs |
| Air Receiver Tank | ✓ | 110 psi |

### Q. SUMPS

| Item | Status | Comments |
|---|---|---|
| Bag Filter Sump | ✓ | |
| Wet Well Sump | ✓ | |

### R. GAS CHROMATOGRAPH

| Item | Status | Comments |
|---|---|---|
| GC Operational | ✓ | GC # checking UV-Ox Effluent: # 2 |
| Alarms Enabled | ✓ | GC - Calibration + Maint 7-14-21 |
| GC Influent Filters | ✓ | |

### S. SAFETY

| Item | Status | Comments |
|---|---|---|
| Building #1 Fire Extinguishers | ✓ | Date inspected: 6-23-21 |
| Building #1 Eye Wash/Shower | ✓ | Checked and Flushed- All OK: Y / N |

**Other Comments:**

UMR30 Sludge Transfer Pump heads for valve replaced.

# TABLE 3.19.2
# STANDARD OPERATIONS CHECKLIST
# BIOLOGICAL TREATMENT SYSTEM

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, July 15, 2021

**Inspection Performed by:** Mike Gelwick

## A. PUMPS

| Item | Status | Flow Rate (gpm) | Pump Speed (CV%) | Discharge Pressure (psi) | | Comments |
|---|---|---|---|---|---|---|
| **T-510 Pumps** | | | | | | |
| P-3301 | SB | – | – % | – | | |
| P-3301A | ✓ | 2.51 | 32.8 % | 7.5 | | |
| **NTES Pump** P-002(Sump) / (P-002W(10R)) | ✓ | 0.51 | 49 % | P035 37-38 | P038 6.5 | Globules Observed at TP-130: Y / (N) Time: 0915 |
| **T-530** P-005 | ✓ | 0.30 | 35 % | 5.5 | | |
| **T-540/541** P-006 | ✓ | 0.30 | 56 % | 4.5 | | |
| **LFG COND Auto-Traps** | ✓ | 0.0 | NA | 4.0 | | Between Cycles: (Y) / N |
| **Reactor Feed Pumps** | | | | | | |
| P-3321 | ✓ | 2.64 | 57.5 % | 6.5 | | |
| P-3322 | ✓ | 3.67 | 48.6 % | 5.0 | | |
| P-3323 | ✓ | 2.65 | 71.5 % | 6.5 | | |
| P-3324 | SB | – | – % | – | | |
| **Reactor Effluent Pumps** | | | | | | |
| P-3341 | ✓ | 2.34 | 42.8 % | 6.5 | | |
| P-3341A | SB | – | – % | – | | |

## B. BLOWERS

| Item | Status | Pressure (psi) | Temp (°F) | Next Scheduled Service (Qtrly) | Comments Last serviced on: 6-22-21 |
|---|---|---|---|---|---|
| B-3331 | ✓ | 4.25 | 152 | 9-2021 | Greased, Belt and Filter Checked: (Y) / N |
| B-3332 | SB | – | – | ↓ | Belt and Filter Checked: Y / (N) |
| B-3333 | ✓ | 4.49 | 158 | ↓ | Greased, Belt and Filter Checked: (Y) / N |
| B-3334 | ✓ | 4.20 | 146 | ↓ | Greased, Belt and Filter Checked: (Y) / N |

## C. REACTOR VENTILATION

| Item | Status | Comments |
|---|---|---|
| Vapor Carbon Contactor | ✓ | On-line: 2/10/18 |
| Reactor Vent Blower | ✓ | |
| Reactor Vent Booster | ✓ | |
| VTP-3350 | ✓ | PID Reading: 1.6 PPM |
| VTP-3360 | ✓ | PID Reading: 0.4 PPM |

# TABLE 3.19.2
# STANDARD OPERATIONS CHECKLIST
# BIOLOGICAL TREATMENT SYSTEM

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, July 15, 2021

**Inspection Performed by:** Mike Gelwick

## D. TANKS / REACTORS / SUMPS / CONTAINMENTS / PIPING / Chiller

| Item | Status | Comments |
|---|---|---|
| T-510 Post HMR-30 Mixing Tank | ✓ Level: 69 % | Last Cleaning (As needed, if 2" of solids accumulate): 12/15/19 |
| T-530 LFG Condensate / NTES Tank | ✓ Level: 28 % | |
| T-530 Mixer | ✓ | |
| LFG Condensate Conveyance Line | ✓ | Last Pressure Test: 8-10-20 Next: 8-2021 (Annual at a minimum or if flow drops off) |
| T-540/541 MW38 Tanks | Lvls: 70 % & 70 % | |
| T-540/541 Mixers | ✓ | |
| Chiller | ✓ | Chiller Coolant Lvl: ~ 1.0 " Below full mark |
| Chiller Cooling Fins (as needed) | ✓ | Last Cleaning: 4/20/18 (unit on Standby) |
| Secondary Containments | ✓ | Heat Trace: On OK / (Off Warm out) |
| Feed Piping to Sedimentation Tank | ✓ | Last Back Flushing (Quarterly): 7-14-21 |
| T-3310 Sedimentation Tank | Visual Level: ok | Last Cleaning (As Needed, use TSS info to determine): 12/2017 |
| T-3320 Blend Tank | ✓ Level: 73 % | Last Cleaning (Semi Annual): 5-7-20 |
| T-3331 Reactor No. 1 | ✓ | Digital Displays: (GOOD) / Needs Attn |
| T-3332 Reactor No. 2 | ✓ | Digital Displays: (GOOD) / Needs Attn |
| T-3333 Reactor No. 3 | ✓ | Digital Displays: (GOOD) / Needs Attn |
| T-3334 Settling Tank | ✓ | Last Cleaning (Semi Annual): 5-7-20 |
| P-3334 Biosolids Pump | ✓ | |
| T-3340 Overflow Tank | ✓ Level: 30 % | |
| Recycle Valve to Blend Tank | ✓ | 3.99 gpm @ 1109 |
| Building Containment Sump | ✓ | Last Alarm Test Date (Monthly): 6-17-21 |

## E. CHEMICAL FEED SYSTEM

| Item | Status | Comments |
|---|---|---|
| Phosphorous Supply | ✓ | Bags: 19,125 Gallons: ~ 70 |
| Phosphorous Pump (P-2221) | ✓ | |
| Caustic Supply | ✓ | ~ 275 Gallons |
| Caustic Pump (P-2211) | SB | Currently in acid addition mode |
| Acid Supply | ✓ | ~ 40 Gallons |
| Acid Pump (P-2211) | ✓ | |
| Caustic Pump (P-2231) | ✓ Leaks: Y / (N) | Last tubing tip cleaning (monthly): 6-17-21 |
| Caustic Pump (P-2232) | ✓ Leaks: Y / (N) | Last tubing tip cleaning (monthly): ↓ |
| Caustic Pump (P-2233) | ✓ Leaks: Y / (N) | Last tubing tip cleaning (monthly): |

# TABLE 3.19.2
# STANDARD OPERATIONS CHECKLIST
# BIOLOGICAL TREATMENT SYSTEM

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, July 15, 2021

**Inspection Performed by:** Mike Gelwick

## F. pH Probes

| pH Probe Location | Calibration Date (Monthly) | Comments |
|---|---|---|
| pH-3320 Blend Tank | 6-24-21 | Spray off clean today |
| pH-3331 Reactor 1 | ↓ | ↓ |
| pH-3332 Reactor 2 | | |
| pH-3333 Reactor 3 | | |

## G. FILTER SYSTEM

| Item | Status | Comments |
|---|---|---|
| BF-3340 a/b Status | ✓ | |
| Automatic Backwash | Cycle Count: 56 | Reset |
| BF-3340 a/b Differential Pressure | PSI: 1 | 11/10 @ 4.6 gpm |
| 75-micron Bags Last Cleaning | Date: 11-14-19 | |
| 75-micron Bags Last Inspection | Date: ↓ | ↓ |
| 75-micron Bags Last Changed | Date: | |
| GACF-3340 Status | ✓ | |
| GACF-3340 Differential Pressure | PSI: 4 | 10/6 @ 4.6 gpm |
| Last Backwash Performed | Date: 7-14-21 | |

## H. ELECTRICAL AND INSTRUMENTATION

| Item | Status | Comments |
|---|---|---|
| "BIO" Backup Generator | ✓ | Block Heater: On OK / (Off Warm Out) |
| Electrical Surge Suppressor | ✓ | |
| Motor Control Center | ✓ | |
| PLC | ✓ | UPS @ 97 min / 71 Events |
| HMI's | ✓ | |
| BTS Process KWH Meter | 1779956 KWH | Time: 1242 |
| Building#2 KWH Meter | 5196749 KWH | Time: 1242 |

## I. GAS CHROMATOGRAPHY

| Item | Status | Comments |
|---|---|---|
| GC Operational | ✓ | GC # checking BIO: #3 |
| Alarms Enabled | ✓ | CC - calibration + maint 7-14-21 |
| GC Influent Filters | ✓ | |

# TABLE 3.19.2
# STANDARD OPERATIONS CHECKLIST
# BIOLOGICAL TREATMENT SYSTEM

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, July 15, 2021

**Inspection Performed by:** Mike Gelwick

## J. TOTALIZERS

| Item | Readings (gallons) | Comments |
|---|---|---|
| FT-3321 Feed to Reactor 1 | 5718596 | |
| FT-3324 Feed Spare | 45628 | |
| FT-3322 Feed to Reactor 2 | 10292601 | |
| FT-3323 Feed to Reactor 3 | 396083 | |
| FT-3301 T-510 to BIO | 51185632 | |
| FT-3341 BIO Effluent | 65880856 | |
| FT-3342 BIO Recycle | 54922499 | |

## K. SAFETY

| Item | Status | Comments |
|---|---|---|
| Building #2 Fire Extinguishers | ✓ | Inspection date: 6-23-21 |
| Building #2 Eye Wash/Shower | ✓ | Checked and Flushed- All OK: (Y) / N |

## L. OTHER COMMENTS:

| |
|---|
| |
| |
| |
| |

# ABLE 3.19.1
# STANDARD OPERATIONS CHECKLIST
# MAIN WTP

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, July 22, 2021

**Inspection Performed by:** Mike Gelwick

## A. PERIMETER COLLECTION SYSTEMS

| Item | Status | Comments |
|---|---|---|
| LFG Cond Automatic Trap CT-1 | Sump Level: 13.23 ∝ | Counter: 177078 Cycles: 614 |
| LFG Cond Automatic Trap CT-2 | Sump Level: 8.54 ∝ | Counter: ~~273773~~ 273609 Cycles: 623 |
| LFG Cond Automatic Trap CT-3 | Sump Level: 7.38 ∝ | Counter: 298372 Cycles: 2019 |
| CT-4 Containment/Vessel (LFG Cond) | ✓ Level: 70 % | Tank Level 2.18 Counter: 191164 Cycles: 0 Sump: 8.82 ∝ |
| PM-15 Containment / Vessel | ✓ Level: 25 % | |
| MW-51 Containment / Vessel | ✓ Level: 40 % | |
| PM-11 Containment / Vessel | ✓ Level: 35 % | |
| MW-38 Systems | ✓ | |
| North Toe System | ✓ | |
| North End Systems (Weekly) | ✓ | |
| Full N. End Systems Check (Monthly) | ✓ | Last Done: 6-23-21 |
| North End Pipeline(s)Flushing (As Needed) | ✓ | Perform if suspended solids present Last Done: 11/15/15 |
| NTES line flush to T-530 (As needed) | ✓ | Perform if suspended solids present Last Done: 2/13/20 |
| NTES Piping Containment | ✓ | Monthly Sump Level: dry 16.07' Date: 7-22-21 - Today |
| North Boundary System P-001: | CV 75.9% @ 7.6 gpm | 42.44 Hz / 2.12 Amps. / vault psi @ 18/No leaks |
| T-101 & T-102 Containment / Tank | ✓ | Levels: 32 % & 31 % Containment Attached 7-21-21 |
| Raw Water Storage Tanks Piping | ✓ | |
| RWST Building Temp. (TT-101) | 75.9 °F | Outside Temp.: ~ 77 °F |
| (P-121) or P-122 | ✓ | 0.6 gpm / CV 58 % |
| RWST 2ndry Cont. High Level Switch | ✓ | (LSH-101) Last Test(monthly): 7-22-21 - Today |
| RWST Back-Up Generator | ✓ | Last Test Run(monthly): 7-22-21 - Today TOP off fuel 7-19-21 |

## B. CHEMICAL STORAGE BAYS

| Item | Status | Comments |
|---|---|---|
| Caustic Tote Levels | | ~455 Gallons Reserve = 4 totes |
| Caustic Bay Heater | ✓ | 50 - WARM OUT. |
| Peroxide Tote Level | ✓ | ~ 195 Gallons Reserve = ~55 gal |
| HCL Tote Levels | ✓ | ~ 300 Gallons Reserve = ~90 gal |
| Chemical Totes and Piping Inspected | ✓ | Leaks observed: Y / (N) |
| Emergency Shower Inspected | ✓ | Checked and Flushed - All OK: (Y) / N |

## C. PRIMARY AND SECONDARY ACID FEED SYSTEM

| Item | Status | Comments |
|---|---|---|
| Primary Acid Feed Pump (P-631) | ✓ | |
| Ion Exchange Acid Feed Pump (P-632) | ✓ | PI-0632 PSI: 68-70 CV: 5 % |
| Primary Acid Retention Tank (T-510) | ✓ | |
| All Acid Feed Lines | ✓ | Leaks observed: Y / (N) |

## D. NBBW INJECTION TRENCH

| Item | Status | Comments |
|---|---|---|
| Injection Carbon (GAC-810) | OFFLINE | Date online: 7/20/18 |
| Injection Rate (FT-800) | 0.0 gpm | NBBW-IW-1= 0.0 NBBW-IW-2= 0.0 NBBW-IW-3= 0.0 gpm ea. |
| Totalizer Reading (FT-800) | 105,135,774 gal | INJ. STOPPED 10/02/18 @ 1545 |

# ABLE 3.19.1
# STANDARD OPERATIONS CHECKLIST
# MAIN WTP

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, July 22, 2021

**Inspection Performed by:** Mike Gelwick

## E. CHEMICAL PRECIPITATION SYSTEM (US FILTER HMR-30)

| Item | Status | Comment |
|---|---|---|
| T-300A Mixer | NA | |
| T-300B (Caustic Mixer) | ✓ | Last Cleaning (Qtrly): 6-3-21 |
| T-300A/B Water Level | ✓ | |
| T-300B (Caustic Mix Chamber) | ✓ | Last Cleaning (Qtrly): 6-3-21 |
| T-300A/B Overflow | ✓ | |
| pH Set-point for (pH 315) | Value: 10.8 | |
| pH 310 | Value: 6.49 | |
| pH 315 | Value: 10.87 | |
| Flocculation Chamber Paddle Wheel | ✓ | |
| Precipitate Floc Quality | ✓ | Good |
| Clarifier Water Quality | ✓ | Good Oil or sheen observed: Y / (N) |
| Clarifier Effluent Piping / Water Level | ✓ | |
| Clear-well Chamber and Water Level | ✓ | |
| HMR PLC Panel | ✓ | |
| Caustic Pump (P-270) | SB | |
| Caustic Pump (P-280) | ✓ | |
| Polymer Pump (P-310) | ✓ | |
| Polymer Tank Mixer | ✓ | |
| Polymer Tank Level | Gallons: ~ 500 | |
| Clear-well Transfer Pumps(P-371 (372) | ✓ | |
| Sludge Transfer Pump (P-330) | ✓ | Exercise Valves Weekly: Bottom ok / 10" suction open |
| Manual Sludge Lateral pumping | ✓ | Last done (As Needed): #3 - 7-20-21 1+2 - 3-2020 |
| Manual Sludge Lateral Ball Valves | ✓ | Exercise Weekly: Allen |
| Automatic Blow-down Operations | ✓ | |

## F. pH PROBES

| pH Probe Location | Calibration Date | Comments: (Time done) |
|---|---|---|
| pH-310 HMR-30 (T-300A) | 7-22-21-Today | 1334 |
| pH-315 HMR-30 (T-300B) | | |
| pH-365 Primary Acid Ret. Tank | | |
| pH-113 Pre-Ion Exchange | | |
| pH-670 Pre-UV-OX | | 1405 |
| pH-740 Discharge Surge Tank | | Discharge suspended: 1325 ↔ 1333 |
| Out of Hold Double Check | ---------- | None in hold: ✓ ✓ ✓ m |
| Valves Back to Normal Position | ---------- | All OK: ✓ ✓ ✓ m |

## G. SLUDGE THICKENER, SLUDGE HOLDING TANKS, FILTER PRESS

| Item | Status | Comments |
|---|---|---|
| Verify Sludge Thickener Running | ✓ | Gauge Reading: 0 % |
| Sludge Thick. Transfer Pump (P-350) | ✓ | |
| Sludge Holding Tank (T-351) | ✓ | Level:~ 65 % |
| Sludge Holding Tank (T-352) | ✓ | Level: 41 % |
| Decant Transfer Pump (P-352) | ✓ | CV 40 % @ 0.6 gpm |
| Filter Press Pumps (P-381 / P-382) | ✓ | |
| Filter Press | ✓ | Stage: Fill |

# ABLE 3.19.1
# STANDARD OPERATIONS CHECKLIST
# MAIN WTP

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, July 22, 2021

**Inspection Performed by:** Mike Gelwick

### H. ION EXCHANGE

| Item | Status | Comments |
|---|---|---|
| Feed Tank (T-113) | ✓ Level: 66 % | |
| Feed Pump (P-114) | ✓ Operating Press: 59.1 psi | CV@ 82 % @ 2.0 gpm |
| Retention Tank (T-114) | ✓ Operating Press: 58 psi | pH-113 @ 3.81 |
| Bag Filter (BF-113) | ✓ Operating Press: 61 psi | |
| Ion Exchange (Cage (1) or 2) + Guard | ✓ Operating Press: 58 psi | TP-173A→TP-177A (Beam Bars + Guard) |
| Post Ion Exchange | ✓ Operating Press: 3.5 psi | |

### I. FEED SURGE TANK

| Item | Status | Comments |
|---|---|---|
| Feed Surge Tank (T-520) | ✓ Level: 39 % | Last Cleaning (As Needed, if 4" of solids accumulate): 12/15/19 |
| Feed Surge Pump (P-521 or (P-522)) | Operating Press: 30 psi | CV@ 73 % @ 37.0 gpm |
| T-520 to GAC Total (FT-675) | 246637341 gal | Time: 1051 |
| North End On-Site Pumping | Operating Press: 2-3 psi | 13.3 gpm @ 1046 |
| North End Off-Site Pumping | Operating Press: 2-6 psi | 8.9 gpm @ 1046 |
| Peroxide Feed Pump (P-680) | ✓ | SPD 2.8 % / RATE 0.7 |
| Peroxide Conc. At (TP-710) | 1.0 PPM | |
| Peroxide Conc. At (TP-740) | 0.0 PPM | |

### J. HAZARDOUS WASTE STORAGE

| Item | Status | Comments |
|---|---|---|
| 180 Day storage area check | ✓ | Check sheet completed: NA/Empty |
| Satellite Haz. Waste Areas (BLDG #1) | ✓ | Condition: Good |
| Satellite Haz. Waste Area (BLDG #2) | ✓ | Condition: Good |

### K. UV-OXIDATION SYSTEM

| Item | Status | Comments |
|---|---|---|
| UV-Oxidation System | ✓ | |
| Annual Test Run (Calgon) | Date: 8-4-20 | Next: 8-2021 |
| Quarterly Test Run | Date: NA/Running | Next: NA/Running |
| Peroxide Feed Pump (P-650) | ✓ | Flow Rate: ~7.0 cc/min. |
| UV-Ox Power | ✓ | 25.7 kVA 2639 Volts 9.8 Amps |
| Lamp Hours | 3,130 Hrs | Change out Planned |
| Crystal Condition & Wiper Status | ✓ | Oiler status: OK |
| UV-OX Bagfilters Status | Last change: 7-13-21 Cleaned: 7-13-21 | 10.5 psi In 11.5 psi Out |
| UV-OX Feed Pump ( P-600 or (P-601) ) | ✓ | CV@ 74 % @ 7.9 gpm |
| UV-OX Temperature | In(TT-670): 16.6 °C | Out(TT-710): 27.6 °C |
| PDU GAC (PDT-710) | ✓ | Δ Pressure: 3 psi |
| Peroxide Concentration Pre UV | 100 PPM | |
| Peroxide Concentration Post UV(TP-720) | 25 PPM | |
| Peroxide Conc. Post PDU (TP-730) | 0.0 PPM | |
| Secondary Acid Feed Pump (P-630) | ✓ | CV @ 1 % |
| Secondary Acid Retention Tank (T-645) | ✓ | |
| Pre – UV Oxidizer Total (FT-670) | 19067258 gal | Time: 1051 |
| Post UV-Ox / Pre PDU | ✓ | Pressure: 13 psi |
| Post PDU | ✓ | Pressure: 7 psi |

# ABLE 3.19.1
# STANDARD OPERATIONS CHECKLIST
# MAIN WTP

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, July 22, 2021

**Inspection Performed by:** Mike Gelwick

### L. PDU AND LIQUID –PHASE GRANULAR ACTIVATED CARBON

| Item | Status | Comments |
|---|---|---|
| PDT-720 | ✓ | Δ Pressure: 14 psi |
| PDT-730 | ✓ | Δ Pressure: 10 psi |

### M. EFFLUENT DISCHARGE

| Item | Status | Comments |
|---|---|---|
| Effluent Surge Pump ((P751) or P752 ) | ✓ | CV@ 55.6 % |
| Effluent Surge Tank (T-740) | ✓ | Level: 40 % |
| Effluent Discharge Rate (FT-770) | ✓ | 36.9 gpm @ 1050 |
| POTW Line Pressure (PT-770) | ✓ | 32.7 psi |
| Effluent Totalizer Reading (FT-770) | 240707472 gal | Time: 1052 |
| POTW MH17S-078 Discharge Check (Monthly) | ✓ | Last Done: 7-8-21 |
| 4X8-Inch POTW Leak Detection Checks (Monthly) | ✓ | Last Done: |
| 4X8-Inch POTW Air Reliefs Checks (Monthly) | ✓ | Last Done: |
| 4X8-Inch POTW Isolation Valves Exercise (Qtrly) | ✓ | Last Done: |
| 2-Inch POTW Backup Pressure Testing (Annual) | ✓ | Last Done: ~~5/19/20~~ |
| 2-In POTW Backup Air Reliefs Checks (Annual) | ✓ | Last Done: ~~5/19/20~~ |
| 2-Inch POTW Isolation Valve Exercise (Annual) | ✓ | Last Done: ~~5/19/20~~ |
| Rotate Chiller Compressors | NA on Standby | ~~Now in Lead: 1 or 2~~ |

### N. LEL EFFLUENT TANK T-740

| Item | Status | Comments |
|---|---|---|
| LEL-740 Sensor | ✓ | Reading: 0 % |
| LEL Sensor Calibration / Automatic High LEL Shutdown Test (monthly) | Last Completed: 6-24-21 | Plant Effluent Suspended: 1255 ↔ 1315 |
| LEL Sensor Bridge Adjustment to 2.0 volts | Reading: 2.001 volts(monthly) | Adjustment Needed: (Y) or N |
| Verify Bridge Current between.300v-.360v | Reading: 0.331 volts(monthly) | 1.998→2.001 / 47%→49% LEL |

### O. WTP INFLUENT TOTALIZERS Time : 1053- 1057

| Source | Reading(Gallons) | Source | Reading(Gallons) |
|---|---|---|---|
| (FT-015) RWST Influent | 19558996 | (FT-505) LFG Cond. to T-530 | 2148311 |
| (FT-025) NBBW Influent | 93057845 | (FT-056) Off - Site N. End Influent | 42051004 |
| (FT-012) MW-38 Inf. to HMR-30 | 8018306 | (FT-113) Ion Exchange Influent | 3784844 |
| (FT-042 HMR30) MW-38 Source to HMR-30 | 35484 | (FT-810) Plant Potable Water In | 30051020 |
| (FT-043) MW-38 to RWST | 3064155 | (FT-026) NBBW Bypass to RWST | 43631366 |
| (FT-042 RWST) MW-38 Source to RWST | 72236 | (FT-014) Misc. Water to RWST | 8112833 |
| (FT-012T) MW-38 to T-540/541 | 8581121 | (FT-035) NTES Inf. to BIO | 6596266 |
| (FT-040T) MW-38N to T-540/541 | 1976607 | (FT-035T) NTES to T-530 | 457895 |
| (FT-041T) MW-38S to T-540/541 | 2694379 | (FT-017) BIO Inf. from T-530 | 646940 |
| (FT-042T) MW-38 Source to T-540/541 | 3982106 | (FT-018) T-540/541 Influent | 86263311 |
| (FT-055) On - Site N. End Influent | 96344647 | (FT-352) T-352 to HMR-30 | 1249517 |

# ABLE 3.19.1
# STANDARD OPERATIONS CHECKLIST
# MAIN WTP

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, July 22, 2021

**Inspection Performed by:** Mike Gelwick

### P. AIR COMPRESSORS

| Item | Status | Comments |
|---|---|---|
| Compressor Intake Temp. | 76 °F (Analog Gauge) | Outside Temp.: ~ 82 °F |
| Compressor Building Vent | ✓ | open - operational |
| Primary Air Compressor (IRN30H) | 2,000 Hour service date: 7-8-21<br>Serviced @ 60952 Hours | Coolant present in sight glass: Y / N<br>Next service @ 62952 Hours<br>Current Hours @ 61142 |
| IRN30H Motor Speed | 31 % | |
| IRN30H Pressure | 116 psi | |
| IRN30H Moisture purge valve chk(Weekly): | ✓ | |
| IRN30H Intake Filter | ✓ | Date Last Changed: 7-8-21 |
| Air Tanks Moisture Purge Valves | Manually Activate(weekly) ✓ | Excessive Moisture: Y / N |
| Backup Air Compressors (T-30 East and West) | ✓ | Both cool to touch: Y / N |
| Air Dryer | ✓ | Moisture at Receiver Tank: Y / N |
| Oil Moisture Prevention (Monthly) | Last Done: 7-22-21 - today | Run at max speed by bleeding air from filter canister above/after air dryer for 2 hrs |
| Air Receiver Tank | ✓ | 108 psi |

### Q. SUMPS

| Item | Status | Comments |
|---|---|---|
| Bag Filter Sump | ✓ | |
| Wet Well Sump | ✓ | |

### R. GAS CHROMATOGRAPH

| Item | Status | Comments |
|---|---|---|
| GC Operational | ✓ | GC # checking UV-Ox Effluent: #2 |
| Alarms Enabled | ✓ | CC-Calibration + maint - 7-21-21 |
| GC Influent Filters | ✓ | |

### S. SAFETY

| Item | Status | Comments |
|---|---|---|
| Building #1 Fire Extinguishers | ✓ | Date inspected: 6-23-21 |
| Building #1 Eye Wash/Shower | ✓ | Checked and Flushed- All OK: Y / N |

**Other Comments:**

| |
|---|
| |
| |
| |
| |
| |

# TABLE 3.19.2
# STANDARD OPERATIONS CHECKLIST
# BIOLOGICAL TREATMENT SYSTEM

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, July 22, 2021

**Inspection Performed by:** Mike Gelwick

## A. PUMPS

| Item | Status | Flow Rate (gpm) | Pump Speed (CV%) | Discharge Pressure (psi) | | Comments |
|---|---|---|---|---|---|---|
| **T-510 Pumps** | | | | | | |
| P-3301 | SB | – | – % | – | | |
| P-3301A | ✓ | 1.91 | 31.5 % | 6.5 | | |
| **NTES Pump** P-002(Sump) / (P-002W(10R)) | ✓ | 0.50 | 48 % | P035 37-38 | P038 6.5 | Globules Observed at TP-130: Y / (N) Time: 1015 |
| **T-530** P-005 | ✓ | 0.20 | 33 % | 5.5 | | |
| **T-540/541** P-006 | ✓ | 0.30 | 49 % | 3.5 | | |
| **LFG COND Auto-Traps** | ✓ | 0.0 | NA | 5.0 | | Between Cycles: (Y) / N |
| **Reactor Feed Pumps** | | | | | | |
| P-3321 | ✓ | 2.55 | 64.9 % | 8.0 | | |
| P-3322 | ✓ | 3.53 | 56.3 % | 5.5 | | |
| P-3323 | ✓ | 2.52 | 50.3 % | 7.5 | | |
| P-3324 | SB | – | – % | – | | |
| **Reactor Effluent Pumps** | | | | | | |
| P-3341 | ✓ | 4.26 | 65.6 % | 20.0 | | |
| P-3341A | SB | – | – % | – | | |

## B. BLOWERS

| Item | Status | Pressure (psi) | Temp (°F) | Next Scheduled Service (Qtrly) | Comments Last serviced on: 6-22-21 |
|---|---|---|---|---|---|
| B-3331 | ✓ | 4.25 | 156 | 9-2021 | Greased, Belt and Filter Checked: (Y) / N |
| B-3332 | SB | – | – | ↓ | Belt and Filter Checked: Y / (N) |
| B-3333 | ✓ | 4.43 | 164 | ↓ | Greased, Belt and Filter Checked: (Y) / N |
| B-3334 | ✓ | 4.12 | 148 | ↓ | Greased, Belt and Filter Checked: (Y) / N |

## C. REACTOR VENTILATION

| Item | Status | Comments |
|---|---|---|
| Vapor Carbon Contactor | ✓ | On-line: 2/10/18 |
| Reactor Vent Blower | ✓ | |
| Reactor Vent Booster | ✓ | |
| VTP-3350 | ✓ | PID Reading: 0.9 PPM |
| VTP-3360 | ✓ | PID Reading: 0.1 PPM |

# TABLE 3.19.2
# STANDARD OPERATIONS CHECKLIST
# BIOLOGICAL TREATMENT SYSTEM

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, July 22, 2021

**Inspection Performed by:** Mike Gelwick

## D. TANKS / REACTORS / SUMPS / CONTAINMENTS / PIPING / Chiller

| Item | Status | Comments |
|---|---|---|
| T-510 Post HMR-30 Mixing Tank | ✓ Level: 67 % | Last Cleaning (As needed, if 2" of solids accumulate): 12/15/19 |
| T-530 LFG Condensate / NTES Tank | ✓ Level: 27 % | |
| T-530 Mixer | ✓ | |
| LFG Condensate Conveyance Line | ✓ | Last Pressure Test: 7-19-21 Next: 7-2022 (Annual at a minimum or if flow drops off) |
| T-540/541 MW38 Tanks | Lvls: 64 % & 65% | |
| T-540/541 Mixers | ✓ | |
| Chiller | ✓ | Chiller Coolant Lvl: ~ 1.0 " Below full mark |
| Chiller Cooling Fins (as needed) | ✓ | Last Cleaning: 4/20/18 (unit on Standby) |
| Secondary Containments | ✓ | Heat Trace: On OK / (Off Warm out) |
| Feed Piping to Sedimentation Tank | ✓ | Last Back Flushing (Quarterly): 7-14-21 |
| T-3310 Sedimentation Tank | Visual Level: OK | Last Cleaning (As Needed, use TSS info to determine): 12/2017 |
| T-3320 Blend Tank | ✓ Level: 70 % | Last Cleaning (Semi Annual): 5-7-20 |
| T-3331 Reactor No. 1 | ✓ | Digital Displays: (GOOD) / Needs Attn |
| T-3332 Reactor No. 2 | ✓ | Digital Displays: (GOOD) / Needs Attn |
| T-3333 Reactor No. 3 | ✓ | Digital Displays: (GOOD) / Needs Attn |
| T-3334 Settling Tank | ✓ | Last Cleaning (Semi Annual): 5-7-20 |
| P-3334 Biosolids Pump | ✓ | |
| T-3340 Overflow Tank | ✓ Level: 30 % | |
| Recycle Valve to Blend Tank | ✓ | 3.98 gpm @ 1113 |
| Building Containment Sump | ✓ | Last Alarm Test Date (Monthly): 7-22-21 - today |

## E. CHEMICAL FEED SYSTEM

| Item | Status | Comments |
|---|---|---|
| Phosphorous Supply | ✓ | Bags: 19 Gallons: ~ 55 |
| Phosphorous Pump (P-2221) | ✓ | |
| Caustic Supply | ✓ | ~ 270 Gallons |
| Caustic Pump (P-2211) | SB | Currently in acid addition mode |
| Acid Supply | ✓ | ~ 40 Gallons |
| Acid Pump (P-2211) | ✓ | |
| Caustic Pump (P-2231) | ✓ Leaks: Y / (N) | Last tubing tip cleaning (monthly): 7-22-21 - today |
| Caustic Pump (P-2232) | ✓ Leaks: Y / (N) | Last tubing tip cleaning (monthly): ↓ |
| Caustic Pump (P-2233) | ✓ Leaks: Y / (N) | Last tubing tip cleaning (monthly): ↓ |

# TABLE 3.19.2
# STANDARD OPERATIONS CHECKLIST
# BIOLOGICAL TREATMENT SYSTEM

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, July 22, 2021

**Inspection Performed by:** Mike Gelwick

### F. pH Probes

| pH Probe Location | Calibration Date (Monthly) | Comments |
|---|---|---|
| pH-3320 Blend Tank | 6-24-21 | Acid/Base clean today |
| pH-3331 Reactor 1 | ↓ | ↓ |
| pH-3332 Reactor 2 | | |
| pH-3333 Reactor 3 | | |

### G. FILTER SYSTEM

| Item | Status | Comments |
|---|---|---|
| BF-3340 a/b Status | ✓ | |
| Automatic Backwash | Cycle Count: 47 | reset |
| BF-3340 a/b Differential Pressure | PSI: 3 | 19/16 @ 3.7 gpm |
| 75-micron Bags Last Cleaning | Date: 11-14-19 | |
| 75-micron Bags Last Inspection | Date: ↓ | |
| 75-micron Bags Last Changed | Date: | |
| GACF-3340 Status | ✓ | |
| GACF-3340 Differential Pressure | PSI: 4 | 19/15 @ 3.7 gpm |
| Last Backwash Performed | Date: 7-14-21 | |

### H. ELECTRICAL AND INSTRUMENTATION

| Item | Status | Comments |
|---|---|---|
| "BIO" Backup Generator | ✓ Top off Fuel 7-19-21 | Block Heater: On OK / (Off Warm Out) |
| Electrical Surge Suppressor | ✓ | |
| Motor Control Center | ✓ | |
| PLC | ✓ | UPS @ 97 min / 71 Events |
| HMI's | ✓ | |
| BTS Process KWH Meter | MB1836 KWH | Time: 1205 |
| Building#2 KWH Meter | 5199525 KWH | Time: 1205 |

### I. GAS CHROMATOGRAPHY

| Item | Status | Comments |
|---|---|---|
| GC Operational | ✓ | GC # checking BIO: #3 |
| Alarms Enabled | ✓ | cc- Calibration + Maint - 7-21-21 |
| GC Influent Filters | ✓ | |

# TABLE 3.19.2
# STANDARD OPERATIONS CHECKLIST
# BIOLOGICAL TREATMENT SYSTEM

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, July 22, 2021

**Inspection Performed by:** Mike Gelwick

## J. TOTALIZERS

| Item | Readings (gallons) | Comments |
|---|---|---|
| FT-3321 Feed to Reactor 1 | 5742648 | |
| FT-3324 Feed Spare | 45628 | |
| FT-3322 Feed to Reactor 2 | 10325998 | |
| FT-3323 Feed to Reactor 3 | 419798 | |
| FT-3301 T-510 to BIO | 51212873 | |
| FT-3341 BIO Effluent | 65916832 | |
| FT-3342 BIO Recycle | 54963778 | |

## K. SAFETY

| Item | Status | Comments |
|---|---|---|
| Building #2 Fire Extinguishers | ✓ | Inspection date: 6-23-21 |
| Building #2 Eye Wash/Shower | ✓ | Checked and Flushed- All OK: (Y) / N |

## L. OTHER COMMENTS:

| |
|---|
| |
| |
| |
| |

# ABLE 3.19.1
# STANDARD OPERATIONS CHECKLIST
# MAIN WTP

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, July 29, 2021

**Inspection Performed by:** Mike Gelwick

## A. PERIMETER COLLECTION SYSTEMS

| Item | Status | Comments |
|---|---|---|
| LFG Cond Automatic Trap CT-1 | Sump Level: 13.21 oz | Counter: 177679 Cycles: 60 |
| LFG Cond Automatic Trap CT-2 | Sump Level: 8.55 oz | Counter: 273873 Cycles: 104 |
| LFG Cond Automatic Trap CT-3 | Sump Level: 7.36 oz | Counter: 299479 Cycles: 1107 |
| CT-4 Containment/Vessel (LFG Cond) | ✓ Level: 90 % | Tank Level: 2.18 Counter: 191165 Cycles: 1 Sump: 8.90 oz |
| PM-15 Containment / Vessel | ✓ Level: 27 % | |
| MW-51 Containment / Vessel | ✓ Level: 70 % | |
| PM-11 Containment / Vessel | ✓ Level: 75 % | |
| MW-38 Systems | ✓ | |
| North Toe System | ✓ | |
| North End Systems (Weekly) | ✓ | |
| Full N. End Systems Check (Monthly) | ✓ | Last Done: 7-26-21 |
| North End Pipeline(s)Flushing (As Needed) | ✓ | Perform if suspended solids present Last Done: 11/15/15 |
| NTES line flush to T-530 (As needed) | ✓ | Perform if suspended solids present Last Done: 2/13/20 |
| NTES Piping Containment | ✓ | Monthly Sump Level: Dry @ 16.07' Date: 7-22-21 |
| North Boundary System P-001: | CV 75.8% @ 7.6 gpm | 42.27 Hz / 2.11 Amps. / vault psi @ 18/20 Inches |
| T-101 & T-102 Containment / Tank | ✓ | Levels: % & % |
| Raw Water Storage Tanks Piping | ✓ | |
| RWST Building Temp. (TT-101) | 76.9 °F | Outside Temp.: ~ 75 °F |
| (P-121) or P-122 | ✓ | 0.6 gpm / CV 65 % |
| RWST 2ndry Cont. High Level Switch | ✓ | (LSH-101) Last Test(monthly): 7-22-21 |
| RWST Back-Up Generator | ✓ | Last Test Run(monthly): 7-22-21 |

## B. CHEMICAL STORAGE BAYS

| Item | Status | Comments |
|---|---|---|
| Caustic Tote Levels | ✓ | ~530 Gallons Reserve = 3 totes |
| Caustic Bay Heater | ✓ | SB - warm out |
| Peroxide Tote Level | ✓ | ~ 175 Gallons Reserve = ~55 gal |
| HCL Tote Levels | ✓ | ~ 275 Gallons Reserve = ~ 90 gal |
| Chemical Totes and Piping Inspected | ✓ | Leaks observed: Y / (N) |
| Emergency Shower Inspected | ✓ | Checked and Flushed - All OK: (Y) / N |

## C. PRIMARY AND SECONDARY ACID FEED SYSTEM

| Item | Status | Comments |
|---|---|---|
| Primary Acid Feed Pump (P-631) | ✓ | |
| Ion Exchange Acid Feed Pump (P-632) | ✓ | PI-0632 PSI: 68-70 CV: 5 % |
| Primary Acid Retention Tank (T-510) | ✓ | |
| All Acid Feed Lines | ✓ | Leaks observed: Y / (N) |

## D. NBBW INJECTION TRENCH

| Item | Status | Comments |
|---|---|---|
| Injection Carbon (GAC-810) | OFFLINE | Date online: 7/20/18 |
| Injection Rate (FT-800) | 0.0 gpm | NBBW-IW-1= 0.0 NBBW-IW-2= 0.0 NBBW-IW-3= 0.0 gpm ea. |
| Totalizer Reading (FT-800) | 105,135,774 gal | INJ. STOPPED 10/02/18 @ 1545 |

# ABLE 3.19.1
# STANDARD OPERATIONS CHECKLIST
# MAIN WTP

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, July 29, 2021

**Inspection Performed by:** Mike Gelwick

## E. CHEMICAL PRECIPITATION SYSTEM (US FILTER HMR-30)

| Item | Status | Comment |
|---|---|---|
| T-300A Mixer | NA | |
| T-300B (Caustic Mixer) | ✓ | Last Cleaning (Qtrly): 6-3-21 |
| T-300A/B Water Level | ✓ | |
| T-300B (Caustic Mix Chamber) | ✓ | Last Cleaning (Qtrly): 6-3-21 |
| T-300A/B Overflow | ✓ | |
| pH Set-point for (pH 315) | Value: 10.8 | |
| pH 310 | Value: 6.74 | |
| pH 315 | Value: 10.84 | |
| Flocculation Chamber Paddle Wheel | ✓ | |
| Precipitate Floc Quality | ✓ | Good |
| Clarifier Water Quality | ✓ | Good Oil or sheen observed: Y / (N) |
| Clarifier Effluent Piping / Water Level | ✓ | |
| Clear-well Chamber and Water Level | ✓ | |
| HMR PLC Panel | ✓ | |
| Caustic Pump (P-270) | SB | |
| Caustic Pump (P-280) | ✓ | |
| Polymer Pump (P-310) | ✓ | |
| Polymer Tank Mixer | ✓ | |
| Polymer Tank Level | Gallons: ~ 425 | |
| Clear-well Transfer Pumps(P-371 / (372)) | ✓ | |
| Sludge Transfer Pump (P-330) | ✓ | Exercise Valves Weekly: Bottom OK / Shut for to close + open but very sticky - still needs replace |
| Manual Sludge Lateral pumping | ✓ | Last done (As Needed): #3 - 7-20-21 / #1 & 2 3-2020 |
| Manual Sludge Lateral Ball Valves | ✓ | Exercise Weekly: All ok |
| Automatic Blow-down Operations | ✓ | |

## F. pH PROBES

| pH Probe Location | Calibration Date | Comments: (Time done) |
|---|---|---|
| pH-310 HMR-30 (T-300A) | 7-29-21 - today | 1253 |
| pH-315 HMR-30 (T-300B) | | |
| pH-365 Primary Acid Ret. Tank | | |
| pH-113 Pre-Ion Exchange | | |
| pH-670 Pre-UV-OX | | 1319 |
| pH-740 Discharge Surge Tank | | Discharge suspended: 1320 ↔ 1340 |
| Out of Hold Double Check | ---------- | None in hold: ✓✓ m |
| Valves Back to Normal Position | ---------- | All OK: ✓✓ m |

## G. SLUDGE THICKENER, SLUDGE HOLDING TANKS, FILTER PRESS

| Item | Status | Comments |
|---|---|---|
| Verify Sludge Thickener Running | ✓ | Gauge Reading: 0 % |
| Sludge Thick. Transfer Pump (P-350) | ✓ | |
| Sludge Holding Tank (T-351) | ✓ | Level:~ 65 % |
| Sludge Holding Tank (T-352) | ✓ | Level: 46 % |
| Decant Transfer Pump (P-352) | ✓ | CV 42 % @ 0.6 gpm |
| Filter Press Pumps (P-381 / P-382) | ✓ | |
| Filter Press | ✓ | Stage: Full |

# ABLE 3.19.1
# STANDARD OPERATIONS CHECKLIST
# MAIN WTP

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, July 29, 2021

**Inspection Performed by:** Mike Gelwick

### H. ION EXCHANGE

| Item | Status | Comments |
|---|---|---|
| Feed Tank (T-113) | ✓ Level: 30 % | |
| Feed Pump (P-114) | ✓ Operating Press: 61.6 psi | CV@ 88 % @ 2.1 gpm |
| Retention Tank (T-114) | ✓ Operating Press: 60 psi | pH-113 @ 3.83 |
| Bag Filter (BF-113) | ✓ Operating Press: 63 psi | |
| Ion Exchange (Cage (1) or 2) + Guard | ✓ Operating Press: 60 psi | TP-173A → TP-177A / 9 canisters + Guard |
| Post Ion Exchange | ✓ Operating Press: 3.5 psi | |

### I. FEED SURGE TANK

| Item | Status | Comments |
|---|---|---|
| Feed Surge Tank (T-520) | ✓ Level: 38 % | Last Cleaning (As Needed, if 4" of solids accumulate): 12/15/19 |
| Feed Surge Pump (P-521 or (P-522)) | Operating Press: ~~831~~ psi | CV@ 73 % @ 35.6 gpm |
| T-520 to GAC Total (FT-675) | 246993048 gal | Time: 1031 |
| North End On-Site Pumping | Operating Press: 2-3 psi | 13.2 gpm @ 1026 |
| North End Off-Site Pumping | Operating Press: 2-6 psi | 8.5 gpm @ 1026 |
| Peroxide Feed Pump (P-680) | ✓ | SPD 2.7 % / RATE 0.7 |
| Peroxide Conc. At (TP-710) | 1.0 PPM | |
| Peroxide Conc. At (TP-740) | 00 PPM | |

### J. HAZARDOUS WASTE STORAGE

| Item | Status | Comments |
|---|---|---|
| 180 Day storage area check | ✓ | Check sheet completed: NA/Empty |
| Satellite Haz. Waste Areas (BLDG #1) | ✓ | Condition: Good |
| Satellite Haz. Waste Area (BLDG #2) | ✓ | Condition: Good |

### K. UV-OXIDATION SYSTEM

| Item | Status | Comments |
|---|---|---|
| UV-Oxidation System | ✓ | |
| Annual Test Run (Calgon) | Date: 8-4-20 | Next: 8-2021 |
| Quarterly Test Run | Date: NA/Running | Next: NA/Running |
| Peroxide Feed Pump (P-650) | ✓ | Flow Rate: ~7.0 cc/min. |
| UV-Ox Power | ✓ | 25.7 kVA 2619 Volts 9.8 Amps |
| Lamp Hours | 2 Hrs | Change out Lamp today - 7-29-21 Lamp Had 3,295 Hrs ⇒ Change out |
| Crystal Condition & Wiper Status | ✓ | Oiler status: OK |
| UV-OX Bagfilters Status | Last change: 7-13-21 Cleaned: 7-13-21 | 11.0 psi In 11.5 psi Out |
| UV-OX Feed Pump ( P-600 or (P-601) ) | ✓ | CV@ 74 % @ 8.0 gpm |
| UV-OX Temperature | In(TT-670): 17.7 °C | Out(TT-710): 29.0 °C |
| PDU GAC (PDT-710) | ✓ | Δ Pressure: 3 psi |
| Peroxide Concentration Pre UV | 100 PPM | |
| Peroxide Concentration Post UV(TP-720) | 20 PPM | |
| Peroxide Conc. Post PDU (TP-730) | 00 PPM | |
| Secondary Acid Feed Pump (P-630) | ✓ | CV @ 1 % |
| Secondary Acid Retention Tank (T-645) | ✓ | |
| Pre – UV Oxidizer Total (FT-670) | 19145150 gal | Time: 1031 |
| Post UV-Ox / Pre PDU | ✓ | Pressure: 14 psi |
| Post PDU | ✓ | Pressure: 7 psi |

# ABLE 3.19.1
# STANDARD OPERATIONS CHECKLIST
# MAIN WTP

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, July 29, 2021

**Inspection Performed by:** Mike Gelwick

### L. PDU AND LIQUID –PHASE GRANULAR ACTIVATED CARBON

| Item | Status | Comments |
|---|---|---|
| PDT-720 | ✓ | Δ Pressure: 15 psi |
| PDT-730 | ✓ | Δ Pressure: 10 psi |

### M. EFFLUENT DISCHARGE

| Item | Status | Comments |
|---|---|---|
| Effluent Surge Pump (P751 or P752 ) | ✓ | CV@ 55.4 % |
| Effluent Surge Tank (T-740) | ✓ | Level: 40 % |
| Effluent Discharge Rate (FT-770) | ✓ | 35.8 gpm @ 1030 |
| POTW Line Pressure (PT-770) | ✓ | 32.5 psi |
| Effluent Totalizer Reading (FT-770) | 241062714 gal | Time: 1032 |
| POTW MH17S-078 Discharge Check (Monthly) | ✓ | Last Done: 7-8-21 |
| 4X8-Inch POTW Leak Detection Checks (Monthly) | ✓ | Last Done: |
| 4X8-Inch POTW Air Reliefs Checks (Monthly) | ✓ | Last Done: |
| 4X8-Inch POTW Isolation Valves Exercise (Qtrly) | ✓ | Last Done: |
| 2-Inch POTW Backup Pressure Testing (Annual) | ✓ | Last Done: ~~5/19/20~~ |
| 2-In POTW Backup Air Reliefs Checks (Annual) | ✓ | Last Done: ~~5/19/20~~ |
| 2-Inch POTW Isolation Valve Exercise (Annual) | ✓ | Last Done: ~~5/19/20~~ |
| Rotate Chiller Compressors | NA on Standby | ~~Now in Lead: 1 or 2~~ |

### N. LEL EFFLUENT TANK T-740

| Item | Status | Comments |
|---|---|---|
| LEL-740 Sensor | ✓ | Reading: 0 % |
| LEL Sensor Calibration / Automatic High LEL Shutdown Test (monthly) ✓ | Last Completed: 7-29-21 - today | Plant Effluent Suspended: 1320 ↔ 1340 |
| LEL Sensor Bridge Adjustment to 2.0 volts | Reading: 2.001 volts(monthly) | Adjustment Needed: Y or (N) |
| Verify Bridge Current between.300v-.360v | Reading: 0.331 volts(monthly) | |

### O. WTP INFLUENT TOTALIZERS Time : 1032 - 1036

| Source | Reading(Gallons) | Source | Reading(Gallons) |
|---|---|---|---|
| (FT-015) RWST Influent | 19565229 | (FT-505) LFG Cond. to T-530 | 214995 |
| (FT-025) NBBW Influent | 93132813 | (FT-056) Off - Site N. End Influent | 42134676 |
| (FT-012) MW-38 Inf. to HMR-30 | 8040535 | (FT-113) Ion Exchange Influent | 398283 |
| (FT-042 HMR30) MW-38 Source to HMR-30 | 35484 | (FT-810) Plant Potable Water In | 30051700 |
| (FT-043) MW-38 to RWST | 3064653 | (FT-026) NBBW Bypass to RWST | 4364940 |
| (FT-042 RWST) MW-38 Source to RWST | 72236 | (FT-014) Misc. Water to RWST | 8112833 |
| (FT-012T) MW-38 to T-540/541 | 8581121 | (FT-035) NTES Inf. to BIO | 4600783 |
| (FT-040T) MW-38N to T-540/541 | 1976607 | (FT-035T) NTES to T-530 | 458394 |
| (FT-041T) MW-38S to T-540/541 | 26943 79 | (FT-017) BIO Inf. from T-530 | 647809 |
| (FT-042T) MW-38 Source to T-540/541 | 3982106 | (FT-018) T-540/541 Influent | 8629262 |
| (FT-055) On - Site N. End Influent | 96477687 | (FT-352) T-352 to HMR-30 | 1253142 |

# ABLE 3.19.1
# STANDARD OPERATIONS CHECKLIST
# MAIN WTP

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, July 29, 2021

**Inspection Performed by:** Mike Gelwick

### P. AIR COMPRESSORS

| Item | Status | Comments |
|---|---|---|
| Compressor Intake Temp. | 72 °F (Analog Gauge) | Outside Temp.: ~ 76 °F |
| Compressor Building Vent | ✓ | open - operational |
| Primary Air Compressor (IRN30H) | 2,000 Hour service date: 7-8-21<br>Serviced @ 60952 Hours | Coolant present in sight glass: Ⓨ / N<br>Next service @ 62952 Hours<br>Current Hours @ 61237 |
| IRN30H Motor Speed | 0 % | |
| IRN30H Pressure | 114 psi | |
| IRN30H Moisture purge valve chk(Weekly): | ✓ | |
| IRN30H Intake Filter | ✓ | Date Last Changed: 7-8-21 |
| Air Tanks Moisture Purge Valves | Manually Activate(weekly) ✓ | Excessive Moisture: Y / Ⓝ |
| Backup Air Compressors (T-30 East and West) | ✓ | Both cool to touch: Ⓨ / N |
| Air Dryer | ✓ | Moisture at Receiver Tank: Y / Ⓝ |
| Oil Moisture Prevention (Monthly) | Last Done: 7-22-21 | Run at max speed by bleeding air from filter canister above/after air dryer for 2 hrs |
| Air Receiver Tank | ✓ | 110 psi |

### Q. SUMPS

| Item | Status | Comments |
|---|---|---|
| Bag Filter Sump | ✓ | |
| Wet Well Sump | ✓ | |

### R. GAS CHROMATOGRAPH

| Item | Status | Comments |
|---|---|---|
| GC Operational | ✓ | GC # checking UV-Ox Effluent: # 2 |
| Alarms Enabled | ✓ | cc-calibration + manual - 7-28-21 |
| GC Influent Filters | ✓ | |

### S. SAFETY

| Item | Status | Comments |
|---|---|---|
| Building #1 Fire Extinguishers | ✓ | Date inspected: 7-26-21 |
| Building #1 Eye Wash/Shower | ✓ | Checked and Flushed- All OK: Ⓨ / N |

**Other Comments:**

# TABLE 3.19.2
# STANDARD OPERATIONS CHECKLIST
# BIOLOGICAL TREATMENT SYSTEM

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, July 29, 2021

**Inspection Performed by:** Mike Gelwick

## A. PUMPS

| Item | Status | Flow Rate (gpm) | Pump Speed (CV%) | Discharge Pressure (psi) | Comments |
|---|---|---|---|---|---|
| **T-510 Pumps** | | | | | |
| P-3301 | SB | – | – % | – | |
| P-3301A | ✓ | 3.97 | 48.3 % | 10.0 | |
| **NTES Pump** P-002(Sump) / (P-002W(10R)) | ✓ | 0.50 | 49 % | P035: 35-36 / P038: 6.5 | Globules Observed at TP-130: Y / (N) Time: 1000 |
| **T-530** P-005 | ✓ | 0.20 | 36 % | 5.5 | |
| **T-540/541** P-006 | ✓ | 0.30 | 57 % | 4.0 | |
| **LFG COND Auto-Traps** | ✓ | 0.0 | NA | 5.0 | Between Cycles: (Y) / N |
| **Reactor Feed Pumps** | | | | | |
| P-3321 | ✓ | 2.65 | 80.3 % | 8.0 | |
| P-3322 | ✓ | 3.68 | 52.8 % | 5.0 | |
| P-3323 | ✓ | 2.66 | 54.4 % | 7.0 | |
| P-3324 | SB | – | – % | – | |
| **Reactor Effluent Pumps** | | | | | |
| P-3341 | ✓ | 3.45 | 69.5 % | 19.0 | |
| P-3341A | SB | – | – % | – | |

## B. BLOWERS

| Item | Status | Pressure (psi) | Temp (°F) | Next Scheduled Service (Qtrly) | Comments Last serviced on: 6-22-21 |
|---|---|---|---|---|---|
| B-3331 | ✓ | 4.24 | 162 | 9-2021 | Greased, Belt and Filter Checked: (Y) / N |
| B-3332 | SB | – | – | ↓ | Belt and Filter Checked: Y / (N) |
| B-3333 | ✓ | 4.34 | 166 | ↓ | Greased, Belt and Filter Checked: (Y) / N |
| B-3334 | ✓ | 4.28 | 160 | ↓ | Greased, Belt and Filter Checked: (Y) / N |

## C. REACTOR VENTILATION

| Item | Status | Comments |
|---|---|---|
| Vapor Carbon Contactor | ✓ | On-line: 2/10/18 |
| Reactor Vent Blower | ✓ | |
| Reactor Vent Booster | ✓ | |
| VTP-3350 | ✓ | PID Reading: 1.1 PPM |
| VTP-3360 | ✓ | PID Reading: 0.7 PPM |

# TABLE 3.19.2
# STANDARD OPERATIONS CHECKLIST
# BIOLOGICAL TREATMENT SYSTEM

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, July 29, 2021

**Inspection Performed by:** Mike Gelwick

## D. TANKS / REACTORS / SUMPS / CONTAINMENTS / PIPING / Chiller

| Item | Status | Comments |
|---|---|---|
| T-510 Post HMR-30 Mixing Tank | ✓ Level: 69 % | Last Cleaning (As needed, if 2" of solids accumulate): 12/15/19 |
| T-530 LFG Condensate / NTES Tank | ✓ Level: 24 % | |
| T-530 Mixer | ✓ | |
| LFG Condensate Conveyance Line | ✓ | Last Pressure Test: 7-19-21 Next: 7-2022 (Annual at a minimum or if flow drops off) |
| T-540/541 MW38 Tanks | Lvls: 41 % & 43 % | |
| T-540/541 Mixers | ✓ | |
| Chiller | ✓ | Chiller Coolant Lvl: ~1,0 " Below full mark |
| Chiller Cooling Fins (as needed) | ✓ | Last Cleaning: 4/20/18 (unit on Standby) |
| Secondary Containments | ✓ | Heat Trace: On OK / (Off Warm out) |
| Feed Piping to Sedimentation Tank | ✓ | Last Back Flushing (Quarterly): 7-14-21 |
| T-3310 Sedimentation Tank | Visual Level: ok | Last Cleaning (As Needed, use TSS info to determine): 12/2017 |
| T-3320 Blend Tank | ✓ Level: 74 % | Last Cleaning (Semi Annual): 5-7-20 |
| T-3331 Reactor No. 1 | ✓ | Digital Displays: (GOOD) / Needs Attn |
| T-3332 Reactor No. 2 | ✓ | Digital Displays: (GOOD) / Needs Attn |
| T-3333 Reactor No. 3 | ✓ | Digital Displays: (GOOD) / Needs Attn |
| T-3334 Settling Tank | ✓ | Last Cleaning (Semi Annual): 5-7-20 |
| P-3334 Biosolids Pump | ✓ | |
| T-3340 Overflow Tank | ✓ Level: 30 % | |
| Recycle Valve to Blend Tank | ✓ | 4.28 gpm @ 1051 |
| Building Containment Sump | ✓ | Last Alarm Test Date (Monthly): 7-22-21 |

## E. CHEMICAL FEED SYSTEM

| Item | Status | Comments |
|---|---|---|
| Phosphorous Supply | ✓ | Bags: 19 Gallons: ~ 70 |
| Phosphorous Pump (P-2221) | ✓ | |
| Caustic Supply | ✓ | ~ 260 Gallons |
| Caustic Pump (P-2211) | SB | Currently in acid addition mode |
| Acid Supply | ✓ | ~ 40 Gallons |
| Acid Pump (P-2211) | ✓ | |
| Caustic Pump (P-2231) | ✓ Leaks: Y / (N) | Last tubing tip cleaning (monthly): 7-22-21 |
| Caustic Pump (P-2232) | ✓ Leaks: Y / (N) | Last tubing tip cleaning (monthly): ↓ |
| Caustic Pump (P-2233) | ✓ Leaks: Y / (N) | Last tubing tip cleaning (monthly): ↓ |

# TABLE 3.19.2
# STANDARD OPERATIONS CHECKLIST
# BIOLOGICAL TREATMENT SYSTEM

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, July 29, 2021

**Inspection Performed by:** Mike Gelwick

### F. pH Probes

| pH Probe Location | Calibration Date (Monthly) | Comments |
|---|---|---|
| pH-3320 Blend Tank | 7-29-21 - today | New 4 + 10 pH Stds today |
| pH-3331 Reactor 1 | ↓ | ↓ |
| pH-3332 Reactor 2 | | |
| pH-3333 Reactor 3 | | |

### G. FILTER SYSTEM

| Item | Status | Comments |
|---|---|---|
| BF-3340 a/b Status | ✓ | |
| Automatic Backwash | Cycle Count: 75 | Reset |
| BF-3340 a/b Differential Pressure | PSI: 8 | 10/18 @ 2.6 gpm |
| 75-micron Bags Last Cleaning | Date: 11-14-19 | |
| 75-micron Bags Last Inspection | Date: | |
| 75-micron Bags Last Changed | Date: ↓ | |
| GACF-3340 Status | ✓ | |
| GACF-3340 Differential Pressure | PSI: 4 | 10/6 @ 2.6 gpm |
| Last Backwash Performed | Date: 7-14-21 | |

### H. ELECTRICAL AND INSTRUMENTATION

| Item | Status | Comments |
|---|---|---|
| "BIO" Backup Generator | ✓ | Block Heater: On OK / (Off Warm Out) |
| Electrical Surge Suppressor | ✓ | |
| Motor Control Center | ✓ | |
| PLC | ✓ | UPS @ 97 min / 71 Events |
| HMI's | ✓ | |
| BTS Process KWH Meter | 1783632 KWH | Time: 1136 |
| Building#2 KWH Meter | 5202219 KWH | Time: 1136 |

### I. GAS CHROMATOGRAPHY

| Item | Status | Comments |
|---|---|---|
| GC Operational | ✓ | GC # checking BIO: #3 |
| Alarms Enabled | ✓ | Cc - Calibration + Maint - 7-28-21 |
| GC Influent Filters | ✓ | |

# TABLE 3.19.2
# STANDARD OPERATIONS CHECKLIST
# BIOLOGICAL TREATMENT SYSTEM

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, July 29, 2021

**Inspection Performed by:** Mike Gelwick

## J. TOTALIZERS

| Item | Readings (gallons) | Comments |
|---|---|---|
| FT-3321 Feed to Reactor 1 | 5766472 | |
| FT-3324 Feed Spare | 45636 | |
| FT-3322 Feed to Reactor 2 | 10359072 | |
| FT-3323 Feed to Reactor 3 | 443288 | |
| FT-3301 T-510 to BIO | 51239611 | |
| FT-3341 BIO Effluent | 65952009 | |
| FT-3342 BIO Recycle | 55004858 | |

## K. SAFETY

| Item | Status | Comments |
|---|---|---|
| Building #2 Fire Extinguishers | ✓ | Inspection date: 7-26-21 |
| Building #2 Eye Wash/Shower | ✓ | Checked and Flushed- All OK: (Y) / N |

## L. OTHER COMMENTS:

| |
|---|
| |
| |
| |
| |

# ABLE 3.19.1
# STANDARD OPERATIONS CHECKLIST
# MAIN WTP

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, August 05, 2021

**Inspection Performed by:** Mike Gelwick

## A. PERIMETER COLLECTION SYSTEMS

| Item | Status | Comments |
|---|---|---|
| LFG Cond Automatic Trap CT-1 | Sump Level: 13.48 ok | Counter: 178521 Cycles: 842 |
| LFG Cond Automatic Trap CT-2 | Sump Level: 8.54 ok | Counter: 273866 Cycles: 93 |
| LFG Cond Automatic Trap CT-3 | Sump Level: 7.36 ok | Counter: 300575 Cycles: 1896 |
| CT-4 Containment/Vessel (LFG Cond) | ✓ Level: 70 % | Tank Level: 2.16 Counter: 19175 Cycles: 10 Sump: 0.92 ok |
| PM-15 Containment / Vessel | ✓ Level: 30 % | |
| MW-51 Containment / Vessel | ✓ Level: 30 % | |
| PM-11 Containment / Vessel | ✓ Level: 25 % | |
| MW-38 Systems | ✓ | |
| North Toe System | ✓ | |
| North End Systems (Weekly) | ✓ | |
| Full N. End Systems Check (Monthly) | ✓ | Last Done: 7-26-21 |
| North End Pipeline(s)Flushing (As Needed) | ✓ | Perform if suspended solids present Last Done: 11/15/15 |
| NTES line flush to T-530 (As needed) | ✓ | Perform if suspended solids present Last Done: 2/13/20 |
| NTES Piping Containment | ✓ | Monthly Sump Level: Dry 2/16.07' Date: 7-22-21 |
| North Boundary System P-001: | CV 73.6% @ 7.6 gpm | 42.52 Hz / 2.12 Amps. / vault psi @ 18/20 inches |
| T-101 & T-102 Containment / Tank | ✓ | Levels: 45 % & 44 % |
| Raw Water Storage Tanks Piping | ✓ | |
| RWST Building Temp. (TT-101) | 71.8 °F | Outside Temp.: ~ 81 °F |
| (P-121) or P-122 | ✓ | 3.0 gpm / CV 61 % |
| RWST 2ndry Cont. High Level Switch | ✓ | (LSH-101) Last Test(monthly): 7-22-21 |
| RWST Back-Up Generator | ✓ | Last Test Run(monthly): 7-22-21 |

## B. CHEMICAL STORAGE BAYS

| Item | Status | Comments |
|---|---|---|
| Caustic Tote Levels | ✓ | ~380 Gallons Reserve = 3 totes |
| Caustic Bay Heater | ✓ | ONSB-warm cut |
| Peroxide Tote Level | ✓ | ~150 Gallons Reserve = ~55 gal |
| HCL Tote Levels | ✓ | ~260 Gallons Reserve = ~55 gal |
| Chemical Totes and Piping Inspected | ✓ | Leaks observed: Y / (N) |
| Emergency Shower Inspected | ✓ | Checked and Flushed - All OK: (Y) / N |

## C. PRIMARY AND SECONDARY ACID FEED SYSTEM

| Item | Status | Comments |
|---|---|---|
| Primary Acid Feed Pump (P-631) | ✓ | |
| Ion Exchange Acid Feed Pump (P-632) | ✓ | PI-0632 PSI: 68-70 CV: 5 % |
| Primary Acid Retention Tank (T-510) | ✓ | |
| All Acid Feed Lines | ✓ | Leaks observed: Y / (N) |

## D. NBBW INJECTION TRENCH

| Item | Status | Comments |
|---|---|---|
| Injection Carbon (GAC-810) | OFFLINE | Date online: 7/20/18 |
| Injection Rate (FT-800) | 0.0 gpm | NBBW-IW-1= 0.0 NBBW-IW-2= 0.0 NBBW-IW-3= 0.0 gpm ea. |
| Totalizer Reading (FT-800) | 105,135,774 gal | INJ. STOPPED 10/02/18 @ 1545 |

# ABLE 3.19.1
# STANDARD OPERATIONS CHECKLIST
# MAIN WTP

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, August 05, 2021

**Inspection Performed by:** Mike Gelwick

### E. CHEMICAL PRECIPITATION SYSTEM (US FILTER HMR-30)

| Item | Status | Comment |
|---|---|---|
| T-300A Mixer | NA | |
| T-300B (Caustic Mixer) | ✓ | Last Cleaning (Qtrly): 6-3-21 |
| T-300A/B Water Level | ✓ | |
| T-300B (Caustic Mix Chamber) | ✓ | Last Cleaning (Qtrly): 6-3-21 |
| T-300A/B Overflow | ✓ | |
| pH Set-point for (pH 315) | Value: 10.8 | |
| pH 310 | Value: 6.81 | |
| pH 315 | Value: 10.86 | |
| Flocculation Chamber Paddle Wheel | ✓ | |
| Precipitate Floc Quality | ✓ | Good |
| Clarifier Water Quality | ✓ | Good Oil or sheen observed: Y / (N) |
| Clarifier Effluent Piping / Water Level | ✓ | |
| Clear-well Chamber and Water Level | ✓ | |
| HMR PLC Panel | ✓ | |
| Caustic Pump (P-270) | SB | |
| Caustic Pump (P-280) | ✓ | |
| Polymer Pump (P-310) | ✓ | |
| Polymer Tank Mixer | ✓ | |
| Polymer Tank Level | Gallons: ~550 | |
| Clear-well Transfer Pumps(P-371 /(372)) | ✓ | |
| Sludge Transfer Pump (P-330) | ✓ | Exercise Valves Weekly: Bottom ok / Top moves but sticky and still needs replaced |
| Manual Sludge Lateral pumping | ✓ | Last done (As Needed): #3 - 7-20-21 / #2 3-2020 |
| Manual Sludge Lateral Ball Valves | ✓ | Exercise Weekly: All ok |
| Automatic Blow-down Operations | ✓ | |

### F. pH PROBES

| pH Probe Location | Calibration Date | Comments: (Time done) |
|---|---|---|
| pH-310 HMR-30 (T-300A) | 8-5-21 - Today | 1340 |
| pH-315 HMR-30 (T-300B) | | |
| pH-365 Primary Acid Ret. Tank | | |
| pH-113 Pre-Ion Exchange | | |
| pH-670 Pre-UV-OX | | 1420 |
| pH-740 Discharge Surge Tank | | Discharge suspended: 1331 ↔ 1339 |
| Out of Hold Double Check | ---------- | None in hold: ✓✓ |
| Valves Back to Normal Position | ---------- | All OK: ✓✓ |

### G. SLUDGE THICKENER, SLUDGE HOLDING TANKS, FILTER PRESS

| Item | Status | Comments |
|---|---|---|
| Verify Sludge Thickener Running | ✓ | Gauge Reading: 0 % |
| Sludge Thick. Transfer Pump (P-350) | ✓ | |
| Sludge Holding Tank (T-351) | ✓ | Level:~ 65 % |
| Sludge Holding Tank (T-352) | ✓ | Level: 60 % |
| Decant Transfer Pump (P-352) | ✓ | CV 36 % @0.40 gpm |
| Filter Press Pumps (P-381 / P-382) | ✓ | |
| Filter Press | ✓ | Stage: Full |

# ABLE 3.19.1
# STANDARD OPERATIONS CHECKLIST
# MAIN WTP

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, August 05, 2021

**Inspection Performed by:** Mike Gelwick

### H. ION EXCHANGE

| Item | Status | Comments |
|---|---|---|
| Feed Tank (T-113) | ✓ Level: 31 % | |
| Feed Pump (P-114) | ✓ Operating Press: 60.9 psi | CV@ 89 % @ 2.1 gpm |
| Retention Tank (T-114) | ✓ Operating Press: 60 psi | pH-113 @ 3.73 |
| Bag Filter (BF-113) | ✓ Operating Press: 63 psi | |
| Ion Exchange (Cage (1) or 2) + Guard | ✓ Operating Press: 60 psi | TP-173A→TP-177A / 9 canisters + Guard |
| Post Ion Exchange | ✓ Operating Press: 3.5 psi | |

### I. FEED SURGE TANK

| Item | Status | Comments |
|---|---|---|
| Feed Surge Tank (T-520) | ✓ Level: 39 % | Last Cleaning (As Needed, if 4" of solids accumulate): 12/15/19 |
| Feed Surge Pump (P-521 or (P-522)) | Operating Press: 34 psi | CV@ 76 % @ 37.1 gpm |
| T-520 to GAC Total (FT-675) | 247326881 gal | Time: 1056 |
| North End On-Site Pumping | Operating Press: 2-3 psi | 13.3 gpm @ 1052 |
| North End Off-Site Pumping | Operating Press: 2-8 psi | 10.1 gpm @ 1052 |
| Peroxide Feed Pump (P-680) | ✓ | SPD 2.8 % / RATE 0.7 |
| Peroxide Conc. At (TP-710) | 1.0 PPM | |
| Peroxide Conc. At (TP-740) | 0.0 PPM | |

### J. HAZARDOUS WASTE STORAGE

| Item | Status | Comments |
|---|---|---|
| 180 Day storage area check | ✓ | Check sheet completed: N/A/Empty |
| Satellite Haz. Waste Areas (BLDG #1) | ✓ | Condition: Good |
| Satellite Haz. Waste Area (BLDG #2) | ✓ | Condition: Good |

### K. UV-OXIDATION SYSTEM

| Item | Status | Comments |
|---|---|---|
| UV-Oxidation System | ✓ | |
| Annual Test Run (Calgon) | Date: 8-4-20 | Next: 8-2021 |
| Quarterly Test Run | Date: N/A/Running | Next: N/A/Running |
| Peroxide Feed Pump (P-650) | ✓ | Flow Rate: ~ 20 cc/min. |
| UV-Ox Power | ✓ | 25.7 kVA 2634 Volts 9.8 Amps |
| Lamp Hours | 159 Hrs | |
| Crystal Condition & Wiper Status | ✓ | Oiler status: OK |
| UV-OX Bagfilters Status | Last change: 7-13-21 Cleaned: 7-13-21 | 11.0 psi In 11.5 psi Out |
| UV-OX Feed Pump ( P-600 or (P-601) ) | ✓ | CV@ 74 % @ 7.9 gpm |
| UV-OX Temperature | In(TT-670): 16.3 °C | Out(TT-710): 27.6 °C |
| PDU GAC (PDT-710) | ✓ | Δ Pressure: 3 psi |
| Peroxide Concentration Pre UV | 100 PPM | |
| Peroxide Concentration Post UV(TP-720) | 25 PPM | |
| Peroxide Conc. Post PDU (TP-730) | 0.0 PPM | |
| Secondary Acid Feed Pump (P-630) | ✓ | CV @ ( % |
| Secondary Acid Retention Tank (T-645) | ✓ | |
| Pre – UV Oxidizer Total (FT-670) | 19218308 gal | Time: 1056 |
| Post UV-Ox / Pre PDU | ✓ | Pressure: 14 psi |
| Post PDU | ✓ | Pressure: 7.5 psi |

# ABLE 3.19.1
# STANDARD OPERATIONS CHECKLIST
# MAIN WTP

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, August 05, 2021

**Inspection Performed by:** Mike Gelwick

### L. PDU AND LIQUID –PHASE GRANULAR ACTIVATED CARBON

| Item | Status | Comments |
|---|---|---|
| PDT-720 | ✓ | Δ Pressure: 17 psi |
| PDT-730 | ✓ | Δ Pressure: 11 psi |

### M. EFFLUENT DISCHARGE

| Item | Status | Comments |
|---|---|---|
| Effluent Surge Pump (P751 or P752 ) | ✓ | CV@ 55.9 % |
| Effluent Surge Tank (T-740) | ✓ | Level: 40 % |
| Effluent Discharge Rate (FT-770) | ✓ | 36.7 gpm @ 1052 |
| POTW Line Pressure (PT-770) | ✓ | 32.7 psi |
| Effluent Totalizer Reading (FT-770) | 241395984 gal | Time: 1057 |
| POTW MH17S-078 Discharge Check (Monthly) | ✓ | Last Done: 7-8-21 |
| 4X8-Inch POTW Leak Detection Checks (Monthly) | ✓ | Last Done: |
| 4X8-Inch POTW Air Reliefs Checks (Monthly) | ✓ | Last Done: |
| 4X8-Inch POTW Isolation Valves Exercise (Qtrly) | ✓ | Last Done: |
| 2-Inch POTW Backup Pressure Testing (Annual) | ✓ | Last Done: 7/8/21 |
| 2-In POTW Backup Air Reliefs Checks (Annual) | ✓ | Last Done: 7/8/21 |
| 2-Inch POTW Isolation Valve Exercise (Annual) | ✓ | Last Done: 7/8/21 |
| Rotate Chiller Compressors | NA on Standby | ~~Now in Lead: 1 or 2~~ |

### N. LEL EFFLUENT TANK T-740

| Item | Status | Comments |
|---|---|---|
| LEL-740 Sensor | ✓ | Reading: 0 % |
| LEL Sensor Calibration / Automatic High LEL Shutdown Test (monthly) | Last Completed: 7-29-21 | Plant Effluent Suspended: 1320 ↔ 1340 |
| LEL Sensor Bridge Adjustment to 2.0 volts | Reading: 2.001 volts(monthly) | Adjustment Needed: Y or (N) |
| Verify Bridge Current between.300v-.360v | Reading: 0.331 volts(monthly) | |

### O. WTP INFLUENT TOTALIZERS Time : 1058– 1103

| Source | Reading(Gallons) | Source | Reading(Gallons) |
|---|---|---|---|
| (FT-015) RWST Influent | 19573325 | (FT-505) LFG Cond. to T-530 | 215267 |
| (FT-025) NBBW Influent | 93203168 | (FT-056) Off - Site N. End Influent | 422128 29 |
| (FT-012) MW-38 Inf. to HMR-30 | 8058378 | (FT-113) Ion Exchange Influent | 417551 |
| (FT-042 HMR30) MW-38 Source to HMR-30 | 35484 | (FT-810) Plant Potable Water In | 30052504 |
| (FT-043) MW-38 to RWST | 30649 79 | (FT-026) NBBW Bypass to RWST | 4371356 |
| (FT-042 RWST) MW-38 Source to RWST | 72236 | (FT-014) Misc. Water to RWST | 8123338 |
| (FT-012T) MW-38 to T-540/541 | 8589238 | (FT-035) NTES Inf. to BIO | 6605443 |
| (FT-040T) MW-38N to T-540/541 | 1976607 | (FT-035T) NTES to T-530 | 458842 |
| (FT-041T) MW-38S to T-540/541 | 2694379 | (FT-017) BIO Inf. from T-530 | 648286 |
| (FT-042T) MW-38 Source to T-540/541 | 3990225 | (FT-018) T-540/541 Influent | 8631730 |
| (FT-055) On - Site N. End Influent | 96602655 | (FT-352) T-352 to HMR-30 | 1256129 |

# ABLE 3.19.1
# STANDARD OPERATIONS CHECKLIST
# MAIN WTP

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, August 05, 2021

**Inspection Performed by:** Mike Gelwick

### P. AIR COMPRESSORS

| Item | Status | Comments |
|---|---|---|
| Compressor Intake Temp. | °F (Analog Gauge) | Outside Temp.: ~ 82 °F |
| Compressor Building Vent | ✓ | open-operational |
| Primary Air Compressor (IRN30H) | 2,000 Hour service date: 7-8-21<br>Serviced @ 60952 Hours | Coolant present in sight glass: (Y) / N<br>Next service @ 62952 Hours<br>Current Hours @ 61327 |
| IRN30H Motor Speed | 31 % | |
| IRN30H Pressure | 119 psi | |
| IRN30H Moisture purge valve chk(Weekly): | ✓ | |
| IRN30H Intake Filter | ✓ | Date Last Changed: 7-8-21 |
| Air Tanks Moisture Purge Valves | Manually Activate(weekly) | Excessive Moisture: Y / (N) |
| Backup Air Compressors (T-30 East and West) | ✓ | Both cool to touch: (Y) / N |
| Air Dryer | ✓ | Moisture at Receiver Tank: Y / (N) |
| Oil Moisture Prevention (Monthly) | Last Done: 7-22-21 | Run at max speed by bleeding air from filter canister above/after air dryer for 2 hrs |
| Air Receiver Tank | ✓ | 110 psi |

### Q. SUMPS

| Item | Status | Comments |
|---|---|---|
| Bag Filter Sump | ✓ | |
| Wet Well Sump | ✓ | |

### R. GAS CHROMATOGRAPH

| Item | Status | Comments |
|---|---|---|
| GC Operational | ✓ | GC # checking UV-Ox Effluent: #2 |
| Alarms Enabled | ✓ | cc-calibration + maint 8-4-21 |
| GC Influent Filters | ✓ | |

### S. SAFETY

| Item | Status | Comments |
|---|---|---|
| Building #1 Fire Extinguishers | ✓ | Date inspected: 7-26-21 |
| Building #1 Eye Wash/Shower | ✓ | Checked and Flushed- All OK: (Y) / N |

**Other Comments:**

# TABLE 3.19.2
# STANDARD OPERATIONS CHECKLIST
# BIOLOGICAL TREATMENT SYSTEM

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, August 05, 2021

**Inspection Performed by:** Mike Gelwick

## A. PUMPS

| Item | Status | Flow Rate (gpm) | Pump Speed (CV%) | Discharge Pressure (psi) | | Comments |
|---|---|---|---|---|---|---|
| **T-510 Pumps** | | | | | | |
| P-3301 | ✓ | 2.32 | 32.5% | 6.5 | | |
| P-3301A | SB | – | – % | – | | |
| **NTES Pump** P-002(Sump) / (P-002W(10R)) | ✓ | 0.51 | 50 % | P035 3436 | P038 6.0 | Globules Observed at TP-130: Y / (N) Time: 1030 |
| **T-530** P-005 | ✓ | 0.20 | 37 % | 5.5 | | |
| **T-540/541** P-006 | SB | – | – % | – | | |
| **LFG COND Auto-Traps** | ✓ | 0.0 | NA | 5.0 | | Between Cycles: (Y) / N |
| **Reactor Feed Pumps** | | | | | | |
| P-3321 | ✓ | 2.58 | 42.9 % | 5.0 | | |
| P-3322 | ✓ | 3.61 | 41.4 % | 5.0 | | |
| P-3323 | ✓ | 2.64 | 56.3 % | 5.0 | | |
| P-3324 | SB | – | – % | – | | |
| **Reactor Effluent Pumps** | | | | | | |
| P-3341 | ✓ | 4.77 | 79.6 % | 22.0 | | |
| P-3341A | SB | – | – % | – | | |

## B. BLOWERS

| Item | Status | Pressure (psi) | Temp (°F) | Next Scheduled Service (Qtrly) | Comments Last serviced on: 6-22-21 |
|---|---|---|---|---|---|
| B-3331 | ✓ | 4.27 | 154 | 9-2021 | Greased, Belt and Filter Checked: (Y) / N |
| B-3332 | SB | – | – | ↓ | Belt and Filter Checked: Y / (N) |
| B-3333 | ✓ | 4.39 | 156 | ↓ | Greased, Belt and Filter Checked: (Y) / N |
| B-3334 | ✓ | 4.29 | 154 | ↓ | Greased, Belt and Filter Checked: (Y) / N |

## C. REACTOR VENTILATION

| Item | Status | Comments |
|---|---|---|
| Vapor Carbon Contactor | ✓ | On-line: 2/10/18 |
| Reactor Vent Blower | ✓ | |
| Reactor Vent Booster | ✓ | |
| VTP-3350 | ✓ | PID Reading: 2.6 PPM |
| VTP-3360 | ✓ | PID Reading: 1.6 PPM |

# TABLE 3.19.2
# STANDARD OPERATIONS CHECKLIST
# BIOLOGICAL TREATMENT SYSTEM

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, August 05, 2021

**Inspection Performed by:** Mike Gelwick

## D. TANKS / REACTORS / SUMPS / CONTAINMENTS / PIPING / Chiller

| Item | Status | Comments |
|---|---|---|
| T-510 Post HMR-30 Mixing Tank | ✓ Level: 71 % | Last Cleaning (As needed, if 2" of solids accumulate): ~~12/15/19~~ 7/14/21 |
| T-530 LFG Condensate / NTES Tank | ✓ Level: 27 % | |
| T-530 Mixer | ✓ | |
| LFG Condensate Conveyance Line | ✓ | Last Pressure Test: 7-19-21 Next: 7-2022 (Annual at a minimum or if flow drops off) |
| T-540/541 MW38 Tanks | Lvls: 82 % & 83% | |
| T-540/541 Mixers | ✓ | |
| Chiller | ✓ | Chiller Coolant Lvl: ~ 1.25 " Below full mark |
| Chiller Cooling Fins (as needed) | ✓ | Last Cleaning: 4/20/18 (unit on Standby) |
| Secondary Containments | ✓ | Heat Trace: On OK / (Off Warm out) |
| Feed Piping to Sedimentation Tank | ✓ | Last Back Flushing (Quarterly): 8-4-21 |
| T-3310 Sedimentation Tank | Visual Level: ok | Last Cleaning (As Needed, use TSS info to determine): 12/2017 |
| T-3320 Blend Tank | ✓ Level: 71 % | Last Cleaning (Semi Annual): 5-7-20 |
| T-3331 Reactor No. 1 | ✓ | Digital Displays: (GOOD) / Needs Attn |
| T-3332 Reactor No. 2 | ✓ | Digital Displays: (GOOD) / Needs Attn |
| T-3333 Reactor No. 3 | ✓ | Digital Displays: (GOOD) / Needs Attn |
| T-3334 Settling Tank | ✓ | Last Cleaning (Semi Annual): 5-7-20 |
| P-3334 Biosolids Pump | ✓ | |
| T-3340 Overflow Tank | ✓ Level: 30 % | |
| Recycle Valve to Blend Tank | — | 4.0 gpm @ 1152 |
| Building Containment Sump | ✓ | Last Alarm Test Date (Monthly): 7-22-21 |

## E. CHEMICAL FEED SYSTEM

| Item | Status | Comments |
|---|---|---|
| Phosphorous Supply | ✓ | Bags: 18,9 Gallons: ~80 |
| Phosphorous Pump (P-2221) | ✓ | |
| Caustic Supply | ✓ | ~230 Gallons |
| Caustic Pump (P-2211) | SB | Currently in acid addition mode |
| Acid Supply | ✓ | ~ 40 Gallons |
| Acid Pump (P-2211) | ✓ | |
| Caustic Pump (P-2231) | ✓ Leaks: Y / (N) | Last tubing tip cleaning (monthly): 7-22-21 |
| Caustic Pump (P-2232) | ✓ Leaks: Y / (N) | Last tubing tip cleaning (monthly): ↓ |
| Caustic Pump (P-2233) | ✓ Leaks: Y / (N) | Last tubing tip cleaning (monthly): ✓ |

# TABLE 3.19.2
# STANDARD OPERATIONS CHECKLIST
# BIOLOGICAL TREATMENT SYSTEM

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, August 05, 2021

**Inspection Performed by:** Mike Gelwick

### F. pH Probes

| pH Probe Location | Calibration Date (Monthly) | Comments |
|---|---|---|
| pH-3320 Blend Tank | 7-29-21 | Spray off clean today |
| pH-3331 Reactor 1 | ↓ | ↓ |
| pH-3332 Reactor 2 | | |
| pH-3333 Reactor 3 | | |

### G. FILTER SYSTEM

| Item | Status | Comments |
|---|---|---|
| BF-3340 a/b Status | ✓ | |
| Automatic Backwash | Cycle Count: 51 | Reset |
| BF-3340 a/b Differential Pressure | PSI: 2 | 21/19 @ 4.0gpm |
| 75-micron Bags Last Cleaning | Date: 11-14-19 | |
| 75-micron Bags Last Inspection | Date: ↓ | |
| 75-micron Bags Last Changed | Date: | |
| GACF-3340 Status | ✓ | |
| GACF-3340 Differential Pressure | PSI: 12 | 19/7 24.0gpm |
| Last Backwash Performed | Date: 7-14-21 | |

### H. ELECTRICAL AND INSTRUMENTATION

| Item | Status | Comments |
|---|---|---|
| "BIO" Backup Generator | ✓ | Block Heater: On OK / (Off Warm Out) |
| Electrical Surge Suppressor | ✓ | |
| Motor Control Center | ✓ | |
| PLC | ✓ | UPS @ 97 min / 73 Events |
| HMI's | ✓ | |
| BTS Process KWH Meter | 1705434 KWH | Time: 1230 |
| Building#2 KWH Meter | 5204767 KWH | Time: 1230 |

### I. GAS CHROMATOGRAPHY

| Item | Status | Comments |
|---|---|---|
| GC Operational | ✓ | GC # checking BIO: #3 |
| Alarms Enabled | ✓ | cc- Calibration + maint 8.4.21 |
| GC Influent Filters | ✓ | |

# TABLE 3.19.2
# STANDARD OPERATIONS CHECKLIST
# BIOLOGICAL TREATMENT SYSTEM

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, August 05, 2021

**Inspection Performed by:** Mike Gelwick

## J. TOTALIZERS

| Item | Readings (gallons) | Comments |
|---|---|---|
| FT-3321 Feed to Reactor 1 | 5775325 | |
| FT-3324 Feed Spare | 59886 | |
| FT-3322 Feed to Reactor 2 | 10391273 | |
| FT-3323 Feed to Reactor 3 | 466149 | |
| FT-3301 T-510 to BIO | 57263538 | |
| FT-3341 BIO Effluent | 65983578 | |
| FT-3342 BIO Recycle | 55046290 | |

## K. SAFETY

| Item | Status | Comments |
|---|---|---|
| Building #2 Fire Extinguishers | ✓ | Inspection date: 7-26-21 |
| Building #2 Eye Wash/Shower | ✓ | Checked and Flushed- All OK: (Y) / N |

## L. OTHER COMMENTS:

| |
|---|
| |
| |
| |
| |

# TABLE 3.19.1
# STANDARD OPERATIONS CHECKLIST
# MAIN WTP

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, August 12, 2021

**Inspection Performed by:** Chris Carlson

### A. PERIMETER COLLECTION SYSTEMS

| Item | Status | Comments |
|---|---|---|
| LFG Cond Automatic Trap CT-1 | Sump Level: 13.46 oz | Counter: 178665 Cycles: 144 |
| LFG Cond Automatic Trap CT-2 | Sump Level: 8.65 oz | Counter: 273891 Cycles: 25 |
| LFG Cond Automatic Trap CT-3 | Sump Level: 7.23 oz | Counter: 301220 Cycles: 645 |
| CT-4 Containment/Vessel (LFG Cond) | ✓ Level: 71 % | Tank Level 2.16 Counter: 191176 Cycles: 1 Sump: 8.90 oz |
| PM-15 Containment / Vessel | ✓ Level: 35 % | |
| MW-51 Containment / Vessel | ✓ Level: 65 % | |
| PM-11 Containment / Vessel | ✓ Level: 75 % | |
| MW-38 Systems | ✓ | |
| North Toe System | ✓ | |
| North End Systems (Weekly) | ✓ | |
| Full N. End Systems Check (Monthly) | ✓ | Last Done: 7-26-21 |
| North End Pipeline(s)Flushing (As Needed) | ✓ | Perform if suspended solids present Last Done: 11/15/15 |
| NTES line flush to T-530 (As needed) | ✓ | Perform if suspended solids present Last Done: 2/13/20 |
| NTES Piping Containment | ✓ | Monthly Sump Level: Dry @ 6.07' Date: 7/22/21 |
| North Boundary System P-001: | CV 75.5% @ 7.4 gpm | 42.16 Hz / 2.11 Amps. / vault psi @ 18/no leaks |
| T-101 & T-102 Containment / Tank | ✓ | Levels: 32 % & 31 % |
| Raw Water Storage Tanks Piping | ✓ | |
| RWST Building Temp. (TT-101) | 73.4 °F | Outside Temp.: ~ 80 °F |
| P-121 or P-122 | ✓ | 0.6 gpm / CV 57 % |
| RWST 2ndry Cont. High Level Switch | ✓ | (LSH-101) Last Test(monthly): 7/22/21 |
| RWST Back-Up Generator | ✓ | Last Test Run(monthly): 7/22/21 |

### B. CHEMICAL STORAGE BAYS

| Item | Status | Comments |
|---|---|---|
| Caustic Tote Levels | ✓ | ~ 540 Gallons Reserve = 2 Totes |
| Caustic Bay Heater | ✓ | SB - Warm out |
| Peroxide Tote Level | ✓ | ~ 125 Gallons Reserve = ~ 55 gal |
| HCL Tote Levels | ✓ | ~ 220 Gallons Reserve = ~ 95 gal |
| Chemical Totes and Piping Inspected | ✓ | Leaks observed: Y / (N) |
| Emergency Shower Inspected | ✓ | Checked and Flushed - All OK: (Y) / N |

### C. PRIMARY AND SECONDARY ACID FEED SYSTEM

| Item | Status | Comments |
|---|---|---|
| Primary Acid Feed Pump (P-631) | ✓ | |
| Ion Exchange Acid Feed Pump (P-632) | ✓ | PI-0632 PSI: 70 |
| Primary Acid Retention Tank (T-510) | ✓ | |
| All Acid Feed Lines | ✓ | Leaks observed: Y / (N) |

### D. NBBW INJECTION TRENCH

| Item | Status | Comments |
|---|---|---|
| Injection Carbon (GAC-810) | **OFFLINE** | Date online: 7/20/18 |
| Injection Rate (FT-800) | 0.0 gpm | NBBW-IW-1= 0.0 NBBW-IW-2= 0.0 NBBW-IW-3= 0.0 gpm ea. |
| Totalizer Reading (FT-800) | 105,135,774 gal | INJ. STOPPED 10/02/18 @ 1545 |

# TABLE 3.19.1
# STANDARD OPERATIONS CHECKLIST
# MAIN WTP

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, August 12, 2021

**Inspection Performed by:** Chris Carlson

### E. CHEMICAL PRECIPITATION SYSTEM (US FILTER HMR-30)

| Item | Status | Comment |
|---|---|---|
| T-300A Mixer | NA | |
| T-300B (Caustic Mixer) | ✓ | Last Cleaning (Qtrly): 6/3/21 |
| T-300A/B Water Level | ✓ | |
| T-300B (Caustic Mix Chamber) | ✓ | Last Cleaning (Qtrly): 6/3/21 |
| T-300A/B Overflow | ✓ | |
| pH Set-point for (pH 315) | Value: 10.8 | |
| pH 310 | Value: 6.99 | |
| pH 315 | Value: 10.84 | |
| Flocculation Chamber Paddle Wheel | ✓ | |
| Precipitate Floc Quality | ✓ | okay |
| Clarifier Water Quality | ✓ | okay Oil or sheen observed: Y / (N) |
| Clarifier Effluent Piping / Water Level | ✓ | |
| Clear-well Chamber and Water Level | ✓ | |
| HMR PLC Panel | ✓ | |
| Caustic Pump (P-270) | SB | |
| Caustic Pump (P-280) | ✓ | |
| Polymer Pump (P-310) | ✓ | |
| Polymer Tank Mixer | ✓ | |
| Polymer Tank Level | Gallons: ~ 450 | |
| Clear-well Transfer Pumps(P-371 (372) | ✓ | |
| Sludge Transfer Pump (P-330) | ✓ | Exercise Valves Weekly: Bothgoal-Top ff Valves to Out. |
| Manual Sludge Lateral pumping | ✓ | Last done (As Needed): #3 7/20/21 #1 3/20/20 |
| Manual Sludge Lateral Ball Valves | ✓ | Exercise Weekly: All good. |
| Automatic Blow-down Operations | ✓ | |

### F. pH PROBES

| pH Probe Location | Calibration Date | Comments: (Time done) |
|---|---|---|
| pH-310 HMR-30 (T-300A) | 8/12/21 | 1153 |
| pH-315 HMR-30 (T-300B) | ↓ | |
| pH-365 Primary Acid Ret. Tank | | |
| pH-113 Pre-Ion Exchange | | |
| pH-670 Pre-UV-OX | | 1218 |
| pH-740 Discharge Surge Tank | ✓ | Discharge suspended: 1146 ↔ 1157 |
| Out of Hold Double Check | ---------- | None in hold: vv'd (M) |
| Valves Back to Normal Position | ---------- | All OK: vv'd (M) |

### G. SLUDGE THICKENER, SLUDGE HOLDING TANKS, FILTER PRESS

| Item | Status | Comments |
|---|---|---|
| Verify Sludge Thickener Running | ✓ | Gauge Reading: 0 % |
| Sludge Thick. Transfer Pump (P-350) | ✓ | |
| Sludge Holding Tank (T-351) | ✓ | Level:~ 70 % |
| Sludge Holding Tank (T-352) | ✓ | Level: 30 % |
| Decant Transfer Pump (P-352) | SB | CV — % @— gpm |
| Filter Press Pumps (P-381 / P-382) | ✓ | |
| Filter Press | ✓ | Stage: Full |

# TABLE 3.19.1
# STANDARD OPERATIONS CHECKLIST
# MAIN WTP

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, August 12, 2021

**Inspection Performed by:** Chris Carlson

### H. ION EXCHANGE

| Item | Status | Comments |
|---|---|---|
| Feed Tank (T-113) | ✓ Level: 60 % | |
| Feed Pump (P-114) | Operating Press: 60.9 psi | CV@ 97 % @ 2.0 gpm |
| Retention Tank (T-114) | Operating Press: 60 psi | pH-113 @ 3.70 |
| Bag Filter (BF-113) | Operating Press: 63 psi | |
| Ion Exchange (Cage 1 or 2) + Guard | Operating Press: 60 psi | |
| Post Ion Exchange | Operating Press: 3.5 psi | |

### I. FEED SURGE TANK

| Item | Status | Comments |
|---|---|---|
| Feed Surge Tank (T-520) | ✓ Level: 38 % | Last Cleaning (As Needed, if 4" of solids accumulate): 12/15/19 |
| Feed Surge Pump (P-521 or P-522) | Operating Press: 33 psi | CV@ 75 % @ 34.7 gpm |
| T-520 to GAC Total (FT-675) | 247673120 gal | Time: 0612 |
| North End On-Site Pumping | Operating Press: 2-3 psi | 13.0 gpm @ 0631 |
| North End Off-Site Pumping | Operating Press: 2-8 psi | 8.4 gpm @ 0631 |
| Peroxide Feed Pump (P-680) | ✓ | SPD 2.6 % / RATE 0.7 |
| Peroxide Conc. At (TP-710) | 1 PPM | |
| Peroxide Conc. At (TP-740) | 0 PPM | |

### J. HAZARDOUS WASTE STORAGE

| Item | Status | Comments |
|---|---|---|
| 180 Day storage area check | ✓ | Check sheet completed: NA Empty |
| Satellite Haz. Waste Areas (BLDG #1) | ✓ | Condition: Good |
| Satellite Haz. Waste Area (BLDG #2) | ✓ | Condition: Good |

### K. UV-OXIDATION SYSTEM

| Item | Status | Comments |
|---|---|---|
| UV-Oxidation System | ✓ | |
| Annual Test Run (Calgon) | Date: 8/4/20 | Next: 9/2021 |
| Quarterly Test Run | Date: NA Running | Next: NA Running |
| Peroxide Feed Pump (P-650) | ✓ | Flow Rate: ~~2418~~ 2417 cc/min. |
| UV-Ox Power | ✓ | 25.7 kVA ~~2280~~ Volts 9.9 Amps |
| Lamp Hours | 322 Hrs | |
| Crystal Condition & Wiper Status | ✓ | Oiler status: okay |
| UV-OX Bagfilters Status | Last change: 7/8/21 Cleaned: 7/13/21 | 11.575 psi In 12 psi Out |
| UV-OX Feed Pump ( P-600 or P-601) | ✓ | CV@ 75 % @ 8 gpm |
| UV-OX Temperature | In(TT-670): 16.3 °C | Out(TT-710): 27.8 °C |
| PDU GAC (PDT-710) | ✓ | Δ Pressure: 4 psi |
| Peroxide Concentration Pre UV | 100 PPM | |
| Peroxide Concentration Post UV(TP-720) | 25 PPM | |
| Peroxide Conc. Post PDU (TP-730) | 0 PPM | |
| Secondary Acid Feed Pump (P-630) | ✓ | CV @ 1 % |
| Secondary Acid Retention Tank (T-645) | ✓ | |
| Pre – UV Oxidizer Total (FT-670) | 192945558 gal | Time: 0615 |
| Post UV-Ox / Pre PDU | ✓ | Pressure: 14 psi |
| Post PDU | ✓ | Pressure: 9.5 psi |

# TABLE 3.19.1
# STANDARD OPERATIONS CHECKLIST
# MAIN WTP

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, August 12, 2021

**Inspection Performed by:** Chris Carlson

### L. PDU AND LIQUID –PHASE GRANULAR ACTIVATED CARBON

| Item | Status | Comments |
|---|---|---|
| PDT-720 | ✓ | Δ Pressure: 17 psi |
| PDT-730 | ✓ | Δ Pressure: 11 psi |

### M. EFFLUENT DISCHARGE

| Item | Status | Comments |
|---|---|---|
| Effluent Surge Pump ( P751 or P752 ) | ✓ | CV@ 54.9 % |
| Effluent Surge Tank (T-740) | ✓ | Level: 40 % |
| Effluent Discharge Rate (FT-770) | ✓ | 34.7 gpm @ 0616 |
| POTW Line Pressure (PT-770) | ✓ | 32.4 psi |
| Effluent Totalizer Reading (FT-770) | 241741236 gal | Time: 0616 |
| POTW MH17S-078 Discharge Check (Monthly) | ✓ | Last Done: 7/8/21 |
| 4X8-Inch POTW Leak Detection Checks (Monthly) | ✓ | Last Done: |
| 4X8-Inch POTW Air Reliefs Checks (Monthly) | ✓ | Last Done: |
| 4X8-Inch POTW Isolation Valves Exercise (Qtrly) | ✓ | Last Done: |
| 2-Inch POTW Backup Pressure Testing (Annual) | ✓ | Last Done: ~~5/19/20~~ 7/8/21 (N) |
| 2-In POTW Backup Air Reliefs Checks (Annual) | ✓ | Last Done: ~~5/19/20~~ 7/8/21 |
| 2-Inch POTW Isolation Valve Exercise (Annual) | ✓ | Last Done: ~~5/19/20~~ 7/8/21 |
| Rotate Chiller Compressors | NA on Standby | ~~Now in Lead: 1 or 2~~ |

### N. LEL EFFLUENT TANK T-740

| Item | Status | Comments |
|---|---|---|
| LEL-740 Sensor | ✓ | Reading: 1 % |
| LEL Sensor Calibration / Automatic High LEL Shutdown Test (monthly) | Last Completed: 7/29/21 | Plant Effluent Suspended: 1320 ↔ 1340 |
| LEL Sensor Bridge Adjustment to 2.0 volts | Reading: 2.001 volts(monthly) | Adjustment Needed: Y or (N) |
| Verify Bridge Current between.300v-.360v | Reading: 0.331 volts(monthly) | |

### O. WTP INFLUENT TOTALIZERS Time : 0826 – 0831

| Source | Reading(Gallons) | Source | Reading(Gallons) |
|---|---|---|---|
| (FT-015) RWST Influent | 19581969 | (FT-505) LFG Cond. to T-530 | 2153141 |
| (FT-025) NBBW Influent | 43276974 | (FT-113) Ion Exchange Influent | 4377998 |
| (FT-012) MW-38 Inf. to HMR-30 | 8077540 | (FT-056) Off - Site N. End Influent | 42294872 |
| (FT-042 HMR30) MW-38 Source to HMR-30 | 354484 | (FT-810) Plant Potable Water In | 30052972 |
| (FT-043) MW-38 to RWST | 3067108 | (FT-026) NBBW Bypass to RWST | 4372648 |
| (FT-042 RWST) MW-38 Source to RWST | 72236 | (FT-014) Misc. Water to RWST | 8123338 |
| (FT-012T) MW-38 to T-540/541 | 8590044 | (FT-035) NTES Inf. to BIO | 6610359 |
| (FT-040T) MW-38N to T-540/541 | 1976891 | (FT-035T) NTES to T-530 | 458472 |
| (FT-041T) MW-38S to T-540/541 | 2694735 | (FT-017) BIO Inf. from T-530 | 648793 |
| (FT-042T) MW-38 Source to T-540/541 | 3990399 | (FT-018) T-540/541 Influent | 8633655 |
| (FT-055) On - Site N. End Influent | 96733259 | (FT-352) T-352 to HMR-30 | 1259186 |

# TABLE 3.19.1
# STANDARD OPERATIONS CHECKLIST
# MAIN WTP

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, August 12, 2021

**Inspection Performed by:** Chris Carlson

### P. AIR COMPRESSORS

| Item | Status | Comments |
|---|---|---|
| Compressor Intake Temp. | 65 °F (Analog Gauge) | Outside Temp.: ~ 80 °F |
| Compressor Building Vent | ✓ | |
| Primary Air Compressor (IRN30H) | 2,000 Hour service date: 7/8/21 Serviced @ 60952 Hours | Coolant present in sight glass: (Y) / N Next service @ 62952 Hours Current Hours @ 61415 |
| IRN30H Motor Speed | 31 % | |
| IRN30H Pressure | 118 psi ✓ | |
| IRN30H Moisture purge valve chk(Weekly): | ✓ | Motor cooling fan good. |
| IRN30H Intake Filter | ✓ | Date Last Changed: ~~7/9/21~~ 8/12/21 |
| Air Tanks Moisture Purge Valves | Manually Activate(weekly) | Excessive Moisture: Y / (N) |
| Backup Air Compressors (T-30 East and West) | ✓ | Both cool to touch: (Y) / N |
| Air Dryer | ✓ ECO ON | Moisture at Receiver Tank: Y (N) |
| Oil Moisture Prevention (Monthly) | Last Done: 7/22/21 | Run at max speed by bleeding air from filter canister above/after air dryer for 2 hrs |
| Air Receiver Tank | ✓ | 111 psi |

### Q. SUMPS

| Item | Status | Comments |
|---|---|---|
| Bag Filter Sump | ✓ | |
| Wet Well Sump | ✓ | |

### R. GAS CHROMATOGRAPH

| Item | Status | Comments |
|---|---|---|
| GC Operational | ✓ | GC # checking UV-Ox Effluent: 2 |
| Alarms Enabled | ✓ | |
| GC Influent Filters | ✓ | |

### S. SAFETY

| Item | Status | Comments |
|---|---|---|
| Building #1 Fire Extinguishers | ✓ | Date inspected: 7/26/21 |
| Building #1 Eye Wash/Shower | ✓ | Checked and Flushed- All OK: Y / N |

**Other Comments:**

# TABLE 3.19.2
# STANDARD OPERATIONS CHECKLIST
# BIOLOGICAL TREATMENT SYSTEM

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, August 12, 2021

**Inspection Performed by:** Chris Carlson

## A. PUMPS

| Item | Status | Flow Rate (gpm) | Pump Speed (CV%) | Discharge Pressure (psi) | | Comments |
|---|---|---|---|---|---|---|
| **T-510 Pumps** | | | | | | |
| P-3301 | ✓ | 1.82 | 31.9 % | 6.5 | | |
| P-3301A | SB | – | – % | – | | |
| **NTES Pump** P-002(Sump) (P-002W(10F)) | ✓ | 0.50 | 50 % | P035 34-36 | P038 7 | Globules Observed at TP-130: Y / (N) Time: 0650 |
| **T-530** P-005 | ✓ | 0.2 | 37 % | 5.5 | | |
| **T-540/541** P-006 | ✓ | 0.3 | 50 % | 3.75 | | |
| **LFG COND Auto-Traps** | ✓ | 0.0 | NA | 5 | | Between Cycles: (Y) / N |
| **Reactor Feed Pumps** | | | | | | |
| P-3321 | SB | – | – % | – | | |
| P-3322 | ✓ | 2.20 | 43.9 % | 6.0 | | |
| P-3323 | ✓ | 1.27 | 58.1% | 7.0 | | |
| P-3324 | ✓ | 1.26 | 32.8% | 7.0 | | |
| **Reactor Effluent Pumps** | | | | | | |
| P-3341 | ✓ | 1.80 | 57.5% | 30.0 | | |
| P-3341A | SB | – | –% | – | | |

## B. BLOWERS

| Item | Status | Pressure (psi) | Temp (°F) | Next Scheduled Service (Qtrly) | Comments Last serviced on: 6/22/21 |
|---|---|---|---|---|---|
| B-3331 | ✓ | 4.22 | 160 | 9/2021 | Greased, Belt and Filter Checked: (Y) / N |
| B-3332 | SB | – | – | – | Belt and Filter Checked: Y / (N) |
| B-3333 | ✓ | 4.37 | 160 | ✓ | Greased, Belt and Filter Checked: (Y) / N |
| B-3334 | ✓ | 4.29 | 150 | ✓ | Greased, Belt and Filter Checked: (Y) / N |

## C. REACTOR VENTILATION

| Item | Status | Comments |
|---|---|---|
| Vapor Carbon Contactor | ✓ | On-line: 2/10/18 |
| Reactor Vent Blower | ✓ | |
| Reactor Vent Booster | ✓ | |
| VTP-3350 | ✓ | PID Reading: 6.5 PPM |
| VTP-3360 | ✓ | PID Reading: 4.8 PPM |

# TABLE 3.19.2
# STANDARD OPERATIONS CHECKLIST
# BIOLOGICAL TREATMENT SYSTEM

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, August 12, 2021

**Inspection Performed by:** Chris Carlson

## D. TANKS / REACTORS / SUMPS / CONTAINMENTS / PIPING / Chiller

| Item | Status | Comments |
|---|---|---|
| T-510 Post HMR-30 Mixing Tank | ✓ Level: 68 % | Last Cleaning (As needed, if 2" of solids accumulate) ~~12/15/19~~ 7/14/21 |
| T-530 LFG Condensate / NTES Tank | ✓ Level: 22 % | |
| T-530 Mixer | ✓ | |
| LFG Condensate Conveyance Line | ✓ | Last Pressure Test: 7/19/21 Next: 7/2022 (Annual at a minimum or if flow drops off) |
| T-540/541 MW38 Tanks | ✓ Lvls: 71 % & 72% | |
| T-540/541 Mixers | ✓ | |
| Chiller | ✓ | Chiller Coolant Lvl: ~ 1.25" Below full mark |
| Chiller Cooling Fins (as needed) | ✓ | Last Cleaning: 4/20/18 (unit on Standby) |
| Secondary Containments | ✓ | Heat Trace: On OK / (Off Warm out) |
| Feed Piping to Sedimentation Tank | ✓ | Last Back Flushing (Quarterly): 8/4/21 |
| T-3310 Sedimentation Tank | Visual Level: OK | Last Cleaning (As Needed, use TSS info to determine): 12/2017 (Needs cleaning) |
| T-3320 Blend Tank | ✓ Level: 72% | Last Cleaning (Semi Annual): 5/7/20 |
| T-3331 Reactor No. 1 | ✓ | Digital Displays: (GOOD) / Needs Attn |
| T-3332 Reactor No. 2 | ✓ | Digital Displays: (GOOD) / Needs Attn |
| T-3333 Reactor No. 3 | ✓ | Digital Displays: (GOOD) / Needs Attn |
| T-3334 Settling Tank | ✓ | Last Cleaning (Semi Annual): 5/7/20 |
| P-3334 Biosolids Pump | ✓ | |
| T-3340 Overflow Tank | ✓ Level: 31 % | |
| Recycle Valve to Blend Tank | ✓ | 4.02 gpm @ 0944 |
| Building Containment Sump | ✓ | Last Alarm Test Date (Monthly): 7/22/21 |

## E. CHEMICAL FEED SYSTEM

| Item | Status | Comments |
|---|---|---|
| Phosphorous Supply | ✓ | Bags: 18.5 Gallons: ~70 |
| Phosphorous Pump (P-2221) | ✓ | |
| Caustic Supply | ✓ | ~ 220 Gallons |
| Caustic Pump (P-2211) | SB | Currently in acid addition mode |
| Acid Supply | ✓ | ~ 40 Gallons |
| Acid Pump (P-2211) | ✓ | |
| Caustic Pump (P-2231) | ✓ Leaks: Y / (N) | Last tubing tip cleaning (monthly): 7/22/21 |
| Caustic Pump (P-2232) | ✓ Leaks: Y / (N) | Last tubing tip cleaning (monthly): ↓ |
| Caustic Pump (P-2233) | ✓ Leaks: Y / (N) | Last tubing tip cleaning (monthly): ↓ |

# TABLE 3.19.2
# STANDARD OPERATIONS CHECKLIST
# BIOLOGICAL TREATMENT SYSTEM

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, August 12, 2021

**Inspection Performed by:** Chris Carlson

## F. pH Probes

| pH Probe Location | Calibration Date (Monthly) | Comments |
|---|---|---|
| pH-3320 Blend Tank | 7/29/21 | Sprayed off clean today |
| pH-3331 Reactor 1 | ↓ | ↓ |
| pH-3332 Reactor 2 | | |
| pH-3333 Reactor 3 | | |

## G. FILTER SYSTEM

| Item | Status | Comments |
|---|---|---|
| BF-3340 a/b Status | ✓ | |
| Automatic Backwash | Cycle Count: 31 | Reset |
| BF-3340 a/b Differential Pressure | PSI: 62 | 36/24 |
| 75-micron Bags Last Cleaning | Date: 11/14/19 | |
| 75-micron Bags Last Inspection | Date: ↓ | |
| 75-micron Bags Last Changed | Date: | |
| GACF-3340 Status | ✓ | |
| GACF-3340 Differential Pressure | PSI: 13 | 24/7 |
| Last Backwash Performed | Date: 7/14/21 | |

## H. ELECTRICAL AND INSTRUMENTATION

| Item | Status | Comments |
|---|---|---|
| "BIO" Backup Generator | ✓ | Block Heater: On OK / Off Warm Out |
| Electrical Surge Suppressor | ✓ | |
| Motor Control Center | ✓ | |
| PLC | ✓ | UPS @ 97 min / 73 Events |
| HMI's | ✓ | |
| BTS Process KWH Meter | 1797333 KWH | Time: 0434 |
| Building#2 KWH Meter | 5207527 KWH | Time: 0434 |

## I. GAS CHROMATOGRAPHY

| Item | Status | Comments |
|---|---|---|
| GC Operational | ✓ | GC # checking BIO: 3 |
| Alarms Enabled | ✓ | |
| GC Influent Filters | ✓ | |

# TABLE 3.19.2
# STANDARD OPERATIONS CHECKLIST
# BIOLOGICAL TREATMENT SYSTEM

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, August 12, 2021

**Inspection Performed by:** Chris Carlson

## J. TOTALIZERS

| Item | Readings (gallons) | Comments |
|---|---|---|
| FT-3321 Feed to Reactor 1 | 5798182 | |
| FT-3324 Feed Spare | 60135 | |
| FT-3322 Feed to Reactor 2 | 10423363 | |
| FT-3323 Feed to Reactor 3 | 488927 | |
| FT-3301 T-510 to BIO | 51289735 | |
| FT-3341 BIO Effluent | 66017438 | |
| FT-3342 BIO Recycle | 55087220 | |

## K. SAFETY

| Item | Status | Comments |
|---|---|---|
| Building #2 Fire Extinguishers | ✓ | Inspection date: 7/26/21 |
| Building #2 Eye Wash/Shower | ✓ | Checked and Flushed- All OK: (Y) / N |

## L. OTHER COMMENTS:

| |
|---|
| |
| |
| |

# ABLE 3.19.1
# STANDARD OPERATIONS CHECKLIST
# MAIN WTP

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, August 19, 2021

**Inspection Performed by:** Mike Gelwick

### A. PERIMETER COLLECTION SYSTEMS

| Item | Status | Comments |
|---|---|---|
| LFG Cond Automatic Trap CT-1 | Sump Level: 13.85 oz | Counter: 179950 Cycles: 1285 |
| LFG Cond Automatic Trap CT-2 | Sump Level: 8.66 oz | Counter: 273917 Cycles: 26 |
| LFG Cond Automatic Trap CT-3 | Sump Level: 7.65 oz | Counter: 302961 Cycles: 1241 |
| CT-4 Containment/Vessel (LFG Cond) | ✓ Level: 70 % | Tank Level: 2.16 Counter: 191182 Cycles: 6 Sump: 9.22 oz |
| PM-15 Containment / Vessel | ✓ Level: 37 % | |
| MW-51 Containment / Vessel | ✓ Level: 20 % | |
| PM-11 Containment / Vessel | ✓ Level: 20 % | |
| MW-38 Systems | ✓ | |
| North Toe System | ✓ | |
| North End Systems (Weekly) | ✓ | |
| Full N. End Systems Check (Monthly) | ✓ | Last Done: 7-26-21 |
| North End Pipeline(s)Flushing (As Needed) | ✓ | Perform if suspended solids present Last Done: 11/15/15 |
| NTES line flush to T-530 (As needed) | ✓ | Perform if suspended solids present Last Done: 2/13/20 |
| NTES Piping Containment | ✓ | Monthly Sump Level: Sump 16.07' Date: 8-19-21 - today |
| North Boundary System P-001: | CV 75.6 % @ 7.5 gpm | 42.13 Hz / 2.12 Amps. / vault psi @ 18 / 20 leaves |
| T-101 & T-102 Containment / Tank | ✓ | Levels: 46 % & 45 % |
| Raw Water Storage Tanks Piping | ✓ | |
| RWST Building Temp. (TT-101) | 74.4 °F | Outside Temp.: ~ 67 °F |
| (P-121) or P-122 | ✓ | 0.6 gpm / CV 45 % |
| RWST 2ndry Cont. High Level Switch | ✓ | (LSH-101) Last Test(monthly): 8-19-21 - today |
| RWST Back-Up Generator | ✓ | Last Test Run(monthly): 8-19-21 - today |

### B. CHEMICAL STORAGE BAYS

| Item | Status | Comments |
|---|---|---|
| Caustic Tote Levels | ✓ | ~ 345 Gallons Reserve = 2 totes |
| Caustic Bay Heater | ✓ | SB-warmout |
| Peroxide Tote Level | ✓ | ~ 100 Gallons Reserve = ~55 gal |
| HCL Tote Levels | ✓ | ~ 180 Gallons Reserve = ~95 gal |
| Chemical Totes and Piping Inspected | ✓ | Leaks observed: Y / (N) |
| Emergency Shower Inspected | ✓ | Checked and Flushed - All OK: (Y) / N |

### C. PRIMARY AND SECONDARY ACID FEED SYSTEM

| Item | Status | Comments |
|---|---|---|
| Primary Acid Feed Pump (P-631) | ✓ | |
| Ion Exchange Acid Feed Pump (P-632) | ✓ | PI-0632 PSI: 78 CV: 8 % |
| Primary Acid Retention Tank (T-510) | ✓ | |
| All Acid Feed Lines | ✓ | Leaks observed: Y / (N) |

### D. NBBW INJECTION TRENCH

| Item | Status | Comments |
|---|---|---|
| Injection Carbon (GAC-810) | OFFLINE | Date online: 7/20/18 |
| Injection Rate (FT-800) | 0.0 gpm | NBBW-IW-1= 0.0 NBBW-IW-2= 0.0 NBBW-IW-3= 0.0 gpm ea. |
| Totalizer Reading (FT-800) | 105,135,774 gal | INJ. STOPPED 10/02/18 @ 1545 |

# ABLE 3.19.1
# STANDARD OPERATIONS CHECKLIST
# MAIN WTP

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, August 19, 2021

**Inspection Performed by:** Mike Gelwick

### E. CHEMICAL PRECIPITATION SYSTEM (US FILTER HMR-30)

| Item | Status | Comment |
|---|---|---|
| T-300A Mixer | NA | |
| T-300B (Caustic Mixer) | ✓ | Last Cleaning (Qtrly): 6-3-21 |
| T-300A/B Water Level | ✓ | |
| T-300B (Caustic Mix Chamber) | ✓ | Last Cleaning (Qtrly): 6-3-21 |
| T-300A/B Overflow | ✓ | |
| pH Set-point for (pH 315) | Value: 10.8 | |
| pH 310 | Value: 6.95 | |
| pH 315 | Value: 10.73 | |
| Flocculation Chamber Paddle Wheel | ✓ | |
| Precipitate Floc Quality | ✓ | Good |
| Clarifier Water Quality | ✓ | good Oil or sheen observed: Y / (N) |
| Clarifier Effluent Piping / Water Level | ✓ | |
| Clear-well Chamber and Water Level | ✓ | |
| HMR PLC Panel | ✓ | |
| Caustic Pump (P-270) | SB | |
| Caustic Pump (P-280) | ✓ | |
| Polymer Pump (P-310) | ✓ | |
| Polymer Tank Mixer | ✓ | |
| Polymer Tank Level | Gallons: ~ 375 | |
| Clear-well Transfer Pumps(P-371 / (372)) | ✓ | |
| Sludge Transfer Pump (P-330) | ✓ | Exercise Valves Weekly: 6 of 104 |
| Manual Sludge Lateral pumping | ✓ | Last done (As Needed): #3- 7-20-21 / 1+2 3-20-20 |
| Manual Sludge Lateral Ball Valves | ✓ | Exercise Weekly: All 104 |
| Automatic Blow-down Operations | ✓ | |

### F. pH PROBES

| pH Probe Location | Calibration Date | Comments: (Time done) |
|---|---|---|
| pH-310 HMR-30 (T-300A) | 8-19-21- today | 1322 |
| pH-315 HMR-30 (T-300B) | | |
| pH-365 Primary Acid Ret. Tank | | |
| pH-113 Pre-Ion Exchange | | |
| pH-670 Pre-UV-OX | | 1355 |
| pH-740 Discharge Surge Tank | | Discharge suspended: 1315 ↔ 1321 |
| Out of Hold Double Check | ---------- | None in hold: ✓ 1st m |
| Valves Back to Normal Position | ---------- | All OK: ✓✓ 1st m |

### G. SLUDGE THICKENER, SLUDGE HOLDING TANKS, FILTER PRESS

| Item | Status | Comments |
|---|---|---|
| Verify Sludge Thickener Running | ✓ | Gauge Reading: 0 % |
| Sludge Thick. Transfer Pump (P-350) | ✓ | |
| Sludge Holding Tank (T-351) | ✓ | Level:~ 65 % |
| Sludge Holding Tank (T-352) | ✓ | Level: 42 % |
| Decant Transfer Pump (P-352) | ✓ | CV 44% @ 0.4 gpm |
| Filter Press Pumps (P-381 / P-382) | ✓ | |
| Filter Press | ✓ | Stage: Full |

# ABLE 3.19.1
# STANDARD OPERATIONS CHECKLIST
# MAIN WTP

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, August 19, 2021

**Inspection Performed by:** Mike Gelwick

### H. ION EXCHANGE

| Item | Status | Comments |
|---|---|---|
| Feed Tank (T-113) | ✓ Level: % | |
| Feed Pump (P-114) | ✓ Operating Press: 75.5 psi | CV@ 73 % @ 3.9 gpm |
| Retention Tank (T-114) | ✓ Operating Press: 73 psi | pH-113 @ 3.75 |
| Bag Filter (BF-113) | ✓ Operating Press: 76 psi | |
| Ion Exchange (Cage (1) or 2) + Guard | ✓ Operating Press: 72 psi | currently TP-173A-2 → TP-175A/4 canisters + Guard |
| Post Ion Exchange | ✓ Operating Press: 4 psi | |

* Increased flow on 8-18-21

### I. FEED SURGE TANK

| Item | Status | Comments |
|---|---|---|
| Feed Surge Tank (T-520) | ✓ Level: 38 % | Last Cleaning (As Needed, if 4" of solids accumulate): 12/15/19 |
| Feed Surge Pump (P-521 or (P-522)) | Operating Press: 38 psi | CV@ 78 % @ 36.6 gpm |
| T-520 to GAC Total (FT-675) | 248037197 gal | Time: 1033 |
| North End On-Site Pumping | Operating Press: 2-3 psi | 13.0 gpm @ 1026 |
| North End Off-Site Pumping | Operating Press: 2-6 psi | 8.5 gpm @ 1026 |
| Peroxide Feed Pump (P-680) | ✓ | SPD 2.7 % / RATE 0.7 |
| Peroxide Conc. At (TP-710) | 1.0 PPM | |
| Peroxide Conc. At (TP-740) | 0.0 PPM | |

### J. HAZARDOUS WASTE STORAGE

| Item | Status | Comments |
|---|---|---|
| 180 Day storage area check | ✓ | Check sheet completed: NA/Empty |
| Satellite Haz. Waste Areas (BLDG #1) | ✓ | Condition: Good |
| Satellite Haz. Waste Area (BLDG #2) | ✓ | Condition: Good |

IX System Anionic Resin satellite container in Good condition

### K. UV-OXIDATION SYSTEM

| Item | Status | Comments |
|---|---|---|
| UV-Oxidation System | ✓ | |
| Annual Test Run (Calgon) | Date: 9-4-20 | Next: 9-2021 |
| Quarterly Test Run | Date: NA/Running | Next: NA/Running |
| Peroxide Feed Pump (P-650) | ✓ | Flow Rate: ~7.0 cc/min. |
| UV-Ox Power | ✓ | 25.7 kVA 2607 Volts 9.9 Amps |
| Lamp Hours | 494 Hrs | |
| Crystal Condition & Wiper Status | ✓ | Oiler status: OK |
| UV-OX Bagfilters Status | Last change: 7-13-21 Cleaned: 7-13-21 | 11.5 psi In 12.0 psi Out |
| UV-OX Feed Pump ( P-600 or (P-601) ) | ✓ | CV@ 75 % @ 8.0 gpm |
| UV-OX Temperature | In(TT-670): 16.6 °C | Out(TT-710): 28.0 °C |
| PDU GAC (PDT-710) | ✓ | Δ Pressure: 4 psi |
| Peroxide Concentration Pre UV | 100 PPM | |
| Peroxide Concentration Post UV(TP-720) | 20 PPM | |
| Peroxide Conc. Post PDU (TP-730) | 0.0 PPM | |
| Secondary Acid Feed Pump (P-630) | ✓ | CV @ ( % |
| Secondary Acid Retention Tank (T-645) | ✓ | |
| Pre – UV Oxidizer Total (FT-670) | 19374532 gal | Time: 1032 |
| Post UV-Ox / Pre PDU | ✓ | Pressure: 14 psi |
| Post PDU | ✓ | Pressure: 7.25 psi |

# ABLE 3.19.1
# STANDARD OPERATIONS CHECKLIST
# MAIN WTP

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, August 19, 2021

**Inspection Performed by:** Mike Gelwick

### L. PDU AND LIQUID –PHASE GRANULAR ACTIVATED CARBON

| Item | Status | Comments |
|---|---|---|
| PDT-720 | ✓ | Δ Pressure: 20 psi |
| PDT-730 | ✓ | Δ Pressure: 11 psi |

### M. EFFLUENT DISCHARGE

| Item | Status | Comments |
|---|---|---|
| Effluent Surge Pump (P751) or P752 ) | ✓ | CV@ 55.6 % |
| Effluent Surge Tank (T-740) | ✓ | Level: 40 % |
| Effluent Discharge Rate (FT-770) | ✓ | 36.3 gpm @ 1031 |
| POTW Line Pressure (PT-770) | ✓ | 32.6 psi |
| Effluent Totalizer Reading (FT-770) | 242104082 gal | Time: 1035 |
| POTW MH17S-078 Discharge Check (Monthly) | ✓ | Last Done: 8-17-21 |
| 4X8-Inch POTW Leak Detection Checks (Monthly) | ✓ | Last Done: |
| 4X8-Inch POTW Air Reliefs Checks (Monthly) | ✓ | Last Done: |
| 4X8-Inch POTW Isolation Valves Exercise (Qtrly) | ✓ | Last Done: |
| 2-Inch POTW Backup Pressure Testing (Annual) | ✓ | Last Done: 7/8/21 |
| 2-In POTW Backup Air Reliefs Checks (Annual) | ✓ | Last Done: 7/8/21 |
| 2-Inch POTW Isolation Valve Exercise (Annual) | ✓ | Last Done: 7/8/21 |
| Rotate Chiller Compressors | NA on Standby | ~~Now in Lead: 1 or 2~~ |

### N. LEL EFFLUENT TANK T-740

| Item | Status | Comments |
|---|---|---|
| LEL-740 Sensor | ✓ | Reading: 1 % |
| LEL Sensor Calibration / Automatic High LEL Shutdown Test (monthly) | Last Completed: 7-29-21 | Plant Effluent Suspended: 1320 ↔ 1340 |
| LEL Sensor Bridge Adjustment to 2.0 volts | Reading: 2.001 volts(monthly) | Adjustment Needed: Y or (N) |
| Verify Bridge Current between.300v-.360v | Reading: 0.331 volts(monthly) | |

### O. WTP INFLUENT TOTALIZERS Time : 1035 - 1039

| Source | Reading(Gallons) | Source | Reading(Gallons) |
|---|---|---|---|
| (FT-015) RWST Influent | 19588274 | (FT-505) LFG Cond. to T-530 | 215775 |
| (FT-025) NBBW Influent | 93352341 | (FT-056) Off - Site N. End Influent | 42378056 |
| (FT-012) MW-38 Inf. to HMR-30 | 8098981 | (FT-113) Ion Exchange Influent | 462468 |
| (FT-042 HMR30) MW-38 Source to HMR-30 | 35484 | (FT-810) Plant Potable Water In | 30053434 |
| (FT-043) MW-38 to RWST | 3067460 | (FT-026) NBBW Bypass to RWST | 4373930 |
| (FT-042 RWST) MW-38 Source to RWST | 72236 | (FT-014) Misc. Water to RWST | 8133454 |
| (FT-012T) MW-38 to T-540/541 | 8590044 | (FT-035) NTES Inf. to BIO | 6615370 |
| (FT-040T) MW-38N to T-540/541 | 1976891 | (FT-035T) NTES to T-530 | 4579141 |
| (FT-041T) MW-38S to T-540/541 | 2694735 | (FT-017) BIO Inf. from T-530 | 649133 |
| (FT-042T) MW-38 Source to T-540/541 | 3990399 | (FT-018) T-540/541 Influent | 8636841 |
| (FT-055) On - Site N. End Influent | 96865944 | (FT-352) T-352 to HMR-30 | 1262752 |

# ABLE 3.19.1
# STANDARD OPERATIONS CHECKLIST
# MAIN WTP

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, August 19, 2021

**Inspection Performed by:** Mike Gelwick

### P. AIR COMPRESSORS

| Item | Status | Comments |
|---|---|---|
| Compressor Intake Temp. | 76 °F (Analog Gauge) | Outside Temp.: ~ 70 °F |
| Compressor Building Vent | ✓ | closed - observed |
| Primary Air Compressor (IRN30H) | 2,000 Hour service date: 7-8-21<br>Serviced @ 60952 Hours | Coolant present in sight glass: Ⓨ / N<br>Next service @ 62952 Hours<br>Current Hours @ 61508 |
| IRN30H Motor Speed | 31 % | |
| IRN30H Pressure | 111 psi | |
| IRN30H Moisture purge valve chk(Weekly) | ✓ | |
| IRN30H Intake Filter | ✓ | Date Last Changed: 8-12-21 |
| Air Tanks Moisture Purge Valves | Manually Activate(weekly) ✓ | Excessive Moisture: Y / Ⓝ |
| Backup Air Compressors (T-30 East and West) | ✓ | Both cool to touch: Ⓨ / N |
| Air Dryer | ✓ Eco on | Moisture at Receiver Tank: Y / Ⓝ |
| Oil Moisture Prevention (Monthly) | Last Done: 7-22-21 | Run at max speed by bleeding air from filter canister above/after air dryer for 2 hrs |
| Air Receiver Tank | ✓ | 110 psi |

### Q. SUMPS

| Item | Status | Comments |
|---|---|---|
| Bag Filter Sump | ✓ | |
| Wet Well Sump | ✓ | |

### R. GAS CHROMATOGRAPH

| Item | Status | Comments |
|---|---|---|
| GC Operational | ✓ | GC # checking UV-Ox Effluent: #2 |
| Alarms Enabled | ✓ | a - calibration + maint 8-18-21 |
| GC Influent Filters | ✓ | |

### S. SAFETY

| Item | Status | Comments |
|---|---|---|
| Building #1 Fire Extinguishers | ✓ | Date inspected: 7-26-21 |
| Building #1 Eye Wash/Shower | ✓ | Checked and Flushed- All OK: Ⓨ / N |

**Other Comments:**

| |
|---|
| * 8-17-21- Begin increasing flow thru EX System. Take TP-173A-1 offline and empty. Now only running thru 4 canisters on stage 1 and GAC vessels. TP-173A-2 -> TP-175A. |
| |
| |
| |

# TABLE 3.19.2
# STANDARD OPERATIONS CHECKLIST
# BIOLOGICAL TREATMENT SYSTEM

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, August 19, 2021

**Inspection Performed by:** Mike Gelwick

## A. PUMPS

| Item | Status | Flow Rate (gpm) | Pump Speed (CV%) | Discharge Pressure (psi) | | Comments |
|---|---|---|---|---|---|---|
| **T-510 Pumps** | | | | | | |
| P-3301 | ✓ | 1.20 | 22.0 % | 5.5 | | |
| P-3301A | SB | — | — % | — | | |
| **NTES Pump** Swapped out 8-17-21 P-002(Sump) / (P-002W(10R)) | ✓ | 0.51 | 47 % | P035 34-35 | P038 6.0 | Globules Observed at TP-130: Y / (N) Time: 1000 |
| **T-530** P-005 | SB | — | — % | — | | |
| **T-540/541** P-006 | ✓ | 0.31 | 57 % | 4.0 | | |
| **LFG COND Auto-Traps** | ✓ | 0.0 | NA | 5.0 | | Between Cycles: (Y) / N Received 325 gal transported |
| **Reactor Feed Pumps** | | | | | | |
| P-3321 | SB | — | — % | — | | |
| P-3322 | ✓ | 3.14 | 49.2 % | 5.0 | | |
| P-3323 | ✓ | 2.27 | 75.4 % | 6.5 | | |
| P-3324 | ✓ | 2.14 | 51.6 % | 11.0 | | |
| **Reactor Effluent Pumps** | | | | | | |
| P-3341 | ✓ | 1.75 | 56.9 % | 10.0 | | |
| P-3341A | SB | — | — % | — | | |

## B. BLOWERS

| Item | Status | Pressure (psi) | Temp (°F) | Next Scheduled Service (Qtrly) | Comments Last serviced on: 6-22-21 |
|---|---|---|---|---|---|
| B-3331 | ✓ | 4.26 | 152 | 9-2021 | Greased, Belt and Filter Checked: (Y) / N |
| B-3332 | SB | — | — | ↓ | Belt and Filter Checked: Y / (N) |
| B-3333 | ✓ | 4.34 | 154 | ↓ | Greased, Belt and Filter Checked: (Y) / N |
| B-3334 | ✓ | 4.29 | 152 | ↓ | Greased, Belt and Filter Checked: (Y) / N |

## C. REACTOR VENTILATION

| Item | Status | Comments |
|---|---|---|
| Vapor Carbon Contactor | ✓ | On-line: 2/10/18 |
| Reactor Vent Blower | ✓ | |
| Reactor Vent Booster | ✓ | |
| VTP-3350 | ✓ | PID Reading: 13.6 PPM |
| VTP-3360 | ✓ | PID Reading: 9.2 PPM |

# TABLE 3.19.2
# STANDARD OPERATIONS CHECKLIST
# BIOLOGICAL TREATMENT SYSTEM

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, August 19, 2021

**Inspection Performed by:** Mike Gelwick

## D. TANKS / REACTORS / SUMPS / CONTAINMENTS / PIPING / Chiller

| Item | Status | Comments |
|---|---|---|
| T-510 Post HMR-30 Mixing Tank | ✓ Level: 68 % | Last Cleaning (As needed, if 2" of solids accumulate): ~~12/15/19~~ 7-14-21 |
| T-530 LFG Condensate / NTES Tank | ✓ Level: 27 % | |
| T-530 Mixer | ✓ | |
| LFG Condensate Conveyance Line | ✓ | Last Pressure Test: 7-19-21 Next: 7-2022 (Annual at a minimum or if flow drops off) |
| T-540/541 MW38 Tanks | Lvls: 48 % & 49 % | |
| T-540/541 Mixers | ✓ | |
| Chiller | ✓ | Chiller Coolant Lvl: ~ 1.5 " Below full mark |
| Chiller Cooling Fins (as needed) | ✓ | Last Cleaning: 4/20/18 (unit on Standby) |
| Secondary Containments | ✓ | Heat Trace: On OK / (Off Warm out) |
| Feed Piping to Sedimentation Tank | ✓ | Last Back Flushing (Quarterly): 8-4-21 |
| T-3310 Sedimentation Tank | Visual Level: ok | Last Cleaning (As Needed, use TSS info to determine): 12/2017 |
| T-3320 Blend Tank | ✓ Level: 74 % | Last Cleaning (Semi Annual): 5-7-20 |
| T-3331 Reactor No. 1 | ✓ | Digital Displays: (GOOD) / Needs Attn |
| T-3332 Reactor No. 2 | ✓ | Digital Displays: (GOOD) / Needs Attn |
| T-3333 Reactor No. 3 | ✓ | Digital Displays: (GOOD) / Needs Attn |
| T-3334 Settling Tank | ✓ | Last Cleaning (Semi Annual): 5-7-20 |
| P-3334 Biosolids Pump | ✓ | |
| T-3340 Overflow Tank | ✓ Level: 30 % | |
| Recycle Valve to Blend Tank | ✓ | 3.94 gpm @ 1110 |
| Building Containment Sump | ✓ | Last Alarm Test Date (Monthly): 8-19-21 - Today |

## E. CHEMICAL FEED SYSTEM

| Item | Status | Comments |
|---|---|---|
| Phosphorous Supply | ✓ | Bags: 18.5 Gallons: ~ 70 |
| Phosphorous Pump (P-2221) | ✓ | |
| Caustic Supply | ✓ | ~ 200 Gallons |
| Caustic Pump (P-2211) | SB | Currently in acid addition mode |
| Acid Supply | ✓ | ~ 40 Gallons |
| Acid Pump (P-2211) | ✓ | |
| Caustic Pump (P-2231) | ✓ Leaks: Y / (N) | Last tubing tip cleaning (monthly): 8-19-21 - Today |
| Caustic Pump (P-2232) | ✓ Leaks: Y / (N) | Last tubing tip cleaning (monthly): ↓ |
| Caustic Pump (P-2233) | ✓ Leaks: Y / (N) | Last tubing tip cleaning (monthly): ↓ |

# TABLE 3.19.2
# STANDARD OPERATIONS CHECKLIST
# BIOLOGICAL TREATMENT SYSTEM

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, August 19, 2021

**Inspection Performed by:** Mike Gelwick

## F. pH Probes

| pH Probe Location | Calibration Date (Monthly) | Comments |
|---|---|---|
| pH-3320 Blend Tank | 7-29-21 | Acid/Base cleaning today |
| pH-3331 Reactor 1 | ↓ | ↓ |
| pH-3332 Reactor 2 | | |
| pH-3333 Reactor 3 | | |

## G. FILTER SYSTEM

| Item | Status | Comments |
|---|---|---|
| BF-3340 a/b Status | ✓ | |
| Automatic Backwash | Cycle Count: 63 | Reset |
| BF-3340 a/b Differential Pressure | PSI: 2 | 15/17 ≈2.9 gpm |
| 75-micron Bags Last Cleaning | Date: 11-14-19 | |
| 75-micron Bags Last Inspection | Date: | |
| 75-micron Bags Last Changed | Date: | |
| GACF-3340 Status | ✓ | |
| GACF-3340 Differential Pressure | PSI: 10 | 17/6 ≈2.9 gpm |
| Last Backwash Performed | Date: 7-14-21 | |

## H. ELECTRICAL AND INSTRUMENTATION

| Item | Status | Comments |
|---|---|---|
| "BIO" Backup Generator | ✓ | Block Heater: On OK / (Off Warm Out) |
| Electrical Surge Suppressor | ✓ | |
| Motor Control Center | ✓ | |
| PLC | ✓ | UPS @ 97 min / 73 Events |
| HMI's | ✓ | |
| BTS Process KWH Meter | 1789160 KWH | Time: 1200 |
| Building#2 KWH Meter | 5210267 KWH | Time: 1200 |

## I. GAS CHROMATOGRAPHY

| Item | Status | Comments |
|---|---|---|
| GC Operational | ✓ | GC # checking BIO: #3 |
| Alarms Enabled | ✓ | CC - Calibration + Maint 8-19-21 |
| GC Influent Filters | ✓ | |

# TABLE 3.19.2
# STANDARD OPERATIONS CHECKLIST
# BIOLOGICAL TREATMENT SYSTEM

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, August 19, 2021

**Inspection Performed by:** Mike Gelwick

## J. TOTALIZERS

| Item | Readings (gallons) | Comments |
|---|---|---|
| FT-3321 Feed to Reactor 1 | 5798182 | |
| FT-3324 Feed Spare | 83880 | |
| FT-3322 Feed to Reactor 2 | 10456563 | |
| FT-3323 Feed to Reactor 3 | 512486 | |
| FT-3301 T-510 to BIO | 51313933 | |
| FT-3341 BIO Effluent | 66049980 | |
| FT-3342 BIO Recycle | 55128837 | |

## K. SAFETY

| Item | Status | Comments |
|---|---|---|
| Building #2 Fire Extinguishers | ✓ | Inspection date: 7-26-21 |
| Building #2 Eye Wash/Shower | ✓ | Checked and Flushed- All OK: Ⓨ / N |

## L. OTHER COMMENTS:

| |
|---|
| |
| |
| |
| |

# ABLE 3.19.1
# STANDARD OPERATIONS CHECKLIST
# MAIN WTP

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, August 26, 2021

**Inspection Performed by:** Mike Gelwick

## A. PERIMETER COLLECTION SYSTEMS

| Item | Status | Comments |
|---|---|---|
| LFG Cond Automatic Trap CT-1 | Sump Level: 13.84 oz | Counter: 180317 Cycles: 367 |
| LFG Cond Automatic Trap CT-2 | Sump Level: 8.61 oz | Counter: 273967 Cycles: 50 |
| LFG Cond Automatic Trap CT-3 | Sump Level: 7.73 oz | Counter: 302996 Cycles: 35 |
| CT-4 Containment/Vessel (LFG Cond) | ✓ Level: 70 % | Tank Level: 2.16 Counter: 191206 Cycles: 24 Sump: 9.14 oz |
| PM-15 Containment / Vessel | ✓ Level: 40 % | |
| MW-51 Containment / Vessel | ✓ Level: 50 % | |
| PM-11 Containment / Vessel | ✓ Level: 55 % | |
| MW-38 Systems | ✓ | |
| North Toe System | ✓ | |
| North End Systems (Weekly) | ✓ | |
| Full N. End Systems Check (Monthly) | ✓ | Last Done: 8-27-21 |
| North End Pipeline(s)Flushing (As Needed) | ✓ | Perform if suspended solids present Last Done: 11/15/15 |
| NTES line flush to T-530 (As needed) | ✓ | Perform if suspended solids present Last Done: 2/13/20 |
| NTES Piping Containment | ✓ | Monthly Sump Level: Dry @ 16.07' Date: 8-19-21 |
| North Boundary System P-001: | CV 75.6 % @ 7.4 gpm | 42.16 Hz / 2.11 Amps. / vault psi @ 18/20 kPa |
| T-101 & T-102 Containment / Tank | ✓ | Levels: 31 % & 30 % |
| Raw Water Storage Tanks Piping | ✓ | |
| RWST Building Temp. (TT-101) | 74.4 °F | Outside Temp.: ~ 77 °F |
| (P-121) or P-122 | ✓ | 0.6 gpm / CV 57 % |
| RWST 2ndry Cont. High Level Switch | ✓ | (LSH-101) Last Test(monthly): 8-19-21 |
| RWST Back-Up Generator | ✓ | Last Test Run(monthly): 8-19-21 |

## B. CHEMICAL STORAGE BAYS

| Item | Status | Comments |
|---|---|---|
| Caustic Tote Levels | ✓ | ~ 510 Gallons Reserve = 1 tote |
| Caustic Bay Heater | ✓ | 56 - warm out |
| Peroxide Tote Level | ✓ | ~ 75 Gallons Reserve = ~55 gal |
| HCL Tote Levels | ✓ | ~ 225 Gallons Reserve = ~30 gal |
| Chemical Totes and Piping Inspected | ✓ | Leaks observed: Y / (N) |
| Emergency Shower Inspected | ✓ | Checked and Flushed - All OK: (Y) / N |

## C. PRIMARY AND SECONDARY ACID FEED SYSTEM

| Item | Status | Comments |
|---|---|---|
| Primary Acid Feed Pump (P-631) | ✓ | |
| Ion Exchange Acid Feed Pump (P-632) | ✓ | PI-0632 PSI: 80 CV: 8 % |
| Primary Acid Retention Tank (T-510) | ✓ | |
| All Acid Feed Lines | ✓ | Leaks observed: Y / (N) |

## D. NBBW INJECTION TRENCH

| Item | Status | Comments |
|---|---|---|
| Injection Carbon (GAC-810) | OFFLINE | Date online: 7/20/18 |
| Injection Rate (FT-800) | 0.0 gpm | NBBW-IW-1= 0.0 NBBW-IW-2= 0.0 NBBW-IW-3= 0.0 gpm ea. |
| Totalizer Reading (FT-800) | 105,135,774 gal | INJ. STOPPED 10/02/18 @ 1545 |

# ABLE 3.19.1
# STANDARD OPERATIONS CHECKLIST
# MAIN WTP

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, August 26, 2021

**Inspection Performed by:** Mike Gelwick

## E. CHEMICAL PRECIPITATION SYSTEM (US FILTER HMR-30)

| Item | Status | Comment |
|---|---|---|
| T-300A Mixer | NA | |
| T-300B (Caustic Mixer) | ✓ | Last Cleaning (Qtrly): 6-3-21 |
| T-300A/B Water Level | ✓ | |
| T-300B (Caustic Mix Chamber) | ✓ | Last Cleaning (Qtrly): 6-3-21 |
| T-300A/B Overflow | ✓ | |
| pH Set-point for (pH 315) | Value: 10.8 | |
| pH 310 | Value: 6.77 | |
| pH 315 | Value: 10.87 | |
| Flocculation Chamber Paddle Wheel | ✓ | |
| Precipitate Floc Quality | ✓ | Good |
| Clarifier Water Quality | ✓ | Good Oil or sheen observed: Y / (N) |
| Clarifier Effluent Piping / Water Level | ✓ | |
| Clear-well Chamber and Water Level | ✓ | |
| HMR PLC Panel | ✓ | |
| Caustic Pump (P-270) | SB | |
| Caustic Pump (P-280) | ✓ | |
| Polymer Pump (P-310) | ✓ | |
| Polymer Tank Mixer | ✓ | |
| Polymer Tank Level | Gallons: ~ 475 | |
| Clear-well Transfer Pumps(P-371 / (372)) | ✓ | |
| Sludge Transfer Pump (P-330) | ✓ | Exercise Valves Weekly: Auto |
| Manual Sludge Lateral pumping | ✓ | Last done (As Needed): #3-7-20-21 / #1&2-5-20-20 |
| Manual Sludge Lateral Ball Valves | ✓ | Exercise Weekly: Allow |
| Automatic Blow-down Operations | ✓ | |

## F. pH PROBES

| pH Probe Location | Calibration Date | Comments: (Time done) |
|---|---|---|
| pH-310 HMR-30 (T-300A) | 8-26-21-Today | 1330 |
| pH-315 HMR-30 (T-300B) | | |
| pH-365 Primary Acid Ret. Tank | | |
| pH-113 Pre-Ion Exchange | | |
| pH-670 Pre-UV-OX | | 1400 |
| pH-740 Discharge Surge Tank | | Discharge suspended: 1400 ↔ 1420 |
| Out of Hold Double Check | ---------- | None in hold: ✓✓ |
| Valves Back to Normal Position | ---------- | All OK: ✓✓ |

## G. SLUDGE THICKENER, SLUDGE HOLDING TANKS, FILTER PRESS

| Item | Status | Comments |
|---|---|---|
| Verify Sludge Thickener Running | ✓ | Gauge Reading: 0 % |
| Sludge Thick. Transfer Pump (P-350) | ✓ | |
| Sludge Holding Tank (T-351) | ✓ | Level:~ 65 % |
| Sludge Holding Tank (T-352) | ✓ | Level: 47 % |
| Decant Transfer Pump (P-352) | ✓ | CV 46 % @0.4 gpm |
| Filter Press Pumps (P-381 / P-382) | ✓ | |
| Filter Press | ✓ | Stage: Full |

# ABLE 3.19.1
# STANDARD OPERATIONS CHECKLIST
# MAIN WTP

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, August 26, 2021

**Inspection Performed by:** Mike Gelwick

### H. ION EXCHANGE

| Item | Status | Comments |
|---|---|---|
| Feed Tank (T-113) | ✓ Level: 30 % | |
| Feed Pump (P-114) | ✓ Operating Press: 68.8 psi | CV@ 79 % @ 3.8 gpm |
| Retention Tank (T-114) | ✓ Operating Press: 62 psi | pH-113 @ 4.01 |
| Bag Filter (BF-113) | ✓ Operating Press: 65 psi | |
| Ion Exchange (Cage (1) or 2) + Guard | ✓ Operating Press: 62 psi | TP-173A-2 → TP-175A / 4 canisters + Guard |
| Post Ion Exchange | ✓ Operating Press: 4 psi | |

### I. FEED SURGE TANK

| Item | Status | Comments |
|---|---|---|
| Feed Surge Tank (T-520) | ✓ Level: 38 % | Last Cleaning (As Needed, if 4" of solids accumulate): 12/15/19 |
| Feed Surge Pump (P-521 or (P-522)) | Operating Press: 24 psi | CV@ 68 % @ 35.7 gpm |
| T-520 to GAC Total (FT-675) | 248403895 gal | Time: 1119 |
| North End On-Site Pumping | Operating Press: 2-3 psi | 12.6 gpm @ 1113 |
| North End Off-Site Pumping | Operating Press: 2-6 psi | 8.6 gpm @ 1113 |
| Peroxide Feed Pump (P-680) | ✓ | SPD 2.7 % / RATE 0.7 |
| Peroxide Conc. At (TP-710) | 1.0 PPM | |
| Peroxide Conc. At (TP-740) | 0.0 PPM | |

### J. HAZARDOUS WASTE STORAGE

| Item | Status | Comments |
|---|---|---|
| 180 Day storage area check | ✓ | Check sheet completed: NA/Empty |
| Satellite Haz. Waste Areas (BLDG #1) | ✓ | Condition: Good |
| Satellite Haz. Waste Area (BLDG #2) | ✓ | Condition: Good |

IX System Anions Resin Satellite container in Good condition

### K. UV-OXIDATION SYSTEM

| Item | Status | Comments |
|---|---|---|
| UV-Oxidation System | ✓ | |
| Annual Test Run (Calgon) | Date: 8-4-20 | Next: 9-2021 |
| Quarterly Test Run | Date: NA/Running | Next: NA/Running |
| Peroxide Feed Pump (P-650) | ✓ | Flow Rate: ~ 7.0 cc/min. |
| UV-Ox Power | ✓ | 25.7 kVA 2618 Volts 9.8 Amps |
| Lamp Hours | 663 Hrs | |
| Crystal Condition & Wiper Status | ✓ | Oiler status: ok |
| UV-OX Bagfilters Status | Last change: 7-13-21 Cleaned: 7-13-21 | 11.5 psi In 12.5 psi Out |
| UV-OX Feed Pump ( P-600 or (P-601) ) | ✓ | CV@ 75 % @ 7.9 gpm |
| UV-OX Temperature | In(TT-670): 16.6 °C | Out(TT-710): 28.0 °C |
| PDU GAC (PDT-710) | ✓ | Δ Pressure: 4 psi |
| Peroxide Concentration Pre UV | 100 PPM | |
| Peroxide Concentration Post UV(TP-720) | 25 PPM | |
| Peroxide Conc. Post PDU (TP-730) | 0.0 PPM | |
| Secondary Acid Feed Pump (P-630) | ✓ | CV @ 1 % |
| Secondary Acid Retention Tank (T-645) | ✓ | |
| Pre – UV Oxidizer Total (FT-670) | 19453084 gal | Time: 1120 |
| Post UV-Ox / Pre PDU | ✓ | Pressure: 14 psi |
| Post PDU | ✓ | Pressure: 7.25 psi |

# ABLE 3.19.1
# STANDARD OPERATIONS CHECKLIST
# MAIN WTP

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, August 26, 2021

**Inspection Performed by:** Mike Gelwick

### L. PDU AND LIQUID –PHASE GRANULAR ACTIVATED CARBON

| Item | Status | Comments |
|---|---|---|
| PDT-720 | ✓ | Δ Pressure: 8 psi |
| PDT-730 | ✓ | Δ Pressure: 10 psi |

### M. EFFLUENT DISCHARGE

| Item | Status | Comments |
|---|---|---|
| Effluent Surge Pump (P751) or P752 ) | ✓ | CV@ 57.3 % |
| Effluent Surge Tank (T-740) | ✓ | Level: 40 % |
| Effluent Discharge Rate (FT-770) | ✓ | 36.2 gpm @ 1118 |
| POTW Line Pressure (PT-770) | ✓ | 32.5 psi |
| Effluent Totalizer Reading (FT-770) | 242470438 gal | Time: 1120 |
| POTW MH17S-078 Discharge Check (Monthly) | ✓ | Last Done: 8-17-21 |
| 4X8-Inch POTW Leak Detection Checks (Monthly) | ✓ | Last Done: |
| 4X8-Inch POTW Air Reliefs Checks (Monthly) | ✓ | Last Done: |
| 4X8-Inch POTW Isolation Valves Exercise (Qtrly) | ✓ | Last Done: |
| 2-Inch POTW Backup Pressure Testing (Annual) | ✓ | Last Done: 7/8/21 |
| 2-In POTW Backup Air Reliefs Checks (Annual) | ✓ | Last Done: 7/8/21 |
| 2-Inch POTW Isolation Valve Exercise (Annual) | ✓ | Last Done: 7/8/21 |
| Rotate Chiller Compressors | NA on Standby | ~~Now in Lead: 1 or 2~~ |

### N. LEL EFFLUENT TANK T-740

| Item | Status | Comments |
|---|---|---|
| LEL-740 Sensor | ✓ | Reading: 0 % |
| LEL Sensor Calibration / Automatic High LEL Shutdown Test (monthly) ✓ | Last Completed: 8-26-21 - gdm | Plant Effluent Suspended: 1400 ◄► 1420 |
| LEL Sensor Bridge Adjustment to 2.0 volts | Reading: 2.001 volts(monthly) | Adjustment Needed: Y or (N) |
| Verify Bridge Current between.300v-.360v | Reading: 0.330 volts(monthly) | |

### O. WTP INFLUENT TOTALIZERS Time : 1121- 1126

| Source | Reading(Gallons) | Source | Reading(Gallons) |
|---|---|---|---|
| (FT-015) RWST Influent | 19596094 | (FT-505) LFG Cond. to T-530 | 215917 |
| (FT-025) NBBW Influent | 93426251 | (FT-056) Off - Site N. End Influent | 42459932 |
| (FT-012) MW-38 Inf. to HMR-30 | 8117659 | (FT-113) Ion Exchange Influent | 500788 |
| (FT-042 HMR30) MW-38 Source to HMR-30 | 35484 | (FT-810) Plant Potable Water In | 30054646 |
| (FT-043) MW-38 to RWST | 3067813 | (FT-026) NBBW Bypass to RWST | 4375418 |
| (FT-042 RWST) MW-38 Source to RWST | 72236 | (FT-014) Misc. Water to RWST | 8133454 |
| (FT-012T) MW-38 to T-540/541 | 8590044 | (FT-035) NTES Inf. to BIO | 6620319 |
| (FT-040T) MW-38N to T-540/541 | 1976891 | (FT-035T) NTES to T-530 | 459283 |
| (FT-041T) MW-38S to T-540/541 | 2694735 | (FT-017) BIO Inf. from T-530 | 649133 |
| (FT-042T) MW-38 Source to T-540/541 | 3790399 | (FT-018) T-540/541 Influent | 8639795 |
| (FT-055) On - Site N. End Influent | 96995104 | (FT-352) T-352 to HMR-30 | 1266447 |

# ABLE 3.19.1
# STANDARD OPERATIONS CHECKLIST
# MAIN WTP

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, August 26, 2021

**Inspection Performed by:** Mike Gelwick

### P. AIR COMPRESSORS

| Item | Status | Comments |
|---|---|---|
| Compressor Intake Temp. | 70 °F (Analog Gauge) | Outside Temp.: ~ 79 °F |
| Compressor Building Vent | ✓ | closed - operational |
| Primary Air Compressor (IRN30H) | 2,000 Hour service date: 7-8-21<br>Serviced @ 60952 Hours | Coolant present in sight glass: (Y) / N<br>Next service @ 62952 Hours<br>Current Hours @ 61604 |
| IRN30H Motor Speed | 0 % | |
| IRN30H Pressure | 119 psi | |
| IRN30H Moisture purge valve chk(Weekly): | ✓ | |
| IRN30H Intake Filter | ✓ | Date Last Changed: 8-12-21 |
| Air Tanks Moisture Purge Valves | Manually Activate(weekly) ✓ | Excessive Moisture: Y / (N) |
| Backup Air Compressors (T-30 East and West) | ✓ | Both cool to touch: (Y) / N |
| Air Dryer | ✓ Eco on | Moisture at Receiver Tank: Y / (N) |
| Oil Moisture Prevention (Monthly) | Last Done: 8-26-21 - Today | Run at max speed by bleeding air from filter canister above/after air dryer for 2 hrs |
| Air Receiver Tank | ✓ | 108 psi |

### Q. SUMPS

| Item | Status | Comments |
|---|---|---|
| Bag Filter Sump | ✓ | |
| Wet Well Sump | ✓ | |

### R. GAS CHROMATOGRAPH

| Item | Status | Comments |
|---|---|---|
| GC Operational | ✓ | GC # checking UV-Ox Effluent: #2 |
| Alarms Enabled | ✓ | cc- calibration + maint 8-25-21 |
| GC Influent Filters | ✓ | |

### S. SAFETY

| Item | Status | Comments |
|---|---|---|
| Building #1 Fire Extinguishers | ✓ | Date inspected: 8-25-21 |
| Building #1 Eye Wash/Shower | ✓ | Checked and Flushed- All OK: (Y) / N |

**Other Comments:**

# TABLE 3.19.2
# STANDARD OPERATIONS CHECKLIST
# BIOLOGICAL TREATMENT SYSTEM

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, August 26, 2021

**Inspection Performed by:** Mike Gelwick

## A. PUMPS

| Item | Status | Flow Rate (gpm) | Pump Speed (CV%) | Discharge Pressure (psi) | | Comments |
|---|---|---|---|---|---|---|
| **T-510 Pumps** | | | | | | |
| P-3301 | ✓ | 1.21 | 27.2 % | 6.0 | | |
| P-3301A | SB | – | – % | – | | |
| **NTES Pump** P-002(Sump) / (P-002W(10R)) | ✓ | 0.50 | 48 % | P035 36-37 | P038 6.0 | Globules Observed at TP-130: Y / (N) Time: 1045 |
| **T-530** P-005 | SB | – | – % | – | | |
| **T-540/541** P-006 | ✓ | 0.30 | 57 % | 3.5 | | |
| **LFG COND Auto-Traps** | ✓ | 0.0 | NA | 4.75 | | Between Cycles: (Y) / N |
| **Reactor Feed Pumps** | | | | | | |
| P-3321 | ✓ | 2.16 | 48.6 % | 5.0 | | |
| P-3322 | ✓ | 3.04 | 43.2 % | 5.0 | | |
| P-3323 | ✓ | 2.20 | 65.0 % | 5.0 | | |
| P-3324 | SB | – | – % | – | | |
| **Reactor Effluent Pumps** | | | | | | |
| P-3341 | ✓ | 3.48 | 45.9 % | 10.0 | | [illegible] GACF-3340 today |
| P-3341A | SB | – | – % | – | | |

## B. BLOWERS

| Item | Status | Pressure (psi) | Temp (°F) | Next Scheduled Service (Qtrly) | Comments Last serviced on: 6-22-21 |
|---|---|---|---|---|---|
| B-3331 | ✓ | 4.25 | 154 | 9-2021 | Greased, Belt and Filter Checked: (Y) / N |
| B-3332 | SB | – | – | ↓ | Belt and Filter Checked: Y / (N) |
| B-3333 | ✓ | 4.36 | 156 | ↓ | Greased, Belt and Filter Checked: (Y) / N |
| B-3334 | ✓ | 4.27 | 154 | ↓ | Greased, Belt and Filter Checked: (Y) / N |

## C. REACTOR VENTILATION

| Item | Status | Comments |
|---|---|---|
| Vapor Carbon Contactor | ✓ | On-line: 2/10/18 |
| Reactor Vent Blower | ✓ | |
| Reactor Vent Booster | ✓ | |
| VTP-3350 | ✓ | PID Reading: 0.6 PPM |
| VTP-3360 | ✓ | PID Reading: 0.3 PPM |

# TABLE 3.19.2
# STANDARD OPERATIONS CHECKLIST
# BIOLOGICAL TREATMENT SYSTEM

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, August 26, 2021

**Inspection Performed by:** Mike Gelwick

## D. TANKS / REACTORS / SUMPS / CONTAINMENTS / PIPING / Chiller

| Item | Status | Comments |
|---|---|---|
| T-510 Post HMR-30 Mixing Tank | ✓ Level: 72 % | Last Cleaning (As needed, if 2" of solids accumulate): ~~12/15/19~~ 7-14-21 |
| T-530 LFG Condensate / NTES Tank | ✓ Level: 31 % | |
| T-530 Mixer | ✓ | |
| LFG Condensate Conveyance Line | ✓ | Last Pressure Test: 7-19-21 Next: 7-2022 (Annual at a minimum or if flow drops off) |
| T-540/541 MW38 Tanks | Lvls: 25 % & 27% | |
| T-540/541 Mixers | ✓ | |
| Chiller | ✓ | Chiller Coolant Lvl: ~ 1.25 " Below full mark |
| Chiller Cooling Fins (as needed) | ✓ | Last Cleaning: 4/20/18 (unit on Standby) |
| Secondary Containments | ✓ | Heat Trace: On OK / (Off Warm out) |
| Feed Piping to Sedimentation Tank | ✓ | Last Back Flushing (Quarterly): 8-4-20 |
| T-3310 Sedimentation Tank | Visual Level: OK | Last Cleaning (As Needed, use TSS info to determine): 12/2017 |
| T-3320 Blend Tank | ✓ Level: 72 % | Last Cleaning (Semi Annual): 5-7-20 |
| T-3331 Reactor No. 1 | ✓ | Digital Displays: (GOOD) / Needs Attn |
| T-3332 Reactor No. 2 | ✓ | Digital Displays: (GOOD) / Needs Attn |
| T-3333 Reactor No. 3 | ✓ | Digital Displays: (GOOD) / Needs Attn |
| T-3334 Settling Tank | ✓ | Last Cleaning (Semi Annual): 5-7-20 |
| P-3334 Biosolids Pump | ✓ | |
| T-3340 Overflow Tank | ✓ Level: 30 % | |
| Recycle Valve to Blend Tank | ✓ | 9.01 gpm @ 1143 |
| Building Containment Sump | ✓ | Last Alarm Test Date (Monthly): 8-19-21 |

## E. CHEMICAL FEED SYSTEM

| Item | Status | Comments |
|---|---|---|
| Phosphorous Supply | ✓ | Bags: 18.25 Gallons: ~ 85 |
| Phosphorous Pump (P-2221) | ✓ | |
| Caustic Supply | ✓ | ~ 180 Gallons |
| Caustic Pump (P-2211) | SB | Currently in acid addition mode |
| Acid Supply | ✓ | ~ 40 Gallons |
| Acid Pump (P-2211) | ✓ | |
| Caustic Pump (P-2231) | ✓ Leaks: Y / (N) | Last tubing tip cleaning (monthly): 8-19-21 |
| Caustic Pump (P-2232) | ✓ Leaks: Y / (N) | Last tubing tip cleaning (monthly): ↓ |
| Caustic Pump (P-2233) | ✓ Leaks: Y / (N) | Last tubing tip cleaning (monthly): |

# TABLE 3.19.2
# STANDARD OPERATIONS CHECKLIST
# BIOLOGICAL TREATMENT SYSTEM

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, August 26, 2021

**Inspection Performed by:** Mike Gelwick

## F. pH Probes

| pH Probe Location | Calibration Date (Monthly) | Comments |
|---|---|---|
| pH-3320 Blend Tank | 8-26-21-today | New 4+10 pH STD's today |
| pH-3331 Reactor 1 | ↓ | ↓ |
| pH-3332 Reactor 2 | | |
| pH-3333 Reactor 3 | | |

## G. FILTER SYSTEM

| Item | Status | Comments |
|---|---|---|
| BF-3340 a/b Status | ✓ | |
| Automatic Backwash | Cycle Count: 25 | Reset |
| BF-3340 a/b Differential Pressure | PSI: 4 | 13/9 24.5 gpm |
| 75-micron Bags Last Cleaning | Date: 11-14-19 | |
| 75-micron Bags Last Inspection | Date: | |
| 75-micron Bags Last Changed | Date: ↓ | |
| GACF-3340 Status | ✓ | |
| GACF-3340 Differential Pressure | PSI: 3 | ~~13~~ 6/9 24.5 gpm |
| Last Backwash Performed | Date: 8-26-21-today | |

## H. ELECTRICAL AND INSTRUMENTATION

| Item | Status | Comments |
|---|---|---|
| "BIO" Backup Generator | ✓ | Block Heater: On OK / (Off Warm Out) |
| Electrical Surge Suppressor | ✓ | |
| Motor Control Center | ✓ | |
| PLC | ✓ | UPS @ 97 min / 73 Events |
| HMI's | ✓ | |
| BTS Process KWH Meter | 1791012 KWH | Time: 1222 |
| Building#2 KWH Meter | 5213037 KWH | Time: 1222 |

## I. GAS CHROMATOGRAPHY

| Item | Status | Comments |
|---|---|---|
| GC Operational | ✓ | GC # checking BIO: #3 |
| Alarms Enabled | ✓ | CC-calibration + maint. 8-25-21 |
| GC Influent Filters | ✓ | |

# TABLE 3.19.2
# STANDARD OPERATIONS CHECKLIST
# BIOLOGICAL TREATMENT SYSTEM

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, August 26, 2021

**Inspection Performed by:** Mike Gelwick

## J. TOTALIZERS

| Item | Readings (gallons) | Comments |
|---|---|---|
| FT-3321 Feed to Reactor 1 | 5817484 | |
| FT-3324 Feed Spare | 87141 | |
| FT-3322 Feed to Reactor 2 | 10487914 | |
| FT-3323 Feed to Reactor 3 | 534731 | |
| FT-3301 T-510 to BIO | 51337544 | |
| FT-3341 BIO Effluent | 66081361 | |
| FT-3342 BIO Recycle | 55170131 | |

## K. SAFETY

| Item | Status | Comments |
|---|---|---|
| Building #2 Fire Extinguishers | ✓ | Inspection date: 8-25-21 |
| Building #2 Eye Wash/Shower | ✓ | Checked and Flushed- All OK: (Y) / N |

## L. OTHER COMMENTS:

| |
|---|
| |
| |
| |
| |

# ABLE 3.19.1
# STANDARD OPERATIONS CHECKLIST
# MAIN WTP

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, September 02, 2021

**Inspection Performed by:** Mike Gelwick

### A. PERIMETER COLLECTION SYSTEMS

| Item | Status | Comments |
|---|---|---|
| LFG Cond Automatic Trap CT-1 | Sump Level: 13.09 ok | Counter: 180744 Cycles: 427 |
| LFG Cond Automatic Trap CT-2 | Sump Level: 8.60 ok | Counter: 273971 Cycles: 4 |
| LFG Cond Automatic Trap CT-3 | Sump Level: 7.45 ok | Counter: 303155 Cycles: 159 |
| CT-4 Containment/Vessel (LFG Cond) | ✓ Level: 70 % | Tank Level: 2.16 Counter: 191211 Cycles: 5 Sump: 9.15 |
| PM-15 Containment / Vessel | ✓ Level: 50 % | |
| MW-51 Containment / Vessel | ✓ Level: 25 % | |
| PM-11 Containment / Vessel | ✓ Level: 20 % | |
| MW-38 Systems | ✓ | |
| North Toe System | ✓ | |
| North End Systems (Weekly) | ✓ | |
| Full N. End Systems Check (Monthly) | ✓ | Last Done: 8-27-21 |
| North End Pipeline(s)Flushing (As Needed) | ✓ | Perform if suspended solids present Last Done: 11/15/15 |
| NTES line flush to T-530 (As needed) | ✓ | Perform if suspended solids present Last Done: 2/13/20 |
| NTES Piping Containment | ✓ | Monthly Sump Level: Dry 16.07' Date: 8-19-21 |
| North Boundary System P-001: | CV 75.3 % @ 7.3 gpm | 41.96 Hz / 2.11 Amps. / vault psi @ 19/100 cells |
| T-101 & T-102 Containment / Tank | ✓ | Levels: 34 % & 33 % |
| Raw Water Storage Tanks Piping | ✓ | |
| RWST Building Temp. (TT-101) | 71.5 °F | Outside Temp.: ~ 63 °F |
| (P-121) or P-122 | ✓ | 0.6 gpm / CV 55 % |
| RWST 2ndry Cont. High Level Switch | ✓ | (LSH-101) Last Test(monthly): 8-19-21 |
| RWST Back-Up Generator | ✓ | Last Test Run(monthly): 8-19-21 |

### B. CHEMICAL STORAGE BAYS

| Item | Status | Comments |
|---|---|---|
| Caustic Tote Levels | ✓ | ~ 315 Gallons Reserve = 4 totes |
| Caustic Bay Heater | ✓ | 56- warmest |
| Peroxide Tote Level | ✓ | ~ 330 Gallons Reserve = ~95 gal |
| HCL Tote Levels | ✓ | ~ 195 Gallons Reserve = ~55 gal |
| Chemical Totes and Piping Inspected | ✓ | Leaks observed: Y / (N) |
| Emergency Shower Inspected | ✓ | Checked and Flushed - All OK: (Y) / N |

### C. PRIMARY AND SECONDARY ACID FEED SYSTEM

| Item | Status | Comments |
|---|---|---|
| Primary Acid Feed Pump (P-631) | ✓ | |
| Ion Exchange Acid Feed Pump (P-632) | ✓ | PI-0632 PSI: 78-80 CV: 7 % |
| Primary Acid Retention Tank (T-510) | ✓ | |
| All Acid Feed Lines | ✓ | Leaks observed: Y / (N) |

### D. NBBW INJECTION TRENCH

| Item | Status | Comments |
|---|---|---|
| Injection Carbon (GAC-810) | OFFLINE | Date online: 7/20/18 |
| Injection Rate (FT-800) | 0.0 gpm | NBBW-IW-1= 0.0 NBBW-IW-2= 0.0 NBBW-IW-3= 0.0 gpm ea. |
| Totalizer Reading (FT-800) | 105,135,774 gal | INJ. STOPPED 10/02/18 @ 1545 |

# ABLE 3.19.1
# STANDARD OPERATIONS CHECKLIST
# MAIN WTP

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, September 02, 2021

**Inspection Performed by:** Mike Gelwick

### E. CHEMICAL PRECIPITATION SYSTEM (US FILTER HMR-30)

| Item | Status | Comment |
|---|---|---|
| T-300A Mixer | NA | |
| T-300B (Caustic Mixer) | ✓ | Last Cleaning (Qtrly): 6-3-21 |
| T-300A/B Water Level | ✓ | |
| T-300B (Caustic Mix Chamber) | ✓ | Last Cleaning (Qtrly): 6-3-21 |
| T-300A/B Overflow | ✓ | |
| pH Set-point for (pH 315) | Value: 10.9 | |
| pH 310 | Value: 6.98 | |
| pH 315 | Value: 10.82 | |
| Flocculation Chamber Paddle Wheel | ✓ | |
| Precipitate Floc Quality | ✓ | Good |
| Clarifier Water Quality | ✓ | Good Oil or sheen observed: Y / (N) |
| Clarifier Effluent Piping / Water Level | ✓ | |
| Clear-well Chamber and Water Level | ✓ | |
| HMR PLC Panel | ✓ | |
| Caustic Pump (P-270) | SB | |
| Caustic Pump (P-280) | ✓ | |
| Polymer Pump (P-310) | ✓ | |
| Polymer Tank Mixer | ✓ | |
| Polymer Tank Level | Gallons: ~ 400 | |
| Clear-well Transfer Pumps(P-371 /(372)) | ✓ | |
| Sludge Transfer Pump (P-330) | ✓ | Exercise Valves Weekly: Both or |
| Manual Sludge Lateral pumping | ✓ | Last done (As Needed): #3-7-2021/#1+2-3-2020 |
| Manual Sludge Lateral Ball Valves | ✓ | Exercise Weekly: Alloc |
| Automatic Blow-down Operations | ✓ | |

### F. pH PROBES

| pH Probe Location | Calibration Date | Comments: (Time done) |
|---|---|---|
| pH-310 HMR-30 (T-300A) | 9-2-21-Today | 1256 |
| pH-315 HMR-30 (T-300B) | | |
| pH-365 Primary Acid Ret. Tank | | |
| pH-113 Pre-Ion Exchange | | |
| pH-670 Pre-UV-OX | | 1326 |
| pH-740 Discharge Surge Tank | | Discharge suspended: 1245 ↔ 1255 |
| Out of Hold Double Check | ---------- | None in hold: ✓ ✓'d m |
| Valves Back to Normal Position | ---------- | All OK: ✓ ✓'d m |

### G. SLUDGE THICKENER, SLUDGE HOLDING TANKS, FILTER PRESS

| Item | Status | Comments |
|---|---|---|
| Verify Sludge Thickener Running | ✓ | Gauge Reading: 0 % |
| Sludge Thick. Transfer Pump (P-350) | ✓ | |
| Sludge Holding Tank (T-351) | ✓ | Level:~ 60 % |
| Sludge Holding Tank (T-352) | ✓ | Level: 36 % |
| Decant Transfer Pump (P-352) | SB | CV – % @ – gpm |
| Filter Press Pumps (P-381 / P-382) | ✓ | |
| Filter Press | ✓ | Stage: Running/Stage 4 |

# ABLE 3.19.1
# STANDARD OPERATIONS CHECKLIST
# MAIN WTP

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, September 02, 2021

**Inspection Performed by:** Mike Gelwick

### H. ION EXCHANGE

| Item | Status | Comments |
|---|---|---|
| Feed Tank (T-113) | ✓ Level: 56 % | |
| Feed Pump (P-114) | ✓ Operating Press: 63.8 psi | CV@ 95 % @ 3.7 gpm |
| Retention Tank (T-114) | ✓ Operating Press: 62 psi | pH-113 @ 3.81 |
| Bag Filter (BF-113) | ✓ Operating Press: 65 psi | |
| Ion Exchange (Cage (1) or 2) + Guard | ✓ Operating Press: 61 psi | TP-173A-2 → TP-175A/4 Canister + Guard |
| Post Ion Exchange | ✓ Operating Press: 4 psi | |

### I. FEED SURGE TANK

| Item | Status | Comments |
|---|---|---|
| Feed Surge Tank (T-520) | ✓ Level: 38 % | Last Cleaning (As Needed, if 4" of solids accumulate): 12/15/19 |
| Feed Surge Pump (P-521 or (P-522)) | Operating Press: 26 psi | CV@ 70 % @ 35.5 gpm |
| T-520 to GAC Total (FT-675) | 248757247 gal | Time: 0927 |
| North End On-Site Pumping | Operating Press: 23 ~~31~~ psi | 13.1 gpm @ 0852 |
| North End Off-Site Pumping | Operating Press: 26 ~~33~~ psi | 8.3 gpm @ 0852 |
| Peroxide Feed Pump (P-680) | ✓ | SPD 2.7 % / RATE 0.7 |
| Peroxide Conc. At (TP-710) | 1.0 PPM | |
| Peroxide Conc. At (TP-740) | 0.0 PPM | |

### J. HAZARDOUS WASTE STORAGE

| Item | Status | Comments |
|---|---|---|
| 180 Day storage area check | ✓ | Check sheet completed: NA/Empty |
| Satellite Haz. Waste Areas (BLDG #1) | ✓ | Condition: Good |
| Satellite Haz. Waste Area (BLDG #2) | ✓ | Condition: Good |

IX System Anionic Resin Satellite Container Area In Good Condition.

### K. UV-OXIDATION SYSTEM

| Item | Status | Comments |
|---|---|---|
| UV-Oxidation System | ✓ | |
| Annual Test Run (Calgon) | Date: 8-4-20 | Next: 9-2021 |
| Quarterly Test Run | Date: NA/Running | Next: NA/Running |
| Peroxide Feed Pump (P-650) | ✓ | Flow Rate: ~ 7.2 cc/min. |
| UV-Ox Power | ✓ | 25.7 kVA 2600 Volts 9.9 Amps |
| Lamp Hours | 827 Hrs | |
| Crystal Condition & Wiper Status | ✓ | Oiler status: OK - Refilled |
| UV-OX Bagfilters Status | Last change: 7-13-21 Cleaned: 7-13-21 | 12 psi In 12.5 psi Out |
| UV-OX Feed Pump ( (P-600) or P-601 ) | ✓ | CV@ 77 % @ 7.9 gpm |
| UV-OX Temperature | In(TT-670): 16.8 °C | Out(TT-710): 28.3 °C |
| PDU GAC (PDT-710) | ✓ | Δ Pressure: 4 psi |
| Peroxide Concentration Pre UV | 100 PPM | |
| Peroxide Concentration Post UV(TP-720) | 25 PPM | |
| Peroxide Conc. Post PDU (TP-730) | 0.0 PPM | |
| Secondary Acid Feed Pump (P-630) | ✓ | CV @ 0 % |
| Secondary Acid Retention Tank (T-645) | ✓ | |
| Pre – UV Oxidizer Total (FT-670) | 195295441 gal | Time: 0928 |
| Post UV-Ox / Pre PDU | ✓ | Pressure: 14 psi |
| Post PDU | ✓ | Pressure: 7.5 psi |

# ABLE 3.19.1
# STANDARD OPERATIONS CHECKLIST
# MAIN WTP

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, September 02, 2021

**Inspection Performed by:** Mike Gelwick

### L. PDU AND LIQUID –PHASE GRANULAR ACTIVATED CARBON

| Item | Status | Comments |
|---|---|---|
| PDT-720 | ✓ | Δ Pressure: 10 psi |
| PDT-730 | ✓ | Δ Pressure: 10 psi |

### M. EFFLUENT DISCHARGE

| Item | Status | Comments |
|---|---|---|
| Effluent Surge Pump ( P751 or (P752)) | ✓ | CV@ 63.8 % |
| Effluent Surge Tank (T-740) | ✓ | Level: 40 % |
| Effluent Discharge Rate (FT-770) | ✓ | 36.7 gpm @ 0924 |
| POTW Line Pressure (PT-770) | ✓ | 38.2 psi |
| Effluent Totalizer Reading (FT-770) | 242830444 gal | Time: 0928 |
| POTW MH17S-078 Discharge Check (Monthly) | ✓ | Last Done: 8-17-21 |
| 4X8-Inch POTW Leak Detection Checks (Monthly) | ✓ | Last Done: |
| 4X8-Inch POTW Air Reliefs Checks (Monthly) | ✓ | Last Done: |
| 4X8-Inch POTW Isolation Valves Exercise (Qtrly) | ✓ | Last Done: |
| 2-Inch POTW Backup Pressure Testing (Annual) | ✓ | Last Done: 7/8/21 |
| 2-In POTW Backup Air Reliefs Checks (Annual) | ✓ | Last Done: 7/8/21 |
| 2-Inch POTW Isolation Valve Exercise (Annual) | ✓ | Last Done: 7/8/21 |
| Rotate Chiller Compressors | NA on Standby | ~~Now in Lead: 1 or 2~~ |

### N. LEL EFFLUENT TANK T-740

| Item | Status | Comments |
|---|---|---|
| LEL-740 Sensor | ✓ | Reading: 0 % |
| LEL Sensor Calibration / Automatic High LEL Shutdown Test (monthly) | Last Completed: 8-26-21 | Plant Effluent Suspended: 1400 ↔ 1420 |
| LEL Sensor Bridge Adjustment to 2.0 volts | Reading: 2.001 volts(monthly) | Adjustment Needed: Y or (N) |
| Verify Bridge Current between.300v-.360v | Reading: 0.331 volts(monthly) | |

### O. WTP INFLUENT TOTALIZERS Time : 0929- 0934

| Source | Reading(Gallons) | Source | Reading(Gallons) |
|---|---|---|---|
| (FT-015) RWST Influent | 196082 82 | (FT-505) LFG Cond. to T-530 | 216105 |
| (FT-025) NBBW Influent | 93499761 | (FT-056) Off - Site N. End Influent | 425 39628 |
| (FT-012) MW-38 Inf. to HMR-30 | 8132117 | (FT-113) Ion Exchange Influent | 538148 |
| (FT-042 HMR30) MW-38 Source to HMR-30 | 35484 | (FT-810) Plant Potable Water In | 30055308 |
| (FT-043) MW-38 to RWST | 3069612 | (FT-026) NBBW Bypass to RWST | 4377701 |
| (FT-042 RWST) MW-38 Source to RWST | 72236 | (FT-014) Misc. Water to RWST | 8142638 |
| (FT-012T) MW-38 to T-540/541 | 8599830 | (FT-035) NTES Inf. to BIO | 6625137 |
| (FT-040T) MW-38N to T-540/541 | 1971172 | (FT-035T) NTES to T-530 | 459475 |
| (FT-041T) MW-38S to T-540/541 | 2695073 | (FT-017) BIO Inf. from T-530 | 649246 |
| (FT-042T) MW-38 Source to T-540/541 | ~~97120431~~ 3999573 | (FT-018) T-540/541 Influent | 8641473 |
| (FT-055) On - Site N. End Influent | 97120431 | (FT-352) T-352 to HMR-30 | 1269367 |

# ABLE 3.19.1
# STANDARD OPERATIONS CHECKLIST
# MAIN WTP

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, September 02, 2021

**Inspection Performed by:** Mike Gelwick

### P. AIR COMPRESSORS

| Item | Status | Comments |
|---|---|---|
| Compressor Intake Temp. | 65 °F (Analog Gauge) | Outside Temp.: ~ 67 °F |
| Compressor Building Vent | ✓ | Closed - operational |
| Primary Air Compressor (IRN30H) | 2,000 Hour service date: 7-8-21<br>Serviced @ 60952 Hours | Coolant present in sight glass: (Y) / N<br>Next service @ 62952 Hours<br>Current Hours @ 61681 |
| IRN30H Motor Speed | 31 % | |
| IRN30H Pressure | 117 psi | |
| IRN30H Moisture purge valve chk(Weekly): | ✓ | |
| IRN30H Intake Filter | ✓ | Date Last Changed: 8-12-21 |
| Air Tanks Moisture Purge Valves | Manually Activate(weekly) | Excessive Moisture: Y / (N) |
| Backup Air Compressors (T-30 East and West) | ✓ | Both cool to touch: (Y) / N |
| Air Dryer | ✓ Econ on | Moisture at Receiver Tank: Y / (N) |
| Oil Moisture Prevention (Monthly) | Last Done: 8-26-21 | Run at max speed by bleeding air from filter canister above/after air dryer for 2 hrs |
| Air Receiver Tank | ✓ | 108 psi |

### Q. SUMPS

| Item | Status | Comments |
|---|---|---|
| Bag Filter Sump | ✓ | |
| Wet Well Sump | ✓ | |

### R. GAS CHROMATOGRAPH

| Item | Status | Comments |
|---|---|---|
| GC Operational | ✓ | GC # checking UV-Ox Effluent: #2 |
| Alarms Enabled | ✓ | cc- calibration + maint 9-1-21 |
| GC Influent Filters | ✓ | |

### S. SAFETY

| Item | Status | Comments |
|---|---|---|
| Building #1 Fire Extinguishers | ✓ | Date inspected: 8-25-21 |
| Building #1 Eye Wash/Shower | ✓ | Checked and Flushed- All OK: (Y) / N |

**Other Comments:**

# TABLE 3.19.2
# STANDARD OPERATIONS CHECKLIST
# BIOLOGICAL TREATMENT SYSTEM

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, September 02, 2021

**Inspection Performed by:** Mike Gelwick

## A. PUMPS

| Item | Status | Flow Rate (gpm) | Pump Speed (CV%) | Discharge Pressure (psi) | | Comments |
|---|---|---|---|---|---|---|
| **T-510 Pumps** | | | | | | |
| P-3301 | ✓ | 1.81 | 27.9 % | 6.0 | | |
| P-3301A | SB | – | – % | – | | |
| **NTES Pump** P-002(Sump) / (P-002W(10R)) | ✓ | 0.49 | 49 % | P035 36-37 | P038 7.5 | Globules Observed at TP-130: Y / (N) Time: 0830 |
| **T-530** P-005 | ✓ | 0.20 | 37 % | 6.0 | | |
| **T-540/541** P-006 | ✓ | 0.30 | 51 % | 4.5 | | |
| **LFG COND Auto-Traps** | ✓ | 0.0 | NA | 4.75 | | Between Cycles: (Y) / N |
| **Reactor Feed Pumps** | | | | | | |
| P-3321 | ✓ | 2.52 | 63.2% | 7.0 | | |
| P-3322 | ✓ | 3.47 | 48.6 % | 5.0 | | |
| P-3323 | ✓ | 2.51 | 74.6 % | 5.0 | | |
| P-3324 | SB | – | – % | – | | |
| **Reactor Effluent Pumps** | | | | | | |
| P-3341 | ✓ | 3.51 | 55.3 % | 11.0 | | |
| P-3341A | SB | – | – % | – | | |

## B. BLOWERS

| Item | Status | Pressure (psi) | Temp (°F) | Next Scheduled Service (Qtrly) | Comments Last serviced on: 6-22-21 |
|---|---|---|---|---|---|
| B-3331 | ✓ | 4.26 | 152 | 9-2021 | Greased, Belt and Filter Checked: (Y) / N |
| B-3332 | SB | – | – | ↓ | Belt and Filter Checked: Y / (N) |
| B-3333 | ✓ | 4.38 | 152 | ↓ | Greased, Belt and Filter Checked: (Y) / N |
| B-3334 | ✓ | 4.26 | 152 | ↓ | Greased, Belt and Filter Checked: (Y) / N |

## C. REACTOR VENTILATION

| Item | Status | Comments |
|---|---|---|
| Vapor Carbon Contactor | ✓ | On-line: 2/10/18 |
| Reactor Vent Blower | ✓ | |
| Reactor Vent Booster | ✓ | |
| VTP-3350 | ✓ | PID Reading: 1.1 PPM |
| VTP-3360 | ✓ | PID Reading: 0.6 PPM |

# TABLE 3.19.2
# STANDARD OPERATIONS CHECKLIST
# BIOLOGICAL TREATMENT SYSTEM

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, September 02, 2021

**Inspection Performed by:** Mike Gelwick

## D. TANKS / REACTORS / SUMPS / CONTAINMENTS / PIPING / Chiller

| Item | Status | Comments |
|---|---|---|
| T-510 Post HMR-30 Mixing Tank | ✓ Level: 71 % | Last Cleaning (As needed, if 2" of solids accumulate): ~~12/15/19~~ 7-14-21 |
| T-530 LFG Condensate / NTES Tank | ✓ Level: 35 % | |
| T-530 Mixer | ✓ | |
| LFG Condensate Conveyance Line | ✓ | Last Pressure Test: 7-19-21 Next: 7-2022 (Annual at a minimum or if flow drops off) |
| T-540/541 MW38 Tanks | Lvls: 83 % & 84 % | |
| T-540/541 Mixers | ✓ | |
| Chiller Coolant level not visible thru sight glass. will fill at some point and check for leaks | | Chiller Coolant Lvl: ~ — " Below full mark |
| Chiller Cooling Fins (as needed) | ✓ | Last Cleaning: 4/20/18 (unit on Standby) |
| Secondary Containments | ✓ | Heat Trace: On OK / (Off Warm out) |
| Feed Piping to Sedimentation Tank | ✓ | Last Back Flushing (Quarterly): 8-30-31 |
| T-3310 Sedimentation Tank | Visual Level: OK | Last Cleaning (As Needed, use TSS info to determine): 12/2017 |
| T-3320 Blend Tank | ✓ Level: 70 % | Last Cleaning (Semi Annual): 5-7-20 |
| T-3331 Reactor No. 1 | ✓ | Digital Displays: (GOOD) / Needs Attn |
| T-3332 Reactor No. 2 | ✓ | Digital Displays: (GOOD) / Needs Attn |
| T-3333 Reactor No. 3 | ✓ | Digital Displays: (GOOD) / Needs Attn |
| T-3334 Settling Tank | ✓ | Last Cleaning (Semi Annual): 5-7-20 |
| P-3334 Biosolids Pump | ✓ | |
| T-3340 Overflow Tank | ✓ Level: 30 % | |
| Recycle Valve to Blend Tank | ✓ | 3.96 gpm @ 0957 |
| Building Containment Sump | ✓ | Last Alarm Test Date (Monthly): 8-19-21 |

## E. CHEMICAL FEED SYSTEM

| Item | Status | Comments |
|---|---|---|
| Phosphorous Supply | ✓ | Bags: 18 Gallons: ~ 85 |
| Phosphorous Pump (P-2221) | ✓ | |
| Caustic Supply | ✓ | ~170 Gallons |
| Caustic Pump (P-2211) | SB | Currently in acid addition mode |
| Acid Supply | ✓ | ~ 40 Gallons |
| Acid Pump (P-2211) | ✓ | |
| Caustic Pump (P-2231) | ✓ Leaks: Y / (N) | Last tubing tip cleaning (monthly): 8-19-21 |
| Caustic Pump (P-2232) | ✓ Leaks: Y / (N) | Last tubing tip cleaning (monthly): |
| Caustic Pump (P-2233) | ✓ Leaks: Y / (N) | Last tubing tip cleaning (monthly): |

# TABLE 3.19.2
# STANDARD OPERATIONS CHECKLIST
# BIOLOGICAL TREATMENT SYSTEM

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, September 02, 2021

**Inspection Performed by:** Mike Gelwick

## F. pH Probes

| pH Probe Location | Calibration Date (Monthly) | Comments |
|---|---|---|
| pH-3320 Blend Tank | 8-26-21 | Spray off Clean today |
| pH-3331 Reactor 1 | ↓ | ↓ |
| pH-3332 Reactor 2 | | |
| pH-3333 Reactor 3 | | |

## G. FILTER SYSTEM

| Item | Status | Comments |
|---|---|---|
| BF-3340 a/b Status | ✓ | |
| Automatic Backwash | Cycle Count: 32 | Reset |
| BF-3340 a/b Differential Pressure | PSI: 0 | 10/10 @ 2.0gpm |
| 75-micron Bags Last Cleaning | Date: 11-14-19 | |
| 75-micron Bags Last Inspection | Date: | |
| 75-micron Bags Last Changed | Date: ↓ | |
| GACF-3340 Status | ✓ | |
| GACF-3340 Differential Pressure | PSI: 4 | 10/6 @ 2.0gpm |
| Last Backwash Performed | Date: 8-26-21 | |

## H. ELECTRICAL AND INSTRUMENTATION

| Item | Status | Comments |
|---|---|---|
| "BIO" Backup Generator | ✓ | Block Heater: On OK / Off Warm Out |
| Electrical Surge Suppressor | ✓ | |
| Motor Control Center | ✓ | |
| PLC | ✓ | UPS @ 97 min / 75 Events |
| HMI's | ✓ | |
| BTS Process KWH Meter | 1792711 KWH | Time: 1110 |
| Building#2 KWH Meter | 5215623 KWH | Time: 1110 |

## I. GAS CHROMATOGRAPHY

| Item | Status | Comments |
|---|---|---|
| GC Operational | ✓ | GC # checking BIO: #3 |
| Alarms Enabled | ✓ | cc- calibration + making. 9-1-21 |
| GC Influent Filters | ✓ | |

# TABLE 3.19.2
# STANDARD OPERATIONS CHECKLIST
# BIOLOGICAL TREATMENT SYSTEM

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, September 02, 2021

**Inspection Performed by:** Mike Gelwick

## J. TOTALIZERS

| Item | Readings (gallons) | Comments |
|---|---|---|
| FT-3321 Feed to Reactor 1 | 5839656 | |
| FT-3324 Feed Spare | 87141 | |
| FT-3322 Feed to Reactor 2 | 10518713 | |
| FT-3323 Feed to Reactor 3 | 556571 | |
| FT-3301 T-510 to BIO | 51360459 | |
| FT-3341 BIO Effluent | 66111004 | |
| FT-3342 BIO Recycle | 55211382 | |

## K. SAFETY

| Item | Status | Comments |
|---|---|---|
| Building #2 Fire Extinguishers | ✓ | Inspection date: 8-25-21 |
| Building #2 Eye Wash/Shower | ✓ | Checked and Flushed- All OK: Ⓨ / N |

## L. OTHER COMMENTS:

| |
|---|
| |
| |
| |

# ABLE 3.19.1
# STANDARD OPERATIONS CHECKLIST
# MAIN WTP

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, September 09, 2021

**Inspection Performed by:** Mike Gelwick

## A. PERIMETER COLLECTION SYSTEMS

| Item | Status | Comments |
|---|---|---|
| LFG Cond Automatic Trap CT-1 | Sump Level: 13.65 oz | Counter: 181404 Cycles: 660 |
| LFG Cond Automatic Trap CT-2 | Sump Level: 8.60 oz | Counter: 274021 Cycles: 50 |
| LFG Cond Automatic Trap CT-3 | Sump Level: 7.55 oz | Counter: 303879 Cycles: 724 |
| CT-4 Containment/Vessel (LFG Cond) | ✓ Level: 70 % | Tank Level: 2.16 Counter: 191229 Cycles: 18 Sump: 9.19 oz |
| PM-15 Containment / Vessel | ✓ Level: ~~60%~~ 50% | |
| MW-51 Containment / Vessel | ✓ Level: 50 % | |
| PM-11 Containment / Vessel | ✓ Level: 45 % | |
| MW-38 Systems | ✓ | |
| North Toe System | ✓ | |
| North End Systems (Weekly) | ✓ | |
| Full N. End Systems Check (Monthly) | ✓ | Last Done: 8-27-21 |
| North End Pipeline(s)Flushing (As Needed) | ✓ | Perform if suspended solids present Last Done: 11/15/15 |
| NTES line flush to T-530 (As needed) | ✓ | Perform if suspended solids present Last Done: 2/13/20 |
| NTES Piping Containment | ✓ | Monthly Sump Level: dry @ 16.07' Date: 8-19-21 |
| North Boundary System P-001: | CV 75.2% @ 7.3 gpm | 41.94 Hz / 2.11 Amps. / vault psi @ 18/20 inches |
| T-101 & T-102 Containment / Tank | ✓ | Levels: 29 % & 27 % |
| Raw Water Storage Tanks Piping | ✓ | |
| RWST Building Temp. (TT-101) | 71.3 °F | Outside Temp.: ~ 69 °F |
| (P-121) or P-122 | ✓ | 0.6 gpm / CV 59 % |
| RWST 2ndry Cont. High Level Switch | ✓ | (LSH-101) Last Test(monthly): 8-19-21 |
| RWST Back-Up Generator | ✓ | Last Test Run(monthly): 8-19-21 |

## B. CHEMICAL STORAGE BAYS

| Item | Status | Comments |
|---|---|---|
| Caustic Tote Levels | ✓ | ~ 465 Gallons Reserve = 3 totes |
| Caustic Bay Heater | ✓ | SB-warmest |
| Peroxide Tote Level | ✓ | ~ 300 Gallons Reserve = ~95 gal |
| HCL Tote Levels | ✓ | ~ 165 Gallons Reserve = ~30 gal |
| Chemical Totes and Piping Inspected | ✓ | Leaks observed: Y / (N) |
| Emergency Shower Inspected | ✓ | Checked and Flushed - All OK: (Y) / N |

## C. PRIMARY AND SECONDARY ACID FEED SYSTEM

| Item | Status | Comments |
|---|---|---|
| Primary Acid Feed Pump (P-631) | ✓ | |
| Ion Exchange Acid Feed Pump (P-632) | ✓ | PI-0632 PSI: 78-80 CV: 7 % |
| Primary Acid Retention Tank (T-510) | ✓ | |
| All Acid Feed Lines | ✓ | Leaks observed: Y / (N) |

## D. NBBW INJECTION TRENCH

| Item | Status | Comments |
|---|---|---|
| Injection Carbon (GAC-810) | **OFFLINE** | Date online: 7/20/18 |
| Injection Rate (FT-800) | 0.0 gpm | NBBW-IW-1= 0.0 NBBW-IW-2= 0.0 NBBW-IW-3= 0.0 gpm ea. |
| Totalizer Reading (FT-800) | 105,135,774 gal | INJ. STOPPED 10/02/18 @ 1545 |

# ABLE 3.19.1
# STANDARD OPERATIONS CHECKLIST
# MAIN WTP

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, September 09, 2021

**Inspection Performed by:** Mike Gelwick

### E. CHEMICAL PRECIPITATION SYSTEM (US FILTER HMR-30)

| Item | Status | Comment |
|---|---|---|
| T-300A Mixer | NA | |
| T-300B (Caustic Mixer) | ✓ | Last Cleaning (Qtrly): 6-3-21 |
| T-300A/B Water Level | ✓ | |
| T-300B (Caustic Mix Chamber) | ✓ | Last Cleaning (Qtrly): 6-3-21 |
| T-300A/B Overflow | ✓ | |
| pH Set-point for (pH 315) | Value: 10.8 | |
| pH 310 | Value: 6.93 | |
| pH 315 | Value: 10.87 | |
| Flocculation Chamber Paddle Wheel | ✓ | |
| Precipitate Floc Quality | ✓ | Good |
| Clarifier Water Quality | ✓ | Good Oil or sheen observed: Y / (N) |
| Clarifier Effluent Piping / Water Level | ✓ | |
| Clear-well Chamber and Water Level | ✓ | |
| HMR PLC Panel | ✓ | |
| Caustic Pump (P-270) | SB | |
| Caustic Pump (P-280) | ✓ | |
| Polymer Pump (P-310) | ✓ | |
| Polymer Tank Mixer | ✓ | |
| Polymer Tank Level | Gallons: ~525 | |
| Clear-well Transfer Pumps (P-371 / 372) | ✓ | |
| Sludge Transfer Pump (P-330) | ✓ | Exercise Valves Weekly: Bottom |
| Manual Sludge Lateral pumping | ✓ | Last done (As Needed): 4-3-7-20-21 / 1-12-2-3-20-20 |
| Manual Sludge Lateral Ball Valves | ✓ | Exercise Weekly: Allow |
| Automatic Blow-down Operations | ✓ | |

### F. pH PROBES

| pH Probe Location | Calibration Date | Comments: (Time done) |
|---|---|---|
| pH-310 HMR-30 (T-300A) | 9-9-21 - today | 1311 |
| pH-315 HMR-30 (T-300B) | | |
| pH-365 Primary Acid Ret. Tank | | |
| pH-113 Pre-Ion Exchange | | |
| pH-670 Pre-UV-OX | | 1338 |
| pH-740 Discharge Surge Tank | | Discharge suspended: 1303 ↔ 1310 |
| Out of Hold Double Check | ---------- | None in hold: ✓ ✓ ✓ |
| Valves Back to Normal Position | ---------- | All OK: ✓ ✓ ✓ |

### G. SLUDGE THICKENER, SLUDGE HOLDING TANKS, FILTER PRESS

| Item | Status | Comments |
|---|---|---|
| Verify Sludge Thickener Running | ✓ | Gauge Reading: 0 % |
| Sludge Thick. Transfer Pump (P-350) | ✓ | |
| Sludge Holding Tank (T-351) | ✓ | Level: ~65 % |
| Sludge Holding Tank (T-352) | ✓ | Level: 42 % |
| Decant Transfer Pump (P-352) | ✓ | CV 55 % @ 0.4 gpm |
| Filter Press Pumps (P-381 / P-382) | ✓ | |
| Filter Press | ✓ | Stage: Empty |

# ABLE 3.19.1
# STANDARD OPERATIONS CHECKLIST
# MAIN WTP

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, September 09, 2021

**Inspection Performed by:** Mike Gelwick

### H. ION EXCHANGE

| Item | Status | Comments |
|---|---|---|
| Feed Tank (T-113) | ✓ Level: 45 % | |
| Feed Pump (P-114) | ✓ Operating Press: 63.5 psi | CV@ 99 % @ 3.7 gpm |
| Retention Tank (T-114) | ✓ Operating Press: 60 psi | pH-113 @ 3.56 |
| Bag Filter (BF-113) | ✓ Operating Press: 63 psi | |
| Ion Exchange (Cage (1) or 2) + Guard | ✓ Operating Press: 58 psi | TP-173A-2 + TP-175A / 4 canisters + Guard |
| Post Ion Exchange | ✓ Operating Press: 4 psi | |

### I. FEED SURGE TANK

| Item | Status | Comments |
|---|---|---|
| Feed Surge Tank (T-520) | ✓ Level: 39 % | Last Cleaning (As Needed, if 4" of solids accumulate): 12/15/19 |
| Feed Surge Pump (P-521 or P-522) | Operating Press: 31 psi | CV@ 83 % @ 36.7 gpm |
| T-520 to GAC Total (FT-675) | 249112428 gal | Time: 1040 |
| North End On-Site Pumping | Operating Press: 2-3 psi | 13.1 gpm @ 1022 |
| North End Off-Site Pumping | Operating Press: 2-6 psi | 8.6 gpm @ 1022 |
| Peroxide Feed Pump (P-680) | ✓ | SPD 2.8 % / RATE 0.7 |
| Peroxide Conc. At (TP-710) | 1.0 PPM | |
| Peroxide Conc. At (TP-740) | 0.0 PPM | |

### J. HAZARDOUS WASTE STORAGE

| Item | Status | Comments |
|---|---|---|
| 180 Day storage area check | ✓ | Check sheet completed: NA/Empty |
| Satellite Haz. Waste Areas (BLDG #1) | ✓ | Condition: both EX Areas + main Good |
| Satellite Haz. Waste Area (BLDG #2) | ✓ | Condition: Good |

### K. UV-OXIDATION SYSTEM

| Item | Status | Comments |
|---|---|---|
| UV-Oxidation System | ✓ | |
| Annual Test Run (Calgon) | Date: 8-4-20 | Next: 9-16-21 |
| Quarterly Test Run | Date: NA/Running | Next: NA/Running |
| Peroxide Feed Pump (P-650) | ✓ | Flow Rate: ~ 7.2 cc/min. |
| UV-Ox Power | ✓ | 25.7 kVA 2620 Volts 9.9 Amps |
| Lamp Hours | 994 Hrs | |
| Crystal Condition & Wiper Status | ✓ | Oiler status: ok |
| UV-OX Bagfilters Status | Last change: 7-13-21 Cleaned: 7-13-21 | 12.5 psi In 13.0 psi Out |
| UV-OX Feed Pump ( P-600 or P-601 ) | ✓ | CV@ 79 % @ gpm |
| UV-OX Temperature | In(TT-670): 16.6 °C | Out(TT-710): 28.3 °C |
| PDU GAC (PDT-710) | ✓ | Δ Pressure: 5 psi |
| Peroxide Concentration Pre UV | 100 PPM | |
| Peroxide Concentration Post UV(TP-720) | 25 PPM | |
| Peroxide Conc. Post PDU (TP-730) | 0.0 PPM | |
| Secondary Acid Feed Pump (P-630) | ✓ | CV @ 2 % |
| Secondary Acid Retention Tank (T-645) | ✓ | |
| Pre – UV Oxidizer Total (FT-670) | 1960750 gal | Time: 1040 |
| Post UV-Ox / Pre PDU | ✓ | Pressure: 14 psi |
| Post PDU | ✓ | Pressure: ~7.5 psi |

# ABLE 3.19.1
# STANDARD OPERATIONS CHECKLIST
# MAIN WTP

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, September 09, 2021

**Inspection Performed by:** Mike Gelwick

### L. PDU AND LIQUID –PHASE GRANULAR ACTIVATED CARBON

| Item | Status | Comments |
|---|---|---|
| PDT-720 | ✓ | Δ Pressure: 13 psi |
| PDT-730 | ✓ | Δ Pressure: 11 psi |

### M. EFFLUENT DISCHARGE

| Item | Status | Comments |
|---|---|---|
| Effluent Surge Pump ( P751 or (P752) | ✓ | CV@ 62.5 % |
| Effluent Surge Tank (T-740) | ✓ | Level: 40 % |
| Effluent Discharge Rate (FT-770) | ✓ | 37.5 gpm @ 1038 |
| POTW Line Pressure (PT-770) | ✓ | 37.5 psi |
| Effluent Totalizer Reading (FT-770) | 243193310 gal | Time: 1040 |
| POTW MH17S-078 Discharge Check (Monthly) | ✓ | Last Done: 8-17-21 |
| 4X8-Inch POTW Leak Detection Checks (Monthly) | ✓ | Last Done: |
| 4X8-Inch POTW Air Reliefs Checks (Monthly) | ✓ | Last Done: |
| 4X8-Inch POTW Isolation Valves Exercise (Qtrly) | ✓ | Last Done: |
| 2-Inch POTW Backup Pressure Testing (Annual) | ✓ | Last Done: 7/8/21 |
| 2-In POTW Backup Air Reliefs Checks (Annual) | ✓ | Last Done: 7/8/21 |
| 2-Inch POTW Isolation Valve Exercise (Annual) | ✓ | Last Done: 7/8/21 |
| Rotate Chiller Compressors | NA on Standby | ~~Now in Lead: 1 or 2~~ |

### N. LEL EFFLUENT TANK T-740

| Item | Status | Comments |
|---|---|---|
| LEL-740 Sensor | ✓ | Reading: 0 % |
| LEL Sensor Calibration / Automatic High LEL Shutdown Test (monthly) | Last Completed: 8-26-21 | Plant Effluent Suspended: 1400 ↔ 1420 |
| LEL Sensor Bridge Adjustment to 2.0 volts | Reading: 2.001 volts(monthly) | Adjustment Needed: Y or (N) |
| Verify Bridge Current between.300v-.360v | Reading: 0.331 volts(monthly) | |

### O. WTP INFLUENT TOTALIZERS Time : 1041-1045

| Source | Reading(Gallons) | Source | Reading(Gallons) |
|---|---|---|---|
| (FT-015) RWST Influent | 19614229 | (FT-505) LFG Cond. to T-530 | 216318 |
| (FT-025) NBBW Influent | 93569401 | (FT-056) Off - Site N. End Influent | 42620820 |
| (FT-012) MW-38 Inf. to HMR-30 | 8153403 | (FT-113) Ion Exchange Influent | 574421 |
| (FT-042 HMR30) MW-38 Source to HMR-30 | 35484 | (FT-810) Plant Potable Water In | 30055996 |
| (FT-043) MW-38 to RWST | 3070358 | (FT-026) NBBW Bypass to RWST | 4380453 |
| (FT-042 RWST) MW-38 Source to RWST | 72236 | (FT-014) Misc. Water to RWST | 8142654 |
| (FT-012T) MW-38 to T-540/541 | 8599830 | (FT-035) NTES Inf. to BIO | 6630033 |
| (FT-040T) MW-38N to T-540/541 | 1977172 | (FT-035T) NTES to T-530 | 459682 |
| (FT-041T) MW-38S to T-540/541 | 2695073 | (FT-017) BIO Inf. from T-530 | 649783 |
| (FT-042T) MW-38 Source to T-540/541 | 3999573 | (FT-018) T-540/541 Influent | 8644393 |
| (FT-055) On - Site N. End Influent | 97252105 | (FT-352) T-352 to HMR-30 | 1272134 |

# ABLE 3.19.1
# STANDARD OPERATIONS CHECKLIST
# MAIN WTP

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, September 09, 2021

**Inspection Performed by:** Mike Gelwick

### P. AIR COMPRESSORS

| Item | Status | Comments |
|---|---|---|
| Compressor Intake Temp. | 73 °F (Analog Gauge) | Outside Temp.: ~ 72 °F |
| Compressor Building Vent | ✓ | Closed - afternoon |
| Primary Air Compressor (IRN30H) | 2,000 Hour service date: 7-8-21<br>Serviced @ 60952 Hours | Coolant present in sight glass: Y / N<br>Next service @ 62952 Hours<br>Current Hours @ 61781 |
| IRN30H Motor Speed | 57 % | cc flashing fault |
| IRN30H Pressure | 110 psi | |
| IRN30H Moisture purge valve chk(Weekly): | ✓ | |
| IRN30H Intake Filter | ✓ | Date Last Changed: 8-12-21 |
| Air Tanks Moisture Purge Valves | Manually Activate(weekly) ✓ | Excessive Moisture: Y / N |
| Backup Air Compressors (T-30 East and West) | ✓ | Both cool to touch: Y / N |
| Air Dryer | ✓ Eco on | Moisture at Receiver Tank: Y / N |
| Oil Moisture Prevention (Monthly) | Last Done: 8-26-21 | Run at max speed by bleeding air from filter canister above/after air dryer for 2 hrs |
| Air Receiver Tank | ✓ | 110 psi |

### Q. SUMPS

| Item | Status | Comments |
|---|---|---|
| Bag Filter Sump | ✓ | |
| Wet Well Sump | ✓ | |

### R. GAS CHROMATOGRAPH

| Item | Status | Comments |
|---|---|---|
| GC Operational | ✓ | GC # checking UV-Ox Effluent: #2 |
| Alarms Enabled | Disabled currently | cc working on calibration & maint today |
| GC Influent Filters | ✓ | |

### S. SAFETY

| Item | Status | Comments |
|---|---|---|
| Building #1 Fire Extinguishers | ✓ | Date inspected: 8-25-21 |
| Building #1 Eye Wash/Shower | ✓ | Checked and Flushed- All OK: Y / N |

**Other Comments**:

# TABLE 3.19.2
# STANDARD OPERATIONS CHECKLIST
# BIOLOGICAL TREATMENT SYSTEM

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, September 09, 2021

**Inspection Performed by:** Mike Gelwick

## A. PUMPS

| Item | Status | Flow Rate (gpm) | Pump Speed (CV%) | Discharge Pressure (psi) | Comments |
|---|---|---|---|---|---|
| **T-510 Pumps** | | | | | |
| P-3301 | ✓ | 1.78 | 32.0 % | 6.0 | |
| P-3301A | SB | – | – % | – | |
| **NTES Pump** P-002(Sump) / (P-002W(10R)) | ✓ | 0.50 | 48 % | P035: 34.35 / P038: 8.0 | Globules Observed at TP-130: Y / (N) Time: 1000 |
| **T-530** P-005 | ✓ | 0.20 | 37 % | 6.0 | |
| **T-540/541** P-006 | ✓ | 0.30 | 57 % | 4.0 | |
| **LFG COND Auto-Traps** | ✓ | 0.0 | NA | 5.0 | Between Cycles: (Y) / N |
| **Reactor Feed Pumps** | | | | | |
| P-3321 | ✓ | 2.44 | 75.4 % | 10.5 | |
| P-3322 | ✓ | 3.41 | 55.2 % | 5.5 | |
| P-3323 | ✓ | 2.51 | 66.7 % | 5.0 | |
| P-3324 | SB | – | – % | – | |
| **Reactor Effluent Pumps** | | | | | |
| P-3341 | ✓ | 2.19 | 57.0% | 22.0 | |
| P-3341A | SB | – | – % | – | |

## B. BLOWERS

| Item | Status | Pressure (psi) | Temp (°F) | Next Scheduled Service (Qtrly) | Comments<br>Last serviced on: 6-22-21 |
|---|---|---|---|---|---|
| B-3331 | ✓ | 4.24 | 156 | 9-2021 | Greased, Belt and Filter Checked: (Y) / N |
| B-3332 | SB | – | – | ↓ | Belt and Filter Checked: Y / (N) |
| B-3333 | ✓ | 4.37 | 158 | ↓ | Greased, Belt and Filter Checked: (Y) / N |
| B-3334 | ✓ | 4.25 | 156 | ↓ | Greased, Belt and Filter Checked: (Y) / N |

## C. REACTOR VENTILATION

| Item | Status | Comments |
|---|---|---|
| Vapor Carbon Contactor | ✓ | On-line: 2/10/18 |
| Reactor Vent Blower | ✓ | |
| Reactor Vent Booster | ✓ | |
| VTP-3350 | ✓ | PID Reading: 2.1 PPM |
| VTP-3360 | ✓ | PID Reading: 1.0 PPM |

# TABLE 3.19.2
# STANDARD OPERATIONS CHECKLIST
# BIOLOGICAL TREATMENT SYSTEM

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, September 09, 2021

**Inspection Performed by:** Mike Gelwick

## D. TANKS / REACTORS / SUMPS / CONTAINMENTS / PIPING / Chiller

| Item | Status | Comments |
|---|---|---|
| T-510 Post HMR-30 Mixing Tank | ✓ Level: 68 % | Last Cleaning (As needed, if 2" of solids accumulate): 7/14/21 |
| T-530 LFG Condensate / NTES Tank | ✓ Level: 32 % | |
| T-530 Mixer | ✓ | |
| LFG Condensate Conveyance Line | ✓ | Last Pressure Test: 7-19-21 Next: 7-2022 (Annual at a minimum or if flow drops off) |
| T-540/541 MW38 Tanks | Lvls: 61 % & 62 % | |
| T-540/541 Mixers | ✓ | |
| Chiller | Coolant leaked into discharge tank thru coil | Chiller Coolant Lvl: ~ NA " Below full mark |
| Chiller Cooling Fins (as needed) | ✓ | Last Cleaning: 4/20/18 (unit on Standby) |
| Secondary Containments | ✓ | Heat Trace: On OK / (Off Warm out) |
| Feed Piping to Sedimentation Tank | ✓ | Last Back Flushing (Quarterly): 8-30-21 |
| T-3310 Sedimentation Tank | Visual Level: ok | Last Cleaning (As Needed, use TSS info to determine): 12/2017 |
| T-3320 Blend Tank | ✓ Level: 72 % | Last Cleaning (Semi Annual): 5-7-20 |
| T-3331 Reactor No. 1 | ✓ | Digital Displays: (GOOD) / Needs Attn |
| T-3332 Reactor No. 2 | ✓ | Digital Displays: (GOOD) / Needs Attn |
| T-3333 Reactor No. 3 | ✓ | Digital Displays: (GOOD) / Needs Attn |
| T-3334 Settling Tank | ✓ | Last Cleaning (Semi Annual): 5-7-20 |
| P-3334 Biosolids Pump | ✓ | |
| T-3340 Overflow Tank | ✓ Level: 32 % | |
| Recycle Valve to Blend Tank | ✓ | 4.25 gpm @ 1600 |
| Building Containment Sump | ✓ | Last Alarm Test Date (Monthly): 8-19-21 |

## E. CHEMICAL FEED SYSTEM

| Item | Status | Comments |
|---|---|---|
| Phosphorous Supply | ✓ | Bags: 17.75 Gallons: ~ 100 |
| Phosphorous Pump (P-2221) | ✓ | |
| Caustic Supply | ✓ | ~ 165 Gallons |
| Caustic Pump (P-2211) | SB | Currently in acid addition mode |
| Acid Supply | ✓ | ~ 40 Gallons |
| Acid Pump (P-2211) | ✓ | |
| Caustic Pump (P-2231) | ✓ Leaks: Y / (N) | Last tubing tip cleaning (monthly): 8-19-21 |
| Caustic Pump (P-2232) | ✓ Leaks: Y / (N) | Last tubing tip cleaning (monthly): ↓ |
| Caustic Pump (P-2233) | ✓ Leaks: Y / (N) | Last tubing tip cleaning (monthly): ↓ |

# TABLE 3.19.2
# STANDARD OPERATIONS CHECKLIST
# BIOLOGICAL TREATMENT SYSTEM

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, September 09, 2021

**Inspection Performed by:** Mike Gelwick

## F. pH Probes

| pH Probe Location | Calibration Date (Monthly) | Comments |
|---|---|---|
| pH-3320 Blend Tank | 8-26-21 | Spray off clean today |
| pH-3331 Reactor 1 | ↓ | ↓ |
| pH-3332 Reactor 2 | | |
| pH-3333 Reactor 3 | | |

## G. FILTER SYSTEM

| Item | Status | Comments |
|---|---|---|
| BF-3340 a/b Status | ✓ | |
| Automatic Backwash | Cycle Count: 37 | reset |
| BF-3340 a/b Differential Pressure | PSI: 4 | 20/16 @ 2.8 gpm |
| 75-micron Bags Last Cleaning | Date: 11-14-19 | |
| 75-micron Bags Last Inspection | Date: ↓ | |
| 75-micron Bags Last Changed | Date: | |
| GACF-3340 Status | ✓ | |
| GACF-3340 Differential Pressure | PSI: 9 | 15/6 @ 2.6 gpm |
| Last Backwash Performed | Date: 8-26-21 | |

## H. ELECTRICAL AND INSTRUMENTATION

| Item | Status | Comments |
|---|---|---|
| "BIO" Backup Generator | ✓ | Block Heater: On OK / ~~Off Warm Out~~ |
| Electrical Surge Suppressor | ✓ | |
| Motor Control Center | ✓ | |
| PLC | ✓ | UPS @ 97 min / 80 Events |
| HMI's | ✓ | |
| BTS Process KWH Meter | 1794577 KWH | Time: 1159 |
| Building#2 KWH Meter | 5218365 KWH | Time: 1159 |

## I. GAS CHROMATOGRAPHY

| Item | Status | Comments |
|---|---|---|
| GC Operational | ✓ | GC # checking BIO: #3 |
| Alarms Enabled | DISABled currently | CC working on Calibration + Maint today |
| GC Influent Filters | ✓ | |

# TABLE 3.19.2
# STANDARD OPERATIONS CHECKLIST
# BIOLOGICAL TREATMENT SYSTEM

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, September 09, 2021

**Inspection Performed by:** Mike Gelwick

## J. TOTALIZERS

| Item | Readings (gallons) | Comments |
|---|---|---|
| FT-3321 Feed to Reactor 1 | 5862424 | |
| FT-3324 Feed Spare | 87141 | |
| FT-3322 Feed to Reactor 2 | 10550340 | |
| FT-3323 Feed to Reactor 3 | 579011 | |
| FT-3301 T-510 to BIO | 51382607 | |
| FT-3341 BIO Effluent | 66141708 | |
| FT-3342 BIO Recycle | 55253310 | |

## K. SAFETY

| Item | Status | Comments |
|---|---|---|
| Building #2 Fire Extinguishers | ✓ | Inspection date: 8-25-21 |
| Building #2 Eye Wash/Shower | ✓ | Checked and Flushed- All OK: (Y) / N |

## L. OTHER COMMENTS:

| |
|---|
| |
| |
| |
| |

# ABLE 3.19.1
# STANDARD OPERATIONS CHECKLIST
# MAIN WTP

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, September 16, 2021

**Inspection Performed by:** Mike Gelwick

## A. PERIMETER COLLECTION SYSTEMS

| Item | Status | Comments |
|---|---|---|
| LFG Cond Automatic Trap CT-1 | Sump Level: 13.34 ok | Counter: 181754 Cycles: 350 |
| LFG Cond Automatic Trap CT-2 | Sump Level: 8.67 ok | Counter: 274034 Cycles: 13 |
| LFG Cond Automatic Trap CT-3 | Sump Level: 7.36 ok | Counter: 50304006 Cycles: 127 |
| CT-4 Containment/Vessel (LFG Cond) | ✓ Level: 68 % | Tank Level: 2.16 2.14 Counter: 191229 191235 Cycles: 10 6 Sump: 5.19 ok 9.000 ok |
| PM-15 Containment / Vessel | ✓ Level: 25 % | |
| MW-51 Containment / Vessel | ✓ Level: 30 % | |
| PM-11 Containment / Vessel | ✓ Level: 20 % | |
| MW-38 Systems | ✓ | |
| North Toe System | ✓ | |
| North End Systems (Weekly) | ✓ | |
| Full N. End Systems Check (Monthly) | ✓ | Last Done: 8-27-21 |
| North End Pipeline(s)Flushing (As Needed) | ✓ | Perform if suspended solids present Last Done: 11/15/15 |
| NTES line flush to T-530 (As needed) | ✓ | Perform if suspended solids present Last Done: 2/13/20 |
| NTES Piping Containment | ✓ | Monthly Sump Level: Dry = 16.07' Date: 8-19-21 |
| North Boundary System P-001: | CV 71.4 % @ 7.3 gpm | 39.13 Hz / 20.5 Amps. / vault psi @ 18/20 levels |
| T-101 & T-102 Containment / Tank | ✓ | Levels: 48 % & 47 % |
| Raw Water Storage Tanks Piping | ✓ | |
| RWST Building Temp. (TT-101) | 71.3 °F | Outside Temp.: ~ 71 °F |
| (P-121) or P-122 | ✓ | 2.5 gpm / CV 43 % |
| RWST 2ndry Cont. High Level Switch | ✓ | (LSH-101) Last Test(monthly): 8-19-21 |
| RWST Back-Up Generator | ✓ | Last Test Run(monthly): 8-19-21 |

## B. CHEMICAL STORAGE BAYS

| Item | Status | Comments |
|---|---|---|
| Caustic Tote Levels | ✓ | ~ 310 Gallons Reserve = 3 totes |
| Caustic Bay Heater | SB - winterized | |
| Peroxide Tote Level | ✓ | ~ 278 Gallons Reserve = ~95 gal |
| HCL Tote Levels | ✓ | ~ 125 Gallons Reserve = ~30 gal |
| Chemical Totes and Piping Inspected | ✓ | Leaks observed: Y / (N) |
| Emergency Shower Inspected | ✓ | Checked and Flushed - All OK: (Y) / N |

## C. PRIMARY AND SECONDARY ACID FEED SYSTEM

| Item | Status | Comments |
|---|---|---|
| Primary Acid Feed Pump (P-631) | ✓ | |
| Ion Exchange Acid Feed Pump (P-632) | ✓ | PI-0632 PSI: 78-80 CV: 6 % |
| Primary Acid Retention Tank (T-510) | ✓ | |
| All Acid Feed Lines | ✓ | Leaks observed: Y / (N) |

## D. NBBW INJECTION TRENCH

| Item | Status | Comments |
|---|---|---|
| Injection Carbon (GAC-810) | OFFLINE | Date online: 7/20/18 |
| Injection Rate (FT-800) | 0.0 gpm | NBBW-IW-1= 0.0 NBBW-IW-2= 0.0 NBBW-IW-3= 0.0 gpm ea. |
| Totalizer Reading (FT-800) | 105,135,774 gal | INJ. STOPPED 10/02/18 @ 1545 |

# ABLE 3.19.1
# STANDARD OPERATIONS CHECKLIST
# MAIN WTP

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, September 16, 2021

**Inspection Performed by:** Mike Gelwick

### E. CHEMICAL PRECIPITATION SYSTEM (US FILTER HMR-30)

| Item | Status | Comment |
|---|---|---|
| T-300A Mixer | NA | |
| T-300B (Caustic Mixer) | ✓ | Last Cleaning (Qtrly): 6-3-21 |
| T-300A/B Water Level | ✓ | |
| T-300B (Caustic Mix Chamber) | ✓ | Last Cleaning (Qtrly): 6-3-21 |
| T-300A/B Overflow | ✓ | |
| pH Set-point for (pH 315) | Value: 10.8 | |
| pH 310 | Value: 7.21 | |
| pH 315 | Value: 10.84 | |
| Flocculation Chamber Paddle Wheel | ✓ | |
| Precipitate Floc Quality | ✓ | Good |
| Clarifier Water Quality | ✓ | Good Oil or sheen observed: Y / (N) |
| Clarifier Effluent Piping / Water Level | ✓ | |
| Clear-well Chamber and Water Level | ✓ | |
| HMR PLC Panel | ✓ | |
| Caustic Pump (P-270) | SB | |
| Caustic Pump (P-280) | ✓ | |
| Polymer Pump (P-310) | ✓ | |
| Polymer Tank Mixer | ✓ | |
| Polymer Tank Level | Gallons: ~ 440 | |
| Clear-well Transfer Pumps (P-371 / 372) | ✓ | |
| Sludge Transfer Pump (P-330) | ✓ | Exercise Valves Weekly: Bottom |
| Manual Sludge Lateral pumping | ✓ | Last done (As Needed): #3-7-2021 / #2-3-20-20 |
| Manual Sludge Lateral Ball Valves | ✓ | Exercise Weekly: All on |
| Automatic Blow-down Operations | ✓ | |

### F. pH PROBES

| pH Probe Location | Calibration Date | Comments: (Time done) |
|---|---|---|
| pH-310 HMR-30 (T-300A) | 9-16-21-today | 1306 |
| pH-315 HMR-30 (T-300B) | | |
| pH-365 Primary Acid Ret. Tank | | |
| pH-113 Pre-Ion Exchange | | |
| pH-670 Pre-UV-OX | | 1335 |
| pH-740 Discharge Surge Tank | | Discharge suspended: 1257 ↔ 1305 |
| Out of Hold Double Check | | None in hold: ✓✓ 'd m |
| Valves Back to Normal Position | | All OK: ✓✓ 'd m |

### G. SLUDGE THICKENER, SLUDGE HOLDING TANKS, FILTER PRESS

| Item | Status | Comments |
|---|---|---|
| Verify Sludge Thickener Running | ✓ | Gauge Reading: 0 % |
| Sludge Thick. Transfer Pump (P-350) | ✓ | |
| Sludge Holding Tank (T-351) | ✓ | Level:~ 60 % |
| Sludge Holding Tank (T-352) | ✓ | Level: 47 % |
| Decant Transfer Pump (P-352) | SB | CV – % @ – gpm |
| Filter Press Pumps (P-381 / P-382) | ✓ | |
| Filter Press | ✓ | Stage: Full |

# ABLE 3.19.1
# STANDARD OPERATIONS CHECKLIST
# MAIN WTP

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, September 16, 2021

**Inspection Performed by:** Mike Gelwick

### H. ION EXCHANGE

| Item | Status | Comments |
|---|---|---|
| Feed Tank (T-113) | ✓ Level: 35 % | |
| Feed Pump (P-114) | ✓ Operating Press: 61.2 psi | CV@ 100 % @ 3.5 gpm |
| Retention Tank (T-114) | ✓ Operating Press: 69.5 psi | pH-113 @ 3.91 |
| Bag Filter (BF-113) | ✓ Operating Press: 62.5 psi | |
| Ion Exchange (Cage (1) or 2) + Guard | ✓ Operating Press: 53 psi | TP-173A-2 → TP-1754 / 4 Cartridges + Guard |
| Post Ion Exchange | ✓ Operating Press: 4 psi | |

### I. FEED SURGE TANK

| Item | Status | Comments |
|---|---|---|
| Feed Surge Tank (T-520) | Level: 34 % | Last Cleaning (As Needed, if 4" of solids accumulate): 12/15/19 |
| Feed Surge Pump (P-521 or P-522) | Operating Press: 61.7 24 psi | CV@ ~~100~~ 75 % @ ~~3.5~~ 28.0 gpm |
| T-520 to GAC Total (FT-675) | 249464144 gal | Time: 1013 |
| North End On-Site Pumping | Operating Press: 2-3 psi | 13.3 gpm @ 1009 |
| North End Off-Site Pumping | Operating Press: 2-6 psi | 8.3 gpm @ 1009 |
| Peroxide Feed Pump (P-680) | ✓ | SPD 2.1 % / RATE 0.6 |
| Peroxide Conc. At (TP-710) | 1.0 PPM | |
| Peroxide Conc. At (TP-740) | 0.0 PPM | |

### J. HAZARDOUS WASTE STORAGE

| Item | Status | Comments |
|---|---|---|
| 180 Day storage area check | ✓ | Check sheet completed: NA/Empty |
| Satellite Haz. Waste Areas (BLDG #1) | ✓ | Condition: Both Ex Resin + main Good |
| Satellite Haz. Waste Area (BLDG #2) | ✓ | Condition: Good |

### K. UV-OXIDATION SYSTEM

| Item | Status | Comments |
|---|---|---|
| UV-Oxidation System | ✓ SB | * Currently Getting Serviced * |
| Annual Test Run (Calgon) | Date: 9-16-21 - today | Next: 9-2022 |
| Quarterly Test Run | Date: NA | Next: NA |
| Peroxide Feed Pump (P-650) | SB | Flow Rate: ~ - cc/min. |
| UV-Ox Power | – | – kVA – Volts – Amps |
| Lamp Hours | 1158 Hrs | |
| Crystal Condition & Wiper Status | ✓ | Oiler status: OK |
| UV-OX Bagfilters Status | Last change: 7-13-21 Cleaned: 7-13-21 | — psi In – psi Out |
| UV-OX Feed Pump ( P-600 or P-601 ) | SB | CV@ – % @ – gpm |
| UV-OX Temperature | In(TT-670): – °C | Out(TT-710): – °C |
| PDU GAC (PDT-710) | Backwashed, Retayed/Rumbled, etc. | Δ Pressure: – psi |
| Peroxide Concentration Pre UV | – PPM | |
| Peroxide Concentration Post UV(TP-720) | – PPM | |
| Peroxide Conc. Post PDU (TP-730) | – PPM | |
| Secondary Acid Feed Pump (P-630) | SB | CV @ – % |
| Secondary Acid Retention Tank (T-645) | ✓ | |
| Pre – UV Oxidizer Total (FT-670) | 19685590 gal | Time: 1013 |
| Post UV-Ox / Pre PDU | – | Pressure: – psi |
| Post PDU | – | Pressure: – psi |

# ABLE 3.19.1
# STANDARD OPERATIONS CHECKLIST
# MAIN WTP

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, September 16, 2021

**Inspection Performed by:** Mike Gelwick

### L. PDU AND LIQUID –PHASE GRANULAR ACTIVATED CARBON

| Item | Status | Comments |
|---|---|---|
| PDT-720 | ✓ | Δ Pressure: 12 psi |
| PDT-730 | ✓ | Δ Pressure: 8 psi |

### M. EFFLUENT DISCHARGE

| Item | Status | Comments |
|---|---|---|
| Effluent Surge Pump (P751) or P752 ) | ✓ | CV@ 57.7 % |
| Effluent Surge Tank (T-740) | ✓ | Level: 40 % |
| Effluent Discharge Rate (FT-770) | ✓ | 286 gpm @ 1011 |
| POTW Line Pressure (PT-770) | ✓ | 33.6 psi |
| Effluent Totalizer Reading (FT-770) | 243554382 gal | Time: 1013 |
| POTW MH17S-078 Discharge Check (Monthly) | ✓ | Last Done: 8-17-21 |
| 4X8-Inch POTW Leak Detection Checks (Monthly) | ✓ | Last Done: |
| 4X8-Inch POTW Air Reliefs Checks (Monthly) | ✓ | Last Done: |
| 4X8-Inch POTW Isolation Valves Exercise (Qtrly) | ✓ | Last Done: 7-19-21 |
| 2-Inch POTW Backup Pressure Testing (Annual) | ✓ | Last Done: 7/8/21 |
| 2-In POTW Backup Air Reliefs Checks (Annual) | ✓ | Last Done: 7/8/21 |
| 2-Inch POTW Isolation Valve Exercise (Annual) | ✓ | Last Done: 7/8/21 |
| Rotate Chiller Compressors | NA on Standby | ~~Now in Lead: 1 or 2~~ |

### N. LEL EFFLUENT TANK T-740

| Item | Status | Comments |
|---|---|---|
| LEL-740 Sensor | ✓ | Reading: 0 % |
| LEL Sensor Calibration / Automatic High LEL Shutdown Test (monthly) | Last Completed: 8-26-21 | Plant Effluent Suspended: 1400 ↔ 1420 |
| LEL Sensor Bridge Adjustment to 2.0 volts | Reading: 2.001 volts(monthly) | Adjustment Needed: Y or (N) |
| Verify Bridge Current between.300v-.360v | Reading: 0.331 volts(monthly) | |

### O. WTP INFLUENT TOTALIZERS Time : 1014-1017

| Source | Reading(Gallons) | Source | Reading(Gallons) |
|---|---|---|---|
| (FT-015) RWST Influent | 19621097 | (FT-505) LFG Cond. to T-530 | 216459 |
| (FT-025) NBBW Influent | 93639012 | (FT-056) Off - Site N. End Influent | 42702416 |
| (FT-012) MW-38 Inf. to HMR-30 | 8172939 | (FT-113) Ion Exchange Influent | 609376 |
| (FT-042 HMR30) MW-38 Source to HMR-30 | 35484 | (FT-810) Plant Potable Water In | 30057890 |
| (FT-043) MW-38 to RWST | 3071283 | (FT-026) NBBW Bypass to RWST | 4384148 |
| (FT-042 RWST) MW-38 Source to RWST | 72236 | (FT-014) Misc. Water to RWST | 8153383 |
| (FT-012T) MW-38 to T-540/541 | 8599830 | (FT-035) NTES Inf. to BIO | 6634837 |
| (FT-040T) MW-38N to T-540/541 | 1977172 | (FT-035T) NTES to T-530 | 459966 |
| (FT-041T) MW-38S to T-540/541 | 2695073 | (FT-017) BIO Inf. from T-530 | 650312 |
| (FT-042T) MW-38 Source to T-540/541 | 3999573 | (FT-018) T-540/541 Influent | 8647240 |
| (FT-055) On - Site N. End Influent | 97382212 | (FT-352) T-352 to HMR-30 | 1276916 |

# ABLE 3.19.1
# STANDARD OPERATIONS CHECKLIST
# MAIN WTP

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, September 16, 2021

**Inspection Performed by:** Mike Gelwick

### P. AIR COMPRESSORS

| Item | Status | Comments |
|---|---|---|
| Compressor Intake Temp. | 72 °F (Analog Gauge) | Outside Temp.: ~ 75 °F |
| Compressor Building Vent | ✓ | open - observed |
| Primary Air Compressor (IRN30H) | 2,000 Hour service date: 7-8-21 Serviced @ 60952 Hours | Coolant present in sight glass: Ⓨ / N Next service @ 62952 Hours Current Hours @ 61888 |
| IRN30H Motor Speed | 31 % | |
| IRN30H Pressure | 110 psi | |
| IRN30H Moisture purge valve chk(Weekly): | ✓ | |
| IRN30H Intake Filter | ✓ | Date Last Changed: 8-12-21 |
| Air Tanks Moisture Purge Valves | Manually Activate(weekly) ✓ | Excessive Moisture: Y / Ⓝ |
| Backup Air Compressors (T-30 East and West) | ✓ | Both cool to touch: Ⓨ / N |
| Air Dryer | ✓ Eco on | Moisture at Receiver Tank: Y / Ⓝ |
| Oil Moisture Prevention (Monthly) | Last Done: 8-26-21 | Run at max speed by bleeding air from filter canister above/after air dryer for 2 hrs |
| Air Receiver Tank | ✓ | 110 psi |

### Q. SUMPS

| Item | Status | Comments |
|---|---|---|
| Bag Filter Sump | ✓ | |
| Wet Well Sump | ✓ | |

### R. GAS CHROMATOGRAPH

| Item | Status | Comments |
|---|---|---|
| GC Operational | ✓ | GC # checking UV-Ox Effluent: #2 |
| Alarms Enabled | ✓ | cc- calibration + maint 9-15-21 |
| GC Influent Filters | ✓ | |

### S. SAFETY

| Item | Status | Comments |
|---|---|---|
| Building #1 Fire Extinguishers | ✓ | Date inspected: 8-25-21 |
| Building #1 Eye Wash/Shower | ✓ | Checked and Flushed- All OK: Ⓨ / N |

**Other Comments:**

| |
|---|
| * UVOX Getting serviced today during checks. |
| |
| |
| |
| |

# TABLE 3.19.2
# STANDARD OPERATIONS CHECKLIST
# BIOLOGICAL TREATMENT SYSTEM

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, September 16, 2021

**Inspection Performed by:** Mike Gelwick

## A. PUMPS

| Item | Status | Flow Rate (gpm) | Pump Speed (CV%) | Discharge Pressure (psi) | Comments |
|---|---|---|---|---|---|
| **T-510 Pumps** | | | | | |
| P-3301 | ✓ | 2.86 | 37.1 % | 8.0 | |
| P-3301A | SB | – | – % | – | |
| **NTES Pump** P-002(Sump) / (P-002W(10R)) | ✓ | 0.52 | 48 % | P035 35-36 / P038 80 | Globules Observed at TP-130: Y / (N) Time: 0940 |
| **T-530** P-005 | ✓ | 0.20 | 39 % | 6 | |
| **T-540/541** P-006 | ✓ | 0.31 | 59 % | 4.5 | |
| **LFG COND Auto-Traps** | ✓ | 0.0 | NA | 5 | Between Cycles: (Y) / N |
| **Reactor Feed Pumps** | | | | | |
| P-3321 | ✓ | 2.40 | 54.9 % | 5.5 | |
| P-3322 | ✓ | 3.27 | 48.7 % | 5.0 | |
| P-3323 | ✓ | 2.40 | 72.1 % | 6.0 | |
| P-3324 | SB | – | – % | – | |
| **Reactor Effluent Pumps** | | | | | |
| P-3341 | ✓ | 3.53 | 73.5 % | 27.0 | |
| P-3341A | SB | – | – % | – | |

## B. BLOWERS

| Item | Status | Pressure (psi) | Temp (°F) | Next Scheduled Service (Qtrly) | Comments Last serviced on: 6-22-21 |
|---|---|---|---|---|---|
| B-3331 | ✓ | 4.23 | 152 | SOON | Greased, Belt and Filter Checked: (Y) / N |
| B-3332 | SB | – | – | ↓ | Belt and Filter Checked: Y / (N) |
| B-3333 | ✓ | 4.35 | 154 | ↓ | Greased, Belt and Filter Checked: (Y) / N |
| B-3334 | ✓ | 4.25 | 152 | ↓ | Greased, Belt and Filter Checked: (Y) / N |

## C. REACTOR VENTILATION

| Item | Status | Comments |
|---|---|---|
| Vapor Carbon Contactor | ✓ | On-line: 2/10/18 |
| Reactor Vent Blower | ✓ | |
| Reactor Vent Booster | ✓ | |
| VTP-3350 | ✓ | PID Reading: 1.8 PPM |
| VTP-3360 | ✓ | PID Reading: 0.6 PPM |

# TABLE 3.19.2
# STANDARD OPERATIONS CHECKLIST
# BIOLOGICAL TREATMENT SYSTEM

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, September 16, 2021

**Inspection Performed by:** Mike Gelwick

## D. TANKS / REACTORS / SUMPS / CONTAINMENTS / PIPING / Chiller

| Item | Status | Comments |
|---|---|---|
| T-510 Post HMR-30 Mixing Tank | ✓ Level: 70 % | Last Cleaning (As needed, if 2" of solids accumulate): 7/14/21 |
| T-530 LFG Condensate / NTES Tank | ✓ Level: 30 % | |
| T-530 Mixer | ✓ | |
| LFG Condensate Conveyance Line | ✓ | Last Pressure Test: 7-19-21 Next: 7-2022 (Annual at a minimum or if flow drops off) |
| T-540/541 MW38 Tanks | Lvls: 39 % & 40 % | |
| T-540/541 Mixers | ✓ | |
| Chiller | ✓ | Chiller Coolant Lvl: ~ — " Below full mark |
| Chiller Cooling Fins (as needed) | ✓ | Last Cleaning: 4/20/18 (unit on Standby) |
| Secondary Containments | ✓ | Heat Trace: On OK / (Off Warm out) |
| Feed Piping to Sedimentation Tank | ✓ | Last Back Flushing (Quarterly): 8-30-31 |
| T-3310 Sedimentation Tank | Visual Level: ok | Last Cleaning (As Needed, use TSS info to determine): ~~12/2017~~ 9-10-21 |
| T-3320 Blend Tank | ✓ Level: 71 % | Last Cleaning (Semi Annual): 9-10-21 |
| T-3331 Reactor No. 1 | ✓ | Digital Displays: (GOOD) / Needs Attn |
| T-3332 Reactor No. 2 | ✓ | Digital Displays: (GOOD) / Needs Attn |
| T-3333 Reactor No. 3 | ✓ | Digital Displays: (GOOD) / Needs Attn |
| T-3334 Settling Tank | ✓ | Last Cleaning (Semi Annual): 9-10-21 |
| P-3334 Biosolids Pump | ✓ | |
| T-3340 Overflow Tank | ✓ Level: 30 % | Cleaned - 9-10-21 |
| Recycle Valve to Blend Tank | ✓ | 3.99 gpm @ 10:39 |
| Building Containment Sump | ✓ | Last Alarm Test Date (Monthly): 8-19-21 |

## E. CHEMICAL FEED SYSTEM

| Item | Status | Comments |
|---|---|---|
| Phosphorous Supply | ✓ | Bags: 17.5 Gallons: ~ 60 |
| Phosphorous Pump (P-2221) | ✓ | |
| Caustic Supply | ✓ | ~ 155 Gallons |
| Caustic Pump (P-2211) | SB | Currently in acid addition mode |
| Acid Supply | ✓ | ~ 40 Gallons |
| Acid Pump (P-2211) | ✓ | |
| Caustic Pump (P-2231) | ✓ Leaks: Y / (N) | Last tubing tip cleaning (monthly): 8-19-21 |
| Caustic Pump (P-2232) | ✓ Leaks: Y / (N) | Last tubing tip cleaning (monthly): |
| Caustic Pump (P-2233) | ✓ Leaks: Y / (N) | Last tubing tip cleaning (monthly): |

# TABLE 3.19.2
# STANDARD OPERATIONS CHECKLIST
# BIOLOGICAL TREATMENT SYSTEM

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, September 16, 2021

**Inspection Performed by:** Mike Gelwick

### F. pH Probes

| pH Probe Location | Calibration Date (Monthly) | Comments |
|---|---|---|
| pH-3320 Blend Tank | 8-26-21 | Spray off clean today |
| pH-3331 Reactor 1 | ↓ | ↓ |
| pH-3332 Reactor 2 | | |
| pH-3333 Reactor 3 | | |

### G. FILTER SYSTEM

| Item | Status | Comments |
|---|---|---|
| BF-3340 a/b Status | ✓ | |
| Automatic Backwash | Cycle Count: 32 | Reset |
| BF-3340 a/b Differential Pressure | PSI: 0 | 9/9 = 2.2 gpm |
| 75-micron Bags Last Cleaning | Date: 11-14-19 | |
| 75-micron Bags Last Inspection | Date: | |
| 75-micron Bags Last Changed | Date: | |
| GACF-3340 Status | ✓ | |
| GACF-3340 Differential Pressure | PSI: 3 | 9/6 = 2.2 gpm |
| Last Backwash Performed | Date: 8-26-21 | |

### H. ELECTRICAL AND INSTRUMENTATION

| Item | Status | Comments |
|---|---|---|
| "BIO" Backup Generator | ✓ | Block Heater: On OK / Off Warm Out |
| Electrical Surge Suppressor | ✓ | |
| Motor Control Center | ✓ | |
| PLC | ✓ | UPS @ 97 min / 84 Events |
| HMI's | ✓ | |
| BTS Process KWH Meter | 1796456 KWH | Time: 1109 |
| Building#2 KWH Meter | 5221118 KWH | Time: 1109 |

### I. GAS CHROMATOGRAPHY

| Item | Status | Comments |
|---|---|---|
| GC Operational | ✓ | GC # checking BIO: #3 |
| Alarms Enabled | ✓ | CC-calibration + maint 9-15-21 |
| GC Influent Filters | ✓ | |

## TABLE 3.19.2
## STANDARD OPERATIONS CHECKLIST
## BIOLOGICAL TREATMENT SYSTEM

**WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST**

**Inspection Date:** Thursday, September 16, 2021

**Inspection Performed by:** Mike Gelwick

### J. TOTALIZERS

| Item | Readings (gallons) | Comments |
|---|---|---|
| FT-3321 Feed to Reactor 1 | 5885085 | |
| FT-3324 Feed Spare | 87149 | |
| FT-3322 Feed to Reactor 2 | 10581808 | |
| FT-3323 Feed to Reactor 3 | 601358 | |
| FT-3301 T-510 to BIO | 51406487 | |
| FT-3341 BIO Effluent | 66172585 | |
| FT-3342 BIO Recycle | 55294085 | |

### K. SAFETY

| Item | Status | Comments |
|---|---|---|
| Building #2 Fire Extinguishers | ✓ | Inspection date: 8-25-21 |
| Building #2 Eye Wash/Shower | ✓ | Checked and Flushed- All OK: (Y) / N |

### L. OTHER COMMENTS:

| |
|---|
| |
| |
| |
| |

# ABLE 3.19.1
# STANDARD OPERATIONS CHECKLIST
# MAIN WTP

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, September 23, 2021

**Inspection Performed by:** Mike Gelwick

## A. PERIMETER COLLECTION SYSTEMS

| Item | Status | Comments |
|---|---|---|
| LFG Cond Automatic Trap CT-1 | Sump Level: 13.35 ok | Counter: 182519 Cycles: 764 |
| LFG Cond Automatic Trap CT-2 | Sump Level: 8.50 ok | Counter: 2274127 Cycles: 93 |
| LFG Cond Automatic Trap CT-3 | Sump Level: 7.40 ok | Counter: 304811 Cycles: 805 |
| CT-4 Containment/Vessel (LFG Cond) | ✓ Level: 68 % | Tank Level: 2.13 Counter: 191242 Cycles: 7 Sump: 8.99 ok |
| PM-15 Containment / Vessel | ✓ Level: 50 % | |
| MW-51 Containment / Vessel | ✓ Level: 60 % | |
| PM-11 Containment / Vessel | ✓ Level: 55 % | |
| MW-38 Systems | ✓ | |
| North Toe System | ✓ | |
| North End Systems (Weekly) | ✓ | |
| Full N. End Systems Check (Monthly) | ✓ | Last Done: 8-27-21 |
| North End Pipeline(s)Flushing (As Needed) | ✓ | Perform if suspended solids present Last Done: 11/15/15 |
| NTES line flush to T-530 (As needed) | ✓ | Perform if suspended solids present Last Done: 2/13/20 |
| NTES Piping Containment | ✓ | Monthly Sump Level: Dry 216.07' Date: 9-23-21 - Today |
| North Boundary System P-001: | CV 74.7 % @ 7.1 gpm | 39.88 Hz / 2.05 Amps. / vault psi @ 18/NBBW/carbs |
| T-101 & T-102 Containment / Tank | ✓ | Levels: 34 % & 32 % |
| Raw Water Storage Tanks Piping | ✓ | |
| RWST Building Temp. (TT-101) | 65.6 °F | Outside Temp.: ~ 64 °F |
| (P-121) or P-122 | ✓ | 0.6 gpm / CV 54 % |
| RWST 2ndry Cont. High Level Switch | ✓ | (LSH-101) Last Test(monthly): 9-23-21 - Today |
| RWST Back-Up Generator | ✓ | Last Test Run(monthly): 9-23-21 - Today |

## B. CHEMICAL STORAGE BAYS

| Item | Status | Comments |
|---|---|---|
| Caustic Tote Levels | ✓ | ~ 450 Gallons Reserve = 2 totes |
| Caustic Bay Heater | ✓ | Running during tote change out on 9-20-21 ok |
| Peroxide Tote Level | ✓ | ~ 290 Gallons Reserve = ~55 gal |
| HCL Tote Levels | ✓ | ~ 110 Gallons Reserve = ~30 gal |
| Chemical Totes and Piping Inspected | ✓ | Leaks observed: Y / (N) |
| Emergency Shower Inspected | ✓ | Checked and Flushed - All OK: (Y) / N |

## C. PRIMARY AND SECONDARY ACID FEED SYSTEM

| Item | Status | Comments |
|---|---|---|
| Primary Acid Feed Pump (P-631) | ✓ | |
| Ion Exchange Acid Feed Pump (P-632) | ✓ | PI-0632 PSI: 78-80 CV: 6 % |
| Primary Acid Retention Tank (T-510) | ✓ | |
| All Acid Feed Lines | ✓ | Leaks observed: Y / (N) |

## D. NBBW INJECTION TRENCH

| Item | Status | Comments |
|---|---|---|
| Injection Carbon (GAC-810) | OFFLINE | Date online: 7/20/18 |
| Injection Rate (FT-800) | 0.0 gpm | NBBW-IW-1= 0.0 NBBW-IW-2= 0.0 NBBW-IW-3= 0.0 gpm ea. |
| Totalizer Reading (FT-800) | 105,135,774 gal | INJ. STOPPED 10/02/18 @ 1545 |

# ABLE 3.19.1
# STANDARD OPERATIONS CHECKLIST
# MAIN WTP

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, September 23, 2021

**Inspection Performed by:** Mike Gelwick

## E. CHEMICAL PRECIPITATION SYSTEM (US FILTER HMR-30)

| Item | Status | Comment |
|---|---|---|
| T-300A Mixer | NA | |
| T-300B (Caustic Mixer) | ✓ | Last Cleaning (Qtrly): 6-3-21 |
| T-300A/B Water Level | ✓ | |
| T-300B (Caustic Mix Chamber) | ✓ | Last Cleaning (Qtrly): 6-3-21 |
| T-300A/B Overflow | ✓ | |
| pH Set-point for (pH 315) | Value: 10.8 | |
| pH 310 | Value: 6.64 | |
| pH 315 | Value: 10.89 | |
| Flocculation Chamber Paddle Wheel | ✓ | |
| Precipitate Floc Quality | ✓ | Good |
| Clarifier Water Quality | ✓ | Good Oil or sheen observed: Y / (N) |
| Clarifier Effluent Piping / Water Level | ✓ | |
| Clear-well Chamber and Water Level | ✓ | |
| HMR PLC Panel | ✓ | |
| Caustic Pump (P-270) | SB | |
| Caustic Pump (P-280) | ✓ | |
| Polymer Pump (P-310) | ✓ | |
| Polymer Tank Mixer | ✓ | |
| Polymer Tank Level | Gallons: ~ 550 | JUST REFILLED |
| Clear-well Transfer Pumps (P-371 / 372) | ✓ | |
| Sludge Transfer Pump (P-330) | ✓ | Exercise Valves Weekly: Both ok |
| Manual Sludge Lateral pumping | ✓ | Last done (As Needed): #3-7-2021 / #2 3-20-20 |
| Manual Sludge Lateral Ball Valves | ✓ | Exercise Weekly: All ok |
| Automatic Blow-down Operations | ✓ | |

## F. pH PROBES

* NOTE: Power off during calibrations *

| pH Probe Location | Calibration Date | Comments: (Time done) |
|---|---|---|
| pH-310 HMR-30 (T-300A) | 9-23-21 - Today | 1358 |
| pH-315 HMR-30 (T-300B) | | |
| pH-365 Primary Acid Ret. Tank | | |
| pH-113 Pre-Ion Exchange | | |
| pH-670 Pre-UV-OX | | 1455 |
| pH-740 Discharge Surge Tank | | Discharge suspended: OFF 1350 ↔ OFF 1357 |
| Out of Hold Double Check | ---------- | None in hold: ✓ ✓ M |
| Valves Back to Normal Position | ---------- | All OK: ✓ ✓ M |

## G. SLUDGE THICKENER, SLUDGE HOLDING TANKS, FILTER PRESS

| Item | Status | Comments |
|---|---|---|
| Verify Sludge Thickener Running | ✓ | Gauge Reading: 0 % |
| Sludge Thick. Transfer Pump (P-350) | ✓ | |
| Sludge Holding Tank (T-351) | ✓ | Level: ~ 50 % |
| Sludge Holding Tank (T-352) | ✓ | Level: 41 % |
| Decant Transfer Pump (P-352) | ✓ | CV 59 % @ 0.6 gpm |
| Filter Press Pumps (P-381 / P-382) | ✓ | |
| Filter Press | ✓ | Stage: Full |

# ABLE 3.19.1
# STANDARD OPERATIONS CHECKLIST
# MAIN WTP

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, September 23, 2021

**Inspection Performed by:** Mike Gelwick

### H. ION EXCHANGE

| Item | Status | Comments |
|---|---|---|
| Feed Tank (T-113) | ✓ Level: 47 % | |
| Feed Pump (P-114) | ✓ Operating Press: 58.8 psi | CV@ 100 % @ 3.4 gpm |
| Retention Tank (T-114) | ✓ Operating Press: 57 psi | pH-113 @ 3.71 |
| Bag Filter (BF-113) | ✓ Operating Press: 60 psi | |
| Ion Exchange (Cage (1) or 2) + Guard | ✓ Operating Press: 53 psi | TP-123A-2 → TP-175A / 4 canisters + Guard |
| Post Ion Exchange | ✓ Operating Press: 4 psi | |

### I. FEED SURGE TANK

| Item | Status | Comments |
|---|---|---|
| Feed Surge Tank (T-520) | Level: 38 % | Last Cleaning (As Needed, if 4" of solids accumulate): 12/15/19 |
| Feed Surge Pump (P-521 or P-522) | Operating Press: 34 psi | CV@ 86 % @ 35.2 gpm |
| T-520 to GAC Total (FT-675) | 249812508 gal | Time: 0952 |
| North End On-Site Pumping | Operating Press: 2-3 psi | 13.2 gpm @ 0942 |
| North End Off-Site Pumping | Operating Press: 2-6 psi | 8.2 gpm @ 0942 |
| Peroxide Feed Pump (P-680) | ✓ | SPD 2.6 % / RATE 0.7 |
| Peroxide Conc. At (TP-710) | 1.0 PPM | |
| Peroxide Conc. At (TP-740) | 0.0 PPM | |

### J. HAZARDOUS WASTE STORAGE

| Item | Status | Comments |
|---|---|---|
| 180 Day storage area check | ✓ | Check sheet completed: NA/Empty |
| Satellite Haz. Waste Areas (BLDG #1) | ✓ | Condition: Both Inclosm + main Good |
| Satellite Haz. Waste Area (BLDG #2) | ✓ | Condition: Good |

### K. UV-OXIDATION SYSTEM

| Item | Status | Comments |
|---|---|---|
| UV-Oxidation System | ✓ | |
| Annual Test Run (Calgon) | Date: 9-16-21 | Next: 9-2022 |
| Quarterly Test Run | Date: NA/Running | Next: NA/Running |
| Peroxide Feed Pump (P-650) | ✓ | Flow Rate: ~7.0 cc/min. |
| UV-Ox Power | ✓ | 25.7 kVA 2613 Volts 9.9 Amps |
| Lamp Hours | 1321 Hrs | |
| Crystal Condition & Wiper Status | ✓ | Oiler status: Ok |
| UV-OX Bagfilters Status | Last change: 7-13-21 Cleaned: 7-13-21 | 11 psi In 11.5 psi Out |
| UV-OX Feed Pump ( P-600 or P-601 ) | ✓ | CV@ 75 % @ 8.0 gpm |
| UV-OX Temperature | In(TT-670): 15.9 °C | Out(TT-710): 27.5 °C |
| PDU GAC (PDT-710) | ✓ | Δ Pressure: 4 psi |
| Peroxide Concentration Pre UV | 1000 PPM | |
| Peroxide Concentration Post UV(TP-720) | 25 PPM | |
| Peroxide Conc. Post PDU (TP-730) | 0.0 PPM | |
| Secondary Acid Feed Pump (P-630) | ✓ | CV @ 3 % |
| Secondary Acid Retention Tank (T-645) | ✓ | |
| Pre – UV Oxidizer Total (FT-670) | 19757948 gal | Time: 0952 |
| Post UV-Ox / Pre PDU | ✓ | Pressure: 19 psi |
| Post PDU | ✓ | Pressure: 7.5 psi |

# ABLE 3.19.1
# STANDARD OPERATIONS CHECKLIST
# MAIN WTP

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, September 23, 2021

**Inspection Performed by:** Mike Gelwick

### L. PDU AND LIQUID –PHASE GRANULAR ACTIVATED CARBON

| Item | Status | Comments |
|---|---|---|
| PDT-720 | ✓ | Δ Pressure: 18 psi |
| PDT-730 | ✓ | Δ Pressure: 10 psi |

### M. EFFLUENT DISCHARGE

| Item | Status | Comments |
|---|---|---|
| Effluent Surge Pump ( P751 or P752 ) | ✓ | CV@ 60 % |
| Effluent Surge Tank (T-740) | ✓ | Level: 40 % |
| Effluent Discharge Rate (FT-770) | ✓ | 35.9 gpm @ 0949 |
| POTW Line Pressure (PT-770) | ✓ | 34.2 psi |
| Effluent Totalizer Reading (FT-770) | 243911840 gal | Time: 0953 |
| POTW MH17S-078 Discharge Check (Monthly) | ✓ | Last Done: 9-27-21 |
| 4X8-Inch POTW Leak Detection Checks (Monthly) | ✓ | Last Done: ↓ |
| 4X8-Inch POTW Air Reliefs Checks (Monthly) | ✓ | Last Done: |
| 4X8-Inch POTW Isolation Valves Exercise (Qtrly) | ✓ | Last Done: 7-19-21 |
| 2-Inch POTW Backup Pressure Testing (Annual) | ✓ | Last Done: 7/8/21 |
| 2-In POTW Backup Air Reliefs Checks (Annual) | ✓ | Last Done: 7/8/21 |
| 2-Inch POTW Isolation Valve Exercise (Annual) | ✓ | Last Done: 7/8/21 |
| Rotate Chiller Compressors | NA on Standby | ~~Now in Lead: 1 or 2~~ |

### N. LEL EFFLUENT TANK T-740

| Item | Status | Comments |
|---|---|---|
| LEL-740 Sensor | ✓ | Reading: 1 % |
| LEL Sensor Calibration / Automatic High LEL Shutdown Test (monthly) | Last Completed: 8-26-21 | Plant Effluent Suspended: 1400 ↔ 1420 |
| LEL Sensor Bridge Adjustment to 2.0 volts | Reading: 2.001 volts(monthly) | Adjustment Needed: Y or (N) |
| Verify Bridge Current between.300v-.360v | Reading: 0.331 volts(monthly) | |

### O. WTP INFLUENT TOTALIZERS Time : 0953-0957

| Source | Reading(Gallons) | Source | Reading(Gallons) |
|---|---|---|---|
| (FT-015) RWST Influent | 19632901 | (FT-505) LFG Cond. to T-530 | 216597 |
| (FT-025) NBBW Influent | 93708032 | (FT-056) Off - Site N. End Influent | 42785212 |
| (FT-012) MW-38 Inf. to HMR-30 | 8187270 | (FT-113) Ion Exchange Influent | 642648 |
| (FT-042 HMR30) MW-38 Source to HMR-30 | 35484 | (FT-810) Plant Potable Water In | 30058696 |
| (FT-043) MW-38 to RWST | 3072979 | (FT-026) NBBW Bypass to RWST | 4387641 |
| (FT-042 RWST) MW-38 Source to RWST | 72236 | (FT-014) Misc. Water to RWST | 8153383 |
| (FT-012T) MW-38 to T-540/541 | 8608152 | (FT-035) NTES Inf. to BIO | 6639852 |
| (FT-040T) MW-38N to T-540/541 | 1977498 | (FT-035T) NTES to T-530 | 460108 |
| (FT-041T) MW-38S to T-540/541 | 2695519 | (FT-017) BIO Inf. from T-530 | 650804 |
| (FT-042T) MW-38 Source to T-540/541 | 4007125 | (FT-018) T-540/541 Influent | 86501555 |
| (FT-055) On - Site N. End Influent | ~~95~~ 95/14287 | (FT-352) T-352 to HMR-30 | 1280099 |

# ABLE 3.19.1
# STANDARD OPERATIONS CHECKLIST
# MAIN WTP

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, September 23, 2021

**Inspection Performed by:** Mike Gelwick

### P. AIR COMPRESSORS

| Item | Status | Comments |
|---|---|---|
| Compressor Intake Temp. | 64 °F (Analog Gauge) | Outside Temp.: ~ 68 °F |
| Compressor Building Vent | ✓ | Closed - operational |
| Primary Air Compressor (IRN30H) | 2,000 Hour service date: 7-8-21<br>Serviced @ 60952 Hours | Coolant present in sight glass: (Y) / N<br>Next service @ 62952 Hours<br>Current Hours @ 61977 |
| IRN30H Motor Speed | 98 % | |
| IRN30H Pressure | 109 psi | |
| IRN30H Moisture purge valve chk(Weekly): | ✓ | |
| IRN30H Intake Filter | ✓ | Date Last Changed: 8-12-21 |
| Air Tanks Moisture Purge Valves | Manually Activate(weekly) ✓ | Excessive Moisture: Y / (N) |
| Backup Air Compressors (T-30 East and West) | ✓ | Both cool to touch: (Y) / N |
| Air Dryer | ✓ ECO on | Moisture at Receiver Tank: Y / (N) |
| Oil Moisture Prevention (Monthly) | Last Done: 9-23-21 - today | Run at max speed by bleeding air from filter canister above/after air dryer for 2 hrs |
| Air Receiver Tank | ✓ | 100 psi |

### Q. SUMPS

| Item | Status | Comments |
|---|---|---|
| Bag Filter Sump | ✓ | |
| Wet Well Sump | ✓ | |

### R. GAS CHROMATOGRAPH

| Item | Status | Comments |
|---|---|---|
| GC Operational | ✓ | GC # checking UV-Ox Effluent: #2 |
| Alarms Enabled | ✓ | CC - Calibration + maint 9-22-21 |
| GC Influent Filters | ✓ | |

### S. SAFETY

| Item | Status | Comments |
|---|---|---|
| Building #1 Fire Extinguishers | ✓ | Date inspected: 8-25-21 |
| Building #1 Eye Wash/Shower | ✓ | Checked and Flushed- All OK: (Y) / N |

**Other Comments:**

# TABLE 3.19.2
# STANDARD OPERATIONS CHECKLIST
# BIOLOGICAL TREATMENT SYSTEM

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, September 23, 2021

**Inspection Performed by:** Mike Gelwick

## A. PUMPS

| Item | Status | Flow Rate (gpm) | Pump Speed (CV%) | Discharge Pressure (psi) | Comments |
|---|---|---|---|---|---|
| **T-510 Pumps** | | | | | |
| P-3301 | ✓ | 1.86 | 33.6 % | 6.0 | |
| P-3301A | SB | – | – % | – | |
| **NTES Pump** P-002(Sump) / (P-002W(10R)) | ✓ | 0.53 | 52 % | P035 35-36 / P038 8 | Globules Observed at TP-130: Y / (N) Time: 0900 |
| **T-530** P-005 | ✓ | 0.22 | 41 % | 5.5 | |
| **T-540/541** P-006 | ✓ | 0.28 | 57 % | 4.5 | |
| **LFG COND Auto-Traps** | ✓ | 0.0 | NA | 5 | Between Cycles: (Y) / N |
| **Reactor Feed Pumps** | | | | | |
| P-3321 | ✓ | 2.44 | 57.6 % | 5.0 | |
| P-3322 | ✓ | 3.40 | 46.0 % | 5.0 | |
| P-3323 | ✓ | 2.42 | 67.3 % | 5.0 | |
| P-3324 | SB | – | – % | – | |
| **Reactor Effluent Pumps** | | | | | |
| P-3341 | ✓ | 3.16 | 77.4 % | 28 | |
| P-3341A | SB | – | – % | – | |

## B. BLOWERS

| Item | Status | Pressure (psi) | Temp (°F) | Next Scheduled Service (Qtrly) | Comments Last serviced on: 6-22-21 |
|---|---|---|---|---|---|
| B-3331 | ✓ | 4.25 | 148 | 5000 | Greased, Belt and Filter Checked: (Y) / N |
| B-3332 | SB | – | – | ↓ | Belt and Filter Checked: Y / (N) |
| B-3333 | ✓ | 4.34 | 150 | | Greased, Belt and Filter Checked: (Y) / N |
| B-3334 | ✓ | 4.26 | 146 | | Greased, Belt and Filter Checked: (Y) / N |

## C. REACTOR VENTILATION

| Item | Status | Comments |
|---|---|---|
| Vapor Carbon Contactor | ✓ | On-line: 2/10/18 |
| Reactor Vent Blower | ✓ | |
| Reactor Vent Booster | ✓ | |
| VTP-3350 | ✓ | PID Reading: 2.4 PPM |
| VTP-3360 | ✓ | PID Reading: 1.8 PPM |

# TABLE 3.19.2
# STANDARD OPERATIONS CHECKLIST
# BIOLOGICAL TREATMENT SYSTEM

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, September 23, 2021

**Inspection Performed by:** Mike Gelwick

## D. TANKS / REACTORS / SUMPS / CONTAINMENTS / PIPING / Chiller

| Item | Status | Comments |
|---|---|---|
| T-510 Post HMR-30 Mixing Tank | ✓ Level: 64 % | Last Cleaning (As needed, if 2" of solids accumulate): 7/14/21 |
| T-530 LFG Condensate / NTES Tank | ✓ Level: 27 % | |
| T-530 Mixer | ✓ | |
| LFG Condensate Conveyance Line | ✓ | Last Pressure Test: 7-19-21 Next: 7-2022 (Annual at a minimum or if flow drops off) |
| T-540/541 MW38 Tanks | Lvls: 78 % & 79 % | |
| T-540/541 Mixers | ✓ | |
| Chiller | ✓ | Chiller Coolant Lvl: ~ — " Below full mark |
| Chiller Cooling Fins (as needed) | ✓ | Last Cleaning: 4/20/18 (unit on Standby) |
| Secondary Containments | ✓ | Heat Trace: On OK / (Off Warm out) |
| Feed Piping to Sedimentation Tank | ✓ | Last Back Flushing (Quarterly): 8-30-21 |
| T-3310 Sedimentation Tank | Visual Level: ok | Last Cleaning (As Needed, use TSS info to determine): 9/2021 |
| T-3320 Blend Tank | ✓ Level: 70 % | Last Cleaning (Semi Annual): 9-10-21 |
| T-3331 Reactor No. 1 | ✓ | Digital Displays: (GOOD) / Needs Attn |
| T-3332 Reactor No. 2 | ✓ | Digital Displays: (GOOD) / Needs Attn |
| T-3333 Reactor No. 3 | ✓ | Digital Displays: (GOOD) / Needs Attn |
| T-3334 Settling Tank | ✓ | Last Cleaning (Semi Annual): 9-10-21 |
| P-3334 Biosolids Pump | ✓ | |
| T-3340 Overflow Tank | ✓ Level: 30 % | |
| Recycle Valve to Blend Tank | ✓ | 3.69 gpm @ 1012 |
| Building Containment Sump | ✓ | Last Alarm Test Date (Monthly): 9-23-21-today |

## E. CHEMICAL FEED SYSTEM

| Item | Status | Comments |
|---|---|---|
| Phosphorous Supply | ✓ | Bags: 12.25 Gallons: ~ 60 |
| Phosphorous Pump (P-2221) | ✓ | |
| Caustic Supply | ✓ | ~85 Gallons |
| Caustic Pump (P-2211) | SB | Currently in acid addition mode |
| Acid Supply | ✓ | ~ 40 Gallons |
| Acid Pump (P-2211) | ✓ | |
| Caustic Pump (P-2231) | ✓ Leaks: Y / (N) | Last tubing tip cleaning (monthly): 9-23-21-today |
| Caustic Pump (P-2232) | ✓ Leaks: Y / (N) | Last tubing tip cleaning (monthly): |
| Caustic Pump (P-2233) | ✓ Leaks: Y / (N) | Last tubing tip cleaning (monthly): |

# TABLE 3.19.2
# STANDARD OPERATIONS CHECKLIST
# BIOLOGICAL TREATMENT SYSTEM

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, September 23, 2021

**Inspection Performed by:** Mike Gelwick

## F. pH Probes

| pH Probe Location | Calibration Date (Monthly) | Comments |
|---|---|---|
| pH-3320 Blend Tank | 8-26-21 | Acid/BASE clean today |
| pH-3331 Reactor 1 | ↓ | ↓ |
| pH-3332 Reactor 2 | | |
| pH-3333 Reactor 3 | | |

## G. FILTER SYSTEM

| Item | Status | Comments |
|---|---|---|
| BF-3340 a/b Status | ✓ | |
| Automatic Backwash | Cycle Count: 26 | Reset |
| BF-3340 a/b Differential Pressure | PSI: 3 | 30/27 @ 3.7 gpm |
| 75-micron Bags Last Cleaning | Date: 11-14-19 | |
| 75-micron Bags Last Inspection | Date: ↓ | |
| 75-micron Bags Last Changed | Date: | |
| GACF-3340 Status | ✓ | 27/7 @ 3.7 gpm |
| GACF-3340 Differential Pressure | PSI: 20 | 27/7 @ 3.7 gpm |
| Last Backwash Performed | Date: 8-26-21 | |

## H. ELECTRICAL AND INSTRUMENTATION

| Item | Status | Comments |
|---|---|---|
| "BIO" Backup Generator | ✓ | Block Heater: On OK / (Off Warm Out) |
| Electrical Surge Suppressor | ✓ | |
| Motor Control Center | ✓ | |
| PLC | ✓ | UPS @ 97 min / 84 Events |
| HMI's | ✓ | |
| BTS Process KWH Meter | 1798495 KWH | Time: 1127 |
| Building#2 KWH Meter | 5224446 KWH | Time: 1127 |

## I. GAS CHROMATOGRAPHY

| Item | Status | Comments |
|---|---|---|
| GC Operational | ✓ | GC # checking BIO: #3 |
| Alarms Enabled | ✓ | cc-calibration & maint 9-22-21 |
| GC Influent Filters | ✓ | |

# TABLE 3.19.2
# STANDARD OPERATIONS CHECKLIST
# BIOLOGICAL TREATMENT SYSTEM

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, September 23, 2021

**Inspection Performed by:** Mike Gelwick

## J. TOTALIZERS

| Item | Readings (gallons) | Comments |
|---|---|---|
| FT-3321 Feed to Reactor 1 | 5907824 | |
| FT-3324 Feed Spare | 87149 | |
| FT-3322 Feed to Reactor 2 | 10613374 | |
| FT-3323 Feed to Reactor 3 | 623781 | |
| FT-3301 T-510 to BIO | 51428408 | |
| FT-3341 BIO Effluent | 66202789 | |
| FT-3342 BIO Recycle | 55335425 | |

## K. SAFETY

| Item | Status | Comments |
|---|---|---|
| Building #2 Fire Extinguishers | ✓ | Inspection date: 8-25-21 |
| Building #2 Eye Wash/Shower | ✓ | Checked and Flushed- All OK: (Y) / N |

## L. OTHER COMMENTS:

| |
|---|
| |
| |
| |
| |

# ABLE 3.19.1
# STANDARD OPERATIONS CHECKLIST
# MAIN WTP

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, September 30, 2021

**Inspection Performed by:** Mike Gelwick

### A. PERIMETER COLLECTION SYSTEMS

| Item | Status | Comments |
|---|---|---|
| LFG Cond Automatic Trap CT-1 | Sump Level: 12.58 oz | Counter: 183304 Cycles: 780 |
| LFG Cond Automatic Trap CT-2 | Sump Level: 8.62 oz | Counter: 274179 Cycles: 52 |
| LFG Cond Automatic Trap CT-3 | Sump Level: 7.25 oz | Counter: 305256 Cycles: 445 |
| CT-4 Containment/Vessel (LFG Cond) | ✓ Level: 72 % | Tank Level: 2.13 Counter: 191242 Cycles: 0 Sump: 8.88 oz |
| PM-15 Containment / Vessel | ✓ Level: 50 % | |
| MW-51 Containment / Vessel | ✓ Level: 20 % | |
| PM-11 Containment / Vessel | ✓ Level: 20 % | |
| MW-38 Systems | ✓ | |
| North Toe System | ✓ | |
| North End Systems (Weekly) | ✓ | |
| Full N. End Systems Check (Monthly) | ✓ | Last Done: 9-24-21 |
| North End Pipeline(s)Flushing (As Needed) | ✓ | Perform if suspended solids present Last Done: 11/15/15 |
| NTES line flush to T-530 (As needed) | ✓ | Perform if suspended solids present Last Done: 2/13/20 |
| NTES Piping Containment | ✓ | Monthly Sump Level: dry 016.07' Date: 9-23-21 |
| North Boundary System P-001: | CV 74.8 % @ 7.1 gpm | 41.57 Hz / 2.09 Amps. / vault psi @ 18/20 levels |
| T-101 & T-102 Containment / Tank | ✓ | Levels: 31 % & 35 % Gauges correctly reflecting |
| Raw Water Storage Tanks Piping | ✓ | |
| RWST Building Temp. (TT-101) | 59.3 °F | Outside Temp.: ~ 44 °F |
| (P-121) or P-122 | ✓ | 0.60 gpm / CV 48 % |
| RWST 2ndry Cont. High Level Switch | ✓ | (LSH-101) Last Test(monthly): 9-23-21 |
| RWST Back-Up Generator | ✓ | Last Test Run(monthly): 9-23-21 |

### B. CHEMICAL STORAGE BAYS

| Item | Status | Comments |
|---|---|---|
| Caustic Tote Levels | ✓ | ~ 900 Gallons Reserve = 3 totes |
| Caustic Bay Heater | ✓ | Operational |
| Peroxide Tote Level | ✓ | ~ 265 Gallons Reserve = ~55gal |
| HCL Tote Levels | ✓ | ~ 85 Gallons Reserve = 1 tote + ~3 gal |
| Chemical Totes and Piping Inspected | ✓ | Leaks observed: Y / (N) |
| Emergency Shower Inspected | ✓ | Checked and Flushed - All OK: (Y) / N |

### C. PRIMARY AND SECONDARY ACID FEED SYSTEM

| Item | Status | Comments |
|---|---|---|
| Primary Acid Feed Pump (P-631) | ✓ | |
| Ion Exchange Acid Feed Pump (P-632) | ✓ | PI-0632 PSI: 80-82 CV: 8 % |
| Primary Acid Retention Tank (T-510) | ✓ | |
| All Acid Feed Lines | ✓ | Leaks observed: Y / (N) |

### D. NBBW INJECTION TRENCH

| Item | Status | Comments |
|---|---|---|
| Injection Carbon (GAC-810) | OFFLINE | Date online: 7/20/18 |
| Injection Rate (FT-800) | 0.0 gpm | NBBW-IW-1= 0.0 NBBW-IW-2= 0.0 NBBW-IW-3= 0.0 gpm ea. |
| Totalizer Reading (FT-800) | 105,135,774 gal | INJ. STOPPED 10/02/18 @ 1545 |

# ABLE 3.19.1
# STANDARD OPERATIONS CHECKLIST
# MAIN WTP

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, September 30, 2021

**Inspection Performed by:** Mike Gelwick

### E. CHEMICAL PRECIPITATION SYSTEM (US FILTER HMR-30)

| Item | Status | Comment |
|---|---|---|
| T-300A Mixer | NA | |
| T-300B (Caustic Mixer) | ✓ | Last Cleaning (Qtrly): 6-3-21 |
| T-300A/B Water Level | ✓ | |
| T-300B (Caustic Mix Chamber) | ✓ | Last Cleaning (Qtrly): 6-3-21 |
| T-300A/B Overflow | ✓ | |
| pH Set-point for (pH 315) | Value: 10.8 | |
| pH 310 | Value: 6.92 | |
| pH 315 | Value: 10.84 | |
| Flocculation Chamber Paddle Wheel | ✓ | |
| Precipitate Floc Quality | ✓ | Good |
| Clarifier Water Quality | ✓ | Good Oil or sheen observed: Y / (N) |
| Clarifier Effluent Piping / Water Level | ✓ | |
| Clear-well Chamber and Water Level | ✓ | |
| HMR PLC Panel | ✓ | |
| Caustic Pump (P-270) | SB | |
| Caustic Pump (P-280) | ✓ | |
| Polymer Pump (P-310) | ✓ | |
| Polymer Tank Mixer | ✓ | |
| Polymer Tank Level | Gallons: ~ 475 | |
| Clear-well Transfer Pumps (P-371 / 372) | ✓ | |
| Sludge Transfer Pump (P-330) | ✓ | Exercise Valves Weekly: Both ok |
| Manual Sludge Lateral pumping | ✓ | Last done (As Needed): #3-7-20-21 / #4 + 2-3-20-21 |
| Manual Sludge Lateral Ball Valves | ✓ | Exercise Weekly: All ok |
| Automatic Blow-down Operations | ✓ | |

### F. pH PROBES

* New 4 + 10 pH STDs today *

| pH Probe Location | Calibration Date | Comments: (Time done) |
|---|---|---|
| pH-310 HMR-30 (T-300A) | 9-30-21 - Today | 1313 |
| pH-315 HMR-30 (T-300B) | | |
| pH-365 Primary Acid Ret. Tank | | |
| pH-113 Pre-Ion Exchange | | |
| pH-670 Pre-UV-OX | | 1348 |
| pH-740 Discharge Surge Tank | | Discharge suspended: 1350 ↔ 1410 |
| Out of Hold Double Check | ---------- | None in hold: ✓✓ |
| Valves Back to Normal Position | ---------- | All OK: ✓✓ |

### G. SLUDGE THICKENER, SLUDGE HOLDING TANKS, FILTER PRESS

| Item | Status | Comments |
|---|---|---|
| Verify Sludge Thickener Running | ✓ * Grease motor bearings today * | Gauge Reading: 0 % |
| Sludge Thick. Transfer Pump (P-350) | ✓ | |
| Sludge Holding Tank (T-351) | ✓ | Level: ~ 65 % |
| Sludge Holding Tank (T-352) | ✓ | Level: 41 % |
| Decant Transfer Pump (P-352) | ✓ | CV 61 % @ 0.6 gpm |
| Filter Press Pumps (P-381 / P-382) | ✓ | |
| Filter Press | ✓ | Stage: Empty / need to wash out |

# ABLE 3.19.1
# STANDARD OPERATIONS CHECKLIST
# MAIN WTP

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, September 30, 2021

**Inspection Performed by:** Mike Gelwick

### H. ION EXCHANGE

| Item | Status | Comments |
|---|---|---|
| Feed Tank (T-113) | ✓ Level: 52 % | |
| Feed Pump (P-114) | ✓ Operating Press: 54 psi | CV@ 100 % @ 3.4 gpm |
| Retention Tank (T-114) | ✓ Operating Press: 52 psi | pH-113 @ 3.56 |
| Bag Filter (BF-113) | ✓ Operating Press: 56 psi | |
| Ion Exchange (Cage (1) or 2) + Guard | ✓ Operating Press: 51.5 psi | TP-173A-2 → TP-175A/4 [illegible] + Guard |
| Post Ion Exchange | ✓ Operating Press: 4 psi | |

### I. FEED SURGE TANK

| Item | Status | Comments |
|---|---|---|
| Feed Surge Tank (T-520) | ✓ Level: 38 % | Last Cleaning (As Needed, if 4" of solids accumulate): 12/15/19 |
| Feed Surge Pump (P-521 or (P-522)) | Operating Press: 35.1 psi | CV@ 64 % @ 35.1 gpm |
| T-520 to GAC Total (FT-675) | 250160586 gal | Time: 1014 |
| North End On-Site Pumping | Operating Press: 2-3 psi | 13.3 gpm @ 1006 |
| North End Off-Site Pumping | Operating Press: 2-6 psi | 8.5 gpm @ 1006 |
| Peroxide Feed Pump (P-680) | ✓ | SPD 2.6 % / RATE 0.7 |
| Peroxide Conc. At (TP-710) | 1.0 PPM | |
| Peroxide Conc. At (TP-740) | 0.0 PPM | |

### J. HAZARDOUS WASTE STORAGE

| Item | Status | Comments |
|---|---|---|
| 180 Day storage area check | ✓ | Check sheet completed: NA/Empty |
| Satellite Haz. Waste Areas (BLDG #1) | ✓ | Condition: |
| Satellite Haz. Waste Area (BLDG #2) | ✓ | Condition: |

### K. UV-OXIDATION SYSTEM

| Item | Status | Comments |
|---|---|---|
| UV-Oxidation System | ✓ | |
| Annual Test Run (Calgon) | Date: 9-16-21 | Next: 9-2022 |
| Quarterly Test Run | Date: NA/Running | Next: NA/Running |
| Peroxide Feed Pump (P-650) | ✓ | Flow Rate: ~7.0 cc/min. |
| UV-Ox Power | | kVA Volts Amps |
| Lamp Hours | 1486 Hrs | |
| Crystal Condition & Wiper Status | ✓ | Oiler status: OK |
| UV-OX Bagfilters Status | Last change: 7-13-21 Cleaned: 7-13-21 | 11.0 psi In 11.5 psi Out |
| UV-OX Feed Pump ( (P-600) or P-601 ) | ✓ | CV@ 72 % @ 7.9 gpm |
| UV-OX Temperature | In(TT-670): 15.8 °C | Out(TT-710): 27.7 °C |
| PDU GAC (PDT-710) | BACKWASHED 9-27-21 ✓ | Δ Pressure: 3 psi |
| Peroxide Concentration Pre UV | 100 PPM | |
| Peroxide Concentration Post UV(TP-720) | 25 PPM | |
| Peroxide Conc. Post PDU (TP-730) | 0.0 PPM | |
| Secondary Acid Feed Pump (P-630) | ✓ | CV @ 3 % |
| Secondary Acid Retention Tank (T-645) | ✓ | |
| Pre – UV Oxidizer Total (FT-670) | 198345772 gal | Time: 1014 |
| Post UV-Ox / Pre PDU | ✓ | Pressure: 13 psi |
| Post PDU | ✓ | Pressure: 7.5 psi |

# ABLE 3.19.1
# STANDARD OPERATIONS CHECKLIST
# MAIN WTP

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, September 30, 2021

**Inspection Performed by:** Mike Gelwick

### L. PDU AND LIQUID –PHASE GRANULAR ACTIVATED CARBON

| Item | Status | Comments |
|---|---|---|
| PDT-720 | ✓ BACKWASHED 9-27-21 | Δ Pressure: 9 psi |
| PDT-730 | ✓ BACKWASHED 9-29-21 | Δ Pressure: 5 psi |

### M. EFFLUENT DISCHARGE

| Item | Status | Comments |
|---|---|---|
| Effluent Surge Pump ( P751 or (P752)) | ✓ | CV@ 57.1 % |
| Effluent Surge Tank (T-740) | ✓ | Level: 40 % |
| Effluent Discharge Rate (FT-770) | ✓ | 35.4 gpm @ 1012 |
| POTW Line Pressure (PT-770) | ✓ | 33.6 psi |
| Effluent Totalizer Reading (FT-770) | 244265118 gal | Time: 1014 |
| POTW MH17S-078 Discharge Check (Monthly) | ✓ | Last Done: 9-27-21 |
| 4X8-Inch POTW Leak Detection Checks (Monthly) | ✓ | Last Done: ↓ |
| 4X8-Inch POTW Air Reliefs Checks (Monthly) | ✓ | Last Done: ↓ |
| 4X8-Inch POTW Isolation Valves Exercise (Qtrly) | ✓ | Last Done: 7-19-21 |
| 2-Inch POTW Backup Pressure Testing (Annual) | ✓ | Last Done: 7/8/21 |
| 2-In POTW Backup Air Reliefs Checks (Annual) | ✓ | Last Done: 7/8/21 |
| 2-Inch POTW Isolation Valve Exercise (Annual) | ✓ | Last Done: 7/8/21 |
| Rotate Chiller Compressors | NA on Standby | ~~Now in Lead: 1 or 2~~ |

### N. LEL EFFLUENT TANK T-740

| Item | Status | Comments |
|---|---|---|
| LEL-740 Sensor | ✓ | Reading: 0 % |
| LEL Sensor Calibration / Automatic High LEL Shutdown Test (monthly) ✓ | Last Completed: 9-30-21 - today | Plant Effluent Suspended: 1350 ↔ 1410 |
| LEL Sensor Bridge Adjustment to 2.0 volts | Reading: 2.001 volts(monthly) | Adjustment Needed: (Y) or N |
| Verify Bridge Current between.300v-.360v | Reading: 0.331 volts(monthly) | very Active - 49.3 → 49% / 2.003 → 2.001 |

### O. WTP INFLUENT TOTALIZERS Time : 1015-1019

| Source | Reading(Gallons) | Source | Reading(Gallons) |
|---|---|---|---|
| (FT-015) RWST Influent | 19638746 | (FT-505) LFG Cond. to T-530 | 216843 |
| (FT-025) NBBW Influent | 93778029 | (FT-056) Off - Site N. End Influent | 42865868 |
| (FT-012) MW-38 Inf. to HMR-30 | 8207863 | (FT-113) Ion Exchange Influent | 674985 |
| (FT-042 HMR30) MW-38 Source to HMR-30 | 35484 | (FT-810) Plant Potable Water In | 30059980 |
| (FT-043) MW-38 to RWST | 3073667 | (FT-026) NBBW Bypass to RWST | 4390222 |
| (FT-042 RWST) MW-38 Source to RWST | 72236 | (FT-014) Misc. Water to RWST | 8157671 |
| (FT-012T) MW-38 to T-540/541 | 8608152 | (FT-035) NTES Inf. to BIO | 6644770 |
| (FT-040T) MW-38N to T-540/541 | 977498 | (FT-035T) NTES to T-530 | 460342 |
| (FT-041T) MW-38S to T-540/541 | 26955519 | (FT-017) BIO Inf. from T-530 | 651336 |
| (FT-042T) MW-38 Source to T-540/541 | 4007125 | (FT-018) T-540/541 Influent | 8653040 |
| (FT-055) On - Site N. End Influent | 97647758 | (FT-352) T-352 to HMR-30 | 1283431 |

# ABLE 3.19.1
# STANDARD OPERATIONS CHECKLIST
# MAIN WTP

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, September 30, 2021

**Inspection Performed by:** Mike Gelwick

### P. AIR COMPRESSORS

| Item | Status | Comments |
|---|---|---|
| Compressor Intake Temp. | 40 °F (Analog Gauge) | Outside Temp.: ~ 45 °F |
| Compressor Building Vent | ✓ | closed - operational |
| Primary Air Compressor (IRN30H) | 2,000 Hour service date: 7-8-21<br>Serviced @ 60952 Hours | Coolant present in sight glass: Ⓨ / N<br>Next service @ 62952 Hours ~Accuracy<br>Current Hours @ 62066 |
| IRN30H Motor Speed | 31 % | |
| IRN30H Pressure | 111 psi | |
| IRN30H Moisture purge valve chk(Weekly): | ✓ | |
| IRN30H Intake Filter | ✓ | Date Last Changed: ~~9-12-21~~ 9-30-21-today |
| Air Tanks Moisture Purge Valves | Manually Activate(weekly) ✓ | Excessive Moisture: Y / Ⓝ |
| Backup Air Compressors (T-30 East and West) | ✓ | Both cool to touch: Ⓨ / N |
| Air Dryer | ✓ Eco on | Moisture at Receiver Tank: Y / Ⓝ |
| Oil Moisture Prevention (Monthly) | Last Done: 9-23-21 | Run at max speed by bleeding air from filter canister above/after air dryer for 2 hrs |
| Air Receiver Tank | ✓ | 108 psi |

### Q. SUMPS

| Item | Status | Comments |
|---|---|---|
| Bag Filter Sump | ✓ | |
| Wet Well Sump | ✓ | |

### R. GAS CHROMATOGRAPH

| Item | Status | Comments |
|---|---|---|
| GC Operational | ✓ | GC # checking UV-Ox Effluent: #2 |
| Alarms Enabled | ✓ | cc-calibration + maint 9-28-21 |
| GC Influent Filters | ✓ | |

### S. SAFETY

| Item | Status | Comments |
|---|---|---|
| Building #1 Fire Extinguishers | ✓ | Date inspected: 9-30-21 |
| Building #1 Eye Wash/Shower | ✓ | Checked and Flushed- All OK: Ⓨ / N |

**Other Comments**:

# TABLE 3.19.2
# STANDARD OPERATIONS CHECKLIST
# BIOLOGICAL TREATMENT SYSTEM

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, September 30, 2021

**Inspection Performed by:** Mike Gelwick

## A. PUMPS

| Item | Status | Flow Rate (gpm) | Pump Speed (CV%) | Discharge Pressure (psi) | Comments |
|---|---|---|---|---|---|
| **T-510 Pumps** | | | | | |
| P-3301 | ✓ | 1.81 | 32.1 % | 6.5 | |
| P-3301A | SB | – | – % | – | |
| **NTES Pump** P-002(Sump) / (P-002W(10R)) | ✓ | 0.61 | 53 % | P035 34.35 / P038 7.5 | Globules Observed at TP-130: Y / (N) Time: 0940 |
| **T-530** P-005 | ✓ | 0.20 | 40 % | 6.5 | |
| **T-540/541** P-006 | ✓ | 0.30 | 65 % | 5.5 | |
| **LFG COND Auto-Traps** | ✓ | 0.0 | NA | 5.0 | Between Cycles: (Y) / N |
| **Reactor Feed Pumps** | | | | | |
| P-3321 | ✓ | 2.44 | 63.3 % | 5.5 | |
| P-3322 | ✓ | 3.29 | 60.1 % | 5.5 | |
| P-3323 | ✓ | 2.47 | 74.5 % | 5.5 | |
| P-3324 | SB | – | – % | – | |
| **Reactor Effluent Pumps** | | | | | |
| P-3341 | ✓ | 1.71 | 36.2 % | 9.0 | |
| P-3341A | SB | – | – % | – | |

## B. BLOWERS

| Item | Status | Pressure (psi) | Temp (°F) | Next Scheduled Service (Qtrly) | Comments Last serviced on: 6.22.21 |
|---|---|---|---|---|---|
| B-3331 | ✓ | 4.28 | 136 | 10-1-21 | Greased, Belt and Filter Checked: (Y) / N |
| B-3332 | SB | – | – | ↓ | Belt and Filter Checked: Y / (N) |
| B-3333 | ✓ | 4.38 | 136 | ↓ | Greased, Belt and Filter Checked: (Y) / N |
| B-3334 | ✓ | 4.29 | 132 | ↓ | Greased, Belt and Filter Checked: (Y) / N |

## C. REACTOR VENTILATION

| Item | Status | Comments |
|---|---|---|
| Vapor Carbon Contactor | ✓ | On-line: 2/10/18 |
| Reactor Vent Blower | ✓ | |
| Reactor Vent Booster | ✓ | |
| VTP-3350 | ✓ | PID Reading: 3.6 PPM |
| VTP-3360 | ✓ | PID Reading: 1.9 PPM |

# TABLE 3.19.2
# STANDARD OPERATIONS CHECKLIST
# BIOLOGICAL TREATMENT SYSTEM

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, September 30, 2021

**Inspection Performed by:** Mike Gelwick

## D. TANKS / REACTORS / SUMPS / CONTAINMENTS / PIPING / Chiller

| Item | Status | Comments |
|---|---|---|
| T-510 Post HMR-30 Mixing Tank | ✓ Level: 55 % | Last Cleaning (As needed, if 2" of solids accumulate): 7/14/21 |
| T-530 LFG Condensate / NTES Tank | ✓ Level: 27 % | |
| T-530 Mixer | ✓ | |
| LFG Condensate Conveyance Line | ✓ | Last Pressure Test: 7-19-21 Next: 7-2022 (Annual at a minimum or if flow drops off) |
| T-540/541 MW38 Tanks | Lvls: 57 % & 57 % | |
| T-540/541 Mixers | ✓ | |
| Chiller | ✓ | Chiller Coolant Lvl: ~ " Below full mark |
| Chiller Cooling Fins (as needed) | ✓ | Last Cleaning: 4/20/18 (unit on Standby) |
| Secondary Containments | ✓ | Heat Trace: On OK / (Off Warm out) |
| Feed Piping to Sedimentation Tank | ✓ | Last Back Flushing (Quarterly): 8-30-21 |
| T-3310 Sedimentation Tank | Visual Level: ok | Last Cleaning (As Needed, use TSS info to determine): 9/2021 |
| T-3320 Blend Tank | ✓ Level: 70 % | Last Cleaning (Semi Annual): 9-10-21 |
| T-3331 Reactor No. 1 | ✓ | Digital Displays: (GOOD) / Needs Attn |
| T-3332 Reactor No. 2 | ✓ | Digital Displays: (GOOD) / Needs Attn |
| T-3333 Reactor No. 3 | ✓ | Digital Displays: (GOOD) / Needs Attn |
| T-3334 Settling Tank | ✓ | Last Cleaning (Semi Annual): 9-10-21 |
| P-3334 Biosolids Pump | ✓ | |
| T-3340 Overflow Tank | ✓ Level: 30 % | |
| Recycle Valve to Blend Tank | ✓ | 3.97 gpm @ 1047 |
| Building Containment Sump | ✓ | Last Alarm Test Date (Monthly): 9-23-21 |

## E. CHEMICAL FEED SYSTEM

| Item | Status | Comments |
|---|---|---|
| Phosphorous Supply | ✓ | Bags: 17 Gallons: ~ 80 |
| Phosphorous Pump (P-2221) | ✓ | |
| Caustic Supply | ✓ | ~ 125 Gallons |
| Caustic Pump (P-2211) | SB | Currently in acid addition mode |
| Acid Supply | ✓ | ~ 40 Gallons |
| Acid Pump (P-2211) | ✓ | |
| Caustic Pump (P-2231) | ✓ Leaks: Y / (N) | Last tubing tip cleaning (monthly): 9-23-21 |
| Caustic Pump (P-2232) | ✓ Leaks: Y / (N) | Last tubing tip cleaning (monthly): ↓ |
| Caustic Pump (P-2233) | ✓ Leaks: Y / (N) | Last tubing tip cleaning (monthly): ↓ |

# TABLE 3.19.2
# STANDARD OPERATIONS CHECKLIST
# BIOLOGICAL TREATMENT SYSTEM

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, September 30, 2021

**Inspection Performed by:** Mike Gelwick

## F. pH Probes

| pH Probe Location | Calibration Date (Monthly) | Comments |
|---|---|---|
| pH-3320 Blend Tank | 9-30-21 - Today | New 4+10 pH stds today |
| pH-3331 Reactor 1 | ↓ | ↓ |
| pH-3332 Reactor 2 | | |
| pH-3333 Reactor 3 | | |

## G. FILTER SYSTEM

| Item | Status | Comments |
|---|---|---|
| BF-3340 a/b Status | ✓ | |
| Automatic Backwash | Cycle Count: 33 | reset |
| BF-3340 a/b Differential Pressure | PSI: 1 | 8/7 @ 1.5 gpm |
| 75-micron Bags Last Cleaning | Date: 11-14-19 | |
| 75-micron Bags Last Inspection | Date: ↓ | |
| 75-micron Bags Last Changed | Date: | |
| GACF-3340 Status | ✓ | |
| GACF-3340 Differential Pressure | PSI: 0 | 7/7 @ 1.5 gpm |
| Last Backwash Performed | Date: 9-27-21 | |

## H. ELECTRICAL AND INSTRUMENTATION

| Item | Status | Comments |
|---|---|---|
| "BIO" Backup Generator | ✓ | Block Heater: On OK / (Off Warm Out) |
| Electrical Surge Suppressor | ✓ | |
| Motor Control Center | ✓ | |
| PLC | ✓ | UPS @ 97 min / 86 Events |
| HMI's | ✓ | |
| BTS Process KWH Meter | 1800502 KWH | Time: 1140 |
| Building#2 KWH Meter | 5227489 KWH | Time: 1140 |

## I. GAS CHROMATOGRAPHY

| Item | Status | Comments |
|---|---|---|
| GC Operational | ✓ | GC # checking BIO: #3 |
| Alarms Enabled | ✓ | CC - Calibration + Maint 9-29-21 |
| GC Influent Filters | ✓ | |

# TABLE 3.19.2
# STANDARD OPERATIONS CHECKLIST
# BIOLOGICAL TREATMENT SYSTEM

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, September 30, 2021

**Inspection Performed by:** Mike Gelwick

## J. TOTALIZERS

| Item | Readings (gallons) | Comments |
|---|---|---|
| FT-3321 Feed to Reactor 1 | 5930468 | |
| FT-3324 Feed Spare | 87149 | |
| FT-3322 Feed to Reactor 2 | 10644830 | |
| FT-3323 Feed to Reactor 3 | 646100 | |
| FT-3301 T-510 to BIO | 57452180 | |
| FT-3341 BIO Effluent | 66232818 | |
| FT-3342 BIO Recycle | 55377411 | |

## K. SAFETY

| Item | Status | Comments |
|---|---|---|
| Building #2 Fire Extinguishers | ✓ | Inspection date: 9-30-21 |
| Building #2 Eye Wash/Shower | ✓ | Checked and Flushed- All OK: (Y) / N |

## L. OTHER COMMENTS:

| |
|---|
| |
| |
| |
| |

# ABLE 3.19.1
# STANDARD OPERATIONS CHECKLIST
# MAIN WTP

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, October 07, 2021

**Inspection Performed by:** Mike Gelwick

### A. PERIMETER COLLECTION SYSTEMS

| Item | Status | Comments |
|---|---|---|
| LFG Cond Automatic Trap CT-1 | Sump Level: 12.48 oc | Counter: 184155 Cycles: 851 |
| LFG Cond Automatic Trap CT-2 | Sump Level: 8.65 oc | Counter: 274231 Cycles: 52 |
| LFG Cond Automatic Trap CT-3 | Sump Level: 7.23 oc | Counter: 306221 Cycles: 965 |
| CT-4 Containment/Vessel (LFG Cond) | ✓ Level: 72 % | Tank Level: 2.13 Counter: 191242 Cycles: 0 Sump: 8.54 oc |
| PM-15 Containment / Vessel | ✓ Level: 52 % | |
| MW-51 Containment / Vessel | ✓ Level: 40 % | |
| PM-11 Containment / Vessel | ✓ Level: 40 % | |
| MW-38 Systems | ✓ | |
| North Toe System | ✓ | |
| North End Systems (Weekly) | ✓ | |
| Full N. End Systems Check (Monthly) | ✓ | Last Done: 9-24-21 |
| North End Pipeline(s)Flushing (As Needed) | ✓ | Perform if suspended solids present Last Done: 11/15/15 |
| NTES line flush to T-530 (As needed) | ✓ | Perform if suspended solids present Last Done: 2/13/20 |
| NTES Piping Containment | ✓ | Monthly Sump Level: Dry 216.07' Date: 9-23-21 |
| North Boundary System P-001: | CV 74.9 % @ 7.1 gpm | 41.71 Hz / 2.10 Amps. / vault psi @ 18/no leaks |
| T-101 & T-102 Containment / Tank | ✓ | Levels: 40 % & 39 % |
| Raw Water Storage Tanks Piping | ✓ | |
| RWST Building Temp. (TT-101) | 63.7 °F | Outside Temp.: ~ 58 °F |
| (P-121) or P-122 | ✓ | 2.0 gpm / CV 57 % |
| RWST 2ndry Cont. High Level Switch | ✓ | (LSH-101) Last Test(monthly): 9-23-21 |
| RWST Back-Up Generator | ✓ | Last Test Run(monthly): 9-23-21 |

### B. CHEMICAL STORAGE BAYS

| Item | Status | Comments |
|---|---|---|
| Caustic Tote Levels | ✓ | ~ 715 Gallons Reserve = 3 totes |
| Caustic Bay Heater | ✓ | |
| Peroxide Tote Level | ✓ | ~ 250 Gallons Reserve = ~55 gal |
| HCL Tote Levels | ✓ | ~ 54 Gallons Reserve = 1 tote + 30 gal |
| Chemical Totes and Piping Inspected | ✓ | Leaks observed: Y / (N) |
| Emergency Shower Inspected | ✓ | Checked and Flushed - All OK: (Y) / N |

### C. PRIMARY AND SECONDARY ACID FEED SYSTEM

| Item | Status | Comments |
|---|---|---|
| Primary Acid Feed Pump (P-631) | ✓ | |
| Ion Exchange Acid Feed Pump (P-632) | ✓ | PI-0632 PSI: 78-82 CV: 7 % |
| Primary Acid Retention Tank (T-510) | ✓ | |
| All Acid Feed Lines | ✓ | Leaks observed: Y / (N) |

### D. NBBW INJECTION TRENCH

| Item | Status | Comments |
|---|---|---|
| Injection Carbon (GAC-810) | **OFFLINE** | Date online: 7/20/18 |
| Injection Rate (FT-800) | 0.0 gpm | NBBW-IW-1= 0.0 NBBW-IW-2= 0.0 NBBW-IW-3= 0.0 gpm ea. |
| Totalizer Reading (FT-800) | 105,135,774 gal | INJ. STOPPED 10/02/18 @ 1545 |

# ABLE 3.19.1
# STANDARD OPERATIONS CHECKLIST
# MAIN WTP

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, October 07, 2021

**Inspection Performed by:** Mike Gelwick

### E. CHEMICAL PRECIPITATION SYSTEM (US FILTER HMR-30)

| Item | Status | Comment |
|---|---|---|
| T-300A Mixer | NA | |
| T-300B (Caustic Mixer) | ✓ | Last Cleaning (Qtrly): 6-3-21 |
| T-300A/B Water Level | ✓ | |
| T-300B (Caustic Mix Chamber) | ✓ | Last Cleaning (Qtrly): 6-3-21 |
| T-300A/B Overflow | ✓ | |
| pH Set-point for (pH 315) | Value: 10.8 | |
| pH 310 | Value: 7.07 | |
| pH 315 | Value: 10.91 | |
| Flocculation Chamber Paddle Wheel | ✓ | |
| Precipitate Floc Quality | ✓ | Good |
| Clarifier Water Quality | ✓ | Good Oil or sheen observed: Y / (N) |
| Clarifier Effluent Piping / Water Level | ✓ | |
| Clear-well Chamber and Water Level | ✓ | |
| HMR PLC Panel | ✓ | |
| Caustic Pump (P-270) | SB | |
| Caustic Pump (P-280) | ✓ | |
| Polymer Pump (P-310) | ✓ | |
| Polymer Tank Mixer | ✓ | |
| Polymer Tank Level | Gallons: ~375 | |
| Clear-well Transfer Pumps (P-371 / 372) | ✓ | |
| Sludge Transfer Pump (P-330) | ✓ | Exercise Valves Weekly: Both ok |
| Manual Sludge Lateral pumping | ✓ | Last done (As Needed): #3-7-20-21 / #12-3-20-21 |
| Manual Sludge Lateral Ball Valves | ✓ | Exercise Weekly: |
| Automatic Blow-down Operations | ✓ | |

### F. pH PROBES

| pH Probe Location | Calibration Date | Comments: (Time done) |
|---|---|---|
| pH-310 HMR-30 (T-300A) | 10-7-21 - today | 1233 |
| pH-315 HMR-30 (T-300B) | | |
| pH-365 Primary Acid Ret. Tank | | |
| pH-113 Pre-Ion Exchange | | |
| pH-670 Pre-UV-OX | | 1335 |
| pH-740 Discharge Surge Tank | | Discharge suspended: 1226 ↔ 1232 |
| Out of Hold Double Check | ---------- | None in hold: ✓✓ |
| Valves Back to Normal Position | ---------- | All OK: ✓✓ |

### G. SLUDGE THICKENER, SLUDGE HOLDING TANKS, FILTER PRESS

| Item | Status | Comments |
|---|---|---|
| Verify Sludge Thickener Running | ✓ | Gauge Reading: 0 % |
| Sludge Thick. Transfer Pump (P-350) | ✓ | |
| Sludge Holding Tank (T-351) | ✓ | Level: ~55 % |
| Sludge Holding Tank (T-352) | ✓ | Level: 44 % |
| Decant Transfer Pump (P-352) | ✓ | CV 56 % @ 0.5 gpm |
| Filter Press Pumps (P-381 / P-382) | ✓ | |
| Filter Press | ✓ | Stage: 4 / currently pumping from T-351 |

# ABLE 3.19.1
# STANDARD OPERATIONS CHECKLIST
# MAIN WTP

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, October 07, 2021

**Inspection Performed by:** Mike Gelwick

### H. ION EXCHANGE

| Item | Status | Comments |
|---|---|---|
| Feed Tank (T-113) | ✓ Level: 47 % | |
| Feed Pump (P-114) | ✓ Operating Press: 51.7 psi | CV@ 100 % @ 3.3 gpm |
| Retention Tank (T-114) | ✓ Operating Press: 50 psi | pH-113 @ 3.56 |
| Bag Filter (BF-113) | ✓ Operating Press: 54 psi | |
| Ion Exchange (Cage (1) or 2) + Guard | ✓ Operating Press: 49 psi | TP-173A-2 → TP-175A / 4 cartridges + GAC |
| Post Ion Exchange | ✓ Operating Press: 4 psi | |

### I. FEED SURGE TANK

| Item | Status | Comments |
|---|---|---|
| Feed Surge Tank (T-520) | ✓ Level: 38 % | Last Cleaning (As Needed, if 4" of solids accumulate): 12/15/19 |
| Feed Surge Pump (P-521 or (P-522)) | Operating Press: 25 psi | CV@ 69 % @ 35.9 gpm |
| T-520 to GAC Total (FT-675) | 250510112 gal | Time: 1001 |
| North End On-Site Pumping | Operating Press: 2-3 psi | 13.2 gpm @ 0952 |
| North End Off-Site Pumping | Operating Press: 2-6 psi | 8.5 gpm @ 0952 |
| Peroxide Feed Pump (P-680) | ✓ | SPD 2.7 % / RATE 0.7 |
| Peroxide Conc. At (TP-710) | 1.0 PPM | |
| Peroxide Conc. At (TP-740) | 0.0 PPM | |

### J. HAZARDOUS WASTE STORAGE

| Item | Status | Comments |
|---|---|---|
| 180 Day storage area check | ✓ | Check sheet completed: NA/Empty |
| Satellite Haz. Waste Areas (BLDG #1) | ✓ | Condition: Exhaust + Main both Good |
| Satellite Haz. Waste Area (BLDG #2) | ✓ | Condition: Good |

### K. UV-OXIDATION SYSTEM

| Item | Status | Comments |
|---|---|---|
| UV-Oxidation System | ✓ | |
| Annual Test Run (Calgon) | Date: 9-16-21 | Next: 9-2022 |
| Quarterly Test Run | Date: NA/Running | Next: NA/Running |
| Peroxide Feed Pump (P-650) | ✓ | Flow Rate: ~ 7.0 cc/min. |
| UV-Ox Power | ✓ | 25.7 kVA 2587 Volts 9.9 Amps |
| Lamp Hours | 1653 Hrs | |
| Crystal Condition & Wiper Status | ✓ | Oiler status: OK |
| UV-OX Bagfilters Status | Last change: 7-13-21 Cleaned: 7-13-21 | 12.0 psi In 12.5 psi Out |
| UV-OX Feed Pump ((P-600) or P-601) | ✓ | CV@ 77 % @ 7.9 gpm |
| UV-OX Temperature | In(TT-670): 15.8 °C | Out(TT-710): 27.4 °C |
| PDU GAC (PDT-710) | ✓ | Δ Pressure: 4 psi |
| Peroxide Concentration Pre UV | 100 PPM | |
| Peroxide Concentration Post UV(TP-720) | 20 PPM | |
| Peroxide Conc. Post PDU (TP-730) | 0.0 PPM | |
| Secondary Acid Feed Pump (P-630) | ✓ | CV @ 3 % |
| Secondary Acid Retention Tank (T-645) | ✓ | |
| Pre – UV Oxidizer Total (FT-670) | 19912158 gal | Time: 1001 |
| Post UV-Ox / Pre PDU | ✓ | Pressure: 14 psi |
| Post PDU | ✓ | Pressure: 7.75 psi |

# ABLE 3.19.1
# STANDARD OPERATIONS CHECKLIST
# MAIN WTP

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, October 07, 2021

**Inspection Performed by:** Mike Gelwick

### L. PDU AND LIQUID –PHASE GRANULAR ACTIVATED CARBON

| Item | Status | Comments |
|---|---|---|
| PDT-720 | ✓ | Δ Pressure: 14 psi |
| PDT-730 | ✓ | Δ Pressure: 5 psi |

### M. EFFLUENT DISCHARGE

| Item | Status | Comments |
|---|---|---|
| Effluent Surge Pump ( P751 or (P752) ) | ✓ | CV@ 56.9 % |
| Effluent Surge Tank (T-740) | ✓ | Level: 40 % |
| Effluent Discharge Rate (FT-770) | ✓ | 36.5 gpm @ 0959 |
| POTW Line Pressure (PT-770) | ✓ | 33.0 psi |
| Effluent Totalizer Reading (FT-770) | 244620682 gal | Time: 1002 |
| POTW MH17S-078 Discharge Check (Monthly) | ✓ | Last Done: 9-27-21 |
| 4X8-Inch POTW Leak Detection Checks (Monthly) | ✓ | Last Done: ↓ |
| 4X8-Inch POTW Air Reliefs Checks (Monthly) | ✓ | Last Done: ↓ |
| 4X8-Inch POTW Isolation Valves Exercise (Qtrly) | ✓ | Last Done: 7-19-21 |
| 2-Inch POTW Backup Pressure Testing (Annual) | ✓ | Last Done: 7/8/21 |
| 2-In POTW Backup Air Reliefs Checks (Annual) | ✓ | Last Done: 7/8/21 |
| 2-Inch POTW Isolation Valve Exercise (Annual) | ✓ | Last Done: 7/8/21 |
| Rotate Chiller Compressors | NA on Standby | ~~Now in Lead: 1 or 2~~ |

### N. LEL EFFLUENT TANK T-740

| Item | Status | Comments |
|---|---|---|
| LEL-740 Sensor | ✓ | Reading: 0 % |
| LEL Sensor Calibration / Automatic High LEL Shutdown Test (monthly) | Last Completed: 9-30-21 | Plant Effluent Suspended: 1350 ↔ 1410 |
| LEL Sensor Bridge Adjustment to 2.0 volts | Reading: 2.001 volts(monthly) | Adjustment Needed: Ⓨ or N |
| Verify Bridge Current between.300v-.360v | Reading: 0.331 volts(monthly) | minor - 49.3→49.0% / 2.003→2.001 |

### O. WTP INFLUENT TOTALIZERS Time : 1002-1006

| Source | Reading(Gallons) | Source | Reading(Gallons) |
|---|---|---|---|
| (FT-015) RWST Influent | 19644964 | (FT-505) LFG Cond. to T-530 | 217084 |
| (FT-025) NBBW Influent | 93848365 | (FT-056) Off - Site N. End Influent | 42948728 |
| (FT-012) MW-38 Inf. to HMR-30 | 8227969 | (FT-113) Ion Exchange Influent | 707971 |
| (FT-042 HMR30) MW-38 Source to HMR-30 | 35484 | (FT-810) Plant Potable Water In | 30060484 |
| (FT-043) MW-38 to RWST | 3073983 | (FT-026) NBBW Bypass to RWST | 4391497 |
| (FT-042 RWST) MW-38 Source to RWST | 72236 | (FT-014) Misc. Water to RWST | 8162856 |
| (FT-012T) MW-38 to T-540/541 | 8608152 | (FT-035) NTES Inf. to BIO | 6649651 |
| (FT-040T) MW-38N to T-540/541 | 1977498 | (FT-035T) NTES to T-530 | 460540 |
| (FT-041T) MW-38S to T-540/541 | 26955519 | (FT-017) BIO Inf. from T-530 | 651889 |
| (FT-042T) MW-38 Source to T-540/541 | 4007125 | (FT-018) T-540/541 Influent | 8655969 |
| (FT-055) On - Site N. End Influent | 97780912 | (FT-352) T-352 to HMR-30 | 1285906 |

# ABLE 3.19.1
# STANDARD OPERATIONS CHECKLIST
# MAIN WTP

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, October 07, 2021

**Inspection Performed by:** Mike Gelwick

### P. AIR COMPRESSORS

| Item | Status | Comments |
|---|---|---|
| Compressor Intake Temp. | 59 °F (Analog Gauge) | Outside Temp.: ~ 58 °F |
| Compressor Building Vent | ✓ | closed - operational |
| Primary Air Compressor (IRN30H) | 2,000 Hour service date: 7-8-21<br>Serviced @ 60952 Hours | Coolant present in sight glass: Ⓨ / N<br>Next service @ 62952 Hours<br>Current Hours @ 62160 |
| IRN30H Motor Speed | 31 % | |
| IRN30H Pressure | 114 psi | |
| IRN30H Moisture purge valve chk(Weekly) | ✓ | |
| IRN30H Intake Filter | ✓ | Date Last Changed: 9-30-21 |
| Air Tanks Moisture Purge Valves | Manually Activate(weekly) ✓ | Excessive Moisture: Y / Ⓝ |
| Backup Air Compressors (T-30 East and West) | ✓ | Both cool to touch: Ⓨ / N |
| Air Dryer | ✓ ECO on | Moisture at Receiver Tank: Y / Ⓝ |
| Oil Moisture Prevention (Monthly) | Last Done: 9-23-21 | Run at max speed by bleeding air from filter canister above/after air dryer for 2 hrs |
| Air Receiver Tank | ✓ | 108 psi |

### Q. SUMPS

| Item | Status | Comments |
|---|---|---|
| Bag Filter Sump | ✓ | |
| Wet Well Sump | ✓ | |

### R. GAS CHROMATOGRAPH

| Item | Status | Comments |
|---|---|---|
| GC Operational | ✓ | GC # checking UV-Ox Effluent: # 2 |
| Alarms Enabled | ✓ | cc-calibration + monthly 10-6-21 |
| GC Influent Filters | ✓ | |

### S. SAFETY

| Item | Status | Comments |
|---|---|---|
| Building #1 Fire Extinguishers | ✓ | Date inspected: 9-30-21 |
| Building #1 Eye Wash/Shower | ✓ | Checked and Flushed- All OK: Ⓨ / N |

**Other Comments:**

# TABLE 3.19.2
# STANDARD OPERATIONS CHECKLIST
# BIOLOGICAL TREATMENT SYSTEM

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, October 07, 2021

**Inspection Performed by:** Mike Gelwick

## A. PUMPS

| Item | Status | Flow Rate (gpm) | Pump Speed (CV%) | Discharge Pressure (psi) | Comments |
|---|---|---|---|---|---|
| **T-510 Pumps** | | | | | |
| P-3301 | ✓ | 3.38 | 48.7 % | 11.0 | |
| P-3301A | SB | – | – % | – | |
| **NTES Pump** P-002(Sump) / (P-002W(10R)) | ✓ | 0.53 | 48 % | P035: 36.37 / P038: 5.0 | Globules Observed at TP-130: Y / (N) Time: 0935 |
| **T-530** P-005 | ✓ | 0.20 | 36 % | 6.0 | |
| **T-540/541** P-006 | ✓ | 0.30 | 57 % | 4.0 | |
| **LFG COND Auto-Traps** | ✓ | 0.0 | NA | 5.0 | Between Cycles: (Y) / N |
| **Reactor Feed Pumps** | | | | | |
| P-3321 | ✓ | 2.64 | 74.1 % | 8.5 | |
| P-3322 | ✓ | 3.67 | 54.7 % | 6.0 | |
| P-3323 | ✓ | 2.64 | 61.5 % | 7.5 | |
| P-3324 | SB | – | – % | – | |
| **Reactor Effluent Pumps** | | | | | |
| P-3341 | ✓ | 2.02 | 36.4 % | 8.5 | |
| P-3341A | SB | – | – % | – | |

## B. BLOWERS

| Item | Status | Pressure (psi) | Temp (°F) | Next Scheduled Service (Qtrly) | Comments Last serviced on: 10-1-21 |
|---|---|---|---|---|---|
| B-3331 | ✓ | 4.26 | 140 | 12-2021 | Greased, Belt and Filter Checked: (Y) / N |
| B-3332 | SB | – | – | ↓ | Belt and Filter Checked: Y / (N) |
| B-3333 | ✓ | 4.39 | 144 | ↓ | Greased, Belt and Filter Checked: (Y) / N |
| B-3334 | ✓ | 4.30 | 140 | ↓ | Greased, Belt and Filter Checked: (Y) / N |

## C. REACTOR VENTILATION

| Item | Status | Comments |
|---|---|---|
| Vapor Carbon Contactor | ✓ | On-line: 2/10/18 |
| Reactor Vent Blower | ✓ | |
| Reactor Vent Booster | ✓ | |
| VTP-3350 | ✓ | PID Reading: 14.6 PPM |
| VTP-3360 | ✓ | PID Reading: 9.1 PPM |

# TABLE 3.19.2
# STANDARD OPERATIONS CHECKLIST
# BIOLOGICAL TREATMENT SYSTEM

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, October 07, 2021

**Inspection Performed by:** Mike Gelwick

## D. TANKS / REACTORS / SUMPS / CONTAINMENTS / PIPING / Chiller

| Item | Status | Comments |
|---|---|---|
| T-510 Post HMR-30 Mixing Tank | ✓ Level: 69 % | Last Cleaning (As needed, if 2" of solids accumulate): 7/14/21 |
| T-530 LFG Condensate / NTES Tank | ✓ Level: 24 % | |
| T-530 Mixer | ✓ | |
| LFG Condensate Conveyance Line | ✓ | Last Pressure Test: 7-19-21 Next: 7-2022 (Annual at a minimum or if flow drops off) |
| T-540/541 MW38 Tanks | Lvls: 33 % & 34% | |
| T-540/541 Mixers | ✓ | |
| Chiller | ✓ | Chiller Coolant Lvl: ~ – " Below full mark |
| Chiller Cooling Fins (as needed) | ✓ | Last Cleaning: 4/20/18 (unit on Standby) |
| Secondary Containments | ✓ | Heat Trace: On OK / (Off Warm out) |
| Feed Piping to Sedimentation Tank | ✓ | Last Back Flushing (Quarterly): 8-30-21 |
| T-3310 Sedimentation Tank | Visual Level: OK | Last Cleaning (As Needed, use TSS info to determine): 9/2021 |
| T-3320 Blend Tank | ✓ Level: 72 % | Last Cleaning (Semi Annual): 9-10-21 |
| T-3331 Reactor No. 1 | ✓ | Digital Displays: (GOOD) / Needs Attn |
| T-3332 Reactor No. 2 | ✓ | Digital Displays: (GOOD) / Needs Attn |
| T-3333 Reactor No. 3 | ✓ | Digital Displays: (GOOD) / Needs Attn |
| T-3334 Settling Tank | ✓ | Last Cleaning (Semi Annual): 9-10-21 |
| P-3334 Biosolids Pump | ✓ | |
| T-3340 Overflow Tank | ✓ Level: 30 % | |
| Recycle Valve to Blend Tank | ✓ | 4.03 gpm @ 1026 |
| Building Containment Sump | ✓ | Last Alarm Test Date (Monthly): 9-23-21 |

## E. CHEMICAL FEED SYSTEM

| Item | Status | Comments |
|---|---|---|
| Phosphorous Supply | ✓ | Bags: 16.9 Gallons: ~ 75 |
| Phosphorous Pump (P-2221) | ✓ | |
| Caustic Supply | ✓ | ~ 110 Gallons |
| Caustic Pump (P-2211) | SB | Currently in acid addition mode |
| Acid Supply | ✓ | ~ 40 Gallons |
| Acid Pump (P-2211) | ✓ | |
| Caustic Pump (P-2231) | ✓ Leaks: Y / (N) | Last tubing tip cleaning (monthly): 9-23-21 |
| Caustic Pump (P-2232) | ✓ Leaks: Y / (N) | Last tubing tip cleaning (monthly): ↓ |
| Caustic Pump (P-2233) | ✓ Leaks: Y / (N) | Last tubing tip cleaning (monthly): |

# TABLE 3.19.2
# STANDARD OPERATIONS CHECKLIST
# BIOLOGICAL TREATMENT SYSTEM

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, October 07, 2021

**Inspection Performed by:** Mike Gelwick

## F. pH Probes

| pH Probe Location | Calibration Date (Monthly) | Comments |
|---|---|---|
| pH-3320 Blend Tank | 9-30-21 | spray off clean tubes |
| pH-3331 Reactor 1 | ↓ | ↓ |
| pH-3332 Reactor 2 | | |
| pH-3333 Reactor 3 | | |

## G. FILTER SYSTEM

| Item | Status | Comments |
|---|---|---|
| BF-3340 a/b Status | ✓ | |
| Automatic Backwash | Cycle Count: 24 | reset to 3 gpm |
| BF-3340 a/b Differential Pressure | PSI: 3 | 15/12 ≈ 4.1 gpm |
| 75-micron Bags Last Cleaning | Date: 11-14-19 | |
| 75-micron Bags Last Inspection | Date: ↓ | |
| 75-micron Bags Last Changed | Date: ↓ | |
| GACF-3340 Status | ✓ | |
| GACF-3340 Differential Pressure | PSI: 5 | 12/7 ≈ 4.1 gpm |
| Last Backwash Performed | Date: 9-27-21 | |

## H. ELECTRICAL AND INSTRUMENTATION

| Item | Status | Comments |
|---|---|---|
| "BIO" Backup Generator | ✓ | Block Heater: On OK / (Off Warm Out) |
| Electrical Surge Suppressor | ✓ | |
| Motor Control Center | ✓ | |
| PLC | ✓ | UPS @ 97 min / 86 Events |
| HMI's | ✓ | |
| BTS Process KWH Meter | 1802536 KWH | Time: 1127 |
| Building#2 KWH Meter | 5230630 KWH | Time: 1127 |

## I. GAS CHROMATOGRAPHY

| Item | Status | Comments |
|---|---|---|
| GC Operational | ✓ | GC # checking BIO: #3 |
| Alarms Enabled | ✓ | GC-calibration + maint 10-6-21 |
| GC Influent Filters | ✓ | |

# TABLE 3.19.2
# STANDARD OPERATIONS CHECKLIST
# BIOLOGICAL TREATMENT SYSTEM

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, October 07, 2021

**Inspection Performed by:** Mike Gelwick

## J. TOTALIZERS

| Item | Readings (gallons) | Comments |
|---|---|---|
| FT-3321 Feed to Reactor 1 | 5952232 | |
| FT-3324 Feed Spare | 87149 | |
| FT-3322 Feed to Reactor 2 | 10675076 | |
| FT-3323 Feed to Reactor 3 | 667552 | |
| FT-3301 T-510 to BIO | 51469844 | |
| FT-3341 BIO Effluent | 66260823 | |
| FT-3342 BIO Recycle | 55418748 | |

## K. SAFETY

| Item | Status | Comments |
|---|---|---|
| Building #2 Fire Extinguishers | ✓ | Inspection date: 9-30-21 |
| Building #2 Eye Wash/Shower | ✓ | Checked and Flushed- All OK: (Y) / N |

## L. OTHER COMMENTS:

| |
|---|
| |
| |
| |
| |

# ABLE 3.19.1
# STANDARD OPERATIONS CHECKLIST
# MAIN WTP

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, October 14, 2021

**Inspection Performed by:** Mike Gelwick

## A. PERIMETER COLLECTION SYSTEMS

| Item | Status | Comments |
|---|---|---|
| LFG Cond Automatic Trap CT-1 | Sump Level: 13.00 ft | Counter: 186409 Cycles: 2254 |
| LFG Cond Automatic Trap CT-2 | Sump Level: 8.65 ft | Counter: 274231 Cycles: 0 |
| LFG Cond Automatic Trap CT-3 | Sump Level: 7.39 ft | Counter: 307080 Cycles: 859 |
| CT-4 Containment/Vessel (LFG Cond) | ✓ Level: 72 % | Tank Level: 2.13 Counter: 191244 Cycles: 2 Sump: 9.10 ft |
| PM-15 Containment / Vessel | ✓ Level: 60 % | |
| MW-51 Containment / Vessel | ✓ Level: 25 % | |
| PM-11 Containment / Vessel | ✓ Level: 25 % | |
| MW-38 Systems | ✓ | |
| North Toe System | ✓ | |
| North End Systems (Weekly) | ✓ | |
| Full N. End Systems Check (Monthly) | ✓ | Last Done: 9-24-21 |
| North End Pipeline(s)Flushing (As Needed) | ✓ | Perform if suspended solids present Last Done: 11/15/15 |
| NTES line flush to T-530 (As needed) | ✓ | Perform if suspended solids present Last Done: 2/13/20 |
| NTES Piping Containment | ✓ | Monthly Sump Level: Dry @ 16.07' Date: 9-25-21 |
| North Boundary System P-001: | CV 74.6% @ 7.0 gpm | 11.41 Hz / 2.09 Amps. / vault psi @ 19/wet leaks |
| T-101 & T-102 Containment / Tank | ✓ | Levels: 37 % & 38 % |
| Raw Water Storage Tanks Piping | ✓ | |
| RWST Building Temp. (TT-101) | 56.9 °F | Outside Temp.: ~ 42 °F |
| P-121 or P-122 | ✓ | 0.6 gpm / CV 49 % |
| RWST 2ndry Cont. High Level Switch | ✓ | (LSH-101) Last Test(monthly): 9-23-21 |
| RWST Back-Up Generator | ✓ | Last Test Run(monthly): 9-23-21 |

## B. CHEMICAL STORAGE BAYS

| Item | Status | Comments |
|---|---|---|
| Caustic Tote Levels | ✓ | ~~560~~ 560 Gallons Reserve = 3 totes |
| Caustic Bay Heater | ✓ | |
| Peroxide Tote Level | ✓ | ~ 225 Gallons Reserve = ~55 gal |
| HCL Tote Levels | ✓ | ~ 300 Gallons Reserve = ~70 gal |
| Chemical Totes and Piping Inspected | ✓ | Leaks observed: Y / (N) |
| Emergency Shower Inspected | ✓ | Checked and Flushed - All OK: (Y) / N |

## C. PRIMARY AND SECONDARY ACID FEED SYSTEM

| Item | Status | Comments |
|---|---|---|
| Primary Acid Feed Pump (P-631) | ✓ | |
| Ion Exchange Acid Feed Pump (P-632) | ✓ | PI-0632 PSI: 78-84 CV: 8 % |
| Primary Acid Retention Tank (T-510) | ✓ | |
| All Acid Feed Lines | ✓ | Leaks observed: Y / (N) |

## D. NBBW INJECTION TRENCH

| Item | Status | Comments |
|---|---|---|
| Injection Carbon (GAC-810) | OFFLINE | Date online: 7/20/18 |
| Injection Rate (FT-800) | 0.0 gpm | NBBW-IW-1= 0.0 NBBW-IW-2= 0.0 NBBW-IW-3= 0.0 gpm ea. |
| Totalizer Reading (FT-800) | 105,135,774 gal | INJ. STOPPED 10/02/18 @ 1545 |

# ABLE 3.19.1
# STANDARD OPERATIONS CHECKLIST
# MAIN WTP

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, October 14, 2021

**Inspection Performed by:** Mike Gelwick

### E. CHEMICAL PRECIPITATION SYSTEM (US FILTER HMR-30)

| Item | Status | Comment |
|---|---|---|
| T-300A Mixer | NA | |
| T-300B (Caustic Mixer) | ✓ | Last Cleaning (Qtrly): 6-3-21 |
| T-300A/B Water Level | ✓ | |
| T-300B (Caustic Mix Chamber) | ✓ | Last Cleaning (Qtrly): 6-3-21 |
| T-300A/B Overflow | ✓ | |
| pH Set-point for (pH 315) | Value: 10.8 | |
| pH 310 | Value: 7.31 | |
| pH 315 | Value: 10.96 | |
| Flocculation Chamber Paddle Wheel | ✓ | |
| Precipitate Floc Quality | ✓ | Good |
| Clarifier Water Quality | ✓ | Good Oil or sheen observed: Y / (N) |
| Clarifier Effluent Piping / Water Level | ✓ | |
| Clear-well Chamber and Water Level | ✓ | |
| HMR PLC Panel | ✓ | |
| Caustic Pump (P-270) | SB | |
| Caustic Pump (P-280) | ✓ | |
| Polymer Pump (P-310) | ✓ | |
| Polymer Tank Mixer | ✓ | |
| Polymer Tank Level | Gallons: ~500 | |
| Clear-well Transfer Pumps (P-371 / 372) | ✓ | |
| Sludge Transfer Pump (P-330) | ✓ | Exercise Valves Weekly: both ok |
| Manual Sludge Lateral pumping | ✓ | Last done (As Needed): #3-7-20-21/#2-3-20-21 |
| Manual Sludge Lateral Ball Valves | ✓ | Exercise Weekly: All ok |
| Automatic Blow-down Operations | ✓ | |

### F. pH PROBES

| pH Probe Location | Calibration Date | Comments: (Time done) |
|---|---|---|
| pH-310 HMR-30 (T-300A) | 10-14-21-Today | 1356 |
| pH-315 HMR-30 (T-300B) | | |
| pH-365 Primary Acid Ret. Tank | | |
| pH-113 Pre-Ion Exchange | | |
| pH-670 Pre-UV-OX | | 1435 |
| pH-740 Discharge Surge Tank | | Discharge suspended: 1348 ↔ 1355 |
| Out of Hold Double Check | ---------- | None in hold: ✓✓ |
| Valves Back to Normal Position | ---------- | All OK: ✓✓ |

### G. SLUDGE THICKENER, SLUDGE HOLDING TANKS, FILTER PRESS

| Item | Status | Comments |
|---|---|---|
| Verify Sludge Thickener Running | ✓ | Gauge Reading: 0 % |
| Sludge Thick. Transfer Pump (P-350) | ✓ | |
| Sludge Holding Tank (T-351) | ✓ | Level:~ 65 % |
| Sludge Holding Tank (T-352) | ✓ | Level: 45 % |
| Decant Transfer Pump (P-352) | ✓ | CV 60 % @ 0.7 gpm |
| Filter Press Pumps (P-381 / P-382) | ✓ | |
| Filter Press | ✓ | Stage: Empty ready to fill |

# ABLE 3.19.1
# STANDARD OPERATIONS CHECKLIST
# MAIN WTP

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, October 14, 2021

**Inspection Performed by:** Mike Gelwick

### H. ION EXCHANGE

| Item | Status | Comments |
|---|---|---|
| Feed Tank (T-113) | ✓ Level: 52 % | Not using TANK / currently Direct Feed Formula |
| Feed Pump (P-114) | ✓ Operating Press: 54.9 psi | CV@ 100 % @ 3.3 gpm |
| Retention Tank (T-114) | ✓ Operating Press: 50-52 psi | pH-113 @ 3.73 |
| Bag Filter (BF-113) | ✓ Operating Press: 54-56 psi | |
| Ion Exchange (Cage (1) or 2) + Guard | ✓ Operating Press: 50-52 psi | TP-173A-2 → TP-175A / 4 cartridges + Guard |
| Post Ion Exchange | ✓ Operating Press: 4 psi | |

### I. FEED SURGE TANK

| Item | Status | Comments |
|---|---|---|
| Feed Surge Tank (T-520) | ✓ Level: 38 % | Last Cleaning (As Needed, if 4" of solids accumulate): 12/15/19 |
| Feed Surge Pump (P-521 or (P-522)) | Operating Press: 27 psi | CV@ 70 % @ 34.8 gpm |
| T-520 to GAC Total (FT-675) | 250849872 gal | Time: 1018 |
| North End On-Site Pumping | Operating Press: 2-3 psi | 13.1 gpm @ 1011 |
| North End Off-Site Pumping | Operating Press: 2-6 psi | 8.5 gpm @ 1011 |
| Peroxide Feed Pump (P-680) | ✓ | SPD 2.6 % / RATE 0.7 |
| Peroxide Conc. At (TP-710) | 1.0 PPM | |
| Peroxide Conc. At (TP-740) | 0.00 PPM | |

### J. HAZARDOUS WASTE STORAGE

| Item | Status | Comments |
|---|---|---|
| 180 Day storage area check | ✓ | Check sheet completed: NA/Empty |
| Satellite Haz. Waste Areas (BLDG #1) | ✓ | Condition: Items mark Good |
| Satellite Haz. Waste Area (BLDG #2) | ✓ | Condition: Good |

### K. UV-OXIDATION SYSTEM

| Item | Status | Comments |
|---|---|---|
| UV-Oxidation System | ✓ | |
| Annual Test Run (Calgon) | Date: 9-16-21 | Next: 9-2022 |
| Quarterly Test Run | Date: NA/Running | Next: NA/Running |
| Peroxide Feed Pump (P-650) | ✓ | Flow Rate: ~ 7.0 cc/min. |
| UV-Ox Power | ✓ | 25.7 kVA 25-43 Volts 10.1 Amps |
| Lamp Hours | 1819 Hrs | |
| Crystal Condition & Wiper Status | ✓ | Oiler status: ok |
| UV-OX Bagfilters Status | Last change: 7-13-21 Cleaned: 7-13-21 | 12.0 psi In 12.5 psi Out |
| UV-OX Feed Pump ( P-600 or (P-601) ) | ✓ | CV@ 77 % @ 7.9 gpm |
| UV-OX Temperature | In(TT-670): 15.4 °C | Out(TT-710): 27.2 °C |
| PDU GAC (PDT-710) | ✓ | Δ Pressure: 4 psi |
| Peroxide Concentration Pre UV | 100 PPM | |
| Peroxide Concentration Post UV(TP-720) | 25 PPM | |
| Peroxide Conc. Post PDU (TP-730) | 0.00 PPM | |
| Secondary Acid Feed Pump (P-630) | ✓ | CV @ 3 % |
| Secondary Acid Retention Tank (T-645) | ✓ | |
| Pre – UV Oxidizer Total (FT-670) | 19989052 gal | Time: 1019 |
| Post UV-Ox / Pre PDU | ✓ | Pressure: 14 psi |
| Post PDU | ✓ | Pressure: 7.75 psi |

# ABLE 3.19.1
# STANDARD OPERATIONS CHECKLIST
# MAIN WTP

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, October 14, 2021

**Inspection Performed by:** Mike Gelwick

### L. PDU AND LIQUID –PHASE GRANULAR ACTIVATED CARBON

| Item | Status | Comments |
|---|---|---|
| PDT-720 | ✓ | Δ Pressure: 16 psi |
| PDT-730 | ✓ | Δ Pressure: 5 psi |

### M. EFFLUENT DISCHARGE

| Item | Status | Comments |
|---|---|---|
| Effluent Surge Pump ( P751 or (P752) ) | ✓ | CV@ 56.0 % |
| Effluent Surge Tank (T-740) | ✓ | Level: 40 % |
| Effluent Discharge Rate (FT-770) | ✓ | 358 gpm @ 1014 |
| POTW Line Pressure (PT-770) | ✓ | 32.6 psi |
| Effluent Totalizer Reading (FT-770) | 244966782 gal | Time: 1019 |
| POTW MH17S-078 Discharge Check (Monthly) | ✓ | Last Done: 9-27-21 |
| 4X8-Inch POTW Leak Detection Checks (Monthly) | ✓ | Last Done: ↓ |
| 4X8-Inch POTW Air Reliefs Checks (Monthly) | ✓ | Last Done: ↓ |
| 4X8-Inch POTW Isolation Valves Exercise (Qtrly) | ✓ | Last Done: 7-19-21 |
| 2-Inch POTW Backup Pressure Testing (Annual) | ✓ | Last Done: 7/8/21 |
| 2-In POTW Backup Air Reliefs Checks (Annual) | ✓ | Last Done: 7/8/21 |
| 2-Inch POTW Isolation Valve Exercise (Annual) | ✓ | Last Done: 7/8/21 |
| Rotate Chiller Compressors | NA on Standby | ~~Now in Lead: 1 or 2~~ |

### N. LEL EFFLUENT TANK T-740

| Item | Status | Comments |
|---|---|---|
| LEL-740 Sensor | ✓ | Reading: 0 % |
| LEL Sensor Calibration / Automatic High LEL Shutdown Test (monthly) | Last Completed: 9-30-21 | Plant Effluent Suspended: 1350 ↔ 1410 |
| LEL Sensor Bridge Adjustment to 2.0 volts | Reading: 2.001 volts(monthly) | Adjustment Needed: Ⓨ or N |
| Verify Bridge Current between.300v-.360v | Reading: 0.331 volts(monthly) | Minor - 49.3→49% / 2.003→2.001 |

### O. WTP INFLUENT TOTALIZERS Time : 1019-1024

| Source | Reading(Gallons) | Source | Reading(Gallons) |
|---|---|---|---|
| (FT-015) RWST Influent | 19657904 | (FT-505) LFG Cond. to T-530 | 217750 |
| (FT-025) NBBW Influent | 93917181 | (FT-056) Off - Site N. End Influent | 43026020 |
| (FT-012) MW-38 Inf. to HMR-30 | 8241469 | (FT-113) Ion Exchange Influent | 739408 |
| (FT-042 HMR30) MW-38 Source to HMR-30 | 35484 | (FT-810) Plant Potable Water In | 30061556 |
| (FT-043) MW-38 to RWST | 3074816 | (FT-026) NBBW Bypass to RWST | 43947255 |
| (FT-042 RWST) MW-38 Source to RWST | 72236 | (FT-014) Misc. Water to RWST | 8171793 |
| (FT-012T) MW-38 to T-540/541 | 8619022 | (FT-035) NTES Inf. to BIO | 6654584 |
| (FT-040T) MW-38N to T-540/541 | 1977936 | (FT-035T) NTES to T-530 | 460794 |
| (FT-041T) MW-38S to T-540/541 | 2695864 | (FT-017) BIO Inf. from T-530 | 652405 |
| (FT-042T) MW-38 Source to T-540/541 | 4017250 | (FT-018) T-540/541 Influent | 86588 51 |
| (FT-055) On - Site N. End Influent | 97913042 | (FT-352) T-352 to HMR-30 | 1288222 |

# ABLE 3.19.1
# STANDARD OPERATIONS CHECKLIST
# MAIN WTP

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, October 14, 2021

**Inspection Performed by:** Mike Gelwick

### P. AIR COMPRESSORS *Currently Running on Backups* Main Down currently *

| Item | Status | Comments |
|---|---|---|
| Compressor Intake Temp. | 60 °F (Analog Gauge) | Outside Temp.: ~ 45 °F |
| Compressor Building Vent | ✓ | open / ok |
| Primary Air Compressor (IRN30H) | 2,000 Hour service date: 7-8-21 Serviced @ 60952 Hours | Coolant present in sight glass: (Y) / N Next service @ 62952 Hours Current Hours @ NA / currently off |
| IRN30H Motor Speed | — % | |
| IRN30H Pressure | — psi | |
| IRN30H Moisture purge valve chk(Weekly): | — | |
| IRN30H Intake Filter | ✓ | Date Last Changed: 9-30-21 |
| Air Tanks Moisture Purge Valves | Manually Activate(weekly) ✓ | Excessive Moisture: Y / (N) |
| Backup Air Compressors (T-30 East and West) | ✓ Running | Both cool to touch: Y / (N) Running |
| Air Dryer | ✓ Eco on | Moisture at Receiver Tank: Y / (N) |
| Oil Moisture Prevention (Monthly) | Last Done: 9-23-21 | Run at max speed by bleeding air from filter canister above/after air dryer for 2 hrs |
| Air Receiver Tank | ✓ | 110 psi |

### Q. SUMPS

| Item | Status | Comments |
|---|---|---|
| Bag Filter Sump | ✓ | |
| Wet Well Sump | ✓ | |

### R. GAS CHROMATOGRAPH

| Item | Status | Comments |
|---|---|---|
| GC Operational | ✓ | GC # checking UV-Ox Effluent: #2 |
| Alarms Enabled | ✓ | CC- Calibrations + maint on 10-13-21 |
| GC Influent Filters | ✓ | |

### S. SAFETY

| Item | Status | Comments |
|---|---|---|
| Building #1 Fire Extinguishers | ✓ | Date inspected: 9-30-21 |
| Building #1 Eye Wash/Shower | ✓ | Checked and Flushed- All OK: (Y) / N |

**Other Comments:**

| |
|---|
| * Main compressor blew fuses last night and developed an air leak, leaving unit until dept. can. currently Running on back up compressors |
| |
| |
| |

# TABLE 3.19.2
# STANDARD OPERATIONS CHECKLIST
# BIOLOGICAL TREATMENT SYSTEM

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, October 14, 2021

**Inspection Performed by:** Mike Gelwick

## A. PUMPS

| Item | Status | Flow Rate (gpm) | Pump Speed (CV%) | Discharge Pressure (psi) | | Comments |
|---|---|---|---|---|---|---|
| **T-510 Pumps** | | | | | | |
| P-3301 | ✓ | 1.83 | 31.8 % | 6.5 | | |
| P-3301A | SB | – | – % | – | | |
| **NTES Pump** P-002(Sump) / (P-002W(10R)) | ✓ | 0.50 | 48 % | P035 34-35 | P038 6.5 | Globules Observed at TP-130: Y / (N) Time: 0955 |
| **T-530** P-005 | ✓ | 0.21 | 41 % | 6.5 | | |
| **T-540/541** P-006 | ✓ | 0.29 | 57 % | 5.5 | | |
| **LFG COND Auto-Traps** | ✓ | 0.0 | NA | 5.0 | | Between Cycles: (Y) / N |
| **Reactor Feed Pumps** | | | | | | |
| P-3321 | ✓ | 2.48 | 45.8 % | 4.5 | | |
| P-3322 | ✓ | 3.24 | 42.1 % | 4.5 | | |
| P-3323 | ✓ | 2.42 | 66.1 % | 4.5 | | |
| P-3324 | SB | – | – % | – | | |
| **Reactor Effluent Pumps** | | | | | | |
| P-3341 | ✓ | 3.09 | 50.1 % | 14.0 | | |
| P-3341A | SB | – | – % | – | | |

## B. BLOWERS

| Item | Status | Pressure (psi) | Temp (°F) | Next Scheduled Service (Qtrly) | Comments Last serviced on: 10-1-21 |
|---|---|---|---|---|---|
| B-3331 | ✓ | 4.29 | 130 | 12-2021 | Greased, Belt and Filter Checked: (Y) / N |
| B-3332 | SB | – | – | ↓ | Belt and Filter Checked: Y / (N) |
| B-3333 | ✓ | 4.50 | 132 | ↓ | Greased, Belt and Filter Checked: (Y) / N |
| B-3334 | ✓ | 4.33 | 130 | ↓ | Greased, Belt and Filter Checked: (Y) / N |

## C. REACTOR VENTILATION

| Item | Status | Comments |
|---|---|---|
| Vapor Carbon Contactor | ✓ | On-line: 2/10/18 |
| Reactor Vent Blower | ✓ | |
| Reactor Vent Booster | ✓ | |
| VTP-3350 | ✓ | PID Reading: 19.6 PPM |
| VTP-3360 | ✓ | PID Reading: 12.8 PPM |

# TABLE 3.19.2
# STANDARD OPERATIONS CHECKLIST
# BIOLOGICAL TREATMENT SYSTEM

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, October 14, 2021

**Inspection Performed by:** Mike Gelwick

## D. TANKS / REACTORS / SUMPS / CONTAINMENTS / PIPING / Chiller

| Item | Status | Comments |
|---|---|---|
| T-510 Post HMR-30 Mixing Tank | ✓ Level: 62 % | Last Cleaning (As needed, if 2" of solids accumulate): 7/14/21 |
| T-530 LFG Condensate / NTES Tank | ✓ Level: 30 % | |
| T-530 Mixer | ✓ | |
| LFG Condensate Conveyance Line | ✓ | Last Pressure Test: 7-19-21 Next: 7-2022 (Annual at a minimum or if flow drops off) |
| T-540/541 MW38 Tanks | Lvls: 90 % & 91 % | |
| T-540/541 Mixers | ✓ ✗ | T-541 Runs a little wobble and trips Breaker. Needs replaced. |
| Chiller | ✓ | Chiller Coolant Lvl: ~ — " Below full mark |
| Chiller Cooling Fins (as needed) | ✓ | Last Cleaning: 4/20/18 (unit on Standby) |
| Secondary Containments | ✓ | Heat Trace: On OK / (Off Warm out) |
| Feed Piping to Sedimentation Tank | ✓ | Last Back Flushing (Quarterly): 10-13-21 |
| T-3310 Sedimentation Tank | Visual Level: OK | Last Cleaning (As Needed, use TSS info to determine): 9/2021 |
| T-3320 Blend Tank | ✓ Level: 72 % | Last Cleaning (Semi Annual): 9-10-21 |
| T-3331 Reactor No. 1 | ✓ | Digital Displays: (GOOD) / Needs Attn |
| T-3332 Reactor No. 2 | ✓ | Digital Displays: (GOOD) / Needs Attn |
| T-3333 Reactor No. 3 | ✓ | Digital Displays: (GOOD) / Needs Attn |
| T-3334 Settling Tank | ✓ | Last Cleaning (Semi Annual): 9-10-21 |
| P-3334 Biosolids Pump | ✓ | |
| T-3340 Overflow Tank | ✓ Level: 32 % | |
| Recycle Valve to Blend Tank | ✓ | 4.01 gpm @ 1052 |
| Building Containment Sump | ✓ | Last Alarm Test Date (Monthly): 9-23-21 |

## E. CHEMICAL FEED SYSTEM

| Item | Status | Comments |
|---|---|---|
| Phosphorous Supply | ✓ | Bags: 16.75 Gallons: ~ 45 |
| Phosphorous Pump (P-2221) | ✓ | |
| Caustic Supply | ✓ | ~ 104 Gallons |
| Caustic Pump (P-2211) | SB | Currently in acid addition mode |
| Acid Supply | ✓ | ~ 40 Gallons |
| Acid Pump (P-2211) | ✓ | |
| Caustic Pump (P-2231) | ✓ Leaks: Y / (N) | Last tubing tip cleaning (monthly): 9-23-21 |
| Caustic Pump (P-2232) | ✓ Leaks: Y / (N) | Last tubing tip cleaning (monthly): |
| Caustic Pump (P-2233) | ✓ Leaks: Y / (N) | Last tubing tip cleaning (monthly): |

# TABLE 3.19.2
# STANDARD OPERATIONS CHECKLIST
# BIOLOGICAL TREATMENT SYSTEM

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, October 14, 2021

**Inspection Performed by:** Mike Gelwick

## F. pH Probes

| pH Probe Location | Calibration Date (Monthly) | Comments |
|---|---|---|
| pH-3320 Blend Tank | 9-30-21 | Spray off clean today |
| pH-3331 Reactor 1 | ↓ | ↓ |
| pH-3332 Reactor 2 | | |
| pH-3333 Reactor 3 | | |

## G. FILTER SYSTEM

| Item | Status | Comments |
|---|---|---|
| BF-3340 a/b Status | ✓ | |
| Automatic Backwash | Cycle Count: 23 | reset |
| BF-3340 a/b Differential Pressure | PSI: 1 | 5/6 21.6 gpm |
| 75-micron Bags Last Cleaning | Date: 11-14-19 | |
| 75-micron Bags Last Inspection | Date: ↓ | |
| 75-micron Bags Last Changed | Date: | |
| GACF-3340 Status | ✓ | |
| GACF-3340 Differential Pressure | PSI: 1 | 6/7 21.6 gpm |
| Last Backwash Performed | Date: 9-27-21 | |

## H. ELECTRICAL AND INSTRUMENTATION

| Item | Status | Comments |
|---|---|---|
| "BIO" Backup Generator | ✓ | Tested ran on OK. Block Heater: On OK / (Off Warm Out) |
| Electrical Surge Suppressor | ✓ | |
| Motor Control Center | ✓ | |
| PLC | ✓ | UPS @ 97 min / 88 Events |
| HMI's | ✓ | |
| BTS Process KWH Meter | 1804702 KWH | Time: 1256 |
| Building#2 KWH Meter | 5234457 KWH | Time: 1256 |

## I. GAS CHROMATOGRAPHY

| Item | Status | Comments |
|---|---|---|
| GC Operational | ✓ | GC # checking BIO: #3 |
| Alarms Enabled | ✓ | cc-calibration + maint 10-13-21 |
| GC Influent Filters | ✓ | |

# TABLE 3.19.2
# STANDARD OPERATIONS CHECKLIST
# BIOLOGICAL TREATMENT SYSTEM

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, October 14, 2021

**Inspection Performed by:** Mike Gelwick

## J. TOTALIZERS

| Item | Readings (gallons) | Comments |
|---|---|---|
| FT-3321 Feed to Reactor 1 | 5974163 | |
| FT-3324 Feed Spare | 87155 | |
| FT-3322 Feed to Reactor 2 | 10705518 | |
| FT-3323 Feed to Reactor 3 | 689163 | |
| FT-3301 T-510 to BIO | 51489391 | |
| FT-3341 BIO Effluent | 66288744 | |
| FT-3342 BIO Recycle | 55460594 | |

## K. SAFETY

| Item | Status | Comments |
|---|---|---|
| Building #2 Fire Extinguishers | ✓ | Inspection date: 9-30-21 |
| Building #2 Eye Wash/Shower | ✓ | Checked and Flushed- All OK: (Y) / N |

## L. OTHER COMMENTS:

| |
|---|
| |
| |
| |
| |

# ABLE 3.19.1
# STANDARD OPERATIONS CHECKLIST
# MAIN WTP

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, October 21, 2021

**Inspection Performed by:** Mike Gelwick

### A. PERIMETER COLLECTION SYSTEMS

| Item | Status | Comments |
|---|---|---|
| LFG Cond Automatic Trap CT-1 | Sump Level: 12.42 ok | Counter: 186490 Cycles: 81 |
| LFG Cond Automatic Trap CT-2 | Sump Level: 8.62 ok | Counter: 274305 Cycles: 74 |
| LFG Cond Automatic Trap CT-3 | Sump Level: 7.29 ok | Counter: 307538 Cycles: 458 |
| CT-4 Containment/Vessel (LFG Cond) | ✓ Level: 72 % | Tank Level: 2.13 Counter: 191244 Cycles: 0 Sump: 8.89 ok |
| PM-15 Containment / Vessel | ✓ Level: 65 % | |
| MW-51 Containment / Vessel | ✓ Level: 50 % | |
| PM-11 Containment / Vessel | ✓ Level: 40 % | |
| MW-38 Systems | ✓ | |
| North Toe System | ✓ | |
| North End Systems (Weekly) | ✓ | |
| Full N. End Systems Check (Monthly) | ✓ | Last Done: 9-24-21 |
| North End Pipeline(s)Flushing (As Needed) | ✓ | Perform if suspended solids present Last Done: 11/15/15 |
| NTES line flush to T-530 (As needed) | ✓ | Perform if suspended solids present Last Done: 2/13/20 |
| NTES Piping Containment | ✓ | Monthly Sump Level: dry @ 16.07' Date: 10-21-21 - Today |
| North Boundary System P-001: | CV 74.4 % @ 6.9 gpm | 41.27 Hz / 7.09 Amps. / vault psi @ 18 / no leaks |
| T-101 & T-102 Containment / Tank | ✓ | Levels: 30 % & 30 % |
| Raw Water Storage Tanks Piping | ✓ | |
| RWST Building Temp. (TT-101) | 57.0 °F | Outside Temp.: ~ 49 °F |
| (P-121) or P-122 | ✓ | 0.60 gpm / CV 55 % |
| RWST 2ndry Cont. High Level Switch | ✓ | (LSH-101) Last Test(monthly): 10-21-21 |
| RWST Back-Up Generator | ✓ | Last Test Run(monthly): 10-21-21 TEST clock hour ok |

### B. CHEMICAL STORAGE BAYS

| Item | Status | Comments |
|---|---|---|
| Caustic Tote Levels | ✓ | ~ 425 Gallons Reserve = 3 totes |
| Caustic Bay Heater | ✓ | |
| Peroxide Tote Level | ✓ | ~ 200 Gallons Reserve = ~55 gal |
| HCL Tote Levels | ✓ | ~ 275 Gallons Reserve = ~70 gal |
| Chemical Totes and Piping Inspected | ✓ | Leaks observed: Y / (N) |
| Emergency Shower Inspected | ✓ | Checked and Flushed - All OK: (Y) / N |

### C. PRIMARY AND SECONDARY ACID FEED SYSTEM

| Item | Status | Comments |
|---|---|---|
| Primary Acid Feed Pump (P-631) | ✓ | |
| Ion Exchange Acid Feed Pump (P-632) | ✓ | PI-0632 PSI: 78-82 CV: 7 % |
| Primary Acid Retention Tank (T-510) | ✓ | |
| All Acid Feed Lines | ✓ | Leaks observed: Y / (N) |

### D. NBBW INJECTION TRENCH

| Item | Status | Comments |
|---|---|---|
| Injection Carbon (GAC-810) | **OFFLINE** | Date online: 7/20/18 |
| Injection Rate (FT-800) | 0.0 gpm | NBBW-IW-1= 0.0 NBBW-IW-2= 0.0 NBBW-IW-3= 0.0 gpm ea. |
| Totalizer Reading (FT-800) | 105,135,774 gal | INJ. STOPPED 10/02/18 @ 1545 |

# ABLE 3.19.1
# STANDARD OPERATIONS CHECKLIST
# MAIN WTP

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, October 21, 2021

**Inspection Performed by:** Mike Gelwick

### E. CHEMICAL PRECIPITATION SYSTEM (US FILTER HMR-30)

| Item | Status | Comment |
|---|---|---|
| T-300A Mixer | NA | |
| T-300B (Caustic Mixer) | ✓ | Last Cleaning (Qtrly): 10-20-21 |
| T-300A/B Water Level | ✓ | |
| T-300B (Caustic Mix Chamber) | ✓ | Last Cleaning (Qtrly): 10-20-21 |
| T-300A/B Overflow | ✓ | |
| pH Set-point for (pH 315) | Value: 10.80 | |
| pH 310 | Value: 6.92 | |
| pH 315 | Value: 10.93 | |
| Flocculation Chamber Paddle Wheel | ✓ | |
| Precipitate Floc Quality | ✓ | Good |
| Clarifier Water Quality | ✓ | Good Oil or sheen observed: Y / (N) |
| Clarifier Effluent Piping / Water Level | ✓ | |
| Clear-well Chamber and Water Level | ✓ | |
| HMR PLC Panel | ✓ | |
| Caustic Pump (P-270) | SB | |
| Caustic Pump (P-280) | ✓ | |
| Polymer Pump (P-310) | ✓ | |
| Polymer Tank Mixer | ✓ | |
| Polymer Tank Level | Gallons: ~ 425 | |
| Clear-well Transfer Pumps (P-371 / 372) | ✓ | |
| Sludge Transfer Pump (P-330) | ✓ | Exercise Valves Weekly: Both ok |
| Manual Sludge Lateral pumping | ✓ | Last done (As Needed): #3-7-20-21 / #42-3-20-21 |
| Manual Sludge Lateral Ball Valves | ✓ | Exercise Weekly: Allen |
| Automatic Blow-down Operations | ✓ | |

### F. pH PROBES

| pH Probe Location | Calibration Date | Comments: (Time done) |
|---|---|---|
| pH-310 HMR-30 (T-300A) | 10-21-21-Today | 1321 |
| pH-315 HMR-30 (T-300B) | | |
| pH-365 Primary Acid Ret. Tank | | |
| pH-113 Pre-Ion Exchange | | |
| pH-670 Pre-UV-OX | | 1352 |
| pH-740 Discharge Surge Tank | | Discharge suspended: 1314 ↔ 1320 |
| Out of Hold Double Check | ---------- | None in hold: ✓✓'d |
| Valves Back to Normal Position | ---------- | All OK: ✓✓'d |

### G. SLUDGE THICKENER, SLUDGE HOLDING TANKS, FILTER PRESS

| Item | Status | Comments |
|---|---|---|
| Verify Sludge Thickener Running | ✓ | Gauge Reading: 0 % |
| Sludge Thick. Transfer Pump (P-350) | ✓ | |
| Sludge Holding Tank (T-351) | ✓ | Level: ~ 45 % |
| Sludge Holding Tank (T-352) | ✓ | Level: 53 % |
| Decant Transfer Pump (P-352) | ✓ | CV 73 % @ 0.8 gpm |
| Filter Press Pumps (P-381 / P-382) | ✓ | |
| Filter Press | ✓ | Stage: Empty / currently getting washout |

# ABLE 3.19.1
# STANDARD OPERATIONS CHECKLIST
# MAIN WTP

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, October 21, 2021

**Inspection Performed by:** Mike Gelwick

### H. ION EXCHANGE

| Item | Status | Comments |
|---|---|---|
| Feed Tank (T-113) | ✓ Level: 48 % | Not using tank/currently direct Feed from well |
| Feed Pump (P-114) | ✓ Operating Press: 50.3 psi | CV@ 100 % @ 3.3 gpm |
| Retention Tank (T-114) | ✓ Operating Press: 49-52 psi | pH-113 @ 3.56 |
| Bag Filter (BF-113) | ✓ Operating Press: 50-54 psi | |
| Ion Exchange (Cage (1) or 2) + Guard | ✓ Operating Press: 49-51 psi | TP-173A-2 → TP-175A/4 canisters + Guard |
| Post Ion Exchange | ✓ Operating Press: 4 psi | |

### I. FEED SURGE TANK

| Item | Status | Comments |
|---|---|---|
| Feed Surge Tank (T-520) | ✓ Level: 38 % | Last Cleaning (As Needed, if 4" of solids accumulate): 12/15/19 |
| Feed Surge Pump (P-521 or (P-522)) | Operating Press: 30 psi | CV@ 73 % @ 35.3 gpm |
| T-520 to GAC Total (FT-675) | 251197040 gal | Time: 1030 |
| North End On-Site Pumping | Operating Press: 2-3 psi | 13.0 gpm @ 1024 |
| North End Off-Site Pumping | Operating Press: 2-6 psi | 8.8 gpm @ 1024 |
| Peroxide Feed Pump (P-680) | ✓ | SPD 2.7 % / RATE 0.7 |
| Peroxide Conc. At (TP-710) | 1.0 PPM | |
| Peroxide Conc. At (TP-740) | 0.0 PPM | |

### J. HAZARDOUS WASTE STORAGE

| Item | Status | Comments |
|---|---|---|
| 180 Day storage area check | ✓ | Check sheet completed: N/A/Empty |
| Satellite Haz. Waste Areas (BLDG #1) | ✓ | Condition: IX Resins + main Good |
| Satellite Haz. Waste Area (BLDG #2) | ✓ | Condition: Good |

### K. UV-OXIDATION SYSTEM

| Item | Status | Comments |
|---|---|---|
| UV-Oxidation System | ✓ | |
| Annual Test Run (Calgon) | Date: 9-16-21 | Next: 9-2022 |
| Quarterly Test Run | Date: N/A/Running | Next: N/A/Running |
| Peroxide Feed Pump (P-650) | ✓ | Flow Rate: ~ 7.2 cc/min. |
| UV-Ox Power | ✓ | 25.7 kVA 2522 Volts 10.1 Amps |
| Lamp Hours | 1985 Hrs | |
| Crystal Condition & Wiper Status | ✓ | Oiler status: ok |
| UV-OX Bagfilters Status | Last change: 7-13-21 Cleaned: 7-13-21 | 12.5 psi In 12.5 psi Out |
| UV-OX Feed Pump ( P-600 or (P-601) ) | ✓ | CV@ 77 % @ 8.0 gpm |
| UV-OX Temperature | In(TT-670): 15.3 °C | Out(TT-710): 27.1 °C |
| PDU GAC (PDT-710) | ✓ | Δ Pressure: 4 psi |
| Peroxide Concentration Pre UV | 100 PPM | |
| Peroxide Concentration Post UV(TP-720) | 25 PPM | |
| Peroxide Conc. Post PDU (TP-730) | 0.0 PPM | |
| Secondary Acid Feed Pump (P-630) | ✓ | CV @ 2 % |
| Secondary Acid Retention Tank (T-645) | ✓ | |
| Pre – UV Oxidizer Total (FT-670) | 200166008 gal | Time: 1030 |
| Post UV-Ox / Pre PDU | ✓ | Pressure: 14 psi |
| Post PDU | ✓ | Pressure: 8 psi |

# ABLE 3.19.1
# STANDARD OPERATIONS CHECKLIST
# MAIN WTP

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, October 21, 2021

**Inspection Performed by:** Mike Gelwick

### L. PDU AND LIQUID –PHASE GRANULAR ACTIVATED CARBON

| Item | Status | Comments |
|---|---|---|
| PDT-720 | ✓ | Δ Pressure: 19 psi |
| PDT-730 | ✓ | Δ Pressure: 5 psi |

### M. EFFLUENT DISCHARGE

| Item | Status | Comments |
|---|---|---|
| Effluent Surge Pump ( P751 or (P752)) | ✓ | CV@ 56.0 % |
| Effluent Surge Tank (T-740) | ✓ | Level: 40 % |
| Effluent Discharge Rate (FT-770) | ✓ | 36.1 gpm @ 1028 |
| POTW Line Pressure (PT-770) | ✓ | 32.6 psi |
| Effluent Totalizer Reading (FT-770) | 245320030 gal | Time: 1031 |
| POTW MH17S-078 Discharge Check (Monthly) | ✓ | Last Done: 10-19-21 |
| 4X8-Inch POTW Leak Detection Checks (Monthly) | ✓ | Last Done: ↓ |
| 4X8-Inch POTW Air Reliefs Checks (Monthly) | ✓ | Last Done: ↓ |
| 4X8-Inch POTW Isolation Valves Exercise (Qtrly) | ✓ | Last Done: 7-19-21 |
| 2-Inch POTW Backup Pressure Testing (Annual) | ✓ | Last Done: 7/8/21 |
| 2-In POTW Backup Air Reliefs Checks (Annual) | ✓ | Last Done: 7/8/21 |
| 2-Inch POTW Isolation Valve Exercise (Annual) | ✓ | Last Done: 7/8/21 |
| Rotate Chiller Compressors | NA on Standby | ~~Now in Lead: 1 or 2~~ |

### N. LEL EFFLUENT TANK T-740

| Item | Status | Comments |
|---|---|---|
| LEL-740 Sensor | ✓ | Reading: 0 % |
| LEL Sensor Calibration / Automatic High LEL Shutdown Test (monthly) | Last Completed: 9-30-21 | Plant Effluent Suspended: 1350 ↔ 1410 |
| LEL Sensor Bridge Adjustment to 2.0 volts | Reading: 2.001 volts(monthly) | Adjustment Needed: Ⓨ or N |
| Verify Bridge Current between.300v-.360v | Reading: 0.331 volts(monthly) | Minor - 49.3→49% / 2.003→2.001 |

### O. WTP INFLUENT TOTALIZERS Time : 1031-1041

| Source | Reading(Gallons) | Source | Reading(Gallons) |
|---|---|---|---|
| (FT-015) RWST Influent | 19663952 | (FT-505) LFG Cond. to T-530 | 217816 |
| (FT-025) NBBW Influent | 93985653 | (FT-056) Off - Site N. End Influent | 43108536 |
| (FT-012) MW-38 Inf. to HMR-30 | ~~35484~~ 8262319 | (FT-113) Ion Exchange Influent | 772887 |
| (FT-042 HMR30) MW-38 Source to HMR-30 | ~~3075411~~ 35484 | (FT-810) Plant Potable Water In | 30062980 |
| (FT-043) MW-38 to RWST | ~~72236~~ 3075411 | (FT-026) NBBW Bypass to RWST | 4396418 |
| (FT-042 RWST) MW-38 Source to RWST | ~~8619022~~ 72236 | (FT-014) Misc. Water to RWST | 8171793 |
| (FT-012T) MW-38 to T-540/541 | ~~1977936~~ 8619022 | (FT-035) NTES Inf. to BIO | 6659539 |
| (FT-040T) MW-38N to T-540/541 | ~~2695864~~ 1977936 | (FT-035T) NTES to T-530 | 461003 |
| (FT-041T) MW-38S to T-540/541 | ~~4017250~~ 2695864 | (FT-017) BIO Inf. from T-530 | 652921 |
| (FT-042T) MW-38 Source to T-540/541 | 4017250 | (FT-018) T-540/541 Influent | 8661759 |
| (FT-055) On - Site N. End Influent | 98044996 | (FT-352) T-352 to HMR-30 | 1291676 |

# ABLE 3.19.1
# STANDARD OPERATIONS CHECKLIST
# MAIN WTP

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, October 21, 2021

**Inspection Performed by:** Mike Gelwick

### P. AIR COMPRESSORS * Main VFD bad shut off/Running on backups

| Item | Status | Comments |
|---|---|---|
| Compressor Intake Temp. | 55 °F (Analog Gauge) | Outside Temp.: ~ 51 °F |
| Compressor Building Vent | ✓ | open/open-mesh |
| Primary Air Compressor (IRN30H) | 2,000 Hour service date: 7-8-21<br>Serviced @ 60952 Hours | Coolant present in sight glass: Ⓨ / N<br>Next service @ 62952 Hours<br>Current Hours @ N4/OFF |
| IRN30H Motor Speed | — % | |
| IRN30H Pressure | — psi | |
| IRN30H Moisture purge valve chk(Weekly): | ~ | |
| IRN30H Intake Filter | — | Date Last Changed: 9-30-31 |
| Air Tanks Moisture Purge Valves | Manually Activate(weekly) ✓ | Excessive Moisture: Y / Ⓝ |
| Backup Air Compressors (T-30 East and West) | Running | Both cool to touch: Y / Ⓝ |
| Air Dryer | ✓ | Moisture at Receiver Tank: Y / Ⓝ |
| Oil Moisture Prevention (Monthly) | Last Done: 9-23-21 | Run at max speed by bleeding air from filter canister above/after air dryer for 2 hrs |
| Air Receiver Tank | ✓ | 110 psi |

### Q. SUMPS

| Item | Status | Comments |
|---|---|---|
| Bag Filter Sump | ✓ | |
| Wet Well Sump | ✓ | |

### R. GAS CHROMATOGRAPH

| Item | Status | Comments |
|---|---|---|
| GC Operational | ✓ | GC # checking UV-Ox Effluent: #2 |
| Alarms Enabled | ✓ | CC-calibration & maint 10-20-21 |
| GC Influent Filters | ✓ | |

### S. SAFETY

| Item | Status | Comments |
|---|---|---|
| Building #1 Fire Extinguishers | ✓ | Date inspected: 9-30-21 |
| Building #1 Eye Wash/Shower | ✓ | Checked and Flushed- All OK: Ⓨ / N |

**Other Comments:**

| |
|---|
| * Main compressor has a bad VFD. Replacement on order. Repair planned |
| |
| |
| |
| |

# TABLE 3.19.2
# STANDARD OPERATIONS CHECKLIST
# BIOLOGICAL TREATMENT SYSTEM

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, October 21, 2021

**Inspection Performed by:** Mike Gelwick

## A. PUMPS

| Item | Status | Flow Rate (gpm) | Pump Speed (CV%) | Discharge Pressure (psi) | Comments |
|---|---|---|---|---|---|
| **T-510 Pumps** | | | | | |
| P-3301 | ✓ | 1.85 | 30.1 % | 6.5 | |
| P-3301A | SB | – | – % | – | |
| NTES Pump P-002(Sump) / (P-002W(10R)) | ✓ | 0.51 | 47 % | P035 34-35 / P038 7.5 | Globules Observed at TP-130: Y / (N) Time: 0935 |
| T-530 P-005 | ✓ | 0.19 | 41 % | 6.5 | |
| T-540/541 P-006 | ✓ | 0.30 | 63 % | 7.0 | |
| LFG COND Auto-Traps | ✓ | 0.0 | NA | 5 | Between Cycles: (Y) / N |
| **Reactor Feed Pumps** | | | | | |
| P-3321 | ✓ | 2.54 | 75.4 % | 10.0 | |
| P-3322 | ✓ | 3.51 | 58.8 % | 7.0 | |
| P-3323 | ✓ | 2.57 | 74.3 % | 5.0 | |
| P-3324 | SB | – | – % | – | |
| **Reactor Effluent Pumps** | | | | | |
| P-3341 | ✓ | 2.74 | 53.6 % | 19.0 | |
| P-3341A | SB | – | – % | – | |

## B. BLOWERS

| Item | Status | Pressure (psi) | Temp (°F) | Next Scheduled Service (Qtrly) | Comments Last serviced on: 10-1-21 |
|---|---|---|---|---|---|
| B-3331 | ✓ | 4.28 | 130 | 12-2021 | Greased, Belt and Filter Checked: (Y) / N |
| B-3332 | SB | – | – | ↓ | Belt and Filter Checked: Y / (N) |
| B-3333 | ✓ | 4.35 | 130 | ↓ | Greased, Belt and Filter Checked: (Y) / N |
| B-3334 | ✓ | 4.32 | 126 | ↓ | Greased, Belt and Filter Checked: (Y) / N |

## C. REACTOR VENTILATION

| Item | Status | Comments |
|---|---|---|
| Vapor Carbon Contactor | ✓ | On-line: 2/10/18 |
| Reactor Vent Blower | ✓ | |
| Reactor Vent Booster | ✓ | |
| VTP-3350 | ✓ | PID Reading: 21.7 PPM |
| VTP-3360 | ✓ | PID Reading: 17.2 PPM |

# TABLE 3.19.2
# STANDARD OPERATIONS CHECKLIST
# BIOLOGICAL TREATMENT SYSTEM

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, October 21, 2021

**Inspection Performed by:** Mike Gelwick

## D. TANKS / REACTORS / SUMPS / CONTAINMENTS / PIPING / Chiller

| Item | Status | Comments |
|---|---|---|
| T-510 Post HMR-30 Mixing Tank | ✓ Level: 71 % | Last Cleaning (As needed, if 2" of solids accumulate): 7/14/21 |
| T-520 LFG Condensate / NTES Tank | ✓ Level: 26 % | |
| T-530 Mixer | ✓ | |
| LFG Condensate Conveyance Line | ✓ | Last Pressure Test: 7-19-21 Next: 7-2022 (Annual at a minimum or if flow drops off) |
| T-540/541 MW38 Tanks | Lvls: 68 % & 69 % | |
| T-540/541 Mixers | ✓ | * T-541 needs new one. Replacement ordered |
| Chiller | ✓ | Chiller Coolant Lvl: ~ — " Below full mark |
| Chiller Cooling Fins (as needed) | ✓ | Last Cleaning: 4/20/18 (unit on Standby) |
| Secondary Containments | ✓ | Heat Trace: On OK / (Off Warm out) Check OK when cold |
| Feed Piping to Sedimentation Tank | ✓ | Last Back Flushing (Quarterly): 10-13-21 |
| T-3310 Sedimentation Tank | Visual Level: ok | Last Cleaning (As Needed, use TSS info to determine): 9/2021 |
| T-3320 Blend Tank | ✓ Level: 71 % | Last Cleaning (Semi Annual): 9-10-21 |
| T-3331 Reactor No. 1 | ✓ | Digital Displays: (GOOD) / Needs Attn |
| T-3332 Reactor No. 2 | ✓ | Digital Displays: (GOOD) / Needs Attn |
| T-3333 Reactor No. 3 | ✓ | Digital Displays: (GOOD) / Needs Attn |
| T-3334 Settling Tank | ✓ | Last Cleaning (Semi Annual): 9-10-21 |
| P-3334 Biosolids Pump | ✓ | |
| T-3340 Overflow Tank | Level: 30 % | |
| Recycle Valve to Blend Tank | ✓ | 4.00 gpm @ 1055 |
| Building Containment Sump | ✓ | Last Alarm Test Date (Monthly): 10-21-21 - today |

## E. CHEMICAL FEED SYSTEM

| Item | Status | Comments |
|---|---|---|
| Phosphorous Supply | ✓ | Bags: 16.50 Gallons: ~ 60 |
| Phosphorous Pump (P-2221) | ✓ | |
| Caustic Supply | ✓ | ~ 85 Gallons |
| Caustic Pump (P-2211) | SB | Currently in acid addition mode |
| Acid Supply | ✓ | ~ 40 Gallons |
| Acid Pump (P-2211) | ✓ | |
| Caustic Pump (P-2231) | ✓ Leaks: Y / (N) | Last tubing tip cleaning (monthly): 10-21-21 - today |
| Caustic Pump (P-2232) | ✓ Leaks: Y / (N) | Last tubing tip cleaning (monthly): |
| Caustic Pump (P-2233) | ✓ Leaks: Y / (N) | Last tubing tip cleaning (monthly): |

# TABLE 3.19.2
# STANDARD OPERATIONS CHECKLIST
# BIOLOGICAL TREATMENT SYSTEM

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, October 21, 2021

**Inspection Performed by:** Mike Gelwick

### F. pH Probes

| pH Probe Location | Calibration Date (Monthly) | Comments |
|---|---|---|
| pH-3320 Blend Tank | 9-30-21 | Acid/BASE clean today |
| pH-3331 Reactor 1 | ↓ | ↓ |
| pH-3332 Reactor 2 | | |
| pH-3333 Reactor 3 | | |

### G. FILTER SYSTEM

| Item | Status | Comments |
|---|---|---|
| BF-3340 a/b Status | ✓ | |
| Automatic Backwash | Cycle Count: 14 | reset |
| BF-3340 a/b Differential Pressure | PSI: 5 | 21/16 @ 3.8gpm |
| 75-micron Bags Last Cleaning | Date: 11-14-19 | |
| 75-micron Bags Last Inspection | Date: | |
| 75-micron Bags Last Changed | Date: ↓ | |
| GACF-3340 Status | ✓ | |
| GACF-3340 Differential Pressure | PSI: 9 | 16/7 @ 3.8gpm |
| Last Backwash Performed | Date: 9-27-21 | |

### H. ELECTRICAL AND INSTRUMENTATION

| Item | Status | Comments |
|---|---|---|
| "BIO" Backup Generator | ✓ | Block Heater: On OK / (Off Warm Out) |
| Electrical Surge Suppressor | ✓ | Been OK on Warm setting |
| Motor Control Center | ✓ | |
| PLC | ✓ | UPS @ 97 min / 88 Events |
| HMI's | ✓ | |
| BTS Process KWH Meter | 1806591 KWH | Time: 1138 |
| Building#2 KWH Meter | 523982 KWH | Time: 1138 |

### I. GAS CHROMATOGRAPHY

| Item | Status | Comments |
|---|---|---|
| GC Operational | ✓ | GC # checking BIO: #3 |
| Alarms Enabled | ✓ | CC-Calibration remains 10-20-21 |
| GC Influent Filters | ✓ | |

## TABLE 3.19.2
## STANDARD OPERATIONS CHECKLIST
## BIOLOGICAL TREATMENT SYSTEM

**WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST**

**Inspection Date:** Thursday, October 21, 2021

**Inspection Performed by:** Mike Gelwick

### J. TOTALIZERS

| Item | Readings (gallons) | Comments |
|---|---|---|
| FT-3321 Feed to Reactor 1 | 5996358 | |
| FT-3324 Feed Spare | 87155 | |
| FT-3322 Feed to Reactor 2 | 10736358 | |
| FT-3323 Feed to Reactor 3 | 711051 | |
| FT-3301 T-510 to BIO | 51509465 | |
| FT-3341 BIO Effluent | 66317434 | |
| FT-3342 BIO Recycle | 55502281 | |

### K. SAFETY

| Item | Status | Comments |
|---|---|---|
| Building #2 Fire Extinguishers | ✓ | Inspection date: 9-30-21 |
| Building #2 Eye Wash/Shower | ✓ | Checked and Flushed- All OK: Ⓨ / N |

### L. OTHER COMMENTS:

# ABLE 3.19.1
# STANDARD OPERATIONS CHECKLIST
# MAIN WTP

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, October 28, 2021

**Inspection Performed by:** Mike Gelwick

### A. PERIMETER COLLECTION SYSTEMS

| Item | Status | Comments |
|---|---|---|
| LFG Cond Automatic Trap CT-1 | Sump Level: 13.02 ok | Counter: 188284 Cycles: 1794 |
| LFG Cond Automatic Trap CT-2 | Sump Level: 8.68 ok | Counter: 274344 Cycles: 39 |
| LFG Cond Automatic Trap CT-3 | Sump Level: 7.60 ok | Counter: 309101 Cycles: 1563 |
| CT-4 Containment/Vessel (LFG Cond) | ✓ Level: 72 % | Tank Level: 2.13 Counter: 191244 Cycles: 0 Sump: 9.17 ok |
| PM-15 Containment / Vessel | ✓ Level: 75 % | |
| MW-51 Containment / Vessel | ✓ Level: 25 % | |
| PM-11 Containment / Vessel | ✓ Level: 25 % | |
| MW-38 Systems | ✓ | |
| North Toe System | ✓ | |
| North End Systems (Weekly) | ✓ | |
| Full N. End Systems Check (Monthly) | ✓ | Last Done: 9-24-21 |
| North End Pipeline(s)Flushing (As Needed) | ✓ | Perform if suspended solids present Last Done: 11/15/15 |
| NTES line flush to T-530 (As needed) | ✓ | Perform if suspended solids present Last Done: 2/13/20 |
| NTES Piping Containment | ✓ | Monthly Sump Level: Dry 216.07' Date: 10-21-21 |
| North Boundary System P-001: | CV 74.6 % @ 6.9 gpm | 4141 Hz / 2.10 Amps. / vault psi @ 18/no leaks |
| T-101 & T-102 Containment / Tank | ✓ | Levels: 30 % & 31 % |
| Raw Water Storage Tanks Piping | ✓ | |
| RWST Building Temp. (TT-101) | 56.6 °F | Outside Temp.: ~ 49 °F |
| (P-121) or P-122 | ✓ | 1.2 gpm / CV 56 % |
| RWST 2ndry Cont. High Level Switch | ✓ | (LSH-101) Last Test(monthly): 10-21-21 |
| RWST Back-Up Generator | ✓ | Last Test Run(monthly): 10-21-21 |

### B. CHEMICAL STORAGE BAYS

| Item | Status | Comments |
|---|---|---|
| Caustic Tote Levels | ✓ | ~ 315 Gallons Reserve = 3 totes |
| Caustic Bay Heater | ✓ | |
| Peroxide Tote Level | ✓ | ~175 Gallons Reserve = ~55 gal |
| HCL Tote Levels | ✓ | ~ 250 Gallons Reserve = ~70 gal |
| Chemical Totes and Piping Inspected | ✓ | Leaks observed: Y / (N) |
| Emergency Shower Inspected | ✓ | Checked and Flushed - All OK: (Y) / N |

### C. PRIMARY AND SECONDARY ACID FEED SYSTEM

| Item | Status | Comments |
|---|---|---|
| Primary Acid Feed Pump (P-631) | ✓ | |
| Ion Exchange Acid Feed Pump (P-632) | ✓ | PI-0632 PSI: 80-82 CV: 7 % |
| Primary Acid Retention Tank (T-510) | ✓ | |
| All Acid Feed Lines | ✓ | Leaks observed: Y / (N) |

### D. NBBW INJECTION TRENCH

| Item | Status | Comments |
|---|---|---|
| Injection Carbon (GAC-810) | OFFLINE | Date online: 7/20/18 |
| Injection Rate (FT-800) | 0.0 gpm | NBBW-IW-1= 0.0 NBBW-IW-2= 0.0 NBBW-IW-3= 0.0 gpm ea. |
| Totalizer Reading (FT-800) | 105,135,774 gal | INJ. STOPPED 10/02/18 @ 1545 |

# ABLE 3.19.1
# STANDARD OPERATIONS CHECKLIST
# MAIN WTP

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, October 28, 2021

**Inspection Performed by:** Mike Gelwick

### E. CHEMICAL PRECIPITATION SYSTEM (US FILTER HMR-30)

| Item | Status | Comment |
|---|---|---|
| T-300A Mixer | NA | |
| T-300B (Caustic Mixer) | ✓ | Last Cleaning (Qtrly): 10-20-21 |
| T-300A/B Water Level | ✓ | |
| T-300B (Caustic Mix Chamber) | ✓ | Last Cleaning (Qtrly): 10-20-21 |
| T-300A/B Overflow | ✓ | |
| pH Set-point for (pH 315) | Value: 10.8 | |
| pH 310 | Value: 6.80 | |
| pH 315 | Value: 10.94 | |
| Flocculation Chamber Paddle Wheel | ✓ | |
| Precipitate Floc Quality | ✓ | Good |
| Clarifier Water Quality | ✓ | Good Oil or sheen observed: Y / (N) |
| Clarifier Effluent Piping / Water Level | ✓ | |
| Clear-well Chamber and Water Level | ✓ | |
| HMR PLC Panel | ✓ | |
| Caustic Pump (P-270) | SB | |
| Caustic Pump (P-280) | ✓ | |
| Polymer Pump (P-310) | ✓ | |
| Polymer Tank Mixer | ✓ | |
| Polymer Tank Level | Gallons: ~ 360 | |
| Clear-well Transfer Pumps(P-371 / 372) | ✓ | |
| Sludge Transfer Pump (P-330) | ✓ | Exercise Valves Weekly: Both ok |
| Manual Sludge Lateral pumping | ✓ | Last done (As Needed): #3-7-20-21 / #1&2-3-20-21 |
| Manual Sludge Lateral Ball Valves | ✓ | Exercise Weekly: Allok |
| Automatic Blow-down Operations | ✓ | |

### F. pH PROBES

| pH Probe Location | Calibration Date | Comments: (Time done) |
|---|---|---|
| pH-310 HMR-30 (T-300A) | 10-29-21-Friday | 1320 |
| pH-315 HMR-30 (T-300B) | | |
| pH-365 Primary Acid Ret. Tank | | |
| pH-113 Pre-Ion Exchange | | |
| pH-670 Pre-UV-OX | | 1352 |
| pH-740 Discharge Surge Tank | | Discharge suspended: 1352 ↔ 1413 |
| Out of Hold Double Check | ---------- | None in hold: ✓✓ |
| Valves Back to Normal Position | ---------- | All OK: ✓✓ |

### G. SLUDGE THICKENER, SLUDGE HOLDING TANKS, FILTER PRESS

| Item | Status | Comments |
|---|---|---|
| Verify Sludge Thickener Running | ✓ | Gauge Reading: 0 % |
| Sludge Thick. Transfer Pump (P-350) | ✓ | |
| Sludge Holding Tank (T-351) | ✓ | Level:~ 45 % |
| Sludge Holding Tank (T-352) | ✓ | Level: 40 % |
| Decant Transfer Pump (P-352) | ✓ | CV 70 % @ 0.6 gpm |
| Filter Press Pumps (P-381 / P-382) | ✓ | |
| Filter Press | ✓ | Stage: Empty/needs washout |

# ABLE 3.19.1
# STANDARD OPERATIONS CHECKLIST
# MAIN WTP

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, October 28, 2021

**Inspection Performed by:** Mike Gelwick

### H. ION EXCHANGE

| Item | Status | Comments |
|---|---|---|
| Feed Tank (T-113) | ✓ Level: 52 % | |
| Feed Pump (P-114) | ✓ Operating Press: 48.9 psi | CV@ 100 % @ 3.1 gpm |
| Retention Tank (T-114) | ✓ Operating Press: 48-49 psi | pH-113 @ 3.99 |
| Bag Filter (BF-113) | ✓ Operating Press: 51-52 psi | |
| Ion Exchange (Cage (1) or 2) + Guard | ✓ Operating Press: 48-49 psi | TP-175A-2 → TP-175A / 4 Canisters + Guard |
| Post Ion Exchange | ✓ Operating Press: 4 psi | |

### I. FEED SURGE TANK

| Item | Status | Comments |
|---|---|---|
| Feed Surge Tank (T-520) | ✓ Level: 39 % | Last Cleaning (As Needed, if 4" of solids accumulate): 12/15/19 |
| Feed Surge Pump (P-521 or (P-522)) | Operating Press: 20 psi | CV@ 64 % @ 39.6 gpm |
| T-520 to GAC Total (FT-675) | 25153624 gal | Time: 1302 |
| North End On-Site Pumping | Operating Press: 2-3 psi | 13.0 gpm @ 1256 |
| North End Off-Site Pumping | Operating Press: 2-6 psi | 8.2 gpm @ 1256 |
| Peroxide Feed Pump (P-680) | ✓ | SPD 2.6 % / RATE 0.7 |
| Peroxide Conc. At (TP-710) | 1.0 PPM | |
| Peroxide Conc. At (TP-740) | 0.0 PPM | |

### J. HAZARDOUS WASTE STORAGE

| Item | Status | Comments |
|---|---|---|
| 180 Day storage area check | ✓ | Check sheet completed: NA/Empty |
| Satellite Haz. Waste Areas (BLDG #1) | ✓ | Condition: Ix Resin + Main Good |
| Satellite Haz. Waste Area (BLDG #2) | ✓ | Condition: Good |

### K. UV-OXIDATION SYSTEM

| Item | Status | Comments |
|---|---|---|
| UV-Oxidation System | ✓ | |
| Annual Test Run (Calgon) | Date: 9-16-21 | Next: 9-2022 |
| Quarterly Test Run | Date: NA/Running | Next: NA/Running |
| Peroxide Feed Pump (P-650) | ✓ | Flow Rate: ~ 20 cc/min. |
| UV-Ox Power | ✓ | 25.7 kVA 2580 Volts 10.0 Amps |
| Lamp Hours | 27 Hrs | Lamp Failed on 10-21-21. Changed out w/new |
| Crystal Condition & Wiper Status | ✓ | Oiler status: OK |
| UV-OX Bagfilters Status | Last change: 7-13-21 Cleaned: 7-13-21 | 13.5 psi In 13.5 psi Out |
| UV-OX Feed Pump ( P-600 or (P-601) ) | ✓ | CV@ 80 % @ 8.0 gpm |
| UV-OX Temperature | In(TT-670): 14.5 °C | Out(TT-710): 26.3 °C |
| PDU GAC (PDT-710) | ✓ | Δ Pressure: 5 psi |
| Peroxide Concentration Pre UV | 100 PPM | |
| Peroxide Concentration Post UV(TP-720) | 25 PPM | |
| Peroxide Conc. Post PDU (TP-730) | 0.0 PPM | |
| Secondary Acid Feed Pump (P-630) | ✓ | CV @ 2 % |
| Secondary Acid Retention Tank (T-645) | ✓ | |
| Pre – UV Oxidizer Total (FT-670) | 20139999 gal | Time: 1302 |
| Post UV-Ox / Pre PDU | ✓ | Pressure: 15 psi |
| Post PDU | ✓ | Pressure: 8 psi |

# ABLE 3.19.1
# STANDARD OPERATIONS CHECKLIST
# MAIN WTP

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, October 28, 2021

**Inspection Performed by:** Mike Gelwick

### L. PDU AND LIQUID –PHASE GRANULAR ACTIVATED CARBON

| Item | Status | Comments |
|---|---|---|
| PDT-720 Backwashed 10-22-21 | ✓ | Δ Pressure: 9 psi |
| PDT-730 | ✓ | Δ Pressure: 6 psi |

### M. EFFLUENT DISCHARGE

| Item | Status | Comments |
|---|---|---|
| Effluent Surge Pump ( P751 or (P752)) | ✓ | CV@ 55.3 % |
| Effluent Surge Tank (T-740) | ✓ | Level: 40 % |
| Effluent Discharge Rate (FT-770) | ✓ | 35.2 gpm @ 1300 |
| POTW Line Pressure (PT-770) | ✓ | 32.5 psi |
| Effluent Totalizer Reading (FT-770) | 24563656 gal | Time: 1304 |
| POTW MH17S-078 Discharge Check (Monthly) | ✓ | Last Done: 10-19-21 |
| 4X8-Inch POTW Leak Detection Checks (Monthly) | ✓ | Last Done: ↓ |
| 4X8-Inch POTW Air Reliefs Checks (Monthly) | ✓ | Last Done: ↓ |
| 4X8-Inch POTW Isolation Valves Exercise (Qtrly) | ✓ | Last Done: 7-19-21 |
| 2-Inch POTW Backup Pressure Testing (Annual) | ✓ | Last Done: 7/8/21 |
| 2-In POTW Backup Air Reliefs Checks (Annual) | ✓ | Last Done: 7/8/21 |
| 2-Inch POTW Isolation Valve Exercise (Annual) | ✓ | Last Done: 7/8/21 |
| Rotate Chiller Compressors | NA on Standby | ~~Now in Lead: 1 or 2~~ |

### N. LEL EFFLUENT TANK T-740

| Item | Status | Comments |
|---|---|---|
| LEL-740 Sensor | ✓ | Reading: 0 % |
| LEL Sensor Calibration / Automatic High LEL Shutdown Test (monthly) ✓ | Last Completed: 10-29-21 | Plant Effluent Suspended: 1352 ↔ 1413 |
| LEL Sensor Bridge Adjustment to 2.0 volts | Reading: 2.000 volts(monthly) | Adjustment Needed: Y or (N) |
| Verify Bridge Current between.300v-.360v | Reading: 0.330 volts(monthly) | |

### O. WTP INFLUENT TOTALIZERS Time : 1304- 1308

| Source | Reading(Gallons) | Source | Reading(Gallons) |
|---|---|---|---|
| (FT-015) RWST Influent | 19671556 | (FT-505) LFG Cond. to T-530 | 218333 |
| (FT-025) NBBW Influent | 94050832 | (FT-056) Off - Site N. End Influent | 43186284 |
| (FT-012) MW-38 Inf. to HMR-30 | 8281522 | (FT-113) Ion Exchange Influent | 8035543 |
| (FT-042 HMR30) MW-38 Source to HMR-30 | 35484 | (FT-810) Plant Potable Water In | 30063844 |
| (FT-043) MW-38 to RWST | 3076642 | (FT-026) NBBW Bypass to RWST | 4402592 |
| (FT-042 RWST) MW-38 Source to RWST | 72236 | (FT-014) Misc. Water to RWST | 8173749 |
| (FT-012T) MW-38 to T-540/541 | 8619025 | (FT-035) NTES Inf. to BIO | 6664270 |
| (FT-040T) MW-38N to T-540/541 | 1977937 | (FT-035T) NTES to T-530 | 461537 |
| (FT-041T) MW-38S to T-540/541 | 2695864 | (FT-017) BIO Inf. from T-530 | 653562 |
| (FT-042T) MW-38 Source to T-540/541 | 4017250 | (FT-018) T-540/541 Influent | 8664543 |
| (FT-055) On - Site N. End Influent | 98177898 | (FT-352) T-352 to HMR-30 | 12955557 |

# ABLE 3.19.1
# STANDARD OPERATIONS CHECKLIST
# MAIN WTP

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, October 28, 2021

**Inspection Performed by:** Mike Gelwick

### P. AIR COMPRESSORS *STill Running on Backups*

| Item | Status | Comments |
|---|---|---|
| Compressor Intake Temp. | 59 °F (Analog Gauge) | Outside Temp.: ~ 50 °F |
| Compressor Building Vent | ✓ | Open/operational |
| Primary Air Compressor (IRN30H) | 2,000 Hour service date: 7-8-21<br>Serviced @ 60952 Hours | Coolant present in sight glass: Y / N<br>Next service @ 62952 Hours<br>Current Hours @ NA/OFF |
| IRN30H Motor Speed | — % | |
| IRN30H Pressure | — psi | |
| IRN30H Moisture purge valve chk(Weekly): | — | |
| IRN30H Intake Filter | — | Date Last Changed: 9-30-31 |
| Air Tanks Moisture Purge Valves | Manually Activate(weekly) ✓ | Excessive Moisture: Y / N |
| Backup Air Compressors (T-30 East and West) | Running | Both cool to touch: Y / N |
| Air Dryer | ✓ Ecoair | Moisture at Receiver Tank: Y / N |
| Oil Moisture Prevention (Monthly) | Last Done: 9-23-21 | Run at max speed by bleeding air from filter canister above/after air dryer for 2 hrs |
| Air Receiver Tank | ✓ | 105 psi |

### Q. SUMPS

| Item | Status | Comments |
|---|---|---|
| Bag Filter Sump | ✓ | |
| Wet Well Sump | ✓ | |

### R. GAS CHROMATOGRAPH

| Item | Status | Comments |
|---|---|---|
| GC Operational | ✓ | GC # checking UV-Ox Effluent: #2 |
| Alarms Enabled | ✓ | cc-calibration + maint 10-28-21 |
| GC Influent Filters | ✓ | |

### S. SAFETY

| Item | Status | Comments |
|---|---|---|
| Building #1 Fire Extinguishers | ✓ | Date inspected: 10-25-21 |
| Building #1 Eye Wash/Shower | ✓ | Checked and Flushed- All OK: Y / N |

**Other Comments:**

| |
|---|
| |
| |
| |
| |
| |

# TABLE 3.19.2
# STANDARD OPERATIONS CHECKLIST
# BIOLOGICAL TREATMENT SYSTEM

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, October 28, 2021

**Inspection Performed by:** Mike Gelwick

## A. PUMPS

| Item | Status | Flow Rate (gpm) | Pump Speed (CV%) | Discharge Pressure (psi) | | Comments |
|---|---|---|---|---|---|---|
| **T-510 Pumps** | | | | | | |
| P-3301 | ✓ | 3.67 | 52.7 % | 12.0 | | |
| P-3301A | SB | — | — % | — | | |
| **NTES Pump** Currently filling Line w/Potable Water ~~P-002(Sump)~~ / ~~P-002W(10R)~~ | ✓ | 0.53 | 52 % | P035 29 | P038 6 | Globules Observed at TP-130: Y / (N) Time: 1245 |
| **T-530** P-005 | ~~SB~~ | 0.0 | — % | — | | |
| **T-540/541** P-006 | ✓ | 0.30 | 68 % | 6.5 | | |
| **LFG COND Auto-Traps** | ✓ | 0.0 | NA | 5.0 | | Between Cycles: (Y) / N |
| **Reactor Feed Pumps** | | | | | | |
| P-3321 | ✓ | 2.65 | 63.5 % | 7.0 | | |
| P-3322 | ✓ | 3.65 | 53.7 % | 6.0 | | |
| P-3323 | ✓ | 2.64 | 85.6 % | 6.0 | | |
| P-3324 | SB | — | — % | — | | |
| **Reactor Effluent Pumps** | | | | | | |
| P-3341 | ✓ | 3.09 | 60.1 % | 19.0 | | |
| P-3341A | SB | — | — % | — | | |

## B. BLOWERS

| Item | Status | Pressure (psi) | Temp (°F) | Next Scheduled Service (Qtrly) | Comments Last serviced on: 10-1-21 |
|---|---|---|---|---|---|
| B-3331 | ✓ | 4.31 | 128 | 12-2021 | Greased, Belt and Filter Checked: (Y) / N |
| B-3332 | SB | — | — | ↓ | Belt and Filter Checked: Y / (N) |
| B-3333 | ✓ | 4.38 | 128 | | Greased, Belt and Filter Checked: (Y) / N |
| B-3334 | ✓ | 4.32 | 124 | | Greased, Belt and Filter Checked: (Y) / N |

## C. REACTOR VENTILATION

| Item | Status | Comments |
|---|---|---|
| Vapor Carbon Contactor | ✓ | On-line: 2/10/18 |
| Reactor Vent Blower | ✓ | |
| Reactor Vent Booster | ✓ | |
| VTP-3350 | ✓ | PID Reading: 10.6 PPM |
| VTP-3360 | ✓ | PID Reading: 3.9 PPM |

# TABLE 3.19.2
# STANDARD OPERATIONS CHECKLIST
# BIOLOGICAL TREATMENT SYSTEM

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, October 28, 2021

**Inspection Performed by:** Mike Gelwick

## D. TANKS / REACTORS / SUMPS / CONTAINMENTS / PIPING / Chiller

| Item | Status | Comments |
|---|---|---|
| T-510 Post HMR-30 Mixing Tank | ✓ Level: 69 % | Last Cleaning (As needed, if 2" of solids accumulate): 7/14/21 |
| T-530 LFG Condensate / NTES Tank | ✓ Level: 33 % | |
| T-530 Mixer | ✓ | |
| LFG Condensate Conveyance Line | ✓ | Last Pressure Test: 7-19-21 Next: 7-2022 (Annual at a minimum or if flow drops off) |
| T-540/541 MW38 Tanks | Lvls: 48 % & 49 % | |
| T-540/541 Mixers | ✓ | * T-541 Mixer needs replace. Replacement ordered. |
| Chiller | ✓ | Chiller Coolant Lvl: ~ — " Below full mark |
| Chiller Cooling Fins (as needed) | ✓ | Last Cleaning: 4/20/18 (unit on Standby) |
| Secondary Containments | ✓ | Heat Trace: On OK / (Off Warm out) |
| Feed Piping to Sedimentation Tank | ✓ | Last Back Flushing (Quarterly): 10-13-21 |
| T-3310 Sedimentation Tank | Visual Level: ok | Last Cleaning (As Needed, use TSS info to determine): 9/2021 |
| T-3320 Blend Tank | ✓ Level: 73 % | Last Cleaning (Semi Annual): 9-10-21 |
| T-3331 Reactor No. 1 | ✓ | Digital Displays: (GOOD) / Needs Attn |
| T-3332 Reactor No. 2 | ✓ | Digital Displays: (GOOD) / Needs Attn |
| T-3333 Reactor No. 3 | ✓ | Digital Displays: (GOOD) / Needs Attn |
| T-3334 Settling Tank | ✓ | Last Cleaning (Semi Annual): 9-10-21 |
| P-3334 Biosolids Pump | ✓ | |
| T-3340 Overflow Tank | ✓ Level: 30 % | |
| Recycle Valve to Blend Tank | ✓ | 4.52 gpm @ 1321 |
| Building Containment Sump | ✓ | Last Alarm Test Date (Monthly): 10-21-21 |

## E. CHEMICAL FEED SYSTEM

| Item | Status | Comments |
|---|---|---|
| Phosphorous Supply | ✓ | Bags: 16.25 Gallons: ~ 75 |
| Phosphorous Pump (P-2221) | ✓ | |
| Caustic Supply | ✓ | ~ 60 Gallons |
| Caustic Pump (P-2211) | SB | Currently in acid addition mode |
| Acid Supply | ✓ | ~ 40 Gallons |
| Acid Pump (P-2211) | ✓ | |
| Caustic Pump (P-2231) | ✓ Leaks: Y / (N) | Last tubing tip cleaning (monthly): 10-21-21 |
| Caustic Pump (P-2232) | ✓ Leaks: Y / (N) | Last tubing tip cleaning (monthly): |
| Caustic Pump (P-2233) | ✓ Leaks: Y / (N) | Last tubing tip cleaning (monthly): |

# TABLE 3.19.2
# STANDARD OPERATIONS CHECKLIST
# BIOLOGICAL TREATMENT SYSTEM

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, October 28, 2021

**Inspection Performed by:** Mike Gelwick

## F. pH Probes

| pH Probe Location | Calibration Date (Monthly) | Comments |
|---|---|---|
| pH-3320 Blend Tank | 10-29-21 - Friday | New 4+10 pH STDS today |
| pH-3331 Reactor 1 | ↓ | ↓ |
| pH-3332 Reactor 2 | | |
| pH-3333 Reactor 3 | | |

## G. FILTER SYSTEM

| Item | Status | Comments |
|---|---|---|
| BF-3340 a/b Status | ✓ | |
| Automatic Backwash | Cycle Count: 21 | reset |
| BF-3340 a/b Differential Pressure | PSI: 4 | 17/21 @ 410gpm |
| 75-micron Bags Last Cleaning | Date: 11-14-19 | |
| 75-micron Bags Last Inspection | Date: ↓ | |
| 75-micron Bags Last Changed | Date: | |
| GACF-3340 Status | ✓ | |
| GACF-3340 Differential Pressure | PSI: 10 | 17/7 @ 410gpm |
| Last Backwash Performed | Date: 9-27-21 | |

## H. ELECTRICAL AND INSTRUMENTATION

| Item | Status | Comments |
|---|---|---|
| "BIO" Backup Generator | ✓ | Block Heater: On OK / (Off Warm Out) |
| Electrical Surge Suppressor | ✓ | |
| Motor Control Center | ✓ | |
| PLC | ✓ | UPS @ 97 min / 93 Events |
| HMI's | ✓ | |
| BTS Process KWH Meter | 1808979 KWH | Time: 1344 |
| Building#2 KWH Meter | 5243065 KWH | Time: 1344 |

## I. GAS CHROMATOGRAPHY

| Item | Status | Comments |
|---|---|---|
| GC Operational | ✓ | GC # checking BIO: #3 |
| Alarms Enabled | ✓ | GC - calibration sample on 10-27-21 |
| GC Influent Filters | ✓ | |

# TABLE 3.19.2
# STANDARD OPERATIONS CHECKLIST
# BIOLOGICAL TREATMENT SYSTEM

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, October 28, 2021

**Inspection Performed by:** Mike Gelwick

## J. TOTALIZERS

| Item | Readings (gallons) | Comments |
|---|---|---|
| FT-3321 Feed to Reactor 1 | 6019208 | |
| FT-3324 Feed Spare | 87164 | |
| FT-3322 Feed to Reactor 2 | 10768102 | |
| FT-3323 Feed to Reactor 3 | 733587 | |
| FT-3301 T-510 to BIO | 51530687 | |
| FT-3341 BIO Effluent | 66346817 | |
| FT-3342 BIO Recycle | 55545739 | |

## K. SAFETY

| Item | Status | Comments |
|---|---|---|
| Building #2 Fire Extinguishers | ✓ | Inspection date: 10-25-21 |
| Building #2 Eye Wash/Shower | ✓ | Checked and Flushed- All OK: (Y) / N |

## L. OTHER COMMENTS:

| |
|---|
| |
| |
| |
| |

# ABLE 3.19.1
# STANDARD OPERATIONS CHECKLIST
# MAIN WTP

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, November 04, 2021

**Inspection Performed by:** Mike Gelwick

## A. PERIMETER COLLECTION SYSTEMS

| Item | Status | Comments |
|---|---|---|
| LFG Cond Automatic Trap CT-1 | Sump Level: 12.59 oz | Counter: 188599 Cycles: 315 |
| LFG Cond Automatic Trap CT-2 | Sump Level: 8.68 oz | Counter: 274413 Cycles: 69 |
| LFG Cond Automatic Trap CT-3 | Sump Level: 7.28 oz | Counter: 309172 Cycles: 71 |
| CT-4 Containment/Vessel (LFG Cond) | ✓ Level: 72 % | Tank Level: 2.45 Counter: 191244 Cycles: 0 Sump: 8.97oz |
| PM-15 Containment / Vessel | ✓ Level: 73 % | |
| MW-51 Containment / Vessel | ✓ Level: 50 % | |
| PM-11 Containment / Vessel | ✓ Level: 40 % | |
| MW-38 Systems | ✓ | |
| North Toe System | ✓ | |
| North End Systems (Weekly) | ✓ | |
| Full N. End Systems Check (Monthly) | ✓ | Last Done: 10-29-21 |
| North End Pipeline(s)Flushing (As Needed) | ✓ | Perform if suspended solids present Last Done: 11/15/15 |
| NTES line flush to T-530 (As needed) | ✓ | Perform if suspended solids present Last Done: ~~5/13/20~~ 10-29-21 |
| NTES Piping Containment | ✓ | Monthly Sump Level: Dry @ 16.0' Date: 10-21-21 |
| North Boundary System P-001: | CV 74.4 % @ 6.9 gpm | 41.27 Hz / 2.08 Amps. / vault psi @ 18/no leaks |
| T-101 & T-102 Containment / Tank | ✓ | Levels: 29 % & 28 % |
| Raw Water Storage Tanks Piping | ✓ | |
| RWST Building Temp. (TT-101) | 56.4 °F | Outside Temp.: ~ 46 °F |
| (P-121) or P-122 | ✓ | 1.2 gpm / CV 60 % |
| RWST 2ndry Cont. High Level Switch | ✓ | (LSH-101) Last Test(monthly): 10-21-21 |
| RWST Back-Up Generator | ✓ | Last Test Run(monthly): 10-21-21 |

## B. CHEMICAL STORAGE BAYS

| Item | Status | Comments |
|---|---|---|
| Caustic Tote Levels | ✓ | ~ 380 Gallons Reserve = 2 totes |
| Caustic Bay Heater | ✓ | |
| Peroxide Tote Level | ✓ | ~ 153 Gallons Reserve = ~55gal |
| HCL Tote Levels | ✓ | ~ 220 Gallons Reserve = ~70gal |
| Chemical Totes and Piping Inspected | ✓ | Leaks observed: Y / (N) |
| Emergency Shower Inspected | ✓ | Checked and Flushed - All OK: (Y) / N |

## C. PRIMARY AND SECONDARY ACID FEED SYSTEM

| Item | Status | Comments |
|---|---|---|
| Primary Acid Feed Pump (P-631) | ✓ | |
| Ion Exchange Acid Feed Pump (P-632) | ✓ | PI-0632 PSI: 80-82 CV: 4 % |
| Primary Acid Retention Tank (T-510) | ✓ | |
| All Acid Feed Lines | ✓ | Leaks observed: Y / (N) |

## D. NBBW INJECTION TRENCH

| Item | Status | Comments |
|---|---|---|
| Injection Carbon (GAC-810) | OFFLINE | Date online: 7/20/18 |
| Injection Rate (FT-800) | 0.0 gpm | NBBW-IW-1= 0.0 NBBW-IW-2= 0.0 NBBW-IW-3= 0.0 gpm ea. |
| Totalizer Reading (FT-800) | 105,135,774 gal | INJ. STOPPED 10/02/18 @ 1545 |

# ABLE 3.19.1
# STANDARD OPERATIONS CHECKLIST
# MAIN WTP

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, November 04, 2021

**Inspection Performed by:** Mike Gelwick

### E. CHEMICAL PRECIPITATION SYSTEM (US FILTER HMR-30)

| Item | Status | Comment |
|---|---|---|
| T-300A Mixer | NA | |
| T-300B (Caustic Mixer) | ✓ | Last Cleaning (Qtrly): 10-20-21 |
| T-300A/B Water Level | ✓ | |
| T-300B (Caustic Mix Chamber) | ✓ | Last Cleaning (Qtrly): 10-20-21 |
| T-300A/B Overflow | ✓ | |
| pH Set-point for (pH 315) | Value: 10.8 | |
| pH 310 | Value: 6.73 | |
| pH 315 | Value: 10.87 | |
| Flocculation Chamber Paddle Wheel | ✓ | |
| Precipitate Floc Quality | ✓ | Good |
| Clarifier Water Quality | ✓ | Good Oil or sheen observed: Y / (N) |
| Clarifier Effluent Piping / Water Level | ✓ | |
| Clear-well Chamber and Water Level | ✓ | |
| HMR PLC Panel | ✓ | |
| Caustic Pump (P-270) | SB | |
| Caustic Pump (P-280) | ✓ | |
| Polymer Pump (P-310) | ✓ | |
| Polymer Tank Mixer | ✓ | |
| Polymer Tank Level | Gallons: ~ 475 | |
| Clear-well Transfer Pumps (P-371) / 372) | ✓ | |
| Sludge Transfer Pump (P-330) | ✓ | Exercise Valves Weekly: Bothok |
| Manual Sludge Lateral pumping | ✓ | Last done (As Needed): #3- 7-20-21 / #1&2-3-20-21 |
| Manual Sludge Lateral Ball Valves | ✓ | Exercise Weekly: Allon |
| Automatic Blow-down Operations | ✓ | |

### F. pH PROBES

| pH Probe Location | Calibration Date | Comments: (Time done) |
|---|---|---|
| pH-310 HMR-30 (T-300A) | 11-4-21 - Today | 1158 |
| pH-315 HMR-30 (T-300B) | | |
| pH-365 Primary Acid Ret. Tank | | |
| pH-113 Pre-Ion Exchange | | |
| pH-670 Pre-UV-OX | | 1237 |
| pH-740 Discharge Surge Tank | | Discharge suspended: 1150 ↔ 1151 |
| Out of Hold Double Check | ---------- | None in hold: ✓ ✓ ✓ |
| Valves Back to Normal Position | ---------- | All OK: ✓ ✓ ✓ |

### G. SLUDGE THICKENER, SLUDGE HOLDING TANKS, FILTER PRESS

| Item | Status | Comments |
|---|---|---|
| Verify Sludge Thickener Running | ✓ | Gauge Reading: 0 % |
| Sludge Thick. Transfer Pump (P-350) | ✓ | |
| Sludge Holding Tank (T-351) | ✓ | Level: ~ 65 % |
| Sludge Holding Tank (T-352) | ✓ | Level: 44 % |
| Decant Transfer Pump (P-352) | ✓ | CV 63 % @ 0.5 gpm |
| Filter Press Pumps (P-381 / P-382) | ✓ | |
| Filter Press | ✓ | Stage: Empty |

# ABLE 3.19.1
# STANDARD OPERATIONS CHECKLIST
# MAIN WTP

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, November 04, 2021

**Inspection Performed by:** Mike Gelwick

### H. ION EXCHANGE

| Item | Status | Comments |
|---|---|---|
| Feed Tank (T-113) | ✓ Level: 53 % | |
| Feed Pump (P-114) | ✓ Operating Press: 48.8 psi | CV@ 98 % @ 3.0 gpm |
| Retention Tank (T-114) | ✓ Operating Press: 45-47 psi | pH-113 @ 3.62 |
| Bag Filter (BF-113) | ✓ Operating Press: 48-50 psi | |
| Ion Exchange (Cage (1) or 2) + Guard | ✓ Operating Press: 45-47 psi | TP-173A-2 → TP-175A / 4 canisters + Guard |
| Post Ion Exchange | ✓ Operating Press: 4 psi | |

### I. FEED SURGE TANK

| Item | Status | Comments |
|---|---|---|
| Feed Surge Tank (T-520) | ✓ Level: 39 % | Last Cleaning (As Needed, if 4" of solids accumulate): 12/15/19 |
| Feed Surge Pump (P-521 or (P-522)) | Operating Press: 23 psi | CV@ 67 % @ 34.3 gpm |
| T-520 to GAC Total (FT-675) | 251875304 gal | Time: 0942 |
| North End On-Site Pumping | Operating Press: 2-3 psi | 13.0 gpm @ 0915 |
| North End Off-Site Pumping | Operating Press: 2-6 psi | 8.2 gpm @ 0915 |
| Peroxide Feed Pump (P-680) | ✓ | SPD 2.6 % / RATE 0.7 |
| Peroxide Conc. At (TP-710) | 1.0 PPM | |
| Peroxide Conc. At (TP-740) | 0.0 PPM | |

### J. HAZARDOUS WASTE STORAGE

| Item | Status | Comments |
|---|---|---|
| 180 Day storage area check | ✓ | Check sheet completed: NA/Empty |
| Satellite Haz. Waste Areas (BLDG #1) | ✓ | Condition: Ex Lgtn + main Good |
| Satellite Haz. Waste Area (BLDG #2) | ✓ | Condition: Good |

### K. UV-OXIDATION SYSTEM

| Item | Status | Comments |
|---|---|---|
| UV-Oxidation System | ✓ | |
| Annual Test Run (Calgon) | Date: 9-16-21 | Next: 9-2022 |
| Quarterly Test Run | Date: NA/Running | Next: NA/Running |
| Peroxide Feed Pump (P-650) | ✓ | Flow Rate: ~ 7.0 cc/min. |
| UV-Ox Power | ✓ | 25.7 kVA 2601 Volts 10.0 Amps |
| Lamp Hours | 191 Hrs | |
| Crystal Condition & Wiper Status | ✓ | Oiler status: OK Refilled |
| UV-OX Bagfilters Status | Last change: 7-13-21 Cleaned: 7-13-21 | 13.0 psi In 13.5 psi Out |
| UV-OX Feed Pump ( P-600 or (P-601) ) | ✓ | CV@ 78 % @ 8.0 gpm |
| UV-OX Temperature | In(TT-670): 14.3 °C | Out(TT-710): 26.0 °C |
| PDU GAC (PDT-710) | ✓ | Δ Pressure: 5 psi |
| Peroxide Concentration Pre UV | 100 PPM | |
| Peroxide Concentration Post UV(TP-720) | 25 PPM | |
| Peroxide Conc. Post PDU (TP-730) | 0.0 PPM | |
| Secondary Acid Feed Pump (P-630) | – | CV @ 0 % |
| Secondary Acid Retention Tank (T-645) | ✓ | |
| Pre – UV Oxidizer Total (FT-670) | 20216484 gal | Time: 0943 |
| Post UV-Ox / Pre PDU | – | Pressure: 15 psi |
| Post PDU | – | Pressure: 8 psi |

# ABLE 3.19.1
# STANDARD OPERATIONS CHECKLIST
# MAIN WTP

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, November 04, 2021

**Inspection Performed by:** Mike Gelwick

### L. PDU AND LIQUID –PHASE GRANULAR ACTIVATED CARBON

| Item | Status | Comments |
|---|---|---|
| PDT-720 | ✓ | Δ Pressure: 12 psi |
| PDT-730 | ✓ | Δ Pressure: 6 psi |

### M. EFFLUENT DISCHARGE

| Item | Status | Comments |
|---|---|---|
| Effluent Surge Pump ( P751 or (P752)) | ✓ | CV@ 55.1 % |
| Effluent Surge Tank (T-740) | ✓ | Level: 40 % |
| Effluent Discharge Rate (FT-770) | ✓ | 34.7 gpm @ 0919 |
| POTW Line Pressure (PT-770) | ✓ | 32.4 psi |
| Effluent Totalizer Reading (FT-770) | 246006886 gal | Time: 0943 |
| POTW MH17S-078 Discharge Check (Monthly) | ✓ | Last Done: 10-19-21 |
| 4X8-Inch POTW Leak Detection Checks (Monthly) | ✓ | Last Done: ↓ |
| 4X8-Inch POTW Air Reliefs Checks (Monthly) | ✓ | Last Done: ↓ |
| 4X8-Inch POTW Isolation Valves Exercise (Qtrly) | ✓ | Last Done: 7-19-21 |
| 2-Inch POTW Backup Pressure Testing (Annual) | ✓ | Last Done: 7/8/21 |
| 2-In POTW Backup Air Reliefs Checks (Annual) | ✓ | Last Done: 7/8/21 |
| 2-Inch POTW Isolation Valve Exercise (Annual) | ✓ | Last Done: 7/8/21 |
| Rotate Chiller Compressors | NA on Standby | ~~New in Lead: 1 or 2~~ |

### N. LEL EFFLUENT TANK T-740

| Item | Status | Comments |
|---|---|---|
| LEL-740 Sensor | ✓ | Reading: 0 % |
| LEL Sensor Calibration / Automatic High LEL Shutdown Test (monthly) ✓ | Last Completed: 10-24-21 | Plant Effluent Suspended: 1352 ↔ 1413 |
| LEL Sensor Bridge Adjustment to 2.0 volts | Reading: 2.000 volts(monthly) | Adjustment Needed: Y or (N) |
| Verify Bridge Current between.300v-.360v | Reading: 0.330 volts(monthly) | |

### O. WTP INFLUENT TOTALIZERS Time : 0943 - 0948

| Source | Reading(Gallons) | Source | Reading(Gallons) |
|---|---|---|---|
| (FT-015) RWST Influent | 19683225 | (FT-505) LFG Cond. to T-530 | 218425 |
| (FT-025) NBBW Influent | 94117434 | (FT-056) Off - Site N. End Influent | 43265688 |
| (FT-012) MW-38 Inf. to HMR-30 | 8301434 | (FT-113) Ion Exchange Influent | 832959 |
| (FT-042 HMR30) MW-38 Source to HMR-30 | 35484 | (FT-810) Plant Potable Water In | 30064908 |
| (FT-043) MW-38 to RWST | 3077015 | (FT-026) NBBW Bypass to RWST | 4403997 |
| (FT-042 RWST) MW-38 Source to RWST | 72236 | (FT-014) Misc. Water to RWST | 8180743 |
| (FT-012T) MW-38 to T-540/541 | 8619025 | (FT-035) NTES Inf. to BIO | 6667330 |
| (FT-040T) MW-38N to T-540/541 | 1977937 | (FT-035T) NTES to T-530 | 464016 |
| (FT-041T) MW-38S to T-540/541 | 2695864 | (FT-017) BIO Inf. from T-530 | 655598 |
| (FT-042T) MW-38 Source to T-540/541 | 4017250 | (FT-018) T-540/541 Influent | 8667419 |
| (FT-055) On - Site N. End Influent | 98306028 | (FT-352) T-352 to HMR-30 | 1298234 |

# ABLE 3.19.1
# STANDARD OPERATIONS CHECKLIST
# MAIN WTP

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, November 04, 2021

**Inspection Performed by:** Mike Gelwick

### P. AIR COMPRESSORS * Still running on backups *

| Item | Status | Comments |
|---|---|---|
| Compressor Intake Temp. | 62 °F (Analog Gauge) | Outside Temp.: ~ 51 °F |
| Compressor Building Vent | ✓ | open / screened |
| Primary Air Compressor (IRN30H) | 2,000 Hour service date: 7-8-21<br>Serviced @ 60952 Hours | Coolant present in sight glass: Ⓨ / N<br>Next service @ 62952 Hours<br>Current Hours @ — |
| IRN30H Motor Speed | — % | |
| IRN30H Pressure | — psi | |
| IRN30H Moisture purge valve chk(Weekly): | — | |
| IRN30H Intake Filter | ✓ | Date Last Changed: 930-21 |
| Air Tanks Moisture Purge Valves | Manually Activate(weekly) ✓ | Excessive Moisture: Y / Ⓝ |
| Backup Air Compressors (T-30 East and West) | Running | Both cool to touch: Y / Ⓝ |
| Air Dryer | ✓ Eco on | Moisture at Receiver Tank: Y / Ⓝ |
| Oil Moisture Prevention (Monthly) | Last Done: 9-23-21 | Run at max speed by bleeding air from filter canister above/after air dryer for 2 hrs |
| Air Receiver Tank | ✓ | 105 psi |

### Q. SUMPS

| Item | Status | Comments |
|---|---|---|
| Bag Filter Sump | ✓ | |
| Wet Well Sump | ✓ | |

### R. GAS CHROMATOGRAPH

| Item | Status | Comments |
|---|---|---|
| GC Operational | ✓ | GC # checking UV-Ox Effluent: * 1 |
| Alarms Enabled | ✓ | Cc calibration + running 11-3-21 |
| GC Influent Filters | ✓ | |

### S. SAFETY

| Item | Status | Comments |
|---|---|---|
| Building #1 Fire Extinguishers | ✓ | Date inspected: 10-25-21 |
| Building #1 Eye Wash/Shower | ✓ | Checked and Flushed- All OK: Ⓨ / N |

**Other Comments:**

# TABLE 3.19.2
# STANDARD OPERATIONS CHECKLIST
# BIOLOGICAL TREATMENT SYSTEM

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, November 04, 2021

**Inspection Performed by:** Mike Gelwick

## A. PUMPS

| Item | Status | Flow Rate (gpm) | Pump Speed (CV%) | Discharge Pressure (psi) | | Comments |
|---|---|---|---|---|---|---|
| **T-510 Pumps** | | | | | | |
| P-3301 | ✓ | 1.92 | 30.5 % | 6.5 | | |
| P-3301A | SB | – | – % | – | | |
| **NTES Pump** P-002(Sump) / (P-002W(10R)) | ✓ | 0.50 | 48 % | P035 35-36 | P038 7.0 | Globules Observed at TP-130: Y / (N) Time: 0850 |
| **T-530** P-005 | ✓ | 0.20 | 41 % | 6.5 | | |
| **T-540/541** P-006 | ✓ | 0.29 | 74 % | 6.5 | | |
| **LFG COND Auto-Traps** | ✓ | 0.0 | NA | 5 | | Between Cycles: (Y) / N |
| **Reactor Feed Pumps** | | | | | | |
| P-3321 | ✓ | 2.52 | 46.9 % | 5.0 | | |
| P-3322 | ✓ | 3.51 | 48.8 % | 5.0 | | |
| P-3323 | ✓ | 2.49 | 67.8 % | 5.0 | | |
| P-3324 | SB | – | – % | – | | |
| **Reactor Effluent Pumps** | | | | | | |
| P-3341 | ✓ | 3.97 | 68.2 % | 23.0 | | |
| P-3341A | SB | – | – % | – | | |

## B. BLOWERS

| Item | Status | Pressure (psi) | Temp (°F) | Next Scheduled Service (Qtrly) | Comments Last serviced on: 10-4-21 |
|---|---|---|---|---|---|
| B-3331 | ✓ | 4.37 | 132 | 12-2021 | Greased, Belt and Filter Checked: (Y) / N |
| B-3332 | SB | – | ✓ | ↓ | Belt and Filter Checked: Y / (N) |
| B-3333 | ✓ | 4.39 | 130 | ↓ | Greased, Belt and Filter Checked: (Y) / N |
| B-3334 | ✓ | 4.35 | 128 | ↓ | Greased, Belt and Filter Checked: (Y) / N |

## C. REACTOR VENTILATION

| Item | Status | Comments |
|---|---|---|
| Vapor Carbon Contactor | ✓ | On-line: 2/10/18 |
| Reactor Vent Blower | ✓ | |
| Reactor Vent Booster | ✓ | |
| VTP-3350 | ✓ | PID Reading: 167 PPM |
| VTP-3360 | ✓ | PID Reading: 10.1 PPM |

# TABLE 3.19.2
# STANDARD OPERATIONS CHECKLIST
# BIOLOGICAL TREATMENT SYSTEM

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, November 04, 2021

**Inspection Performed by:** Mike Gelwick

## D. TANKS / REACTORS / SUMPS / CONTAINMENTS / PIPING / Chiller

| Item | Status | Comments |
|---|---|---|
| T-510 Post HMR-30 Mixing Tank | ✓ Level: 69 % | Last Cleaning (As needed, if 2" of solids accumulate): 7/14/21 |
| T-530 LFG Condensate / NTES Tank | ✓ Level: 43 % | |
| T-530 Mixer | ✓ | |
| LFG Condensate Conveyance Line | ✓ | Last Pressure Test: 7-19-21 Next: 7-2022 (Annual at a minimum or if flow drops off) |
| T-540/541 MW38 Tanks | Lvls: 25 % & 25 % | |
| T-540/541 Mixers | ✓ | T541 mixer shutdown. |
| Chiller | ✓ | Chiller Coolant Lvl: ~ — " Below full mark |
| Chiller Cooling Fins (as needed) | ✓ | Last Cleaning: 4/20/18 (unit on Standby) |
| Secondary Containments | ✓ | Heat Trace: On OK / (Off Warm out) |
| Feed Piping to Sedimentation Tank | ✓ | Last Back Flushing (Quarterly): 10-13-21 |
| T-3310 Sedimentation Tank | Visual Level: OK | Last Cleaning (As Needed, use TSS info to determine): 9/2021 |
| T-3320 Blend Tank | ✓ Level: 73 % | Last Cleaning (Semi Annual): 9-10-21 |
| T-3331 Reactor No. 1 | ✓ | Digital Displays: (GOOD) / Needs Attn |
| T-3332 Reactor No. 2 | ✓ | Digital Displays: (GOOD) / Needs Attn |
| T-3333 Reactor No. 3 | ✓ | Digital Displays: (GOOD) / Needs Attn |
| T-3334 Settling Tank | ✓ | Last Cleaning (Semi Annual): 9-10-21 |
| P-3334 Biosolids Pump | ✓ | |
| T-3340 Overflow Tank | ✓ Level: 31 % | |
| Recycle Valve to Blend Tank | ✓ | 4.01 gpm @ 1003 |
| Building Containment Sump | ✓ | Last Alarm Test Date (Monthly): 10-21-21 |

## E. CHEMICAL FEED SYSTEM

| Item | Status | Comments |
|---|---|---|
| Phosphorous Supply | ✓ | Bags: 16 Gallons: ~85 |
| Phosphorous Pump (P-2221) | ✓ | |
| Caustic Supply | ✓ | ~ 55 Gallons |
| Caustic Pump (P-2211) | SB | Currently in acid addition mode |
| Acid Supply | ✓ | ~ 40 Gallons |
| Acid Pump (P-2211) | ✓ | |
| Caustic Pump (P-2231) | ✓ Leaks: Y / (N) | Last tubing tip cleaning (monthly): 10-21-21 |
| Caustic Pump (P-2232) | ✓ Leaks: Y / (N) | Last tubing tip cleaning (monthly): |
| Caustic Pump (P-2233) | ✓ Leaks: Y / (N) | Last tubing tip cleaning (monthly): |

# TABLE 3.19.2
# STANDARD OPERATIONS CHECKLIST
# BIOLOGICAL TREATMENT SYSTEM

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, November 04, 2021

**Inspection Performed by:** Mike Gelwick

## F. pH Probes

| pH Probe Location | Calibration Date (Monthly) | Comments |
|---|---|---|
| pH-3320 Blend Tank | 10-29-21 | Spray after clean today |
| pH-3331 Reactor 1 | ↓ | ↓ |
| pH-3332 Reactor 2 | | |
| pH-3333 Reactor 3 | | |

## G. FILTER SYSTEM

| Item | Status | Comments |
|---|---|---|
| BF-3340 a/b Status | ✓ | |
| Automatic Backwash | Cycle Count: 36 | Reset |
| BF-3340 a/b Differential Pressure | PSI: 6 | 18/24 24.0gpm |
| 75-micron Bags Last Cleaning | Date: 11-14-19 | |
| 75-micron Bags Last Inspection | Date: ↓ | |
| 75-micron Bags Last Changed | Date: ↓ | |
| GACF-3340 Status | ✓ | |
| GACF-3340 Differential Pressure | PSI: 11 | ~~18/7~~ 18/7 24.0gpm |
| Last Backwash Performed | Date: 9-27-21 | |

## H. ELECTRICAL AND INSTRUMENTATION

| Item | Status | Comments |
|---|---|---|
| "BIO" Backup Generator | ✓ | Block Heater: On OK / Off Warm Out |
| Electrical Surge Suppressor | ✓ | |
| Motor Control Center | ✓ | |
| PLC | ✓ | UPS @ 97 min / 93 Events |
| HMI's | ✓ | |
| BTS Process KWH Meter | 1811482 KWH | Time: 1107 |
| Building#2 KWH Meter | 5248364 KWH | Time: 1107 |

## I. GAS CHROMATOGRAPHY

| Item | Status | Comments |
|---|---|---|
| GC Operational | ✓ | GC # checking BIO: #3 |
| Alarms Enabled | ✓ | Cc- Calibration mixt 10-21 |
| GC Influent Filters | ✓ | |

# TABLE 3.19.2
# STANDARD OPERATIONS CHECKLIST
# BIOLOGICAL TREATMENT SYSTEM

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, November 04, 2021

**Inspection Performed by:** Mike Gelwick

## J. TOTALIZERS

| Item | Readings (gallons) | Comments |
|---|---|---|
| FT-3321 Feed to Reactor 1 | 6041847 | |
| FT-3324 Feed Spare | 93574 | |
| FT-3322 Feed to Reactor 2 | 10799535 | |
| FT-3323 Feed to Reactor 3 | 749772 | |
| FT-3301 T-510 to BIO | 51553896 | |
| FT-3341 BIO Effluent | 66377951 | |
| FT-3342 BIO Recycle | 55596121 | |

## K. SAFETY

| Item | Status | Comments |
|---|---|---|
| Building #2 Fire Extinguishers | ✓ | Inspection date: 10-25-21 |
| Building #2 Eye Wash/Shower | ✓ | Checked and Flushed- All OK: (Y) / N |

## L. OTHER COMMENTS:

| |
|---|
| |
| |
| |
| |

# ABLE 3.19.1
# STANDARD OPERATIONS CHECKLIST
# MAIN WTP

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, November 11, 2021

**Inspection Performed by:** Mike Gelwick

## A. PERIMETER COLLECTION SYSTEMS

| Item | Status | Comments |
|---|---|---|
| LFG Cond Automatic Trap CT-1 | Sump Level: 12.52 ok | Counter: 189413 Cycles: 814 |
| LFG Cond Automatic Trap CT-2 | Sump Level: 8.46 ok | Counter: 274542 Cycles: 129 |
| LFG Cond Automatic Trap CT-3 | Sump Level: 7.21 ok | Counter: 310014 Cycles: 842 |
| CT-4 Containment/Vessel (LFG Cond) | ✓ Level: 72 % | Tank Level: 2.13 Counter: 19246 Cycles: 2 Sump: 8.32 ok |
| PM-15 Containment / Vessel | ✓ Level: 76 % | |
| MW-51 Containment / Vessel | ✓ Level: 30 % | |
| PM-11 Containment / Vessel | ✓ Level: 30 % | |
| MW-38 Systems | ✓ | |
| North Toe System | ✓ | |
| North End Systems (Weekly) | ✓ | |
| Full N. End Systems Check (Monthly) | ✓ | Last Done: 10-29-21 |
| North End Pipeline(s)Flushing (As Needed) | ✓ | Perform if suspended solids present Last Done: 11/15/15 |
| NTES line flush to T-530 (As needed) | ✓ | Perform if suspended solids present Last Done: 10/29/21 |
| NTES Piping Containment | ✓ | Monthly Sump Level: ~216.07' Date: 10-21-21 |
| North Boundary System P-001: | CV 74.2 % @ 6.8 gpm | 41.13 Hz / 2.08 Amps. / vault psi @ 18/No leaks |
| T-101 & T-102 Containment / Tank | ✓ | Levels: 46 % & 45 % |
| Raw Water Storage Tanks Piping | ✓ | |
| RWST Building Temp. (TT-101) | 55.9 °F | Outside Temp.: ~ 45 °F |
| (P-121) or P-122 | ✓ | 1.0 gpm / CV 45 % |
| RWST 2ndry Cont. High Level Switch | ✓ | (LSH-101) Last Test(monthly): 10-21-21 |
| RWST Back-Up Generator | ✓ | Last Test Run(monthly): 10-21-21 |

## B. CHEMICAL STORAGE BAYS

| Item | Status | Comments |
|---|---|---|
| Caustic Tote Levels | ✓ | ~ 345 Gallons Reserve = 1 totes |
| Caustic Bay Heater | ✓ | |
| Peroxide Tote Level | ✓ | ~ 126 Gallons Reserve = ~55 gal |
| HCL Tote Levels | ✓ | ~ 205 Gallons Reserve = ~70 gal |
| Chemical Totes and Piping Inspected | ✓ | Leaks observed: Y / (N) |
| Emergency Shower Inspected | ✓ | Checked and Flushed - All OK: (Y) / N |

## C. PRIMARY AND SECONDARY ACID FEED SYSTEM

| Item | Status | Comments |
|---|---|---|
| Primary Acid Feed Pump (P-631) | ✓ | |
| Ion Exchange Acid Feed Pump (P-632) | ✓ | PI-0632 PSI: 80-82 CV: 6 % |
| Primary Acid Retention Tank (T-510) | ✓ | |
| All Acid Feed Lines | ✓ | Leaks observed: Y / (N) |

## D. NBBW INJECTION TRENCH

| Item | Status | Comments |
|---|---|---|
| Injection Carbon (GAC-810) | **OFFLINE** | Date online: 7/20/18 |
| Injection Rate (FT-800) | 0.0 gpm | NBBW-IW-1= 0.0 NBBW-IW-2= 0.0 NBBW-IW-3= 0.0 gpm ea. |
| Totalizer Reading (FT-800) | 105,135,774 gal | INJ. STOPPED 10/02/18 @ 1545 |

# ABLE 3.19.1
# STANDARD OPERATIONS CHECKLIST
# MAIN WTP

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, November 11, 2021

**Inspection Performed by:** Mike Gelwick

## E. CHEMICAL PRECIPITATION SYSTEM (US FILTER HMR-30)

| Item | Status | Comment |
|---|---|---|
| T-300A Mixer | NA | |
| T-300B (Caustic Mixer) | ✓ | Last Cleaning (Qtrly): 10-20-21 |
| T-300A/B Water Level | ✓ | |
| T-300B (Caustic Mix Chamber) | ✓ | Last Cleaning (Qtrly): 10-20-21 |
| T-300A/B Overflow | ✓ | |
| pH Set-point for (pH 315) | Value: 10.8 | |
| pH 310 | Value: 7.01 | |
| pH 315 | Value: 10.96 | |
| Flocculation Chamber Paddle Wheel | ✓ | |
| Precipitate Floc Quality | ✓ | Good |
| Clarifier Water Quality | ✓ | Good Oil or sheen observed: Y / (N) |
| Clarifier Effluent Piping / Water Level | ✓ | |
| Clear-well Chamber and Water Level | ✓ | |
| HMR PLC Panel | ✓ | |
| Caustic Pump (P-270) | SB | |
| Caustic Pump (P-280) | ✓ | |
| Polymer Pump (P-310) | ✓ | |
| Polymer Tank Mixer | ✓ | |
| Polymer Tank Level | Gallons: ~ 400 | |
| Clear-well Transfer Pumps (P-371 / 372) | ✓ | |
| Sludge Transfer Pump (P-330) | ✓ | Exercise Valves Weekly: Both ok |
| Manual Sludge Lateral pumping | ✓ | Last done (As Needed): #3-7-2021 / #12-3-20-21 |
| Manual Sludge Lateral Ball Valves | ✓ | Exercise Weekly: All ok |
| Automatic Blow-down Operations | ✓ | |

## F. pH PROBES

| pH Probe Location | Calibration Date | Comments: (Time done) |
|---|---|---|
| pH-310 HMR-30 (T-300A) | 11-11-21 - today | 1202 |
| pH-315 HMR-30 (T-300B) | | |
| pH-365 Primary Acid Ret. Tank | | |
| pH-113 Pre-Ion Exchange | | |
| pH-670 Pre-UV-OX | | 1240 |
| pH-740 Discharge Surge Tank | | Discharge suspended: 1152 ↔ 1201 |
| Out of Hold Double Check | ---------- | None in hold: |
| Valves Back to Normal Position | ---------- | All OK: |

## G. SLUDGE THICKENER, SLUDGE HOLDING TANKS, FILTER PRESS

| Item | Status | Comments |
|---|---|---|
| Verify Sludge Thickener Running | | Gauge Reading: % |
| Sludge Thick. Transfer Pump (P-350) | ✓ | |
| Sludge Holding Tank (T-351) | ✓ | Level:~ 65 % |
| Sludge Holding Tank (T-352) | ✓ | Level: 42 % |
| Decant Transfer Pump (P-352) | ✓ | CV 61 % @ 0.5 gpm |
| Filter Press Pumps (P-381 / P-382) | ✓ | |
| Filter Press | ✓ | Stage: Ready to fill |

# ABLE 3.19.1
# STANDARD OPERATIONS CHECKLIST
# MAIN WTP

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, November 11, 2021

**Inspection Performed by:** Mike Gelwick

### H. ION EXCHANGE

| Item | Status | Comments |
|---|---|---|
| Feed Tank (T-113) | ✓ Level: 49 % | |
| Feed Pump (P-114) | ✓ Operating Press: 42.8 psi | CV@ 84 % @ 2.9 gpm |
| Retention Tank (T-114) | ✓ Operating Press: 40-42 psi | pH-113 @ 3.73 |
| Bag Filter (BF-113) | ✓ Operating Press: 43-45 psi | |
| Ion Exchange (Cage 1 or 2) + Guard | ✓ Operating Press: 40-42 psi | TP-173A-2 → TP-175A/4 Chem's Hours + Gallons |
| Post Ion Exchange | ✓ Operating Press: 4 psi | |

### I. FEED SURGE TANK

| Item | Status | Comments |
|---|---|---|
| Feed Surge Tank (T-520) | ✓ Level: 39 % | Last Cleaning (As Needed, if 4" of solids accumulate): 12/15/19 |
| Feed Surge Pump (P-521 or P-522) | Operating Press: ~~80~~ 26 psi | CV@ 80 % @ 33.8 gpm |
| T-520 to GAC Total (FT-675) | 252195564 gal | Time: 0936 |
| North End On-Site Pumping | Operating Press: 2-3 psi | 12.8 gpm @ 0931 |
| North End Off-Site Pumping | Operating Press: 2-6 psi | 8.4 gpm @ 0931 |
| Peroxide Feed Pump (P-680) | ✓ | SPD 2.5 % / RATE 0.7 |
| Peroxide Conc. At (TP-710) | 1.0 PPM | |
| Peroxide Conc. At (TP-740) | 0.0 PPM | |

### J. HAZARDOUS WASTE STORAGE

| Item | Status | Comments |
|---|---|---|
| 180 Day storage area check | ✓ | Check sheet completed: NA/Empty |
| Satellite Haz. Waste Areas (BLDG #1) | ✓ | Condition: IX Area + Main Good |
| Satellite Haz. Waste Area (BLDG #2) | ✓ | Condition: Good |

### K. UV-OXIDATION SYSTEM

| Item | Status | Comments |
|---|---|---|
| UV-Oxidation System | ✓ | |
| Annual Test Run (Calgon) | Date: 9-16-21 | Next: 9-2022 |
| Quarterly Test Run | Date: NA/Running | Next: NA/Running |
| Peroxide Feed Pump (P-650) | ✓ | Flow Rate: ~ 7.0 cc/min. |
| UV-Ox Power | ✓ | 25.7 kVA 257 Volts 10.0 Amps |
| Lamp Hours | 339 Hrs | |
| Crystal Condition & Wiper Status | ✓ | Oiler status: OK |
| UV-OX Bagfilters Status | Last change: 7-13-21 Cleaned: 7-13-21 | 12.0 psi In 12.5 psi Out |
| UV-OX Feed Pump ( P-600 or P-601 ) | ✓ | CV@ 77 % @ 7.9 gpm |
| UV-OX Temperature | In(TT-670): 14.5 °C | Out(TT-710): 26.0 °C |
| PDU GAC (PDT-710) | ✓ | Δ Pressure: 4 psi |
| Peroxide Concentration Pre UV | 100 PPM | |
| Peroxide Concentration Post UV(TP-720) | 25 PPM | |
| Peroxide Conc. Post PDU (TP-730) | 0.0 PPM | |
| Secondary Acid Feed Pump (P-630) | ✓ | CV @ 0 % |
| Secondary Acid Retention Tank (T-645) | ✓ | |
| Pre – UV Oxidizer Total (FT-670) | 20284232 gal | Time: 0936 |
| Post UV-Ox / Pre PDU | ✓ | Pressure: 15 psi |
| Post PDU | ✓ | Pressure: 8 psi |

# ABLE 3.19.1
# STANDARD OPERATIONS CHECKLIST
# MAIN WTP

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, November 11, 2021

**Inspection Performed by:** Mike Gelwick

### L. PDU AND LIQUID –PHASE GRANULAR ACTIVATED CARBON

| Item | Status | Comments |
|---|---|---|
| PDT-720 | ✓ | Δ Pressure: 15 psi |
| PDT-730 | ✓ | Δ Pressure: 6 psi |

### M. EFFLUENT DISCHARGE

| Item | Status | Comments |
|---|---|---|
| Effluent Surge Pump ( P751 or (P752)) | ✓ | CV@ 54.5 % |
| Effluent Surge Tank (T-740) | ✓ | Level: 40 % |
| Effluent Discharge Rate (FT-770) | ✓ | 34.0 gpm @ 0934 |
| POTW Line Pressure (PT-770) | ✓ | 32.4 psi |
| Effluent Totalizer Reading (FT-770) | 246329884 gal | Time: 0936 |
| POTW MH17S-078 Discharge Check (Monthly) | ✓ | Last Done: 11-8-21 |
| 4X8-Inch POTW Leak Detection Checks (Monthly) | ✓ | Last Done: ↓ |
| 4X8-Inch POTW Air Reliefs Checks (Monthly) | ✓ | Last Done: ↓ |
| 4X8-Inch POTW Isolation Valves Exercise (Qtrly) | ✓ | Last Done: ↓ |
| 2-Inch POTW Backup Pressure Testing (Annual) | ✓ | Last Done: 7/8/21 |
| 2-In POTW Backup Air Reliefs Checks (Annual) | ✓ | Last Done: 7/8/21 |
| 2-Inch POTW Isolation Valve Exercise (Annual) | ✓ | Last Done: 7/8/21 |
| Rotate Chiller Compressors | NA on Standby | ~~Now in Lead: 1 or 2~~ |

### N. LEL EFFLUENT TANK T-740

| Item | Status | Comments |
|---|---|---|
| LEL-740 Sensor | ✓ | Reading: 0 % |
| LEL Sensor Calibration / Automatic High LEL Shutdown Test (monthly) | Last Completed: 10-29-21 | Plant Effluent Suspended: 1352 ↔ 1413 |
| LEL Sensor Bridge Adjustment to 2.0 volts | Reading: 2.000 volts(monthly) | Adjustment Needed: Y or (N) |
| Verify Bridge Current between.300v-.360v | Reading: 0.330 volts(monthly) | |

### O. WTP INFLUENT TOTALIZERS Time : 0937 - 0941

| Source | Reading(Gallons) | Source | Reading(Gallons) |
|---|---|---|---|
| (FT-015) RWST Influent | 19696869 | (FT-505) LFG Cond. to T-530 | 218619 |
| (FT-025) NBBW Influent | 94176860 | (FT-056) Off - Site N. End Influent | 43340164 |
| (FT-012) MW-38 Inf. to HMR-30 | 8313838 | (FT-113) Ion Exchange Influent | 860340 |
| (FT-042 HMR30) MW-38 Source to HMR-30 | 35484 | (FT-810) Plant Potable Water In | 30065290 |
| (FT-043) MW-38 to RWST | 3080261 | (FT-026) NBBW Bypass to RWST | 4414089 |
| (FT-042 RWST) MW-38 Source to RWST | 72236 | (FT-014) Misc. Water to RWST | 8187853 |
| (FT-012T) MW-38 to T-540/541 | 8628632 | (FT-035) NTES Inf. to BIO | 6672066 |
| (FT-040T) MW-38N to T-540/541 | 1978197 | (FT-035T) NTES to T-530 | 464291 |
| (FT-041T) MW-38S to T-540/541 | 2696237 | (FT-017) BIO Inf. from T-530 | 656512 |
| (FT-042T) MW-38 Source to T-540/541 | 4026207 | (FT-018) T-540/541 Influent | 8669467 |
| (FT-055) On - Site N. End Influent | 98434419 | (FT-352) T-352 to HMR-30 | 1300656 |

# ABLE 3.19.1
# STANDARD OPERATIONS CHECKLIST
# MAIN WTP

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, November 11, 2021

**Inspection Performed by:** Mike Gelwick

### P. AIR COMPRESSORS * Still Running on BACK UPS *

| Item | Status | Comments |
|---|---|---|
| Compressor Intake Temp. | 56 °F (Analog Gauge) | Outside Temp.: ~ 47 °F |
| Compressor Building Vent | ✓ | |
| Primary Air Compressor (IRN30H) | 2,000 Hour service date: 7-8-21<br>Serviced @ 60952 Hours | Coolant present in sight glass: (Y) / N<br>Next service @ 62952 Hours<br>Current Hours @ — off |
| IRN30H Motor Speed | — % | |
| IRN30H Pressure | — psi | |
| IRN30H Moisture purge valve chk(Weekly): | — | |
| IRN30H Intake Filter | ✓ | Date Last Changed: 9-30-21 |
| Air Tanks Moisture Purge Valves | Manually Activate(weekly) ✓ | Excessive Moisture: Y / (N) |
| Backup Air Compressors (T-30 East and West) | Running | Both cool to touch: Y / (N) |
| Air Dryer | ✓ Eco on | Moisture at Receiver Tank: Y / (N) |
| Oil Moisture Prevention (Monthly) | Last Done: 9-23-21 | Run at max speed by bleeding air from filter canister above/after air dryer for 2 hrs |
| Air Receiver Tank | | 102 psi |

### Q. SUMPS

| Item | Status | Comments |
|---|---|---|
| Bag Filter Sump | ✓ | |
| Wet Well Sump | ✓ | |

### R. GAS CHROMATOGRAPH

| Item | Status | Comments |
|---|---|---|
| GC Operational | ✓ | GC # checking UV-Ox Effluent: #2 |
| Alarms Enabled | ✓ | cc - calibration + maint 11-10-21 * NEW TRAP * |
| GC Influent Filters | ✓ | |

### S. SAFETY

| Item | Status | Comments |
|---|---|---|
| Building #1 Fire Extinguishers | ✓ | Date inspected: 10-25-21 |
| Building #1 Eye Wash/Shower | ✓ | Checked and Flushed- All OK: (Y) / N |

**Other Comments:**

# TABLE 3.19.2
# STANDARD OPERATIONS CHECKLIST
# BIOLOGICAL TREATMENT SYSTEM

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, November 11, 2021

**Inspection Performed by:** Mike Gelwick

## A. PUMPS

| Item | Status | Flow Rate (gpm) | Pump Speed (CV%) | Discharge Pressure (psi) | | Comments |
|---|---|---|---|---|---|---|
| **T-510 Pumps** | | | | | | |
| P-3301 | ✓ | 1.79 | 32.0 % | 6.5 | | |
| P-3301A | SB | – | – % | – | | |
| **NTES Pump** P-002(Sump) / (P-002W(10R)) | ✓ | 0.51 | 49 % | P035 34-35 | P038 6.5 | Globules Observed at TP-130: Y / (N) Time: 0905 |
| **T-530** P-005 | ✓ | 0.20 | 41 % | 7.0 | | |
| **T-540/541** P-006 | ✓ | 0.30 | 57 % | 7.0 | | |
| **LFG COND Auto-Traps** | ✓ | 0.0 | NA | 5.0 | | Between Cycles: (Y) / N |
| **Reactor Feed Pumps** | | | | | | |
| P-3321 | ~~2.28~~ ✓ | ~~57.8~~ 2.28 | 57.8 % | 7.0 | | |
| P-3322 | ✓ | 3.19 | 51.2 % | 5.5 | | |
| P-3323 | SB | – | – % | – | | |
| P-3324 | ~~2.34~~ ✓ | ~~36.4~~ 2.34 | 36.4 % | 5.0 | | |
| **Reactor Effluent Pumps** | | | | | | |
| P-3341 | ✓ | 2.15 | 48.9 % | 16 | | |
| P-3341A | SB | – | – % | – | | |

## B. BLOWERS

| Item | Status | Pressure (psi) | Temp (°F) | Next Scheduled Service (Qtrly) | Comments Last serviced on: 10-1-21 |
|---|---|---|---|---|---|
| B-3331 | ✓ | 4.35 | 126 | 12-2021 | Greased, Belt and Filter Checked: (Y) / N |
| B-3332 | SB | – | – | ↓ | Belt and Filter Checked: Y / (N) |
| B-3333 | ✓ | 4.36 | 126 | ↓ | Greased, Belt and Filter Checked: (Y) / N |
| B-3334 | ✓ | 4.34 | 122 | ↓ | Greased, Belt and Filter Checked: (Y) / N |

## C. REACTOR VENTILATION

| Item | Status | Comments |
|---|---|---|
| Vapor Carbon Contactor | ✓ | On-line: 2/10/18 |
| Reactor Vent Blower | ✓ | |
| Reactor Vent Booster | ✓ | |
| VTP-3350 | ✓ | PID Reading: 21.7 PPM |
| VTP-3360 | ✓ | PID Reading: 12.6 PPM |

# TABLE 3.19.2
# STANDARD OPERATIONS CHECKLIST
# BIOLOGICAL TREATMENT SYSTEM

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, November 11, 2021

**Inspection Performed by:** Mike Gelwick

## D. TANKS / REACTORS / SUMPS / CONTAINMENTS / PIPING / Chiller

| Item | Status | Comments |
|---|---|---|
| T-510 Post HMR-30 Mixing Tank | ✓ Level: 69 % | Last Cleaning (As needed, if 2" of solids accumulate): 7/14/21 |
| T-530 LFG Condensate / NTES Tank | ✓ Level: 37 % | |
| T-530 Mixer | ✓ | |
| LFG Condensate Conveyance Line | ✓ | Last Pressure Test: 7-19-21 Next: 7-2022 (Annual at a minimum or if flow drops off) |
| T-540/541 MW38 Tanks | Lvls: 71 % & 80 % | |
| T-540/541 Mixers | ✓ | T-541 SP: 71 Down |
| Chiller | ✓ | Chiller Coolant Lvl: ~ — " Below full mark |
| Chiller Cooling Fins (as needed) | ✓ | Last Cleaning: 4/20/18 (unit on Standby) |
| Secondary Containments | ✓ | Heat Trace: On OK / (Off Warm out) |
| Feed Piping to Sedimentation Tank | ✓ | Last Back Flushing (Quarterly): 10-13-21 |
| T-3310 Sedimentation Tank | Visual Level: OK | Last Cleaning (As Needed, use TSS info to determine): 9/2021 |
| T-3320 Blend Tank | ✓ Level: 71 % | Last Cleaning (Semi Annual): 9-10-21 |
| T-3331 Reactor No. 1 | ✓ | Digital Displays: (GOOD) / Needs Attn |
| T-3332 Reactor No. 2 | ✓ | Digital Displays: (GOOD) / Needs Attn |
| T-3333 Reactor No. 3 | ✓ | Digital Displays: (GOOD) / Needs Attn |
| T-3334 Settling Tank | ✓ | Last Cleaning (Semi Annual): 9-10-21 |
| P-3334 Biosolids Pump | ✓ | |
| T-3340 Overflow Tank | ✓ Level: 30 % | |
| Recycle Valve to Blend Tank | ✓ | 4.32 gpm @ 0952 |
| Building Containment Sump | ✓ | Last Alarm Test Date (Monthly): 10-21-21 |

## E. CHEMICAL FEED SYSTEM

| Item | Status | Comments |
|---|---|---|
| Phosphorous Supply | ✓ | Bags: 15.95 Gallons: ~ 70 |
| Phosphorous Pump (P-2221) | ✓ | |
| Caustic Supply | ✓ | ~ 45 Gallons |
| Caustic Pump (P-2211) | SB | Currently in acid addition mode |
| Acid Supply | ✓ | ~ 40 Gallons |
| Acid Pump (P-2211) | ✓ | |
| Caustic Pump (P-2231) | ✓ Leaks: Y / (N) | Last tubing tip cleaning (monthly): 10-21-21 |
| Caustic Pump (P-2232) | ✓ Leaks: Y / (N) | Last tubing tip cleaning (monthly): ↓ |
| Caustic Pump (P-2233) | ✓ Leaks: Y / (N) | Last tubing tip cleaning (monthly): |

# TABLE 3.19.2
# STANDARD OPERATIONS CHECKLIST
# BIOLOGICAL TREATMENT SYSTEM

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, November 11, 2021

**Inspection Performed by:** Mike Gelwick

## F. pH Probes

| pH Probe Location | Calibration Date (Monthly) | Comments |
|---|---|---|
| pH-3320 Blend Tank | 10-29-21 | Spray off clean today |
| pH-3331 Reactor 1 | ↓ | ↓ |
| pH-3332 Reactor 2 | | |
| pH-3333 Reactor 3 | | |

## G. FILTER SYSTEM

| Item | Status | Comments |
|---|---|---|
| BF-3340 a/b Status | ✓ | |
| Automatic Backwash | Cycle Count: 109 | Reset |
| BF-3340 a/b Differential Pressure | PSI: 3 | 20/17 → 3.6 gpm |
| 75-micron Bags Last Cleaning | Date: 11-14-19 | |
| 75-micron Bags Last Inspection | Date: ↓ | |
| 75-micron Bags Last Changed | Date: | |
| GACF-3340 Status | ✓ | |
| GACF-3340 Differential Pressure | PSI: 10 | 17/7 → 3.6 gpm |
| Last Backwash Performed | Date: 9-27-21 | |

## H. ELECTRICAL AND INSTRUMENTATION

| Item | Status | Comments |
|---|---|---|
| "BIO" Backup Generator | ✓ | Block Heater: (On OK) / Off Warm Out |
| Electrical Surge Suppressor | ✓ | |
| Motor Control Center | ✓ | |
| PLC | ✓ | UPS @ 97 min / 95 Events |
| HMI's | ✓ | |
| BTS Process KWH Meter | 1813933 KWH | Time: 1031 |
| Building#2 KWH Meter | 5252953 KWH | Time: 1031 |

## I. GAS CHROMATOGRAPHY

| Item | Status | Comments |
|---|---|---|
| GC Operational | ✓ | GC # checking BIO: #3 |
| Alarms Enabled | ✓ | Ac-cal3 revision + method 11-10-21 |
| GC Influent Filters | ✓ | |

# TABLE 3.19.2
# STANDARD OPERATIONS CHECKLIST
# BIOLOGICAL TREATMENT SYSTEM

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, November 11, 2021

**Inspection Performed by:** Mike Gelwick

## J. TOTALIZERS

| Item | Readings (gallons) | Comments |
|---|---|---|
| FT-3321 Feed to Reactor 1 | 6063404 | |
| FT-3324 Feed Spare | 104106 | |
| FT-3322 Feed to Reactor 2 | 10824487 | |
| FT-3323 Feed to Reactor 3 | 760556 | |
| FT-3301 T-510 to BIO | 51572914 | |
| FT-3341 BIO Effluent | 66404687 | |
| FT-3342 BIO Recycle | 55628075 | |

## K. SAFETY

| Item | Status | Comments |
|---|---|---|
| Building #2 Fire Extinguishers | ✓ | Inspection date: 10-25-21 |
| Building #2 Eye Wash/Shower | ✓ | Checked and Flushed- All OK: Ⓨ / N |

## L. OTHER COMMENTS:

| |
|---|
| |
| |
| |
| |

# ABLE 3.19.1
# STANDARD OPERATIONS CHECKLIST
# MAIN WTP

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, November 18, 2021

**Inspection Performed by:** Mike Gelwick

## A. PERIMETER COLLECTION SYSTEMS

| Item | Status | Comments |
|---|---|---|
| LFG Cond Automatic Trap CT-1 | Sump Level: 12.49 ac | Counter: 189973 Cycles: 560 |
| LFG Cond Automatic Trap CT-2 | Sump Level: 8.71 ac | Counter: 274542 Cycles: 0 |
| LFG Cond Automatic Trap CT-3 | Sump Level: 7.22 ac | Counter: 311383 Cycles: 1369 |
| CT-4 Containment/Vessel (LFG Cond) | ✓ Level: 72 % | Tank Level: 2.13 Counter: 191255 Cycles: 9 Sump: 8.65 ac |
| PM-15 Containment / Vessel | ✓ Level: 80 % | |
| MW-51 Containment / Vessel | ✓ Level: 60 % | |
| PM-11 Containment / Vessel | ✓ Level: 60 % | |
| MW-38 Systems | ✓ | |
| North Toe System | ✓ | |
| North End Systems (Weekly) | ✓ | |
| Full N. End Systems Check (Monthly) | ✓ | Last Done: 10-29-21 |
| North End Pipeline(s)Flushing (As Needed) | ✓ | Perform if suspended solids present Last Done: 11/15/15 |
| NTES line flush to T-530 (As needed) | ✓ | Perform if suspended solids present Last Done: 10/29/21 |
| NTES Piping Containment | ✓ | Monthly Sump Level: dry @ 16.07' Date: 11-18-21 - today |
| North Boundary System P-001: | CV 74.0% @ 6.8 gpm | 41.07 Hz / 2.08 Amps. / vault psi @ 18/NO leaks |
| T-101 & T-102 Containment / Tank | ✓ | Levels: 33 % & 32 % |
| Raw Water Storage Tanks Piping | ✓ | |
| RWST Building Temp. (TT-101) | 58.5 °F | Outside Temp.: ~ 40 °F |
| (P-121) or P-122 | ✓ | 0.60 gpm / CV 54 % |
| RWST 2ndry Cont. High Level Switch | ✓ | (LSH-101) Last Test(monthly): 11-18-21 - today |
| RWST Back-Up Generator | ✓ | Last Test Run(monthly): 11-18-21 - today |

## B. CHEMICAL STORAGE BAYS

| Item | Status | Comments |
|---|---|---|
| Caustic Tote Levels | ✓ | ~ 555 Gallons Reserve = 3 totes |
| Caustic Bay Heater | ✓ | |
| Peroxide Tote Level | ✓ | ~ 300 Gallons Reserve = 180 gal |
| HCL Tote Levels | ✓ | ~ 165 Gallons Reserve = 170 gal |
| Chemical Totes and Piping Inspected | ✓ | Leaks observed: Y / (N) |
| Emergency Shower Inspected | ✓ | Checked and Flushed - All OK: (Y) / N |

## C. PRIMARY AND SECONDARY ACID FEED SYSTEM

| Item | Status | Comments |
|---|---|---|
| Primary Acid Feed Pump (P-631) | ✓ | |
| Ion Exchange Acid Feed Pump (P-632) | ✓ | PI-0632 PSI: 82-84 CV: 6 % |
| Primary Acid Retention Tank (T-510) | ✓ | |
| All Acid Feed Lines | ✓ | Leaks observed: Y / (N) |

## D. NBBW INJECTION TRENCH

| Item | Status | Comments |
|---|---|---|
| Injection Carbon (GAC-810) | OFFLINE | Date online: 7/20/18 |
| Injection Rate (FT-800) | 0.0 gpm | NBBW-IW-1= 0.0 NBBW-IW-2= 0.0 NBBW-IW-3= 0.0 gpm ea. |
| Totalizer Reading (FT-800) | 105,135,774 gal | INJ. STOPPED 10/02/18 @ 1545 |

# ABLE 3.19.1
# STANDARD OPERATIONS CHECKLIST
# MAIN WTP

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, November 18, 2021

**Inspection Performed by:** Mike Gelwick

### E. CHEMICAL PRECIPITATION SYSTEM (US FILTER HMR-30)

| Item | Status | Comment |
|---|---|---|
| T-300A Mixer | NA | |
| T-300B (Caustic Mixer) | ✓ | Last Cleaning (Qtrly): 10-20-21 |
| T-300A/B Water Level | ✓ | |
| T-300B (Caustic Mix Chamber) | ✓ | Last Cleaning (Qtrly): 10-20-21 |
| T-300A/B Overflow | ✓ | |
| pH Set-point for (pH 315) | Value: 10.8 | |
| pH 310 | Value: 7.10 | |
| pH 315 | Value: 10.96 | |
| Flocculation Chamber Paddle Wheel | ✓ | |
| Precipitate Floc Quality | ✓ | Good |
| Clarifier Water Quality | ✓ | Good Oil or sheen observed: Y / (N) |
| Clarifier Effluent Piping / Water Level | ✓ | |
| Clear-well Chamber and Water Level | ✓ | |
| HMR PLC Panel | ✓ | |
| Caustic Pump (P-270) | SB | |
| Caustic Pump (P-280) | ✓ | |
| Polymer Pump (P-310) | ✓ | |
| Polymer Tank Mixer | ✓ | |
| Polymer Tank Level | Gallons: ~500 | |
| Clear-well Transfer Pumps (P-371 / 372) | ✓ | |
| Sludge Transfer Pump (P-330) | ✓ | Exercise Valves Weekly: Balloon |
| Manual Sludge Lateral pumping | ✓ | Last done (As Needed): #3-7-20-21/#12-5-20-21 |
| Manual Sludge Lateral Ball Valves | ✓ | Exercise Weekly: Allon |
| Automatic Blow-down Operations | ✓ | |

### F. pH PROBES

| pH Probe Location | Calibration Date | Comments: (Time done) |
|---|---|---|
| pH-310 HMR-30 (T-300A) | 11-18-21-Today | 1334 |
| pH-315 HMR-30 (T-300B) | | |
| pH-365 Primary Acid Ret. Tank | | |
| pH-113 Pre-Ion Exchange | | |
| pH-670 Pre-UV-OX | | 1406 |
| pH-740 Discharge Surge Tank | | Discharge suspended: 1324 ↔ 1323 |
| Out of Hold Double Check | ---------- | None in hold: ✓✓ 'm |
| Valves Back to Normal Position | ---------- | All OK: ✓✓ 'm |

### G. SLUDGE THICKENER, SLUDGE HOLDING TANKS, FILTER PRESS

| Item | Status | Comments |
|---|---|---|
| Verify Sludge Thickener Running | ✓ | Gauge Reading: 0 % |
| Sludge Thick. Transfer Pump (P-350) | ✓ | |
| Sludge Holding Tank (T-351) | ✓ | Level: ~ 65 % |
| Sludge Holding Tank (T-352) | ✓ | Level: 48 % |
| Decant Transfer Pump (P-352) | ✓ | CV 59% @ 0.6 gpm |
| Filter Press Pumps (P-381 / P-382) | ✓ | |
| Filter Press | ✓ | Stage: Empty/Ready to Fill |

# ABLE 3.19.1
# STANDARD OPERATIONS CHECKLIST
# MAIN WTP

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, November 18, 2021

**Inspection Performed by:** Mike Gelwick

### H. ION EXCHANGE

| Item | Status | Comments |
|---|---|---|
| Feed Tank (T-113) | ✓ Level: 54 % | |
| Feed Pump (P-114) | ✓ Operating Press: 37.1 psi | CV@ 71 % @ 2.5 gpm |
| Retention Tank (T-114) | ✓ Operating Press: 35 psi | pH-113 @ 3.89 |
| Bag Filter (BF-113) | ✓ Operating Press: 42 psi | |
| Ion Exchange (Cage (1) or 2) + Guard | ✓ Operating Press: 35 psi | TP-173A→TP-175A/4 canisters + Guard. |
| Post Ion Exchange | ✓ Operating Press: 4 psi | |

### I. FEED SURGE TANK

| Item | Status | Comments |
|---|---|---|
| Feed Surge Tank (T-520) | ✓ Level: 38 % | Last Cleaning (As Needed, if 4" of solids accumulate): 12/15/19 |
| Feed Surge Pump (P-521 or P-522) | Operating Press: 27 psi | CV@ 79 % @ 33.1 gpm |
| T-520 to GAC Total (FT-675) | 252534182 gal | Time: 1041 |
| North End On-Site Pumping | Operating Press: 2-3 psi | 12.9 gpm @ 1036 |
| North End Off-Site Pumping | Operating Press: 2-6 psi | 8.2 gpm @ 1036 |
| Peroxide Feed Pump (P-680) | ✓ | SPD 2.5 % / RATE 0.7 |
| Peroxide Conc. At (TP-710) | 1.0 PPM | |
| Peroxide Conc. At (TP-740) | 0.0 PPM | |

### J. HAZARDOUS WASTE STORAGE

| Item | Status | Comments |
|---|---|---|
| 180 Day storage area check | ✓ | Check sheet completed: NA/Empty |
| Satellite Haz. Waste Areas (BLDG #1) | ✓ | Condition: Ex Resin + mats Good |
| Satellite Haz. Waste Area (BLDG #2) | ✓ | Condition: Good |

### K. UV-OXIDATION SYSTEM

| Item | Status | Comments |
|---|---|---|
| UV-Oxidation System | ✓ | |
| Annual Test Run (Calgon) | Date: 9-16-21 | Next: 9-2022 |
| Quarterly Test Run | Date: NA/Running | Next: NA/Running |
| Peroxide Feed Pump (P-650) | ✓ | Flow Rate: ~ 7.2 cc/min. |
| UV-Ox Power | ✓ | 25.7 kVA 2568 Volts 10.1 Amps |
| Lamp Hours | 504 Hrs | |
| Crystal Condition & Wiper Status | ✓ | Oiler status: OK |
| UV-OX Bagfilters Status | Last change: 7-13-21 Cleaned: 7-13-21 | 11.5 psi In 11.0 psi Out |
| UV-OX Feed Pump ( P-600 or (P-601) ) | ✓ | CV@ 71 % @ 7.5 gpm |
| UV-OX Temperature | In(TT-670): 14.4 °C | Out(TT-710): 27.1 °C |
| PDU GAC (PDT-710) | ✓ | Δ Pressure: 2 psi |
| Peroxide Concentration Pre UV | 100 PPM | |
| Peroxide Concentration Post UV(TP-720) | 25 PPM | |
| Peroxide Conc. Post PDU (TP-730) | 0.0 PPM | |
| Secondary Acid Feed Pump (P-630) | ✓ | CV @ 3 % |
| Secondary Acid Retention Tank (T-645) | ✓ | |
| Pre – UV Oxidizer Total (FT-670) | 20360868 gal | Time: 1041 |
| Post UV-Ox / Pre PDU | ✓ | Pressure: 13 psi |
| Post PDU | ✓ | Pressure: 8 psi |

# ABLE 3.19.1
# STANDARD OPERATIONS CHECKLIST
# MAIN WTP

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, November 18, 2021

**Inspection Performed by:** Mike Gelwick

### L. PDU AND LIQUID –PHASE GRANULAR ACTIVATED CARBON

| Item | Status | Comments |
|---|---|---|
| PDT-720 | ✓ | Δ Pressure: 16 psi |
| PDT-730 | ✓ | Δ Pressure: 6 psi |

### M. EFFLUENT DISCHARGE

| Item | Status | Comments |
|---|---|---|
| Effluent Surge Pump (P751 or P752 ) | ✓ | CV@ 55.9 % |
| Effluent Surge Tank (T-740) | ✓ | Level: 40 % |
| Effluent Discharge Rate (FT-770) | ✓ | 32.9 gpm @ 1039 |
| POTW Line Pressure (PT-770) | ✓ | 32.1 psi |
| Effluent Totalizer Reading (FT-770) | 2466709.72 gal | Time: 1041 |
| POTW MH17S-078 Discharge Check (Monthly) | ✓ | Last Done: 11-8-21 |
| 4X8-Inch POTW Leak Detection Checks (Monthly) | ✓ | Last Done: |
| 4X8-Inch POTW Air Reliefs Checks (Monthly) | ✓ | Last Done: |
| 4X8-Inch POTW Isolation Valves Exercise (Qtrly) | ✓ | Last Done: |
| 2-Inch POTW Backup Pressure Testing (Annual) | ✓ | Last Done: 7/8/21 |
| 2-In POTW Backup Air Reliefs Checks (Annual) | ✓ | Last Done: 7/8/21 |
| 2-Inch POTW Isolation Valve Exercise (Annual) | ✓ | Last Done: 7/8/21 |
| Rotate Chiller Compressors | NA on Standby | ~~Now in Lead: 1 or 2~~ |

### N. LEL EFFLUENT TANK T-740

| Item | Status | Comments |
|---|---|---|
| LEL-740 Sensor | ✓ | Reading: 0 % |
| LEL Sensor Calibration / Automatic High LEL Shutdown Test (monthly) | Last Completed: 10-29-21 | Plant Effluent Suspended: 1352 ↔ 1413 |
| LEL Sensor Bridge Adjustment to 2.0 volts | Reading: 2.000 volts(monthly) | Adjustment Needed: Y or N |
| Verify Bridge Current between.300v-.360v | Reading: 0.330 volts(monthly) | |

### O. WTP INFLUENT TOTALIZERS Time : 1042-1046

| Source | Reading(Gallons) | Source | Reading(Gallons) |
|---|---|---|---|
| (FT-015) RWST Influent | 19706548 | (FT-505) LFG Cond. to T-530 | 218806 |
| (FT-025) NBBW Influent | 94242410 | (FT-056) Off - Site N. End Influent | 43425024 |
| (FT-012) MW-38 Inf. to HMR-30 | 8333599 | (FT-113) Ion Exchange Influent | 886426 |
| (FT-042 HMR30) MW-38 Source to HMR-30 | 35484 | (FT-810) Plant Potable Water In | 30066388 |
| (FT-043) MW-38 to RWST | 3081218 | (FT-026) NBBW Bypass to RWST | 4417406 |
| (FT-042 RWST) MW-38 Source to RWST | 72236 | (FT-014) Misc. Water to RWST | 8187833 |
| (FT-012T) MW-38 to T-540/541 | 8628632 | (FT-035) NTES Inf. to BIO | 6676940 |
| (FT-040T) MW-38N to T-540/541 | 1978197 | (FT-035T) NTES to T-530 | 464586 |
| (FT-041T) MW-38S to T-540/541 | 2696237 | (FT-017) BIO Inf. from T-530 | 656998 |
| (FT-042T) MW-38 Source to T-540/541 | 4026207 | (FT-018) T-540/541 Influent | 8672337 |
| (FT-055) On - Site N. End Influent | 98563298 | (FT-352) T-352 to HMR-30 | 1303083 |

# ABLE 3.19.1
# STANDARD OPERATIONS CHECKLIST
# MAIN WTP

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, November 18, 2021

**Inspection Performed by:** Mike Gelwick

### P. AIR COMPRESSORS * Still running on BACKUP *

| Item | Status | Comments |
|---|---|---|
| Compressor Intake Temp. | 56 °F (Analog Gauge) | Outside Temp.: ~ 45 °F |
| Compressor Building Vent | ✓ | open - observed |
| Primary Air Compressor (IRN30H) | 2,000 Hour service date: 7-8-21<br>Serviced @ 60952 Hours | Coolant present in sight glass: Ⓨ / N<br>Next service @ 62952 Hours<br>Current Hours @ — off |
| IRN30H Motor Speed | — % | |
| IRN30H Pressure | — psi | |
| IRN30H Moisture purge valve chk(Weekly): | — | |
| IRN30H Intake Filter | ✓ | Date Last Changed: 9-30-21 |
| Air Tanks Moisture Purge Valves | Manually Activate(weekly) ✓ | Excessive Moisture: Y / Ⓝ |
| Backup Air Compressors (T-30 East and West) | Running / * New motor on #1 BACKUP * | Both cool to touch: Y / Ⓝ |
| Air Dryer | ✓ ECO on | Moisture at Receiver Tank: Y / Ⓝ |
| Oil Moisture Prevention (Monthly) | Last Done: 9-23-21 | Run at max speed by bleeding air from filter canister above/after air dryer for 2 hrs |
| Air Receiver Tank | ✓ | 110 psi |

### Q. SUMPS

| Item | Status | Comments |
|---|---|---|
| Bag Filter Sump | ✓ | |
| Wet Well Sump | ✓ | |

### R. GAS CHROMATOGRAPH

| Item | Status | Comments |
|---|---|---|
| GC Operational | ✓ | GC # checking UV-Ox Effluent: #2 |
| Alarms Enabled | ✓ | cc calibration + maint - 11-17-21 |
| GC Influent Filters | ✓ | |

### S. SAFETY

| Item | Status | Comments |
|---|---|---|
| Building #1 Fire Extinguishers | ✓ | Date inspected: 10-25-21 |
| Building #1 Eye Wash/Shower | ✓ | Checked and Flushed- All OK: Ⓨ / N |

**Other Comments:**

* 11-12-21 - New Motor put on BACK UP compressor #1 (Southern most compressor)

# TABLE 3.19.2
# STANDARD OPERATIONS CHECKLIST
# BIOLOGICAL TREATMENT SYSTEM

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, November 18, 2021

**Inspection Performed by:** Mike Gelwick

## A. PUMPS

| Item | Status | Flow Rate (gpm) | Pump Speed (CV%) | Discharge Pressure (psi) | | Comments |
|---|---|---|---|---|---|---|
| **T-510 Pumps** | | | | | | |
| P-3301 | ✓ | 1.83 | 35.3 % | 6.5 | | |
| P-3301A | SB | – | – % | – | | |
| **NTES Pump** P-002(Sump) / (P-002W(10R)) | ✓ | 0.51 | 49 % | P035 35-36 | P038 8 | Globules Observed at TP-130: Y / (N) Time: 1020 |
| **T-530** P-005 | ✓ | 0.24 | 40 % | 7.5 | | |
| **T-540/541** P-006 | ✓ | 0.30 | 71 % | 8.0 | | |
| **LFG COND Auto-Traps** | ✓ | 0.0 | NA | 6.0 | | Between Cycles: (Y) / N |
| **Reactor Feed Pumps** | | | | | | |
| P-3321 | ✓ | 2.53 | 56.4 % | 7.5 | | |
| P-3322 | ✓ | 3.50 | 50.2 % | 5.0 | | |
| P-3323 | ✓ | 2.61 | 78.7 % | 6.5 | | |
| P-3324 | SB | – | – % | – | | |
| **Reactor Effluent Pumps** | | | | | | |
| P-3341 | ✓ | 3.38 | 57.6 % | 16.0 | | |
| P-3341A | SB | – | – % | – | | |

## B. BLOWERS

| Item | Status | Pressure (psi) | Temp (°F) | Next Scheduled Service (Qtrly) | Comments Last serviced on: 10-1-21 |
|---|---|---|---|---|---|
| B-3331 | ✓ | 4.32 | 126 | 12-2021 | Greased, Belt and Filter Checked: (Y) / N |
| B-3332 | SB | – | – | ↓ | Belt and Filter Checked: Y / (N) |
| B-3333 | ✓ | 4.42 | 128 | ↓ | Greased, Belt and Filter Checked: (Y) / N |
| B-3334 | ✓ | 4.33 | 124 | ↓ | Greased, Belt and Filter Checked: (Y) / N |

## C. REACTOR VENTILATION

| Item | Status | Comments |
|---|---|---|
| Vapor Carbon Contactor | ✓ | On-line: 2/10/18 |
| Reactor Vent Blower | ✓ | |
| Reactor Vent Booster | ✓ | |
| VTP-3350 | ✓ | PID Reading: 19.8 PPM |
| VTP-3360 | ✓ | PID Reading: 15.7 PPM |

# TABLE 3.19.2
# STANDARD OPERATIONS CHECKLIST
# BIOLOGICAL TREATMENT SYSTEM

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, November 18, 2021

**Inspection Performed by:** Mike Gelwick

## D. TANKS / REACTORS / SUMPS / CONTAINMENTS / PIPING / Chiller

| Item | Status | Comments |
|---|---|---|
| T-510 Post HMR-30 Mixing Tank | ✓ Level: 69 % | Last Cleaning (As needed, if 2" of solids accumulate): 7/14/21 |
| T-530 LFG Condensate / NTES Tank | ✓ Level: 35 % | |
| T-530 Mixer | ✓ | |
| LFG Condensate Conveyance Line | ✓ | Last Pressure Test: 7-19-21 Next: 7-2022 (Annual at a minimum or if flow drops off) |
| T-540/541 MW38 Tanks | Lvls: 57 % & 57 % | |
| T-540/541 Mixers | ✓ | T-541-Still needs replace |
| Chiller | ✓ | Chiller Coolant Lvl: ~ — " Below full mark |
| Chiller Cooling Fins (as needed) | ✓ | Last Cleaning: 4/20/18 (unit on Standby) |
| Secondary Containments | ✓ | Heat Trace: On OK / (Off Warm out) |
| Feed Piping to Sedimentation Tank | ✓ | Last Back Flushing (Quarterly): 11-12-21 |
| T-3310 Sedimentation Tank | Visual Level: ✓ | Last Cleaning (As Needed, use TSS info to determine): 9/2021 |
| T-3320 Blend Tank | Level: % | Last Cleaning (Semi Annual): 9-10-21 |
| T-3331 Reactor No. 1 | ✓ | Digital Displays: (GOOD) / Needs Attn |
| T-3332 Reactor No. 2 | ✓ | Digital Displays: (GOOD) / Needs Attn |
| T-3333 Reactor No. 3 | ✓ | Digital Displays: (GOOD) / Needs Attn |
| T-3334 Settling Tank | ✓ | Last Cleaning (Semi Annual): 9-10-21 |
| P-3334 Biosolids Pump | ✓ | |
| T-3340 Overflow Tank | Level: 30 % | |
| Recycle Valve to Blend Tank | ✓ | 3.97 gpm @ 1116 |
| Building Containment Sump | ✓ | Last Alarm Test Date (Monthly): 11-18-21 - today |

## E. CHEMICAL FEED SYSTEM

| Item | Status | Comments |
|---|---|---|
| Phosphorous Supply | ✓ | Bags: 15.75 Gallons: ~ >0 |
| Phosphorous Pump (P-2221) | ✓ | |
| Caustic Supply | ✓ | ~ 300 Gallons * New today * |
| Caustic Pump (P-2211) | SB | Currently in acid addition mode |
| Acid Supply | ✓ | ~ 40 Gallons |
| Acid Pump (P-2211) | ✓ | |
| Caustic Pump (P-2231) | ✓ Leaks: Y / (N) | Last tubing tip cleaning (monthly): 11-18-21 - today |
| Caustic Pump (P-2232) | ✓ Leaks: Y / (N) | Last tubing tip cleaning (monthly): ↓ |
| Caustic Pump (P-2233) | ✓ Leaks: Y / (N) | Last tubing tip cleaning (monthly): ↓ |

# TABLE 3.19.2
# STANDARD OPERATIONS CHECKLIST
# BIOLOGICAL TREATMENT SYSTEM

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, November 18, 2021

**Inspection Performed by:** Mike Gelwick

### F. pH Probes

| pH Probe Location | Calibration Date (Monthly) | Comments |
|---|---|---|
| pH-3320 Blend Tank | 10-29-21 | Acid/Caustic clean today |
| pH-3331 Reactor 1 | ↓ | ↓ |
| pH-3332 Reactor 2 | | |
| pH-3333 Reactor 3 | | |

### G. FILTER SYSTEM

| Item | Status | Comments |
|---|---|---|
| BF-3340 a/b Status | ✓ | |
| Automatic Backwash | Cycle Count: 34 | Reset |
| BF-3340 a/b Differential Pressure | PSI: 5 | 19/14 @ 3.6 gpm |
| 75-micron Bags Last Cleaning | Date: 11-14-19 | |
| 75-micron Bags Last Inspection | Date: ↓ | |
| 75-micron Bags Last Changed | Date: | |
| GACF-3340 Status | ✓ | |
| GACF-3340 Differential Pressure | PSI: > | 14/7 @ 3.6 gpm |
| Last Backwash Performed | Date: 9-27-21 | |

### H. ELECTRICAL AND INSTRUMENTATION

| Item | Status | Comments |
|---|---|---|
| "BIO" Backup Generator | ✓ | Block Heater: On OK / (Off Warm Out) |
| Electrical Surge Suppressor | ✓ | |
| Motor Control Center | ✓ | |
| PLC | ✓ | UPS @ 97 min / 95 Events |
| HMI's | ✓ | |
| BTS Process KWH Meter | 1816271 KWH | Time: 1154 |
| Building#2 KWH Meter | 5258252 KWH | Time: 1154 |

### I. GAS CHROMATOGRAPHY

| Item | Status | Comments |
|---|---|---|
| GC Operational | ✓ | GC # checking BIO: #3 |
| Alarms Enabled | ✓ | GC-Calibration + Maint 11-17-21 |
| GC Influent Filters | ✓ | |

# TABLE 3.19.2
# STANDARD OPERATIONS CHECKLIST
# BIOLOGICAL TREATMENT SYSTEM

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, November 18, 2021

**Inspection Performed by:** Mike Gelwick

## J. TOTALIZERS

| Item | Readings (gallons) | Comments |
|---|---|---|
| FT-3321 Feed to Reactor 1 | 6085028 | |
| FT-3324 Feed Spare | 107199 | |
| FT-3322 Feed to Reactor 2 | 10859536 | |
| FT-3323 Feed to Reactor 3 | 778819 | |
| FT-3301 T-510 to BIO | 51592049 | |
| FT-3341 BIO Effluent | 6643183S | |
| FT-3342 BIO Recycle | 55669829 | |

## K. SAFETY

| Item | Status | Comments |
|---|---|---|
| Building #2 Fire Extinguishers | ✓ | Inspection date: 10-25-21 |
| Building #2 Eye Wash/Shower | ✓ | Checked and Flushed- All OK: (Y) / N |

## L. OTHER COMMENTS:

| |
|---|
| |
| |
| |
| |

# ABLE 3.19.1
# STANDARD OPERATIONS CHECKLIST
# MAIN WTP

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Wednesday, November 24, 2021

**Inspection Performed by:** Mike Gelwick

## A. PERIMETER COLLECTION SYSTEMS

| Item | Status | Comments |
|---|---|---|
| LFG Cond Automatic Trap CT-1 | Sump Level: 12.55 ok | Counter: 190,345 Cycles: 372 |
| LFG Cond Automatic Trap CT-2 | Sump Level: 8.64 ok | Counter: 274,548 Cycles: 6 |
| LFG Cond Automatic Trap CT-3 | Sump Level: 7.23 ok | Counter: 312,237 Cycles: 854 |
| CT-4 Containment/Vessel (LFG Cond) | ✓ Level: 72 % | Tank Level: Counter: 191,255 Cycles: 0 Sump: 8.68 ok |
| PM-15 Containment / Vessel | ✓ Level: 25 % | |
| MW-51 Containment / Vessel | ✓ Level: 80 % | Guy Pumped later in day 11/24/21 |
| PM-11 Containment / Vessel | ✓ Level: 85 % | Guy pumped later in day 11/24/21 |
| MW-38 Systems | ✓ | Good, no leaks flow Rate @ 2.0 GPM |
| North Toe System | ✓ | MPE-10R @ 17,305,795 Sump Still off |
| North End Systems (Weekly) | ✓ | System good |
| Full N. End Systems Check (Monthly) | ✓ | Last Done: 11-22-21 |
| North End Pipeline(s)Flushing (As Needed) | ✓ | Perform if suspended solids present Last Done: 11/15/15 |
| NTES line flush to T-530 (As needed) | ✓ | Perform if suspended solids present Last Done: 10/29/21 |
| NTES Piping Containment | ✓ | Monthly Sump Level: Dry 216.07' Date: 11-18-21 |
| North Boundary System P-001: | CV 73.9 % @ 6.7 gpm | 40.91 Hz / 2.07 Amps. / vault psi @ 18 / no leaks |
| T-101 & T-102 Containment / Tank | ✓ | Levels: 24 % & 23 % |
| Raw Water Storage Tanks Piping | ✓ | |
| RWST Building Temp. (TT-101) | 54.0 °F | Outside Temp.: ~34.0 °F |
| (P-121) or P-122 | ✓ | 0.60 gpm / CV 60 % |
| RWST 2ndry Cont. High Level Switch | ✓ | (LSH-101) Last Test(monthly): 11-18-21 |
| RWST Back-Up Generator | ✓ | Last Test Run(monthly): 11-18-21 |

## B. CHEMICAL STORAGE BAYS

| Item | Status | Comments |
|---|---|---|
| Caustic Tote Levels | ✓ | ~ 450 Gallons Reserve = 3 totes |
| Caustic Bay Heater | ✓ | |
| Peroxide Tote Level | ✓ | ~ 275 Gallons Reserve = ~180 gal |
| HCL Tote Levels | ✓ | ~ 155 Gallons Reserve = ~70 gal |
| Chemical Totes and Piping Inspected | ✓ | Leaks observed: Y / (N) |
| Emergency Shower Inspected | ✓ | Checked and Flushed - All OK: (Y) / N |

## C. PRIMARY AND SECONDARY ACID FEED SYSTEM

| Item | Status | Comments |
|---|---|---|
| Primary Acid Feed Pump (P-631) | ✓ | |
| Ion Exchange Acid Feed Pump (P-632) | ✓ | PI-0632 PSI: 81-82 CV: 5 % |
| Primary Acid Retention Tank (T-510) | ✓ | |
| All Acid Feed Lines | ✓ | Leaks observed: Y / (N) |

## D. NBBW INJECTION TRENCH

| Item | Status | Comments |
|---|---|---|
| Injection Carbon (GAC-810) | **OFFLINE** | Date online: 7/20/18 |
| Injection Rate (FT-800) | 0.0 gpm | NBBW-IW-1= 0.0 NBBW-IW-2= 0.0 NBBW-IW-3= 0.0 gpm ea. |
| Totalizer Reading (FT-800) | 105,135,774 gal | INJ. STOPPED 10/02/18 @ 1545 |

# ABLE 3.19.1
# STANDARD OPERATIONS CHECKLIST
# MAIN WTP

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Wednesday, November 24, 2021

**Inspection Performed by:** Mike Gelwick

## E. CHEMICAL PRECIPITATION SYSTEM (US FILTER HMR-30)

| Item | Status | Comment |
|---|---|---|
| T-300A Mixer | NA | |
| T-300B (Caustic Mixer) | ✓ | Last Cleaning (Qtrly): 10-20-21 |
| T-300A/B Water Level | ✓ | |
| T-300B (Caustic Mix Chamber) | ✓ | Last Cleaning (Qtrly): 10-20-21 |
| T-300A/B Overflow | ✓ | |
| pH Set-point for (pH 315) | Value: 10.8 | |
| pH 310 | Value: 6.87 | |
| pH 315 | Value: 10.86 | |
| Flocculation Chamber Paddle Wheel | ✓ | |
| Precipitate Floc Quality | ✓ | Good |
| Clarifier Water Quality | ✓ | Good Oil or sheen observed: Y / (N) |
| Clarifier Effluent Piping / Water Level | ✓ | |
| Clear-well Chamber and Water Level | ✓ | |
| HMR PLC Panel | ✓ | |
| Caustic Pump (P-270) | SB | |
| Caustic Pump (P-280) | ✓ | |
| Polymer Pump (P-310) | ✓ | |
| Polymer Tank Mixer | ✓ | |
| Polymer Tank Level | Gallons: ~ 450 | |
| Clear-well Transfer Pumps (P-371) / 372) | ✓ | |
| Sludge Transfer Pump (P-330) | ✓ | Exercise Valves Weekly: Both ok |
| Manual Sludge Lateral pumping | ✓ | Last done (As Needed): #3-7-20-21 / #1 #2 - 3-20-21 |
| Manual Sludge Lateral Ball Valves | ✓ | Exercise Weekly: All ok |
| Automatic Blow-down Operations | ✓ | |

## F. pH PROBES

* new 4+10 pH stds today *

| pH Probe Location | Calibration Date | Comments: (Time done) |
|---|---|---|
| pH-310 HMR-30 (T-300A) | 11-24-21 - Today | 1150 |
| pH-315 HMR-30 (T-300B) | | |
| pH-365 Primary Acid Ret. Tank | | |
| pH-113 Pre-Ion Exchange | | |
| pH-670 Pre-UV-OX | | 1225 |
| pH-740 Discharge Surge Tank | | Discharge suspended: 1225 ↔ 1315 |
| Out of Hold Double Check | ---------- | None in hold: ✓✓ |
| Valves Back to Normal Position | ---------- | All OK: ✓✓ |

## G. SLUDGE THICKENER, SLUDGE HOLDING TANKS, FILTER PRESS

| Item | Status | Comments |
|---|---|---|
| Verify Sludge Thickener Running | ✓ | Gauge Reading: 0 % |
| Sludge Thick. Transfer Pump (P-350) | ✓ | |
| Sludge Holding Tank (T-351) | ✓ | Level:~ 65 % |
| Sludge Holding Tank (T-352) | ✓ | Level: 42 % |
| Decant Transfer Pump (P-352) | ✓ | CV 65 % @ 05 gpm |
| Filter Press Pumps (P-381 / P-382) | ✓ | |
| Filter Press | ✓ | Stage: Empty / Ready to fill |

# ABLE 3.19.1
# STANDARD OPERATIONS CHECKLIST
# MAIN WTP

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Wednesday, November 24, 2021

**Inspection Performed by:** Mike Gelwick

### H. ION EXCHANGE

| Item | Status | Comments |
|---|---|---|
| Feed Tank (T-113) | ✓ Level: 30 % | BACK RUNNING USING TANK level |
| Feed Pump (P-114) | ✓ Operating Press: 34.7 psi | CV@ 79 % @ 2.3 gpm |
| Retention Tank (T-114) | ✓ Operating Press: 32 psi | pH-113 @ 3.65 |
| Bag Filter (BF-113) | ✓ Operating Press: 37 psi | |
| Ion Exchange (Cage (1) or 2) + Guard | ✓ Operating Press: 33 psi | TP-173A-2 → TP-175A / 4 canisters + GAURD |
| Post Ion Exchange | ✓ Operating Press: 3.5 psi | |

### I. FEED SURGE TANK

| Item | Status | Comments |
|---|---|---|
| Feed Surge Tank (T-520) | ✓ Level: 39 % | Last Cleaning (As Needed, if 4" of solids accumulate): 12/15/19 |
| Feed Surge Pump (P-521 or P-522) | Operating Press: 30 psi | CV@ 82 % @ 34.4 gpm |
| T-520 to GAC Total (FT-675) | 252818471 gal | Time: 0913 |
| North End On-Site Pumping | Operating Press: 2-3 psi | 12.8 gpm @ 0908 |
| North End Off-Site Pumping | Operating Press: 2-6 psi | 8.8 gpm @ 0908 |
| Peroxide Feed Pump (P-680) | ✓ | SPD 2.6 % / RATE 0.7 |
| Peroxide Conc. At (TP-710) | 1.0 PPM | |
| Peroxide Conc. At (TP-740) | 0.0 PPM | |

### J. HAZARDOUS WASTE STORAGE

| Item | Status | Comments |
|---|---|---|
| 180 Day storage area check | ✓ | Check sheet completed: NA/Empty |
| Satellite Haz. Waste Areas (BLDG #1) | ✓ | Condition: IX Resin + main Good |
| Satellite Haz. Waste Area (BLDG #2) | ✓ | Condition: Good |

### K. UV-OXIDATION SYSTEM

| Item | Status | Comments |
|---|---|---|
| UV-Oxidation System | ✓ | |
| Annual Test Run (Calgon) | Date: 9-16-21 | Next: 9-2022 |
| Quarterly Test Run | Date: NA/Running | Next: NA/Running |
| Peroxide Feed Pump (P-650) | ✓ | Flow Rate: ~ 7.2 cc/min. |
| UV-Ox Power | ✓ | 25.7 kVA 2567 Volts 10.( Amps |
| Lamp Hours | 647 Hrs | |
| Crystal Condition & Wiper Status | ✓ | Oiler status: OK |
| UV-OX Bagfilters Status | Last change: 7-13-21 Cleaned: 7-13-21 | 13 psi In 13 psi Out |
| UV-OX Feed Pump ( P-600 or (P-601) ) | ✓ | CV@ 78 % @ 7.5 gpm |
| UV-OX Temperature | In(TT-670): 14.4 °C | Out(TT-710): 26.8 °C |
| PDU GAC (PDT-710) | ✓ | Δ Pressure: 5 psi |
| Peroxide Concentration Pre UV | 100 PPM | |
| Peroxide Concentration Post UV(TP-720) | 25 PPM | |
| Peroxide Conc. Post PDU (TP-730) | 0.0 PPM | |
| Secondary Acid Feed Pump (P-630) | ✓ | CV @ 3 % |
| Secondary Acid Retention Tank (T-645) | ✓ | |
| Pre – UV Oxidizer Total (FT-670) | 20422900 gal | Time: 0913 |
| Post UV-Ox / Pre PDU | ✓ | Pressure: 15 psi |
| Post PDU | ✓ | Pressure: 8 psi |

# ABLE 3.19.1
# STANDARD OPERATIONS CHECKLIST
# MAIN WTP

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Wednesday, November 24, 2021

**Inspection Performed by:** Mike Gelwick

### L. PDU AND LIQUID –PHASE GRANULAR ACTIVATED CARBON

| Item | Status | Comments |
|---|---|---|
| PDT-720 | ✓ | Δ Pressure: 18 psi |
| PDT-730 | ✓ | Δ Pressure: 7 psi |

### M. EFFLUENT DISCHARGE

| Item | Status | Comments |
|---|---|---|
| Effluent Surge Pump ((P751) or P752 ) | ✓ | CV@ 56.7 % |
| Effluent Surge Tank (T-740) | ✓ | Level: 40 % |
| Effluent Discharge Rate (FT-770) | ✓ | 34.6 gpm @ 0911 |
| POTW Line Pressure (PT-770) | ✓ | 32.4 psi |
| Effluent Totalizer Reading (FT-770) | 246956826 gal | Time: 0913 |
| POTW MH17S-078 Discharge Check (Monthly) | ✓ | Last Done: 11-8-21 |
| 4X8-Inch POTW Leak Detection Checks (Monthly) | ✓ | Last Done: |
| 4X8-Inch POTW Air Reliefs Checks (Monthly) | ✓ | Last Done: |
| 4X8-Inch POTW Isolation Valves Exercise (Qtrly) | ✓ | Last Done: |
| 2-Inch POTW Backup Pressure Testing (Annual) | ✓ | Last Done: 7/8/21 |
| 2-In POTW Backup Air Reliefs Checks (Annual) | ✓ | Last Done: 7/8/21 |
| 2-Inch POTW Isolation Valve Exercise (Annual) | ✓ | Last Done: 7/8/21 |
| Rotate Chiller Compressors | NA on Standby | ~~Now in Lead: 1 or 2~~ |

### N. LEL EFFLUENT TANK T-740

| Item | Status | Comments |
|---|---|---|
| LEL-740 Sensor | ✓ | Reading: 0 % |
| LEL Sensor Calibration / Automatic High LEL Shutdown Test (monthly) ✓ | Last Completed: 11-24-21-today | Plant Effluent Suspended: 1225 ↔ 1315 |
| LEL Sensor Bridge Adjustment to 2.0 volts | Reading: 2.001 volts(monthly) | Adjustment Needed: Y or (N) |
| Verify Bridge Current between.300v-.360v | Reading: 0.331 volts(monthly) | |

### O. WTP INFLUENT TOTALIZERS Time : 0914-0918

| Source | Reading(Gallons) | Source | Reading(Gallons) |
|---|---|---|---|
| (FT-015) RWST Influent | 19711820 | (FT-505) LFG Cond. to T-530 | 218946 |
| (FT-025) NBBW Influent | 94298898 | (FT-056) Off - Site N. End Influent | 43497220 |
| (FT-012) MW-38 Inf. to HMR-30 | 8350681 | (FT-113) Ion Exchange Influent | 906571 |
| (FT-042 HMR30) MW-38 Source to HMR-30 | 35484 | (FT-810) Plant Potable Water In | 30066756 |
| (FT-043) MW-38 to RWST | 3081586 | (FT-026) NBBW Bypass to RWST | 4418687 |
| (FT-042 RWST) MW-38 Source to RWST | 72236 | (FT-014) Misc. Water to RWST | 8187833 |
| (FT-012T) MW-38 to T-540/541 | 8628632 | (FT-035) NTES Inf. to BIO | 6681156 |
| (FT-040T) MW-38N to T-540/541 | 1978197 | (FT-035T) NTES to T-530 | 464723 |
| (FT-041T) MW-38S to T-540/541 | 2696237 | (FT-017) BIO Inf. from T-530 | 657439 |
| (FT-042T) MW-38 Source to T-540/541 | 4026207 | (FT-018) T-540/541 Influent | 8674823 |
| (FT-055) On - Site N. End Influent | 98672887 | (FT-352) T-352 to HMR-30 | 1305410 |

# ABLE 3.19.1
# STANDARD OPERATIONS CHECKLIST
# MAIN WTP

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Wednesday, November 24, 2021

**Inspection Performed by:** Mike Gelwick

### P. AIR COMPRESSORS * Still Running on Backups *

| Item | Status | Comments |
|---|---|---|
| Compressor Intake Temp. | 50 °F (Analog Gauge) | Outside Temp.: ~ 36 °F |
| Compressor Building Vent | ✓ | closed - opens wind |
| Primary Air Compressor (IRN30H) | 2,000 Hour service date: 7-8-21<br>Serviced @ 60952 Hours | Coolant present in sight glass: (Y) / N<br>Next service @ 62952 Hours<br>Current Hours @ — off |
| IRN30H Motor Speed | — % | |
| IRN30H Pressure | — psi | |
| IRN30H Moisture purge valve chk(Weekly): | — | |
| IRN30H Intake Filter | ✓ | Date Last Changed: 9-30-21 |
| Air Tanks Moisture Purge Valves | Manually Activate(weekly) ✓ | Excessive Moisture: Y / (N) |
| Backup Air Compressors (T-30 East and West) | Running | Both cool to touch: Y / (N) |
| Air Dryer | ✓ Econ on | Moisture at Receiver Tank: Y / (N) |
| Oil Moisture Prevention (Monthly) | Last Done: 9-23-21 | Run at max speed by bleeding air from filter canister above/after air dryer for 2 hrs |
| Air Receiver Tank | ✓ | 108 psi |

### Q. SUMPS

| Item | Status | Comments |
|---|---|---|
| Bag Filter Sump | ✓ | |
| Wet Well Sump | ✓ | |

### R. GAS CHROMATOGRAPH

| Item | Status | Comments |
|---|---|---|
| GC Operational | ✓ | GC # checking UV-Ox Effluent: # 2 |
| Alarms Enabled | ✓ | CC - calibration & maint 11-24-21 - today |
| GC Influent Filters | ✓ | |

### S. SAFETY

| Item | Status | Comments |
|---|---|---|
| Building #1 Fire Extinguishers | ✓ | Date inspected: 11-22-21 |
| Building #1 Eye Wash/Shower | ✓ | Checked and Flushed- All OK: (Y) / N |

**Other Comments:**

| |
|---|
| |
| |
| |
| |
| |

# TABLE 3.19.2
# STANDARD OPERATIONS CHECKLIST
# BIOLOGICAL TREATMENT SYSTEM

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Wednesday, November 24, 2021

**Inspection Performed by:** Mike Gelwick

## A. PUMPS

| Item | Status | Flow Rate (gpm) | Pump Speed (CV%) | Discharge Pressure (psi) | Comments |
|---|---|---|---|---|---|
| **T-510 Pumps** | | | | | |
| P-3301 | ✓ | 1.86 | 34.1 % | 6.5 | |
| P-3301A | SB | – | – % | – | |
| **NTES Pump** P-002(Sump) / (P-002W(10R)) | ✓ | 0.52 | 48 % | P035 34-35 / P038 6 | Globules Observed at TP-130: Y / (N) Time: 0845 |
| **T-530** P-005 | ✓ | 0.18 | 41 % | 7.0 | |
| **T-540/541** P-006 | ✓ | 0.32 | 73 % | 7.0 | |
| **LFG COND Auto-Traps** | ✓ | 0.0 | NA | 5 | Between Cycles: (Y) / N |
| **Reactor Feed Pumps** | | | | | |
| P-3321 | ✓ | 2.66 | 43.8 % | 5.5 | |
| P-3322 | ✓ | 3.65 | 45.4 % | 5.0 | |
| P-3323 | ✓ | 2.66 | 62.9 % | 4.5 | |
| P-3324 | SB | – | – % | – | |
| **Reactor Effluent Pumps** | | | | | |
| P-3341 | ✓ | 4.51 | 66.8 % | 22.0 | |
| P-3341A | SB | – | – % | – | |

## B. BLOWERS

| Item | Status | Pressure (psi) | Temp (°F) | Next Scheduled Service (Qtrly) | Comments Last serviced on: 10-1-21 |
|---|---|---|---|---|---|
| B-3331 | ✓ | 4.35 | 125 | 12-2021 | Greased, Belt and Filter Checked: (Y) / N |
| B-3332 | SB | – | – | ↓ | Belt and Filter Checked: Y / (N) |
| B-3333 | ✓ | 4.41 | 125 | ↓ | Greased, Belt and Filter Checked: (Y) / N |
| B-3334 | ✓ | 4.34 | 122 | ↓ | Greased, Belt and Filter Checked: (Y) / N |

## C. REACTOR VENTILATION

| Item | Status | Comments |
|---|---|---|
| Vapor Carbon Contactor | ✓ | On-line: 2/10/18 |
| Reactor Vent Blower | ✓ | |
| Reactor Vent Booster | ✓ | |
| VTP-3350 | ✓ | PID Reading: 22.6 PPM |
| VTP-3360 | ✓ | PID Reading: 19.2 PPM |

# TABLE 3.19.2
# STANDARD OPERATIONS CHECKLIST
# BIOLOGICAL TREATMENT SYSTEM

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Wednesday, November 24, 2021

**Inspection Performed by:** Mike Gelwick

## D. TANKS / REACTORS / SUMPS / CONTAINMENTS / PIPING / Chiller

| Item | Status | Comments |
|---|---|---|
| T-510 Post HMR-30 Mixing Tank | ✓ Level: 64 % | Last Cleaning (As needed, if 2" of solids accumulate): 7/14/21 |
| T-530 LFG Condensate / NTES Tank | ✓ Level: 34 % | |
| T-530 Mixer | ✓ | |
| LFG Condensate Conveyance Line | ✓ | Last Pressure Test: 7-19-21 Next: 7-2022 (Annual at a minimum or if flow drops off) |
| T-540/541 MW38 Tanks | Lvls: 40 % & 41 % | |
| T-540/541 Mixers | ✓ | T-541 shrouds replace |
| Chiller | ✓ | Chiller Coolant Lvl: ~ — " Below full mark |
| Chiller Cooling Fins (as needed) | ✓ | Last Cleaning: 4/20/18 (unit on Standby) |
| Secondary Containments | ✓ | Heat Trace: (On OK) / Off Warm out |
| Feed Piping to Sedimentation Tank | ✓ | Last Back Flushing (Quarterly): 11-12-21 |
| T-3310 Sedimentation Tank | Visual Level: ok | Last Cleaning (As Needed, use TSS info to determine): 9/2021 |
| T-3320 Blend Tank | ✓ Level: 71 % | Last Cleaning (Semi Annual): 9-10-21 |
| T-3331 Reactor No. 1 | ✓ | Digital Displays: (GOOD) / Needs Attn |
| T-3332 Reactor No. 2 | ✓ | Digital Displays: (GOOD) / Needs Attn |
| T-3333 Reactor No. 3 | ✓ | Digital Displays: (GOOD) / Needs Attn |
| T-3334 Settling Tank | ✓ | Last Cleaning (Semi Annual): 9-10-21 |
| P-3334 Biosolids Pump | ✓ | |
| T-3340 Overflow Tank | ✓ Level: 31 % | |
| Recycle Valve to Blend Tank | ✓ | 4.01 gpm @ 0936 |
| Building Containment Sump | ✓ | Last Alarm Test Date (Monthly): 11-18-21 |

## E. CHEMICAL FEED SYSTEM

| Item | Status | Comments |
|---|---|---|
| Phosphorous Supply | ✓ | Bags: 15.5 Gallons: ~ 70 |
| Phosphorous Pump (P-2221) | ✓ | |
| Caustic Supply | ✓ | ~ 280 Gallons |
| Caustic Pump (P-2211) | SB | Currently in acid addition mode |
| Acid Supply | ✓ | ~ 40 Gallons |
| Acid Pump (P-2211) | ✓ | |
| Caustic Pump (P-2231) | ✓ Leaks: Y / (N) | Last tubing tip cleaning (monthly): 11-18-21 |
| Caustic Pump (P-2232) | ✓ Leaks: Y / (N) | Last tubing tip cleaning (monthly): |
| Caustic Pump (P-2233) | ✓ Leaks: Y / (N) | Last tubing tip cleaning (monthly): ↓ |

# TABLE 3.19.2
# STANDARD OPERATIONS CHECKLIST
# BIOLOGICAL TREATMENT SYSTEM

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Wednesday, November 24, 2021

**Inspection Performed by:** Mike Gelwick

## F. pH Probes

| pH Probe Location | Calibration Date (Monthly) | Comments |
|---|---|---|
| pH-3320 Blend Tank | 11-24-21 - today | New 4 & 10 pH STDs today |
| pH-3331 Reactor 1 | ↓ | ↓ |
| pH-3332 Reactor 2 | | |
| pH-3333 Reactor 3 | | |

## G. FILTER SYSTEM

| Item | Status | Comments |
|---|---|---|
| BF-3340 a/b Status | ✓ | |
| Automatic Backwash | Cycle Count: 33 | reset |
| BF-3340 a/b Differential Pressure | PSI: 4 | 18/14 @ 3.5 gpm |
| 75-micron Bags Last Cleaning | Date: 11-14-19 | |
| 75-micron Bags Last Inspection | Date: ↓ | |
| 75-micron Bags Last Changed | Date: | |
| GACF-3340 Status | ✓ | |
| GACF-3340 Differential Pressure | PSI: 7 | 14/7 @ 3.5 gpm |
| Last Backwash Performed | Date: 9-27-21 | |

## H. ELECTRICAL AND INSTRUMENTATION

| Item | Status | Comments |
|---|---|---|
| "BIO" Backup Generator | ✓ | Block Heater: (On OK) / Off Warm Out |
| Electrical Surge Suppressor | ✓ | |
| Motor Control Center | ✓ | |
| PLC | ✓ | UPS @ 97 min / 95 Events |
| HMI's | ✓ | |
| BTS Process KWH Meter | 1818421 KWH | Time: 1028 |
| Building#2 KWH Meter | 5262785 KWH | Time: 1028 |

## I. GAS CHROMATOGRAPHY

| Item | Status | Comments |
|---|---|---|
| GC Operational | ✓ | GC # checking BIO: #3 |
| Alarms Enabled | ✓ | CC - calibration + maint 11-24-21 - today |
| GC Influent Filters | ✓ | |

# TABLE 3.19.2
# STANDARD OPERATIONS CHECKLIST
# BIOLOGICAL TREATMENT SYSTEM

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Wednesday, November 24, 2021

**Inspection Performed by:** Mike Gelwick

## J. TOTALIZERS

| Item | Readings (gallons) | Comments |
|---|---|---|
| FT-3321 Feed to Reactor 1 | 6103939 | |
| FT-3324 Feed Spare | 120021 | |
| FT-3322 Feed to Reactor 2 | 10885806 | |
| FT-3323 Feed to Reactor 3 | 784743 | |
| FT-3301 T-510 to BIO | 51609950 | |
| FT-3341 BIO Effluent | 66456582 | |
| FT-3342 BIO Recycle | 55704881 | |

## K. SAFETY

| Item | Status | Comments |
|---|---|---|
| Building #2 Fire Extinguishers | ✓ | Inspection date: 11-22-21 |
| Building #2 Eye Wash/Shower | ✓ | Checked and Flushed- All OK: Ⓨ / N |

## L. OTHER COMMENTS:

| |
|---|
| |
| |
| |
| |

# ABLE 3.19.1
# STANDARD OPERATIONS CHECKLIST
# MAIN WTP

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, December 02, 2021

**Inspection Performed by:** Mike Gelwick / Tom Gilbert

## A. PERIMETER COLLECTION SYSTEMS

| Item | Status | Comments |
|---|---|---|
| LFG Cond Automatic Trap CT-1 | Sump Level: 12.48 ok | Counter: 190,869 Cycles: 524 |
| LFG Cond Automatic Trap CT-2 | Sump Level: 8.70 ok | Counter: 274,548 Cycles: 0 |
| LFG Cond Automatic Trap CT-3 | Sump Level: 7.22 ok | Counter: 314,021 Cycles: 1784 |
| CT-4 Containment/Vessel (LFG Cond) | Level: 72 % | Tank Level: 2.13 Counter: 191,255 Cycles: 0 Sump: 8.40 ok |
| PM-15 Containment / Vessel | Level: 28 % | |
| MW-51 Containment / Vessel | Level: 78 % | |
| PM-11 Containment / Vessel | Level: 75 % | |
| MW-38 Systems | ✓ | |
| North Toe System | ✓ | |
| North End Systems (Weekly) | ✓ | |
| Full N. End Systems Check (Monthly) | ✓ | Last Done: 11-22-21 |
| North End Pipeline(s)Flushing (As Needed) | ✓ | Perform if suspended solids present Last Done: 11/15/15 |
| NTES line flush to T-530 (As needed) | ✓ | Perform if suspended solids present Last Done: 10/29/21 |
| NTES Piping Containment | ✓ | Monthly Sump Level: dry @ 16.07' Date: 11-18-21 |
| North Boundary System P-001: | CV 73.8% @ 6.7 gpm | 40.88 Hz / 2.07 Amps. / vault psi @ 18/no leaks |
| T-101 & T-102 Containment / Tank | ✓ | Levels: 29 % & 29 % |
| Raw Water Storage Tanks Piping | ✓ | |
| RWST Building Temp. (TT-101) | 55.6 °F | Outside Temp.: ~ 47 °F |
| (P-121) or P-122 | ✓ | 0.0 gpm / CV 56 % |
| RWST 2ndry Cont. High Level Switch | ✓ | (LSH-101) Last Test(monthly): 11-18-21 |
| RWST Back-Up Generator | ✓ | Last Test Run(monthly): 11-18-21 |

## B. CHEMICAL STORAGE BAYS

| Item | Status | Comments |
|---|---|---|
| Caustic Tote Levels | ✓ | ~ 515 Gallons Reserve = 2 totes |
| Caustic Bay Heater | ✓ | |
| Peroxide Tote Level | ✓ | ~ 255 Gallons Reserve = ~180 gallons |
| HCL Tote Levels | ✓ | ~ 115 Gallons Reserve = ~ 70 gallons |
| Chemical Totes and Piping Inspected | ✓ | Leaks observed: Y / (N) |
| Emergency Shower Inspected | ✓ | Checked and Flushed - All OK: (Y) / N |

## C. PRIMARY AND SECONDARY ACID FEED SYSTEM

| Item | Status | Comments |
|---|---|---|
| Primary Acid Feed Pump (P-631) | ✓ | |
| Ion Exchange Acid Feed Pump (P-632) | ✓ | PI-0632 PSI: 81-84 CV: 4 % |
| Primary Acid Retention Tank (T-510) | ✓ | |
| All Acid Feed Lines | ✓ | Leaks observed: Y / (N) |

## D. NBBW INJECTION TRENCH

| Item | Status | Comments |
|---|---|---|
| Injection Carbon (GAC-810) | OFFLINE | Date online: 7/20/18 |
| Injection Rate (FT-800) | 0.0 gpm | NBBW-IW-1= 0.0 NBBW-IW-2= 0.0 NBBW-IW-3= 0.0 gpm ea. |
| Totalizer Reading (FT-800) | 105,135,774 gal | INJ. STOPPED 10/02/18 @ 1545 |

# ABLE 3.19.1
# STANDARD OPERATIONS CHECKLIST
# MAIN WTP

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, December 02, 2021

**Inspection Performed by:** Mike Gelwick / Tom Gilbert

### E. CHEMICAL PRECIPITATION SYSTEM (US FILTER HMR-30)

| Item | Status | Comment |
|---|---|---|
| T-300A Mixer | NA | |
| T-300B (Caustic Mixer) | ✓ | Last Cleaning (Qtrly): 10-20-21 |
| T-300A/B Water Level | ✓ | |
| T-300B (Caustic Mix Chamber) | ✓ | Last Cleaning (Qtrly): 10-20-21 |
| T-300A/B Overflow | ✓ | |
| pH Set-point for (pH 315) | Value: 10.8 | |
| pH 310 | Value: 7.04 | |
| pH 315 | Value: 10.90 | |
| Flocculation Chamber Paddle Wheel | ✓ | good |
| Precipitate Floc Quality | ✓ | good |
| Clarifier Water Quality | ✓ | good Oil or sheen observed: Y / (N) |
| Clarifier Effluent Piping / Water Level | ✓ | |
| Clear-well Chamber and Water Level | ✓ | |
| HMR PLC Panel | ✓ | |
| Caustic Pump (P-270) | SB | |
| Caustic Pump (P-280) | ✓ | |
| Polymer Pump (P-310) | ✓ | |
| Polymer Tank Mixer | ✓ | |
| Polymer Tank Level | Gallons: ~ 375 | |
| Clear-well Transfer Pumps (P-371 / 372) | ✓ | |
| Sludge Transfer Pump (P-330) | ✓ | Exercise Valves Weekly: Both OK |
| Manual Sludge Lateral pumping | ✓ | Last done (As Needed): #3 - 7-20-21 #2 3-20-21 #1 3-20-21 |
| Manual Sludge Lateral Ball Valves | ✓ | Exercise Weekly: All OK ✓ |
| Automatic Blow-down Operations | ✓ | |

### F. pH PROBES

| pH Probe Location | Calibration Date | Comments: (Time done) |
|---|---|---|
| pH-310 HMR-30 (T-300A) | 12-2-21 - Today | 1420 |
| pH-315 HMR-30 (T-300B) | | |
| pH-365 Primary Acid Ret. Tank | | |
| pH-113 Pre-Ion Exchange | | |
| pH-670 Pre-UV-OX | | 1500 |
| pH-740 Discharge Surge Tank | | Discharge suspended: 1410 ↔ 1420 |
| Out of Hold Double Check | ---------- | None in hold: ✓✓ m |
| Valves Back to Normal Position | ---------- | All OK: ✓✓ m |

### G. SLUDGE THICKENER, SLUDGE HOLDING TANKS, FILTER PRESS

| Item | Status | Comments |
|---|---|---|
| Verify Sludge Thickener Running | ✓ | Gauge Reading: 0 % |
| Sludge Thick. Transfer Pump (P-350) | ✓ | |
| Sludge Holding Tank (T-351) | ✓ | Level:~ 65 % |
| Sludge Holding Tank (T-352) | ✓ | Level: 40 % |
| Decant Transfer Pump (P-352) | ✓ | CV 63 % @ 0.5 gpm |
| Filter Press Pumps (P-381 / P-382) | ✓ | |
| Filter Press | ✓ | Stage: Empty - Ready to Fill |

# ABLE 3.19.1
# STANDARD OPERATIONS CHECKLIST
# MAIN WTP

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, December 02, 2021

**Inspection Performed by:** Mike Gelwick / Tom Gilbert

### H. ION EXCHANGE

| Item | Status | Comments |
|---|---|---|
| Feed Tank (T-113) | ✓ Level: 30 % | |
| Feed Pump (P-114) | ✓ Operating Press: 31.7 psi | CV@ 78 % @ 2.2 gpm |
| Retention Tank (T-114) | ✓ Operating Press: 31 psi | pH-113 @ 3.73 |
| Bag Filter (BF-113) | ✓ Operating Press: 34 psi | |
| Ion Exchange (Cage (1) or 2) + Guard | ✓ Operating Press: 30 psi | TP173-A-2 → TP175A 4 canisters |
| Post Ion Exchange | ✓ Operating Press: 3.5 psi | |

### I. FEED SURGE TANK

| Item | Status | Comments |
|---|---|---|
| Feed Surge Tank (T-520) | Level: 38 % | Last Cleaning (As Needed, if 4" of solids accumulate): 12/15/19 |
| Feed Surge Pump (P-521 or P-522) | Operating Press: 31 psi | CV@ 83 % @ 33.1 gpm |
| T-520 to GAC Total (FT-675) | 253197624 gal | Time: 1009 |
| North End On-Site Pumping | Operating Press: 2-3 psi | 12.7 gpm @ 9:50 AM |
| North End Off-Site Pumping | Operating Press: 2-6 psi | 8.5 gpm @ 0950 |
| Peroxide Feed Pump (P-680) | ✓ | SPD 2.5 % / RATE 0.7 GPM |
| Peroxide Conc. At (TP-710) | 0.0 PPM | Pump was off - OK Now |
| Peroxide Conc. At (TP-740) | 0.0 PPM | |

### J. HAZARDOUS WASTE STORAGE

| Item | Status | Comments |
|---|---|---|
| 180 Day storage area check | ✓ | Check sheet completed: N/A - Empty |
| Satellite Haz. Waste Areas (BLDG #1) | ✓ | Condition: Ix Resin + Main good |
| Satellite Haz. Waste Area (BLDG #2) | ✓ | Condition: Good |

### K. UV-OXIDATION SYSTEM

| Item | Status | Comments |
|---|---|---|
| UV-Oxidation System | | |
| Annual Test Run (Calgon) | Date: 9-16-21 | Next: 9-2022 |
| Quarterly Test Run | Date: N/A - running | Next: N/A - Running |
| Peroxide Feed Pump (P-650) | ✓ | Flow Rate: ~7.2 cc/min. |
| UV-Ox Power | ✓ | 25.7-9 kVA 2592 Volts 10.0 Amps |
| Lamp Hours | 839 Hrs | |
| Crystal Condition & Wiper Status | ✓ | Oiler status: OK ✓ |
| UV-OX Bagfilters Status | Last change: 7-13-21 Cleaned: 7-13-21 | 10 psi In 10.5 psi Out |
| UV-OX Feed Pump ( P-600 or P-601 ) | | CV@ 68 % @ 7.4 gpm |
| UV-OX Temperature | In(TT-670): 14.0 °C | Out(TT-710): 26.6 °C |
| PDU GAC (PDT-710) | ✓ | Δ Pressure: 2 psi |
| Peroxide Concentration Pre UV | 100 PPM | |
| Peroxide Concentration Post UV(TP-720) | 25 PPM | |
| Peroxide Conc. Post PDU (TP-730) | 0.0 PPM | |
| Secondary Acid Feed Pump (P-630) | ✓ | CV @ 2 % |
| Secondary Acid Retention Tank (T-645) | ✓ | |
| Pre – UV Oxidizer Total (FT-670) | 20505838 gal | Time: 1010 |
| Post UV-Ox / Pre PDU | ✓ | Pressure: 13 psi |
| Post PDU | ✓ | Pressure: 7.5 psi |

# ABLE 3.19.1
# STANDARD OPERATIONS CHECKLIST
# MAIN WTP

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, December 02, 2021

**Inspection Performed by:** Mike Gelwick / Tom Gilbert

### L. PDU AND LIQUID –PHASE GRANULAR ACTIVATED CARBON

| Item | Status | Comments |
|---|---|---|
| PDT-720 | ✓ | Δ Pressure: 19 psi |
| PDT-730 | ✓ | Δ Pressure: 7 psi |

### M. EFFLUENT DISCHARGE

| Item | Status | Comments |
|---|---|---|
| Effluent Surge Pump ((P751) or P752 ) | ✓ | CV@ 55.5 % |
| Effluent Surge Tank (T-740) | ✓ | Level: 40 % |
| Effluent Discharge Rate (FT-770) | ✓ | 32.2 gpm @ 1000 |
| POTW Line Pressure (PT-770) | ✓ | 32.1 psi |
| Effluent Totalizer Reading (FT-770) | ~~TG 50100~~ 247338008 ↑ gal | Time: ~~10005~~ 1011 |
| POTW MH17S-078 Discharge Check (Monthly) | ✓ | Last Done: 11-8-21 |
| 4X8-Inch POTW Leak Detection Checks (Monthly) | ✓ | Last Done: |
| 4X8-Inch POTW Air Reliefs Checks (Monthly) | ✓ | Last Done: |
| 4X8-Inch POTW Isolation Valves Exercise (Qtrly) | ✓ | Last Done: |
| 2-Inch POTW Backup Pressure Testing (Annual) | ✓ | Last Done: 7/8/21 |
| 2-In POTW Backup Air Reliefs Checks (Annual) | ✓ | Last Done: 7/8/21 |
| 2-Inch POTW Isolation Valve Exercise (Annual) | ✓ | Last Done: 7/8/21 |
| Rotate Chiller Compressors | NA on Standby | ~~Now in Lead: 1 or 2~~ |

### N. LEL EFFLUENT TANK T-740

| Item | Status | Comments |
|---|---|---|
| LEL-740 Sensor | ✓ | Reading: 0 % |
| LEL Sensor Calibration / Automatic High LEL Shutdown Test (monthly) | Last Completed: 11-24-21 | Plant Effluent Suspended: 1225 ↔ 1315 |
| LEL Sensor Bridge Adjustment to 2.0 volts | Reading: 2.001 volts(monthly) | Adjustment Needed: Y or (N) |
| Verify Bridge Current between.300v-.360v | Reading: 0.331 volts(monthly) | |

### O. WTP INFLUENT TOTALIZERS Time : 1011 - 1018

| Source | Reading(Gallons) | Source | Reading(Gallons) |
|---|---|---|---|
| (FT-015) RWST Influent | 19724515 | (FT-505) LFG Cond. to T-530 | 219108 |
| (FT-025) NBBW Influent | 94374447 | (FT-056) Off - Site N. End Influent | 43595024 |
| (FT-012) MW-38 Inf. to HMR-30 | 8366305 | (FT-113) Ion Exchange Influent | 932375 |
| (FT-042 HMR30) MW-38 Source to HMR-30 | 35484 | (FT-810) Plant Potable Water In | 30067502 |
| (FT-043) MW-38 to RWST | 3033542 | (FT-026) NBBW Bypass to RWST | 4420534 |
| (FT-042 RWST) MW-38 Source to RWST | 72236 | (FT-014) Misc. Water to RWST | 1888 71 |
| (FT-012T) MW-38 to T-540/541 | 8637998 | (FT-035) NTES Inf. to BIO | 6686800 |
| (FT-040T) MW-38N to T-540/541 | 1978498 | (FT-035T) NTES to T-530 | 464931 |
| (FT-041T) MW-38S to T-540/541 | 2696658 | (FT-017) BIO Inf. from T-530 | 658049 |
| (FT-042T) MW-38 Source to T-540/541 | 1034839 | (FT-018) T-540/541 Influent | 86780 44 |
| (FT-055) On - Site N. End Influent | 98819767 | (FT-352) T-352 to HMR-30 | 1308209 |

# ABLE 3.19.1
# STANDARD OPERATIONS CHECKLIST
# MAIN WTP

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, December 02, 2021

**Inspection Performed by:** Mike Gelwick / Tom Gilbert

### P. AIR COMPRESSORS * Still Running on backups

| Item | Status | Comments |
|---|---|---|
| Compressor Intake Temp. | 58 °F (Analog Gauge) | Outside Temp.: ~ 62 °F |
| Compressor Building Vent | ✓ | ~~Closed~~ OPEN - function good |
| Primary Air Compressor (IRN30H) | 2,000 Hour service date: 7-8-21<br>Serviced @ 60952 Hours | Coolant present in sight glass: (Y) / N<br>Next service @ 62952 Hours<br>Current Hours @ -OFF |
| IRN30H Motor Speed | — % | |
| IRN30H Pressure | — psi | |
| IRN30H Moisture purge valve chk(Weekly): | — | |
| IRN30H Intake Filter | ✓ | Date Last Changed: 9-30-21 |
| Air Tanks Moisture Purge Valves | Manually Activate(weekly) ✓ | Excessive Moisture: Y / (N) |
| Backup Air Compressors (T-30 East and West) | Running | Both cool to touch: Y / (N) |
| Air Dryer | ✓ ECO ON | Moisture at Receiver Tank: Y / (N) |
| Oil Moisture Prevention (Monthly) | Last Done: 9-23-21 | Run at max speed by bleeding air from filter canister above/after air dryer for 2 hrs |
| Air Receiver Tank | ✓ | 110 psi ~~110~~ TG |

### Q. SUMPS

| Item | Status | Comments |
|---|---|---|
| Bag Filter Sump | ✓ | |
| Wet Well Sump | ✓ | |

### R. GAS CHROMATOGRAPH

| Item | Status | Comments |
|---|---|---|
| GC Operational | ✓ | GC # checking UV-Ox Effluent: #2 |
| Alarms Enabled | ✓ | CC - calibration + maintnme 12-1-21 |
| GC Influent Filters | ✓ | |

### S. SAFETY

| Item | Status | Comments |
|---|---|---|
| Building #1 Fire Extinguishers | ✓ | Date inspected: 11-22-21 |
| Building #1 Eye Wash/Shower | ✓ | Checked and Flushed- All OK: (Y) / N |

**Other Comments:**

# TABLE 3.19.2
# STANDARD OPERATIONS CHECKLIST
# BIOLOGICAL TREATMENT SYSTEM

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, December 02, 2021

**Inspection Performed by:** Mike Gelwick / Tom Gilbert

## A. PUMPS

| Item | Status | Flow Rate (gpm) | Pump Speed (CV%) | Discharge Pressure (psi) | Comments |
|---|---|---|---|---|---|
| **T-510 Pumps** | | | | | |
| P-3301 | ✓ | 3.11 | 48.3 % | 11 | |
| P-3301A | SB | — | — % | — | |
| **NTES Pump** P-002(Sump) (P-002W(10R)) | ✓ | 0.49 | 49 % | P035 34-35 / P038 6.5 | Globules Observed at TP-130: Y / (N) Time: 8:50 AM |
| **T-530** P-005 | ✓ | 0.19 | 41 % | 7 | |
| **T-540/541** P-006 | ✓ | 0.30 | 57 % | 7 PSI | |
| **LFG COND Auto-Traps** | ✓ | 0 | NA | 5 PSI | Between Cycles: (Y) / N |
| **Reactor Feed Pumps** | | | | | |
| P-3321 | ✓ | 2.58 | 51.9 % | 7 | |
| P-3322 | ✓ | 3.59 | 57.4 % | 6.5 | |
| P-3323 | ✓ | 2.55 | 77.7 % | 5.5 | |
| P-3324 | SB ✓ | ~~0.01~~ 16 | ~~44~~ 16 % | — | |
| **Reactor Effluent Pumps** | | | | | |
| P-3341 | ✓ | 2.67 | 56.9 % | 17 | |
| P-3341A | SB | — | — % | — | |

## B. BLOWERS

| Item | Status | Pressure (psi) | Temp (°F) | Next Scheduled Service (Qtrly) | Comments |
|---|---|---|---|---|---|
| B-3331 | ✓ | 4.29 | 138 | 12-2021 | Last serviced on: 10-1-21 Greased, Belt and Filter Checked: (Y) / N |
| B-3332 | SB | ~~0.0~~ | — | ↓ | Belt and Filter Checked: (X) / (N) |
| B-3333 | ✓ | 4.40 | 140 | ↓ | Greased, Belt and Filter Checked: (Y) / N |
| B-3334 | ✓ | 4.34 | 138 | ↓ | Greased, Belt and Filter Checked: (Y) / N |

## C. REACTOR VENTILATION

| Item | Status | Comments |
|---|---|---|
| Vapor Carbon Contactor | ✓ | On-line: 2/10/18 |
| Reactor Vent Blower | ✓ | |
| Reactor Vent Booster | ✓ | |
| VTP-3350 | ✓ | PID Reading: 30.6 PPM |
| VTP-3360 | ✓ | PID Reading: 6.5 PPM |

# TABLE 3.19.2
# STANDARD OPERATIONS CHECKLIST
# BIOLOGICAL TREATMENT SYSTEM

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, December 02, 2021

**Inspection Performed by:** Mike Gelwick / Tom Gilbert

## D. TANKS / REACTORS / SUMPS / CONTAINMENTS / PIPING / Chiller

| Item | Status | Comments |
|---|---|---|
| T-510 Post HMR-30 Mixing Tank | ✓ Level: 67 % | Last Cleaning (As needed, if 2" of solids accumulate): 7/14/21 |
| T-530 LFG Condensate / NTES Tank | ✓ Level: 28 % | |
| T-530 Mixer | ✓ | |
| LFG Condensate Conveyance Line | ✓ | Last Pressure Test: 7-14-21 Next: 7-2022 (Annual at a minimum or if flow drops off) |
| T-540/541 MW38 Tanks | Lvls: 82 % & 83% | |
| T-540/541 Mixers | both off/ bad | popping breakers T-541 Needs to be replaced and T-540 |
| Chiller | ✓ | Chiller Coolant Lvl: ~ — " Below full mark |
| Chiller Cooling Fins (as needed) | ✓ | Last Cleaning: 4/20/18 (unit on Standby) |
| Secondary Containments | ✓ | Heat Trace: On OK / (Off Warm out) |
| Feed Piping to Sedimentation Tank | ✓ | Last Back Flushing (Quarterly): 11-12-21 |
| T-3310 Sedimentation Tank | Visual Level: OK | Last Cleaning (As Needed, use TSS info to determine): 9/2021 |
| T-3320 Blend Tank | ✓ Level: 70 % | Last Cleaning (Semi Annual): 9-10-21 |
| T-3331 Reactor No. 1 | ✓ | Digital Displays: (GOOD) / Needs Attn |
| T-3332 Reactor No. 2 | ✓ | Digital Displays: (GOOD) / Needs Attn |
| T-3333 Reactor No. 3 | ✓ | Digital Displays: (GOOD) / Needs Attn |
| T-3334 Settling Tank | ✓ | Last Cleaning (Semi Annual): 9-10-21 |
| P-3334 Biosolids Pump | ✓ | |
| T-3340 Overflow Tank | ✓ Level: 28 % | |
| Recycle Valve to Blend Tank | ✓ | 4.20 gpm @ 1137 |
| Building Containment Sump | ✓ | Last Alarm Test Date (Monthly): 11-18-21 |

## E. CHEMICAL FEED SYSTEM

| Item | Status | Comments |
|---|---|---|
| Phosphorous Supply | ✓ | Bags: 15.25 Gallons: ~ 70 |
| Phosphorous Pump (P-2221) | ✓ | |
| Caustic Supply | ✓ | ~ 270 Gallons |
| Caustic Pump (P-2211) | SB | Currently in acid addition mode |
| Acid Supply | ✓ | ~ 40 Gallons |
| Acid Pump (P-2211) | ✓ | |
| Caustic Pump (P-2231) | ✓ Leaks: Y / (N) | Last tubing tip cleaning (monthly): 11-18-21 |
| Caustic Pump (P-2232) | ✓ Leaks: Y / (N) | Last tubing tip cleaning (monthly): 11-18-21 |
| Caustic Pump (P-2233) | ✓ Leaks: Y / (N) | Last tubing tip cleaning (monthly): 11-18-21 |

# TABLE 3.19.2
# STANDARD OPERATIONS CHECKLIST
# BIOLOGICAL TREATMENT SYSTEM

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, December 02, 2021

**Inspection Performed by:** Mike Gelwick / Tom Gilbert

## F. pH Probes

| pH Probe Location | Calibration Date (Monthly) | Comments |
|---|---|---|
| pH-3320 Blend Tank | 11-24-21 | Spray off clean today |
| pH-3331 Reactor 1 | ↓ | ↓ |
| pH-3332 Reactor 2 | | |
| pH-3333 Reactor 3 | | |

## G. FILTER SYSTEM

| Item | Status | Comments |
|---|---|---|
| BF-3340 a/b Status | ✓ | |
| Automatic Backwash | Cycle Count: 41 | Reset to 0 |
| BF-3340 a/b Differential Pressure | PSI: 1 | 11/12 @ 3.5 GPM |
| 75-micron Bags Last Cleaning | Date: ~~11-14-21~~ ~~11-14-21~~ 11-14-21 | |
| 75-micron Bags Last Inspection | Date: ↓ ~~11-14-21~~ TG | |
| 75-micron Bags Last Changed | Date: ~~11-14-21~~ | |
| GACF-3340 Status | ✓ | |
| GACF-3340 Differential Pressure | PSI: 2 | ~~TB 11-14-21~~ 6/8 @ 1.9 GPM |
| Last Backwash Performed | Date: 9-27-21 | |

## H. ELECTRICAL AND INSTRUMENTATION

| Item | Status | Comments |
|---|---|---|
| "BIO" Backup Generator | ✓ | Block Heater: On OK / (Off Warm Out) |
| Electrical Surge Suppressor | ✓ | |
| Motor Control Center | ✓ | |
| PLC | ✓ | UPS @ 97 min / 45 Events |
| HMI's | ✓ | |
| BTS Process KWH Meter | 01821302 KWH | Time: 1215 |
| Building#2 KWH Meter | 05268706 KWH | Time: 1215 |

## I. GAS CHROMATOGRAPHY

| Item | Status | Comments |
|---|---|---|
| GC Operational | ✓ | GC # checking BIO: #3 |
| Alarms Enabled | ✓ | CC - calibration + maintenance 12-1-21 |
| GC Influent Filters | ✓ | |

# TABLE 3.19.2
# STANDARD OPERATIONS CHECKLIST
# BIOLOGICAL TREATMENT SYSTEM

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, December 02, 2021

**Inspection Performed by:** Mike Gelwick / Tom Gilbert

## J. TOTALIZERS

| Item | Readings (gallons) | Comments |
|---|---|---|
| FT-3321 Feed to Reactor 1 | 6129081 | |
| FT-3324 Feed Spare | 120021 | |
| FT-3322 Feed to Reactor 2 | 10920744 | |
| FT-3323 Feed to Reactor 3 | 809522 | |
| FT-3301 T-510 to BIO | 51632417 | |
| FT-3341 BIO Effluent | 66488285 | |
| FT-3342 BIO Recycle | 55752636 | |

## K. SAFETY

| Item | Status | Comments |
|---|---|---|
| Building #2 Fire Extinguishers | ✓ | Inspection date: 11-22-21 |
| Building #2 Eye Wash/Shower | ✓ | Checked and Flushed- All OK: (Y) / N |

## L. OTHER COMMENTS:

| |
|---|
| |
| |
| |
| |

# ABLE 3.19.1
# STANDARD OPERATIONS CHECKLIST
# MAIN WTP

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, December 09, 2021

**Inspection Performed by:** Mike Gelwick / Tom Gilbert

## A. PERIMETER COLLECTION SYSTEMS

| Item | Status | Comments |
|---|---|---|
| LFG Cond Automatic Trap CT-1 12.50' | Sump Level: ~~12.51'~~ TB | Counter: TB ~~191,365~~ 191197 Cycles: TB ~~169~~ 328 |
| LFG Cond Automatic Trap CT-2 8.72' | Sump Level: ~~8.54'~~ TB | Counter: TB ~~274,554~~ 274552 Cycles: TB 2 4 |
| LFG Cond Automatic Trap CT-3 7.22' | Sump Level: ~~7.23'~~ TB | Counter: TB ~~315,845~~ 315169 Cycles: 676 1148 |
| CT-4 Containment/Vessel (LFG Cond) | 74 Level: ~~74~~ % TB | Tank Level: 2.12 Counter: 191,256 Cycles: TB 1 Sump: ~~8.52'~~ TB 8.31' |
| PM-15 Containment / Vessel | 30 Level: ~~33~~ % TB | |
| MW-51 Containment / Vessel | 35 Level: ~~55~~ % TB | |
| PM-11 Containment / Vessel | 30 Level: ~~50~~ % TB | |
| MW-38 Systems | ✓ | |
| North Toe System | ✓ | |
| North End Systems (Weekly) | ✓ | |
| Full N. End Systems Check (Monthly) | ✓ | Last Done: 11-22-21 |
| North End Pipeline(s)Flushing (As Needed) | ✓ | Perform if suspended solids present Last Done: 11/15/15 |
| NTES line flush to T-530 (As needed) | ✓ | Perform if suspended solids present Last Done: 10/29/21 |
| NTES Piping Containment | ✓ | Monthly Sump Level: dry @ 16.07 Date: 11-18-21 |
| North Boundary System P-001: | CV 73.9 % @ 6.7 gpm | 40.88 Hz / 2.08 Amps. / vault psi @ 18/no leaks |
| T-101 & T-102 Containment / Tank | ✓ | Levels: 19 % & 18 % |
| Raw Water Storage Tanks Piping | ✓ | |
| RWST Building Temp. (TT-101) | 56.1 °F | Outside Temp.: ~ 37 °F |
| (P-121) or P-122 | ✓ | 0.6 gpm / CV 64 % |
| RWST 2ndry Cont. High Level Switch | ✓ | (LSH-101) Last Test(monthly): 11-18-21 |
| RWST Back-Up Generator | ✓ | Last Test Run(monthly): 11-18-21 |

## B. CHEMICAL STORAGE BAYS

| Item | Status | Comments |
|---|---|---|
| Caustic Tote Levels | ✓ | ~ 490 Gallons Reserve = 2 ~~tote~~ |
| Caustic Bay Heater | ✓ | |
| Peroxide Tote Level | ✓ | ~ 230 Gallons Reserve = 180 |
| HCL Tote Levels | ✓ | ~ 130 Gallons Reserve = 30 |
| Chemical Totes and Piping Inspected | ✓ | Leaks observed: Y / (N) |
| Emergency Shower Inspected | ✓ | Checked and Flushed - All OK: (Y) / N |

## C. PRIMARY AND SECONDARY ACID FEED SYSTEM

| Item | Status | Comments |
|---|---|---|
| Primary Acid Feed Pump (P-631) | ✓ | |
| Ion Exchange Acid Feed Pump (P-632) | ✓ | PI-0632 PSI: 84-90 CV: 4 % |
| Primary Acid Retention Tank (T-510) | ✓ | |
| All Acid Feed Lines | ✓ | Leaks observed: Y / (N) |

## D. NBBW INJECTION TRENCH

| Item | Status | Comments |
|---|---|---|
| Injection Carbon (GAC-810) | **OFFLINE** | Date online: 7/20/18 |
| Injection Rate (FT-800) | 0.0 gpm | NBBW-IW-1= 0.0 NBBW-IW-2= 0.0 NBBW-IW-3= 0.0 gpm ea. |
| Totalizer Reading (FT-800) | 105,135,774 gal | INJ. STOPPED 10/02/18 @ 1545 |

# ABLE 3.19.1
# STANDARD OPERATIONS CHECKLIST
# MAIN WTP

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, December 09, 2021

**Inspection Performed by:** Mike Gelwick / Tom Gilbert

### E. CHEMICAL PRECIPITATION SYSTEM (US FILTER HMR-30)

| Item | Status | Comment |
|---|---|---|
| T-300A Mixer | NA | |
| T-300B (Caustic Mixer) | ✓ | Last Cleaning (Qtrly): 10-20-21 |
| T-300A/B Water Level | ✓ | |
| T-300B (Caustic Mix Chamber) | ✓ | Last Cleaning (Qtrly): 10-20-21 |
| T-300A/B Overflow | ✓ | |
| pH Set-point for (pH 315) | Value: 10.8 | |
| pH 310 | Value: 6.86 | |
| pH 315 | Value: 10.88 | |
| Flocculation Chamber Paddle Wheel | ✓ | |
| Precipitate Floc Quality | ✓ | Good |
| Clarifier Water Quality | ✓ | Good Oil or sheen observed: Y / (N) |
| Clarifier Effluent Piping / Water Level | ✓ | |
| Clear-well Chamber and Water Level | ✓ | |
| HMR PLC Panel | ✓ | |
| Caustic Pump (P-270) | SB | |
| Caustic Pump (P-280) | ✓ | |
| Polymer Pump (P-310) | ✓ | |
| Polymer Tank Mixer | ✓ | |
| Polymer Tank Level | Gallons: ~ 475 | |
| Clear-well Transfer Pumps (P-371 / 372) | ✓ | |
| Sludge Transfer Pump (P-330) | ✓ | Exercise Valves Weekly: Both OK ✓ |
| Manual Sludge Lateral pumping | ✓ | Last done (As Needed): #3 7-20-21 #2 3-20-21 #1 3-20-21 |
| Manual Sludge Lateral Ball Valves | ✓ | Exercise Weekly: All good |
| Automatic Blow-down Operations | ✓ | |

### F. pH PROBES

| pH Probe Location | Calibration Date | Comments: (Time done) |
|---|---|---|
| pH-310 HMR-30 (T-300A) | 12-10-21-Friday | 0840 |
| pH-315 HMR-30 (T-300B) | | |
| pH-365 Primary Acid Ret. Tank | | |
| pH-113 Pre-Ion Exchange | | |
| pH-670 Pre-UV-OX | | 0925 |
| pH-740 Discharge Surge Tank | 12-9-21 | Discharge suspended: 1458 ↔ 1512 |
| Out of Hold Double Check | ---------- | None in hold: ✓✓ |
| Valves Back to Normal Position | ---------- | All OK: ✓✓ |

### G. SLUDGE THICKENER, SLUDGE HOLDING TANKS, FILTER PRESS

| Item | Status | Comments |
|---|---|---|
| Verify Sludge Thickener Running | ✓ | Gauge Reading: 0 % |
| Sludge Thick. Transfer Pump (P-350) | ✓ | |
| Sludge Holding Tank (T-351) | ✓ | Level:~ 45 % |
| Sludge Holding Tank (T-352) | ✓ | Level: 37 % |
| Decant Transfer Pump (P-352) | ✓ | CV 65 % @ 0.5 gpm |
| Filter Press Pumps (P-381 / P-382) | ✓ | |
| Filter Press | ✓ | Stage: Full |

# ABLE 3.19.1
# STANDARD OPERATIONS CHECKLIST
# MAIN WTP

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, December 09, 2021

**Inspection Performed by:** Mike Gelwick / Tom Gilbert

### H. ION EXCHANGE

| Item | Status | Comments |
|---|---|---|
| Feed Tank (T-113) | ✓ Level: 30 % | |
| Feed Pump (P-114) | ✓ Operating Press: 30.30 psi | CV@ 76 % @ 2.1 gpm |
| Retention Tank (T-114) | ✓ Operating Press: 29 psi | pH-113 @ 3.5 |
| Bag Filter (BF-113) | ✓ Operating Press: 3.2 psi | |
| Ion Exchange (Cage (1) or 2) + Guard | ✓ Operating Press: 29 psi | FP-173A-2 → TP-175A/4 + Guard |
| Post Ion Exchange | ✓ Operating Press: 3.5 psi | |

### I. FEED SURGE TANK

| Item | Status | Comments |
|---|---|---|
| Feed Surge Tank (T-520) | ✓ Level: 38 % | Last Cleaning (As Needed, if 4" of solids accumulate): 12/15/19 |
| Feed Surge Pump (P-521 or P-522) | Operating Press: 23 psi | CV@ 75 % @ 33.0 gpm |
| T-520 to GAC Total (FT-675) | 25352486 gal | Time: 0823 |
| North End On-Site Pumping | Operating Press: 2-3 psi | 12.5 gpm @ 0824 |
| North End Off-Site Pumping | Operating Press: 2-5 psi | 8.5 gpm @ 0824 |
| Peroxide Feed Pump (P-680) | ✓ | SPD 2.5 % / RATE 0.7 gpm |
| Peroxide Conc. At (TP-710) | 1.0 PPM | |
| Peroxide Conc. At (TP-740) | 0 PPM | |

### J. HAZARDOUS WASTE STORAGE

| Item | Status | Comments |
|---|---|---|
| 180 Day storage area check | ✓ | Check sheet completed: N/A Empty |
| Satellite Haz. Waste Areas (BLDG #1) | ✓ | Condition: IX Resin Main good |
| Satellite Haz. Waste Area (BLDG #2) | ✓ | Condition: Good |

### K. UV-OXIDATION SYSTEM

| Item | Status | Comments |
|---|---|---|
| UV-Oxidation System | ✓ | |
| Annual Test Run (Calgon) | Date: 9-16-21 | Next: 9-2022 |
| Quarterly Test Run | Date: N/A - Running | Next: N/A - Running |
| Peroxide Feed Pump (P-650) | ✓ | Flow Rate: ~7.2 cc/min. |
| UV-Ox Power | ✓ | 25.8 kVA 257.2 Volts 10.0 Amps |
| Lamp Hours | 1005 Hrs | ✓ |
| Crystal Condition & Wiper Status | ✓ | Oiler status: ✓ |
| UV-OX Bagfilters Status | Last change: 7-13-21 Cleaned: 7-13-21 | 13 psi In 13 psi Out |
| UV-OX Feed Pump ( P-600 or P-601 ) | ✓ | CV@ 76 % @ 7.5 gpm |
| UV-OX Temperature | In(TT-670): 14.2 °C | Out(TT-710): 26.7 °C |
| PDU GAC (PDT-710) | ✓ | Δ Pressure: 4 psi |
| Peroxide Concentration Pre UV | 100 PPM | |
| Peroxide Concentration Post UV(TP-720) | 25 PPM | |
| Peroxide Conc. Post PDU (TP-730) | 0 PPM | |
| Secondary Acid Feed Pump (P-630) | ✓ | CV @ 0 % |
| Secondary Acid Retention Tank (T-645) | ✓ | |
| Pre – UV Oxidizer Total (FT-670) | 20578296 gal | Time: 0830 |
| Post UV-Ox / Pre PDU | ✓ | Pressure: 15 psi |
| Post PDU | ✓ | Pressure: 7.5 psi |

# ABLE 3.19.1
# STANDARD OPERATIONS CHECKLIST
# MAIN WTP

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, December 09, 2021

**Inspection Performed by:** Mike Gelwick / Tom Gilbert

### L. PDU AND LIQUID –PHASE GRANULAR ACTIVATED CARBON

| Item | Status | Comments |
|---|---|---|
| PDT-720 | ✓ | Δ Pressure: 10 psi |
| PDT-730 | ✓ | Δ Pressure: 7 psi |

### M. EFFLUENT DISCHARGE

| Item | Status | Comments |
|---|---|---|
| Effluent Surge Pump ( P751 or P752 ) | ✓ | CV@ 55.7 % |
| Effluent Surge Tank (T-740) | ✓ | Level: 40 % |
| Effluent Discharge Rate (FT-770) | ✓ | 33.3 gpm @ 0840 |
| POTW Line Pressure (PT-770) | ✓ | 32.4 psi |
| Effluent Totalizer Reading (FT-770) | 247666218 gal | Time: 0841 |
| POTW MH17S-078 Discharge Check (Monthly) | ✓ | Last Done: ~~11-8-21~~ ~~11-8-21~~ end ~~12-13-21~~ |
| 4X8-Inch POTW Leak Detection Checks (Monthly) | ✓ | Last Done: ~~11-8-21~~ |
| 4X8-Inch POTW Air Reliefs Checks (Monthly) | ✓ | Last Done: ~~11-8-21~~ |
| 4X8-Inch POTW Isolation Valves Exercise (Qtrly) | ✓ | Last Done: 11-8-21 |
| 2-Inch POTW Backup Pressure Testing (Annual) | ✓ | Last Done: 7/8/21 |
| 2-In POTW Backup Air Reliefs Checks (Annual) | ✓ | Last Done: 7/8/21 |
| 2-Inch POTW Isolation Valve Exercise (Annual) | ✓ | Last Done: 7/8/21 |
| Rotate Chiller Compressors | NA on Standby | ~~Now in Lead: 1 or 2~~ |

### N. LEL EFFLUENT TANK T-740

| Item | Status | Comments |
|---|---|---|
| LEL-740 Sensor | ✓ | Reading: 0 % |
| LEL Sensor Calibration / Automatic High LEL Shutdown Test (monthly) | Last Completed: 11-24-21 | Plant Effluent Suspended: 1225 ↔ 1315 |
| LEL Sensor Bridge Adjustment to 2.0 volts | Reading: 2.001 volts(monthly) | Adjustment Needed: Y or (N) |
| Verify Bridge Current between.300v-.360v | Reading: 0.331 volts(monthly) | |

### O. WTP INFLUENT TOTALIZERS Time : 0842- 0852

| Source | Reading(Gallons) | Source | Reading(Gallons) |
|---|---|---|---|
| (FT-015) RWST Influent | 19730371 | (FT-505) LFG Cond. to T-530 | 219225 |
| (FT-025) NBBW Influent | 94439809 | (FT-056) Off - Site N. End Influent | 43680476 |
| (FT-012) MW-38 Inf. to HMR-30 | 8385728 | (FT-113) Ion Exchange Influent | 953400 |
| (FT-042 HMR30) MW-38 Source to HMR-30 | 35484 | (FT-810) Plant Potable Water In | 30069096 |
| (FT-043) MW-38 to RWST | 3083875 | (FT-026) NBBW Bypass to RWST | 4421674 |
| (FT-042 RWST) MW-38 Source to RWST | 72236 | (FT-014) Misc. Water to RWST | 8188871 |
| (FT-012T) MW-38 to T-540/541 | 8637998 | (FT-035) NTES Inf. to BIO | 6691334 |
| (FT-040T) MW-38N to T-540/541 | 1978498 | (FT-035T) NTES to T-530 | 465555 |
| (FT-041T) MW-38S to T-540/541 | 2696658 | (FT-017) BIO Inf. from T-530 | 659002 |
| (FT-042T) MW-38 Source to T-540/541 | 4034839 | (FT-018) T-540/541 Influent | 8680963 |
| (FT-055) On - Site N. End Influent | 98945620 | (FT-352) T-352 to HMR-30 | 1311240 |

# ABLE 3.19.1
# STANDARD OPERATIONS CHECKLIST
# MAIN WTP

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, December 09, 2021

**Inspection Performed by:** Mike Gelwick / Tom Gilbert

### P. AIR COMPRESSORS *See comments

| Item | Status | Comments |
|---|---|---|
| Compressor Intake Temp. | 66 °F (Analog Gauge) | Outside Temp.: ~ 55 °F |
| Compressor Building Vent | ✓ | Open - Operational |
| Primary Air Compressor (IRN30H) | 2,000 Hour service date: 7-8-21 Serviced @ 60952 Hours | Coolant present in sight glass: (Y) / N Next service @ 62952 Hours Current Hours @ 62197 |
| IRN30H Motor Speed | 36 % | |
| IRN30H Pressure | 114 psi | |
| IRN30H Moisture purge valve chk(Weekly): | ✓ | |
| IRN30H Intake Filter | ✓ | Date Last Changed: 9-30-21 |
| Air Tanks Moisture Purge Valves | Manually Activate(weekly) ✓ | Excessive Moisture: Y / (N) |
| Backup Air Compressors (T-30 East and West) | ✓ | Both cool to touch: (Y) / N |
| Air Dryer | ✓ ECO ON | Moisture at Receiver Tank: Y / (N) |
| Oil Moisture Prevention (Monthly) | Last Done: 9-23-21 | Run at max speed by bleeding air from filter canister above/after air dryer for 2 hrs |
| Air Receiver Tank | ✓ | psi 110 |

### Q. SUMPS

| Item | Status | Comments |
|---|---|---|
| Bag Filter Sump | ✓ | |
| Wet Well Sump | ✓ | |

### R. GAS CHROMATOGRAPH

| Item | Status | Comments |
|---|---|---|
| GC Operational | ✓ | GC # checking UV-Ox Effluent: #1 |
| Alarms Enabled | ✓ | CC calibration and maintance *12-9-21 |
| GC Influent Filters | ✓ | |

### S. SAFETY

| Item | Status | Comments |
|---|---|---|
| Building #1 Fire Extinguishers | ✓ | Date inspected: 11-22-21 |
| Building #1 Eye Wash/Shower | ✓ | Checked and Flushed- All OK: (Y) / N |

**Other Comments:**

| |
|---|
| *R Main Air compressor VFD Replaced 12-6-21. Running OK now. |
| |
| |
| |
| |

# TABLE 3.19.2
# STANDARD OPERATIONS CHECKLIST
# BIOLOGICAL TREATMENT SYSTEM

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, December 09, 2021

**Inspection Performed by:** Mike Gelwick / Tom Gilbert

## A. PUMPS

| Item | Status | Flow Rate (gpm) | Pump Speed (CV%) | Discharge Pressure (psi) | Comments |
|---|---|---|---|---|---|
| **T-510 Pumps** | | | | | |
| P-3301 | ✓ | 2.22 | 74.7 % | 9 | |
| P-3301A | SB | — | — % | — | |
| **NTES Pump** P-002(Sump) / P-002W(10R) (12-8-21 swapped) | ✓ | 0.52 | 49 % | P035 33.34 / P038 6.5 | Globules Observed at TP-130: Y / (N) Time: 1150 |
| **T-530** P-005 | ✓ | 0.20 | 41 % | 6.5 | |
| **T-540/541** P-006 | ✓ | 0.30 | 67 % | 7 | |
| **LFG COND Auto-Traps** | ✓ | 0.0 | NA | 4 | Between Cycles: (Y) / N |
| **Reactor Feed Pumps** | | | | | |
| P-3321 | ✓ | 2.45 | 82.1 % | 12 | |
| P-3322 | ✓ | 3.49 | 60.5 % | 6.5 | |
| P-3323 | ✓ | 2.60 | 72.1 % | 6.5 | |
| P-3324 | SB | — | — % | — | |
| **Reactor Effluent Pumps** | | | | | |
| P-3341 | ✓ | 2.73 | 50.6 % | 16 | |
| P-3341A | SB | — | — % | — | |

## B. BLOWERS

| Item | Status | Pressure (psi) | Temp (°F) | Next Scheduled Service (Qtrly) | Comments Last serviced on: |
|---|---|---|---|---|---|
| B-3331 | ✓ | 4.37 | 4.35 145 | 12-2021 | Greased, Belt and Filter Checked: (Y) / N |
| B-3332 | SB | — | — | ↓ | Belt and Filter Checked: Y / (N) |
| B-3333 | ✓ | 4.39 | 4.36 132 | ↓ | Greased, Belt and Filter Checked: (Y) / N |
| B-3334 | ✓ | 4.34 | 128 | ↓ | Greased, Belt and Filter Checked: (Y) / N |

## C. REACTOR VENTILATION

| Item | Status | Comments |
|---|---|---|
| Vapor Carbon Contactor | ✓ | On-line: 2/10/18 |
| Reactor Vent Blower | ✓ | |
| Reactor Vent Booster | ✓ | |
| VTP-3350 | ✓ | PID Reading: 2.7 PPM |
| VTP-3360 | ✓ | PID Reading: 1.3 PPM |

# TABLE 3.19.2
# STANDARD OPERATIONS CHECKLIST
# BIOLOGICAL TREATMENT SYSTEM

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, December 09, 2021

**Inspection Performed by:** Mike Gelwick / Tom Gilbert

## D. TANKS / REACTORS / SUMPS / CONTAINMENTS / PIPING / Chiller

| Item | Status | Comments |
|---|---|---|
| T-510 Post HMR-30 Mixing Tank | Level: 70 % | Last Cleaning (As needed, if 2" of solids accumulate): 7/14/21 |
| T-530 LFG Condensate / NTES Tank | Level: 25 % | |
| T-530 Mixer | ✓ | |
| LFG Condensate Conveyance Line | ✓ | Last Pressure Test: 7-19-21 Next: 7-2022 (Annual at a minimum or if flow drops off) |
| T-540/541 MW38 Tanks | Lvls: 60 % & 61 % | |
| T-540/541 Mixers | Both Need Fix | Repair Planned |
| Chiller | ✓ | Chiller Coolant Lvl: ~ — " Below full mark |
| Chiller Cooling Fins (as needed) | ✓ | Last Cleaning: 4/20/18 (unit on Standby) |
| Secondary Containments | ✓ | Heat Trace: On OK / (Off Warm out) |
| Feed Piping to Sedimentation Tank | ✓ | Last Back Flushing (Quarterly): 11-12-21 |
| T-3310 Sedimentation Tank | Visual Level: OK | Last Cleaning (As Needed, use TSS info to determine): 9/2021 |
| T-3320 Blend Tank | ✓ Level: 73 % | Last Cleaning (Semi Annual): 9-10-21 |
| T-3331 Reactor No. 1 | ✓ | Digital Displays: (GOOD) / Needs Attn |
| T-3332 Reactor No. 2 | ✓ | Digital Displays: (GOOD) / Needs Attn |
| T-3333 Reactor No. 3 | ✓ | Digital Displays: (GOOD) / Needs Attn |
| T-3334 Settling Tank | ✓ | Last Cleaning (Semi Annual): 9-10-21 |
| P-3334 Biosolids Pump | ✓ | |
| T-3340 Overflow Tank | Level: 30 % | |
| Recycle Valve to Blend Tank | ✓ | 4.01 gpm @ 0920 |
| Building Containment Sump | ✓ | Last Alarm Test Date (Monthly): 11-18-21 |

## E. CHEMICAL FEED SYSTEM

| Item | Status | Comments |
|---|---|---|
| Phosphorous Supply | ✓ | Bags: 14.75 Gallons: ~ 60 |
| Phosphorous Pump (P-2221) | ✓ | |
| Caustic Supply | ✓ | ~ 260 Gallons |
| Caustic Pump (P-2211) | SB | Currently in acid addition mode |
| Acid Supply | ✓ | ~ 40 Gallons |
| Acid Pump (P-2211) | ✓ | |
| Caustic Pump (P-2231) | ✓ Leaks: Y / (N) | Last tubing tip cleaning (monthly): 11-15-21 |
| Caustic Pump (P-2232) | ✓ Leaks: Y / (N) | Last tubing tip cleaning (monthly): 11-15-21 |
| Caustic Pump (P-2233) | ✓ Leaks: Y / (N) | Last tubing tip cleaning (monthly): 11-15-21 |

# TABLE 3.19.2
# STANDARD OPERATIONS CHECKLIST
# BIOLOGICAL TREATMENT SYSTEM

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, December 09, 2021

**Inspection Performed by:** Mike Gelwick / Tom Gilbert

## F. pH Probes

| pH Probe Location | Calibration Date (Monthly) | Comments |
|---|---|---|
| pH-3320 Blend Tank | 11-24-21 | Spray off Clean |
| pH-3331 Reactor 1 | 11-24-21 | ↓ |
| pH-3332 Reactor 2 | 11-24-21 | |
| pH-3333 Reactor 3 | 11-24-21 | |

## G. FILTER SYSTEM

| Item | Status | Comments |
|---|---|---|
| BF-3340 a/b Status | ✓ | |
| Automatic Backwash | Cycle Count: 32 | Reset |
| BF-3340 a/b Differential Pressure | PSI: 3 | 20 PSI / 17 PSI @ 3.8 GPM |
| 75-micron Bags Last Cleaning | Date: 11-14-21 | 16.5/7 |
| 75-micron Bags Last Inspection | Date: 11-14-21 | |
| 75-micron Bags Last Changed | Date: 11-14-21 | |
| GACF-3340 Status | ✓ | |
| GACF-3340 Differential Pressure | PSI: 9.5 | 16.5/7 @ 3.8 GPM |
| Last Backwash Performed | Date: 9-27-21 | |

## H. ELECTRICAL AND INSTRUMENTATION

| Item | Status | Comments |
|---|---|---|
| "BIO" Backup Generator | ✓ | Block Heater: On OK / (Off Warm Out) |
| Electrical Surge Suppressor | ✓ | |
| Motor Control Center | ✓ | |
| PLC | ✓ | UPS @ 97 min / 95 Events |
| HMI's | ✓ | |
| BTS Process KWH Meter | 1823860 KWH | Time: 1400 |
| Building#2 KWH Meter | 5274470 KWH | Time: 1400 |

## I. GAS CHROMATOGRAPHY

| Item | Status | Comments |
|---|---|---|
| GC Operational | ✓ | GC # checking BIO: GC #2 |
| Alarms Enabled | ✓ | CC calibration 12-8-21 |
| GC Influent Filters | ✓ | |

# TABLE 3.19.2
# STANDARD OPERATIONS CHECKLIST
# BIOLOGICAL TREATMENT SYSTEM

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, December 09, 2021

**Inspection Performed by:** Mike Gelwick / Tom Gilbert

## J. TOTALIZERS

| Item | Readings (gallons) | Comments |
|---|---|---|
| FT-3321 Feed to Reactor 1 | 6151293 | |
| FT-3324 Feed Spare | 120021 | |
| FT-3322 Feed to Reactor 2 | 10951606 | |
| FT-3323 Feed to Reactor 3 | 831417 | |
| FT-3301 T-510 to BIO | 51652302 | |
| FT-3341 BIO Effluent | 66516313 | |
| FT-3342 BIO Recycle | 55793718 | |

## K. SAFETY

| Item | Status | Comments |
|---|---|---|
| Building #2 Fire Extinguishers | ✓ | Inspection date: 11-22-21 |
| Building #2 Eye Wash/Shower | ✓ | Checked and Flushed- All OK: (Y) / N |

## L. OTHER COMMENTS:

| |
|---|
| |
| |
| |
| |

# ABLE 3.19.1
# STANDARD OPERATIONS CHECKLIST
# MAIN WTP

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, December 16, 2021

**Inspection Performed by:** Mike Gelwick / Tom Gilbert

## A. PERIMETER COLLECTION SYSTEMS

| Item | Status | Comments |
|---|---|---|
| LFG Cond Automatic Trap CT-1 | Sump Level: 12.51 | Counter: 191,365 Cycles: 168 |
| LFG Cond Automatic Trap CT-2 | Sump Level: 8.54 | Counter: 274,554 Cycles: 2 |
| LFG Cond Automatic Trap CT-3 | Sump Level: 7.23 | Counter: 315,845 Cycles: 676 |
| CT-4 Containment/Vessel (LFG Cond) | Level: 74 % | Tank Level: 2.12 Counter: 191,256 Cycles: 0 Sump: 8.52' |
| PM-15 Containment / Vessel | Level: 33 % | |
| MW-51 Containment / Vessel | Level: 55 % | |
| PM-11 Containment / Vessel | Level: 50 % | |
| MW-38 Systems | ✓ | |
| North Toe System | ✓ | |
| North End Systems (Weekly) | ✓ | |
| Full N. End Systems Check (Monthly) | ✓ | Last Done: 11-22-21 |
| North End Pipeline(s)Flushing (As Needed) | ✓ | Perform if suspended solids present Last Done: 11/15/15 |
| NTES line flush to T-530 (As needed) | ✓ | Perform if suspended solids present Last Done: 10/29/21 |
| NTES Piping Containment | ✓ | Monthly Sump Level: Dry @ 16.07 Date: 12-16-21 |
| North Boundary System P-001: | CV 73.8% @ 6.6 gpm | 40.71 Hz / 2.08 Amps. / vault psi @ 18 No leaks |
| T-101 & T-102 Containment / Tank | ✓ | Levels: 35 % & 34 % |
| Raw Water Storage Tanks Piping | ✓ | |
| RWST Building Temp. (TT-101) | 52.1 °F | Outside Temp.: ~ 27 °F |
| (P-121) or P-122 | ✓ | 1.2 gpm / CV 54 % |
| RWST 2ndry Cont. High Level Switch | ✓ | (LSH-101) Last Test(monthly): 12-16-21 |
| RWST Back-Up Generator | ✓ | Last Test Run(monthly): 12-16-21 |

## B. CHEMICAL STORAGE BAYS

| Item | Status | Comments |
|---|---|---|
| Caustic Tote Levels | ✓ | ~ 375 Gallons Reserve = 2 totes |
| Caustic Bay Heater | ✓ | |
| Peroxide Tote Level | ✓ | ~ 215 Gallons Reserve = ~180 |
| HCL Tote Levels | ✓ | ~ 113 Gallons Reserve = ~30 |
| Chemical Totes and Piping Inspected | ✓ | Leaks observed: Y / (N) |
| Emergency Shower Inspected | ✓ | Checked and Flushed - All OK: (Y) / N |

## C. PRIMARY AND SECONDARY ACID FEED SYSTEM

| Item | Status | Comments |
|---|---|---|
| Primary Acid Feed Pump (P-631) | ✓ | |
| Ion Exchange Acid Feed Pump (P-632) | ✓ | PI-0632 PSI: 84-90 CV: 4 % |
| Primary Acid Retention Tank (T-510) | ✓ | |
| All Acid Feed Lines | ✓ | Leaks observed: Y / (N) |

## D. NBBW INJECTION TRENCH

| Item | Status | Comments |
|---|---|---|
| Injection Carbon (GAC-810) | OFFLINE | Date online: 7/20/18 |
| Injection Rate (FT-800) | 0.0 gpm | NBBW-IW-1= 0.0 NBBW-IW-2= 0.0 NBBW-IW-3= 0.0 gpm ea. |
| Totalizer Reading (FT-800) | 105,135,774 gal | INJ. STOPPED 10/02/18 @ 1545 |

# ABLE 3.19.1
# STANDARD OPERATIONS CHECKLIST
# MAIN WTP

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, December 16, 2021

**Inspection Performed by:** Mike Gelwick / Tom Gilbert

### E. CHEMICAL PRECIPITATION SYSTEM (US FILTER HMR-30)

| Item | Status | Comment |
|---|---|---|
| T-300A Mixer | NA | |
| T-300B (Caustic Mixer) | ✓ | Last Cleaning (Qtrly): 10-20-21 |
| T-300A/B Water Level | ✓ | |
| T-300B (Caustic Mix Chamber) | ✓ | Last Cleaning (Qtrly): 10-20-21 |
| T-300A/B Overflow | ✓ | |
| pH Set-point for (pH 315) | Value: 10.8 | |
| pH 310 | Value: 6.87 | |
| pH 315 | Value: 10.80 | |
| Flocculation Chamber Paddle Wheel | ✓ | |
| Precipitate Floc Quality | ✓ | good |
| Clarifier Water Quality | ✓ | good Oil or sheen observed: Y / (N) |
| Clarifier Effluent Piping / Water Level | ✓ | |
| Clear-well Chamber and Water Level | ✓ | |
| HMR PLC Panel | ✓ | |
| Caustic Pump (P-270) | SB | |
| Caustic Pump (P-280) | ✓ | |
| Polymer Pump (P-310) | ✓ | |
| Polymer Tank Mixer | ✓ | |
| Polymer Tank Level | Gallons: ~ 390 | |
| Clear-well Transfer Pumps (P-371 / 372) | ✓ | |
| Sludge Transfer Pump (P-330) | ✓ | Exercise Valves Weekly: Both ok ✓ |
| Manual Sludge Lateral pumping | ✓ | Last done (As Needed): #1 3-20-21 #2 3-20-21 #3 7-20-21 |
| Manual Sludge Lateral Ball Valves | ✓ | Exercise Weekly: All good |
| Automatic Blow-down Operations | ✓ | |

### F. pH PROBES

| pH Probe Location | Calibration Date | Comments: (Time done) |
|---|---|---|
| pH-310 HMR-30 (T-300A) | 12-16-21 today | 1443 |
| pH-315 HMR-30 (T-300B) | | |
| pH-365 Primary Acid Ret. Tank | | |
| pH-113 Pre-Ion Exchange | | |
| pH-670 Pre-UV-OX | | 1546 |
| pH-740 Discharge Surge Tank | | Discharge suspended: 1424 ↔ 1438 |
| Out of Hold Double Check | ---------- | None in hold: ✓✓ Double checked TG |
| Valves Back to Normal Position | ---------- | All OK: ✓✓ TG |

### G. SLUDGE THICKENER, SLUDGE HOLDING TANKS, FILTER PRESS

| Item | Status | Comments |
|---|---|---|
| Verify Sludge Thickener Running | ✓ | Gauge Reading: 0 % |
| Sludge Thick. Transfer Pump (P-350) | ✓ | |
| Sludge Holding Tank (T-351) | ✓ | Level:~ 45 % |
| Sludge Holding Tank (T-352) | ✓ | Level: 30 % |
| Decant Transfer Pump (P-352) | ✓ | CV 70 % @ 0.0 gpm |
| Filter Press Pumps (P-381 / P-382) | ✓ | |
| Filter Press | ✓ | Stage: Full |

# ABLE 3.19.1
# STANDARD OPERATIONS CHECKLIST
# MAIN WTP

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, December 16, 2021

**Inspection Performed by:** Mike Gelwick / Tom Gilbert

### H. ION EXCHANGE

| Item | Status | Comments |
|---|---|---|
| Feed Tank (T-113) | ✓ Level: 30 % | |
| Feed Pump (P-114) | Operating Press: 29.4 psi | CV@ 73 % @ 2.0 gpm |
| Retention Tank (T-114) | Operating Press: 29 psi | pH-113 @ 3.9 |
| Bag Filter (BF-113) | Operating Press: 32 psi | |
| Ion Exchange (Cage (1) or 2) + Guard | Operating Press: 28 psi | TP-173A-2 → TP-175A/4 canisters + Guard |
| Post Ion Exchange | Operating Press: 3.5 psi | |

### I. FEED SURGE TANK

| Item | Status | Comments |
|---|---|---|
| Feed Surge Tank (T-520) | Level: 38 % | Last Cleaning (As Needed, if 4" of solids accumulate): 12/15/19 |
| Feed Surge Pump (P-521 or P-522) | Operating Press: 24 psi | CV@ 76 % @ 31.9 gpm |
| T-520 to GAC Total (FT-675) | 253851837 gal | Time: 0843 |
| North End On-Site Pumping | Operating Press: 2-3 psi | 12.4 gpm @ 0845 |
| North End Off-Site Pumping | Operating Press: 2-6 psi | 9.1 gpm @ 0845 |
| Peroxide Feed Pump (P-680) | ✓ | SPD 2.4 % / RATE 0.6 gpm |
| Peroxide Conc. At (TP-710) | 1.0 PPM | |
| Peroxide Conc. At (TP-740) | 0.0 PPM | |

### J. HAZARDOUS WASTE STORAGE

| Item | Status | Comments |
|---|---|---|
| 180 Day storage area check | ✓ | Check sheet completed: N/A Empty |
| Satellite Haz. Waste Areas (BLDG #1) | ✓ | Condition: IX Resin main good |
| Satellite Haz. Waste Area (BLDG #2) | ✓ | Condition: Good |

### K. UV-OXIDATION SYSTEM

| Item | Status | Comments |
|---|---|---|
| UV-Oxidation System | ✓ | |
| Annual Test Run (Calgon) | Date: 9-16-21 | Next: 9-2022 |
| Quarterly Test Run | Date: N/A - Running | Next: N/A - Running |
| Peroxide Feed Pump (P-650) | ✓ | Flow Rate: ~ 7.2 cc/min. |
| UV-Ox Power | ✓ | 25.7 kVA 256.3 Volts 10.1 Amps |
| Lamp Hours | 1173 Hrs | |
| Crystal Condition & Wiper Status | ✓ | Oiler status: OK ✓ |
| UV-OX Bagfilters Status | Last change: 7-13-21 Cleaned: 7-13-21 | 14 psi In 14 psi Out |
| UV-OX Feed Pump ( P-600 or (P-601)) | ✓ | CV@ 82 % @ 7.4 gpm |
| UV-OX Temperature | In(TT-670): 14.1 °C | Out(TT-710): 26.8 °C |
| PDU GAC (PDT-710) | ✓ | Δ Pressure: 6 psi |
| Peroxide Concentration Pre UV | 100 PPM | |
| Peroxide Concentration Post UV(TP-720) | 25 PPM | |
| Peroxide Conc. Post PDU (TP-730) | 0 PPM | |
| Secondary Acid Feed Pump (P-630) | ✓ | CV @ 2 % |
| Secondary Acid Retention Tank (T-645) | ✓ | |
| Pre – UV Oxidizer Total (FT-670) | 20650984 gal | Time: 0854 |
| Post UV-Ox / Pre PDU | ✓ | Pressure: 17 psi |
| Post PDU | ✓ | Pressure: 7.5 psi |

# ABLE 3.19.1
# STANDARD OPERATIONS CHECKLIST
# MAIN WTP

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, December 16, 2021

**Inspection Performed by:** Mike Gelwick / Tom Gilbert

### L. PDU AND LIQUID –PHASE GRANULAR ACTIVATED CARBON

| Item | Status | Comments |
|---|---|---|
| PDT-720 | ✓ | Δ Pressure: 12 psi |
| PDT-730 | ✓ | Δ Pressure: 7 psi |

### M. EFFLUENT DISCHARGE

| Item | Status | Comments |
|---|---|---|
| Effluent Surge Pump (P751 or P752 ) | ✓ | CV@ 54.9 % |
| Effluent Surge Tank (T-740) | ✓ | Level: 40 % |
| Effluent Discharge Rate (FT-770) | ✓ | 32.1 gpm @ 0857 |
| POTW Line Pressure (PT-770) | ✓ | 32.2 psi |
| Effluent Totalizer Reading (FT-770) | 247994456 gal | Time: 0858 |
| POTW MH17S-078 Discharge Check (Monthly) | ✓ | Last Done: 12-13-21 |
| 4X8-Inch POTW Leak Detection Checks (Monthly) | ✓ | Last Done: 12-13-21 |
| 4X8-Inch POTW Air Reliefs Checks (Monthly) | ✓ | Last Done: 12-13-21 |
| 4X8-Inch POTW Isolation Valves Exercise (Qtrly) | ✓ | Last Done: ~~12-13-21~~ 11-8-21 |
| 2-Inch POTW Backup Pressure Testing (Annual) | ✓ | Last Done: 7/8/21 |
| 2-In POTW Backup Air Reliefs Checks (Annual) | ✓ | Last Done: 7/8/21 |
| 2-Inch POTW Isolation Valve Exercise (Annual) | ✓ | Last Done: 7/8/21 |
| Rotate Chiller Compressors | NA on Standby | ~~Now in Lead: 1 or 2~~ |

### N. LEL EFFLUENT TANK T-740

| Item | Status | Comments |
|---|---|---|
| LEL-740 Sensor | ✓ | Reading: 0 % |
| LEL Sensor Calibration / Automatic High LEL Shutdown Test (monthly) | Last Completed: 11-24-21 | Plant Effluent Suspended: 1225 ↔ 1315 |
| LEL Sensor Bridge Adjustment to 2.0 volts | Reading: 2.001 volts(monthly) | Adjustment Needed: Y or (N) |
| Verify Bridge Current between.300v-.360v | Reading: 0.331 volts(monthly) | |

### O. WTP INFLUENT TOTALIZERS Time : 0900 - 0910

| Source | Reading(Gallons) | Source | Reading(Gallons) |
|---|---|---|---|
| (FT-015) RWST Influent | 19736730 | (FT-505) LFG Cond. to T-530 | 219304 |
| (FT-025) NBBW Influent | 94504820 | (FT-056) Off - Site N. End Influent | 43766952 |
| (FT-012) MW-38 Inf. to HMR-30 | 8404037 | (FT-113) Ion Exchange Influent | 973455 |
| (FT-042 HMR30) MW-38 Source to HMR-30 | 35484 | (FT-810) Plant Potable Water In | 30069988 |
| (FT-043) MW-38 to RWST | 3084314 | (FT-026) NBBW Bypass to RWST | 4423294 |
| (FT-042 RWST) MW-38 Source to RWST | 72236 | (FT-014) Misc. Water to RWST | 8199356 |
| (FT-012T) MW-38 to T-540/541 | 8637998 | (FT-035) NTES Inf. to BIO | 6696424 |
| (FT-040T) MW-38N to T-540/541 | 1978498 | (FT-035T) NTES to T-530 | 465753 |
| (FT-041T) MW-38S to T-540/541 | 2696658 | (FT-017) BIO Inf. from T-530 | 659179 |
| (FT-042T) MW-38 Source to T-540/541 | 4034839 | (FT-018) T-540/541 Influent | 8683485 |
| (FT-055) On - Site N. End Influent | 9907697 | (FT-352) T-352 to HMR-30 | 1314027 |

# ABLE 3.19.1
# STANDARD OPERATIONS CHECKLIST
# MAIN WTP

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, December 16, 2021

**Inspection Performed by:** Mike Gelwick / Tom Gilbert

### P. AIR COMPRESSORS

| Item | Status | Comments |
|---|---|---|
| Compressor Intake Temp. | 65 °F (Analog Gauge) | Outside Temp.: ~ 34 °F |
| Compressor Building Vent | ✓ | OPEN - Operational |
| Primary Air Compressor (IRN30H) | 2,000 Hour service date: 7-8-21<br>Serviced @ 60952 Hours | Coolant present in sight glass: (Y) / N<br>Next service @ 62952 Hours<br>Current Hours @ 62286 |
| IRN30H Motor Speed | 31 % | |
| IRN30H Pressure | 123 psi | |
| IRN30H Moisture purge valve chk(Weekly): | ✓ | |
| IRN30H Intake Filter | ✓ | Date Last Changed: 9-30-21 |
| Air Tanks Moisture Purge Valves | Manually Activate(weekly) ✓ | Excessive Moisture: Y / (N) |
| Backup Air Compressors (T-30 East and West) | ✓ | Both cool to touch: (Y) / N |
| Air Dryer | ✓ ECO ON | Moisture at Receiver Tank: Y / (N) |
| Oil Moisture Prevention (Monthly) | Last Done: 9-23-21 | Run at max speed by bleeding air from filter canister above/after air dryer for 2 hrs |
| Air Receiver Tank | ✓ | psi 108 |

### Q. SUMPS

| Item | Status | Comments |
|---|---|---|
| Bag Filter Sump | ✓ | |
| Wet Well Sump | ✓ | |

### R. GAS CHROMATOGRAPH

| Item | Status | Comments |
|---|---|---|
| GC Operational | ✓ | GC # checking UV-Ox Effluent: #1 |
| Alarms Enabled | ✓ | cc - Calibration + Maint 12-15-21 |
| GC Influent Filters | ✓ | |

### S. SAFETY

| Item | Status | Comments |
|---|---|---|
| Building #1 Fire Extinguishers | ✓ | Date inspected: 11-22-21 |
| Building #1 Eye Wash/Shower | ✓ | Checked and Flushed- All OK: (Y) / N |

**Other Comments:**

# TABLE 3.19.2
# STANDARD OPERATIONS CHECKLIST
# BIOLOGICAL TREATMENT SYSTEM

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, December 16, 2021

**Inspection Performed by:** Mike Gelwick / Tom Gilbert

## A. PUMPS

| Item | Status | Flow Rate (gpm) | Pump Speed (CV%) | Discharge Pressure (psi) | Comments |
|---|---|---|---|---|---|
| **T-510 Pumps** | | | | | |
| P-3301 | ✓ | 1.3 | 28 % | 7 | |
| P-3301A | SB | — | — % | — | |
| **NTES Pump** P-002(Sump) / (P-002W(10R)) | ✓ | 0.53 | 49 % | P035 34-38 / P038 7 | Globules Observed at TP-130: Y / (N) Time: 1100 |
| **T-530** P-005 | SB✓ | ~~0.00~~ | ~~40~~ % | ~~7~~ | |
| **T-540/541** P-006 | ✓ | 0.30 | 73 % | 6.5 | |
| **LFG COND Auto-Traps** | ✓ | 0.0 | NA | 4 | Between Cycles: (Y) / N |
| **Reactor Feed Pumps** | | | | | |
| P-3321 | ✓ | 2.21 | 47.7 % | 7 | |
| P-3322 | ✓ | 2.66 | 43.1 % | 5 | |
| P-3323 | ✓ | 2.12 | 70.2 % | 6.5 | |
| P-3324 | SB | — | — % | — | |
| **Reactor Effluent Pumps** | | | | | |
| P-3341 | ✓ | 2.24 | 50.7 % | 14 | |
| P-3341A | SB | — | — % | — | |

## B. BLOWERS

| Item | Status | Pressure (psi) | Temp (°F) | Next Scheduled Service (Qtrly) | Comments |
|---|---|---|---|---|---|
| | | | | | Last serviced on: 10-1-21 |
| B-3331 | ✓ | 4.33 | 129 | 12-2021-soon | Greased, Belt and Filter Checked: (Y) / N |
| B-3332 | SB | — | — | ↓ | Belt and Filter Checked: (X) / (N) |
| B-3333 | ✓ | 4.43 | 129 | ↓ | Greased, Belt and Filter Checked: (Y) / N |
| B-3334 | ✓ | 4.37 | 125 | ↓ | Greased, Belt and Filter Checked: (Y) / N |

## C. REACTOR VENTILATION

| Item | Status | Comments |
|---|---|---|
| Vapor Carbon Contactor | ✓ | On-line: 2/10/18 |
| Reactor Vent Blower | ✓ | |
| Reactor Vent Booster | ✓ | |
| VTP-3350 | ✓ | PID Reading: 4.8 PPM |
| VTP-3360 | ✓ | PID Reading: 2.4 PPM |

# TABLE 3.19.2
# STANDARD OPERATIONS CHECKLIST
# BIOLOGICAL TREATMENT SYSTEM

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, December 16, 2021

**Inspection Performed by:** Mike Gelwick / Tom Gilbert

## D. TANKS / REACTORS / SUMPS / CONTAINMENTS / PIPING / Chiller

| Item | Status | Comments |
|---|---|---|
| T-510 Post HMR-30 Mixing Tank | Level: 66 % | Last Cleaning (As needed, if 2" of solids accumulate): 7/14/21 |
| T-530 LFG Condensate / NTES Tank | Level: 26 % | |
| T-530 Mixer | ✓ | |
| LFG Condensate Conveyance Line | ✓ | Last Pressure Test: 7-19-21 Next: 7-2022 (Annual at a minimum or if flow drops off) |
| T-540/541 MW38 Tanks | Lvls: 43 % & 43% | |
| T-540/541 Mixers | ✓ | New mixers on 12-15-21 * |
| Chiller | ✓ | Chiller Coolant Lvl: ~ — " Below full mark |
| Chiller Cooling Fins (as needed) | ✓ | Last Cleaning: 4/20/18 (unit on Standby) |
| Secondary Containments | ✓ | Heat Trace: (On OK) / Off Warm out |
| Feed Piping to Sedimentation Tank | ✓ | Last Back Flushing (Quarterly): 11-12-21 |
| T-3310 Sedimentation Tank | Visual Level: ok | Last Cleaning (As Needed, use TSS info to determine): 9/2021 |
| T-3320 Blend Tank | ✓ Level: 70 % | Last Cleaning (Semi Annual): 9-10-21 |
| T-3331 Reactor No. 1 | ✓ | Digital Displays: (GOOD) / Needs Attn |
| T-3332 Reactor No. 2 | ✓ | Digital Displays: (GOOD) / Needs Attn |
| T-3333 Reactor No. 3 | ✓ | Digital Displays: (GOOD) / Needs Attn |
| T-3334 Settling Tank | ✓ | Last Cleaning (Semi Annual): 9-10-21 |
| P-3334 Biosolids Pump | ✓ | |
| T-3340 Overflow Tank | ✓ Level: 30 % | |
| Recycle Valve to Blend Tank | ✓ | 3.92 gpm @ 1139 |
| Building Containment Sump | ✓ | Last Alarm Test Date (Monthly): 12-16-21 |

## E. CHEMICAL FEED SYSTEM

| Item | Status | Comments |
|---|---|---|
| Phosphorous Supply | ✓ | Bags: 14.5 Gallons: ~ 70 |
| Phosphorous Pump (P-2221) | ✓ | |
| Caustic Supply | ✓ | ~ 245 Gallons |
| Caustic Pump (P-2211) | SB | Currently in acid addition mode |
| Acid Supply | ✓ | ~ 40 Gallons |
| Acid Pump (P-2211) | ✓ | |
| Caustic Pump (P-2231) | ✓ Leaks: Y / (N) | Last tubing tip cleaning (monthly): 12-16-21 |
| Caustic Pump (P-2232) | ✓ Leaks: Y / (N) | Last tubing tip cleaning (monthly): ↓ |
| Caustic Pump (P-2233) | ✓ Leaks: Y / (N) | Last tubing tip cleaning (monthly): ↓ |

# TABLE 3.19.2
# STANDARD OPERATIONS CHECKLIST
# BIOLOGICAL TREATMENT SYSTEM

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, December 16, 2021

**Inspection Performed by:** Mike Gelwick / Tom Gilbert

### F. pH Probes

| pH Probe Location | Calibration Date (Monthly) | Comments |
|---|---|---|
| pH-3320 Blend Tank | 11-24-21 | ACID/BASE Clean today |
| pH-3331 Reactor 1 | ↓ | ↓ |
| pH-3332 Reactor 2 | ↓ | ↓ |
| pH-3333 Reactor 3 | ↓ | ↓ |

### G. FILTER SYSTEM

| Item | Status | Comments |
|---|---|---|
| BF-3340 a/b Status | ✓ | |
| Automatic Backwash | Cycle Count: 19 | Reset |
| BF-3340 a/b Differential Pressure | PSI: .5 | 7 PSI / 6.5 @ 1 gpm |
| 75-micron Bags Last Cleaning | Date: 11-14-21 | |
| 75-micron Bags Last Inspection | Date: ↓ | |
| 75-micron Bags Last Changed | Date: | |
| GACF-3340 Status | ✓ | |
| GACF-3340 Differential Pressure | PSI: .5 | 7 / 6.5 @ .9 GPM |
| Last Backwash Performed | Date: 9-27-21 | |

### H. ELECTRICAL AND INSTRUMENTATION

| Item | Status | Comments |
|---|---|---|
| "BIO" Backup Generator | ✓ | Block Heater: (On OK) / Off Warm Out |
| Electrical Surge Suppressor | ✓ | |
| Motor Control Center | ✓ | |
| PLC | ✓ | UPS @ 97 min / 95 Events |
| HMI's | ✓ | |
| BTS Process KWH Meter | ✓ 01826363 KWH | Time: 1252 |
| Building#2 KWH Meter | 05280578 KWH | Time: 1253 |

### I. GAS CHROMATOGRAPHY

| Item | Status | Comments |
|---|---|---|
| GC Operational | ✓ | GC # checking BIO: #2 |
| Alarms Enabled | ✓ | cc-calibration + maint 12-15-21 |
| GC Influent Filters | ✓ | |

# TABLE 3.19.2
# STANDARD OPERATIONS CHECKLIST
# BIOLOGICAL TREATMENT SYSTEM

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, December 16, 2021

**Inspection Performed by:** Mike Gelwick / Tom Gilbert

## J. TOTALIZERS

| Item | Readings (gallons) | Comments |
|---|---|---|
| FT-3321 Feed to Reactor 1 | 6166816 | |
| FT-3324 Feed Spare | 122744 | |
| FT-3322 Feed to Reactor 2 | 10980830 | |
| FT-3323 Feed to Reactor 3 | 852145 | |
| FT-3301 T-510 to BIO | 51670663 | |
| FT-3341 BIO Effluent | 66541420 | |
| FT-3342 BIO Recycle | 55834335 | |

## K. SAFETY

| Item | Status | Comments |
|---|---|---|
| Building #2 Fire Extinguishers | ✓ | Inspection date: 11-22-21 |
| Building #2 Eye Wash/Shower | ✓ | Checked and Flushed- All OK: (Y) / N |

## L. OTHER COMMENTS:

| |
|---|
| 12-15-21- New mixers w/Checked Propellers installed in T540 + T541 |
| |
| |
| |

# ABLE 3.19.1
# STANDARD OPERATIONS CHECKLIST
# MAIN WTP

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, December 23, 2021

**Inspection Performed by:** Mike Gelwick

## A. PERIMETER COLLECTION SYSTEMS

| Item | Status | Comments |
|---|---|---|
| LFG Cond Automatic Trap CT-1 | Sump Level: 12.55 | Counter: 191718 Cycles: 353 |
| LFG Cond Automatic Trap CT-2 | Sump Level: 8.54ok | Counter: 274591 Cycles: 37 |
| LFG Cond Automatic Trap CT-3 | Sump Level: 7.27ok | Counter: 316777 Cycles: 932 |
| CT-4 Containment/Vessel (LFG Cond) | ✓ Level: 76 % | Tank Level: 2.06 Counter: 191257 Cycles: 1 Sump: 8.55ok |
| PM-15 Containment / Vessel | ✓ Level: 35 % | |
| MW-51 Containment / Vessel | ✓ Level: 25 % | |
| PM-11 Containment / Vessel | ✓ Level: 30 % | |
| MW-38 Systems | ✓ | |
| North Toe System | ✓ | |
| North End Systems (Weekly) | ✓ | |
| Full N. End Systems Check (Monthly) | ✓ | Last Done: 12-23-21 |
| North End Pipeline(s)Flushing (As Needed) | ✓ | Perform if suspended solids present Last Done: 11/15/15 |
| NTES line flush to T-530 (As needed) | ✓ | Perform if suspended solids present Last Done: 10/29/21 |
| NTES Piping Containment | ✓ | Monthly Sump Level: Dry 2160? Date: 12-16-21 |
| North Boundary System P-001: | CV 74.2 % @ 6.5 gpm | 40.96 Hz 12.08 Amps. / vault psi @ 18 / no leaks |
| T-101 & T-102 Containment / Tank | ✓ | Levels: 39 % & 35 % |
| Raw Water Storage Tanks Piping | ✓ | |
| RWST Building Temp. (TT-101) | 54.1 °F | Outside Temp.: ~ 42 °F |
| (P-123) or P-122 | ✓ | 2.6 gpm / CV 63 % Sawtooth Batch Controls |
| RWST 2ndry Cont. High Level Switch | ✓ | (LSH-101) Last Test(monthly): 12-16-21 |
| RWST Back-Up Generator | ✓ | Last Test Run(monthly): 12-16-21 |

## B. CHEMICAL STORAGE BAYS

| Item | Status | Comments |
|---|---|---|
| Caustic Tote Levels | ✓ | ~ 555 Gallons Reserve = 1 tote |
| Caustic Bay Heater | ✓ | |
| Peroxide Tote Level | ✓ | ~ 185 Gallons Reserve = ~ 80 |
| HCL Tote Levels | ✓ | ~ 100 Gallons Reserve = ~ 30 |
| Chemical Totes and Piping Inspected | ✓ | Leaks observed: Y / (N) |
| Emergency Shower Inspected | ✓ | Checked and Flushed - All OK: (Y) / N |

## C. PRIMARY AND SECONDARY ACID FEED SYSTEM

| Item | Status | Comments |
|---|---|---|
| Primary Acid Feed Pump (P-631) | ✓ | |
| Ion Exchange Acid Feed Pump (P-632) | ✓ | PI-0632 PSI: 86-90 CV: 4 % |
| Primary Acid Retention Tank (T-510) | ✓ | |
| All Acid Feed Lines | ✓ | Leaks observed: Y / (N) |

## D. NBBW INJECTION TRENCH

| Item | Status | Comments |
|---|---|---|
| Injection Carbon (GAC-810) | OFFLINE | Date online: 7/20/18 |
| Injection Rate (FT-800) | 0.0 gpm | NBBW-IW-1= 0.0 NBBW-IW-2= 0.0 NBBW-IW-3= 0.0 gpm ea. |
| Totalizer Reading (FT-800) | 105,135,774 gal | INJ. STOPPED 10/02/18 @ 1545 |

# ABLE 3.19.1
# STANDARD OPERATIONS CHECKLIST
# MAIN WTP

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, December 23, 2021

**Inspection Performed by:** Mike Gelwick

### E. CHEMICAL PRECIPITATION SYSTEM (US FILTER HMR-30)

| Item | Status | Comment |
|---|---|---|
| T-300A Mixer | NA | |
| T-300B (Caustic Mixer) | ✓ | Last Cleaning (Qtrly): 10-20-21 |
| T-300A/B Water Level | ✓ | |
| T-300B (Caustic Mix Chamber) | ✓ | Last Cleaning (Qtrly): 10-20-21 |
| T-300A/B Overflow | ✓ | |
| pH Set-point for (pH 315) | Value: 10.8 | |
| pH 310 | Value: 6.81 | |
| pH 315 | Value: 10.96 | |
| Flocculation Chamber Paddle Wheel | ✓ | |
| Precipitate Floc Quality | ✓ | Good |
| Clarifier Water Quality | ✓ | Good Oil or sheen observed: Y / (N) |
| Clarifier Effluent Piping / Water Level | ✓ | |
| Clear-well Chamber and Water Level | ✓ | |
| HMR PLC Panel | ✓ | |
| Caustic Pump (P-270) | SB | |
| Caustic Pump (P-280) | ✓ | |
| Polymer Pump (P-310) | ✓ | |
| Polymer Tank Mixer | ✓ | |
| Polymer Tank Level | Gallons: ~ 510 | |
| Clear-well Transfer Pumps (P-371 / 372) | ✓ | |
| Sludge Transfer Pump (P-330) | ✓ | Exercise Valves Weekly: Both ok |
| Manual Sludge Lateral pumping | ✓ | Last done (As Needed): #3 - 7-2021 / #2 - 3-22-21 |
| Manual Sludge Lateral Ball Valves | ✓ | Exercise Weekly: All ok |
| Automatic Blow-down Operations | ✓ | |

### F. pH PROBES

* New 4 + 10 pH STDs today *

| pH Probe Location | Calibration Date | Comments: (Time done) |
|---|---|---|
| pH-310 HMR-30 (T-300A) | 12-23-21 - today | 1310 |
| pH-315 HMR-30 (T-300B) | | |
| pH-365 Primary Acid Ret. Tank | | |
| pH-113 Pre-Ion Exchange | | |
| pH-670 Pre-UV-OX | | 1353 |
| pH-740 Discharge Surge Tank | | Discharge suspended: 1401 ↔ 1425 |
| Out of Hold Double Check | ---------- | None in hold: ✓✓ " " |
| Valves Back to Normal Position | ---------- | All OK: ✓✓ " " |

### G. SLUDGE THICKENER, SLUDGE HOLDING TANKS, FILTER PRESS

| Item | Status | Comments * Grease Thickener motor bearings today * |
|---|---|---|
| Verify Sludge Thickener Running | ✓ | Gauge Reading: 0 % |
| Sludge Thick. Transfer Pump (P-350) | ✓ | |
| Sludge Holding Tank (T-351) | ✓ | Level: ~ 45 % |
| Sludge Holding Tank (T-352) | ✓ | Level: 48 % |
| Decant Transfer Pump (P-352) | ✓ | CV 59 % @ 0.5 gpm |
| Filter Press Pumps (P-381 / P-382) | ✓ | |
| Filter Press | ✓ | Stage: Full |

# ABLE 3.19.1
# STANDARD OPERATIONS CHECKLIST
# MAIN WTP

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, December 23, 2021

**Inspection Performed by:** Mike Gelwick

### H. ION EXCHANGE

| Item | Status | Comments |
|---|---|---|
| Feed Tank (T-113) | ✓ Level: 30 % | |
| Feed Pump (P-114) | ✓ Operating Press: 29.1 psi | CV@ 71 % @ 2.0 gpm |
| Retention Tank (T-114) | ✓ Operating Press: 29 psi | pH-113 @ 3.65 |
| Bag Filter (BF-113) | ✓ Operating Press: 31 psi | |
| Ion Exchange (Cage (1) or 2) + Guard | ✓ Operating Press: 28 psi | TP-173A-2 → TP-175A/4 canisters + Guard |
| Post Ion Exchange | ✓ Operating Press: 3.5 psi | |

### I. FEED SURGE TANK

| Item | Status | Comments |
|---|---|---|
| Feed Surge Tank (T-520) | ✓ Level: 38 % | Last Cleaning (As Needed, if 4" of solids accumulate): 12/15/19 |
| Feed Surge Pump (P-521 or P-522) | Operating Press: 26 psi | CV@ 79 % @ 32.8 gpm |
| T-520 to GAC Total (FT-675) | 254180282 gal | Time: 1005 |
| North End On-Site Pumping | Operating Press: 2-3 psi | 12.2 gpm @ 0939 |
| North End Off-Site Pumping | Operating Press: 2-8 psi | 9.0 gpm @ 0939 |
| Peroxide Feed Pump (P-680) | ✓ | SPD 2.5 % / RATE 0.7 |
| Peroxide Conc. At (TP-710) | 1.0 PPM | |
| Peroxide Conc. At (TP-740) | 0.0 PPM | |

### J. HAZARDOUS WASTE STORAGE

| Item | Status | Comments |
|---|---|---|
| 180 Day storage area check | ✓ | Check sheet completed: NA/Empty |
| Satellite Haz. Waste Areas (BLDG #1) | ✓ | Condition: Inventory Mark Good |
| Satellite Haz. Waste Area (BLDG #2) | ✓ | Condition: Good |

### K. UV-OXIDATION SYSTEM

| Item | Status | Comments |
|---|---|---|
| UV-Oxidation System | ✓ | |
| Annual Test Run (Calgon) | Date: 9-16-21 | Next: 9-2022 |
| Quarterly Test Run | Date: NA/Running | Next: NA/Running |
| Peroxide Feed Pump (P-650) | ✓ | Flow Rate: ~7.2 cc/min. |
| UV-Ox Power | ✓ | 25.7 kVA 2552 Volts 10.1 Amps |
| Lamp Hours | 1342 Hrs | |
| Crystal Condition & Wiper Status | ✓ | Oiler status: ok |
| UV-OX Bagfilters Status | Last change: 9-13-21 Cleaned: 9-13-21 | 9.5 psi In 10.0 psi Out |
| UV-OX Feed Pump ( P-600 or (P-601) ) | ✓ | CV@ 66 % @ 7.5 gpm |
| UV-OX Temperature | In(TT-670): 13.3 °C | Out(TT-710): 25.8 °C |
| PDU GAC (PDT-710) | ✓ | Δ Pressure: 1 psi |
| Peroxide Concentration Pre UV | 100 PPM | |
| Peroxide Concentration Post UV(TP-720) | 25 PPM | |
| Peroxide Conc. Post PDU (TP-730) | 0.0 PPM | |
| Secondary Acid Feed Pump (P-630) | ✓ | CV @ 2 % |
| Secondary Acid Retention Tank (T-645) | ✓ | |
| Pre – UV Oxidizer Total (FT-670) | 20724672 gal | Time: 1005 |
| Post UV-Ox / Pre PDU | ✓ | Pressure: 13 psi |
| Post PDU | ✓ | Pressure: 7.5 psi |

# ABLE 3.19.1
# STANDARD OPERATIONS CHECKLIST
# MAIN WTP

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, December 23, 2021

**Inspection Performed by:** Mike Gelwick

### L. PDU AND LIQUID –PHASE GRANULAR ACTIVATED CARBON

| Item | Status | Comments |
|---|---|---|
| PDT-720 | ✓ | Δ Pressure: 13 psi |
| PDT-730 | ✓ | Δ Pressure: 8 psi |

### M. EFFLUENT DISCHARGE

| Item | Status | Comments |
|---|---|---|
| Effluent Surge Pump ((P751) or P752 ) | ✓ | CV@ 54.8 % |
| Effluent Surge Tank (T-740) | ✓ | Level: 40 % |
| Effluent Discharge Rate (FT-770) | ✓ | 32.8 gpm @ 0942 |
| POTW Line Pressure (PT-770) | ✓ | 32.3 psi |
| Effluent Totalizer Reading (FT-770) | 248323692 gal | Time: 1006 |
| POTW MH17S-078 Discharge Check (Monthly) | ✓ | Last Done: 12-13-21 |
| 4X8-Inch POTW Leak Detection Checks (Monthly) | ✓ | Last Done: 12-13-21 |
| 4X8-Inch POTW Air Reliefs Checks (Monthly) | ✓ | Last Done: 12-13-21 |
| 4X8-Inch POTW Isolation Valves Exercise (Qtrly) | ✓ | Last Done: 11-8-21 |
| 2-Inch POTW Backup Pressure Testing (Annual) | ✓ | Last Done: 7/8/21 |
| 2-In POTW Backup Air Reliefs Checks (Annual) | ✓ | Last Done: 7/8/21 |
| 2-Inch POTW Isolation Valve Exercise (Annual) | ✓ | Last Done: 7/8/21 |
| Rotate Chiller Compressors | NA on Standby | ~~Now in Lead: 1 or 2~~ |

### N. LEL EFFLUENT TANK T-740

| Item | Status | Comments |
|---|---|---|
| LEL-740 Sensor | ✓ | Reading: 0 % |
| LEL Sensor Calibration / Automatic High LEL Shutdown Test (monthly) ✓ | Last Completed: 12-23-21 | Plant Effluent Suspended: 1401 ↔ 1425 |
| LEL Sensor Bridge Adjustment to 2.0 volts | Reading: 2.001 volts(monthly) | Adjustment Needed: Y or (N) |
| Verify Bridge Current between.300v-.360v | Reading: 0.330volts(monthly) | |

### O. WTP INFLUENT TOTALIZERS Time : 1006 → 1011

| Source | Reading(Gallons) | Source | Reading(Gallons) |
|---|---|---|---|
| (FT-015) RWST Influent | 19746631 | (FT-505) LFG Cond. to T-530 | 219394 |
| (FT-025) NBBW Influent | 94569420 | (FT-056) Off - Site N. End Influent | 43854456 |
| (FT-012) MW-38 Inf. to HMR-30 | 8419560 | (FT-113) Ion Exchange Influent | 994118 |
| (FT-042 HMR30) MW-38 Source to HMR-30 | 35484 | (FT-810) Plant Potable Water In | 30071596 |
| (FT-043) MW-38 to RWST | 30845543 | (FT-026) NBBW Bypass to RWST | 4424951 |
| (FT-042 RWST) MW-38 Source to RWST | 72236 | (FT-014) Misc. Water to RWST | 8207590 |
| (FT-012T) MW-38 to T-540/541 | 8646109 | (FT-035) NTES Inf. to BIO | 6701517 |
| (FT-040T) MW-38N to T-540/541 | 1978498 | (FT-035T) NTES to T-530 | 465933 |
| (FT-041T) MW-38S to T-540/541 | 2696658 | (FT-017) BIO Inf. from T-530 | 659180 |
| (FT-042T) MW-38 Source to T-540/541 | 4042952 | (FT-018) T-540/541 Influent | 8686270 |
| (FT-055) On - Site N. End Influent | 99197171 | (FT-352) T-352 to HMR-30 | 1317208 |

# ABLE 3.19.1
# STANDARD OPERATIONS CHECKLIST
# MAIN WTP

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, December 23, 2021

**Inspection Performed by:** Mike Gelwick

### P. AIR COMPRESSORS

| Item | Status | Comments |
|---|---|---|
| Compressor Intake Temp. | 75 °F (Analog Gauge) | Outside Temp.: ~ 45 °F |
| Compressor Building Vent | ✓ | Open - Operational |
| Primary Air Compressor (IRN30H) | 2,000 Hour service date: 7-8-21 Serviced @ 60952 Hours | Coolant present in sight glass: (Y) / N Next service @ 62952 Hours Current Hours @ 62376 |
| IRN30H Motor Speed | 73 % | |
| IRN30H Pressure | 115 psi | |
| IRN30H Moisture purge valve chk(Weekly): | ✓ | |
| IRN30H Intake Filter | ✓ | Date Last Changed: 9-30-21 |
| Air Tanks Moisture Purge Valves | Manually Activate(weekly) ✓ | Excessive Moisture: Y / (N) |
| Backup Air Compressors (T-30 East and West) | ✓ | Both cool to touch: (Y) / N |
| Air Dryer | ✓ Eco on | Moisture at Receiver Tank: Y / (N) |
| Oil Moisture Prevention (Monthly) | Last Done: 12-23-21 - Today | Run at max speed by bleeding air from filter canister above/after air dryer for 2 hrs |
| Air Receiver Tank | ✓ | 110 psi |

### Q. SUMPS

| Item | Status | Comments |
|---|---|---|
| Bag Filter Sump | ✓ | |
| Wet Well Sump | ✓ | |

### R. GAS CHROMATOGRAPH

| Item | Status | Comments |
|---|---|---|
| GC Operational | ✓ | GC # checking UV-Ox Effluent: #1 |
| Alarms Enabled | ✓ | CC-Calibration + maint 12-22-21 |
| GC Influent Filters | ✓ | |

### S. SAFETY

| Item | Status | Comments |
|---|---|---|
| Building #1 Fire Extinguishers | ✓ | Date inspected: 12-22-21 |
| Building #1 Eye Wash/Shower | ✓ | Checked and Flushed- All OK: (Y) / N |

**Other Comments:**

| |
|---|
| |
| |
| |
| |
| |

# TABLE 3.19.2
# STANDARD OPERATIONS CHECKLIST
# BIOLOGICAL TREATMENT SYSTEM

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, December 23, 2021

**Inspection Performed by:** Mike Gelwick

## A. PUMPS

| Item | Status | Flow Rate (gpm) | Pump Speed (CV%) | Discharge Pressure (psi) | Comments |
|---|---|---|---|---|---|
| **T-510 Pumps** | | | | | |
| P-3301 | ✓ | 2.50 | 39.2 % | 8.0 | |
| P-3301A | SB | – | – % | – | |
| **NTES Pump** P-002(Sump) / (P-002W(10R)) | ✓ | 0.53 | 48 % | P035 34-35 / P038 8.0 | Globules Observed at TP-130: Y / (N) Time: 0915 |
| **T-530** P-005 | SB | – | – % | – | |
| **T-540/541** P-006 | ✓ | 0.20 | 64 % | 7.5 | |
| **LFG COND Auto-Traps** | ✓ | 0.0 | NA | 9.0 | Between Cycles: (Y) / N |
| **Reactor Feed Pumps** | | | | | |
| P-3321 | ✓ | 2.50 | 43.1 % | 5.5 | |
| P-3322 | ✓ | 3.37 | 41.1 % | 5.0 | |
| P-3323 | ✓ | 2.52 | 60.1 % | 5.5 | |
| P-3324 | SB | – | – % | – | |
| **Reactor Effluent Pumps** | | | | | |
| P-3341 | ✓ | 2.02 | 48.3 % | 10.0 | |
| P-3341A | SB | – | – % | – | |

## B. BLOWERS

| Item | Status | Pressure (psi) | Temp (°F) | Next Scheduled Service (Qtrly) | Comments Last serviced on: 12-20-21 |
|---|---|---|---|---|---|
| B-3331 | ✓ | 4.18 | 126 | 3-2022 | Greased, Belt and Filter Checked: (Y) / N |
| B-3332 | SB | – | – | ↓ | Belt and Filter Checked: (Y) / [illegible] |
| B-3333 | ✓ | 4.62 | 142 | ↓ | Greased, Belt and Filter Checked: (Y) / N |
| B-3334 | ✓ | 4.21 | 124 | ↓ | Greased, Belt and Filter Checked: (Y) / N |

## C. REACTOR VENTILATION

| Item | Status | Comments |
|---|---|---|
| Vapor Carbon Contactor | ✓ | On-line: 2/10/18 |
| Reactor Vent Blower | ✓ | |
| Reactor Vent Booster | ✓ | |
| VTP-3350 | ✓ | PID Reading: 25.4 PPM |
| VTP-3360 | ✓ | PID Reading: 17.3 PPM |

# TABLE 3.19.2
# STANDARD OPERATIONS CHECKLIST
# BIOLOGICAL TREATMENT SYSTEM

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, December 23, 2021

**Inspection Performed by:** Mike Gelwick

## D. TANKS / REACTORS / SUMPS / CONTAINMENTS / PIPING / Chiller

| Item | Status | Comments |
|---|---|---|
| T-510 Post HMR-30 Mixing Tank | ✓ Level: 70 % | Last Cleaning (As needed, if 2" of solids accumulate): 7/14/21 |
| T-530 LFG Condensate / NTES Tank | ✓ Level: 30 % | |
| T-530 Mixer | ✓ | |
| LFG Condensate Conveyance Line | ✓ | Last Pressure Test: 7-19-21 Next: ?-2022 (Annual at a minimum or if flow drops off) |
| T-540/541 MW38 Tanks | Lvls: 81 % & 82% | |
| T-540/541 Mixers | ✓ Both New 12-15-21 | |
| Chiller | ✓ | Chiller Coolant Lvl: ~ — " Below full mark |
| Chiller Cooling Fins (as needed) | ✓ | Last Cleaning: 4/20/18 (unit on Standby) |
| Secondary Containments | ✓ | Heat Trace: (On OK) / Off Warm out |
| Feed Piping to Sedimentation Tank | ✓ | Last Back Flushing (Quarterly): 12-22-21 |
| T-3310 Sedimentation Tank | Visual Level: ok | Last Cleaning (As Needed, use TSS info to determine): 9/2021 |
| T-3320 Blend Tank | ✓ Level: 71 % | Last Cleaning (Semi Annual): 9-10-21 |
| T-3331 Reactor No. 1 | ✓ | Digital Displays: (GOOD) / Needs Attn |
| T-3332 Reactor No. 2 | ✓ | Digital Displays: (GOOD) / Needs Attn |
| T-3333 Reactor No. 3 | ✓ | Digital Displays: (GOOD) / Needs Attn |
| T-3334 Settling Tank | ✓ | Last Cleaning (Semi Annual): 9-10-21 |
| P-3334 Biosolids Pump | ✓ | |
| T-3340 Overflow Tank | ✓ Level: 31 % | |
| Recycle Valve to Blend Tank | ✓ | 3.99 gpm @ 1024 |
| Building Containment Sump | ✓ | Last Alarm Test Date (Monthly): 12-16-21 |

## E. CHEMICAL FEED SYSTEM

| Item | Status | Comments |
|---|---|---|
| Phosphorous Supply | ✓ | Bags: 14.5 Gallons: ~ 75 |
| Phosphorous Pump (P-2221) | ✓ | |
| Caustic Supply | ✓ | ~ 225 Gallons |
| Caustic Pump (P-2211) | SB | Currently in acid addition mode |
| Acid Supply | ✓ | ~ 40 Gallons |
| Acid Pump (P-2211) | ✓ | |
| Caustic Pump (P-2231) | ✓ Leaks: Y / (N) | Last tubing tip cleaning (monthly): 12-16-21 |
| Caustic Pump (P-2232) | ✓ Leaks: Y / (N) | Last tubing tip cleaning (monthly): ↓ |
| Caustic Pump (P-2233) | ✓ Leaks: Y / (N) | Last tubing tip cleaning (monthly): ↓ |

# TABLE 3.19.2
# STANDARD OPERATIONS CHECKLIST
# BIOLOGICAL TREATMENT SYSTEM

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, December 23, 2021

**Inspection Performed by:** Mike Gelwick

## F. pH Probes

| pH Probe Location | Calibration Date (Monthly) | Comments |
|---|---|---|
| pH-3320 Blend Tank | 12-23-21 - today | New 4+10 pH stds today |
| pH-3331 Reactor 1 | ↓ | ↓ |
| pH-3332 Reactor 2 | | |
| pH-3333 Reactor 3 | | |

## G. FILTER SYSTEM

| Item | Status | Comments |
|---|---|---|
| BF-3340 a/b Status | ✓ | |
| Automatic Backwash | Cycle Count: 19 | reset |
| BF-3340 a/b Differential Pressure | PSI: 2 | 15/13 @ 3.1 gpm |
| 75-micron Bags Last Cleaning | Date: 11-14-21 | |
| 75-micron Bags Last Inspection | Date: ↓ | |
| 75-micron Bags Last Changed | Date: | |
| GACF-3340 Status | ✓ | |
| GACF-3340 Differential Pressure | PSI: 6.5 | 13/6.5 @ 3.1 gpm |
| Last Backwash Performed | Date: 9-27-21 | |

## H. ELECTRICAL AND INSTRUMENTATION

| Item | Status | Comments on this month |
|---|---|---|
| "BIO" Backup Generator | ✓ | Block Heater: On OK / (Off Warm Out) |
| Electrical Surge Suppressor | ✓ | |
| Motor Control Center | ✓ | |
| PLC | ✓ | UPS @ 97 min / 95 Events |
| HMI's | ✓ | |
| BTS Process KWH Meter | 1828902 KWH | Time: 1137 |
| Building#2 KWH Meter | 5286776 KWH | Time: 1137 |

## I. GAS CHROMATOGRAPHY

| Item | Status | Comments |
|---|---|---|
| GC Operational | ✓ | GC # checking BIO: #2 |
| Alarms Enabled | ✓ | CC-Calibration + Maint 12-22-21 |
| GC Influent Filters | ✓ | |

# TABLE 3.19.2
# STANDARD OPERATIONS CHECKLIST
# BIOLOGICAL TREATMENT SYSTEM

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Thursday, December 23, 2021

**Inspection Performed by:** Mike Gelwick

## J. TOTALIZERS

| Item | Readings (gallons) | Comments |
|---|---|---|
| FT-3321 Feed to Reactor 1 | 6187673 | |
| FT-3324 Feed Spare | 122754 | |
| FT-3322 Feed to Reactor 2 | 11009804 | |
| FT-3323 Feed to Reactor 3 | 872689 | |
| FT-3301 T-510 to BIO | 51688324 | |
| FT-3341 BIO Effluent | 66566441 | |
| FT-3342 BIO Recycle | 55875303 | |

## K. SAFETY

| Item | Status | Comments |
|---|---|---|
| Building #2 Fire Extinguishers | ✓ | Inspection date: 12-22-21 |
| Building #2 Eye Wash/Shower | ✓ | Checked and Flushed- All OK: Ⓨ / N |

## L. OTHER COMMENTS:

| |
|---|
| |
| |
| |
| |

# ABLE 3.19.1
# STANDARD OPERATIONS CHECKLIST
# MAIN WTP

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Monday, December 27, 2021

**Inspection Performed by:** Mike Gelwick

## A. PERIMETER COLLECTION SYSTEMS

| Item | Status | Comments |
|---|---|---|
| LFG Cond Automatic Trap CT-1 | Sump Level: 12.62 | Counter: 192109 Cycles: 391 |
| LFG Cond Automatic Trap CT-2 | Sump Level: 8.63 | Counter: 274603 Cycles: 12 |
| LFG Cond Automatic Trap CT-3 | Sump Level: 7.30 ok | Counter: 317723 Cycles: 946 |
| CT-4 Containment/Vessel (LFG Cond) | ✓ Level: 78 % | Tank Level: 2.02 Counter: 191259 Cycles: 2 Sump: 7.73 |
| PM-15 Containment / Vessel | ✓ Level: 40 % | |
| MW-51 Containment / Vessel | ✓ Level: 60 % | |
| PM-11 Containment / Vessel | ✓ Level: 65 % | |
| MW-38 Systems | ✓ | |
| North Toe System | ✓ | |
| North End Systems (Weekly) | ✓ | |
| Full N. End Systems Check (Monthly) | ✓ | Last Done: 12-22-21 |
| North End Pipeline(s)Flushing (As Needed) | ✓ | Perform if suspended solids present Last Done: 11/15/15 |
| NTES line flush to T-530 (As needed) | ✓ | Perform if suspended solids present Last Done: 10/29/21 |
| NTES Piping Containment | ✓ | Monthly Sump Level: Dry 016.07' Date: 12-16-21 |
| North Boundary System P-001: | CV 73.8 % @ 6.5 gpm | 60.71 Hz / 2.08 Amps. / vault psi @ 18/Nolcans |
| T-101 & T-102 Containment / Tank | ✓ | Levels: 27 % & 26 % |
| Raw Water Storage Tanks Piping | ✓ | |
| RWST Building Temp. (TT-101) | 54.9 °F | Outside Temp.: ~ 39 °F |
| (P-121) or P-122 | ✓ | 0.60 gpm / CV 58 % |
| RWST 2ndry Cont. High Level Switch | ✓ | (LSH-101) Last Test(monthly): 12-16-21 |
| RWST Back-Up Generator | ✓ | Last Test Run(monthly): 12-16-21 |

## B. CHEMICAL STORAGE BAYS

| Item | Status | Comments |
|---|---|---|
| Caustic Tote Levels | ✓ | ~ 475 Gallons Reserve = 1 tote |
| Caustic Bay Heater | ✓ | |
| Peroxide Tote Level | ✓ | ~ 300 Gallons Reserve = 55 gal |
| HCL Tote Levels | ✓ | ~ 75 Gallons Reserve = ~30 gal |
| Chemical Totes and Piping Inspected | ✓ | Leaks observed: Y / (N) |
| Emergency Shower Inspected | ✓ | Checked and Flushed - All OK: (Y) / N |

## C. PRIMARY AND SECONDARY ACID FEED SYSTEM

| Item | Status | Comments |
|---|---|---|
| Primary Acid Feed Pump (P-631) | ✓ | |
| Ion Exchange Acid Feed Pump (P-632) | ✓ | PI-0632 PSI: 86-90 CV: 4 % |
| Primary Acid Retention Tank (T-510) | ✓ | |
| All Acid Feed Lines | ✓ | Leaks observed: Y / (N) |

## D. NBBW INJECTION TRENCH

| Item | Status | Comments |
|---|---|---|
| Injection Carbon (GAC-810) | OFFLINE | Date online: 7/20/18 |
| Injection Rate (FT-800) | 0.0 gpm | NBBW-IW-1= 0.0 NBBW-IW-2= 0.0 NBBW-IW-3= 0.0 gpm ea. |
| Totalizer Reading (FT-800) | 105,135,774 gal | INJ. STOPPED 10/02/18 @ 1545 |

# ABLE 3.19.1
# STANDARD OPERATIONS CHECKLIST
# MAIN WTP

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Monday, December 27, 2021

**Inspection Performed by:** Mike Gelwick

### E. CHEMICAL PRECIPITATION SYSTEM (US FILTER HMR-30)

| Item | Status | Comment |
|---|---|---|
| T-300A Mixer | NA | |
| T-300B (Caustic Mixer) | ✓ | Last Cleaning (Qtrly): 10-20-21 |
| T-300A/B Water Level | ✓ | |
| T-300B (Caustic Mix Chamber) | ✓ | Last Cleaning (Qtrly): 10-20-21 |
| T-300A/B Overflow | ✓ | |
| pH Set-point for (pH 315) | Value: 10.8 | |
| pH 310 | Value: 6.65 | |
| pH 315 | Value: 10.92 | |
| Flocculation Chamber Paddle Wheel | ✓ | |
| Precipitate Floc Quality | ✓ | Good |
| Clarifier Water Quality | ✓ | Good Oil or sheen observed: Y / (N) |
| Clarifier Effluent Piping / Water Level | ✓ | |
| Clear-well Chamber and Water Level | ✓ | |
| HMR PLC Panel | ✓ | |
| Caustic Pump (P-270) | SB | |
| Caustic Pump (P-280) | ✓ | |
| Polymer Pump (P-310) | ✓ | |
| Polymer Tank Mixer | ✓ | |
| Polymer Tank Level | Gallons: ~ 475 | |
| Clear-well Transfer Pumps(P-371)/ 372) | ✓ | |
| Sludge Transfer Pump (P-330) | ✓ | Exercise Valves Weekly: Both OK |
| Manual Sludge Lateral pumping | ✓ | Last done (As Needed): #3-7-20-21 / #1+2-3-20-21 |
| Manual Sludge Lateral Ball Valves | ✓ | Exercise Weekly: All OK |
| Automatic Blow-down Operations | ✓ | |

### F. pH PROBES

| pH Probe Location | Calibration Date | Comments: (Time done) |
|---|---|---|
| pH-310 HMR-30 (T-300A) | 12-27-21 – Today | 1400 |
| pH-315 HMR-30 (T-300B) | | |
| pH-365 Primary Acid Ret. Tank | | |
| pH-113 Pre-Ion Exchange | | |
| pH-670 Pre-UV-OX | | 1445 |
| pH-740 Discharge Surge Tank | | Discharge suspended: 1351 ↔ 1359 |
| Out of Hold Double Check | ---------- | None in hold: ✓✓ |
| Valves Back to Normal Position | ---------- | All OK: ✓✓ |

### G. SLUDGE THICKENER, SLUDGE HOLDING TANKS, FILTER PRESS

| Item | Status | Comments |
|---|---|---|
| Verify Sludge Thickener Running | ✓ | Gauge Reading: 0 % |
| Sludge Thick. Transfer Pump (P-350) | ✓ | |
| Sludge Holding Tank (T-351) | ✓ | Level:~ 45 % |
| Sludge Holding Tank (T-352) | ✓ | Level: 40 % |
| Decant Transfer Pump (P-352) | ✓ | CV 64 % @ 0.5 gpm |
| Filter Press Pumps (P-381 / P-382) | ✓ | |
| Filter Press | ✓ | Stage: Full |

# ABLE 3.19.1
# STANDARD OPERATIONS CHECKLIST
# MAIN WTP

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Monday, December 27, 2021

**Inspection Performed by:** Mike Gelwick

### H. ION EXCHANGE

| Item | Status | Comments |
|---|---|---|
| Feed Tank (T-113) | ✓ Level: 30 % | |
| Feed Pump (P-114) | ✓ Operating Press: 28.5 psi | CV@ 70 % @ 2.0 gpm |
| Retention Tank (T-114) | ✓ Operating Press: 28 psi | pH-113 @ 3.82 |
| Bag Filter (BF-113) | ✓ Operating Press: 30 psi | |
| Ion Exchange (Cage (1) or 2) + Guard | ✓ Operating Press: 27 psi | TP-173A-2 → TP-175A/4 canisters + Guard |
| Post Ion Exchange | ✓ Operating Press: 3.5 psi | |

### I. FEED SURGE TANK

| Item | Status | Comments |
|---|---|---|
| Feed Surge Tank (T-520) | ✓ Level: 38 % | Last Cleaning (As Needed, if 4" of solids accumulate): 12/15/19 |
| Feed Surge Pump (P-521) or P-522) | Operating Press: 26 psi | CV@ 78 % @ 31.8 gpm |
| T-520 to GAC Total (FT-675) | 2543677241 gal | Time: 1109 |
| North End On-Site Pumping | Operating Press: 2-3 psi | 11.9 gpm @ 1104 |
| North End Off-Site Pumping | Operating Press: 2-6 psi | 8.4 gpm @ 1104 |
| Peroxide Feed Pump (P-680) | ✓ | SPD 2.4 % / RATE 0.6 |
| Peroxide Conc. At (TP-710) | 1.0 PPM | |
| Peroxide Conc. At (TP-740) | 0.0 PPM | |

### J. HAZARDOUS WASTE STORAGE

| Item | Status | Comments |
|---|---|---|
| 180 Day storage area check | ✓ | Check sheet completed: NA/Empty |
| Satellite Haz. Waste Areas (BLDG #1) | ✓ | Condition: IX Resin + main Good |
| Satellite Haz. Waste Area (BLDG #2) | ✓ | Condition: Good |

### K. UV-OXIDATION SYSTEM

| Item | Status | Comments |
|---|---|---|
| UV-Oxidation System | ✓ | |
| Annual Test Run (Calgon) | Date: 9-16-21 | Next: 9-2022 |
| Quarterly Test Run | Date: NA/Running | Next: NA/Running |
| Peroxide Feed Pump (P-650) | ✓ | Flow Rate: ~ 7.2 cc/min. |
| UV-Ox Power | ✓ | 25.7 kVA 253 Volts 10.1 Amps |
| Lamp Hours | 1439 Hrs | |
| Crystal Condition & Wiper Status | ✓ | Oiler status: ok |
| UV-OX Bagfilters Status | Last change: 7-13-21 Cleaned: 7-13-21 | 11.0 psi In 11.0 psi Out |
| UV-OX Feed Pump ( P-600 or (P-601) ) | ✓ | CV@ 70 % @ 7.5 gpm |
| UV-OX Temperature | In(TT-670): 13.4 °C | Out(TT-710): 26.0 °C |
| PDU GAC (PDT-710) | ✓ | Δ Pressure: 3 psi |
| Peroxide Concentration Pre UV | 100 PPM | |
| Peroxide Concentration Post UV(TP-720) | 25 PPM | |
| Peroxide Conc. Post PDU (TP-730) | 0.0 PPM | |
| Secondary Acid Feed Pump (P-630) | ✓ | CV @ 0 % |
| Secondary Acid Retention Tank (T-645) | ✓ | |
| Pre – UV Oxidizer Total (FT-670) | 20766802 gal | Time: 1109 |
| Post UV-Ox / Pre PDU | ✓ | Pressure: 14 psi |
| Post PDU | ✓ | Pressure: 7.5 psi |

# ABLE 3.19.1
# STANDARD OPERATIONS CHECKLIST
# MAIN WTP

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Monday, December 27, 2021

**Inspection Performed by:** Mike Gelwick

### L. PDU AND LIQUID –PHASE GRANULAR ACTIVATED CARBON

| Item | Status | Comments |
|---|---|---|
| PDT-720 | ✓ | Δ Pressure: 13 psi |
| PDT-730 | ✓ | Δ Pressure: 8 psi |

### M. EFFLUENT DISCHARGE

| Item | Status | Comments |
|---|---|---|
| Effluent Surge Pump ( (P751) or P752 ) | ✓ | CV@ 54.2 % |
| Effluent Surge Tank (T-740) | ✓ | Level: 40 % |
| Effluent Discharge Rate (FT-770) | ✓ | 31.7 gpm @ 1107 |
| POTW Line Pressure (PT-770) | ✓ | 32.0 psi |
| Effluent Totalizer Reading (FT-770) | 248511912 gal | Time: 1110 |
| POTW MH17S-078 Discharge Check (Monthly) | ✓ | Last Done: 12-13-21 |
| 4X8-Inch POTW Leak Detection Checks (Monthly) | ✓ | Last Done: ↓ |
| 4X8-Inch POTW Air Reliefs Checks (Monthly) | ✓ | Last Done: ↓ |
| 4X8-Inch POTW Isolation Valves Exercise (Qtrly) | ✓ | Last Done: 11-8-21 |
| 2-Inch POTW Backup Pressure Testing (Annual) | ✓ | Last Done: 7/8/21 |
| 2-In POTW Backup Air Reliefs Checks (Annual) | ✓ | Last Done: 7/8/21 |
| 2-Inch POTW Isolation Valve Exercise (Annual) | ✓ | Last Done: 7/8/21 |
| Rotate Chiller Compressors | NA on Standby | ~~Now in Lead: 1 or 2~~ |

### N. LEL EFFLUENT TANK T-740

| Item | Status | Comments |
|---|---|---|
| LEL-740 Sensor | ✓ | Reading: 0 % |
| LEL Sensor Calibration / Automatic High LEL Shutdown Test (monthly) | Last Completed: 12-23-21 | Plant Effluent Suspended: 1401 ↔ 1425 |
| LEL Sensor Bridge Adjustment to 2.0 volts | Reading: 2.001 volts(monthly) | Adjustment Needed: Y or (N) |
| Verify Bridge Current between.300v-.360v | Reading: 0.330 volts(monthly) | |

### O. WTP INFLUENT TOTALIZERS Time : 1110→1114

| Source | Reading(Gallons) | Source | Reading(Gallons) |
|---|---|---|---|
| (FT-015) RWST Influent | 19751732 | (FT-505) LFG Cond. to T-530 | 219428 |
| (FT-025) NBBW Influent | 94606624 | (FT-056) Off - Site N. End Influent | 43904060 |
| (FT-012) MW-38 Inf. to HMR-30 | 8430041 | (FT-113) Ion Exchange Influent | 1005498 |
| (FT-042 HMR30) MW-38 Source to HMR-30 | 35484 | (FT-810) Plant Potable Water In | 30071622 |
| (FT-043) MW-38 to RWST | 3084732 | (FT-026) NBBW Bypass to RWST | 4425737 |
| (FT-042 RWST) MW-38 Source to RWST | 72236 | (FT-014) Misc. Water to RWST | 8207590 |
| (FT-012T) MW-38 to T-540/541 | 8646830 | (FT-035) NTES Inf. to BIO | 6704476 |
| (FT-040T) MW-38N to T-540/541 | 1978778 | (FT-035T) NTES to T-530 | 466018 |
| (FT-041T) MW-38S to T-540/541 | 2697029 | (FT-017) BIO Inf. from T-530 | 659180 |
| (FT-042T) MW-38 Source to T-540/541 | 4043007 | (FT-018) T-540/541 Influent | 8687421 |
| (FT-055) On - Site N. End Influent | 99267215 | (FT-352) T-352 to HMR-30 | 1318966 |

# ABLE 3.19.1
# STANDARD OPERATIONS CHECKLIST
# MAIN WTP

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Monday, December 27, 2021

**Inspection Performed by:** Mike Gelwick

### P. AIR COMPRESSORS

| Item | Status | Comments |
|---|---|---|
| Compressor Intake Temp. | 64 °F (Analog Gauge) | Outside Temp.: ~ 42 °F |
| Compressor Building Vent | ✓ | closed/operational |
| Primary Air Compressor (IRN30H) | 2,000 Hour service date: 7-8-21<br>Serviced @ 60952 Hours | Coolant present in sight glass: Ⓨ / N<br>Next service @ 62952 Hours<br>Current Hours @ 62427 |
| IRN30H Motor Speed | 31 % | |
| IRN30H Pressure | 119 psi | |
| IRN30H Moisture purge valve chk(Weekly): | ✓ | |
| IRN30H Intake Filter | ✓ | Date Last Changed: 9-30-21 |
| Air Tanks Moisture Purge Valves | Manually Activate(weekly) ✓ | Excessive Moisture: Y / Ⓝ |
| Backup Air Compressors (T-30 East and West) | ✓ | Both cool to touch: Ⓨ / N |
| Air Dryer | ✓ ECO OFF | Moisture at Receiver Tank: Y / Ⓝ |
| Oil Moisture Prevention (Monthly) | Last Done: 12-23-21 | Run at max speed by bleeding air from filter canister above/after air dryer for 2 hrs |
| Air Receiver Tank | ✓ | 110 psi |

### Q. SUMPS

| Item | Status | Comments |
|---|---|---|
| Bag Filter Sump | ✓ | |
| Wet Well Sump | ✓ | |

### R. GAS CHROMATOGRAPH

| Item | Status | Comments |
|---|---|---|
| GC Operational | ✓ | GC # checking UV-Ox Effluent: #1 |
| Alarms Enabled | ✓ | |
| GC Influent Filters | ✓ | |

### S. SAFETY

| Item | Status | Comments |
|---|---|---|
| Building #1 Fire Extinguishers | ✓ | Date inspected: 12-22-21 |
| Building #1 Eye Wash/Shower | ✓ | Checked and Flushed- All OK: Ⓨ / N |

**Other Comments:**

| |
|---|
| |
| |
| |
| |
| |

# TABLE 3.19.2
# STANDARD OPERATIONS CHECKLIST
# BIOLOGICAL TREATMENT SYSTEM

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Monday, December 27, 2021

**Inspection Performed by:** Mike Gelwick

## A. PUMPS

| Item | Status | Flow Rate (gpm) | Pump Speed (CV%) | Discharge Pressure (psi) | | Comments |
|---|---|---|---|---|---|---|
| **T-510 Pumps** | | | | | | |
| P-3301 | ✓ | 1.24 | 24.9 % | 5.5 | | |
| P-3301A | SB | – | – % | – | | |
| **NTES Pump** P-002(Sump) / (P-002W(10R)) | ✓ | 0.51 | 48 % | P035 33-34 | P038 6.0 | Globules Observed at TP-130: Y / (N) Time: 1030 |
| **T-530** P-005 | SB | – | – % | – | | |
| **T-540/541** P-006 | ✓ | 0.30 | 59 % | 7.0 | | |
| **LFG COND Auto-Traps** | ✓ | 0.0 | NA | 5 | | Between Cycles: (Y) / N |
| **Reactor Feed Pumps** | | | | | | |
| P-3321 | ✓ | 2.23 | 46.0 % | 5.5 | | |
| P-3322 | ✓ | 3.09 | 42.1 % | 5.0 | | |
| P-3323 | ✓ | 2.20 | 65.3 % | 5.0 | | |
| P-3324 | SB | – | – % | – | | |
| **Reactor Effluent Pumps** | | | | | | |
| P-3341 | ✓ | 3.21 | 59.7 % | 15.0 | | |
| P-3341A | SB | – | – % | – | | |

## B. BLOWERS

| Item | Status | Pressure (psi) | Temp (°F) | Next Scheduled Service (Qtrly) | Comments Last serviced on: 12-2021 |
|---|---|---|---|---|---|
| B-3331 | ✓ | 4.19 | 118 | 3-2022 | Greased, Belt and Filter Checked: (Y) / N |
| B-3332 | SB | – | – | ↓ | Belt and Filter Checked: Y / (N) |
| B-3333 | ✓ | 4.48 | 122 | ↓ | Greased, Belt and Filter Checked: (Y) / N |
| B-3334 | ✓ | 4.21 | 118 | ↓ | Greased, Belt and Filter Checked: (Y) / N |

## C. REACTOR VENTILATION

| Item | Status | Comments |
|---|---|---|
| Vapor Carbon Contactor | ✓ | On-line: 2/10/18 |
| Reactor Vent Blower | ✓ | |
| Reactor Vent Booster | ✓ | |
| VTP-3350 | ✓ | PID Reading: 31.6 PPM |
| VTP-3360 | ✓ | PID Reading: 28.2 PPM |

# TABLE 3.19.2
# STANDARD OPERATIONS CHECKLIST
# BIOLOGICAL TREATMENT SYSTEM

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Monday, December 27, 2021

**Inspection Performed by:** Mike Gelwick

## D. TANKS / REACTORS / SUMPS / CONTAINMENTS / PIPING / Chiller

| Item | Status | Comments |
|---|---|---|
| T-510 Post HMR-30 Mixing Tank | ✓ Level: 68 % | Last Cleaning (As needed, if 2" of solids accumulate): 7/14/21 |
| T-530 LFG Condensate / NTES Tank | ✓ Level: 32 % | |
| T-530 Mixer | ✓ | |
| LFG Condensate Conveyance Line | ✓ | Last Pressure Test: 7-19-21 Next: 7-2022 (Annual at a minimum or if flow drops off) |
| T-540/541 MW38 Tanks | Lvls: 78 % & 79 % | |
| T-540/541 Mixers | ✓ | both new 12-15-21 |
| Chiller | ✓ | Chiller Coolant Lvl: ~ — " Below full mark |
| Chiller Cooling Fins (as needed) | ✓ | Last Cleaning: 4/20/18 (unit on Standby) |
| Secondary Containments | ✓ | Heat Trace: (On OK) / Off Warm out |
| Feed Piping to Sedimentation Tank | ✓ | Last Back Flushing (Quarterly): 12-22-21 |
| T-3310 Sedimentation Tank | Visual Level: ok | Last Cleaning (As Needed, use TSS info to determine): 9/2021 |
| T-3320 Blend Tank | ✓ Level: 70 % | Last Cleaning (Semi Annual): 9-10-21 |
| T-3331 Reactor No. 1 | ✓ | Digital Displays: (GOOD) / Needs Attn |
| T-3332 Reactor No. 2 | ✓ | Digital Displays: (GOOD) / Needs Attn |
| T-3333 Reactor No. 3 | ✓ | Digital Displays: (GOOD) / Needs Attn |
| T-3334 Settling Tank | ✓ | Last Cleaning (Semi Annual): 9-10-21 |
| P-3334 Biosolids Pump | ✓ | |
| T-3340 Overflow Tank | ✓ Level: 30 % | |
| Recycle Valve to Blend Tank | ✓ | 4.00 gpm @ 1131 |
| Building Containment Sump | ✓ | Last Alarm Test Date (Monthly): 12-16-21 |

## E. CHEMICAL FEED SYSTEM

| Item | Status | Comments |
|---|---|---|
| Phosphorous Supply | ✓ | Bags: 14.25 Gallons: ~55 |
| Phosphorous Pump (P-2221) | ✓ | |
| Caustic Supply | ✓ | ~ 220 Gallons |
| Caustic Pump (P-2211) | SB | Currently in acid addition mode |
| Acid Supply | ✓ | ~ 40 Gallons |
| Acid Pump (P-2211) | ✓ | |
| Caustic Pump (P-2231) | ✓ Leaks: Y / (N) | Last tubing tip cleaning (monthly): 12-16-21 |
| Caustic Pump (P-2232) | ✓ Leaks: Y / (N) | Last tubing tip cleaning (monthly): |
| Caustic Pump (P-2233) | ✓ Leaks: Y / (N) | Last tubing tip cleaning (monthly): |

# TABLE 3.19.2
# STANDARD OPERATIONS CHECKLIST
# BIOLOGICAL TREATMENT SYSTEM

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Monday, December 27, 2021

**Inspection Performed by:** Mike Gelwick

## F. pH Probes

| pH Probe Location | Calibration Date (Monthly) | Comments |
|---|---|---|
| pH-3320 Blend Tank | 12-23-21 | Spray off clean today |
| pH-3331 Reactor 1 | ↓ | ↓ |
| pH-3332 Reactor 2 | | |
| pH-3333 Reactor 3 | | |

## G. FILTER SYSTEM

| Item | Status | Comments |
|---|---|---|
| BF-3340 a/b Status | ✓ | |
| Automatic Backwash | Cycle Count: 5 | reset |
| BF-3340 a/b Differential Pressure | PSI: 1 | 13/12 22.2 gpm |
| 75-micron Bags Last Cleaning | Date: 11-14-21 | |
| 75-micron Bags Last Inspection | Date: ↓ | |
| 75-micron Bags Last Changed | Date: | |
| GACF-3340 Status | ✓ | |
| GACF-3340 Differential Pressure | PSI: 5.5 | 12/6.5 22.2 gpm |
| Last Backwash Performed | Date: 9-27-21 | |

## H. ELECTRICAL AND INSTRUMENTATION

| Item | Status | Comments |
|---|---|---|
| "BIO" Backup Generator | ✓ | Block Heater: (On OK) / Off Warm Out |
| Electrical Surge Suppressor | ✓ | |
| Motor Control Center | ✓ | |
| PLC | ✓ | UPS @ 97 min / 95 Events |
| HMI's | ✓ | |
| BTS Process KWH Meter | 1830310 KWH | Time: 1230 |
| Building#2 KWH Meter | 5290182 KWH | Time: 1230 |

## I. GAS CHROMATOGRAPHY

| Item | Status | Comments |
|---|---|---|
| GC Operational | ✓ | GC # checking BIO: #2 |
| Alarms Enabled | ✓ | |
| GC Influent Filters | ✓ | |

TABLE 3.19.2
# STANDARD OPERATIONS CHECKLIST
# BIOLOGICAL TREATMENT SYSTEM

## WEEKLY OPERATIONS AND MAINTENANCE INSPECTION CHECKLIST

**Inspection Date:** Monday, December 27, 2021

**Inspection Performed by:** Mike Gelwick

## J. TOTALIZERS

| Item | Readings (gallons) | Comments |
|---|---|---|
| FT-3321 Feed to Reactor 1 | 6199747 | |
| FT-3324 Feed Spare | 122754 | |
| FT-3322 Feed to Reactor 2 | 11026581 | |
| FT-3323 Feed to Reactor 3 | 884580 | |
| FT-3301 T-510 to BIO | 5169595 | |
| FT-3341 BIO Effluent | 66581597 | |
| FT-3342 BIO Recycle | 55899161 | |

## K. SAFETY

| Item | Status | Comments |
|---|---|---|
| Building #2 Fire Extinguishers | ✓ | Inspection date: 12-22-21 |
| Building #2 Eye Wash/Shower | ✓ | Checked and Flushed- All OK: Y / N |

## L. OTHER COMMENTS:

| |
|---|
| |
| |
| |
| |

# LOWRY WTP OPERATIONS LOG

Date: **Thursday, July 01, 2021**

| Time: | |
|---|---|
| 0615 | Plan operations good. Mike working on weekly systems checks and calibrations. |
| 0720 | Start filterpress on T-351 (in stage 1) |
| 1020 | - Clean PH-315 probe w/ Acid solution. Check the HACH 50 for ammonia: None observed. Starting down wash |
| | - Check TP-130 for oily globules: None observed. water 53 clear w/ yellowish green tint |
| | - Refill polymer make w/ 2 cups of NALCO polymer and 2000 gal of potable water. |
| 1315 | - Suspend Plant 03 discharge to calibrate pH-740 probe to 4+10 pH STD's. |
| 1322 | - Resume Normal 03 discharge. Continue with other pH probes calibrations to 4+10 pH STD's ⇒ pH-113, 670, 310, 315 & 365. |
| 1400 | - weekly plants systems checks and calibrations complete. Filter press full. |
| 1410 | - TP-150 molybdenum HACH value ⇒ 10 ug/L. |
| 1419 | - work on setting up and calibrating Autosamplers. Triple rinse composite containers with DI water, will add preservatives on Tuesday prior to start up. |
| 1530 | - Plants operations Good |

Influent Sources and Flow Rates: @ 0650
NBBW – 7.5 gpm
North End On Site- 12.2 gpm
North End Off-Site – 8.5 gpm
RWST – 0.6 gpm
NTES – 0.50 gpm(10R only)
MW38 T-540/541 – 0.30 gpm(Source well and 38 pumping wells mix)
MW38 N & S– 2.9 gpm
COND/NTES T-530- 0.20 gpm(6am-1pm daily)
MW113 Area – 2.0 gpm

Operator: **Mike Gelwick / Chris Carlson**

0.45" of rain Thursday P.M.

## LOWRY WTP OPERATIONS LOG

Date: Friday, July 02, 2021

| Time: | |
|---|---|
| 0500 | Plant operations good. Refill phosphorus tank with 40 gallons potable water + 1/16 TSP. |
| 0600 | TP-150 molybdenum Hach value reading 0 ug/L. Clean the HMR-30 weir and pH probe. |
| ↓ | No oil or sheen observed in the HMR-30. Check TP-130 for oil globules - none observed. |
| ↓ | Water is clear, light yellow/green. |
| 0715 | Blowdown operations working well. Plant operations good |
| 7/3/21 0645 | Check plant remotely - All okay. |
| 1905 | Check plant remotely - All okay. |

Influent Sources and Flow Rates: @0500
NBBW – 7.5 gpm
North End On Site- 13.2 gpm
North End Off-Site – 8.4 gpm
RWST – 0.6 gpm
NTES – 0.5 gpm(10R only)
MW38 T-540/541 – 0.3 gpm(Source well and 38 pumping wells mix)
MW38 N & S– 2.4 gpm
COND/NTES T-530- 0.2 gpm(6am-1pm daily)
MW113 Area – 2.0 gpm

OPERATOR Chris Carlson

0.37" rain on 7/5/21 PM.

# LOWRY WTP OPERATIONS LOG

Date: Sunday July 04, 2021

| | |
|---|---|
| 0600 | ON site for weekend / holiday systems checks. Plant operations good. Refill phosphate |
| ↓ | tank with 30 gallons potable water + 3 lbs TSP. |
| 0625 | Decant T-35 / bottom valve. Wet well activated. Water is clear, no color. Clean |
| ↓ | the HMR-30 weir and pH probe - no oil or sheen observed in the HMR-30. Check TP-130 |
| ↓ | for oil globules - none observed. Water is clear, light green / yellow. |
| 0645 | TP-150 molybdenum Hach value reading 0 ug/L. |
| 0750 | Blowdown operations good. |
| 0815 | Plant operations good. |
| 1830 | Check plant remotely - All okay. |
| 7/5/21 0650 | Check plant remotely - All okay. |
| 1600 | Check plant remotely - All okay. |

Influent Sources and Flow Rates: 0605
NBBW – 7.5 gpm
N. END ON-SITE – 13.2 gpm
N. END OFF-SITE – 8.3 gpm
RWST – 0.6 gpm
NTES – 0.5 gpm
COND/NTES T-530 – 0.2 gpm CAP-1/M
MW38 – 2.4 gpm
T-540/541 – 0.3 gpm
OTHER ~~NA~~ MW11BArea - 20 gpm.

OPERATOR(S) Chris Carlson

# LOWRY WTP OPERATIONS LOG

Date: **Tuesday, July 06, 2021** pg 1 of 2

| Time | |
|---|---|
| 0545 | Plant operations good. |
| 0615 | Mike working on weekly efficiency sampling. Observe P-352 strainer is clogging clean strainer, transfer settled sludge from T-352 to T-351. Replace impeller on P-352. |
| 0730 | - Add preservatives to composite containers. Sodium thiosulfate to 5 VOC's composite containers and nitric acid to metals/RADS containers. |
| 0800 | - START Auto Samplers for monthly/Qtrly WTP sampling. TOTAL Effluent @ 239882192 gal @ 6.85 SU @ 16.8°C @ 33.3 gpm. |
| 0915 | - working on weekly BTS sampling. |
| 1000 | - Put BTS samples on ice. Prepare for rest of Qtrly sampling. |
| 1030 | - TP-150 molybdenum HACH value @ 10 ug/L |
| 1100 | - IX performance HACH testing and LAB split sampling after 333,454 gal Treated: TP-183 @ 500 ug/L; TP-174A @ 1,900 ug/L TP-173A @ 6,800 ug/L; TP-170 @ 8,200 ug/L. Decanted T-351 TO TOP valve. water is clear NO color. |
| 1150 | - START Flush of MP-001 and check for Residual chlorine: NONE detected. OK to use HCl preserved vials |
| 1200 | - Collect 1st set of time paced grab samples @ MP-001 for, VOC's, 1,4-Dioxane (low level) and NONYphenols. water is clear NO color. Place samples in fridge. 1205 Restart P-352. @ 29% CV |
| 1230 | - begin monthly/Qtrly Early warning sampling. |
| 1340 | - PACK TOday SS Samples on ice for Shipment to LAB. |
| 1500 | - Clean pH-315 probe w/ acid solution. check TPH Hanna for oil or sheen: None observed. Spray down weir. Check TP-130 for oil globules: None observed water is clear w/ yellow-green hues |
| 1550 | - START Flush of MP-001 sample port and check for Residual chlorine; None detected. |
| 1600 | - Collect 2nd set of time paced grab samples from MP-001 sample port for: VOC's, Low Level 1,4-Dioxane and NONYphenols. water is clear NO color. Place samples in fridge with others |
| 1615 | - Reboot GC2 PC. Had a sentex Error message: File not open or invalid Handle. |
| 1630 | - Plants operations Good. Auto Samplers on sentex/OK. |
| 1945 | Start MP-001 port Flush and check for residual chlorine - none detected. |
| 2000 | Collect 3rd set of time paced grab samples for: VOC's, low level 1,4-Dioxane and (continued) |

Influent Sources and Flow Rates: @ 0635
- NBBW – 7.5 gpm
- North End On Site- 13.4 gpm
- North End Off-Site – 8.3 gpm
- RWST – 0.6 gpm
- NTES – 0.5 gpm(10R only)
- MW38 T-540/541 – 0.3 gpm(Source well and 38 pumping wells mix)
- MW38 N & S– 2.4 gpm
- COND/NTES T-530- 0.2 gpm(6am-1pm daily)
- MW113 Area – 2.0 gpm

Operator: **Mike Gelwick / Chris Carlson**

## LOWRY WTP OPERATIONS LOG

Date: Tuesday, July 06, 2021 pg 2 of 2

| Time: | |
|---|---|
| @ Cont. | Nonylphenols. Water is very clear, NO color. Place samples in fridge with others. |
| 2345 | Start MP-001 post flush and check for residual chlorine - none detected. |
| 7/7/21 0000 | Collect 4th set of time paced grab samples for VOC's, low level 1,4-Dioxane and Nonylphenols. Water is very clear, no color. Place samples in fridge with others. |

Influent Sources and Flow Rates: @ 2010
NBBW – 7.6 gpm
North End On Site- 13.3 gpm
North End Off-Site – 8.2 gpm
RWST – 0.6 gpm
NTES – 0.51 gpm(10R only)
MW38 T-540/541 – 0.3 gpm(Source well and 38 pumping wells mix)
MW38 N & S– 2.4 gpm
COND/NTES T-530- 0.0 gpm(~~6am-1pm daily~~)
MW113 Area – 2.0 gpm

OPERATOR Chris Carlson

985 gal potable not used in plant today.

# LOWRY WTP OPERATIONS LOG

Date: **Wednesday, July 07, 2021**

| Time: | |
|---|---|
| 0345 | - Plants operations Good. |
| 0350 | - START Flush of MP-001 sample port and check for residual chlorine: None Detected. |
| 0400 | - Collect 5th set of time paced grab samples from MP-001 sample port for: VOC's, Low Level 1,4-Dioxane and NONYLphenols. water ES clear NO color place samples on fridge with others. |
| 0440 | - working on weekly GTS field Readings |
| 0600 | - Chris Working on weekly GC's calibrations and maint. and data backup. |
| 0640 | - Decant T-352 to TOP valve. Wet well did NOT activate. Water ES clear NO color. |
| | - Clean pH-315 probe w/Acid solution. Check TPC HMR 30 for oil or sheen: None observed. Spray down wash. |
| | - Check TP-130 for Oil globules: None observed. water ES clear w/ yellow-green hue. |
| 0750 ~~0800~~ | - ~~STOP~~ START Flush of MP-001 sample port and check for residual chlorine: None detected. |
| 0800 | - Collect 6th set of time paced grab samples from MP-001 sample port for: VOC's, Low Level 1,4-Dioxane and NONYLphenols with QC volume for each. water ES clear NO color. STOP Autosamplers. Total Effluent = 23993358 gal. A total of 51,396 gal treated during sample period. Process Sample composites By gently stirring each composite and checking the pH. pH of SVOC's composite = 6.97 su / Metals-RADs composite = 1.42 su. Fill sample containers and PACK all samples on ICE for SHIPMENT to labs. |
| 1003 | - TP-150 molybdenum HACH value = 0 ug/L |
| 1200 | Begin running potable water into the 2" PVC POTW backup discharge line to displace the air in the system - E.T. Tech has tie-in connected for the DADS septic lift system and will use some of this ~~potable~~ potable water to flush any dirt in their section of line out before they attempt a pressure test of the newly installed septic line. |
| 1255 | Stop potable after 985 gallons - E.T. pressure testing going well. Will plan to retest Laury backup section of the 2" POTW line tomorrow. |
| 1315 | Back up WTP data to Flash & CD. OneDrive daily cloud backup working well. 1340 Plant operations good. |

Influent Sources and Flow Rates: @0455
NBBW – 7.6 gpm
North End On Site- 13.2 gpm
North End Off-Site – 8.7 gpm
RWST – 0.6 gpm
NTES – 0.50 gpm(10R only)
MW38 T-540/541 – 0.30 gpm(Source well and 38 pumping wells mix)
MW38 N & S– 2.3 gpm
COND/NTES T-530- 0.0 gpm(6am-1pm daily)
MW113 Area – 2.0 gpm

Operator: **Mike Gelwick / Chris Carlson**

700gal potable water for pressure test on Backup POTW 2" line

# LOWRY WTP OPERATIONS LOG

Date: **Thursday, July 08, 2021**

| Time | |
|---|---|
| 0550 ↓ | Plant operations good. Prepare for 2-inch POTW backup discharge line testing, post DADS septic line tie-in - note E.T. Tech pressure tested new piping from DADS offices to tie-in with 150psi for 1 hour yesterday - All okay. |
| 0730 | Blowdown operations good. |
| 0830 | - working on weekly Plants Systems checks and calibrations. |
| 0840 | - Decant T-351 to TOP valve. Wet well activated. water is clear No odors |
| | - Clean pH-315 probe w/Acid solution. Check the Hach 10 for oil or sheen; None observed. Spray down with. |
| | - Check TP-130 for oil globules: None observed. water is clear w/yellow-green tint |
| 1040 | - Refill BTS phosphorus TANK w/6 # of TSP and 60gal of potable water. |
| | - Suspend Plant Discharge for Chris to do 4x8" [redacted] POTW Isolation valve Exercising. Also checking for leaks and leak detection |
| | Also doing a Pressure test on the BACKUP 2" POTW Line and checking and Exercising those Isolation valves too. |
| 1054 | - Resume normal Discharge. Finish up on 2" POTW checks and valves. Close the valve on the 2" @ the end and check |
| | POTW MH175-078. All ok. |
| 1126 | Start potable water Flowing through Backup 2" POTW discharge line - Perform ANNUAL valve exercising and air relief checks with Mike - All okay. |
| 1215 | Close pressure test isolation valve NEXT to MH175-078 |
| 1225 | Return to plant - line is at potable supply pressure of ~95psi Flow rate of potable 0.0gpm. |
| 1231 | HOUSE hydrostatic pump to set line pressure to 150 psi and start test. |
| 1251 | - Suspend Plant Discharge to calibrate pH-740 probe to 4+10 pH STDs |
| 1258 | - Resume normal Discharge. Continue with other WTP pH probes calibrations to 4+10 pH STDs @ MH113, 670, 310, 315 & 365 |
| 1330 | - Weekly Plants Systems checks and calibrations complete. |
| 1331 | - POTW BACKUP 2" pipeline pressure test complete. Dropped to 148psi. All ok. Slowly Release [redacted] pressure |
| | and water BACK to the WTP wetwell. PUT New NaOH TOTE on line to BTS |
| 1435 | - TP-150 Molybdenum HACH value @ 10 ug/L. |
| 1445 | - Plants operations Good. |

Influent Sources and Flow Rates: @ 0835
NBBW – 7.6 gpm
North End On Site- 13.3 gpm
North End Off-Site – 8.5 gpm
RWST – 0.6 gpm
NTES – 0.53 gpm(10R only)
MW38 T-540/541 – 0.29 gpm(Source well and 38 pumping wells mix)
MW38 N & S– 2.3 gpm
COND/NTES T-530- 0.20 gpm(6am-1pm daily)
MW113 Area – 2.0 gpm

* 1257 - TDM calling in NBBW sump level for TRANSducer QTRly calibration check. DTW @ 26.91' = 5685.64'. HMI Reading 5685.51' No calibration needed at this time.

Operator: **Mike Gelwick / Chris Carlson**

# LOWRY WTP OPERATIONS LOG

Date: **Friday, July 09, 2021**

| Time: | |
|---|---|
| 0645 | - Plants operating Good |
| 0745 | - Piper Electric on Site (Hadem) to Replace VFD FAN on MW170-EW-1. Also to work on BACKUP P-114 motor to be the same as current one. |
| 0753 | - Change N:EW on Site Flow Alarm value to 0 gpm while He works on FAN. Needs to turn off Pump power. |
| 0840 | - MW170-EW-1 BACK on. Return Flow Alarm value to 11 gpm. |
| 0950 | - Piper Electric off Site. VFD FAN Replaced and BACKUP motor Ready. |
| 1015 | - Decant T-351 TO TOP valve. wetwell activated. water is clear no color |
| | - Clean pH-315 probe w/Acid solution. Check the HMR for oil or sheen: None observed. 3 Array down well |
| | - Check TP-130 for oil globules: None observed. water is clear w/ yellow-green tint |
| 1245 | - TP-150 molybdenum HACH value = 0 ug/L |
| 1515 | - DTS into Maint Hold to Flush Reactor Feed Lines. |
| 1540 | - DTS BACK to Normal operations. |
| 1600 | - Plants operations Good. |

Influent Sources and Flow Rates: @ 0650
NBBW – 7.6 gpm
North End On Site- 13.3 gpm
North End Off-Site – 8.8 gpm
RWST – 0.6 gpm
NTES – 0.51 gpm(10R only)
MW38 T-540/541 – 0.30 gpm(Source well and 38 pumping wells mix)
MW38 N & S– 2.3 gpm
COND/NTES T-530- 0.20 gpm(6am-1pm daily)
MW113 Area – 2.0 gpm

Operator: **Mike Gelwick**

# LOWRY WTP OPERATIONS LOG

Date: Saturday, July 10, 2021

| | |
|---|---|
| Time: 0815 | Plant operations good. Start perimeter check of site |
| 0915 | Perimeter fence and gates secured and all sheds and compressors in normal operations. |
| 0930 | Decant T-351 Top valve until wet well activated -Stopped decant when water got cloudy |
| 1000 | Cleaned T-315 probe with Acid Solution. Check HMR30 for oil sheens: None observed<br>↳ tank is slightly cloudy → Sprayed down weir |
| 1030 | Checked TP-130 for oil globules and sheens: None observed water is clear with yellowish tint |
| 1100 | TP-150 molybdenum HACH value @ 10 ug/L |
| 1200 | Plant operations normal. Depart |
| 1800 | -Logon Remotely Allow. |
| Sunday | July 11, 2021 |
| 0616 | - Receive Alarm for UV-OK Shutdown. Log on looks like BagFilters plugging. |
| 0640 | - onsite. Pressure on BagFilter outlet is High. Change out BAgs during Shutdown while UVOK on Recycle. |
| 0710 | - Install New 5 micron BAgs on UVOK BagFilter Systems |
| 0755 | - Plants operations Good |

Influent Sources and Flow Rates: @0820
NBBW – 7.6 gpm
North End On Site-13.3 gpm
North End Off-Site – 8.7 gpm
RWST – 0.6 gpm
NTES – 0.52 gpm(10R only)
MW38 T-540/541 – 0.30 gpm(Source well and 38 pumping wells mix)
MW38 N & S– 1.2 gpm
COND/NTES T-530- 0.20 gpm(6am-1pm daily)
MW113 Area – 2.0 gpm

OPERATOR Tom Gilbert / mike Gadwick

# LOWRY WTP OPERATIONS LOG

Date: **Monday, July 12, 2021**

| Time | |
|---|---|
| 0540 | Plant operations good. |
| 0820 | - Decant T-351 TO TOP valve. Backwash activated. Water IS clear noted. |
| | - Clean pH-315 probe w/ Acid solution. Check THE HMR 30 for oil or Sheen: None observed. Spray down wash. |
| | - Check TP-130 for oil globules: None observed. Water IS clear w/ yellow-green tint. |
| 0840 | - TP-150 molybdenum HACH value @ 10 ug/L |
| 1354 ↓ | Tom send SN MW38N Extraction well level for quarterly transducer calibration check- DTW @ 52.13' = GWE 5719.67'. HMI reading 5719.56', No calibration needed at this time. |
| 1545 ↓ | Observe a small amount of air is getting past the HMR-30 sparge valve, close manual ball valve until Wandown tomorrow, then will change out the auto valve. |
| 1556 | Plant operations good. |

Influent Sources and Flow Rates: @0650
NBBW – 7.6 gpm
North End On Site- 13.3 gpm
North End Off-Site – 8.5 gpm
RWST – 0.6 gpm
NTES – 0.49 gpm(10R only)
MW38 T-540/541 – 0.30 gpm(Source well and 38 pumping wells mix)
MW38 N & S– 2.3 gpm
COND/NTES T-530- 0.20 gpm(6am-1pm daily)
MW113 Area – 2.0 gpm

Operator: **Mike Gelwick / Chris Carlson**

# LOWRY WTP OPERATIONS LOG

Date: **Tuesday, July 13, 2021**

| Time: | |
|---|---|
| 0530 | Plant operations good. |
| 0615 | Mike working on weekly efficiency sampling / prep for weekly BTS performance sampling |
| 0750 | Blowdown operations good, sparge manual valve reopened then closed after sparge cycled. |
| 0755 | IX Performance Hach values with splits going to lab after 352,836 gallons treated. |
| ↓ | TP-163 @ 700 ug/L ; TP-174A @ 1,200 ug/L ; TP-173A @ 6,600 ug/L ; TP-170 @ 7,700 ug/L. |
| 0850 | TP-150 molybdenum Hach value reading 0 ug/L. |
| 0800 | - Refill BTS phosphorus tank w/ ½ of TSP and 70 gal of potable water |
| 0825 | - Decant T-351 to POP valve. wet well activated water IS clear NO color |
| | - Clean pH-315 probe w/ Acid solution. Check TP-140 for oil or sheen : None observed. Spray down weir. |
| | - Check TP-130 for oil globules : None observed. water IS clear w/ yellow green tint. |
| 1430 | Replace the air valve on the Half-30 sparge system - working well. |
| 1500 | Change 5-micron bags on UV-OX Feed. |
| 1600 | Plant operations good. |

Influent Sources and Flow Rates: @ 0650
NBBW – 7.7 gpm
North End On Site- 13.4 gpm
North End Off-Site – 8.7 gpm
RWST – 0.6 gpm
NTES – 0.50 gpm(10R only)
MW38 T-540/541 – 0.30 gpm(Source well and 38 pumping wells mix)
MW38 N & S– 2.3 gpm
COND/NTES T-530- 0.2 gpm(6am-1pm daily)
MW113 Area – 2.0 gpm

Operator: **Mike Gelwick / Chris Carlson**

# LOWRY WTP OPERATIONS LOG

Date: **Wednesday, July 14, 2021**

| Time | |
|---|---|
| 0600 | Plant operations good. Start weekly GC maintenance & Calibrations. Prepare for T-510 cleaning. |
| 0710 | New sparge valve working well. Begin T-510 cleaning while HMR-30 is in blowdown. |
| 0730 | T-510 cleaning completed - clean UV-OX & BTS Feed y-strainers. Blowdown operations okay - observe sludge lateral #3 is partly clogged - will work on clearing it later after blowdown and the UV-OX has cooled back down. |
| 0800 | Tom sending MANUAL DTW of MW38 south well for transducer check. DTW @ 72.17' = GWE 5734.59'. HMI reading 5734.63', NO calibration needed at this time. |
| 0900 | Work on clearing sludge lateral #3 - Decant T-351, wet well on - water is clear, NO color. |
| 0915 | Lateral #3 clear - refill HMR-30 |
| 0925 | ~~TP-180~~ TP-150 molybdenum Hach values reading 0 ug/L. |
| 0930 | Decant T-351 again - wet well did not activate. Water is clear, no color. Clean the HMR-30 weir and pH probe - no oil or sheen observed in the HMR-30. Check TP-130 for oil globules - none observed. Water is very clear, light yellow/green. |
| 1015 | Weekly data backup done. OneDrive daily auto backup working well. |
| 1200 | Shutdown MW38 N & S extraction in preparation for MW38 source well batch extraction. |
| 1225 | Increase RWST influent from 0.6 gpm to 2.6 gpm and switch MW38 from direct HMR-30 influent to T-540/541. Run down to source well and start batch extraction to T-540/541. |
| 1310 | Place BTS in maintenance hold for Sediment tank feed line flush and GAC F-3340 backflushing. |
| 1400 | BTS out of maintenance hold. |
| 1415 | Plant operations good. |

Influent Sources and Flow Rates: @ 0650
NBBW – 7.6 gpm
North End On Site- 13.4 gpm
North End Off-Site – 8.9 gpm
RWST – 0.6 gpm
NTES – 0.52 gpm(10R only)
MW38 T-540/541 – 0.30 gpm(Source well and 38 pumping wells mix)
MW38 N & S– 2.3 gpm
COND/NTES T-530- 0.20 gpm(6am-1pm daily)
MW113 Area – 2.0 gpm

Operator: **Mike Gelwick / Chris Carlson**

# LOWRY WTP OPERATIONS LOG

Date: **Thursday, July 15, 2021**

| Time: | |
|---|---|
| 0540 ↓ | Plant operations good. T-540/541 @ 60%, will continue MW38 batch extraction until 80% to 85% Full. |
| 0740 | Blowdown operations okay - observe sludge later #3 is partly plugged again after blowdown. |
| 0800 | Decant T-351 top valve, wet well activated. Water is clear, no color. |
| 0810 | Work on pumping sludge lateral #3 clean out port. |
| 0820 | Later #3 Clear again - Mike working on weekly systems checks and calibrations today. |
| 0915 | - Clean pH-315 probe w/Acid solution. Check the Hach 30 for oil or sheen: None observed. Spray down with. |
| | - Check TP-130 for oil globules: None observed, water is clear w/yellow-green tint |
| 1331 | - Suspend Plant Discharge to calibrate pH-740 probe to 4+10 pH STD's. |
| 1340 | - Resume normal Discharge, continue with other WTP pH probes calibrations to 4+10 pH STD's ⇒ pH-113, 670, 310, 315 + 365. |
| 1420 | - Plant's weekly systems checks and calibrations complete. |
| 1426 | - Receive Cac warning alarm. GAC 3 1,2 DCA ⇒ 108.22 ppb Probably due to fresh MW38 Source well water hitting the system. Still OK. Conservative setting. |
| 1447 | - TP-150 molybdenum HACH value ⇒ 0 ug/L. |
| 1615 | - STOP MW38 Source well pumping to T-540/541. TANKS = 81% |
| 1708 | - START MW38 N+S wells pumping to T-540/541 TO Displace any residual Source well water in pipeline. At least 600 gal. |
| 1715 | - Plant's Operations Good. |
| 2131 | - Switch MW38 N+S pumping wells to RWST. 621 gal flushed thru effective to T-540/541. |

Influent Sources and Flow Rates: @ 0650
NBBW – 7.6 gpm
North End On Site- 13.3 gpm
North End Off-Site – 8.7 gpm
RWST – 2.6 gpm
NTES – 0.51 gpm(10R only)
MW38 T-540/541 – 30 gpm(Source well and 38 pumping wells mix)
MW38 ~~N+S~~ – 5.1 gpm Source well
COND/NTES T-530- 0.20 gpm(6am-1pm daily)
MW113 Area – 2.0 gpm

Operator: **Mike Gelwick / Chris Carlson**

# LOWRY WTP OPERATIONS LOG

Date: **Friday, July 16, 2021**

| Time: | |
|---|---|
| 0635 | - Plants operations Good |
| 0643 | - Switch manual valves on 38 pipeline to HMR30 and switch MW38 N+S wells pumping to the HMR30. Return RWST Flow to 0.60 gpm. |
| 0720 | - Receive GC3/Bio warning VOC Alarm 1,2-DCA @ 109 ppb. Consecutive sampling. SRILLOK. |
| 0740 | - Refill BT3 phosphorus TANK w/ 4# of TSP and 40 gal of potable water. |
| 0810 | - Decant T-351 to TDP valve. Wetwell activated. Water is clear no color. |
| | - Clean pH-315 probe w/ ACID solution. Check the HMR30 for oil or sheen: None observed. Spray down well. |
| | - Check TP-130 for oil globules: None observed. Water is clear w/ yellow-green tint. |
| 0830 | - TP-150 Molybdenum HACH value @ 10 ug/L. |
| 1415 | - Plants operations Good |

Influent Sources and Flow Rates: @ 0645
NBBW – 7.6 gpm
North End On Site- 13.8 gpm
North End Off-Site – 9.1 gpm
RWST – 0.60 gpm
NTES – 0.51 gpm(10R only)
MW38 T-540/541 – 0.31 gpm(Source well and 38 pumping wells mix)
MW38 N & S– 2.2 gpm
COND/NTES T-530- 0.20 gpm(6am-1pm daily)
MW113 Area – 2.0 gpm

Operator: **Mike Gelwick**

0.1 Rain

## LOWRY WTP OPERATIONS LOG

Date: Sunday, July 18, 2021

| Time: | |
|---|---|
| 0830 | Plants operations good. |
| 0905 MS | Decant T-351 to top valve. Wet well activated. Water is clear no color. Clean pH-315 probe w/ acid solution. Check HMR-30 for oil sheen: none observed. Spray down weir. Check TP-130 for oil globules: none observed. Water is clear with light yellow-greenish tint. |
| 1035 | FP-150 Molybdenum HACH value @ 20µg/L. |
| 1045 | Plants operations good. |

Influent Sources and Flow Rates: @ 0900
NBBW – 7.6 gpm
North End On Site- 13.3 gpm
North End Off-Site – 8.6 gpm
RWST – 0.6 gpm
NTES – 0.51 gpm(10R only)
MW38 T-540/541 – 0.29 gpm(Source well and 38 pumping wells mix)
MW38 N & S– 2.2 gpm
COND/NTES T-530- 0.2 gpm(6am-1pm daily)
MW113 Area – 1.9 gpm

OPERATOR Manuela Seewald

# LOWRY WTP OPERATIONS LOG

Date: **Monday, July 19, 2021**

| Time: | |
|---|---|
| 0600 | Plant operations good. IX system flow dropped to 1.9 gpm over the weekend. |
| 0630 | Change out 1-Micron bag in temporary filter before T-113, bag that was online did have a lot of fine silt trapped in it. |
| ↓ | Set up for annual LFG condensate conveyance line flushing / Pressure testing. |
| 0750 | Blowdown operations good. Refill phosphoric tank with 50 gallons potable water + 5 lbs TSP. |
| 0800 | Mike adding potable water to auto traps 1, 2 & 3 to displace air in the conveyance line. |
| 0917 | ~200 gallons of potable sent through the conveyance line - valves ~~stop~~ closed and pressure test started, holding at 41 psi (condensate operating pressure ~20 psi - not). |
| ↓ | Decant T-351 top valve, wet well activated. Water is clear, no color. Clean the HACH-30 weir and pH probe - No oil or sheen observed in the Hach-30. Refill polymer tank with 200 gallons potable + 2 cups polymer. Flush lateral #3. |
| ↓ | Check TP-130 for oil globules - NONE observed. Water is clear, light green/yellow. |
| 0940 | TP-150 molybdenum Hach value reading 20 ug/L. |
| 1020 | LFG condensate conveyance line pressure at 40 psi - PASSING. Resume normal auto trap pumping. |
| | Mike topping up backup generators fuel today. |
| 1500 | - Plants operations good |

Influent Sources and Flow Rates: @0650
NBBW – 7.6 gpm
North End On Site- 13.2 gpm
North End Off-Site – 8.3 gpm
RWST – 0.6 gpm
NTES – 0.53 gpm(10R only)
MW38 T-540/541 – 0.30 gpm(Source well and 38 pumping wells mix)
MW38 N & S– 2.2 gpm
COND/NTES T-530- 0.20 gpm(6am-1pm daily)
MW113 Area – gpm

Operator: **Mike Gelwick / Chris Carlson**

# LOWRY WTP OPERATIONS LOG

Date: **Tuesday, July 20, 2021**

| Time: | |
|---|---|
| 0615 | Plant operations good. Setup for weekly efficiency & performance sampling. |
| 0640 | Mike starting weekly efficiency sampling. |
| 0730 | IX performance with lab splits. Note: Running both Low & High range Hach test on TP-183 & TP-174A, logging low range on spreadsheet because it matches up closer to historical weekly lab results. TP-183 Low Range @ 120ug/L & High Range @ 400ug/L (Historical lab result ~200ug/L); TP-174A Low Range @ 170ug/L & High Range @ 600ug/L (Historical lab result ~300ug/L); TP-173A @ 6,900ug/L and TP-170 @ 7,600ug/L, IX performance readings / samples take after a total of 372,436 gallons treated. |
| 0835 | TP-150 molybdenum Hach value reading 0ug/L. Mike working on weekly BTS performance. |
| 0845 | - Decant T-351 to TDP valve wetwell activated. water is clear no color. |
| | - Clean pH-315 probe w/ Acid solution. Check TP-430 for oil or sheen: none observed. Spray down weir. |
| | - Check TP-430 for oil globules: none observed. water is clear w/ light yellow green tint. |
| 1515 | - Plants operations good. |

Influent Sources and Flow Rates: @0830
- NBBW – 7.6 gpm
- North End On Site- 13.4 gpm
- North End Off-Site – 8.6 gpm
- RWST – 0.6 gpm
- NTES – 0.52 gpm(10R only)
- MW38 T-540/541 – 0.3 gpm(Source well and 38 pumping wells mix)
- MW38 N & S– 2.2 gpm
- COND/NTES T-530- 0.2 gpm(6am-1pm daily)
- MW113 Area – 2.0 gpm

Operator: **Mike Gelwick / Chris Carlson**

# LOWRY WTP OPERATIONS LOG

Date: **Wednesday, July 21, 2021**

| Time: | |
|---|---|
| 0540 | Plant operations good. Start on weekly GC maintenance and calibrations. |
| 0700 | Jim B of Brown Hill on site for OneDay database creation, fix P-632 PID control input value update, backup PID programs to OneDrive. |
| 0835 | TP-150 Molybdenum Hach value reading 0 ug/L. |
| 1015 | Reboot HMI2 after BioTrend data fix. |
| 1017 | HMI2 online. |
| 1040 | Swap out battery on HMR-30 PLC CPU card - All OK. |
| 1205 | -Decant T-351 to TOP valve. wet well activated. water IS clear NO color. |
| | -clean pH-315 probe w/ Acid solution. Check the HMR30 for oil or sheen: None observed. Spray down wash. |
| | -Check TP-430 for oil globules: None observed. water IS clear w/ yellow-green tint. |
| 1420 | Refresh FTVIEW1 (possibly note logging data since 1314). working NOW. Jim done for now - will update him tomorrow on how well OneDay data logging / backup is working. |
| | Work on backing up data to CD & Flash drive. |
| 1520 | Plant operations good. |

Influent Sources and Flow Rates: @0653
NBBW – 7.0 gpm
North End On Site- 13.3 gpm
North End Off-Site – 8.7 gpm
RWST – 0.6 gpm
NTES – 0.53 gpm(10R only)
MW38 T-540/541 – 0.30 gpm(Source well and 38 pumping wells mix)
MW38 N & S– 2.2 gpm
COND/NTES T-530- 0.20 gpm(6am-1pm daily)
MW113 Area – 2.0 gpm

Operator: **Mike Gelwick / Chris Carlson**

# LOWRY WTP OPERATIONS LOG

Date: **Thursday, July 22, 2021**

| Time: | |
|---|---|
| 0500 | Plant operations good. Oneclay database didn't log on HMI2 but did on HMI FTVIEW1 at 11:59pm. |
| 0538 | Stop HMI2 RSVIEW and backup all data to flash drive, then reboot CPU. |
| 0546 | HMI1 online - note Oneclay did log at startup. |
| 0610 | BACKUP all data on HMI FTVIEW1 |
| 0612 | Reboot HMI FTVIEW1 - online @ 0647. |
| 0730 | Blowdown operations good. Work with Mike to add remaining ~100gallons hydrogen peroxide to main bay supply, one full HCL tote & 1.25 tote of Caustic also to main bay supply. Also do some prep work for HCL supply line upgrade/refresh. |
| 0940 | Kelly working on OneDay comparison / backup remotely (adding VBA script) |
| 0940 | - Mike working on weekly Plant & Systems checks and calibrations |
| 1015 | - Recount T-351 to TOP valve. Wet well activated. Water is clear NO color |
| | - Clean pH-315 probe w/Acid solution. Check Tk Hood 30 for oil or sheen: None observed. Spray down water |
| | - Check TP-130 for oil globules; None observed, water is clear w/yellow-green plant |
| 1100 | - Begin main compressor oil moisture prevention MAX speed 12m. |
| 1300 | - STOP main compressor MAX Run. |
| 1325 | - Suspend Plant Discharge to calibrate pH-740 probe to 4+10 pH STD's |
| 1333 | - Resume Normal Discharge. Continue with other pH probes calibrations to 4+10 pH STD's → pH-113, 620, 310, 315 & 365. |
| 1415 | - Plant & Systems and calibrations checks complete. |
| 1420 | - TP-150 molybdenum HACH value → 10 ug/L |
| 1500 | - Plants operations Good |

Influent Sources and Flow Rates: @ 1015
NBBW – 7.6 gpm
North End On Site- 13.3 gpm
North End Off-Site – 2.8 gpm
RWST – 0.6 gpm
NTES – 0.57 gpm(10R only)
MW38 T-540/541 – 0.30 gpm(Source well and 38 pumping wells mix)
MW38 N & S– 2.2 gpm
COND/NTES T-530- 0.80 gpm(6am-1pm daily)
MW113 Area – 2.0 gpm

Operator: **Mike Gelwick / Chris Carlson**

# LOWRY WTP OPERATIONS LOG

Date: **Friday, July 23, 2021**

| Time: | |
|---|---|
| 0650 | - Plants operations Good. |
| 0710 | - TP-#50 molybdenum HACH value = 0 ug/L. Blowdown operations good. |
| 0810 | - Decant T-351 to TP value. wetwell activated. water BS clear No color |
| | - Clean pH-315 probe w/ Acid solution. Check the Hach 50 for oil or sheen! None observed. Spray Down wet. |
| | - Check TP-130 for oil globules; None observed. water BS clear w/ light yellow green hue |
| 0835 | - Kelly from Browns Hill working on DATA issue remotely, Refill BTS phosphorus tank w/ 6 # of TSP and 60 gal of potable water |
| 0855 | - Kelly found one more possible mistake but will need to wait until morning tomorrow to see if fixed, Place BTS Dist to Hold to Flush Reactor |
| | Feed Lines |
| 0928 | - Resume Normal BTS operations |
| 0940 | - Plants operations Good. |

Influent Sources and Flow Rates: @ 0635
NBBW – 7.6 gpm
North End On Site- 13.3 gpm
North End Off-Site – 8.5 gpm
RWST – 0.6 gpm
NTES – 0.51 gpm(10R only)
MW38 T-540/541 – 0.30 gpm(Source well and 38 pumping wells mix)
MW38 N & S– 2.2 gpm
COND/NTES T-530- 0.20 gpm(6am-1pm daily)
MW113 Area – 2.0 gpm

Operator: **Mike Gelwick / Chris Carlson**

# LOWRY WTP OPERATIONS LOG

Date: **Saturday, July 24, 2021**

| | |
|---|---|
| Time: 0500 | - Plants operations Good. |
| 0525 | - Decant T-351 to TOP valve. Wetwell activated. water is clear no odor. |
| | - Clean pH-315 probe w/ Acid solution. Check the HMI50 for oil or sheen: None observed. Spray down weir |
| | - Check TP-130 for oil globules: none observed. water is clear w/ light yellow-green tint. |
| | - Both GC's operational within Limits. |
| | - All blowers on. Bag filters backwash operations Good. NO Refill on phosphorus tank needed. ~90 gal full. |
| 0600 | - TP-150 molybdenum HACH value @ 10 ug/L. Go to check other site systems. |
| 0825 | - Plants operations Good 2100- Log in Remotely. All on. |
| Sunday, | July 25, 2021 |
| 0900 | - Log in Remotely. All ok |
| 2100 | - Receive Alarm for NTES unstable flow. Log in and set NTES to manual and START T-530/R005 @ 0.50 gpm. Invert NTES |
| | to T-530. 100ks like trench may have pumped down to a Recharge Rate which was not enough to stay Above flow Alarm set point. |

Influent Sources and Flow Rates: @0500
NBBW – 7.6 gpm
North End On Site- 13.3gpm
North End Off-Site – 8.7 gpm
RWST – 0.6 gpm
NTES – 0.50 gpm(10R only)
MW38 T-540/541 – 0.30 gpm(Source well and 38 pumping wells mix)
MW38 N & S– 2.3 gpm
COND/NTES T-530- 0.0 gpm(6am-1pm daily)
MW113 Area – 2.0 gpm

Operator: **Mike Gelwick** ~~**Chris Carlson**~~

# LOWRY WTP OPERATIONS LOG

Date: **Monday, July 26, 2021**

| Time: | |
|---|---|
| 0610 | Plant operations good. P-002UV did not stall out again overnight, will plan to pull and clean pump this week. |
| 0815 | - Decant T-351 to TOP valve. Wetwell activated. Water is Clear No odor. |
| | - Clean pH-315 probe w/ Acid solution. Check the HMI 30 for oil or sheen: None observed. Spray down weir. |
| | - Check TP-130 For oil globules: None observed. Water is Clear w/ light yellow-green tint. |
| 0825 | - TP-150 molybdenum HACH value = 0 ug/L |
| 1055 | - Return NTES to normal flow mode = 0.51 gpm. Been running OK. Return T-530 to Auto Run = 0.20 gpm 6 AM-1pm. |
| 1440 | - Plant is operating Good. |

Influent Sources and Flow Rates: @ 0830
NBBW – 7.6 gpm
North End On Site- 13.2 gpm
North End Off-Site – 8.9 gpm
RWST – 0.6 gpm
NTES – 0.51 gpm(10R only) to T-530
MW38 T-540/541 – 0.29 gpm(Source well and 38 pumping wells mix)
MW38 N & S– 2.3 gpm
COND/NTES T-530- 0.51 gpm(~~6am-1pm daily~~)
MW113 Area – 2.0 gpm

Operator: **Mike Gelwick / Chris Carlson**

# LOWRY WTP OPERATIONS LOG

Date: **Tuesday, July 27, 2021**

| Time: | |
|---|---|
| 0540 | Plant operations good. |
| 0630 | Mike working on weekly efficiency sampling - Tom to continue training on Bio weekly performance today. 4 Samples |
| 0730 | IX performance HACH testing and LAB split sampling AFTER 392191gal treated: TP-183 = 110 ug/L ; TP-174A = 115 ug/L TP-173A = 5100 ug/L ; TP-170 = 7300 ug/L. Using Low RANGE KIT for TP-183 + 174A. Using High RANGE KIT for TP-173A + 170. |
| 0817 | TP-150 Molybdenum HACH value = 0 ug/L |
| 1215 | -Refill STS phosphorus tank w/ 6 #s of TSP and 60 gal of potable water. |
| 1255 | -Decant T-351 to TDP valve. wet well activated. water is clear no color. |
| | -Clean pH-315 probe w/ Acid solution. check the HMI 80 for oil or sheen: None observed. Spray down weir. |
| | -Check TP-130 for oily globules ; None observed. water is clear w/ light yellow-green tint. |
| 1510 | -Plants operating Good. |

Influent Sources and Flow Rates: @ 0653
NBBW – 7.6 gpm
North End On Site- 13.3 gpm
North End Off-Site – 8.5 gpm
RWST – 0.6 gpm
NTES – 0.49 gpm(10R only)
MW38 T-540/541 – 0.30 gpm(Source well and 38 pumping wells mix)
MW38 N & S– 2.3 gpm
COND/NTES T-530- 0.20 gpm(6am-1pm daily)
MW113 Area – 2.0 gpm

Operator: **Mike Gelwick / Chris Carlson**

# LOWRY WTP OPERATIONS LOG

Date: **Wednesday, July 28, 2021**

| Time: | |
|---|---|
| 0550 | Plant operations good. Start on weekly GC maintenance and calibrations. |
| 0600 | Turn up IX Feed to 2.2 GPM max to handle the small amount greater than |
| ↓ | 2 GPM to extraction pump is making. Total volume through the IX system |
| ↓ | at 394,850 gallons. |
| 0730 | Blowdown operations good. |
| 1400 | GC's completed - Backup WTP data to Flash & CD. Automatic daily OneDrive backup |
| ↓ | working well. |
| 1440 | TP-150 molybdenum Hach value reading 0 ug/L. |
| 1450 | Decant T-351 top valve, wet well activated. Water is clear, no color - Clean the |
| | HMR-30 water and pH probe - no oil or sheen observed in the HMR-30. Check TP-150 |
| | for oil globules - none observed. Water is clear - light yellow / green - |
| 1550 | Plants operations Good |

Influent Sources and Flow Rates: @ 0656
NBBW – 7.6 gpm
North End On Site- 13.3 gpm
North End Off-Site – 8.1 gpm
RWST – 0.6 gpm
NTES – 0.52 gpm(10R only)
MW38 T-540/541 – 0.3 gpm(Source well and 38 pumping wells mix)
MW38 N & S– 2.3 gpm
COND/NTES T-530- 0.20 gpm(6am-1pm daily)
MW113 Area – 1.9 gpm

Operator: **Mike Gelwick / Chris Carlson**

# LOWRY WTP OPERATIONS LOG

Date: **Thursday, July 29, 2021**

| Time: | |
|---|---|
| 0600 | Plant operations good. |
| 0650 | Shutdown UV-ox for lamp change out. Asset# LT-358 @ |
| 0730 | Change out lamp SERIAL NUMBER 10763094 after 3,295 service hours with NEW |
| ↓ | lamp serial number 10011753 40/9 |
| 0750 | Blowdown operations good. New lamp working well. Mike working on weekly systems checks and calibrations. New 4+10 pH STD's today. Calibrate S/C multimeter to 50% LEL to check T-740 Ambient to ensure 0% LEL. |
| 1000 | - Decant T-351 to TOP valve wet well activated. water IS clear no color |
| | - Clean pH-315 probe w/Acid solution. Check the HMK30 for oil or sheen: None observed. Enter SprayDown water. |
| | - Check TP-130 for oily globules: None observed. water IS clear w/ light yellow-green tint. |
| 1020 | - TP-150 molybdenum HACH value @ 10 ug/L |
| 1150 | - Calibrate BT3 pH probes w/new 4+10 pH STD's (monthly) |
| 1253 | - Cal-Brate WTP pH probes w/New 4+10 pH STD's @ pH-113, 670, 310, 315 + 365. |
| 1320 | - Suspend Plant Effluent to calibrate pH-740 probe and LEL-740 sensor. Use sonic multimeter to ensure T-740 Ambient Air IS 0% LEL |
| 1331 | - Plant SHUTDOWN during calibration of LEL-740 @ 8% LEL. Automatic SHUTDOWN operating correctly. |
| 1339 | - RESTART Plant while Discharge STILL Suspended. |
| 1340 | - Resume Normal Discharge. |
| 1555 | - Plants operations Great. |

Influent Sources and Flow Rates: @ 0640
NBBW – 7.6 gpm
North End On Site- 13.2 gpm
North End Off-Site – 8.9 gpm
RWST – 0.6 gpm
NTES – 0.50 gpm(10R only)
MW38 T-540/541 – 0.30 gpm(Source well and 38 pumping wells mix)
MW38 N & S– 2.2 gpm
COND/NTES T-530- 0.20 gpm(6am-1pm daily)
MW113 Area – 2.0 gpm

Operator: **Mike Gelwick / Chris Carlson**

0.23" Rain P.M.

# LOWRY WTP OPERATIONS LOG

Date: Friday, July 30, 2021

| Time: | |
|---|---|
| 0800 | Plant operations good. |
| 0830 | - Decant T-351 from top valve - wet well activated - water is clear w/ no color - stopped decant when water got cloudy |
| | - Cleaned pH-315 probe w/ acid solution. Checked HMR30 for oil or sheens → none observed |
| | - Sprayed down HMR30 weir → good flow |
| | - Checked TP-130 for oil globules: none observed → water is clear w/ yellow greenish tint |
| 0915 | TP-150 molybdenum HACH value @ 10 ug/L |
| 1430 | Plant operations good. |

Influent Sources and Flow Rates: @
NBBW – gpm
North End On Site- gpm
North End Off-Site – gpm
RWST – gpm
NTES – gpm(1pm daily)
MW38 T-540/541 – gpm(Source well and 38 pumping wells mix)
MW38 N & S– gpm
COND/NTES T-530- gpm(6am-1pm daily)
MW113 Area – gpm

OPERATOR Tom Gilbert

0.25" rain P.M.

## LOWRY WTP OPERATIONS LOG

Date: Saturday, July 31, 2021

| Time | |
|---|---|
| 0620 | ON site for weekend systems check. Plant operations good. Decant T-351 top valve, east well did not activate. Water is clear, no color. Clean the HMR-30 weir and pH probe - no oil or sheen observed in the HMR-30. Check TP-120 for oil globules - none observed. Water is clear- light yellow/green. Refill phosphorus tank with 50 gallons potable water + 5 lbs TSP. Switch Reactor 1 feed from P-3321 to P-3324 (3321 partly clogging, motor speed 81%) |
| 0750 | Blowdown operations okay - HMR-30 Sludge lateral #2 partly clogged. |
| 0835 | TP-150 molybdenum Hach value reading 0 ug/L. |
| 0900 | Plant operations good. |
| 8/1/21 0627 | Check plant remotely - All okay. |
| 1410 | Check plant remotely - All okay. |

Influent Sources and Flow Rates: @0627
NBBW – 7.5 gpm
North End On Site- 13.1 gpm
North End Off-Site – 8.4 gpm
RWST – 0.6 gpm
NTES – 0.5 gpm(10R only)
MW38 T-540/541 – 0.3 gpm(Source well and 38 pumping wells mix)
MW38 N & S– 2.2gpm
COND/NTES T-530- 0.2 gpm(6am-1pm daily)
MW113 Area – 2.0 gpm

OPERATOR Chris Carlson

# LOWRY WTP OPERATIONS LOG

Date: **Monday, August 02, 2021**

| | |
|---|---|
| Time: 0620 | Plant operations good. Mike setting up autosampler for monthly MP-001 Flow paced molybdenum sampling. |
| 0800 | -START Auto Sampler. TOTAL Effluent → 24125882 8 gal → 6.75 MG → 17.5 AC → 33.4 gpm |
| 1000 | - Begin monthly Early warning and weekly IX System Sampling. Splitting IX HACH Samples w/ LAB. |
| 1032 | IX Performance HACH testing AFter 409947 gal treated; TP-183 → 130 ug/L ; TP-174A → 160 ug/L ; TP-173A → 6200 ug/L TP-170 → 6700 ug/L. TP-150 Molybdenum HACH value → 0 ug/L. All Lab samples put in Fridge until packing tomorrow. |
| 1150 | -START Flush of mp-001 and check for residual chlorine; None detected. OK to use HCl Preserved vials |
| 1200 | -Collect 1st set of Time paced grab samples for Low Level 1,4-Dioxane. Water IS Clear No color Place SAMPLES in to Fridge. |
| 1240 | - Decant T-351 to TOP valve. Wet well activated. Water IS clear No color |
| | -Clean pH-315 probe w/ Acid Solution. Check the HMR30 for oil or Sheen: None observed. Spray down weir. |
| | -Check TP-130 for oily globules: None observed. Water IS Clear w/ light yellow-green tint. |
| 1550 | - START Flush of MP-001 SAmple Port and check for Residual chlorine: None detected. |
| 1600 | -Collect 2nd set of time paced grab samples for Low Level 1,4-Dioxane. Water IS Clear No color. Place SAmples IN Fridge with others |
| 1605 | - Plants operations Good. |
| 1945 | Start flush of MP-001 sample port - check for residual chlorine - none detected. |
| 2000 | Collect 3rd set of time paced grab samples for low level 1,4-Dioxane. Water is very clear, NO color. Place sample in fridge with others. Plant operations good. |
| 2345 | Start MP-001 port Flush - check for residual chlorine - none detected. |
| 0000 | Collect 4th set of time paced grab samples for low level 1,4-Dioxane. Water is very clear, NO color. Place sample in fridge with others. Plant operations good. |

Influent Sources and Flow Rates: @0650
NBBW – 7.6 gpm
North End On Site- 13.2 gpm
North End Off-Site – 8.6 gpm
RWST – 0.6 gpm
NTES – 0.51 gpm(10R only)
MW38 T-540/541 – 0.3 gpm(Source well and 38 pumping wells mix)
MW38 N & S– 2.2 gpm
COND/NTES T-530- 0.2 gpm(6am-1pm daily)
MW113 Area – 2.0 gpm

Operator: **Mike Gelwick / Chris Carlson**

0.02" rain P.M.

# LOWRY WTP OPERATIONS LOG

Date: **Tuesday, August 03, 2021**

| Time: | |
|---|---|
| 0340 | - Plants operating Good |
| 0350 | - START Flush of MP-001 sample port and check for Residual chlorine: None detected. |
| 0400 | - Collect 5th set of time paced grab samples for Low Level 1,4-Dioxane. Water is clear No color. Place samples in fridge with others |
| 0405 | - Begin GTS sampling and Efficiency checks. TOM assisting/training |
| 0600 | - continuing on GTS field readings. TOM helping/training |
| 0652 | Restart MW38 N well extraction early (reached it's low level stop last night at 2059). |
| 0750 | - START Flush of MP-001 and check for residual chlorine: None detected. |
| 0800 | - collect 6th/final set of time paced grab samples for Low Level 1,4-Dioxane. Water is Clear No color. Place samples in fridge with others |
| | - STOP Auto sampler. Total Effluent = 241,309,032 gal. A Total of 50,204 gal treated during sample period. Process composite sample by |
| | Gently stirring and Check pH value. Composite pH value = 1.83 su. Fill bottle and pack All samples on Ice for shipment to Lab. |
| 1105 | - ~~Became~~ Re-fill GTS phosphorus tank w/ 5# of TSP and 50 gal of potable water. |
| 1155 | - Decant T-351 to top value. Wetwell activated. Water is Clear No color |
| | - Clean pH-315 probe w/ Acid solution. Check the HMI-30 for oil or sheen: None observed. Spray down weir. |
| | - Check TP-130 for oily globules: None observed. Water is clear w/ yellow-green tint. |
| 1207 | - TP-150 Molybdenum HACH value = 10 ug/L |

Influent Sources and Flow Rates: @0345
NBBW – 7.6 gpm
North End On Site- 13.1 gpm
North End Off-Site – 2.6 gpm
RWST – 0.6 gpm
NTES – 0.51 gpm(10R only)
MW38 T-540/541 – 0.30 gpm(Source well and 38 pumping wells mix)
MW38 N & S– 1.2 gpm
COND/NTES T-530- 0.0 gpm(6am-1pm daily)
MW113 Area – 2.0 gpm

Operator: **Mike Gelwick / Chris Carlson**

# LOWRY WTP OPERATIONS LOG

Date: **Wednesday, August 04, 2021**

| Time: | |
|---|---|
| 0620 | Plant operations good - start on weekly GC maintenance and calibrations. |
| 0659 | Stop both MW38N's extraction to prepare for MW38 source well batch extraction. |
| 0700 | Shutdown UV-OX to prepare for planned high voltage outage later today for relocation of underground line near DADS scales. |
| 0720 | -TP-150 molybdenum HACH value 0 0 ug/L |
| 0727 | -Decant T-551 TO TOP valve, wet well activated, water IS clear NO color. |
| | -Clean pH-315 probe w/ Acid solution, check TPH-80 for oil or sheen: none observed. Spray down weir. |
| | -check TPH-30 for oil globules: None observed. water IS clear w/ yellow-green tint. |
| | -Refill polymer TANK w/ 2 cups of NALCO polymer and 200 gal of potable water. |
| 0745 | Switch MW38 from direct HMR-30 influent to T-540/541 then start MW38 source well extraction. |
| 0748 | Stop MW170-EW-1 extraction |
| 0750 | Shutdown plant - Kill MB Main plant power. RWST generator starting up - All ok. |
| ↓ | Kill Bio building power - backup generator ON - All ok. Note: NTES backup generator |
| | running also. |
| 0850 | Shutdown HMIFTVIEW1 CPU (PLC traffic lagging with it on and some PLC's down). |
| | Mike working on flushing P-005 / P-006 / NTES feed line to BTS sediment tank and reactor feed lines. |
| 1527 | Restart HMIFTVIEW1 CPU - Weekly WTP data backup. |
| 1710 | Power restored - switch off from backup power to utility - restart compressor - Unable to get UV-ox PLC to full power up. Power and input cards rapidly flashing. Power cycling PLC CPU not working. |
| 1732 | Restart plant without UV-ox. UV-ox PLC CPU restored normal start by itself after leaving it ~~alone~~ alone (made notes to ask Calgon about it - possibly old stepped out diodes on circuit board(? |

Influent Sources and Flow Rates: @ 0658
NBBW – 7.6 gpm
North End On Site- 13.1 gpm
North End Off-Site – 8.9 gpm
RWST – 0.6 gpm
NTES – 0.52 gpm(10R only)
MW38 T-540/541 – 0.3 gpm(Source well and 38 pumping wells mix)
MW38 N & S– 2.2 gpm
COND/NTES T-530- 0.2 gpm(6am-1pm daily)
MW113 Area – 2.0 gpm

Operator: **Mike Gelwick / Chris Carlson**

## LOWRY WTP OPERATIONS LOG

Date: Wednesday, August 04, 2021 (continued)

| Time: | |
|---|---|
| 1808 | Start UV-OX warm up. Mike going around site and restarting extractions / taking NTES off generator power. Set RWST influent to 3.0 gpm tonight while MW38 N's & S remain off for Source well batch extraction (T-540/541 @ 46%.) will leave source well running overnight - also leaving *P-006 off tonight so BTS can recover from downtime without source well water running into it. |
| 1905 | Plant operations good. |
| 2100 | - Receive BTS Overflow TANK High Alarm. Log in remotely and set things going Again, Increase BTS to Plant % to 19%. From 17%. Set TANK High to 95% to Clear Alarm<br>- Blend Ratio Alarm came out during overflow TANK pumping down and I had BTD out of Hold. Reset TANK set point to 73% to get flows regulated and put back to 30% once Alarm Cleared out. Overflow High level set back to 90% |
| 2145 | - All ok. Plants operations Good. |

Influent Sources and Flow Rates: @ 1905
NBBW – 7.6 gpm
North End On Site- 13.5 gpm
North End Off-Site – 8.4 gpm
RWST – 3.0 gpm
NTES – 0.51 gpm(10R only)
*MW38 T-540/541 – 0.0 gpm(Source well and 38 pumping wells mix)
MW38 N & S– 0.0 gpm
COND/NTES T-530- 0.0 gpm(~~Send 1gpm daily~~)
MW113 Area – 2.0 gpm

OPERATOR Chris Carlson / Mike Gelenick

# LOWRY WTP OPERATIONS LOG

Date: **Thursday, August 05, 2021**

| Time: | |
|---|---|
| 0640 | - Plants operations Good. MW113-EW-1 flow has slowed down slightly, will Adjust to slightly more than 2.1 gpm |
| 0730 | - Increase psi on MW113-EW-1 to 45psi. will Adjust later if needed to maintain a more stable flow. |
| 0950 | - Working on weekly Plants System checks and calibrations. looks like MW113-EW-1 needs a slight bit more adjustment. TANK filling too quickly, will decrease ~~psi~~ to 42psi. |
| 1030 | - Decant T-351 to TOP valve. wetwell activated. water is clear no color. |
| | - Clean pH-315 probe w/ Acid solution, check the HMI30 for oil or sheen; none observed. spray down area. |
| | - Check TP130 for oil globules; none observed. water is clear w/ yellow-green tint. |
| 1115 | - STOP MW38 source well Batch. MW113-EW-1 flow currently Good where it is @. Dosing slightly more than 2.1 gpm. |
| 1155 | - Restart MW38 N+S wells pumping to T-540/541 until at least 600 gal thru pipeline to displace any residual MW38 source well waters. |
| 1331 | - Suspend Plant Discharge to calibrate pH-740 probe to 4+10 pH STD's. |
| 1339 | - Resume Normal Discharge. Continue with other WTP pH probes calibrations to 4+10 pH STD's @ pH-113, 670, 310, 315 + 365. |
| 1425 | - Plants weekly systems checks and calibrations complete. |
| 1430 | - Change out 1 micron Bag Filter in front of T-113 (MW113-EW-1 INF) with a new 1 micron bag filter. Flow slowed down during change out due to tank level pumping down. |
| 1452 | - TP-150 Molybdenum HACH value @ 0 ug/L |
| 1510 | - Plants operations Good. |

Influent Sources and Flow Rates: @0645
NBBW – 7.6 gpm
North End On Site- 13.3 gpm
North End Off-Site – 8.7 gpm
RWST – 3.0 gpm
NTES – 0.51 gpm(10R only)
MW38 T-540/541 – 0.0 gpm(Source well and 38 pumping wells mix)
MW38 ~~N & S~~ – 5.1 gpm source well to T540/541
COND/NTES T-530- 0.21 gpm(6am-1pm daily)
MW113 Area – 1.4 gpm

Operator: **Mike Gelwick** /~~**Chris Carlson**~~

# LOWRY WTP OPERATIONS LOG

Date: **Friday, August 06, 2021**

| Time: | |
|---|---|
| 0620 | - Plants operations Good. MW113-EW-1 flow a little to High. Filling TANK ~ Every 3 Hrs. will adjust down slightly to get closer to 2.1 gpm. |
| 0628 | - START P-006/T-540-541 @ 0.20 gpm |
| 0630 | - Switch manual valves on MW38 to HMR30 and switch MW38 N+S wells to HMR30 mode. Turndown RWST Flow to 0.60 gpm |
| 0645 | - work w/ TOM to PUT a NEW TOTE of $Na_2OH$ on Line on chemical BAY. |
| 0730 | - Very Minor Decrease on psi @ MW113-EW-1. TANK STILL Filling but much slower. Slightly more than 2.1 gpm coming from MW113-EW-1. |
| | - Automatic blowdown operations Good. |
| 0940 | - Recount T-351 TO TOP valve. Wet well activated. water is clear no color. |
| | - Clean pH-315 probe w/ Acid Solution. Check the HMR30 for oil or sheen: None observed. Spray down well. |
| | - Check TP-130 for oil globules: None observed. water is clear w/ yellow green tint. |
| 1010 | - TP-150 Molybdenum HACH value 0 ug/L |
| 1110 | - Plants operations Good |

Influent Sources and Flow Rates: @ 0810
NBBW – 7.6 gpm
North End On Site- 13.2 gpm
North End Off-Site – 8.6 gpm
RWST – 0.6 gpm
NTES – 0.51 gpm(10R only)
MW38 T-540/541 – 0.20 gpm(Source well and 38 pumping wells mix)
MW38 N & S– 2.3 gpm
COND/NTES T-530- 0.20 gpm(6am-1pm daily)
MW113 Area – 2.1 gpm

Operator: **Mike Gelwick / ~~Chris Carlson~~**

## LOWRY WTP OPERATIONS LOG

Date: August 7, 2021

| Time: | |
|---|---|
| 1100 | Plants operations good. |
| 1150 | Decant T-351 from top valve, wet well activated, water is clear, no color. |
| | Clean pH-315 probe with acid solution. |
| | Check HMR-30 for oil sheen: none observed, spray down weir. |
| | Check TP-130 for oil globules: none observed. Water is clear with light yellow-greenish tint. |
| 1215 | TP-150 Molybdenum HACH test: result: 0 ug/L |
| 1230 | Refill phosphorus tank with 5# TSP and 50 gal of water. |
| | Both GC's operational within limits. |
| | All blowers ok. |
| 1330 | Plants operations good. |

Influent Sources and Flow Rates: @ 1130
NBBW – 7.5 gpm
North End On Site- 13.2 gpm
North End Off-Site – 8.6 gpm
RWST – 0.6 gpm
NTES – 0.5 gpm(10R only)
MW38 T-540/541 – 0.2 gpm(Source well and 38 pumping wells mix)
MW38 N & S– 2.3 gpm
COND/NTES T-530- 0.2 gpm(6am-1pm daily)
MW113 Area – 2.0 gpm

OPERATOR Manuela Seewald

# LOWRY WTP OPERATIONS LOG

Date: August 9, 2021

| Time: | |
|---|---|
| 0800 | Plant operations good. |
| 0900 | - Decant T-351 from top valve, wet well activated. Water is clear no color |
| | - Clean pH 315 probe w/ Muriatic Acid solution. Check HMR30 for oil or sheens |
| | - checked TP-130 for oil globules: ↳ none observed, Sprayed down weir |
| [redacted] | ↳ none observed → water is clear w/ yellow-green tint |
| 0930 | TP-150 molybdenum Hach Value @ 0 ug/L ~~after 429,303 gallons treated~~ |
| 1000 | Replaced V-326 Sparger air connection valve → was snapped upon arrival. |
| 1230 | @ shed 15 → no air in compressor. Troubleshoot → motor would not reset → turned on blue back up compressor. Will return later to ensure operation ok |
| 1600 | Back up Compressor running ok. Extraction wells are cycling Tank 15 level @ 35% |
| 1700 | Plant operations good. |

Influent Sources and Flow Rates: @0830
NBBW – 7.5 gpm
North End On Site- 13.2 gpm
North End Off-Site – 8.6 gpm
RWST – .6 gpm
NTES – .52 gpm(10R only)
MW38 T-540/541 – .30 gpm(Source well and 38 pumping wells mix)
MW38 N & S– 2.2 gpm
COND/NTES T-530- 0.20 gpm(6am-1pm daily)
MW113 Area – 2.1 gpm

OPERATOR Tom Gilbert

# LOWRY WTP OPERATIONS LOG

Date: **Tuesday, August 10, 2021**

| Time: 0530 | Plant operations good. Start on weekly efficiency checks and IX performance sampling. |
|---|---|
| 0610 | IX performance with lab splits after 431,640 gallons treated. TP-183 @ 110 ug/L; |
| ↓ | TP-174A @ 130 ug/L; TP-173A @ 6,000 ug/L and TP-170 @ 6,900 ug/L. Tom preparing |
| ↓ | for weekly BTS performance sampling / field readings |
| 0735 | Blowdown operations good. |
| 0740 | TP-150 molybdenum Hach reading @ 0 ug/L. |
| 1340 | Tom refilling phosphorus tank with 30 gallons potable water + 5lbs TSP. |
| ↓ | Decant T-351 top valve, wet well activated. Water is clear, no color. Clean the HMR-30 |
| ↓ | weir and pH probe - no oil or sheen observed in the HMR-30. Check TP-130 for oil globules |
| ↓ | none observed - water is clear, light yellow/green. |
| 1515 | Plant operations good. End. |

Influent Sources and Flow Rates: 0655
NBBW – 7.5GPM
N. END ON-SITE – 13.1GPM
N. END OFF-SITE – 8.3GPM
RWST – 0.6GPM
NTES – 0.51GPM
COND/NTES T-530 – 0.2GPM(6AM–1PM)
MW38 – 2.4GPM
T-540/541 – 0.3GPM
MW113 IX SYSTEM – 2.0GPM
OTHER – NA

OPERATOR(S) Chris Carlson / Tom Gilbert

# LOWRY WTP OPERATIONS LOG

Date: **Wednesday, August 11, 2021**

| | |
|---|---|
| Time: 0525 | Plant operations good. Start on weekly GC maintenance and calibrations. |
| 0649 | Reboot HMIFTVIEW1 to install latest virus software program update, Online 0659. |
| ↓ | Work on adding Tom Gilbert to alarm callouts. |
| 0740 | Blowdown operations good. |
| 0845 | Decant T-351 top valve, wet well activated. Water is clear, no color. Clean the HMP-30 weir and pH probe - no oil or sheen observed in the HMP-30. Check TP-130 for oil globules - NONE observed. Water is clear, light yellow/green. |
| ↓ | |
| 0855 | TP-150 molybdenum bleach valve reading 0 ug/L. |
| 1230 | Weekly WTP data backed up to Flash & CD. Automatic daily cloud backup working well. |
| 1600 | Plant operations good. UV-ox peroxide feed pump needed priming - All okay. |

Influent Sources and Flow Rates: 0537
NBBW – 7.5GPM
N. END ON-SITE – 13.1GPM
N. END OFF-SITE – 8.6GPM
RWST – 0.6GPM
NTES – 0.51GPM
COND/NTES T-530 – 0.2GPM(6AM–1PM)
MW38 – 2.2GPM
T-540/541 – 0.3GPM
MW113 IX SYSTEM – 2.0GPM
OTHER – NA

OPERATOR(S) Chris Carlson

# LOWRY WTP OPERATIONS LOG

Date: **Thursday, August 12, 2021**

| | |
|---|---|
| Time: 0540 | Plant operations good. Start on weekly systems checks & calibrations |
| 0650 | Decant T-351 top valve, wet well click not activate. Water is clear, no color. |
| ↓ | Clean the HMR-30 weir and pH probe - no oil or sheen observed in the HMR-30. |
| ↓ | Check TP-130 for oil globules - none observed. Water is clear, light green/yellow. |
| 0810 | Blowdown operations good. Tom given training on remotely accessing the plant |
| ↓ | computers and will be taking remote access computer #3 home with him today. |
| 1030 | Jim B. of Brown Hill on site to complete OneDay database on HMI2 - Also have him |
| ↓ | add a tag for N.End on site daily total to OneDay databases. |
| 1055 | Reboot HMI2 - online 1057. Jim done - leaving site |
| 1126 | HMI2 needed second reboot - online 1128. |
| 1135 | Reboot HMIFTVIEW1 to accept change of added tag. - online @ 1139. |
| 1146 | Suspend discharge for pH-740 calibration. |
| 1157 | pH-740 calibration completed - resume normal discharge - Continue on pH calibrations |
| ↓ | at pH-670, 113, 310, 315 & pH-365 |
| 1218 | Weekly check completed. |
| 1225 | TP-150 moly Hach value reading 0 ug/L |

Influent Sources and Flow Rates: 0550
NBBW – 7.5GPM
N. END ON-SITE – 13.0GPM
N. END OFF-SITE – 8.7GPM
RWST – 0.6GPM
NTES – 0.51GPM
COND/NTES T-530 – 0.2GPM(6AM–1PM)
MW38 – 2.2GPM
T-540/541 – 0.3GPM
MW113 IX SYSTEM – 2.0GPM
OTHER – NA

OPERATOR(S) Chris Carlson

# LOWRY WTP OPERATIONS LOG

Date: Friday, August 13, 2021

| Time: | |
|---|---|
| 0800 | Plant operations good. Starting on plant dailys |
| 0830 | TP-150 molybdenum Hach value reading Ø ug/L |
| 0845 | Decant T-351 from top valve, wet well activated. Water is clear - no color |
| | Clean HMR-30 probe with Acid Solution, Sprayed weir holes with water - good flow |
| | Visually Inspected HMR-30 chamber - No oil or sheens observed |
| | Checked TP-130 for oil globules - none observed - water is clear w/ slight yellow tint |
| 1400 | Plant operations good. |


Influent Sources and Flow Rates: 0815
NBBW – 7.4 gpm
N. END ON-SITE – 13.0 gpm
N. END OFF-SITE – 8.6 gpm
RWST – 0.6 gpm
NTES – 0.52 gpm
COND/NTES T-530 – 0.21 gpm
MW38 – 2.2 gpm
T-540/541 – .29 gpm
OTHER – NA
MW113 Ix - 2.0 gpm

OPERATOR(S) _____

# LOWRY WTP OPERATIONS LOG

Date: Saturday, August 14, 2021

| | |
|---|---|
| 1015 | Plant operations good. Start weekend operations dutys |
| | Decant T-351 from top valve, wet well activated. Water is clear - no color |
| | Clean HMR-30 probe w/ Muriatic acid solution. Sprayed weir with water - good flow |
| | Visually inspected HMR-30 chamber for oil or sheens - none observed |
| | Checked TP-130 for oil globules - none observed - water is clear w/ slight yellow-green tint |
| 1230 | TP-150 molybdenum Hach value reading Ø ug/L |
| 1320 | Plant operations good. |
| (W) 0630 | Check plant remotely - All okay. |
| 1650 | Check plant remotely - All okay. |
| 8/15/21 0900 | Check plant remotely - All okay. |
| 1750 | Check plant remotely - MW38N reached it's low level stop @ 1650, increase RWST influent from 0.6 gpm to 1.0 gpm |



Influent Sources and Flow Rates: 1030
NBBW – 7.5 gpm
N. END ON-SITE – 13.1 gpm
N. END OFF-SITE – 8.7 gpm
RWST – 0.6 gpm
NTES – 0.51 gpm
COND/NTES T-530 – 0.20 gpm
MW38 – 2.2 gpm
T-540/541 – 0.30 gpm
OTHER – NA
MW113 Ix system - 2.0 gpm

OPERATOR(S) Tom Gilbert / Chris Carlson

# LOWRY WTP OPERATIONS LOG

Date: **Monday, August 16, 2021**

| Time: | |
|---|---|
| 0600 | Plant operations good. |
| 0624 | Windows error RSVIEW Project Manager Stopped on HMI2 - Reboot. Online okay @ 0627. |
| 0720 | Observe MW38 N well has reached it's high level restart setpoint, extraction @ 1.0 gpm. reduce RWST from 1.0 gpm to 0.6 gpm. Observe T-530 level at 21', place P-005 on standby. |
| 0735 | Blowdown operations good. Start on P-114 upgrade - |
| 0820 | - Decant T-351 to TP valve. clear well activated. water IS clear no color |
| | - clean PH-315 probe w/Acid solution. check TK HMW30 for oil or sheen: None observed. Spray down weir |
| | - check TP-130 for oily globules: None observed. water IS very clear w/light yellow tint. |
| 0850 | - TP-150 molybdenum HACH value > 10 ug/L |
| 0921 | Shutdown Ex system after 1149656 gallons treated. Swap out P-114 pump with a new pump that can pump 4 GPM - |
| 1102 | Restart Ex system with new pump - will keep slow at 2 gpm until after tomorrows lab samples are collected. |
| 1200 | New pump working very well - no leaks CV @ 27%. at 2.0 gpm and 56.8 psi. |
| 1500 | Plants operations Good. |

Influent Sources and Flow Rates: @ 0730
NBBW – 7.5 gpm
North End On Site- 13.0 gpm
North End Off-Site – 8.3 gpm
RWST – 0.6 gpm
NTES – 0.5 gpm(10R only)
MW38 T-540/541 – 0.3 gpm(Source well and 38 pumping wells mix)
MW38 N & S– 2.3 gpm
COND/NTES T-530- 0.0 gpm ~~(6am-1pm daily)~~
MW113 Area – 2.0 gpm

Operator: **Mike Gelwick / Chris Carlson**

# LOWRY WTP OPERATIONS LOG

Date: **Tuesday, August 17, 2021**

| Time: | |
|---|---|
| 0530 | Plant operations good. |
| 0630 | Mike working on weekly efficiency sampling. |
| 0723 | Mike starting weekly IX performance sampling after 452,131 gallons treated. |
| ↓ | TP-183 @ 100 ug/L, TP-174A @ 340 ug/L, TP-173A @ 5,800 ug/L and TP-170 @ 6,500 ug/L |
| ↓ | (All Hach test split with samples to be sent to the lab). |
| 0805 | TP-150 molybdenum Hach value reading 0 ug/L. TOM working on weekly BTS sampling and readings. |
| 0809 | Shutdown IX system to take column #1 offline, Note: TP-173A sample port moved |
| ↓ | to after column #2 which is now the lead column. IX Total treated @ 452,227 gal. |
| 0833 | Restart IX System @ 2 GPM. |
| 0843 | P-114 CV% @ 26%; PIT-113 @ 54.1 PSI TP-173A (post lead column 2) Hach value reading 530 ug/L |
| 0900 | IX system @ 452,282 gallons. Increase flow from 2 gpm to 3 gpm. |
| 0915 | P-114 CV @ 52%; PIT-113 @ 85.8 psi Flow @ 3.0 gpm (Mike has increased rate at MW113-FW-1 also). pH control adjusting to higher operating pressure, currently 4.2 and dropping slowly. Note: Higher pressure is throughout the system PIT-113 in same as columns IN. |
| 1035 | - Decant T-351 to TSP valve. Wet well activated water is clear no color. |
| | - Clean pH-315 probe w/ Acid solution. Check the HMI-30 for oil or sheen: None observed. Spray down wash. |
| | - Check TP-130 for oil globules: None observed. Water is very clear w/ light yellow tint |
| 1115 | - Refill BTS phosphate tank w/ 5 gal of TSP and 50 gal of potable water |
| 1207 | - Switch NTES to T-530 and START T-530 @ 0.50 gpm to BTS. while I work on MPZ-10R pump swap |
| 1335 | - Switch NTES BACK TO Normal and turn T-530 BACK OFF. MPZ-10R pump swapped. |
| 1515 | - Plants operations Normal. Chris Checking Discharge Line 4x8" leak detections and vaults and |
| | POTW MH175-078 Discharge manhole today. All ok. |

Influent Sources and Flow Rates: @0645
NBBW – 7.5 gpm
North End On Site- 13.0 gpm
North End Off-Site – 8.3 gpm
RWST – 0.6 gpm
NTES – 0.51 gpm(10R only)
MW38 T-540/541 – 0.3 gpm(Source well and 38 pumping wells mix)
MW38 N & S– 2.3 gpm
COND/NTES T-530- 0.0 gpm ~~(Sent 1pm daily)~~
MW113 Area – 2.0 gpm

Operator: **Mike Gelwick / Chris Carlson**

# LOWRY WTP OPERATIONS LOG

Date: **Wednesday, August 18, 2021**

| Time: | |
|---|---|
| 0540 ↓ | Plant operations good. Note: IX system @ 90 psi at 2.8 gpm. Start on weekly GC maintenance and calibrations. |
| 0608 ~~0608~~ ↓ | Check moly after lead column, reading 580 ug/L (working very well, influent concentration running at 6,500 ug/L yesterday). Currently P-114 CV @ 47%. at 90.0 psi - flow 2.8 gpm. |
| 0615 ↓ | Shutdown IX system - take columns #6, 7, 8 & 9 offline (place on standby for later use). IX treatment total at 455,970 gallons. |
| 0630 | Restart with Columns #2 (lead now that column #1 offline), #3, #4, #5 & Guard column. |
| 0635 | Flow set to 3.0 gpm. P-114 CV @ 51%. at 59.1 psi. |
| 0640 | Flow set to 3.5 gpm. P-114 CV @ 63%. at 69.5 psi |
| 0645 | Flow set to 4.0 gpm. P-114 CV @ 75%. at 79.0 psi |
| 0715 ↓ | 4.0 gpm. P-114 CV @ 75%. at 78.7 psi - Mike increasing MW113-EW-1 extraction in the Field to keep up with 4 GPM rate. |
| 0910 | TP-150 molybdenum Hach value reading 0 ug/L. |
| 0920 | Check IX performance with Hach test at 4 gpm and 456,640 gallons treated. TP-153 @ 80 ug/L; TP-175A @ 180 ug/L; TP-174A @ 360 ug/L; TP-173A @ 690 ug/L and TP-170 @ 8,300 ug/L. Column #2 (lead) working very well at 4 GPM. Note: Observe T-113 level dropping at 4 GPM. Extraction well MW113-EW-1 maxed out at slightly less than 4 GPM. IX system will begin to auto regulate to the flow when tank level reaches 30%. |
| 1125 | - Decant T-351 to TOP valve. Wet well activated. water IS clear NO color. |
| | - clean pH-315 probe w/ fresh solution. check the HMW30 for oil or sheen: NONE observed. Sump shows water |
| | - Check TP-130 for oil globules: NONE observed. water IS very clear w/ slight yellow tint |
| 1500 | - Plants operations Good |

Influent Sources and Flow Rates: @ 0740
NBBW – 7.4 gpm
North End On Site- 13.0 gpm
North End Off-Site – 8.2 gpm
RWST – 0.6 gpm
NTES – 0.5 gpm(10R only)
MW38 T-540/541 – 0.3 gpm(Source well and 38 pumping wells mix)
MW38 N & S– 2.2 gpm
COND/NTES T-530- 0.0 gpm ~~(Gam-1pm daily)~~
MW113 Area – 4.0 gpm

Operator: **Mike Gelwick / Chris Carlson**

0.39" rain
P.M.-

# LOWRY WTP OPERATIONS LOG

Date: **Thursday, August 19, 2021**

| Time: | |
|---|---|
| 0700 | - Plants operations Good. Automatic Blowdown operations Good. IX Systems operations Good. Flow Fluctuating Between 3.5 + 4.0 gpm. |
| 0825 | - Checking IX Performance ⇒ 4 gpm After 461,963 gal treated: TP-173A ⇒ 540 ug/L. (Low Range HACH test) |
| 0835 | - TP-150 molybdenum HACH value ⇒ 0 ug/L. Working on Plants Systems checks and calibrations today. |
| 1000 | - Decant T-351 to TOP valve. Wet well activated. Water IS clear no color |
| | - Clean pH-315 probe w/Acid Solution. Check THE HMI 50 for oil or sheen: None observed. Spray down wash |
| | - Check TP-130 for oil globules: None observed. water IS very clear w/yellow tint. |
| 1315 | - Suspend Plant Discharge to calibrate pH-740 Probe to 4+10 pH STD's. |
| 1320 | - Resume Normal Discharge. Continue with Other WTP pH probes calibrations to 4+10 pH STD ⇒ pH-113, 370, 310, 315 + 365. |
| 1410 | - Plants weekly Systems checks and calibrations Complete. |
| 1500 | - Plants operations Good. |

Influent Sources and Flow Rates: @ 0810
NBBW – 7.5 gpm
North End On Site- 12.9 gpm
North End Off-Site – 8.1 gpm
RWST – 0.6 gpm
NTES – 0.49 gpm(10R only)
MW38 T-540/541 – 0.29 gpm(Source well and 38 pumping wells mix)
MW38 N & S– 2.2 gpm
COND/NTES T-530- 0.0 gpm(~~6gpm – 1gpm daily~~)
MW113 Area – 3.80 gpm

Operator: **Mike Gelwick / ~~Chris Carlson~~**

0.14" rain overnight

# LOWRY WTP OPERATIONS LOG

Date: Friday, August 20, 2021

| | |
|---|---|
| Time: 0530 | Plant operations good. |
| 0600 | Jim B of Brownshill onsite to troubleshoot OneDay data backup on HMI 2. |
| 0648 | Reboot HMI 2 after VBA & OneDay fixes. 0651 online. Jim waiting for 7AM blowdown / |
| ↓ | data backup to verify fixes worked. |
| 0708 | OneDay data backed up correctly. Jim leaving. |
| 0653 | - IX system performance HACH testing after 4671039al treated: TP-1731 → 430 ug/L |
| 0700 | - TP-150 molybdenum HACH value → 0 ug/L |
| 0830 | - Decant T-351 to TOP valve. wet well activated. water is clear no odor. |
| | - clean pH-315 probe w/ferric solution. check the HMI 30 for oil or sheen: none observed. Spray down wash. |
| | - check TP-130 for oil globules: None observed. water is very clear w/ light yellow tint. |
| | - Refill polymer tank w/ 2 cups of NALCO polymer and 200gal of potable water |
| | - working on back wash of lead GAC-720. Pressure up to 20psi. |
| 0845 | - Reduce flow on P-522 to 20gpm. will work up to max flow slowly. |
| 0935 | - Backwash of GAC-720 complete. Pressure down to 6psi 239.5gpm. |
| 1110 | - Decant T-351 to top valve again. wet well activated. water is clear no odor. |
| 1120 | - Place BTS into maint hold and flush reactor feed lines |
| 1155 | - Resume normal BTS operations. |
| 1235 | - Plants operations Good. |

Influent Sources and Flow Rates: 0600
NBBW – 7.5GPM
N. END ON-SITE – 12.9GPM
N. END OFF-SITE – 8.1GPM
RWST – 0.6GPM
NTES – 0.51GPM
COND/NTES T-530 – 0.0GPM
MW38 – 2.2GPM
T-540/541 – 0.3GPM
MW113 IX SYSTEM – 4.0GPM
OTHER – NA

OPERATOR(S) Chris Carlson / Mike Gelwick

0.19" rain today

# LOWRY WTP OPERATIONS LOG

Date: SATURDAY, AUGUST 21, 2021

| | |
|---|---|
| 0715 | - Plants operations Good. Automatic blowdown operations Good. Go to check other 5.7c systems. |
| 0840 | - IX Performance HACH TESTING AFTER 472984 gal TREATED: TP-173A ⇒ 510 ug/L. |
| 0850 | - TP-150 Molybdenum HACH value ⇒ 0 ug/L |
| 0855 | - Decant T-351 to top valve. WATER well activated. Water B3 clear NO color. |
| | - Clean pH-315 probe w/ Acid solution. Check TIH HOMES for oil or sheen: None observed. Spray down water. |
| | - Check TM-130 for oil globules: None observed. water B3 very clear w/ light yellow-green tint. |
| 0915 | - Refill BT3 phosphorus tank w/ 6# of TSP and 60 gal of potable water. All blowers OK. Both GAC operational w/ typical limits. Bag filter operations Good |
| 1000 | - Plants operations Good. |

Influent Sources and Flow Rates: 0830
NBBW – 7.5 gpm
N. END ON-SITE – 12.9 gpm
N. END OFF-SITE – 8.4 gpm
RWST – 0.6 gpm
NTES – 0.50 gpm
COND/NTES T-530 – 0.0 gpm
MW38 – 2.2 gpm
T-540/541 – 0.31 gpm
OTHER – NA
IX / MW13 Area – 3.8 gpm

OPERATOR(S) Mike Gatewood

# LOWRY WTP OPERATIONS LOG

Date: **Monday, August 23, 2021**

| Time: | |
|---|---|
| 0540 | Plant operations good. |
| 0700 | - Automatic blowdown operations Good. Working on Qtrly Building Methane SAFety checks today 5.7ppm/wtr. |
| 0754 | - IX performance HACH testing After 4836 15 gal treated: TP-173A → 720 ug/L. |
| 0800 | - TP-150 Molybdenum HACH value → 0 ug/L. |
| 0820 | - Decant T-351 to top valve. wet well activated water IS clear No color. |
| | - Clean pH-315 probe w/Acid solution. Check the HAL30 for oil or sheen: None observed. Spray down water. |
| | - check TA130 for oil globules: None observed. water IS very clear w/yellow green tint. |
| 1300 | - Sludge Roll off Box Dumped/Emptied |
| 1515 | - Plants operations Good. |

Influent Sources and Flow Rates: @0645
NBBW – 7.4 gpm
North End On Site- 12.7 gpm
North End Off-Site – 8.2 gpm
RWST – 0.6 gpm
NTES – 0.50 gpm(10R only)
MW38 T-540/541 – 0.30 gpm(Source well and 38 pumping wells mix)
MW38 N & S– 2.2 gpm
COND/NTES T-530- 0.0 gpm~~(6am-1pm daily)~~
MW113 Area – 3.9 gpm

Operator: **Mike Gelwick / Chris Carlson**

# LOWRY WTP OPERATIONS LOG

Date: **Tuesday, August 24, 2021**

| Time: | |
|---|---|
| 0500 | - Plants operations Good. Working on TP-730 GAC/LAB SAMPLE SPLIT + TP-740-710 1,4-Dioxane SAMPLES and START Efficiency checks |
| 0530 | Observe MW38S well reached it's low level stop this MORNING at 0500. INCREASE RWST INFLUENT from 0.6 gpm to 1.6 gpm while it's off and recharging. |
| 0710 | Blowdown operations good. |
| 0915 | Metro sampling technicians on site to setup MP-001 auto sampler(s). |
| 0845 | - IX performance HACH testing and Lab sample splits After 489254 gal treated: TP-183 = 130 ug/L; TP-174A = 160 ug/L; TP-173A = 830 ug/L; TP-170 = 5800 ug/L (using Low Range test on TP-183, 174A + 173A) |
| 0915 | - TP-150 Molybdenum HACH value = 0 ug/L, TOM working on BTS sampling and field Readings today |
| 1000 | - Decant T-551 to TOP valve. Wet well activated. Water is clear No color |
| | - Clean pH-315 probe w/Acid solution. Check the Hands for oil or sheen: NONE observed. Spray down mat. |
| | - Check TP-130 for oil globules: NONE observed. water IS very clear w/Light yellow-green tint. |
| 1020 | - Line Sludge Roll off Box R18306 ML w/Plastic sheeting. |
| 1145 | Change out both 1 micron bags on IX system. High rate and lowering levels in the MW113 Area ~~stirring~~ stirring up sediments. |
| 1340 | - Working on Empty out Sludge press. |
| 1515 | Press cleanout completed - plant operations good. |

Influent Sources and Flow Rates: @ 0535
NBBW – 7.4 gpm
North End On Site- 12.7 gpm
North End Off-Site – 8.7 gpm
RWST – 0.6 gpm
NTES – 0.50 gpm(10R only)
MW38 T-540/541 – 0.31 gpm(Source well and 38 pumping wells mix)
MW38 N & S– 1.2 gpm
COND/NTES T-530- 0.0 gpm(6am-1pm daily)
MW113 Area – 3.9 gpm

Operator: **Mike Gelwick / Chris Carlson**

# LOWRY WTP OPERATIONS LOG

Date: **Wednesday, August 25, 2021**

| Time: 0048 | Receive GC2 comm alarm - access remotely to acknowledge alarm. GC2 CPU has |
|---|---|
| ↓ | rebooted after a Windows error. Restart GC2 sampling TP-730 at 0059 - All okay. |
| 0540 | Plant operations good - start weekly GC maintenance and calibrations. |
| 0618 | Reboot HMIFTVIEW1 to reset available temporary memory. Online @ 0622. |
| 0714 | Receive Heartbeat ERR2 alarm - HMI2 has rebooted itself after a Windows error (very |
| ↓ | similar to GC2 last night). HMI2 online again at 0717. |
| 0730 | Start Filterpress on T-351 (in stage 1). |
| 0735 | Metro Sample technicians on site. |
| 0845 | Refill phosphorus tank with 60 gallons potable water + 6lbs TSP. |
| 1000 | Backup plant data to flash & CD. Daily onedrive backup working well. |
| 1010 | Filterpress full. |
| 1018 | Restart MW385 and reduce RWST influent from 1.6 gpm to 0.6 gpm. |
| 1040 | - Clean pH-315 probe w/ Acid solution. Check the Hach 30 for oil or sheen: None observed. Spray down wash |
| | - check the 130 for oil globules: None observed. water is very clear w/ light yellow-green tint. |
| 1055 | - TP-750 Molybdenum HACH value → 0 ug/L |
| 1510 | - Plants operations good. |

Influent Sources and Flow Rates: 0600
NBBW – 7.4GPM
N. END ON-SITE – 12.6GPM
N. END OFF-SITE – 8.5GPM
RWST – 1.6GPM
NTES – 0.50GPM
COND/NTES T-530 – 0.0GPM
MW38 – 1.0GPM
T-540/541 – 0.3GPM
MW113 IX SYSTEM – 3.9GPM
OTHER – NA

OPERATOR(S) Chris Carlson / Mike Gelwicks

# LOWRY WTP OPERATIONS LOG

Date: **Thursday, August 26, 2021**

| | |
|---|---|
| Time: 0535 | Plant operations good. |
| 0745 | Blowdown operations good. Work on adding one full tote of caustic to main plant supply. |
| 0915 | Backwash GACF-3340, completed 0945. |
| 1000 | - working on weekly/monthly plants systems checks and calibrations. Calibrate site multimeter to 49% LEL to use during LEL-740 calibration to ensure T-740 ambient air @ 0% LEL. Change out pH 4+10 STD's w/new. |
| 1045 | - Decant T-351 to topvalve. wetwell activated. water @ BS clear NOC odor. |
| | - Clean pH-315 probe w/Acid solution. Check the Hanelson for oil or sheen: None observed. Spray down wash. |
| | - Check TP-130 for oil globules; none observed. Water @ BS very clear w/light yellow-green tint. |
| 1100 | - TP-150 Molybdenum HACH value @ 0 ug/L |
| 1130 | - START main compressor Max speed Run oil moisture precipitation for 2 hrs |
| 1240 | - Perform monthly BTS pH-probes calibrations w/New 4+10 pH STD's |
| 1330 | - STOP MAX Speed Run of main compressor. Calibrating WTP pH probes to New 4+10 pH STD's @ pH-111, 670, 310, 315 & T65 |
| 1400 | - Suspend plant @ BS charge to calibrate pH-740 probe to 4+10 pH STD's and calibrate LEL-740 sensor to 49% LEL. |
| 1410 | - Plant shutdown @ 8% LEL during LEL-740 sensor calibration. Automatic shutdown operating properly. |
| 1419 | - Restart Plant. |
| 1420 | - Restart Normal Discharge. |
| 1440 | - Plants operations back to normal. |
| 1520 | - Plants operations Good. |

Influent Sources and Flow Rates: 0550
NBBW – 7.4GPM
N. END ON-SITE – 12.6GPM
N. END OFF-SITE – 8.3GPM
RWST – 0.6GPM
NTES – 0.50GPM
COND/NTES T-530 – 0.0GPM
MW38 – 2.2GPM
T-540/541 – 0.3GPM
MW113 IX SYSTEM – 3.8GPM
OTHER – NA

OPERATOR(S) Chris Carlson / Mike Gelwick

# LOWRY WTP OPERATIONS LOG

Date: **Friday, August 27, 2021**

| | |
|---|---|
| Time: 0550 | Plant operations good. Observe MW38N extraction reached it's low level stop late yesterday at ~2100. |
| 0605 | Increase RWST influent from 0.6 gpm to 1.6 gpm. |
| 0625 | Decant T-351 top valve, wet well did not activate. Water is clear, no color. Clean the Hook-30 weir and pH probe - no oil or sheen observed in the Hook-30. Check TP-130 for oil globules - none observed. Water is very clear, light green/yellow. |
| 0640 | Check TP-150 molybdenum value, reading 0 ug/L. Note: NBBW-EW-3 has dewatered and is producing ~0.12 gpm now that gradient has dipped to MW113-EW-1. The threat of molybdenum migrating to NBBW-EW-3 has passed and daily monitoring of TP-150 is no longer needed. NBBW-EW-3 will continue to be sampled quarterly for molybdenum in the field, if possible based on the availability of water to be sampled. |
| 0740 | Blowdown operations good. Empty filter press. |
| 0820 | Press empty |
| 0900 | Plant operations good. |
| 1400 | MW170-EW-1 totalizer reading 0.0 gpm → Extraction OK |
| 1850 | Check plant remotely. Observe MW38N has reached it high level restart. Reduce RWST influent from 0.6 gpm to 1.6 gpm. Plant operations good. |

Influent Sources and Flow Rates: 0556
NBBW – 7.5GPM
N. END ON-SITE – 12.6GPM
N. END OFF-SITE – 8.7GPM
RWST – 0.6GPM
NTES – 0.50GPM
COND/NTES T-530 – 0.0GPM
MW38 – 1.2GPM
T-540/541 – 0.3GPM
MW113 IX SYSTEM – 4.0GPM
OTHER – NA

OPERATOR(S) Chris Carlson

# LOWRY WTP OPERATIONS LOG

Date: **Saturday, August 28, 2021**

| | |
|---|---|
| Time: 0645 | On site for weekend systems checks. Plant operations good. |
| 0810 | Bloudown operations good. Refill phosphorus tank with 40 gallons potable water + 4 lbs TSP. Decant T-351 top valve, wet well activated. Water is clear, no color. Clean the HMR-30 weir and pH probe - no oil or sheen observed in the HMR-30. Check TP-130 for oil globules - none observed. Water is very clear, light green/yellow. |
| 0930 | Shut down T-540/541 to BTS (tanks at 10% & 21%) Will plan for Sourcewell batch extraction on Monday. |
| 1005 | Plant operations good. |
| 1750 | Check plant remotely - HMI2 RSView program stopped responding - reboot CPU remotely. Online okay at 1755. Plant operations good. |
| 8/29/21 0620 | Check plant remotely - All okay. |
| 1810 | Check plant remotely - All okay. |

Influent Sources and Flow Rates: 0812
NBBW – 7.4GPM
N. END ON-SITE – 12.6GPM
N. END OFF-SITE – 8.5GPM
RWST – 0.6GPM
NTES – 0.51GPM
COND/NTES T-530 – 0.0GPM
MW38 – 2.2GPM
T-540/541 – 0.3GPM
MW113 IX SYSTEM – 3.8GPM
OTHER – NA

OPERATOR(S) Chris Carlson

# LOWRY WTP OPERATIONS LOG

Date: **Monday, August 30, 2021**

| Time: 0550 | Plant operations good. |
|---|---|
| 0625 ↓ | Stop both MW38N & S extraction in preperation for MW38 source well batch extraction. |
| 0650 | Increase RWST influent from 0.6 gpm to 2.6 gpm |
| 0715 | Switch MW38 to T-540/541 and start MW38 source well batch extraction. |
| 0740 | Blowdown operations good. |
| 0749 ↓ | Blown high voltage fuse - Plant off. Starlings got into the lightning arrestor on the pole Southeast of the plant. Kuchar called to replace fuse this morning. |
| 0830 ↓ | Jim with Kuchar on site - power restored at 0854. Begin refill air supply - Note, Primary compressor VFD has a high temp warning alarm but control is not working to allow reset - possibly damaged due to power outage - Restore air pressure using backup compressors |
| 0911 | Restart plant |
| 1150 | - Decant T-351 to top valve. wetwell activated, water B3 clear location. |
| | - Clean AH-315 probes w/ Acid solution. Check the hose ID for oil or sheen: None observed. Spray down water. |
| | - Check TP-130 for oily globules: None observed. Water B3 very clear w/ light yellow-green tint. |
| | - Working on set up for BT3 sediment tank feed line flush. |
| 1225 | - BT3 INT in manual Hold to flush sediment tank feed line |
| 1300 | - BT3 out of Hold. START P-006/T-540 @ 0.30 gpm. |
| 1509 | - Plants operations Good. |

Influent Sources and Flow Rates: 0623
NBBW – 7.4GPM
N. END ON-SITE – 12.5GPM
N. END OFF-SITE – 8.2GPM
RWST – 0.6GPM
NTES – 0.51GPM
COND/NTES T-530 – 0.0GPM
MW38 – 2.3GPM
T-540/541 – 0.0GPM
MW113 IX SYSTEM – 3.8GPM
OTHER – NA

OPERATOR(S) Chris Carlson / Mike Gelwick

# LOWRY WTP OPERATIONS LOG

Date: **Tuesday, August 31, 2021**

| Time: | |
|---|---|
| 0530 | - Plants operations Good. Begin working on Efficiency Sampling ⇒ TP-730. Also collect Lowland 1,4-Dioxane ⇒ TP-710 + 740. |
| 0630 | - IX Performance HACH testing w/ Lab Splits After 526768 gal treated: TP-183 ⇒ 140 ug/L; TP-174A ⇒ 200 ug/L TP-173A ⇒ 1690 ug/L using Low Range and 1900 ug/L using High Range; TP-170 ⇒ 5200 ug/L |
| 0800 | - working on BTS Sampling and Field Readings today |
| 0950 | - Decant T-351 to TOP Valve. Wet well activated. Water IS clear no color. |
| | - Clean pH-315 probe w/ Acid solution. Check THE HMEJO for oil or sheen: None observed. Spray down weir. |
| | - Check TP-180 for oil globules: None observed. Water IS very clear w/ light yellow-green tint. |
| 1230 ↓ | IR on site to trouble shoot primary air compressor - combination of LCD screen failed; B-phase primary fuse blown (Cover temp alarm trips when overload trips, overload tripped due to the phase imbalance). LCD screen needed the serial port connection cleaned and tightened) 1330 Unit online and working well IR technician off site. |
| 1430 | - STOP MW38 Source well and START MW38 N+S wells pumping to T-540's to displace any Residual MW38 source well water. (600 gal or more) |
| | - PUT P-005/T-530 IN TO Auto, will START ⇒ 6AM tomorrow. |
| 1510 | - GC2 comm loss Alarm. Reboot pc and restart on sample TP-730 Remotely. |
| 1905 ↓ | Mike switching ~~MW38~~ MW38 N+S to RWSTs after 618 gallons pumped into the conveyance line to displace source well water to T-540/541. |
| 2039 ↓ | Receive Bio GC warning alarm. 1,2-DCA at TP-3350 reading 117 ug/L - Mike to shut off T-540/541 and will try introducing the Fresh source well water into the BTS again tomorrow. |
| 2123 ↓ | Receive GC2 comm loss alarm again - CPU has had another Windows error and rebooted itself - Mike restarting it on TP-730 sampling remotely. |

Influent Sources and Flow Rates: @ 0605
NBBW – 7.4 gpm
North End On Site- 12.9 gpm
North End Off-Site – 8.2 gpm
RWST – 2.6 gpm
NTES – 0.50 gpm(10R only)
MW38 T-540/541 – 0.31 gpm(Source well and 38 pumping wells mix)
MW38 ~~N & S~~ – 5.0 gpm ~~to T-540 Source well~~
COND/NTES T-530- 0.0 gpm(~~6am-1pm daily~~)
MW113 Area – 3.7 gpm

Operator: **Mike Gelwick / Chris Carlson**

# LOWRY WTP OPERATIONS LOG

Date: **Wednesday, September 01, 2021**

| Time: | |
|---|---|
| 0500 | Plant operations good. Start on weekly GC maintenance and calibrations. Refill phos. tank with 60 gallons potable water + 6 lbs TSP. |
| 0530 | Latest TP-3350 (BTS effluent) result just posted and 1,2-DCA back down low at 10 ug/L. |
| 0600 | T-530 to BTS resumed at 0.2 gpm between 6AM - 1PM daily (tank @ 37%). |
| 0725 | Switch MW38N+S from RWSTs to Direct HMR-30 influent and reduce RWST influent from 2.6 gpm to 0.6 gpm - Also set T-540/541 to restart after blowdown at 0.2 gpm to BTS. |
| 0735 | Decant T-351 top valve, wet well activated. Water is clear, no color. Clean the HMR-30 weir and pH probe - no oil or sheen observed in the HMR-30. Check TP-130 for oil globules - none observed. Water is very clear, light green/yellow. |
| 1100 | Weekly data backup to Flash ½ ~~DVD~~ CD completed. Daily OneDrive back working well. |
| 1120 | Weekly GC maintenance and calibrations completed - All Okay |
| 1330 | Work on washing press / Step ~ 2/3 done. |
| 1515 | Plant operations good. |

Influent Sources and Flow Rates: 0655
NBBW – 7.3GPM
N. END ON-SITE – 12.8GPM
N. END OFF-SITE – 8.1GPM
RWST – 2.6GPM
NTES – 0.51GPM
COND/NTES T-530 – 0.2GPM(6AM-1PM)
MW38 – 2.1GPM (to RWSTs)
T-540/541 – 0.0GPM
MW113 IX SYSTEM – 3.7GPM
OTHER – NA

OPERATOR(S) Chris Carlson

0.1" Wed PM.

# LOWRY WTP OPERATIONS LOG

Date: **Thursday, September 02, 2021**

| Time | |
|---|---|
| 0515 | Plant operations good. Observe latest GC result of BTS effluent is normal for 1,2-DCA (Bio adjusting to the fresh source well water). Work on completing press wash-out. |
| ↓ | |
| 0700 | Start press on T-351 (stage 1). |
| 0745 | Blowdown operations good. Mike working on weekly WTP systems checks. |
| 0812 | Increase T-540/541 to BTS from 0.2 gpm to 0.3 gpm. |
| 0830 | - Clean pH-315 probe w/ Acid solution. Check tote Hose 80 for oil or sheen: none observed. Spray down wash. |
| ↓ | - check TP-130 for oil globules: none observed. water is very clear w/ light yellow-green tint. |
| 1000 | Adam Bowers with Brownshill on site to check control lan speeds/connections to see if anything can be done to improve stability when attempting to operate three HMI at once. Third HMI being the second Factory talk (HMI FT2) that will eventually |
| ↓ | replace the old RSVIEW32 HMI2. |
| 1058 | Plant shutdown to upgrade CTL NET switches and |
| 1107 | Reboot HMI FTVIEW1 - online 1110. |
| 1113 | Reboot HMI2 - observed MAIN PLC lag stops when only one HMI is online, adding third will not be possible because MAIN PLC CPU is at it's limits running two HMI's. |
| ↓ | (Network is not the choke point). ~~Acknowledged~~ Adam offsite. |
| 1133 | Restart plant - All Okay except ~~##~~ FV-056 not opening automatically - running in manual unt. Jim can look at it. |
| 215 | - Filter Press to full. |
| 1245 | - Suspend Plant Discharge to calibrate pH-740 probe to 4 & 10 pH STD's. |
| 1255 | - Resume normal Discharge. Continue with other pH probes calibrations to 4 & 10 pH STD's @ pH-113, 670, 310, 315 & 565. |
| 1330 | - Weekly plant systems checks and calibrations complete. |
| 1435 | - START Empty Filter Press |
| 1545 | - Plant operations Good. Finish Press tomorrow. |

Influent Sources and Flow Rates: @0804
NBBW – 7.3 gpm
North End On Site- 13.2 gpm
North End Off-Site – 8.0 gpm
RWST – 0.6 gpm
NTES – 0.52 gpm(10R only)
MW38 T-540/541 – 0.2 gpm(Source well and 38 pumping wells mix)
MW38 N & S– 2.2 gpm
COND/NTES T-530- 0.2 gpm(6am-1pm daily)
MW113 Area – 3.7 gpm

Operator: **Mike Gelwick / Chris Carlson**

0.4" rain P.M

# LOWRY WTP OPERATIONS LOG

Date: **Friday, September 03, 2021**

| Time: | |
|---|---|
| 0715 | -Plants operations Good. Received ONE min Log off Alarm from HMI2. Acknowledged. Automatic Blowdown operations Good. |
| 0840 | -Get STARTed on cleaning up Filter Bags cleanup. No Internet currently. Scale House expansion contractor August Line Trying to get Repaired. |
| 0900 | -No Decant today below TOP valve on T-357. Bottom valve still shutdown |
| | -Clean pH-315 probe w/Acid Solution. Check THC HMI30 for oil or Silicon: None observed. Spray down weir |
| | -Check TP430 for oil globules: None observed. water IS very clear w/Light yellow-green tint. |
| 1100 | -Filter Bags Ready to Fill. |
| 1445 | -Work on setting up Auto Sampler and calibrating EC. Triple Rinse dedicated composite container. will Add Preservative Acid to sample. |
| 1510 | -Plants operations Good. |

Influent Sources and Flow Rates: @ 0835
NBBW – 7.3 gpm
North End On Site- 13.2 gpm
North End Off-Site – 8.2 gpm
RWST – 0.6 gpm
NTES – 0.49 gpm(10R only)
MW38 T-540/541 – 0.30 gpm(Source well and 38 pumping wells mix)
MW38 N & S– 2.2 gpm
COND/NTES T-530- 0.21 gpm(6am-1pm daily)
MW113 Area – 3.7 gpm

Operator: **Mike Gelwick**

# LOWRY WTP OPERATIONS LOG

Date: Sunday, September 05, 2021

| | |
|---|---|
| 1300 | Plants operations good. |
| 1340 | Decant T-351 to top valve wet well activated, water is clear, no color. Clean pH-315 probe with acid solution. Check HMR-30 for oil or sheen: none observed. Spray down weir. Check TP-130 for oil globules: none observed. Water is very clear with light yellow-green tint. Both GC's operational within limits. All Blowers ok. Phosphorus tank was @ 40 gals. Added 6# TSP and 60 gal water. |
| 1530 | Plants operations good. 0800 - Log in remotely Allow. ~~0900~~ 2100 - Log in remotely. GC3 can't see screen. |
| Monday 9-6-21 | |
| 0900 | - log in remotely. Allow. GC3 still can't see screen. |
| 1000 | - Had a power surge or drop momentarily which caused some Alarms. |
| 1015 | - on site to fix things that didn't come back on and also Reboot GC3 computer. Able to see screen remotely Now ok. |
| 1140 | - Plants operations Good |
| 2200 | - log in remotely Allow. |

Influent Sources and Flow Rates: @ 1330
NBBW – 7.4 gpm
N. END ON-SITE – 13.1 gpm
N. END OFF-SITE – 8.3 gpm
RWST – 0.69 gpm
NTES – 0.51 gpm
COND/NTES T-530 – 0.00 gpm
MW38 – 2.2 gpm
T-540/541 – 0.3 gpm
OTHER – NA
MW113 Area: 3.7 gpm

OPERATOR(S) Manuela Seewald / Mike Grelwick

# LOWRY WTP OPERATIONS LOG

Date: **Tuesday, September 07, 2021**

| Time: | |
|---|---|
| 0500 | - Plants Operations Good. START Efficiency check sampling ⇒ TP-730. Also collect TP-710 + 740 Low Level 1,4 Dioxane samples |
| 0700 | - Automatic blowdown operations Good. |
| 0740 | - START Filter Press pumping from T-351. Add preservative to MP-001 composite container for Molybdenum. |
| 0800 | - START Auto Sampler. TOTAL effluent ⇒ 243085701 gal ⇒ 34.3 gpm ⇒ 6.86 SU ⇒ 17.8°C |
| 0915 | - Working on weekly BTS sampling. |
| 1010 | - Working on monthly Early warning sampling. 1040 - TP-150 Molybdenum HACH Value ⇒ 0 ug/L. |
| 1050 | - Working on weekly DX System performance HACH testing w/Lab samples SN 475 After 5645101 gal Treated: TP-183 ⇒ 120 ug/L; TP-174A ⇒ 160 ug/L; TP-173A ⇒ 2900 ug/L; TP-170 ⇒ 4800 ug/L |
| 1150 | - START Flush of MP-201 sample port and check for residual chlorine: None detected. |
| 1200 | - Collect 1st set of time paced grab samples for Low Level 1,4-Dioxane. Water is very clear No odor. Place samples in Fridge. |
| 1205 | - Clean pH-315 probe w/Acid Solution. Check the HMI 30 for oil or sheen: None observed. Spray down well. |
| | - Check TP-130 for oil globules: None observed. water is very clear w/yellow-green tint. |
| | - Refill polymer tank w/200 gal of potable water and 2 cups of NALCO polymer. |
| | - PACK All other samples on Ice for SHIPMENT to Labs |
| 1228 | - GC3 blue screened in middle of sample. Ice bath and Restart on TP-3350. |
| 1243 | - Plant Shut-Down Due to Birds On wires/Fuses blown. Shut things down for a more controlled RESTART. |
| 1320 | - Kucher on site to repair fuses. |
| 1426 | - Restart Plant. All ok. Go to check other site systems. |
| 1550 | - START Flush of MP-001 sample port and check for residual chlorine: None detected |
| 1600 | - Collect 2nd set of time paced grab samples for Low Level 1,4-Dioxane. Water is very clean. Place samples in Fridge with others. Plants operations Good. STOP Filter Press. Finish Filling tomorrow. |
| 1945 | Start MP-001 port Flush and check for residual chlorine - None detected. |
| 2000 | Collect 3rd set of time paced grab samples for low level 1,4-Dioxane. |
| 2345 | Start MP-001 port Flush and check for residual chlorine - none detected. |
| 9/8/21 0000 | Collect 4th set of time paced grab samples for low level 1,4-Dioxane. Note: Observe a white film on the inside of the effluent Y-strainer, film not present where water enters the tank - chiller coils leaking Down frost into effluent tank - isolate coils from chiller unit. (W) |

Influent Sources and Flow Rates: @ 0515
NBBW – 7.3 gpm
North End On Site- 13.1 gpm
North End Off-Site – 8.4 gpm
RWST – 0.6 gpm
NTES – 0.50 gpm(10R only)
MW38 T-540/541 – 0.31 gpm(Source well and 38 pumping wells mix)
MW38 N & S– ~~0.00~~ gpm 2.2 gpm
COND/NTES T-530- 0.0 gpm(6am-1pm daily)
MW113 Area – 3.6 gpm

Operator: **Mike Gelwick** / Chris Carlson

# LOWRY WTP OPERATIONS LOG

Date: **Wednesday, September 08, 2021**

| Time: | |
|---|---|
| 0345 | - Plants operations Good. RESTART Filter Press. Auto Sampler operational OK. |
| 0350 | - START Flush of MP-001 sample port and check for residual chlorine; None detected. |
| 0400 | - Collect 5th Set of time paced grab samples for Low Level 1,4-Bioxane. Water IS very clear NO color. Place samples in fridge with others. |
| 0410 | - Filter Press says full. |
| | - Clean pH-315 probe w/Acid solution. Check the HMI30 for oil or sheen: None detected. Spray down work. |
| | - Check xP-130 for oil globules: None observed. Water IS very clear w/light yellow-green tint |
| 0430 | - working on BTS field Readings |
| 0750 | - START Flush of MP-001 sample port & check for Residual chlorine; None detected. |
| 0800 | - STOP Auto Sampler. TOTAL EFFluent = 243134608 gal. A TOTAL of 48907 gal treated during sample period. |
| | - Collect 6th/final set of time paced grab samples for Low Level 1,4-Bioxane. Water IS clear NO color. Place SAMPLE in Fridge with others |
| | - process/check composite sample By Gently stirring and checking pH value. pH of composite = 1.71 s.u. Fill sample bottle. PACK All Samples on ICE for SHIPMENT to Lab. |
| 0950 | - Continue working on BTS field Readings |
| 1311 | - Slow Flow down to 3.6 gpm on IX System to Alleviate pump Hunting to Run @ Max Speed Constantly |
| 1330 | - Plants operations Good. |

Influent Sources and Flow Rates: @0345
NBBW – 7.3 gpm
North End On Site- 13.3 gpm
North End Off-Site – 8.4 gpm
RWST – 0.6 gpm
NTES – 0.51 gpm(10R only)
MW38 T-540/541 – 0.30 gpm(Source well and 38 pumping wells mix)
MW38 N & S– 2.2 gpm
COND/NTES T-530- 0.0 gpm(6am-1pm daily)
MW113 Area – 3.5 gpm

Operator: **Mike Gelwick** /

# LOWRY WTP OPERATIONS LOG

Date: **Thursday, September 09, 2021**

| Time: | |
|---|---|
| 0535 | Plant operations good. Start on weekly GC maintenance and calibrations. Refill phosphorus tank with 55 gallons potable water + 5.5 lbs TSP. |
| ↓ 0740 | Blowdown operations good. Mike working on weekly systems ~~checkers~~ checks / Tom & Mike emptying Filter press A.M. (Tom ~~starting~~ forklift training). Tom to wash press A.M.. Add one full caustic tote to main plant supply. |
| 1000 / 1050 | ~~START Filter Press running on T-351~~ Decant T-351 to tap water. wet well activated. water is clear no color |
| | - clean pH-315 probe w/ acid solution. Check the HUM30 for oil or sheen: None observed. Spray down wash. |
| | - check TP-130 for O/G globules: None observed. water is very clear w/ light yellow-green tint. |
| 1050 | - START Filter Press running on T-351. |
| 1303 | - Suspend Plant Discharge to calibrate pH-740 to 4+10 pH STDs. |
| 1310 | - Resume Normal Discharge. continue with other pH probes calibrations to 4+10 pH STDs → pH-113, 670, 310, 315 + 865. |
| 1340 | - Plants weekly systems checks and calibrations complete. |
| | - Filter Press Full. |
| 1500 | - Slow IK System Flow down to 3.6 gpm for the night. Pump Runs @ 100% when Higher Flow Demand. |
| 1510 | - Plants operations Good. |

Influent Sources and Flow Rates: @ 0951
NBBW – 7.3 gpm
North End On Site- 13.1 gpm
North End Off-Site – 8.5 gpm
RWST – 0.6 gpm
NTES – 0.5 gpm(10R only)
MW38 T-540/541 – 0.3 gpm(Source well and 38 pumping wells mix)
MW38 N & S– 2.2 gpm
COND/NTES T-530- 0.2 gpm(6am-1pm daily)
MW113 Area – 3.7 gpm

Operator: **Mike Gelwick / Chris Carlson** / Tom Gilbert.

# LOWRY WTP OPERATIONS LOG

Date: **Friday, September 10, 2021**

| Time: 0520 | Plant operations good. Observe MW38N reached it's low level stop overnight, well is |
|---|---|
| ↓ | recharging slowly and is ~ 0.15' from it's restart level. Setup for BTS tank cleaning. |
| 0540 | Increase FX system rate from ~3.5 to ~3.7 gpm. |
| 0600 | Direct N. Tic to T-530 and stop T-540/540 to BTS - Begin to pump/decant water |
| ↓ | from sediment tank to blend tank. |
| 0740 | Blowdown operations good - Place BTS in Maintenance hold and start tank cleanouts. |
| | (Transferring sludges to T-351). |
| 0925 ~~0935~~ | BTS out of hold - tanks refilling Note: Sediment, Blend, Settling, overflow, |
| | containment sump cleaned out. Also Flushed Reactor Feed piping. |
| 1115 | Increase RWST influent from 0.6 gpm to 2.0 gpm while MW38N is off. |
| 1125 | - Clean pH-315 probe w/Acid solution. Check the Humbo for oil or sheen: None observed. Spray down weir. |
| | - Check TP-130 for oil globules: None observed. Water is very clear w/slight yellow-green tint. |
| | Empty filter press. |
| 1615 | MW38N extraction has restarted. Lower RWST influent from 2.0 gpm to 0.6 gpm. |
| 1630 | Plant operations good. |

Influent Sources and Flow Rates: 0530
NBBW – 7.3GPM
N. END ON-SITE – 13.0GPM
N. END OFF-SITE – 8.4GPM
RWST – 0.6GPM
NTES – 0.50GPM
COND/NTES T-530 – 0.0GPM
MW38 – 1.2GPM (MW38N Recharging)
T-540/541 – 0.0GPM
MW113 IX SYSTEM – 3.5GPM
OTHER – NA

OPERATOR(S) Chris Carlson / Mike Gelwick

# LOWRY WTP OPERATIONS LOG

Date: September 11, 2021

| | |
|---|---|
| 0945 | - Plant operations good. Start perimeter check |
| | - cleaned HMR-30 probe w/ acid solution |
| | - Sprayed down HMR-30 weir - good flow |
| 1200 | - Plant operations good. |
| | - Checked Tp-130 for oil globules or sheens. None observed - water is clear w/ yellow/green tint |

Influent Sources and Flow Rates @ 10:00
NBBW – 7.3 gpm
N. END ON-SITE – 13.0 gpm
N. END OFF-SITE – 8.4 gpm
RWST – .6 gpm
NTES – .53 gpm
COND/NTES T-530 – .20 gpm
MW38 – 2.2 gpm
T-540/541 – .29 gpm
OTHER – NA

OPERATOR(S) Tom Gilbert

# LOWRY WTP OPERATIONS LOG

Date: **Monday, September 13, 2021**

| Time: | |
|---|---|
| 0720 | - Plants Operations Good. Automatic blowdown operations Good. |
| 0830 | - Decant T-351 from top valve. Wet well activated. water is clear no odor. |
| | - Clean pH-315 probe w/weld Solution. Check the Hypo for oil or sheen: None observed. Spray down water. |
| | - Check TP-130 for oil globules: None observed. water is very clear w/light yellow-green tint. |
| | - TDM working on washing out filter press. |
| 0910 | - Refill BB phosphorus tank w/5 # of TSP and 50 gal of potable water. |
| 1043 | - Increase p-352 to 0.70 gpm. START Filterpress running on T-351 |
| 1413 | - Plant STOPPED Due to Blown Fuse/NO power. Kuchar called. Turn some systems off For more controlled startup (Birds Eagles) |
| 1515 | - Kuchar on site to replace fuses. |
| 1550 | - Power restored. Begin returning Plant to Normal operations. |
| 1556 | - Re START Plant. |
| 1630 | - Plants operations BACK to Normal. Will continue Filling Filterpress in AM. |
| 1640 | - Plants operations ok. |

Influent Sources and Flow Rates: @0845
NBBW – 7.3 gpm
North End On Site- 13.0 gpm
North End Off-Site – 8.2 gpm
RWST – 0.6 gpm
NTES – 0.49 gpm(10R only)
MW38 T-540/541 – 0.31 gpm(Source well and 38 pumping wells mix)
MW38 N & S– 2.1 gpm
COND/NTES T-530- 0.20 gpm(6am-1pm daily)
MW113 Area – 3.5 gpm

Operator: **Mike Gelwick** / TDM Gilbert

# LOWRY WTP OPERATIONS LOG

Date: **Tuesday, September 14, 2021**

| Time: | |
|---|---|
| 0510 | - Plants operations Good. |
| 0520 | - working on TP-730 GAC/Lab splits samples and TP-710 & 740 Low level 1,4-Dioxane samples. STARTING Efficiency checks |
| 0608 | - Reboot HMI FTU#1 to reset temporary file memory |
| 0612 | - GAC on Line |
| 0710 | - Restart Filter #5 running on T-351. |
| 0830 | - working on weekly BTS sampling and readings today |
| 0958 | - IX System Performance HACH Testing w/Lab splits AFTER 5 99342 gal Treated: TP-183 ⊃ 110 ug/L; TP-174A ⊃ 160 ug/L; TP-173A ⊃ 2900 ug/L; TP-170 ⊃ 4600 ug/L |
| 1042 | - Clean pH-315 probe w/Acid solution. Check the Hypalon for oil or sheen: None observed. Spray down weir. |
| | - check TP130 for oil globules: None observed. Water is very clear w/Light yellow green tint. |
| 1600 | - Plants operations Good. |

Influent Sources and Flow Rates: @ 0510
NBBW – 7.3 gpm
North End On Site- 13.3 gpm
North End Off-Site – 8.6 gpm
RWST – 0.60 gpm
NTES – 0.51 gpm(10R only)
MW38 T-540/541 – 0.30 gpm(Source well and 38 pumping wells mix)
MW38 N & S– 2.1 gpm
COND/NTES T-530- 0.0 gpm(6am-1pm daily) 0820 ⊃ 0947
MW113 Area – 3.51 gpm

Operator: **Mike Gelwick / Chris Carlson**

# LOWRY WTP OPERATIONS LOG

Date: **Wednesday, September 15, 2021**

| Time: | |
|---|---|
| 0535 | Plant operations good. Start on weekly GC maintenance and calibrations. |
| 0900 | - Decant T-351 from bottom valve. Wetwell activated. water is clear no color. |
| | - Clean pH-315 probe w/ Acid solution. Check the Hawk 30 for oil or sheen: None observed. Spray down weir. |
| | - Check TP-130 for oil globules: None observed, water is very clear w/ light yellow-green tint |
| 1540 | - Plants operations Good |

Influent Sources and Flow Rates: @0905
NBBW – 7.3 gpm
North End On Site- 13.4 gpm
North End Off-Site – 8.2 gpm
RWST – 0.60 gpm
NTES – 0.51 gpm(10R only)
MW38 T-540/541 – 0.31 gpm(Source well and 38 pumping wells mix)
MW38 N & S– 2.1 gpm
COND/NTES T-530- 0.20 gpm(6am-1pm daily)
MW113 Area – 3.5 gpm

Operator: **Mike Gelwick / Chris Carlson**

# LOWRY WTP OPERATIONS LOG

Date: **Thursday, September 16, 2021**

| Time: | |
|---|---|
| 0550 | Plant operations good. |
| 0700 | James K of DANORA (Calgon) on site for annual UV-Ox service & inspection. |
| 0740 | Blowdown operations good. |
| 0811 | James alone inspecting unit while running - shut down UV-Ox. Note: James changing out crystal and O-rings also reactor tower temp sensor today. Noted one wire on lower capacitor broken - will replace also. |
| 0940 | - Decant T-351 from bottom valve. Wet well activated. water is clear no color. |
| | - Clean pH-315 probe w/ ACID solution. Check the HMX 30 for oil or sheen: None observed. Spray down weir. |
| | - Check TP-130 for O-ring globules: None observed. Water is very clear with light yellow-green tint |
| | - working on weekly WTP's systems checks and calibrations today. |
| 1115 | - Back wash ADV-GAC while UV-Ox is off. |
| 1257 | - Suspend plant discharge to calibrate pH-740 probe to 4+10 pH STD's. |
| 1305 | - Resume Normal discharge. Continue with other pH probes calibrations to 4+10 pH STD's ⇒ pH-113, 670, 310, 315 + 365 |
| 1345 | - Plants weekly checks and calibrations complete. |
| 1413 | Restart UV-Ox - working well. |
| 1500 | James testing is complete - off site. Note: T1 service was temporarily down today while lines were moved to make room for additional scale on exit side of DADS facility. Internet back up at 1530. |

Influent Sources and Flow Rates: @ 1030
NBBW – 7.3 gpm
North End On Site- 13.3 gpm
North End Off-Site – 8.2 gpm
RWST – 2.5 gpm
NTES – 0.53 gpm(10R only)
MW38 T-540/541 – 0.31 gpm(Source well and 38 pumping wells mix)
MW38 N & S– 1.9 gpm
COND/NTES T-530- 0.20 gpm(6am-1pm daily)
MW113 Area – 3.5 gpm

Operator: **Mike Gelwick / Chris Carlson**

# LOWRY WTP OPERATIONS LOG

Date: **Friday, September 17, 2021**

| Time: | |
|---|---|
| 0550 | Plant operations good. Jim B of Brownshill onsite to start planning the UV-OX |
| ↓ | PLC upgrade. Noted - will need an ethernet comm line ran between UV-OX and |
| ↓ | main PLC DA cabinet in order to network new PLC to the Rockwell Software. |
| 0630 | Jim off site. |
| 0745 | Blowdown operations good. Refill phosphorus tank with 50 gallons potable water + 5lbs TSP. |
| 0855 | - Decant T-351 from bottom valve. Wetwell activated. Water is clear no odor. |
| | - Clean pH-315 probe w/ acid solution. Check the Hach 50 for oil or sheen: None observed. Spray down weir. |
| | - Check TP-130 for oily globules: None observed. Water is very clear w/ slight yellow-green hint. |
| 0915 | - Decrease psi @ MW113-EW1 to slow down tank filling so often and stopping the pump on well. |
| 1100 | - Decrease psi @ MW113-EW1 slightly more. |
| 1245 | - Plant is operating good. |

Influent Sources and Flow Rates: @0745

- NBBW – 7.1 gpm
- North End On Site- 13.2 gpm
- North End Off-Site – 8.3 gpm
- RWST – 0.6 gpm
- NTES – 0.5 gpm(10R only)
- MW38 T-540/541 – 0.3 gpm(Source well and 38 pumping wells mix)
- MW38 N & S– 2.2 gpm
- COND/NTES T-530- 0.2 gpm(6am-1pm daily)
- MW113 Area – 3.4 gpm

Operator: **Mike Gelwick / Chris Carlson**

# LOWRY WTP OPERATIONS LOG

Date: SATURday, September 18-2021

| | |
|---|---|
| 0630 | - Plants operations Good. Go to check other SITE Systems |
| 0745 | - Comming over for Automatic blowdown operations OK. |
| | - Accent T-351 to bottom valve. wet and activated. water IS clear NO color |
| | - Clean pH-315 probe w/field solution. Check the Hach 30 for oil or sheen : None observed. Spray down work. |
| | - Check TP-130 for oil globules : None observed. water IS very clear w/light yellow-green tint. |
| 0930 | - Plants operations Good |

Influent Sources and Flow Rates: 0630
NBBW – 7.3 gpm
N. END ON-SITE – 13.2 gpm
N. END OFF-SITE – 8.4 gpm
RWST – 0.6 gpm
NTES – 0.51 gpm
COND/NTES T-530 – 0.20 gpm
MW38 – 2.1 gpm
T-540/541 – 0.31 gpm
OTHER – ~~NA~~ 13 Area/IX - 3.42

OPERATOR(S) Mike Gelwick

# LOWRY WTP OPERATIONS LOG

Date: **Monday, September 20, 2021**

| Time: | |
|---|---|
| 0745 | - Plants operations Good. Coming out of automatic blowdown ok. |
| 0815 | - Account T-351 TO bottom valve. Wet well activated. water is clear no color |
| | - Check TP-130 for oily globules: None observed. water is very clear w/ light yellow green tint. |
| | - Clean pH-315 probe w/ Acid solution. Check the Hach 50 for oil or sheen: None observed. Spray Down wall |
| 1320 | - Refill 65% phosphorus tank w/ 5 gal of T.P and 50 gal of potable water |
| 1515 | - Plants operating Good |

Influent Sources and Flow Rates: @0755
NBBW – 7.2 gpm
North End On Site- 13.1 gpm
North End Off-Site – 8.3 gpm
RWST – 0.6 gpm
NTES – 0.52 gpm(10R only)
MW38 T-540/541 – 0.31 gpm(Source well and 38 pumping wells mix)
MW38 N & S– 2.0 gpm
COND/NTES T-530- 0.20 gpm(6am-1pm daily)
MW113 Area – 3.4 gpm

Operator: **Mike Gelwick**

0.08" Rain overnight

# LOWRY WTP OPERATIONS LOG

Date: **Tuesday, September 21, 2021**

| Time: | |
|---|---|
| 0520 | -Plants Operations Cabot. working on TP-730 LAB/GC SPLITS and STARTING EFFLUENT CHECKS. Also collect TP-740 + 710 Low Level 1,4-Dioxane samples. |
| 0820 | -Decant T-351 to Bottom valves, wet well activated. Water IS clear NO color. |
| | -Clean pH-315 probe w/Acid solution. Check TPH HMR30 for oil or SHEEN: NONE OBSERVED. Spray down weir |
| | -Check TP-130 for oil globules: NONE OBSERVED. Water IS very clear w/ slight yellow-green tint |
| | -working on BTS weekly SAMPLING and Field Readings today |
| 0830 | - Increase RWST to 1.9 gpm. MW38 South pumping well reached ITS CUT OFF point @ 2643. will leave RWST THIS WAY to make up water being lost to MW38 pumping well recharging/OFF. Also NBBW Flow Has Dropped to 7.1 gpm currently. |
| 0948 | IX System Performance weekly HACH Testing w/LAB SPLITS After 633,470 gal Treated: TP-183 @ 140 ug/L; TP-174A @ 170 ug/L; TP-173A @ 3000 ug/L; TP-170 @ 4300 ug/L. (NOTE: High Range TEST on TP-170 + 173A, Low Range TEST on TP183 + 174A.) PACE AM SAMPLES on ICE for courier PICK UP. |
| 1112 | Shutdown IX system to Flush P-114 pump with potable water |
| 1158 | Main PLC faulted when P-114 was taken out of MANUAL and placed back into auto PID logic error. PLC was power cycled - did not clear - went into the PLC program and cleared the fault. Jim B of Brown Hill to take another look at the P-114 logic. Note: P-001 was off ~~briefly~~ briefly while PLC error occurred. ran it briefly at 13 gpm to get sump level back to normal before switching back to NORMAL HMR 30 INFLUENT. Note: Found main PLC UPS BACKUP is now flashing replace battery after power cycle was performed - will switch out PLC for new unit (this unit is ~~eight~~ (8) eight years old and has had it's battery replaced ONCE already in 2018). |
| 1215 | able to run P-114 in MANUAL mode while auto mode programming is bad. Leave MW38 S well off and turn MW38 N well ~~off~~ on for MW38 Source well batch extraction. Increase RWST INFLUENT from 2 gpm to 2.6 gpm and Start Source well pumping to T-540/541 |

Influent Sources and Flow Rates: @0542
NBBW – 7.1 gpm
North End On Site- 13.1 gpm
North End Off-Site – 8.5 gpm
RWST – 0.6 gpm
NTES – 0.50 gpm(10R only)
MW38 T-540/541 – 0.31 gpm(Source well and 38 pumping wells mix)
MW38 N & S– 2.0 gpm
COND/NTES T-530- 0.0 gpm(6am-1pm daily) @ 2045
MW113 Area – 3.3 gpm

Operator: **Mike Gelwick / Chris Carlson**

## LOWRY WTP OPERATIONS LOG

Date: Tuesday, September 21, 2021 (continued)

| | |
|---|---|
| 1445 | Shutdown plant to swap out UPS on main PLC. |
| 1450 | New UPS online PLC restarted. |
| 1452 | Restart plant. |
| 1530 | Plant operations good. |

Influent Sources and Flow Rates: 1440
NBBW – 7.2 gpm
N. END ON-SITE – 13.4 gpm
N. END OFF-SITE – 8.6 gpm
RWST – 2.6 gpm
NTES – 0.52 gpm
COND/NTES T-530 – 0.0 gpm
MW38 – 3.9 gpm (Source to T-540/541)
T-540/541 – 0.3 gpm
~~OTHER~~ – NA
IX System MW13 Area 3.4 gpm.

OPERATOR(S) Chris Carlson / Mike Gelwicks

# LOWRY WTP OPERATIONS LOG

Date: **Wednesday, September 22, 2021**

| Time: | |
|---|---|
| 0550 | Plant operations good. MW38 Source well batch okay overnight, T-540/541 @ 55%. |
| ↓ | * Flushing of P-114 with potable water didn't improve flow rate. Start on weekly |
| ↓ | GC maintenance and calibrations. |
| 0740 | Blow down operations good. Work with Mike to add full caustic tote ~~&~~ and ~~275~~ ~50 @ gallons peroxide to main bay supply. |
| 0950 | - Decant T-351 from bottom valve. Wet well activated. Water is clear no color |
| | - Clean pH-315 probe w/ Acid solution. Check THE HMI 30 for O2 of 3.4 ppm: None observed. Spray down wet well. |
| | - Check TP-130 for oil globules: None observed. Water is very clear w/ light yellow - green tint. |
| 1540 | - Plants operations Good |
| 1550 ~~1720~~ | Shutdown MW38 Source well extraction. |
| 1720 | Start MW38N #5 extraction to T-540/541 to displace Source well water in the |
| ↓ | conveyance line to T-540/541. |
| 2305 | 770 gallons of MW38N #5 water has been used to displace source well water. Switch |
| ↓ | MW38 to RWST's for the night. |

Influent Sources and Flow Rates: @0945
NBBW – 7.1 gpm
North End On Site- 13.2 gpm
North End Off-Site – 8.5 gpm
RWST – 2.6 gpm
NTES – 0.51 gpm(10R only)
MW38 T-540/541 – 0.3 gpm(Source well and 38 pumping wells mix)
MW38 ~~N & S~~ 4.9 gpm (Source to T-540/541)
COND/NTES T-530- 0.2 gpm(6am-1pm daily)
MW113 Area – 3.3* gpm

Operator: **Mike Gelwick / Chris Carlson**

# LOWRY WTP OPERATIONS LOG

Date: **Thursday, September 23, 2021**

| Time: | |
|---|---|
| 0550 | Plant operations good. |
| 0600 | Jim B. of Brownshill on site to trouble shoot P-114 logic error - Note: Had |
| ↓ | to simulate the problem again in order the fix it. Main PLC Faulted at 0611 |
| ↓ | but brought back online quickly after seeing the error. Jim able to fix it quickly |
| 0710 | Jim B. off site. |
| 0740 | Blowdown operations good. Mike working on weekly system checks and calibrations. |
| 0900 | - START Monthly Main Air compressor max speed Run for 2 Hrs for oil moisture prevention. |
| 0910 | - Decant T-351 From Bottom valve. Wetwell activated. Water is clear No color. |
| | - Check TP-130 for oily globules: None observed. Water is very clear w/light yellow-green tint. |
| | - Clean pH-315 probe w/Acid solution. Check the Hach 30 for oil or sheen: None observed. Spray down wash |
| | - Refill polymer TANK w/ 200gal of potable water and 2 cups of NALCO polymer. |
| 1100 | - STOP Main compressor MAX speed Run. |
| 1235 | - Plant loss of power Due to Birds on wires again. Only lost 1 leg which some power still on. Shut down Plant and turn |
| | things OFF for controlled RESTART. NOTE: Small grass fire started from Flaming Bird. Able to Extinguish with Fire Extinguisher and Have |
| | WM water Et down w/water TRUCK. |
| 1350 | - Work on calibrating Plant pH probes while power is down since they are still powered on. Calibrate pH-740, 113, 670, 310, 315 + 365 probes |
| | to 4 + 10 pH STDS. |
| 1455 | - Plants weekly systems checks and calibrations complete. |
| 1525 | - Restored Power. |
| 1539 | - RESTART Plant. |
| 1600 | - Systems Running Normal. |
| 1630 | - Plants operations Good. |

Influent Sources and Flow Rates: @ 0905
NBBW – 7.1 gpm
North End On Site- 13.2 gpm
North End Off-Site – 8.6 gpm
RWST – 0.6 gpm
NTES – 0.52 gpm(10R only)
MW38 T-540/541 – 0.3 gpm(Source well and 38 pumping wells mix)
MW38 N & S– 2.4 gpm
COND/NTES T-530- 0.2 gpm(6am-1pm daily)
MW113 Area – 3.4 gpm

Operator: **Mike Gelwick / Chris Carlson**

# LOWRY WTP OPERATIONS LOG

Date: **Friday, September 24, 2021**

| | |
|---|---|
| Time: 0545 | Plant operations good. |
| 0630 | Decant T-351 bottom valve, wet well did not activate. Water is clear, no color. Clean the HMR-30 weir and pH probe - no oil or sheen observed in the HMR-30. Check TP-130 for oil |
| ↓ | globules - none observed. Water is very clear, light green/yellow. |
| 0740 | Blowdown operations good. |
| 1230 | Empty filter press. |
| 1400 | Plant operations good. |

Influent Sources and Flow Rates: 0552
NBBW – 7.2GPM
N. END ON-SITE – 13.6GPM
N. END OFF-SITE – 8.2GPM
RWST – 0.6GPM
NTES – 0.51GPM
COND/NTES T-530 – 0.2GPM (6AM-1PM)
MW38 – 2.1GPM
T-540/541 – 0.3GPM
MW113 IX SYSTEM – 3.3GPM
OTHER – NA

OPERATOR(S) Chris Carlson

# LOWRY WTP OPERATIONS LOG

Date: Saturday September 25, 2021

| | |
|---|---|
| 0710 | ONsite for weekend systems checks. Plant operations good. Refill phosphorus tank with |
| ↓ | 65 gallons potable water + 6.5 lbs TSP. |
| 0740 | Blanchard operations good. |
| 0915 | Clean the Hach-30 weir and pH probe - No oil or sheen observed in the Hach-30. Check |
| ↓ | TP-130 for oil globules - none observed. Water is very clear, light green/yellow. |
| 0950 | Plant operations good. |
| 9/26/21 0550 | Check plant remotely - All Okay. |
| 1740 | Check plant remotely - All Okay. |

Influent Sources and Flow Rates: 0750
NBBW – 7.1 gpm
N. END ON-SITE – 13.6 gpm
N. END OFF-SITE – 8.3 gpm
RWST – 0.6 gpm
NTES – 0.52 gpm
COND/NTES T-530 – 0.2 gpm (6AM-1PM)
MW38 – 2.1 gpm
T-540/541 – 0.3 gpm
~~OTHER – NA~~
MW113 Area 3.3 gpm

OPERATOR(S) Chris Carlson

# LOWRY WTP OPERATIONS LOG

Date: **Monday, September 27, 2021**

| Time: 0545 | Plant operations good. |
|---|---|
| 0615 | Decant T-351 top valve, wet well activated. Water is clear, no color. Clean the HMR-30 |
| ↓ | weir and pH probe - no oil or sheen observed in the HMR-30. Check TP-130 for oil globules. |
| ↓ | None observed, water is very clear - light green/yellow. Setup for GAC-720 backwash. |
| 0700 | Backwash PDU with potable water while in blowdown. Δ psi improved from 5 to 1. |
| 0715 | Backwash GAC-720 with process and compressed air bubbled into the system. Load GAC-720 |
| ↓ | Δ psi improved from 20 to 7. |
| 0800 | Check 4" B discharge line for leaks and visual check of discharge into sewer manhole. |
| ↓ | Note: DADS septic lift system is now online using 2" discharge line to sewer. |
| 0900 | POTW discharge line check completed - All okay. Note: did not witness the DADS |
| ↓ | lift system discharging (between cycles). Hi Hi limit switches not active - system is operational. |
| 0930 | Decant T-351 top valve, wet well activated. Water is clear, no color. |
| 1000 | Backwash GAC F-3340. |
| 1415 | Plant operations good. |

Influent Sources and Flow Rates: 0550
NBBW – 7.2GPM
N. END ON-SITE – 13.4GPM
N. END OFF-SITE – 8.1GPM
RWST – 0.6GPM
NTES – 0.51GPM
COND/NTES T-530 – 0.2GPM (6AM-1PM)
MW38 – 2.1GPM
T-540/541 – 0.3GPM
MW113 IX SYSTEM – 3.3GPM
OTHER – NA

OPERATOR(S) Chris Carlson

# LOWRY WTP OPERATIONS LOG

Date: **Tuesday, September 28, 2021**

| Time: | |
|---|---|
| 0500 | - Plants operations Good. |
| 0520 | - Working on collecting TP-730 GC/CAB split sample and starting Effluent weekly checks. Also collect TP-710 + 740 Low Level 1, 4-Nitroaniline samples. |
| 0640 | Decant T-351 top valve, wet well activated. Water is clear, NO color. |
| 0900 | - Working on BT3 weekly sampling and field testing to do. |
| 0950 | - IX System performance HACH testing and Lab split sampling After 1665, 488 gal Treated: TP-185 ⊃170 ug/L; TP-174A ⊃ 220 ug/L; TP-173A ⊃2800 ug/L; TP-170 ⊃4500 ug/L |
| 1029 | - Decant T-351 to top valve again. wetwell activated. water is clear NO color. |
| | - Clean pH-315 probe w/Acid solution. Check the Hach 30 for oil or sheen: None observed. Spray down weir |
| | - Check TP-130 for oil globules: None observed. Water is very clear w/ light yellow-green tint. |
| | - PACK All SAMPLES on ICE FOR COURIER to Lab. |
| 1500 | - Collect and Fill SAMPLE JARS for Sludge: TCLP, RADS + TENORM. |
| 1545 | - Plants operations Good. |

Influent Sources and Flow Rates: @ 0520
NBBW – 7.2 gpm
North End On Site- 13.4 gpm
North End Off-Site – 8.3 gpm
RWST – 0.6 gpm
NTES – 0.52 gpm(10R only)
MW38 T-540/541 – 0.30 gpm(Source well and 38 pumping wells mix)
MW38 N & S– 2.1 gpm
COND/NTES T-530- 0.0 gpm(6am-1pm daily)
MW113 Area – 3.2 gpm

Operator: **Mike Gelwick / Chris Carlson**

# LOWRY WTP OPERATIONS LOG

Date: **Wednesday, September 29, 2021**

| Time | |
|---|---|
| 0545 | Plant operations good. Start on weekly GAC maintenance and calibrations - Refill phosphorus tank with 60 gallons potable water + 6 lbs TSP. |
| 0740 | Blowdown operations good. Work with Mike to consolidate ~~caustic~~ caustic totes so older totes can be returned on today truck. |
| 0845 | Stop EX system and change out BF-113, Δ pressure improved from 10 psi to 1 psi. Note: This 1 Micron bag was online for ~ 1 month. Bag drying - will put in satellite haz waste drum tomorrow. |
| 0910 | Stop P-521/522 and backwash lag GAC-730 with potable water and compressed air bubbles. Note: T-351 decanted before backwash - wet well activated water is clear, no color. |
| 0930 | Backwash completed. Restart P-521/522. Δ pressure improved from 10 psi to 4 psi. |
| 1100 | - Decant T-351 Again TO TOP valve. wet well activated water is clear no color.<br>- Clean pH-315 probe w/test solution. Check TH-HMI-30 for oil or sheen: None observed. Spray down work.<br>- Check TP-130 For oil globules: None observed. water is clear w/yellow green tint<br>Add two full caustic totes to main bay supply. |
| 1225 | Weekly Data backup to Flash and CD. Daily OneDrive backup working well. |
| 1230 | Reboot HMI2 to apply latest virus software update - online 1233. |
| 1240 | Reboot HMIFTVIEW1 to apply latest virus software update - ONline 1244. |
| 1520 | -Plant operations Good. |

Influent Sources and Flow Rates: @ 0905
NBBW – 7.2 gpm
North End On Site- 13.3 gpm
North End Off-Site – 8.5 gpm
RWST – 0.6 gpm
NTES – 0.54 gpm(10R only)
MW38 T-540/541 – 0.3 gpm(Source well and 38 pumping wells mix)
MW38 N & S– 2.1 gpm
COND/NTES T-530- 0.2 gpm(6am-1pm daily)
MW113 Area – 3.4 gpm

Operator: **Mike Gelwick / Chris Carlson**

# LOWRY WTP OPERATIONS LOG

Date: **Thursday, September 30, 2021**

| Time: | |
|---|---|
| 0740 | - Plants operations Good. Coming out of Automatic Shutdown operations OK. |
| 0830 | - working on weekly/monthly Plants Systems checks and calibrations. Change out pH STD's w/ New 4+10 pH STD's. Calibrate Site multimeter to 50% LEL to use during LEL-740 calibration to ensure 0% LEL on T-740. |
| 0940 | - Decant T-351 to TO Pvalve. wetwell activated water is clear no color. |
| | - Clean pH-315 probe w/ Acid solution. Check the HMI 30 for oil or sheen; None observed. Spray down west. |
| | - Check TP-130 for oil globules: None observed. Water is clear w/ yellow-green front. |
| 1150 | - Perform monthly BTS pH probes calibrations using New 4+10 pH STD's. |
| 1313 | - Begin WTP pH probes calibrations to New 4+10 pH STD's ⇒ pH-113, 670, 310, 315 & 365. |
| 1350 | - Suspend Discharge to calibrate pH-740 probe to 4+10 pH STD's & LEL-740 to 49% LEL. |
| 1400 | - Plant Shutdown @ 8% LEL during LEL-740 calibration. Hi LEL Shutdown operational. |
| 1409 | - Restart Plants. |
| 1410 | - Resume Normal Discharge. |
| 1420 | - Plants operations Back to Normal. |
| 1540 | End Plants operations Good |

Influent Sources and Flow Rates: @0825
NBBW – 7.1 gpm
North End On Site- 13.3 gpm
North End Off-Site – 8.7 gpm
RWST – 0.6 gpm
NTES – 0.50 gpm(10R only)
MW38 T-540/541 – 0.30 gpm(Source well and 38 pumping wells mix)
MW38 N & S– 2.0 gpm
COND/NTES T-530- 0.21 gpm(6am-1pm daily)
MW113 Area – 3.4 gpm

Operator: **Mike Gelwick**

# LOWRY WTP OPERATIONS LOG

Date: **Friday, October 01, 2021**

| Time: | |
|---|---|
| 0745 | - Plants operations Good. Coming out of Automatic Blowdown operations OK |
| 0805 | - Recount T-351 to TOP Value. Wet well activated. Water IS clear no color. |
| | - Clean pH-315 probe w/Acid solution. Check the HMR30 for oil or sheen: None observed. Spray down weir. |
| | - Check TP-130 for oil globules: None observed. Water IS very clear w/ light yellow-green tint. |
| 0845 | - Switch NTES to Bi-vert and increase P-005 to 0.50 gpm to flush out MDZ-10R pump w/Bleach. Blowing a little air and stalling periodically. |
| 1010 | - Switch NTES back to Normal and put P005 back to 0.20 gpm. |
| 1020 | - Working on QTRly Blowers maint today. |
| 1300 | - All Blowers serviced w/New Gear oil, Air filters & Greased. Tightened All Belts. |
| 1325 | - Setup and calibrate Autosamplers for monday START UP. Change out Sampler 5.7 i core tubing. Triple Rinse each composite container. |
| 1605 | - Plants operations Good. |

Influent Sources and Flow Rates: @ 0800
NBBW – 7.1 gpm
North End On Site- 13.3 gpm
North End Off-Site – 8.3 gpm
RWST – 0.6 gpm
NTES – 0.49 gpm(10R only)
MW38 T-540/541 – 0.30 gpm(Source well and 38 pumping wells mix)
MW38 N & S– 2.0 gpm
COND/NTES T-530- 0.19 gpm(6am-1pm daily)
MW113 Area – 3.3 gpm

Operator: **Mike Gelwick**

# LOWRY WTP OPERATIONS LOG

Date: Saturday, October 02, 2021

| | |
|---|---|
| 0850 | - Plant operations good. Phosphorus tank Filled with 50gallons potable water + 5lbs TSP (cc) |
| | - Decant T-351 from Top valve - Wet well activated - water is clear no color |
| | - Clean plt-315 probe with acid solution. Check HMR30 for oil sheens: None observed |
| | - sprayed down HMR30 weir - good flow |
| | - Checked Tp-130 for oil globules: none observed water is very clear w/ Yellow-green tint |
| [redacted] 1130 | - Plant operations good |
| Sunday, October 3, 2021 | |
| 0800 | - Log In Remotely. See that GC2 not showing peaks Like Normal. Come to Site and Investigate. Find that Sample tubing IS Air locked. Reprime Air In Line and Get a New Sample going on Pd. 730. Checked Again Later and Allow. |
| 1215 | - Log in remotely. Allow. GC2 Filling cell |
| 1945 | - Log in remotely Allow. GC2 normal operations, usual peaks. |

Influent Sources and Flow Rates: @ 0900
NBBW – 7.1 gpm
N. END ON-SITE – 13.2 gpm
N. END OFF-SITE – 8.0 gpm
RWST – 0.6 gpm
NTES – .51 gpm
COND/NTES T-530 – .20 gpm
MW38 – 2.0 gpm
T-540/541 – .30 gpm
OTHER – NA IX/113 Area - 3.3 gpm

OPERATOR(S) TDM Gilbert / Mike Gelwicks

# LOWRY WTP OPERATIONS LOG

Date: **Wednesday, October 06, 2021**

| Time: | |
|---|---|
| 0600 | Plant operations good. Start on weekly GC maintenance and calibrations. |
| 0740 | Blowdown operations good. Mike working on weekly ~~GC~~ BTS Field readings. |
| 0900 | Work on reducing the size of the One Minute databases on HMIFTVIEW1 by removing older data after it has been backed up. |
| 1053 | Stop HMIFTVIEW1 to load reduced databases and to reset available temp memory. Online - 1103. |
| | -Decant T-351 to TOP Valve. wet well activated. water IS clear no color. |
| | -Clean pH-315 probe w/ Acid solution. Check the thickener for oil or sheen: None observed. Spray down wash. |
| | -check TA130 for oil globules: None observed- water IS clear w/ light yellow-green hue. |
| 1132 | Reboot HMI2 to update virus software version. Online - 1135. |
| 1200 | Wash out Filterpress. |
| 1510 | - Plants operations Good. Filterpress Ready to fill |

Influent Sources and Flow Rates: @ 0740
NBBW – 7.1 gpm
North End On Site- 13.2 gpm
North End Off-Site – 8.3 gpm
RWST – 0.6 gpm
NTES – 0.5 gpm(10R only)
MW38 T-540/541 – 0.3 gpm(Source well and 38 pumping wells mix)
MW38 N & S– 2.2 gpm
COND/NTES T-530- 0.2 gpm(6am-1pm daily)
MW113 Area – 3.3 gpm

Operator: **Mike Gelwick / Chris Carlson**

# LOWRY WTP OPERATIONS LOG

Date: **Thursday, October 07, 2021**

| Time: | |
|---|---|
| 0550 | Plant operations good. |
| 0600 | INCrease RWST INFluent from 0.6 gpm to 2.0 gpm - MW38N well reached it's low stop |
| ↓ | level at 2000 yesterday and is slowly recharging. |
| 0630 | Start Filterpress on ~~T-352~~ T-351 (IN Stage 1). |
| 0740 | Blowdown operations good. |
| 0915 | - working on weekly Plants Systems checks and calibrations |
| 0935 | - Clean Alt-315 probe w/Acid Solution. Check THickener 30 for oil or Sheen: None observed. Spray down wash |
| | - Check TP-130 for oil globules: NO ones observed. water IS clear w/yellow-green tint. |
| 1226 | - Suspend Plant Discharge to calibrate Alt-740 probe to 4 & 10 pH STD's. |
| 1232 | - Resume Normal Discharge. continue with other pH probes calibrations to 4 & 10 pH STD's @ pH-113, 670, 310, 315 & 365. |
| 1245 | - Plant SHUT Down Due to Loss of Power/Blown Fuse. SHUT things OFF/Down for a controlled RESTART once Power IS Restored. |
| 1335 | - Plants weekly Systems check and calibrations complete. *(11) Manuela sampling IN MW38S extraction Manual level for transducer cal. check. DTW @ 72.19' = GWE 5734.57' WMI reading 5734.52' - No calibration Needed at this time (W). |
| 1440 | - Power Restored. begin RESTART Process. |
| 1455 | - RESTART Plant. + UV-OK |
| 1509 | - MW38N. Pump RESTART. TURN RWSTS BACK Down TO 0.60 gpm |
| 1523 | - Plants Operations BACK to Normal. |
| 1607 | - Change Low Flow on N. End OFF 3.1 TO 5 gpm. MW37 Area NO power. Blown Fuse. |
| 1610 | - Plants operating Good. |

Influent Sources and Flow Rates: @ 0748
- NBBW – 7.1 gpm
- North End On Site- 13.2 gpm
- North End Off-Site – 8.7 gpm
- RWST – 2.0 gpm
- NTES – 0.5 gpm(10R only)
- MW38 T-540/541 – 0.3 gpm(Source well and 38 pumping wells mix)
- MW38 N & S– 1.0 gpm
- COND/NTES T-530- 0.2 gpm(6am-1pm daily)
- MW113 Area – 3.2 gpm

Operator: **Mike Gelwick / Chris Carlson**

# LOWRY WTP OPERATIONS LOG

Date: **Friday, October 08, 2021**

| Time: | |
|---|---|
| 0550 | Plant operations good. |
| 0610 | Start filterpress on T-351 (in stage 4) |
| 0740 | Blowdown operations good. |
| 0815 | Filterpress full. |
| 0830 | -Clean pH-315 probe w/Acid solution. Check the HMI 80 for oil or sheen: None observed. Strong chlorine |
| | -Check TP-130 for oil globules: None observed. water is clear w/yellow-green tint. |
| 1111 | Manuela sending in manual level at MW38N extraction well for transducer calibration check. |
| | DTW @ 52.62' = GWE ~~5744~~ 5719.68'. HMI reading 5719.70', No calibration needed. |
| 1230 | Plant operations good. |

Influent Sources and Flow Rates: @ 0745
NBBW – 7.0 gpm
North End On Site- 13.5gpm
North End Off-Site – 7.8 gpm
RWST – 0.6 gpm
NTES – 0.5 gpm(10R only)
MW38 T-540/541 – 0.3 gpm(Source well and 38 pumping wells mix)
MW38 N & S– 2.2 gpm
COND/NTES T-530- 0.2 gpm(6am-1pm daily)
MW113 Area – 3.2 gpm

Operator: **Mike Gelwick / Chris Carlson**

# LOWRY WTP OPERATIONS LOG

Date: Sunday, October 10, 2021

| | |
|---|---|
| 1330 | Plant operations good. |
| 1440 | Decant T-351 to top valve. Wet well activated. Water is clear, no color. Check TP-130 for oil globules: none observed. Water is very clear w/ yellow-green tint. Clean pH-315 probe w/ acid solution. Check HMR-30 for oil or sheen: none observed. Spray down weir. Both GC's operational within limits. All Blowers o/k. Phosphorus tank @ 30 gal. Added #7 TSP and 70 gallons of water. |
| 1600 | Plant operations good. |
| Sat 10/9/21 0620 | Check plant remotely - All okay. |
| 1301 | Receive P-3322 Strainer Alarm - Able to get pump primed and running again remotely (air pocket hit inlet?) Plant operations good. |
| Sun 10/10/21 0650 | Check plant remotely - All okay. |
| 1950 | Check plant remotely - All okay. |

Influent Sources and Flow Rates: @1500
NBBW – 7.1 gpm
N. END ON-SITE – 13.3 gpm
N. END OFF-SITE – 7.9 gpm
RWST – 0.69 gpm
NTES – 0.52 (10R only)
COND/NTES T-530 – 0.0 gpm
MW38 – 2.0 gpm
T-540/541 – 0.3 gpm
OTHER – NA
MW113 Area: 3.2 gpm

OPERATOR(S) Manuela Seewald / Chris Carlson

# LOWRY WTP OPERATIONS LOG

Date: **Monday, October 04, 2021**

| | |
|---|---|
| Time: 0600 | Plant operations good. |
| 0740 | Blowdown operations good. |
| 0800 | -START Auto Samplers. Total Effluent = 244463456 gal = 34.5 gpm = 17.2°C = 6.75 su. |
| 1015 | -Begin WTP QTRLY Eddy water sampling for WTP Permit. |
| 1110 | - IX System Performance HACH TESTing with Lab Split sampling After 694142 gal Treated: TP-183 = 110 ug/L; TP-174A = 150 ug/L; TP-173A = 2900 ug/L; TP-170 = 4400 ug/L. (High Range on TP-170+173A/Low range on TP-183+174A) |
| 1150 | -START Flush of MP-001 Sample port and check for residual chlorine: NONE detected. OK TO USE HCl preserved vials. |
| 1200 | - Collect 1st set of time paced grab samples From MP-001 for Qtrly WTP Permit sampling - Low Level 1,4-Dioxane, VOCs + NONYPhenols. |
| | -Place samples in to Fridge until packing for Labs. (K) 1405 TOM WAS TAKEN A MANUAL |
| 1300 | -Decant T-351 TO TOP valve. WET well activated. water IS clear NO color. level at the NBIBW SUMP for T/ANS. |
| | -Clean pH-315 probe w/Acid solution. Check the HMI-30 for oil or sheen: None observed. Spray down with Cal. Check. DTW @ 27.06': |
| | -Check TP-430 for oil globules: None observed. water IS clear with yellow-green tint. 6WE 5685.49'. HMI reading |
| 1550 | -START Flush of MP-001 Sample port and check for residual chlorine: None detected. 6585.51' - No cal. Needed. (K) |
| 1600 | - Collect 2nd set of time paced grab samples for Low Level 1,4-Dioxane, VOCs, & NONYPhenols. Place samples in Fridge with others. |
| | -Auto samplers on track/ok. |
| 1945 | Start MP-001 port flush and check for residual chlorine - NONE detected. |
| 2000 | Collect 3rd set of time paced grab samples for low level 1,4-Dioxane, VOC's & NONYphenols - place samples in fridge. |
| 2345 | Start MP-001 port flush and check for residual chlorine - NONE detected. |
| 10/5/21 0000 | Collect 4th set of time paced grab samples for low level 1,4-Dioxane, VOC's & NONYphenols - place samples in fridge with other. |

Influent Sources and Flow Rates: @0745
NBBW – 7.1 gpm
North End On Site- 13.2 gpm
North End Off-Site – 8.8 gpm
RWST – 0.6 gpm
NTES – 0.5 gpm(10R only)
MW38 T-540/541 – 0.3 gpm(Source well and 38 pumping wells mix)
MW38 N & S– 2.2 gpm
COND/NTES T-530- 0.2 gpm(6am-1pm daily)
MW113 Area – 3.3 gpm

Operator: **Mike Gelwick / Chris Carlson**

# LOWRY WTP OPERATIONS LOG

Date: **Tuesday, October 05, 2021**

| Time: | |
|---|---|
| 0335 | -Plants operations Good. STOP GC's SOI can START Efficency checks with BTS sampling |
| 0350 | -START Flush of MP-001 sample port and check for resitual chlorine: None detected. |
| 0400 | - collect 5th set of time paced grab samples for Low Level 1,4-Dioxane, VOCs + NDMA phenols. Place samples in fridge with others |
| 0415 | - BTS sampling and START Efficency checks. Collect TP-730 710 + 740 weekly Low level 1,4-Dioxane samples After BTS sampling. |
| 0710 | - Decant T-351 to TOP valve. wet well activated. water is clear no color. |
| 0750 | - START Flush of MP-001 sample port and check for resitual chlorine: None detected. |
| 0800 | - collect 6th and final set of time paced grab samples for Low Level 1,4-Dioxane, VOC's + NDMA phenols, w/QC volume on all. Place samples in fridge. |
| | - STOP Autosamplers. TOTAL Effluent = 24451464 8gal, A total of 57192 gal treated during sample period. Process composite |
| | samples by gently stirring each with stir stick triple rinsed between composites and checking the pH value of each composite: |
| | SVOC composite = 7.585U and metals/leads composite = 1.945U. Fill sample bottles |
| 1015 | - PACK All samples on ICE for SHIPMENT to Labs (5 coolers) |
| 1300 | - clean pH-315 probe w/Acid solution. Check the Hand Jo for oil or sheen: None observed. Spray down work. |
| | - Check TP-130 for oil globules: None observed water is clear w/light yellow-green tint. |
| 1320 | - Refill BTS phosphorus tank w/5 # of TSP and 50 gal of potable water. |
| 1515 | - Plants operations Good. |

Influent Sources and Flow Rates: @ 0340
NBBW – 7.1 gpm
North End On Site- 13.2 gpm
North End Off-Site – 8.4 gpm
RWST – 0.6 gpm
NTES – 0.49 gpm(10R only)
MW38 T-540/541 – 0.29 gpm(Source well and 38 pumping wells mix)
MW38 N & S– 2.1 gpm
COND/NTES T-530- 0.0 gpm(6am-1pm daily)
MW113 Area – 3.2 gpm

Operator: **Mike Gelwick**

# LOWRY WTP OPERATIONS LOG

Date: **Monday, October 11, 2021**

| Time: | |
|---|---|
| 0550 | Plant operations good. |
| 0600 | Stop MW38N & S Extraction in preparation for MW38 source well batch extraction. |
| 0620 | Increase RWST influent from 0.6 gpm to 2.6 gpm. |
| 0720 | ~~Switch~~ Switch MW38 from direct HMR-30 influent to T-540/541 then start source well. |
| 0840 | - Decant T-351 to TOP valve. Wet well activated. Water is clear Nocolor. |
| | - Clean pH-315 probe w/ Acid solution. Check the HMR30 for oil or sheen: None observed. Spray down wash. |
| | - Check TP-130 for oil globules: None observed. water is very clear and light yellow-green tint. |
| | - Refill polymer tanks w/ 2 cups of NALCO polymer and 200 gal of potable water. |
| 0925 | - working on filter press cleanout + General Plants cleanup |
| 1420 | Change out both 1 Micron bag filters on IX system - very silty from MW113-EW-1 currently. |
| | - Power restored to MW77 Area and system back running. Flow back up to ~8.1 gpm. Change Low Flow Alarm back to 6 gpm. |
| 1540 | - Plants operations Good |
| | *@ Tom has taken manual levels at N. Toe for transducer calibration checks. |
| | MPZ-12 DTW @ 23.79' = GWE 5739.30'. HMI Reading 5739.22' - No Calibration Needed. |
| | MPZ-11 DTW @ 31.98' = GWE 5734.45'. HMI Reading 5734.44' - No Calibration Needed. |
| | NTES-10UN DTW @ 35.93' = GWE 5729.50'. HMI Reading 5729.91' - No Calibration Needed. |
| | MPZ-10R DTW @ 33.96' = GWE 5226.67'. HMI Reading 5729.50' - No Calibration Needed. |
| | NTES SUMP DTW @ 28.79' = GWE 5734.04'. HMI Reading 5731.20' - No Calibration Needed. *@ |

Influent Sources and Flow Rates: @ 0830
NBBW – 2.1 gpm
North End On Site- 13.2 gpm
North End Off-Site – 2.5 gpm
RWST – 2.6 gpm
NTES – 0.51 gpm(10R only)
MW38 T-540/541 – 0.30 gpm(Source well and 38 pumping wells mix)
MW38 ~~N & S~~ 4.8 gpm (Source well 6HCL)
COND/NTES T-530- 0.20 gpm(6am-1pm daily)
MW113 Area – 3.1 gpm

Operator: **Mike Gelwick / Chris Carlson**

# LOWRY WTP OPERATIONS LOG

Date: **Tuesday, October 12, 2021**

| Time: | |
|---|---|
| 0500 | - Plants Operations Good. working on collecting TP-730 GAC/LAB SPLITS and STARTING Effluent checks. ALSO collect TP-740 + 710 Low level 1,4-DIOXANE weekly samples. |
| 0830 | - Decant T-351 to TOP valve. water roll activated. water IS clear no color |
| | - Clean pH-315 probe w/ Acid solution. check the HACH 80 for 0.7 or 5 Green; none observed. Stay Down wash. |
| | - Check TP-180 for oil globules; none observed. water IS very clear w/ Light yellow-green trace |
| | - working on BES sampling and field testing today. |
| 1000 | - IX System performance HACH testing with Lab SPLIT sampling After 730,286 gal treated: TP-183 ⇒ 110 ug/L; TP-174A ⇒ 160 ug/L TP-173A ⇒ 3100 ug/L; TP-170 ⇒ 4200 ug/L |
| 1450 | - working on General Plant clean up. |
| 1600 | - Plants Operations Good. |

Influent Sources and Flow Rates: @ 0525
NBBW – 7.1 gpm
North End On Site- 13.2 gpm
North End Off-Site – 0.7 gpm
RWST – 2.6 gpm
NTES – 0.51 gpm(10R only)
MW38 T-540/541 – 0.30 gpm(Source well and 38 pumping wells mix)
MW38 ~~N&S~~ – 5.0 gpm (SOURCE well STATUS)
COND/NTES T-530- 0.0 gpm(6am-1pm daily)
MW113 Area – 3.3 gpm

Operator: **Mike Gelwick / Chris Carlson**

0.02" rain late yesterday

# LOWRY WTP OPERATIONS LOG

Date: **Wednesday, October 13, 2021**

| Time: | |
|---|---|
| 0500 | Plant operations good. Start MW38N&S extraction to T-540/541 to displace source well water in the conveyance line to T-540/541. Start on weekly GC maintenance & calibrations. |
| ↓ | |
| 0637 | Reboot HMIFTVIEW1 to reset temporary memory, ONLine 0641. |
| 0740 | Blowdown operations good. |
| 0750 | Work with Mike to add 1 full caustic and 1 full HCL tote to main plant supply. |
| 0955 | 783 gallons of MW38N&S have been used to displace source well water to T-540/541. Switch MW38N&S to RWST's. |
| | -Decant T-351 to TOP valve. wetwell activated. Water IS clear NO color. |
| | -Clean pH-315 probe w/Acid solution. Check the HMR30 for oil or sheen: None observed. Spray down water |
| | -Check TP-130 for oil globules: None observed. water IS very clear with light yellow-green tint. |
| 1051 | -Place BTS switch Hold to Flush P-006 pipeline. and flush reactor feed Lines. |
| 1210 | -BTS out of Hold. |
| 1335 | Switch MW38N&S to direct HMR-30 influent - reduce RWST influent from 2.6gpm to 0.6gpm. |
| 1400 | Start on annual device calibrations checks, starting with PDT's |
| 1430 | Stop IX system so those devices can be checked |
| 1615 | Restart IX system. |
| 1630 | Plant operations |

Influent Sources and Flow Rates: @1000
NBBW – 7.1 gpm
North End On Site- 13.7 gpm
North End Off-Site – 8.6 gpm
RWST – 2.6 gpm
NTES – 0.51 gpm(10R only)
MW38 T-540/541 – 0.30 gpm(Source well and 38 pumping wells mix)
MW38 N & S– 2.1 gpm to RWSTs
COND/NTES T-530- 0.20 gpm(6am-1pm daily)
MW113 Area – 3.2 gpm

Operator: **Mike Gelwick / Chris Carlson**

# LOWRY WTP OPERATIONS LOG

Date: **Thursday, October 14, 2021**

| Time: | |
|---|---|
| 0210 | Receive P-601 Fault - check remotely and acknowledge alarm. UV-ox Feed has switched |
| ↓ | automatically to P-600, will troubleshoot later this morning. |
| 0610 | On site - plant operations okay. Primary air compressor down with two blown Fuses. Backup |
| | running but also hear an air leak from the primary, making the backup run harder. |
| | Able to get primary running after changing out A.C Fuses but unit is struggling to |
| | generate air with motor at 100%. Stop primary and isolate it so backup |
| | can keep up better. Note: P-601 Fault was an over voltage fault, possibly related |
| ↓ | to when compressor fuses ~~blew~~ went. Able to get P-601 started again. |
| 0840 | Blowdown operations good. |
| 0900 | -Mike working on weekly Plants Systems checks and calibrations. |
| 0930 | Hayden Meyer of Piper Electric on site to run conduit and network cable from UV-ox to |
| | main PLC for future PLC upgrade. Also will change out two photocell outdoor light |
| | controls if he has time. |
| 0955 | -Decant T-351 to drain when wet well activated. Water is clear no odor. |
| | -Clean pH-315 probe w/ acid solution. Check the HMI 30 for oil or sheen: None observed. Spray down water. |
| | -Check TP-130 for oil globules: None observed. Water is clear w/ light yellow-green hint. |
| 1330 | -Refill 6T3 phosphorus tank w/ 5.5 gal of TSP and 55 gal of potable water. |
| 1340 | -IR on site to troubleshoot/repair main compressor |
| 1348 | -Suspend plant discharge to calibrate pH-740 probe to 4 + 10 pH STD's |
| 1355 | -Resume Normal Discharge, continue with other Plants pH probes calibrations to 4 + 10 pH STD's → pH-113, 629, |
| | 310, 315 + 365. |
| 1440 | - weekly Plants Systems checks and calibrations complete. |
| 1620 | Hayden has finished UV-ox to main PLC comm cable install and replace two out- |
| ↓ | door photocells on lights, leaving now. |
| 1650 | Travis with IR done with his assessment - VFD is damaged (most likely due |
| ↓ | to power surges). Will get new unit on ~~order~~ order. |
| 1715 | Plant ops good. Backup compressors working well. End. |

Influent Sources and Flow Rates: @ 0918
- NBBW – 7.0 gpm
- North End On Site- 13.1 gpm
- North End Off-Site – 8.2 gpm
- RWST – 0.6 gpm
- NTES – 0.57 gpm(10R only)
- MW38 T-540/541 – 0.31 gpm(Source well and 38 pumping wells mix)
- MW38 N & S– 2.2 gpm
- COND/NTES T-530- 0.24 gpm(6am-1pm daily)
- MW113 Area – 3.3 gpm

Operator: **Mike Gelwick / Chris Carlson**

# LOWRY WTP OPERATIONS LOG

Date: **Friday, October 15, 2021**

| Time: 0615 | Plant operations good. Continue on general cleaning / organizing. |
|---|---|
| 0720 | Clean the HACH-30 weir and pH probe - no oil or sheen observed in the HACH-30. Check TP-130 |
| ↓ | for oil globules - none observed. Water is very clear, light green / yellow. |
| 0740 | Blowdown operations good. |
| 1015 | Amy Burk and Mark Petersen of Metro Water Recovery on site for annual pretreatment audit. |
| 1130 | Decant T-351 bottom valve, wet well activated. Water is clear, no color. |
| 1240 | Plant operations good. |

Influent Sources and Flow Rates: 0655
NBBW – 7.0GPM
N. END ON-SITE – 13.0GPM
N. END OFF-SITE – 8.3GPM
RWST – 0.6GPM
NTES – 0.51GPM
COND/NTES T-530 – 0.2GPM (6AM-1PM)
MW38 – 2.1GPM
T-540/541 – 0.3GPM
MW113 IX SYSTEM – 3.3GPM
OTHER – NA

OPERATOR(S) Chris Carlson

# LOWRY WTP OPERATIONS LOG

Date: Saturday, October, 16 2021

| | |
|---|---|
| 0640 | ON site for Weekend systems checks - plant operations good. |
| 0650 | Decant T-351 bottom valve, wet well activated. Water is clear, no color. Clean the HMR-30 weir and pH probe - no oil or sheen observed in the HMR-30. Check TP-130 for oil globules - none observed. Water is very clear, light green / yellow. |
| 0750 | Blowdown operations good. |
| 0940 | PLANT operations good. |
| 10/17/21 0745 | Check plant remotely - All okay. |
| 1815 | Check plant remotely - All okay. |

Influent Sources and Flow Rates: 0643
NBBW – 6.9 gpm
N. END ON-SITE – 13.1
N. END OFF-SITE – 3.4
RWST – 0.6
NTES – 0.53
COND/NTES T-530 – 0.2 gpm (6AM-1PM)
MW38 – ~~0.3 gpm~~ 2.1 gpm
T-540/541 – 0.3 gpm
~~OTHER – NA~~
MW113 Area (IX) 3.4 gpm

OPERATOR(S) Chris Carlson

# LOWRY WTP OPERATIONS LOG

Date: **Monday, October 18, 2021**

| | |
|---|---|
| Time: 0610 | Plant operations good. |
| 0620 | Start Filter press on T-351 (2nd stage 1) |
| 0945 | Blowdown operations good. Clean the HMR-30 weir and pH probe - no oil or sheen observed in the HMR-30. Check TP-130 for oil globules - none observed. Water is very clear, light green/yellow. |
| ↓ | |
| 1220 | filter press full. |
| | Refill phosphorus tank with 60 gallons potable water + 6lbs TSP. |
| 1430 | Plant operations good. |

Influent Sources and Flow Rates: 0647
NBBW – 7.0GPM
N. END ON-SITE – 13.1GPM
N. END OFF-SITE – 8.5GPM
RWST – 0.6GPM
NTES – 0.51GPM
COND/NTES T-530 – 0.2GPM (6AM-1PM)
MW38 – 2.1GPM
T-540/541 – 0.3GPM
MW113 IX SYSTEM – 3.3GPM
OTHER – NA

OPERATOR(S) Chris Carlson

# LOWRY WTP OPERATIONS LOG

Date: **Tuesday, October 19, 2021**

| Time: | |
|---|---|
| 0500 | - Plants operators Good. working on GC's split samplers and starting Efficiency checks. Collect TP-730 GC SPLIT sample and TP-740 & 710 Low level 1,4-Dioxane weekly samples. |
| 0840 | -Decant T-351 to bottom valve. water IS clear No color. working on ATS sampling and field readings today |
| | -Clean pH-315 probe w/Acid Solution. Check the Hmie 30 for oil or sheen: none observed. Spray down work. |
| | - Check TP-130 for oil globules: None observed. Water IS very clear w/ Light yellow-green tint. |
| 0948 | - IX System performance HACH Testing with Lab split sampling After 763,248 gal treated: TP-183 ⊃ 110 ug/L; TP-174A ⊃ 1704 ug/L; TP-173A ⊃ 3200 ug/L; TP-170 ⊃ 4000 ug/L. |
| 1200 | -working on ATS field readings |
| 1540 | - Plants operations Good. |

Influent Sources and Flow Rates: @ 0535
NBBW – 7.0 gpm
North End On Site- 13.1 gpm
North End Off-Site – 8.5 gpm
RWST – 0.6 gpm
NTES – 0.50 gpm(10R only)
MW38 T-540/541 – 0.30 gpm(Source well and 38 pumping wells mix)
MW38 N & S– 2.1 gpm
COND/NTES T-530- 0.0 gpm(6am-1pm daily) 0.20 gpm @ 0840
MW113 Area – 3.4 gpm

Operator: **Mike Gelwick / Chris Carlson**

# LOWRY WTP OPERATIONS LOG

Date: **Wednesday, October 20, 2021**

| Time: | |
|---|---|
| 0545 | Plant operations good. Start on weekly GC maintenance and calibrations. |
| 0745 | Reboot AMIFTVIEW1 to reset available temporary memory, ONline 0748. Blowdown operations good. |
| 1030 | Backup WTP data to flash & CD - daily OneDrive backup working well. |
| | -Decant T-351 to Bottom valve. Wetwell activated. Water is clear no color. |
| | -Clean pH-315 probe w/Acid solution. Check the HMR30 for oil or sheen: None observed. Spray down weir |
| | -Check TP-130 for oil globules: None observed. Water is clear w/ Light yellow-green tint |
| 1115 | - E.T. (Hector + Joel) on site to clean out HMR30 Chamber B. |
| | - Shut down UV-ox and put BTS into Hold. Turn down P-280 CV from MAX IBs to 0% to stop cavitate from pumping. |
| 1256 | - START RWSTS @ 2.9 gpm to START Refilling the HMR30. Also using some potable water to speed up the filling process |
| | - E.T. off site. Chamber B on the HMR30 and its mixer cleaned. |
| 1328 | - START UVOX warming up. |
| 1335 | - Take BTS out of Hold. |
| 1345 | - Plants operations BACK to Normal. |
| 1450 | - Decant T-351 to bottom valve again. Wetwell activated. Water is clear No color. |
| 1530 | - Plants Operations Good |

Influent Sources and Flow Rates: @1355
NBBW – 7.0 gpm
North End On Site- 13.1 gpm
North End Off-Site – 8.1 gpm
RWST – 0.60 gpm
NTES – 0.50 gpm(10R only)
MW38 T-540/541 – 0.30 gpm(Source well and 38 pumping wells mix)
MW38 N & S– 2.1 gpm
COND/NTES T-530- 0.0 gpm(6am-1pm daily)
MW113 Area – 3.3 gpm

Operator: **Mike Gelwick / Chris Carlson**

# LOWRY WTP OPERATIONS LOG

Date: **Thursday, October 21, 2021**

| Time: | |
|---|---|
| 0550 | Plant operations good. |
| 0640 | Reboot HMI-TVIEW1 to upgrade virus detection software - Online 0644. |
| 0745 | Blowdown operations good. |
| 0930 | - Chris working on Emulsion Blower Press. Mike working on weekly plants checks and calibrations |
| 0935 | - decant T-351 to bottom valve. wet well activated. Water IS clear No color. |
| | - Clean pH-315 probe w/ Acid solution. Check TAH-130 for oil or sheen: None observed. Spray down weir. |
| | - Check TAH-130 for oil globules: None observed. water IS Very clear w/ light yellow green tint. |
| 1215 | - Filter Press Ready to Fill. |
| 1330 | Work on annual device calibration checks FT-055 & FT-056. |
| 1314 | - Suspend plant discharge to calibrate pH-740 probe to 4+10 pH STD's. |
| 1320 | - Resume normal Discharge. continue with other WTP pH probes calibrations to 4+10 pH STD's pH #'s 113, 670, 310, 315 & 365 |
| 1400 | - Weekly plants systems checks and calibrations complete. |
| 1550 | - Plants operations Good. |

Influent Sources and Flow Rates: @0956
NBBW – 6.9 gpm
North End On Site- 13.0 gpm
North End Off-Site – 8.1 gpm
RWST – 0.60 gpm
NTES – 0.51 gpm(10R only)
MW38 T-540/541 – 0.30 gpm(Source well and 38 pumping wells mix)
MW38 N & S– 2.2 gpm
COND/NTES T-530- 0.20 gpm(6am-1pm daily)
MW113 Area – 3.3 gpm

Operator: **Mike Gelwick / Chris Carlson**

# LOWER WTP OPERATIONS LOG

Date: **Friday, October 22, 2021**

| Time: | |
|---|---|
| 0545 | Plant operations good. Setup for MW38 pipeline Flushing (sending Flushed water to T-351/352) |
| ↓ | Refill phosphorous tank with 50 gallons potable water + 5 lbs TSP. |
| 0800 | Stop MW38 N & S extraction for pipline Flushing. |
| 0826 | Increase RWST influent to 2.6 gpm From 0.6 gpm. |
| | -Clean pH-315 probe w/Acid solution. Check the AMESO for oil or sheen: None observed. spray down wash. |
| ↓ | -Check pH-130 for oil globules: None observed. water is clear w/ a light yellow-green tint. |
| 0950 | MW38 line Flushing completed - observed a lot of orange / dark orange solids flushing out into T-351, estimated flushing rate was ~30 gpm (used the 2" Trash pump to send clean water from W.M. water truck into the pipeline. |
| ↓ | |
| 1000 | Work with Mike to pull and clean the MW170-ECN1 Flow sensor. |
| 1020 | MW170-ECN1 local Flow meter working well. |
| 1035 | Reduce RWST influent from 2.6 gpm to 0.6 gpm and restart MW38 N & S to direct HMR-30 influent. |
| 1410 | - Work on Backwash of lead carbon GAC-720. Pressure up to 19 psi. |
| 1440 | - Backwash complete. Pressure in GAC-720 Down From 19 to 7 psi. @ 39 gpm. |
| 1530 | - Plants operations Good. Stop Filter Pumps for the night. Alarms set. |
| 1544 | - Receive BTS Strainer warning Alarm. |
| 1600 | - BTS in to Hold to Flush Reactor feed Lines. |
| 1630 | - BTS out of Hold. Resume Normal operations. |
| 1645 | - Receive ADTW Pressure Drop Alarm. P-752 slows down too quickly. After Catch up from maint activities like Flushing or Calibrations |
| | - Switch to P-751 lead. |
| 1700 | - Plants operations Good. |

Influent Sources and Flow Rates: @ 0754
NBBW – 6.9 gpm
North End On Site- 13.0 gpm
North End Off-Site – 8.3 gpm
RWST – 0.6 gpm
NTES – 0.5 gpm(10R only)
MW38 T-540/541 – 0.3 gpm(Source well and 38 pumping wells mix)
MW38 N & S– 2.1 gpm
COND/NTES T-530- 0.2 gpm(6am-1pm daily)
MW113 Area – 3.2 gpm

Operator: **Mike Gelwick / Chris Carlson**

# LOWRY WTP OPERATIONS LOG

Date: SATURDAY, OCTober 23, 2021

| | |
|---|---|
| 0735 | -Plants operations Good. Backpart Filter ES, coming out of Automatic blowdown ok. Go to check other site systems + site security |
| 0900 | -Filter tress full. Decant T-351 to bottom valve. Wetwell activated. Water IS clear NO color |
| | -Clean pH-315 probe w/ Acid solution. Check TK #1 #2 #3 for oil or sheen: None observed. Spray down water |
| | - Check TP-130 for oily globules: None observed. Water IS very clear w/ light yellow-green tint. |
| 1030 | - Plants operations Good |
| 2100 | -Log In From Home Allok |
| Sunday, OCTober 24, 2021 | |
| 0900 | -log in From Home. Plants operations Good. unable to see GC3, try again later. |
| 1145 | - Still unable to Log in to GC3. Come to site to check on it. Lost Network access. Rebooted 2x and still NOT ABLE to Log in Remotely |
| | Chats to check out Dr morning. NOTE: GC3 IS taking and Running samples properly just can't log In Remotely. |
| 2030 | - Log in From Home. Allok. Still can't see GC3. |

Influent Sources and Flow Rates: @ 0800
NBBW – 7.0 gpm
N. END ON-SITE – 13.1 gpm
N. END OFF-SITE – 8.1 gpm
RWST – 0.60 gpm
NTES – 0.53 gpm
COND/NTES T-530 – 0.20 gpm
MW38 – 2.1 gpm
T-540/541 – 0.30 gpm
OTHER – ~~NA~~ IX System/113 Area – 3.3 gpm

OPERATOR(S) Mike Gedwick

# LOWRY WTP OPERATIONS LOG

Date: Monday, October 25, 2021

| Time: | |
|---|---|
| 0530 | Plant operations good. Able to get GE3 reconnected to the 'internet by unplugging and replugging in the LAN connection on the back of the CPU. Work on annual device calibration of flow meters that can be checked while plant is running. |
| 0715 | Blowdown operations good |
| 0915 | Switch MW38 to RWST and increase RWST influent from 0.6 gpm to 2.6 gpm so calibration of FT-012 can be checked. |
| 1000 | Resume MW38 direct influent to HMR-30 and stop RWST influent so FT-015 calibration can be checked. |
| 1040 | Restart RWST influent. |
| 1410 | - Decant T-351 to bottom valve. wet-well activated. water is clear No color. Cleaning on Emmaty filter press |
| | - Clean pH-315 probe w/Acid solution. Check the HMR30 for oil or sheen: None observed. Spray down well. |
| | - Check TP-130 for oily globules: None observed. water is clear w/light yellow-green tint |
| 1525 | - Plant is operations Good. |

Influent Sources and Flow Rates: @0850
NBBW – 6.9 gpm
North End On Site- 13.0 gpm
North End Off-Site – 7.9 gpm
RWST – 0.6 gpm
NTES – 0.5 gpm(10R only)
MW38 T-540/541 – 0.3 gpm(Source well and 38 pumping wells mix)
MW38 N & S– 2.1 gpm
COND/NTES T-530- 0.2 gpm(6am-1pm daily)
MW113 Area – 3.3 gpm

Operator: **Mike Gelwick / Chris Carlson**

# PLANT OPERATIONS LOG

Date: **Tuesday, October 26, 2021**

| Time: | |
|---|---|
| 0500 | - Plant operations Good. working on TP-730 GAC/LAB split sampling and TP-740+710 Low Level 1,4-Dioxane standards. START Efficiency Checks. |
| 0845 | - working on BTS weekly sampling & Field Readings today. Refill phosphorus tank w/ 6 # of TSP and 60 gal of potable water. |
| 0950 | - IX System Performance HACH Testing and weekly Lab split sampling After 795,734 gal Treated: TP-183 = 110 ug/L ; TP-174A = 180 ug/L ; TP-173A = 3300 ug/L ; TP-170 = 4100 ug/L. |
| 1150 | - Decant T-351 to bottom valve. wetwell activated. Water is clear No color. |
| | - Clean PH-315 probe w/ Acid solution. Check the HMR30 for oil or sheen: None observed. Spray down wash. |
| | - Check TP-130 for oil globules: None observed. Water is clear w/ Yellow green hint. |
| 1330 | Place N. TOE in divert to T-530 and ~~increase~~ Set T-530 to BTS at 0.5 gpm for FT-035 calibration check. |
| 1402 | Place NBBW in divert to RWST for FT-025 calibration check. 1425 NBBW back to normal HMR-30 influent. |
| 1440 | Stop T-530 to BTS and return N. TOE to direct BTS influent. |
| 1545 | - Plants operations Good. |
| 2005 | - lose Partial down to the plant. Come to site to troubleshoot and turn things off for restart. |
| | - leave MW170-End running and the 0.3 charge pumps. these not Affected by power outage. 610 En Hold Rest of plant off NBBW Into RWBTS + Also MW38. Could not see Any fuses on site blown. May be an Xcel Fuse. I leave En this mode overnight. |
| 2145 | - Leave site |

Influent Sources and Flow Rates: @ 0535
NBBW – 7.0 gpm
North End On Site- 13.1 gpm
North End Off-Site – 8.2 gpm
RWST – 0.6 gpm
NTES – 0.51 gpm(10R only)
MW38 T-540/541 – 0.30 gpm(Source well and 38 pumping wells mix)
MW38 N & S– 2.1 gpm
COND/NTES T-530- 0.0 gpm(6am-1pm daily)
MW113 Area – 3.2 gpm

Operator: **Mike Gelwick / Chris Carlson**

# LOWRY WTP OPERATIONS LOG

Date: **Wednesday, October 27, 2021**

| Time | |
|---|---|
| 0450 | Check plant remotely - Look like power was restored to normal by Xcel at 0028. Start |
| ↓ | on weekly GC maintenance and calibrations. |
| 0517 | Take BTS out of hold |
| 0600 | On site - get compressors restarted |
| 0615 | Start UV-Ox (warming up). |
| 0620 | Start N. End off site influent |
| 0622 | Start Ion Exchange - continue on GC's. |
| 0740 | Blowdown operations good. |
| 0810 | Increase RWST influent from 0.6 gpm to 1.2 gpm (tanks @ 34%). |
| 0906 | Receive UV-Ox shutdown - Lamp No Contact #1 indicated on local display - when trying restart |
| ↓ | observed no Amps, indicating the lamp has failed. Note: 2188 hours and 18 restarts on |
| ↓ | this lamp. Checked capacitor bank - All look good - no burnt wiring. Change out lamp |
| ↓ | and restart - Unit warmed up and started discharging with new lamp. Hopefully just |
| ↓ | a bad lamp - lamp put in is from the same batch. |
| 0945 | - Decant T-351 to bottom valve. Wet well activated. water is clear no color. |
| | - Clean pH-315 probe w/ acid solution. Check the HMI-30 for oil or sheen: none observed. Spray down work. |
| | - Check TP-130 for oil globules: None observed. water is clear w/ light yellow green tint. |
| 1102 | - Switch NTES to divert and increase P-005 to 0.50 gpm while I setup for pipeline flushing. Need to change out a valve. |
| 1224 | - NTES back to normal operations. Switch back to normal mode and turn P-005 back down to 0.20 gpm. |
| 1500 | - Plants operations Good. |

Influent Sources and Flow Rates: @ 0740
NBBW – 6.9 gpm
North End On Site- 13.0 gpm
North End Off-Site – 9.3 gpm
RWST – 0.6 gpm
NTES – 0.50 gpm(10R only)
MW38 T-540/541 – 0.25 gpm(Source well and 38 pumping wells mix)
MW38 N & S– 2.0 gpm
COND/NTES T-530- 0.23 gpm(6am-1pm daily)
MW113 Area – 3.1 gpm

Operator: **Mike Gelwick / Chris Carlson**

# LOWRY WTP OPERATIONS LOG

Date: **Thursday, October 28, 2021**

| Time: | |
|---|---|
| 0735 | - Plants operations Good. Coming out of blowdown arc. Worker starting up to push potable water thru the NTES pipeline @ 0.50 gpm to the BTS to displace NTES water in pipeline. Using 1" Diaphram pump set @ low psi to match what NTES has been doing. Will track the water being pushed out until at least 400 gal ~~has been~~ in of potable water has been put into the pipeline. MPZ-10R is off. |
| 0840 | - START 1" Diaphram pump @ NTES pumping potable water to NTES pipeline. FT-035 NTES to BTS total at START 6664160 gal. |
| 1023 | - lose pressure on pipeline to NTES. troubleshoot problem. STOP 1" Diaphram pump. Put NTES into divert and set p-005 to 0.50 gpm until I fix the issue. |
| 1115 | - NTES flow BACK to Normal mode. Pump had a piece of HOPE shaving stuck in check ball. seems to be ok now. working on weekly/monthly Plants Systems checks and calibrations |
| 1245 | - Decant T-351 to top valve. wet well activated. water is clear No Color |
| | - Clean pH-315 probe w/Acid solution. Check the Hand 30 for oil or sheen: None observed. Spray down weir. |
| | - Check TP-130 for oil globules! None observed. water is very clear w/ light yellow-green tint. |
| 1430 | - Plants system checks complete. STILL need to perform weekly/monthly pH probe calibrations and LEL-740 calibration. |
| 1600 | - Plants operations Good. leaving pump running potable water into NTES pipeline and will return later to stop it. |
| 2230 ~~2235~~ | - switch NTES to divert to T-530 and turn on p-005 @ 0.50 gpm. will let whatever is left in pipeline gravity feed to T-530 |
| | - STOP 1" Diaphram pump and close valves @ NTES. FT-035 NTES to BTS total @ 6664563 gal / 403 gal potable water into pipeline |
| 0035 | - receive BTS 3323 strainer Alarm. Log in remotely and switch to 3324 BACKUP for Reactor 3. |

Influent Sources and Flow Rates: @ 0735
NBBW – 6.8 gpm
North End On Site- 12.9 gpm
North End Off-Site – 8.3 gpm
RWST – 1.2 gpm
NTES – 0.49 gpm(10R only)
MW38 T-540/541 – 0.30 gpm(Source well and 38 pumping wells mix)
MW38 N & S– 2.1 gpm
COND/NTES T-530- 0.20 gpm(6am-1pm daily)
MW113 Area – 3.1 gpm

Operator: **Mike Gelwick / Chris Carlson**

# LOWRY WTP OPERATIONS LOG

Date: **Friday, October 29, 2021**

| Time: | |
|---|---|
| 0545 | Plant operations good. |
| 0610 | Restart clean water displacement of N. Tee water in conveyance pipeline for preflushing prep. |
| 0800 | - STARTing Flush of NTES pipeline w/clean water using a 2" trash pump and WM water truck. ~500gal of clean water introduced to pipeline prior to flushing |
| 0930 | - Flushing w/clean water thru NTES pipeline complete. Water started out THICK and black but cleared up to very clear. |
| 0945 | - RESTART MP2:10R pumping. Set @ 60psi for now to clear some of the clean water out to T-530, T-530/A-005 @ 0.5gpm to BTS. |
| 1140 | - Decant T-351 to TOP valve. wet well activated. Water IS clear NO color. |
| | - Check THE HAWK 30 for oil or sheen: None observed. Spray down Weir, will clean pH-345 just prior to calibration |
| | - Check TP-130 for oil globules: None observed. Water IS very clear NO color. STILL clean water coming THRU pipeline |
| | - Refill polymer TANK w/ 2 cups of NALCO polymer and 200gal of potable water. |
| 1200 | - Work on set up and calibration of Autosamplers for Monday Monthly Sampling Event. Will be resampling SVOC's for Analyte bis (2-Ethylhexyl) phthalate. Triple Rinse each dedicated composite container, will add preservatives just prior to start up. |
| 1240 | - Calibrate BTS pH probes (monthly) w/ new 4+10 pH STD's |
| 1320 | - START on calibrations of WTP pH probes to NEW 4+10 pH STD's. |
| 1352 | - Suspend plant discharge to calibrate pH-740 probe to New 4+10 pH STD's and LEL-740 sensor to 49% LEL, U sing calibrated site multimeter to ensure 0% LEL in T-740 |
| 1408 | - Plant Shut down for High LEL during calibration @ 8% LEL. High LEL shut down operations Good. |
| 1412 | - RESTART Plant. |
| 1413 | - Resume Normal Discharge |
| 1445 | - Plant is operations Good. Leaving NTES pump to T-530 For A while to ensure clean water out of pipeline. |

Influent Sources and Flow Rates: @ 1140
NBBW – 6.9 gpm
North End On Site- 13.0gpm
North End Off-Site – 8.5 gpm
RWST – 1.2 gpm
NTES – 1.29 gpm(10R only) to T-530
MW38 T-540/541 – 0.31 gpm(Source well and 38 pumping wells mix)
MW38 N & S– 2.1 gpm
COND/NTES T-530- 0.48 gpm(~~6am-4pm daily~~) to BTS on overflow
MW113 Area – 2.9 gpm

Operator: **Mike Gelwick / Chris Carlson**

# LOWRY WTP OPERATIONS LOG

Date: 10/31/21 Sunday

| | |
|---|---|
| 1200 | Plant operations good (Mike was remotely logged in)<br>Check TP-130 for oil globules: None observed. Water is very clear with yellow-green tint.<br>Clean pH-315 probe with acid solution. Check HMR-30 for oil or sheen: none observed. Spray down weir.<br>Both GC's operational within limits<br>All Blowers ok<br>Phosphorus tank @ 90 gal |
| 1400 | Plants operations good. |

~~Saturday~~ Sunday, October 31, 2021

| | |
|---|---|
| 0754 | - Receive NTES unstable Alarm. Log in and switch NTES to Normal mode and set p-005 to 0.20 gpm 6Am → 1pm daily. Looks like trench has pumped down to a recharge level and NOT quite making 0.50 gpm. |
| 1200 | - Log in Remotely. Allow. |
| 2230 | - Log in Remotely. Allow. |

Saturday, October 30, 2021

| | |
|---|---|
| 1400 | - Log on Remotely. p-352 in Alarm for Starter but did NOT Receive Alarm. It has turned itself off OK. Acknowledge alarm and leave off until I can clean strainer. All else ok. NTES shilgoing to T-530. |
| ~~2015~~ 1952 | - Receive p-332 starter warning. Unable to fix from Home due to using BACKUP on R3 currently. Go to 5.2 to Flush BTB Lines |
| 2040 | - BTB In to maint. Hold to Flush BTB Feed Lines. & Fill phosphorus tank w/ 6# of TSP and 60 gal of potable water |
| 2105 | - BTB out of Hold |
| 2115 | - BTB Running ok now. End. |

Influent Sources and Flow Rates: @ 1300
NBBW – 6.9 gpm
N. END ON-SITE – 13.0 gpm
N. END OFF-SITE – 8.9 gpm
RWST – 1.2 gpm
NTES – 0.51 gpm
COND/NTES T-530 – 0.20 gpm
MW38 – 2.1 gpm
T-540/541 – 0.3 gpm
OTHER – NA
MW113 Area: 2.9 gpm

OPERATOR(S) Manuela Seewald

# LOWRY WTP OPERATIONS LOG

Date: **Monday, November 01, 2021**

| Time: | |
|---|---|
| 0600 | Plant operations good. |
| 0610 | Decant T-551 top valve, wet well activated. Water is clear, no color. Clean the HMR-30 weir and pH probe - No oil or sheen observed in the HMR-30. Check TP-130 for oil globules - none observed. Water is slightly cloudy green/yellow (to be expected - NTES trench was pumped harder saturday and level is now down to the pump activation level. - Stop IX system and change out the 1 micron bag filter before T-113 - flow improved a little when restarted but stopped again to change out 1 micron bag filter after the retention tank T-114. This bag looked okay and could go longer but changed out anyway - will note to run this bag for ~2 months before inspecting and changing next time. |
| 0740 | Blowdown operations good. Mike - adding preservitives to composite containers for month effluent sampling (note: resampling for quarterly SVOAs due to blank contamination at the lab when running the sample collected in October). - Auto samplers pre setup by Mike on Friday. |
| 0800 | Mike starting both auto samplers. Effluent total reading 245,852,464 gallons, FT-770 @ 34.6 gpm, pH-740 @ 6.77 @ 16.8°c |
| 0810 | Observed NTES conveyance pipeline pressure is lower than normal. Trench may not be producing 0.5 gpm (current flow set point) or pipeline issue - Mike checking the N. Toe double containment sump to rule out any pipline issue - sump is still dry as normal. Adjust flow set point to 0.49 GPM @ 0825. |
| 1015 | -working on monthly Early warning sampling |
| 1100 | - IX system performance HACH testing with LAB split sampling AFTER 820202 gal treated: TP183 ≈ 150 ug/L |
| | TP-174A ≈ 250 ug/L; TP-173A ≈ 3400 ug/L; TP-170 ≈ 4200 ug/L. |
| 1150 | -START FLUSH OF MP-001 sample port and check for Residual Chlorine: None detected. OK to use tested personal vials |
| 1200 | -collect 1st set of time paced GRAB samples for Low-Level 1,4-Dioxane. Place samples onto Fridge. |

Influent Sources and Flow Rates: @0805
- NBBW – 6.6 gpm
- North End On Site- 13.0 gpm
- North End Off-Site – 8.2 gpm
- RWST – 1.2 gpm
- NTES – 0.48 gpm(10R only)
- MW38 T-540/541 – 0.3 gpm(Source well and 38 pumping wells mix)
- MW38 N & S– 2.1 gpm
- COND/NTES T-530- 0.2 gpm(6am-1pm daily)
- MW113 Area – 3.1 gpm

Operator: **Mike Gelwick / Chris Carlson**

# LOWRY WTP OPERATIONS LOG

Date: **Monday, November 01, 2021 – Cont'd**

| Time: | |
|---|---|
| 1225 | -Clean P-352 y strainer and flush line after. |
| 1230 | -START P-352 pumping to Hwy30 @ 0.50gpm. |
| 1550 | -START Flush of MP-001 sample port and check for Residual Chlorine: NONE Detected. Auto samplers on track ok. |
| 1600 | -Collect 2nd set of time paced GRAB samples for Low Level 1,4-Dioxane and place samples in fridge with others. |
| | -Plants operations Good. |
| 1945 | Start MP-001 port flush and check for residual chlorine - none detected. |
| 2000 | Collect 3rd set of time paced grab samples for low level 1,4-Dioxane - place sample in fridge. |
| 2345 | Start MP-001 port flush and check for residual chlorine - none detected. |
| 0000 | Collect 4th set of time paced grab samples for low level 1,4-Dioxane - place sample in fridge. |

Influent Sources and Flow Rates: @1350
NBBW – 6.9 gpm
North End On Site- 13.0 gpm
North End Off-Site – 8.9 gpm
RWST – 1.12 gpm
NTES – 0.50 gpm(10R only)
MW38 T-540/541 – 0.30 gpm(Source well and 38 pumping wells mix)
MW38 N & S– 2.1 gpm
COND/NTES T-530- 0.0 gpm(6am-1pm daily)
MW113 Area – 3.1 gpm

Operator: **Mike Gelwick / Chris Carlson**

# LOWRY WTP OPERATIONS LOG

Date: **Tuesday, November 02, 2021**

| Time: | |
|---|---|
| 0335 | - Plants operations Good. Get ready for BTS sampling and START Tng of Efficiency checks |
| 0350 | - START Flush of MP-001 and check for Residual Chlorine: None Detected |
| 0400 | - Collect 5th set of Time paced grab samples for Low Level 1,4-Dioxane. Places Samples in Fridge with others |
| 0408 | - Working on BTS sampling and START Efficiency checks |
| 0455 | - Collect TP-730 GC Lab split samples and TP-710 + 740 Low Level 1,4-Dioxane Labs Samples |
| 0515 | - work on getting ready for BTS Field Readings. |
| 0750 | - START Flush of MP-001 sample port and check for Residual chlorine: None detected |
| 0800 | - collect 6th and final set of time paced grab samples for Low-Level 1,4-Dioxane. Place samples in Fridge with others. |
| | - STOP Auto samplers and process composites by Gently stirring each w/Rinse of SHR Stick in between composites and checking the pH values of each composite. SVOC's Resample composite pH ⇒ 6.92 SU and Metals composite 7.39 SU. Fill sample bottles. |
| | - TOTAL EFFluent ⇒ 24590 774 gal. A TOTAL of 50,310 gal treated during sample period. NOTE: only Analyte getting Resampled in the SVOC's composite is bis(2-ethylhexyl) pthalate. PACK Samples on Ice for courier pickup |
| 1004 | Observe MW113-EW-1 extraction pump had stalled, restarted at 1111. |
| 1119 | Reboot HMI FT VIEW1 to ~~reste~~ reset available temporary memory. Online 1124. |
| 1240 | - Decant T-351 to TOP valve. wetwell activated. water is clear no color |
| ↓ | - Clean pH-315 probe w/ Acid solution. Check the Hood 80 for oil or sheen: None observed. Spray down area. |
| ↓ | - Check PA130 for oil globules: None observed. water is Clear w/ Yellow-green tint. |
| 1400 | Plant operations good. |

Influent Sources and Flow Rates: @0350
NBBW – 6.9 gpm
North End On Site- 13.0 gpm
North End Off-Site – 9.2 gpm
RWST – 1.2 gpm
NTES – 0.50 gpm(10R only)
MW38 T-540/541 – 0.30 gpm(Source well and 38 pumping wells mix)
MW38 N & S– 2.0 gpm
COND/NTES T-530- 0.0 gpm(6am-1pm daily) 0.20 ⇒ 0745
MW113 Area – 3.1 gpm

Operator: **Mike Gelwick / Chris Carlson**

# LOWRY WTP OPERATIONS LOG

Date: **Wednesday, November 03, 2021**

| Time: | |
|---|---|
| 0540 | Plant operations good. Start on weekly GC maintenance and calibrations. Refill phos. |
| ↓ | tank with 50 gallons potable water + 5lbs TSP. |
| 0750 | Blowdown operations good. Work on device calibration checks (BTS reactor flow meter) |
| 0835 | - Decant T-351 to TDP valve. Wet well accumulated. Water ES clear no odor. |
| | - Clean pH-315 probe w/Acid solution. Check the HMI#30 for oil or sheen: None observed. Spray down wall. |
| | - Check TP-130 for oil globules: None observed. Water ES Clear w/yellow green tint. Pressure on Line back up to normal. |
| 1130 | Weekly WTP data back up to CD & FlashDrive. Daily OneDrive backup working well. |
| 1230 | - Washout Filter Area 5 |
| 1345 | - Filter Press Ready to fill. |
| 1545 | - Plants operating Good. |

Influent Sources and Flow Rates: @0456
NBBW – 6.6 gpm
North End On Site- 12.9 gpm
North End Off-Site – 8.2 gpm
RWST – 1.2 gpm
NTES – 0.5 gpm(10R only)
MW38 T-540/541 – 0.3 gpm(Source well and 38 pumping wells mix)
MW38 N & S– 2.0 gpm
COND/NTES T-530- 0.2 gpm(6am-1pm daily)
MW113 Area – 3.1 gpm

Operator: **Mike Gelwick / Chris Carlson**

# LOWRY WTP OPERATIONS LOG

Date: **Thursday, November 04, 2021**

| Time: | |
|---|---|
| 0530 | Plant operations good. Perform waste characterization on full sludge roll-off box R19306ML |
| 0850 | - Decant T-351 to TDP valve. Wet well activated. water is clear no DC chlor. |
| | - Clean pH-315 probe w/Acid solution. Check the Hood for oil or sheen: None observed. Stay down water. |
| | - Check TA-130 for oily globules: None observed. water is very clear w/light yellow-green tint. |
| | - working on Plants Systems checks and calibrations today. |
| 1145 | - Reduce RWST flow to 0.60 gpm. TANKS @ 27%. |
| 1150 | - Suspend WTP Discharge to calibrate pH-7&10 to 4+10 pH STD's. |
| 1157 | - Resume Normal Discharge. continue with other WTP pH probes calibrations to 4+10 pH STD's @ pH-113, 670, 310, 315 & 365. |
| 1245 | - Plants weekly systems checks and calibrations complete. |
| | Continue on annual device calibration check at RWST then outdoor Ultrasonic level sensor |
| | ON T-530, 540 & 541. |
| 1500 | Plant operations good. |

Influent Sources and Flow Rates: @0803
NBBW – 6.6 gpm
North End On Site- 13.0 gpm
North End Off-Site – 8.1 gpm
RWST – 1.2 gpm
NTES – 0.4 gpm(10R only) 0.5
MW38 T-540/541 – 0.3 gpm(Source well and 38 pumping wells mix)
MW38 N & S– 2.0 gpm
COND/NTES T-530- 0.2 gpm(6am-1pm daily)
MW113 Area –3.0 gpm

Operator: **Mike Gelwick / Chris Carlson**

# LOWRY WTP OPERATIONS LOG

Date: **Friday, November 05, 2021**

| Time | |
|---|---|
| 0540 | Plant operations good. Refill phosphorous tank with 30 gallons of potable water + 3 lbs TSP. |
| ↓ | Continue annual device calibration checks at TT-710, TT-670, TT-740 FE-3541 FT-3541. |
| 0740 | Blowdown operations good. |
| 0800 | ANNUAL RCRA training - given by Brian Kelly of WSP. DAN G., Manuela S., Tom G., Mike G. & Chris C. in attendance. |
| 1125 | -Decant T-351 to TOP valve. Wet well activated. water is clear no color. |
| | -Clean AH-315 probe w/Alert solution. Check the tank for oil or sheen: None observed. Spray down weir. |
| | -Check TA-130 for oil globules: None observed. water is very clear w/ light yellow-green tint. |

Influent Sources and Flow Rates: @0952
NBBW – 6.6 gpm
North End On Site- 12.9 gpm
North End Off-Site – 2.4 gpm
RWST – 0.6 gpm
NTES – 0.5 gpm(10R only)
MW38 T-540/541 – 0.3 gpm(Source well and 38 pumping wells mix)
MW38 N & S– 2.0 gpm
COND/NTES T-530- 0.2 gpm(6am-1pm daily)
MW113 Area – 3.1 gpm

Operator: **Mike Gelwick / Chris Carlson**

# LOWRY WTP OPERATIONS LOG

Date: Saturday, November 06, 2021

| | |
|---|---|
| 0800 | Plant operations good. |
| 0945 | - Decant T-351 from top valve - wet well activated - water is clear no color |
| | - Clean ph-315 probe w/ muriatic Acid solution |
| | - Checked HMR30 for oil or sheens; none observed - sprayed down weir. |
| | - Check TP-130 for oil globules; none observed, water is clear w/ green/yellow tint |
| 1030 | - Plant operations good |
| (E) 0301 | Receive T-540/541 low warning alarm, level at 20%. - Stop P-006 for the remainder of the weekend. Note: Held of on doing source well batch because it's close to be sampled and sample crew couldn't get to it until Monday at the earliest. Plant operations good. |
| 1415 | Check plant remotely - All Okay |
| 11/7/21 0510 | (0610 plant time) Not adjusting clocks until Monday. All okay. |
| 1304 | (1403 plant time) Receive multi Alarms / plant off. Power interruption - Acknowledge alarm remotely then go to site. |
| 1336 | On site A phase fuse on Xcel feed ~~pole~~ (W) power pole on west side of Gun Club blown. - call in outage to Xcel. And prepare to be down for a while - both backup generators working. Last NTES generator started. |
| 1400 1600 (E) | Plant set to be off with BTS in hold for the night @ 1615 (plant time) |
| 1701 | (1601 plant time) Xcel has restored power - Restart plant remotely. Will run on BTS & N. End on-site overnight (both do not need compressed air - compressors powered off so they can be restarted under controlled conditions. (E) |

Influent Sources and Flow Rates: 0918
NBBW – 6.9 GPM
N. END ON-SITE – 13.0 GPM
N. END OFF-SITE – 8.7 GPM
RWST – 0.6 GPM
NTES – 0.47 GPM
COND/NTES T-530 – 0.21 GPM
MW38 – 2.1 GPM
T-540/541 – 0.0 OFF
OTHER – NA

OPERATOR(S) Tom Gilbert

# LOWRY WTP OPERATIONS LOG

Date: **Monday, November 08, 2021**

| Time: | |
|---|---|
| 0254 | (0354 plant time) Receive P-3323 strainer alarm. Remotely acknowledge alarm and |
| ↓ | switch R3 feed from P-3323 to P-3324. |
| 0400 | (0500 plant time) ON site. Plant operations okay - BTS & N. End ONSITE only overnight. |
| ↓ | Power on air compressors - adjust GC CPU clocks back to standard time and reboot. |
| 0420 | (0520 plant time) Stop plant and begin to adjust HMI's and PLC times back to standard |
| ↓ | time. |
| 0426 | HMI FTVIEW1 Online with new time setting and reboot. |
| 0431 | HMI2 Online with new time setting and reboot. |
| 0432 | PLC times sync'd. |
| 0435 | Restart plant, including UV-Ox, IX & N. End off site. Keep RWST influent at 2.5gpm |
| ↓ | in preperation for MW36 source well batch extraction. |
| 0600 | MW38 N&S wells off - Switch MW38 from direct HMR-30 influent to T-540/541 - Then |
| ↓ | go to source well and start batch extraction. |
| 0740 | Blowdown operations good. |
| 0900 | - Put new tote of NaOH in bay ready for blowdown |
| 0945 | - Becant FT351 to TOP valve, wet well activated, water FS clear NO odor. |
| | - Clean pH-315 probe w/acid solution. Check reactor 30 for oil or sheen: None observed. Spray down room. |
| | - Check TP-130 for oily globules: None observed. water FS very clear w/ light yellow green tint. |
| 1015 | Begin quarterly/monthly POTW discharge line valve exercising / leak |
| ↓ | check at discharge manhole - Flow looks good. |
| 1030 | Suspend discharge and exercise isolation valve on west side of |
| ↓ | E-470 - 1032 Restart discharge - 1046 Suspend discharge for valve |
| ↓ | exercising on east side of E 470 - 1049 Restart discharge. 1118 |
| ↓ | Suspend discharge for on site valve exercising - 1121 resume discharge |
| 1130 | Discharge line check / valve exercising completed - no leaks All okay. |
| 1530 | Plants operations Good |

Influent Sources and Flow Rates: 0533
NBBW – 6.8GPM
N. END ON-SITE – 12.9GPM
N. END OFF-SITE – 9.6GPM
RWST – 2.5GPM
NTES – 0.51GPM
COND/NTES T-530 – 0.2GPM (6AM-1PM)
MW38 – 0.8GPM
T-540/541 – 0.0GPM
MW113 IX SYSTEM – 3.1GPM
OTHER – NA

OPERATOR(S) Chris Carlson / Mike Gelwick

# LOWRY WTP OPERATIONS LOG

Date: **Tuesday, November 09, 2021**

| Time: | |
|---|---|
| 0450 | - Plants operations Good. working on TP-730 GC/Lab split sampling and Also collect TA 710+740 low level 1, 4-D Skane samples and Stacy working on Efficiency checks. |
| 0545 | Plant operations good - work on GC2 trap change out. |
| 0700 | Receive FV-746 Fail to open alarm when plant dropped into blowdown - UV-ox shutdown due to low flow. Solenoid connection loose, valve opened when solenoid moved. Leave UV-ox off for now (Need to check calibration of FT-670 anyway). |
| 0845 | - Decant T-351 to TOP valve. wet well activated. water is clear no color<br>- Clean pH-315 probe w/Acid solution. Check the Hose for oil or sheen: None observed. Spray down wash<br>- Check TP-130 for oil globules: None observed. Water is very clear w/light yellow-green tint<br>- Refill BTS phosphorus tank w/6 # of TSP and 60 gal of potable water. working on BTS sampling and weekly BTS Field readings today. |
| 1000 | FT-670 calibration completed - All OK. |
| ~~1023~~ | ~~Stop P-521/522 so FT-675 calibration could be checked~~ |
| 1030 | IX performance HACH testing and Lab split samples AFTER 852,214 gal treated: TP-185 = 130 ug/L; TP-174A = 190 ug/L; TP-173A = 3700 ug/L; TP-170 = 4600 ug/L. |
| 1230 | T-540/541 at 80%. Stop MW38 batch extraction. |
| 1255 | Restart MW38 N+S extraction to T-540/541 to displace source well water IN the pipeline to T-540/541 |
| 1258 | Restart UV-ox - Note 1308 when warm up completed FV-746 worked - will continue to watch for more failures and replace solenoid if needed. |
| 1311 | Stop P-521/522 so FT-675 calibration can be checked. |
| 1330 | Restart P-521/522. |
| 1525 | - Plants operations Good. |
| 1820 | - Switch MW38 N+S wells from T-540/541 to EWST. 6,33 gal Run thru pipeline Prior to switch |

Influent Sources and Flow Rates: @0522
NBBW – 6.8 gpm
North End On Site- 12.9 gpm
North End Off-Site – 8.2 gpm
RWST – 2.5 gpm
NTES – 0.51 gpm(10R only)
MW38 T-540/541 – 0.30 gpm(Source well and 38 pumping wells mix)
MW38 ~~N&S~~ 5.0 gpm ~~seasonal~~ BATCH
COND/NTES T-530- 0.24 gpm(~~6am-1pm daily~~)
MW113 Area – 3.0 gpm

Operator: **Mike Gelwick / Chris Carlson**

# LOWRY WTP OPERATIONS LOG

Date: Wednesday, November 10, 2021

| Time: | |
|---|---|
| 0545 | Plant operations good. Start on weekly GC maintenance and calibrations. |
| 0615 | Jim B. of Brownhill on site to troubleshoot P-114 high CV alarm and talk about UV-OX |
| ↓ | PLC upgrade. Jim able to do a quick fix for P-114 logic - alarm tested and working. |
| 0715 | Observe HART2 CPU is not responding (locked up during data backup). Reboot CPU - Online 0719. |
| 0740 | Blowdown operation good. |
| 0750 | Reduce RWST influent from 2.5 gpm to 1.0 gpm and switch MW38 N & S from RWST influent to direct HMR-30 influent. |
| 0915 | - Decant ~~T-351a~~ T-530 to TOP valve, wet well activated. water is clear locator |
| | - Clean pH-315 probe w/ acid solution. Check the HMR-30 for oil or sheen: None observed. Spray down weir |
| | - Check HP-130 for oil globules: None observed. water is very clear w/ light yellow-green tint. |
| 1200 | Backup data to CD & Flash. Daily OneDrive backup working well. |
| 1340 | - Add ~20 gal of Water Phase Layer of MNA-09 satellite Drum in to T-530. NO NAPL collected. Decanted from drum using a perisaltic pump. |
| 1500 | - Plants operations Good. |

Influent Sources and Flow Rates: @ 0905
NBBW – 6.8 gpm
North End On Site- 12.9 gpm
North End Off-Site – 8.2 gpm
RWST – 1.0 gpm
NTES – 0.51 gpm(10R only)
MW38 T-540/541 – 0.30 gpm(Source well and 38 pumping wells mix)
MW38 N & S– 2.1 gpm
COND/NTES T-530- 0.20 gpm(6am-1pm daily)
MW113 Area – 2.3 gpm

Operator: **Mike Gelwick / Chris Carlson**

# LOWRY WTP OPERATIONS LOG

Date: **Thursday, November 11, 2021**

| Time: | |
|---|---|
| 0530 | Plant operations good. Setup for yearly personal SUMA air sampling - Mike, Tom & self to wear the air samples during a normal 8hr shift today. |
| 0740 | Blowdown operations good. |
| 0846 | Shutdown ION exchange to change out 1 micron bag filter before P-114. |
| 0856 | Restart ION Exchange. |
| 0905 | - Decant T-351 to TOP valve. Wetwell activated. Water is clear no odor. |
| | - clean pH-315 probe w/Acid solution. Check the HMI-30 for oil or sheen: None observed. Spray down weir. |
| | - Check TP-130 for oil globules: None observed. Water is very clear w/light yellow-green tint. Working on weekly Plants Systems checks and calibrations. |
| 1152 | - Suspend plant discharge to calibrate pH-740 probe to 4 + 10 pH STDs. Switch to P-751 lead to clean P-752 Check ball AFter checks |
| 1201 | - Resume Normal Discharge. Continue with other pH probes calibrations to 4+10 pH STDs: pH-113, 679, 310, 315 & 365. |
| 1250 | - Weekly plants systems checks and calibrations complete. Work on clean of P-752 check ball. |
| 1310 | - Cleaned check ball on P-752. Not too bad. A little dirty. Upon switching back to lead on P-752 received Pressure drop alarm again. Check ball may still be sticking. May need to change out w/New ones. |
| 1314 | - Discharging Normal again. Leave on P-751 until next week and will switch to P-752 AFter calibration of pH-740. |
| 1530 | - Plants operations Good. |

Influent Sources and Flow Rates: @ 0754
NBBW – 6.8 gpm
North End On Site- 12.8gpm
North End Off-Site – 8.8 gpm
RWST – 1.0 gpm
NTES – 0.5 gpm(10R only)
MW38 T-540/541 – 0.3 gpm(Source well and 38 pumping wells mix)
MW38 N & S– 2.1 gpm
COND/NTES T-530- 0.2 gpm(6am-1pm daily)
MW113 Area – 2.9 gpm

Operator: **Mike Gelwick / Chris Carlson**

# LOWRY WTP OPERATIONS LOG

Date: **Friday, November 12, 2021**

| Time: | |
|---|---|
| 0730 | - Plant Operations Good. |
| 0800 | - Decant T-351 to TOP valve. WCT well activated. Water IS clear no color |
| | - Clean pH-315 Probe w/Acid solution. Check the HMI 30 for oil or sheen: None observed. Spray down water |
| | - Check TH-130 for oily globules: None observed. Water IS very clear w/ light yellow-green tint. |
| 0845 | - IR on site (2 techs) to fix motor on one of the Black UP compressors and service others. |
| 0907 | - Place BTS Influent Maint. Hold and work on Flushing P-006/T-540/541/sediment tank piping and BTS Reactor Feed piping. |
| 1022 | - ~~Out of~~ In BTS out of Hold. |
| 1215 | - Refill BTS phosphorus tank w/5# of TSP and 50 gal of potable water. Put Bottle orders Away. |
| 1255 | - Decrease flow on IX System to 2.7 gpm From 2.8 gpm. CV on the pump came up fairly quickly around 8Am and we just changed out the BAG Filter yesterday. Decreasing flow Helped CV come down a little. Will see if it increases again, well may be slowing down. |
| 1300 | IR off site. All BACKUP compressors serviced and New motor installed on #1 lead Black UP compressor. |
| 1320 | - IX system pump CV coming down. Well production must be slowing. |
| 1425 | - Plant Operations Good. |

Influent Sources and Flow Rates: @0736
NBBW – 6.8 gpm
North End On Site- 12.8 gpm
North End Off-Site – 8.8 gpm
RWST – 1.0 gpm
NTES – 0.49 gpm(10R only)
MW38 T-540/541 – 0.30 gpm(Source well and 38 pumping wells mix)
MW38 N & S– 2.1 gpm
COND/NTES T-530- 0.19 gpm(6am-1pm daily)
MW113 Area – 2.8 gpm

Operator: **Mike Gelwick / Chris Carlson**

# LOWRY WTP OPERATIONS LOG

Date: SATURDAY, NOVEMBER 13th, 2021

| | |
|---|---|
| 0620 | - Plants operations Good. Notice the ADU carbon psi came up a bit to 6 psi, and pumps CV @ 84%. Will backwash ADU during blowdown. |
| 0700 | - Into blowdown ok. BACKWAS ADU with potable water while in recycle for blowdown. IX running well @ 2.7 gpm. |
| 0725 | - STOP BACKWASH and Get Valves back to Normal Positions for AFF for blowdown. |
| 0740 | - Flowgoing thru ADU again, bleed Residual Air from ADU. psi down to 1. Go over and will Bleed any Air out of GC Feed Line After Fill cycle completes. |
| 0810 | - Go to check other site systems. |
| 0910 | - Decant T-357 to TOP Valve. Wet well activated. Water is clear no color. |
| | - Clean PH-315 probe w/ Acid Solution. Check the Hose JO for oil or sheen; None observed. Spray down a wash. |
| | - Check TP-130 For oil globules: None observed. water is very clear w/ light yellow-green tint. |
| 1015 | - Plants operations Good |
| 2100 | - Remote log in. Allok. |
| Sunday, November 14, 2021 | |
| 0830 | - Remote log in. Allok. |
| 1810 | - Remote log in. Reduce IX system flow to 2.6 gpm. CV on pump @ 100%. All Else ok. |
| 2100 | - Remote log in. Allok. IX System Running well, CV down to 76% @ 2.6 gpm. |

Influent Sources and Flow Rates: @0620
NBBW – 6.8 gpm
N. END ON-SITE – 12.8 gpm
N. END OFF-SITE – 8.5 gpm
RWST – 1.0 gpm
NTES – 0.50 gpm
COND/NTES T-530 – 0.20 gpm
MW38 – 2.0 gpm
T-540/541 – 0.30 gpm
OTHER – ~~NA~~ MW113 Area Inf / IX System 2.7 gpm

OPERATOR(S) Mike Gehrke

# LOWRY WTP OPERATIONS LOG

Date: **Monday, November 15, 2021**

| Time: | |
|---|---|
| 0545 | Plant operations good. Work on annual device calibrations FT-3342 & FT-3307. |
| # | Observe the Flow rate being produced at MW113-EW-1 is dropping off (saturated zone getting less; less in that area) |
| | Blowdown operations good. |
| 0820 | - Decant T-351 to top rack. wet well activated. water BTS clear NO color |
| | - Clean pH-315 probe w/Acid solution. Check Hach Hmeter for oil or sheen: None observed. Spray down wash. |
| | - Check TM130 for oil globules: None observed. water BTS very clear w/light yellow-green hint. |
| 0821 | Place BTS in hold while checking Blend & overflow tank level sensor calibrations |
| 0910 | Take BTS out of hold. Shut down UV-OX. |
| 0915 | Place effluent in Timed suspension while checking FT-770 calibration. |
| ↓ | Simulated flow logged between 0934 & 0937 |
| 0943 | Take effluent out of suspension - plant discharging NORMally again. |
| ↓ | Work on LT-510 device calibration check - Note BTS went in to hold when T-510 level |
| ↓ | went low. Leave BTS in hold. LT-510 calibration check done at 1020 start on LT-520 |
| 1037 | Plant shutdown when Hi Hi alarm level of T-520 was tripped with calibration equipment. |
| ↓ | Leave plant off, move to LT-740 (effluent discharge tank) calibration check, then PIT-530, |
| ↓ | PIT-770 - All have ~~critical~~ critical plant shut down alarms attached to them |
| 1211 | Restart plant, UV-ox; take BTS out of hold. UV-OX warming up. |
| ↓ | Only one device remaining. FT-043 (missed it when doing the RWST calibs) |
| 1340 | Annual device calibration checks completed. |
| 1520 | - Plants operations Good |
| 1945 | Plant operations good. |

Influent Sources and Flow Rates: @ 0802
NBBW – 6.7 gpm
North End On Site- 12.8 gpm
North End Off-Site – 8.8 gpm
RWST – 1.0 gpm
NTES – 0.5 gpm(10R only)
MW38 T-540/541 – 0.3 gpm(Source well and 38 pumping wells mix)
MW38 N & S– 2.0 gpm
COND/NTES T-530- 0.2 gpm(6am-1pm daily)
MW113 Area – 2.5 gpm

Operator: **Mike Gelwick / Chris Carlson**

# LOWRY WTP OPERATIONS LOG

Date: **Tuesday, November 16, 2021**

| Time: | |
|---|---|
| 0450 | - Plants operations Good. On Site to collect TP-730 GAC Split samples w/LAB and TP-740 + 710 Lowlevel 1,4-Dioxane weekly samples |
| | - START Efficiency checks. working on WEEKLY BTS Sampling and Readings today |
| 1010 | - IX System performance HACH testing w/LAB Split Samples AFTER 879,192 gal treated; TP-183 = 110 ug/L; TP-174A = 210 ug/L; TP-173A = 3500 ug/L; TP-170 = 4600 ug/L |
| 1200 | - Decant T-351 to TOP valve wetwell activated water is clear NO color. |
| | - Clean pH-315 probe w/acid solution. Check the Hach 30 for oil or sheen: None observed. Spray down wash. |
| | - Check TP-130 for Oil globules: None observed. Water is very clear w/ light yellow-green tint. |
| | - Refill Polymer tank w/200 gal of potable water and 2 cups of NALCO polymer. |
| | - Refill BTS phosphorus tank w/5.5 # of TSP and 55 gal of potable water. |
| 1530 | - Reduce RWST Flow to 0.60 gpm. Tanks = 35 %. Plants operations Good. |

Influent Sources and Flow Rates: @ 0528
NBBW – 6.8 gpm
North End On Site- 12.9 gpm
North End Off-Site – 8.5 gpm
RWST – 1.0 gpm
NTES – 0.52 gpm(10R only)
MW38 T-540/541 – 0.30 gpm(Source well and 38 pumping wells mix)
MW38 N & S– 2.0 gpm
COND/NTES T-530- 0.0 gpm(6am-1pm daily)
MW113 Area – 2.6 gpm

Operator: **Mike Gelwick / Chris Carlson**

# LOWRY WTP OPERATIONS LOG

Date: **Wednesday, November 17, 2021**

| Time: | |
|---|---|
| 0600 | Plant operations good. Start on weekly GC maintenance and calibrations - Add two more carbon unit inline on the potable water source before the GC's and sink under the BTS building sink. Hope to get longer life out of the carbon used for GC blank water. |
| 0607 | Observe Ion Exchange P-114 CV running high again - reduce rate from 2.6 gpm to 2.5 gpm. |
| 0830 | - Decant P-351 TO TOP valve. Wetwell activated. Water is clear no color. |
| | - Clean AH-345 probe w/ acid solution. Check rate Hose 30 for oil or sheen: None observed. Sump down well. |
| | - Check TP-130 for oil globules: None observed. Water is very clear w/ light yellow green tint. |
| | - Working on Qtrly Building's methane safety checks today. Calibrate GEM 5000 rental SN G506880 to 2.5% CH4: Reading 2.5% CH4. |
| 1050 | Backup data to CD & Flashdrive - Daily OneDrive backup working well. |
| 1530 | - Plants operations Good. |

Influent Sources and Flow Rates: @ 0820
NBBW – 6.7 gpm
North End On Site- 12.9 gpm
North End Off-Site – 7.8 gpm
RWST – 0.6 gpm
NTES – 0.5 gpm(10R only)
MW38 T-540/541 – 0.3 gpm(Source well and 38 pumping wells mix)
MW38 N & S– 2.1 gpm
COND/NTES T-530- 0.2 gpm(6am-1pm daily)
MW113 Area – 2.5 gpm

Operator: **Mike Gelwick / Chris Carlson**

# LOWRY WTP OPERATIONS LOG

Date: **Thursday, November 18, 2021**

| Time: | |
|---|---|
| 0720 | - Plants operations Good. |
| 0830 | - Add 200 gal of peroxide to tote from new one. Add New TOTE of NaOH to BT3. Add one new tote to main supply for down down later. Work w/ Ice to do this. |
| 0930 | - Reduce flow on UV-Ox to 7.5 gpm from 8.0 gpm to help ~~stabilize the ozone system with ozone~~ T-510 Be more stable / full. |
| 1000 | - working on weekly Plants checks and calibrations today |
| 1020 | - Decant T-351 to top valve. wet well activated. water is clear no color. |
| | - Clean pH-315 probe w/ Acid solution. Check the Hach 50 for oil or sheen: none observed. Spray down with. |
| | - Check TP-130 for oily globules: none observed. water is very clear w/ light yellow green tint. |
| 1324 | - Suspend Plant Discharge to calibrate pH-740 to 4+10 pH stds. |
| 1333 | - Resume normal Discharge. Continue with other pH probes calibrations to 4+10 pH stds: 2 pH-113, 670, 310, 315 and 365. |
| 1415 | - Weekly Plants Systems checks and calibrations complete. |
| 1500 | - Plants operating as Good. |

Influent Sources and Flow Rates: @ 1005
NBBW – 6.7 gpm
North End On Site- 12.8 gpm
North End Off-Site – 4.3 gpm
RWST – 0.6 gpm
NTES – 0.53 gpm(10R only)
MW38 T-540/541 – 0.29 gpm(Source well and 38 pumping wells mix)
MW38 N & S– 2.1 gpm
COND/NTES T-530- 0.22 gpm(6am-1pm daily)
MW113 Area – 2.5 gpm

Operator: **Mike Gelwick / Chris Carlson**

# LOWRY WTP OPERATIONS LOG

Date: Friday, November 19, 2021

| | |
|---|---|
| 0000 | Receive P-114 strainer alarm - acknowledged alarm remotely - attempt to restart P-114 remotely |
| ↓ | - Flow to P-114 restricted, possibly P-113 has stalled. |
| 0100 | ON site - able to get P-113 running / IX system running, also turned up MW113-FLW-1 (P-113) |
| ↓ | pressure to ~70 psi. Also switch R3 feed from P-3323 to P-3324 (P-3323 starting to clogg up a little). |
| 0140 | IX system and plant operations good. Leave site. |
| 0730 | - Plant operations good |
| | - Decant T-351 from top valve, wet well activated, water is clear no color |
| | - Clean ph-315 probe with acid solution. check HMR30 for oil or sheens: none observed. Sprayed down weir |
| | - check Jp-130 for oil globules: none observed: water is clear with yellow/green tint |
| 1500 | - Plant operations good |
| | - Filled phosphorous tank w/ 50 gallons / 5LBS TSP |

Influent Sources and Flow Rates: 0137
NBBW – 6.8 gpm
N. END ON-SITE – 12.9 gpm
N. END OFF-SITE – 8.3 gpm
RWST – 0.6 gpm
NTES – 0.5 gpm
COND/NTES T-530 – 0.0 gpm
MW38 – 2.1 gpm
T-540/541 – 0.3 gpm
OTHER – ~~NA~~ MW113 area 2.9 gpm

OPERATOR(S) Chris Carlson / Tom Gilbert

## LOWRY WTP OPERATIONS LOG

Date: Saturday, November 20, 2021

| | |
|---|---|
| 0625 | ON site for weekend systems checks. Plant operations good. |
| 0650 | Decant T-351 top valve, wet well did not activate. Water is clear, no color. Clean the HMR-30 weir and pH probe - no oil or sheen observed in the HMR-30. Check TO-130 for oil globules - none observed. Water is very clear light green / yellow. |
| 0740 | Blowdown operations good. |
| 0840 | Plant operations good. |
| 1630 | Check plant operations remotely - All okay. |
| 11/21/21 0600 | Check plant remotely - All okay. |
| 1400 | Check plant remotely - All okay |

Influent Sources and Flow Rates: 0645
NBBW – 6.7 gpm
N. END ON-SITE – 12.6 gpm
N. END OFF-SITE – 6.2 gpm
RWST – 0.6 gpm
NTES – 0.5 gpm
COND/NTES T-530 – 0.2 gpm (6 hrs · IRM)
MW38 – 2.1 gpm
T-540/541 – 0.3 gpm
OTHER ~~NA~~ MW33 Area 2.3 gpm

OPERATOR(S) Chris Carlson

# LOWRY WTP OPERATIONS LOG

Date: **Monday, November 22, 2021**

| Time: | |
|---|---|
| 0700 | -Plants operations Good. Automatic Shutdown operations Normal |
| 0704 | -Receive P-114 Strainer Alarm. Increased slightly this morning to 2.6 gpm. Too much. Reduce to 2.5 gpm and Regenerate with Match and make sure this is not too much flow. Ran @ 2.4 gpm this weekend ok. |
| 0940 | -Vacuum T-351 to top valve. Water well activated, Water is clear No color. |
| | -Clean pH-315 probe w/Acid solution. Check the HMR 30 for oil or sheen: None observed. Spray down water. |
| | - Check TA-130 for oil globules: None observed. Water is very clear w/slight yellow green tint |
| | -Increase IX Flow to 2.4 gpm Pump curve up to 83%. |
| 1010 | -Refill BTS phosphorus tank w/5 # of TSP + 50 gal of potable water. |
| 1030 | -Working on Change out of Acid Fume Hood vent motor/belt. |
| 1510 | -Plants operations Good. |

Influent Sources and Flow Rates: @ 0725
NBBW – 6.7 gpm
North End On Site- 12.8 gpm
North End Off-Site – 8.7 gpm
RWST – 0.6 gpm
NTES – 0.50 gpm(10R only)
MW38 T-540/541 – 0.30 gpm(Source well and 38 pumping wells mix)
MW38 N & S– 1.9 gpm
COND/NTES T-530- 0.20 gpm(6am-1pm daily)
MW113 Area – 2.5 gpm

Operator: **Mike Gelwick / Chris Carlson**

# LOWRY WTP OPERATIONS LOG

Date: **Tuesday, November 23, 2021**

| Time: | |
|---|---|
| 0145 | - Receive P-3321 strainer Alarm. Not @ shutoff point, just warning. Acknowledge from Horn. |
| 0230 | - Acknowledge P-3321 strainer Alarm again and come to site to Flush BTS Reactors Feed Piping. Already using Back up Pump for 3323. |
| 0300 | - on site. Plants operations Good. |
| 0308 | - BTS in to maint Hold to Flush Reactor Feed Piping. |
| 0345 | - BTS out of Hold. All ok. |
| 0415 | - Work on BTS weekly sampling and START Efficiency checks. |
| 0505 | - Collect TP-730 weekly GC/Lab split samples. Also collect TP-710+740 weekly Low Level 1, 4-Dioxane samples. |
| 0549 | - IX Performance HACH testing with Lab split samples After 902, 713 gal treated: TP-183 @ 190 ug/L; TP-174A @ 290 ug/L; |
| | TP-173A @ 4000 ug/L; TP-170 @ 5000 ug/L. |
| 0940 | - Work on on BTS Field Readings |
| 1210 | - Decant T-351 to TOP valve, wetwell activated. Water is clear no color. |
| | - Clean pH-315 probe w/ Acid solution. Check the Hood 30 for oil or sheen; None observed. Spray down water. |
| | - check TP-130 for oily globules; None observed water is very clear w/ light yellow green tint. |
| 1320 | Plant operations good. |

Influent Sources and Flow Rates: @ 0445
NBBW – 6.8 gpm
North End On Site- 12.8 gpm
North End Off-Site – 9.1 gpm
RWST – 0.60 gpm
NTES – 0.49 gpm(10R only)
MW38 T-540/541 – 0.31 gpm(Source well and 38 pumping wells mix)
MW38 N & S– 2.0 gpm
COND/NTES T-530- 0.0 gpm(6am-1pm daily)
MW113 Area – 2.4 gpm

Operator: **Mike Gelwick / Chris Carlson**

# LOWRY WTP OPERATIONS LOG

Date: **Wednesday, November 24, 2021**

| Time: | |
|---|---|
| 0525 | Plant operations good. Start on weekly GC maintenance and calibrations. |
| 0740 | Blowdown operations good. Mike working on weekly/monthly plants systems checks and calibrations today. Calibrate site multimeter to 2.5% $CH_4$/50% LEL to use during LEL-740 calibrations to ensure 0% LEL on T-740. |
| 0845 | - Decant T-351 to TOP valve. Wetwell activated. Water ES clean No color. |
| | - Clean pH-315 probe w/Acid solution. Check TPE Hawk 30 for oil or sheen: None observed. Spray down wash. |
| | - Check TP-130 for oil globules: None observed. Water ES very clear w/light yellow-green tint. |
| | - Prepare new 4 + 10 pH STDs for calibrations today |
| 1020 | Backup plant data to flash drive & DVD disk. Daily OneDrive backup working well. |
| 1045 | - Work on monthly BTS pH probes calibrations to NEW 4+10 pH STDs |
| 1150 | - START WTP pH probes calibrations to New 4+10 pH STDs ⇨ pH-113, 670, 310, 315 + 365. |
| 1225 | - Suspend plant discharge to calibrate pH-740 to New 4 + 10 pH STDs and LEL-740 to 50% LEL. |
| | - Having trouble getting the New cal gas to calibrate on LEL-740. New Gas + Hydrogen + one ES 2.45% $CH_4$ and a Nitrogen balance which will not work for calibration. Use another can of cal gas which ES 2.5% $CH_4$ + Air balance. Works better now. |
| 1236 | - Plant Shut down for High LEL @ 8% LEL during calibration. High LEL shut down operations Good. |
| 1315 | - Restart Plant. |
| 1400 | - Plants operations Good. |

Influent Sources and Flow Rates: @ 0650
NBBW – 6.7 gpm
North End On Site- 12.8 gpm
North End Off-Site – 8.3 gpm
RWST – 0.6 gpm
NTES – 0.52 gpm(10R only)
MW38 T-540/541 – 0.31 gpm(Source well and 38 pumping wells mix)
MW38 N & S– 1.9 gpm
COND/NTES T-530- 0.20 gpm(6am-1pm daily)
MW113 Area – 2.3 gpm

Operator: **Mike Gelwick / Chris Carlson**

# LOWRY WTP OPERATIONS LOG

Date: Friday, November 26, 2021

| | |
|---|---|
| 0800 | - Plant operations good. |
| | - Decant T-351 top valve. Wet well activated. Water is very clear, no color |
| | - clean pH-315 probe w/ Acid solution. Check AMR30 for oil or sheen: none observed - Sprayed down weir |
| | - Check Tp-130 for oil globules: none observed. Water is clear w/ yellow-green tint |
| | - Filled phosphorus tank w/ 60 gallons $H_2O$ + 6LBS TSP |
| 1100 | - Plant operations good |

Influent Sources and Flow Rates: @0815
NBBW – 6.7 gpm
N. END ON-SITE – 12.7 gpm
N. END OFF-SITE – 8.7 gpm
RWST – 0.6 gpm
NTES – 0.51 gpm
COND/NTES T-530 –0.20gpm (6AM–1PM daily)
MW38 – 1.9 gpm
T-540/541 – 0.29 gpm
MW113 Area – 2.3 gpm

OPERATOR(S) Tom Gilbert

# LOWRY WTP OPERATIONS LOG

Date: Saturday, November 27, 2021

| | |
|---|---|
| 0900 | Plant operations good. |
| | - cleaned HMR-30 probe w/ Acid Solution |
| | - checked chambers A and B for oil or sheen: none observed - sprayed down weir |
| | - check TP-130 for oil globules and sheens: none observed water is clear w/ green-yellow tint |
| | - Sprayed down floc mixer belt |
| 1130 | - Plant operations good |
| | - Decant T-351 top valve. wet-well activated. Water is clear, no color |
| | |
| | Sunday, November 28, 2021 |
| 1300 | Remotly logged in - plant operations good. |

Influent Sources and Flow Rates: @ 0915
NBBW – 6.7 gpm
N. END ON-SITE – 12.7 gpm
N. END OFF-SITE – 8.4 gpm
RWST – 0.6 gpm
NTES – 0.52
COND/NTES T-530 – 0.21 gpm (6AM–1PM daily)
MW38 – 1.9 gpm
T-540/541 – 0.33 gpm
MW113 Area – 2.3 gpm

OPERATOR(S) Tom Gilbert

# LOWRY WTP OPERATIONS LOG

Date: **Monday, November 29, 2021**

| Time: | |
|---|---|
| 0530 | Plant operations good. Observe MW38N extraction reached its low level stop yesterday at 1540 |
| ↓ | and is recharging but slower than in the past. |
| 0610 | Stop MW38S extraction and prepare for MW38 source well batch extraction (T-540/541 @ 25%) |
| 0617 | Increase RWST influent from 0.6 gpm to 2.6 gpm. |
| 0634 | Switch MW38 from direct HMR-30 influent to T-540/541 then startup MW38 source well. |
| 0800 | Blowdown operations good. |
| 0810 | Reboot HMIFTVIEW1 to reset temporary memory file space, online @ 0815 - |
| 0915 | - Decant T-351 to TD1 valve. wetwell activated. water is clear No color |
| | - Clean pH-315 probe w/Acid solution. Check the HMR30 for oil or sheen: None observed. Spray down wash. |
| | - check TP-130 for oil globules: None observed. water is very clear w/ light yellow green tint. |
| | Lube up solinoids of Flow control valves FV-708 & FV-746 of the UV-OX, fix loose air bleed fitting. |
| 0930 | Restart UV-OX - 0940 Warm up completed - FV-708 & FV-746 working well. |
| | - Mike working on swap out of RWST's MISC. water's Flow Tube. |
| 1345 | - Test Flow tube by running ~100 gal of potable water thru Eff. I + E3 Registering Flow ok and registered 66 gal. Resolved by Piping and Hoses accounting for Rest. All seems ok. |
| 1520 | Plant operations good. |
| 0~~1520 Plant~~ | |

Influent Sources and Flow Rates: 0545
NBBW – 6.7GPM
N. END ON-SITE – 12.7GPM
N. END OFF-SITE – 8.7GPM
RWST – 0.6GPM
NTES – 0.51GPM
COND/NTES T-530 – 0.2GPM (6AM-1PM)
MW38 – 1.1GPM
T-540/541 – 0.3GPM
MW113 IX SYSTEM – 2.2GPM
OTHER – NA

OPERATOR(S) Chris Carlson / Mike Gelwick

# LOWRY WTP OPERATIONS LOG

Date: **Tuesday, November 30, 2021**

| Time: | |
|---|---|
| 0500 | - Plants operations Good. Working on STARTing Efficiency checks and collecting TP-730 GC/Lab Split samples. Also collecting TP-710 and TP-740 Low Level 1,4-Dioxane SAMPLES. |
| | Refill phosphorus tank with 60gallons potable water + 6lbs TSP |
| 0700 | Backwash PDU and clean PDU air releases. |
| 0845 | - Decant T-351 to top valve. wetwell activated. water is Clear No color. |
| | - Clean pH-315 probe w/Acid solution. Check the Hach-30 for oil or sheen: None observed. Spray down weirs |
| | - Check TP-130 for oil globules: None observed. water is very clear w/light yellow/green hue |
| | - working on weekly BTS sampling and Field readings today. |
| 0955 | - IX System Performance HACH testing w/Lab Split Sampling AFTER 926,078 gal treated: TP-183 = 190 ug/L; TP-174A = 270 ug/L; TP-173A = 4300 ug/L; TP-170 = 5200 ug/L |
| 1030 | GC results of TP-3340 indicate 1,2-DCA is increasing in the BTS effluent (Fresh MW38 Source well water is impacting BTS). Reduce T-540/541 influent from 0.3gpm to 0.2 gpm until BTS can adjust to the increased 1,2-DCA load. Note: T-540/541 now at 80%, Mike to stop Source well batch extraction after packing up samples. |
| 1125 | -STOP MW38 source well pumping. |
| 1238 | Restart MW38N's extraction to T-540/541 to displace the MW38 source well water in the pipeline to T-540/541. |
| 1500 | - Plants operations Good. Will remote in and switch MW38N+S wells to RWSTS Later tonight. |
| 1845 | 740 gallons from MW38N's have been pumped to displace source well water in the conveyance pipeline to T-540/541. MW38 switched from T-540/541 to RWSTS - Plant operation good. |

Influent Sources and Flow Rates: @ 0535
NBBW – 6.6 gpm
North End On Site- 12.7 gpm
North End Off-Site – 8.4 gpm
RWST – 2.6 gpm
NTES – 0.50 gpm(10R only)
MW38 T-540/541 – 0.30 gpm(Source well and 38 pumping wells mix)
MW38 ~~N&S~~ – 5.0 gpm source well to T-540
COND/NTES T-530- 0.0 gpm(6am-1pm daily)
MW113 Area – 2.2 gpm

Operator: **Mike Gelwick / Chris Carlson**

# LOWRY WTP OPERATIONS LOG

Date: **Wednesday, December 01, 2021**

| Time: | |
|---|---|
| 0510 | Plant operations good. Start on weekly GC maintenance and calibrations |
| 0745 | Blowdown operations good. |
| 0851 | Reduce RWST inFluent from 2.6 gpm to 0.6 gpm and switch MW38 N&S extraction back to normal direct HMR-30 inFluent. Increase T-540/541 from 0.2 gpm to 0.3 gpm (GC results from TP-3350 have dropped overnight for 1,2-DCA). |
| 1145 | - Decant T-351 to TOP valve. wet well activated. water is clear no color |
| | - Clean pH-315 probe w/ acid solution, check the HMR-30 for oil or sheen; None observed. Spray down water. |
| | - Check TP-130 for oil globules; None observed. water is very clear w/ light yellow-green tint. |
| 1315 | Backup plant data to Flash drive and CD. Daily OneDrive backup working well. |
| 1523 | - Plant is operations Good. |

Influent Sources and Flow Rates: @ 0850
NBBW – 6.6 gpm
North End On Site- 12.7 gpm
North End Off-Site – 8.7 gpm
RWST – 2.6 gpm
NTES – 0.5 gpm(10R only)
MW38 T-540/541 – 0.2 gpm(Source well and 38 pumping wells mix)
MW38 N & S– 1.9 gpm (to RWST)
COND/NTES T-530- 0.2 gpm(6am-1pm daily)
MW113 Area – 2.2 gpm

Operator: **Mike Gelwick / Chris Carlson**

# LOWRY WTP OPERATIONS LOG

Date: **Thursday, December 02, 2021**

| Time: | |
|---|---|
| 0525 | Plant operations good. |
| 0750 | Blowdown operations good. Mike and Tom (training) working on weekly systems checks and calibrations today. |
| ~~0815~~ | ~~- Mike + Tom (training) on weekly plants systems checks and~~ |
| 0845 | Hayden with Piper Electric on site to install line reactor in front of primary air compressors VFD to protect it from spikes in power - 1240 - Line reactor installed |
| 0850 | - Decant T-351 to TOP valve. wet well activated. Water is clear no color |
| | - Clean pH-315 probe w/ Acid solution. Check the Hose 30 for oil or sheen; None observed. 3 Array is clean water |
| | - Check TP-130 for oily globules; None observed water is very clean w/ light yellow green tones. |
| 1410 | - Suspend Plant Discharge to calibrate pH-740 probe to 4 + 10 pH STDs. |
| 1420 | - Resume Normal Discharge. Continue with other pH probes calibrations to 4 + 10 pH STDs @ pH-113, 670, 310, 315 + 365 |
| 1515 | - Weekly plants systems checks and calibrations complete. |
| 1530 | - Plants operations Good. |
| 1715 | Check plant remotely - All Okay |

Influent Sources and Flow Rates: @ 0750
NBBW – 6.7 gpm
North End On Site- 12.7 gpm
North End Off-Site – 8.7 gpm
RWST – 0.6 gpm
NTES – 0.51 gpm(10R only)
MW38 T-540/541 – 0.3 gpm(Source well and 38 pumping wells mix)
MW38 N & S– 2.0 gpm
COND/NTES T-530- 0.2 gpm(6am-1pm daily)
MW113 Area – 2.2 gpm

Operator: **Mike Gelwick / Chris Carlson**

# LOWRY WTP OPERATIONS LOG

Date: **Friday, December 03, 2021**

| Time: | |
|---|---|
| 0730 | - Plants operations Good. Coming out of blowdown ok |
| 0845 | - START setting up to Backwash lead GAC-720 with process water. |
| | - Decant T-351 to TOP valve. Wet well activated. Water is clear No odor |
| | - Clean pH-315 probe w/Acid solution. Check the HMR30 for oil or sheen: None observed. Spray Down W.C.V. |
| | - Check TP130 for oil globules: None observed. Water is very clear w/ light yellow-green tint. |
| | - Refill polymer tank w/ 2 cups of NALCO polymer and 200 gal of potable water. |
| 1050 | - Refill BTS phosphate TANK w/ 5# of TSP and 50 gal of potable water. |
| 1110 | - Work on setting up Autosampler and calibrating delivery volume for Monthly WTP 5 Sampling Event. |
| | - Triple Rinse dedicated 10 lb composite container. will add Nitric Acid Preservative just prior to START UP on Monday. |
| 1130 | - Work on BACKWASH of lead GAC-720. |
| 1215 | - GAC-720 BACKWASH complete. Pressure on vessel went from 20. to 7 PSI. @ 37 gpm |
| 1225 | - Work on Cleaning 2 new Bitumonas carbon vessels Hydrated with potable water. |
| 1430 | - Plants operations Good. |

Influent Sources and Flow Rates: @ 0800
NBBW – 6.6 gpm
North End On Site- 12.6 gpm
North End Off-Site – 8.4 gpm
RWST – 0.60 gpm
NTES – 0.52 gpm(10R only)
MW38 T-540/541 – 0.29 gpm(Source well and 38 pumping wells mix)
MW38 N & S– 2.0 gpm
COND/NTES T-530- 0.18 gpm(6am-1pm daily)
MW113 Area – 2.2 gpm

Operator: **Mike Gelwick**

# LOWRY WTP OPERATIONS LOG

Date: Saturday, December 4, 2021

| | |
|---|---|
| 0800 | Plant's operations good. |
| 0840 | Decant T-351 to top valve. Wet well activated. Water is clear no color. Clean pH-315 probe w/ acid solution. Check HMR-30 for oil or sheen: None observed. Spray down weir. Check TP-130 for oil globules - none observed. Water clear with light yellow/green tint. |
| 0900 | Both GCs operational within limits. All blowers okay. Phosphorus tank: 90 gal |
| 1015 | Plant operations good. |
| @ 0550 | Check plant remotely - All okay. |
| 1700 | Check plant remotely - All okay. |
| 12/5/21 0630 | Check plant remotely - All okay. |
| 1704 | Receive NTES Flow unstable alarm - Remotely see Flow rate is below 0.3gpm and trench level raising slightly P-002W pump stalled. Switch NTES from direct BTS influent to T-530 and start up T-530 at 0.5gpm to BTS. Will run like this overnight - check plant operations. Observe GC2 had a file error WARNING pop up on screen - restart program and ~~for~~ T-730 sampling on it, note last sample results look normal. File error occured after that sample was completed. |
| 2015 | Check plant remotely - NTES P-002W has resumed pumping but will leave in divert to T-530 for the night in case it stalls again. Plant operations good. |

Influent Sources and Flow Rates: @ 0825
NBBW – 6.6 gpm
N. END ON-SITE – 12.7 gpm
N. END OFF-SITE – 8.5 gpm
RWST – 0.6 gpm
NTES – 0.52 gpm
COND/NTES T-530 – 0.21 gpm (6AM–1PM daily)
MW38 – 2.0 gpm
T-540/541 – 0.3 gpm
MW113 Area – 2.1 gpm

OPERATOR(S) Manuela Seewald / Chris Carlson

# LOWRY WTP OPERATIONS LOG

Date: **Monday, December 06, 2021**

| Time: | |
|---|---|
| 0600 | Plant operations good |
| 0610 | Observe NTES ran all night to T-530 without stalling again. Switch it back to direct BTS influent and lower T-530 to 0.2 gpm with timer activated for 6AM-1PM. |
| ↓ | Decant T-351 top valve, wet well activated. Water is clear, no color. |
| 0620 | Start Filter press on T-351 (in stage 1). |
| 0740 | Blowdown operations good. |
| 0800 | Mike has added preservative to composite container for monthly MP-001 Flow paced sampling and started auto sampler. Effluent totalizer reading 247522652 gallons, pH-740 reading 6.91@15.9°C & FT-770 Flow rate reading 32.5 gpm. |
| 0940 | -Clean pH-315 probe w/Acid solution. Check the HMR30 for odor/screen: None observed. Spray down wash. |
| | -Check PM130 for oil globules: None observed. water is slightly cloudy w/yellow-orange tint. |
| 1015 | -working on Monthly Early warning sampling for Total molybdenum and Low level 1,4-Dioxane. |
| 1100 | - IX System performance HACH testing with weekly Lab split sampling after 944,704 gal treated: TP-185 → 180 ug/L; TP-174A → 250 ug/L; TP-173A → 4300 ug/L; TP-170 → 5500 ug/L. All Lab samples placed in fridge via shipment tomorrow to Lab. |
| 1150 | -START FLUSH of MP-001 and check for Residual Chlorine; None Detected. Starting MP-001 monthly time paced sampling. |
| 1200 | -collect 1st set of MP-001 time paced grab samples for Low Level 1,4-Dioxane. Place samples into fridge. Water is very clear NO color |
| 1300 | -Filter press is full. |
| 1515 | -Refill BTS phosphorus tank w/5# of TSP and 50 gal of potable water. |
| 1550 | -START Flush of MP-001 sample port and check for Residual chlorine: None detected |
| 1600 | -collect 2nd set of time paced grab samples for low level 1,4-Dioxane. Water is very clear no color. |
| | -Place samples in fridge with others. Auto Sampler on track/Good |
| | -Plants operations Good. |
| 1950 | Start MP-001 port flush; check for residual chlorine, None detected. |
| 2000 | Collect 3rd set of time paced grab samples for low level 1,4 Dioxane, water is clear NO color. Place sample in fridge with others. |

Influent Sources and Flow Rates: @0605
NBBW – 6.6 gpm
North End On Site- 12.6 gpm
North End Off-Site – 8.7 gpm
RWST – 0.6 gpm
NTES – 0.5 gpm(10R only)
MW38 T-540/541 – 0.3 gpm(Source well and 38 pumping wells mix)
MW38 N & S– 2.0 gpm
COND/NTES T-530- 0.2 gpm(6am-1pm daily)
MW113 Area – 2.1 gpm

Operator: **Mike Gelwick / Chris Carlson**

## LOWRY WTP OPERATIONS LOG

Date: Monday, December 06, 2021 (Continued)

| | |
|---|---|
| 2345 | Start MP-001 port flush and check for residual chlorine, NONE detected. |
| 0000 | Collect 4th set of time paced grab samples for low level 1,4-Dioxane, water is very clear no color. Place samples in fridge with others. |

Influent Sources and Flow Rates: @
NBBW – gpm
N. END ON-SITE – gpm
N. END OFF-SITE – gpm
RWST – gpm
NTES –
COND/NTES T-530 – gpm (6AM–1PM daily)
MW38 – gpm
T-540/541 – gpm
MW113 Area – gpm

OPERATOR(S) Chris Carlson

# LOWRY WTP OPERATIONS LOG

Date: **Tuesday, December 7, 2021**

| Time: | |
|---|---|
| 0315 | - Plants operations Good. Prepare GC's for Efficiency checks. |
| 0350 | - START Flush of MP-001 sample port and check for Residual chlorine; None detected |
| 0400 | - collect 5th set of MP-001 time paced grabs samples for Low-Level 1,4-Dioxane. Water is very clear NO color. Place samples in Fridge with others |
| 0415 | - working on BTS weekly sampling along with starting Efficiency checks and collecting TA-730 GC/Lab Spl47 samples and TA-740 + 710 Low level 1,4-Dioxane weekly samples. |
| 0515 | - working on prep for BTS Field Readings. |
| 0750 | - START Flush of MP-001 sample port and check for Residual chlorine: None detected. |
| 0800 | - collect 6th and final set of MP-001 Time paced grab samples for Low-Level 1,4-Dioxane. Water is very clear NO color. Place samples in fridge with others. STOP Auto sampler. TOTAL Effluent = 247,570,300 gal. A total of 47,648 gal treated during sample period. Process Quenty stir composite with timed stir since sample composite Check pH of sample composite. pH = 1.62 SU. Fill sample bottle. Pack all samples on Ecocar courier Pickup for Lab. |
| | - TOM working on filter Press cleanout |
| 1100 | - Decant T-351 to TOA Vault. wetwell is not activated water is clear NO color |
| | - Clean pH-315 probe w/ Acid solution. Check TP-HMI-30 for oil or sheen; NONE observed. Spray downwell. |
| | - Check TP-130 for oil globules; NONE observed. water is clear w/ yellow-green tint. |
| | - filter Press ready to fill. |
| 1125 | - work on BTS Field Readings |
| 1415 | Plant operations good. |

Influent Sources and Flow Rates: @ 0340
NBBW – 6.7 gpm
North End On Site- 12.6 gpm
North End Off-Site – 9.0 gpm
RWST – 0.60 gpm
NTES – 0.52 gpm(10R only)
MW38 T-540/541 – 0.30 gpm(Source well and 38 pumping wells mix)
MW38 N & S– 2.0 gpm
COND/NTES T-530- 0.0 gpm(6am-1pm daily)
MW113 Area – 2.1 gpm

OPERATOR **Mike Gelwick / Chris Carlson**

# LOWRY WTP OPERATIONS LOG

Date: **Wednesday, December 08, 2021**

| Time: | |
|---|---|
| 0515 | Plant operations good. Start on weekly GC maintenance and calibrations |
| 0600 | Start Filter-press on T-351 (Stage 1) |
| 0740 | Blowdown operations good. |
| 0815 | - Clean pH-315 probe w/ Acid solution. Check the Hose bib for oil or sheen: None observed. Spray down area. |
| | - Check FP-130 for oil globules: None observed - water is clear w/ yellow-green hint. |
| 0822 | - Divert NTES to T-530 and increase T-530/P-005 to 0.50 gpm to work on issue out of MP2-10R pump. |
| 0915 | Backup plant data to Flash drive & CD. Daily OneDrive backup working well. |
| 1100 | - Switch NTES back to Normal mode and decrease T-530/P-005 back to 0.20 gpm. |
| 1150 | - Work w/ Chris to add a full tote of NaOH to chemical day for drawdown later and Drain/Empty HCl tote into ON line tote. |
| 1700 | Shutdown filter press (in stage 4). Plant operations good. |

Influent Sources and Flow Rates: 0645
NBBW – 6.6GPM
N. END ON-SITE – 12.5GPM
N. END OFF-SITE – 8.7GPM
RWST – 0.6GPM
NTES – 0.51GPM
COND/NTES T-530 – 0.2GPM (6AM-1PM)
MW38 – 2.0GPM
T-540/541 – 0.3GPM
MW113 IX SYSTEM – 2.1GPM
OTHER – NA

OPERATOR(S) Chris Carlson / Mike Cockrick

# LOWRY WTP OPERATIONS LOG

Date: **Thursday, December 09, 2021**

| Time: | |
|---|---|
| 0740 | - Plants operations Good. Carrying out of Automatic blowdown OK. Restart Filter Press. (Finish Stage 4) |
| | - TDM training on weekly Plants checks again this week. STARTING weekly Plants Systems checks and calibrations. |
| 1017 | - Filter Press full. |
| 1035 | - Decant T-351 from bottom valve. Wet well backwash water is clear no color. |
| 1027 | - Clean ph-315 probe w/ Acid solution. Check HMR 30 for oil or sheens: none observed. Sprayed down weir |
| 1150 | - Check TP-130 for oil globules: none observed water is clear w/ yellow-green tint. |
| 1458 | - Discharge suspended to calibrate pH-740 to 10 and 4 PH STDS. |
| 1512 | - Resume normal discharge |
| | - Finish WTP probe calibrations tomorrow morning |
| 1522 | - Switch STS P-3324 to P-3321 position. CVON P-3321 Increasing with flow plugging |
| 1600 | - Plants operations Good. |

Influent Sources and Flow Rates: @ 0745
NBBW – 6.6 gpm
North End On Site- 12.5 gpm
North End Off-Site – 8.3 gpm
RWST – 0.6 gpm
NTES – 0.54 gpm(10R only)
MW38 T-540/541 – 0.30 gpm(Source well and 38 pumping wells mix)
MW38 N & S– 1.9 gpm
COND/NTES T-530- 0.18 gpm(6am-1pm daily)
MW113 Area – 2.1 gpm

Operator: **Mike Gelwick / Tom Gilbert**

# LOWRY WTP OPERATIONS LOG

Date: **Friday, December 10, 2021**

| Time: | |
|---|---|
| 0745 | - Plants operations Good. Automatic blowdown operations Good. |
| 0840 | - Work on Finishing up on WTP pH probes calibrations to 4+10pH STD's. |
| 0905 | - Clean pH-315 probe w/ Acid solution. Check the HMI 30 for oil or sheen: ~~Yes~~ No observed. Spray down well |
| 0925 | - pH probes weekly calibration complete ⇒ pH-113, 365, 310, 315 & 370. |
| 0930 | - check TP-130 for oil globules: None observed. water is clear w/ yellow-green tint. |
| 0935 | - Decant T-351 from bottom valve. wet well activated. water is clear No Odor. |
| 1115 | - Refill BTS phosphorus tank w/ 5 # of TSP and 50 gal of potable water |
| 1130 | - Place BTS Into Maint. Hold to flush Reactors feed Piping and pumps. |
| 1205 | - BTS out of Hold. |
| 1405 | - Plants operations Good. |

Influent Sources and Flow Rates: @0825
NBBW – 6.6 gpm
North End On Site- 12.5 gpm
North End Off-Site – 8.6 gpm
RWST – 0.6 gpm
NTES – 0.52 gpm(10R only)
MW38 T-540/541 – 0.31 gpm(Source well and 38 pumping wells mix)
MW38 N & S– 1.9 gpm
COND/NTES T-530- 0.20 gpm(6am-1pm daily)
MW113 Area – 2.1 gpm

Operator: **Mike Gelwick**

# LOWRY WTP OPERATIONS LOG

Date: SATURDAY, December 11, 2021

| | |
|---|---|
| 0700 | - Plants operations Good. Automatic blowdown operations Good. Go to check other site systems |
| 0825 | - Decant T-351 From bottom valve. wet well activated. water IS clear NO color |
| | - Clean pH-315 probe w/ Acid solution. Check the Hach 30 for oil or sheen: NONE observed. Spray Down well |
| | - Check TP 430 for oil globules: NONE observed. water IS clear w/ yellow-green tint. |
| | - Notice p-3321 on BTS IS @ 0.0 gpm. Check on pump, NOT Running. Message on totalizer head at says "Electronics Failure". Switch to p-3324 Backup. Did NOT receive any Alarm for this, looks like It stopped Around 1510 on 12-10-21 yesterday. Trouble shooting: Re booted the totalizer head at By taking Fuse out and Re inserting. Electronics Failure message off Now. Restart pump. Seems to be working ok now. will watch it closely and switch to p-3324 BACKUP IF It occurs again. |
| 1000 | - plants operations Good. |
| 1123 | - Receive GC 2 BTS VOC Alarm. BTS In to Hold. 1, 4-Dioxane level came up to 290 ppb. Reset Alarm Remotely and put GC 2 on Standby for An Hr and STOP T-530/p-005 and T-540'/p-006 to Allow BTS time to catch up. May be High due to p-3321 issue. |
| 1400 | - ~~Re~~ Remote log In and START a New TP-3350 Sample on GC 2. T-540'/p-006 + T-530/p-005 started. |
| 1600 | - Remote log In. GC 2 1, 4-Dioxane results for TP-3350 are coming down. Now @ 160 ppb. will leave T-540'/p-006 + T-530/p-005 off for the Night |
| 1930 | - Remote log In. All ok. NO New GC 2 / TP-3350 Sample yet |

Influent Sources and Flow Rates: @ 08/5
NBBW – 6.6 gpm
N. END ON-SITE – 12.5 gpm
N. END OFF-SITE – 8.7 gpm
RWST – 0.6 gpm
NTES – 0.52 gpm
COND/NTES T-530 – 0.19 gpm (6AM–1PM daily)
MW38 – 2.0 gpm
T-540/541 – 0.31 gpm
MW113 Area – 2.1 gpm

OPERATOR(S) Mike Gelwicks

# LOWRY WTP OPERATIONS LOG

Date: Sunday, December 12, 2021

0708 - Receive POTW pressure drop alarm. Log in remotely and reset/restart. Seems after the T-740 tank is pumped down to 20% it stops the discharge pump abruptly and causes a pipeline pressure issue. GC2 in delay, check again in a bit. Plant running again ok.

0845 - Log in remotely. GC2/TP-3350 1,4-Dioxane results are down to 2ppb. START T-540'/P-006 @ 0.20gpm. Will start a new GC2 TP-3350 sample later.

0911 - Receive POTW pressure drop alarm again. Log in remotely and reset/check out. Seems to be the same issue. T-740 tank pumped down to 20% and discharge pump stopped abruptly causing the pressure issue in the pipeline. Pump and plant running ok again.

1130 - Remote log in and START a new GC2/TP-3350 sample.

1315 - Log in remotely. GC2/TP-3350 1,4-Dioxane results are @ 3ppb. Increase T-540'/P-006 to 0.30gpm. Leaving T-530/P-005 off for awhile. START a new GC2/TP-3350 sample later.

1745 - START a new GC2/TP-3350 sample remotely.

1930 - Log in remotely. GC2/TP-3350 results for 1,4-dioxane @ 18ppb. ok. Plants operations ok.

2059 Receive UV-OX GC Fault - high VOC alarm. Check remotely and can see GC1 has logged a ~~fault~~ false high value to the normal looking 1,1-DCE peak. Take screen snapshots to support the ~~fault~~ false value determination then start next ~~TP-17~~ TP-730 sample early on GC1 after taking UV-OX out of recycle mode.

2130 Plant operations good.

Influent Sources and Flow Rates: @
NBBW – gpm
N. END ON-SITE – gpm
N. END OFF-SITE – gpm
RWST – gpm
NTES –
COND/NTES T-530 – gpm (6AM–1PM daily)
MW38 – gpm
T-540/541 – gpm
MW113 Area – gpm

OPERATOR(S) Mike Gedwicke / Chris Carlson

# LOWRY WTP OPERATIONS LOG

Date: **Monday, December 13, 2021**

| Time: | |
|---|---|
| 0600 | Plant operations good. |
| 0745 | Blowdown operations good. |
| 0906 | Reboot HMIFTVIEW1 to update virus program software, online 0911. |
| 1110 | - Decant T-351 to bottom valve. Wetwell activated. Water DS clear NO color. TOM working on Filterpress cleanout. |
| | - Clean pH-315 probe w/ Acid solution. Check TTH HMI30 for oil or sheen; None observed. Spray down weir |
| | - Check TTH130 for oil globules; None observed. Water DS clear w/ yellow green tint. |
| 1300 | - Filterpress Ready to Fill. |
| 1505 | - Plants operations Good. Checked POTW leak detection points and vaults Air Releases. All ok. Also check POTW MH175-078 D/S change point All ok. today |

Influent Sources and Flow Rates: @ 0815
NBBW – 6.6 gpm
North End On Site- 12.5 gpm
North End Off-Site – 8.6 gpm
RWST – 0.6 gpm
NTES – 0.5 gpm(10R only)
MW38 T-540/541 – 0.3 gpm(Source well and 38 pumping wells mix)
MW38 N & S– 2.0 gpm
COND/NTES T-530- 0.0 gpm~~(6am-1pm daily)~~
MW113 Area – 2.0 gpm

Operator: **Mike Gelwick / Chris Carlson**

# LOWRY WTP OPERATIONS LOG

Date: **Tuesday, December 14, 2021**

| Time: | |
|---|---|
| 0450 | - Plants operations Good. working on collecting TP-730 weekly CoC/Lab split samples. Also collect TP-740 + 710 weekly Low Level 1, 4-Dioxane samples. START weekly Efficiency checks |
| 0630 | ~~Start~~ Filter press on T-351 (in stage 1), use firehose nozzle and potable water to begin to backup thick sludge in T-351. |
| 0800 | - Clean pH-315 probe w/Acid solution. Check Tilt Hom330 for oil or sheen: None observed. Spray down work. |
| | - Check TP-130 for oil globules: None observed. water is very clear w/ light yellow-green tint. |
| | - working on weekly BTS samplings + field readings today |
| 0820 | Clean P-352 y-strainer |
| 0950 | - IX performance HACH testing with Lab split sampling AFTER 968,257 gal treated: TP-183 ⇒ 190 ug/L; TP-174A ⇒ 280 ug/L; TP-173A ⇒ 4300 ug/L; TP-170 ⇒ 5500 ug/L. Flow thru system ⇒ ~2.0 gpm. |
| 1150 | - Refill BTS phosphorus TANK w/6 # of TSP and 60 gal of potable water. |
| 1545 | - STOP Filter press. NOT Quite Full. In STAGE 4. Plants operations Good |

Influent Sources and Flow Rates: @ 0540
NBBW – 6.5 gpm
North End On Site- 12.5 gpm
North End Off-Site – 8.7 gpm
RWST – 0.6 gpm
NTES – 0.51 gpm(10R only)
MW38 T-540/541 – 0.30 gpm(Source well and 38 pumping wells mix)
MW38 N & S– 1.9 gpm
COND/NTES T-530- 0.00 gpm(~~6am-1pm daily~~)
MW113 Area – 2.0 gpm

Operator: **Mike Gelwick / Chris Carlson**

# LOWRY WTP OPERATIONS LOG

Date: **Wednesday, December 15, 2021**

| Time: | |
|---|---|
| 0545 | Plant operations good. Start on weekly GC maintenace and calibrations |
| 0645 | Restart Filter press (IN stage 4). |
| 0835 | -Clean pH-315 probe w/ Acid solution. Check the HMI-30 for oil or sheen; None observed. Spray down wash. |
| | -check TA-130 for oil globules; None observed. water is very clear w/ light yellow green tint. |
| 0900 | -Filter Press Full. |
| 1020 | -Replace mixers on T-540 + T-541. |
| 1215 | Backup WTP data to CD & Flash drive. Daily OneDrive backup working well. |
| 1350 | -Empty out filter Press |
| 1540 | -Plants operations Good. filter Press empty needs washout |

Influent Sources and Flow Rates: @ 0830
NBBW – 6.7 gpm
North End On Site- 12.4 gpm
North End Off-Site – 9.1 gpm
RWST – 0.6 gpm
NTES – 0.50 gpm(10R only)
MW38 T-540/541 – 0.32 gpm(Source well and 38 pumping wells mix)
MW38 N & S– 1.9 gpm
COND/NTES T-530- 0.0 gpm~~(6am-1pm daily)~~
MW113 Area – 2.0 gpm

Operator: **Mike Gelwick / Chris Carlson**

# LOWRY WTP OPERATIONS LOG

Date: **Thursday, December 16, 2021**

| Time: | |
|---|---|
| 0700 | - Plants operations Good. Automatic Blowdown operations Good. MW38 North pumping well Reached STS Low level cut off yesterday @ ~1730. Increase RWSTS Flow to 1.2 gpm to Aid T-510 Tank in keeping a stable level until MW38 N. well comes back on. Working with Tom today to Do the weekly Plants Systems checks and calibrations with some monthly work. |
| 0935 | - Clean ph-315 probe w/ acid Solution. Checked HMR30 for oil or Sheens: None observed: Sprayed down weir |
| | - Decant T-351 from bottom Valve - wet well activated. Water IS clear No odor |
| 1100 | - Checked TP-130 for oil globules: None observed - water is very clear w/ green - yellow tint |
| 1424 ~~1443~~ | - Suspended plant discharge to calibrate ph-740 probe to 10 and 4 PH STDS |
| 1438 | Resume normal discharge. |
| 1443 | Continued other plant probe calibrations to 4 and 10 PH STDS @ PH-113, 670, 310, 315, 365 |
| 1545 | Plant System Check and calibrations complete |
| 1552 | - MW38 N. Pumping well Restarted. Turn Down RWSTS gate to 0.6 gpm. |
| 1620 | - Plants operations Good. |

Influent Sources and Flow Rates: @ 0750
NBBW – 6.6 gpm
North End On Site- 12.4 gpm
North End Off-Site – 8.9 gpm
RWST – 1.2 gpm
NTES – 0.53 gpm(10R only)
MW38 T-540/541 – 0.31 gpm(Source well and 38 pumping wells mix)
MW38 N & S– 1.0 gpm
COND/NTES T-530- 0.0 gpm(~~6am-1pm daily~~)
MW113 Area – 2.0 gpm

Operator: **Mike Gelwick / Tom Gilbert**

# LOWRY WTP OPERATIONS LOG

Date: Friday, December 17, 2021

| | |
|---|---|
| 0730 | - Plant operations good. |
| 0830 | - Clean ph-315 probe w/ HCL acid solution. Checked HMR30 for oil or sheens: none observed; sprayed down weir |
| | - Deant T-351 from bottom valve - wet well activated. Water is very clear no color |
| | - checked TP-130 for oil globules: none observed - water is very clear w/ green-yellow tint |
| 1230 | - Acknowledged alarm: GC1 computer failed to communicate @ (Windows error - CPU rebooted) |
| 1430 | - Plant operations good |
| (R) 1030 | Check plant remotely - All okay. |
| (W) 1335 | Remotely restart GC1 sampling on TP-730. Check plant operations. All okay. |

Influent Sources and Flow Rates: @1415
NBBW – 6.6 gpm
N. END ON-SITE – 12.4 gpm
N. END OFF-SITE – 8.8 gpm
RWST – 0.6 gpm
NTES – 0.52
COND/NTES T-530 – 58 gpm (6AM–1PM daily)
MW38 – 1.9 gpm
T-540/541 – 0.32 gpm
MW113 Area – 2.0 gpm

OPERATOR(S) Tom Gilbert / Chris Gibson (remote)

# LOWRY WTP OPERATIONS LOG

Date: Saturday, December 18, 2021

| | |
|---|---|
| 0630 | On site For weekend systems checks - plant operations good. GC I working well |
| ↓ | since yesterday Windows CPU error / crash. |
| 0645 | Decant T-351 bottom valve, wet well did not activate. Water is clear, no color. |
| ↓ | Clean the Hach-30 water and pH probe - no oil or sheen observed in the Hach-30. Check |
| ↓ | TP-130 for oil globules - none observed. Water is clear, light yellow/green. |
| 0715 | Refill phosphorus tank with 50 gallons potable water + 5lbs TSP |
| 0735 | Blowdown operations good. |
| 0945 | Check plant operations before leaving - All okay. |
| 12/19/21 | 0835 Check plant operations - All okay. |
| 1745 | Check plant operations - All okay. |

Influent Sources and Flow Rates: @ 0650
NBBW – 0.5 gpm
N. END ON-SITE – 12.4 gpm
N. END OFF-SITE – 6.7 gpm
RWST – 0.6 gpm
NTES – 0.51 gpm
COND/NTES T-530 – 0.0 gpm (6AM-1PM ~~daily~~)
MW38 – 1.9 gpm
T-540/541 – 0.3 gpm
MW113 Area – 2.0 gpm

OPERATOR(S) Chris Carlson

# LOWRY WTP OPERATIONS LOG

Date: **Monday, December 20, 2021**

| Time: | |
|---|---|
| 0615 | Plant operations good. Decant T-351 from bottom valve. wetwell activated. water ES clear no odor. |
| 0655 | Mike starting up filterpress on T-351 (Stage 1). |
| 0900 | Blowdown operations good. |
| 0840 | - Clean pH-315 probe w/ Acid solution. Check the Hach TO for oil or sheen: None observed. Spray down room. |
| | - Check TP-130 for oily globules: None observed. water ES very clear w/ light yellow green tint. |
| 0900 | - Working on BTS Qtrly Blowers Maint. |
| 1415 | - Filterpress full |
| 1500 | - Plants operations good. |

Influent Sources and Flow Rates: @ 0845
NBBW – 6.5 gpm
North End On Site- 12.3 gpm
North End Off-Site – 8.9 gpm
RWST – 0.6 gpm
NTES – 0.52 gpm(10R only)
MW38 T-540/541 – 0.30 gpm(Source well and 38 pumping wells mix)
MW38 N & S– 1.9 gpm
COND/NTES T-530- 0.0 gpm(~~6am-1pm daily~~)
MW113 Area – 2.0 gpm

Operator: **Mike Gelwick / Chris Carlson**

# LOWRY WTP OPERATIONS LOG

Date: **Tuesday, December 21, 2021**

| Time: | |
|---|---|
| 0530 | - Plants operations Good. Prep for BTS Sampling and Efficiency checks Sampling. GCI Still In a TP-730 SAmple. Wait until it finishes then START with TP-730 GC/Lab split SAmples and TP-740/710 1,4-Dioxane Low level SAmpling. Set up to BACKWASH AAU during blowdown |
| 0630 | - Collect TP-730 GC/Lab Split SAmple and TP-740 + TP-710 Low level 1,4-Dioxane weekly SAmples. START Efficiency checks. |
| 0700 | - Blowdown operations Good. BACKWASH AAU with potable water and clean Air Releases. PSI From 6 PSI to 1 PSI. @ 7.5 gpm. |
| 0830 | - Decant T-351 to bottom valve. wet well activated. water IS clean NO color. |
| | - Clean pH-315 probe w/Acid Solution. check TANK 30 for oil or SHeen: None observed. Spray down weir. |
| | - Check TP-130 for oil globules: None observed. water IS very clear w/ light yellow-green tint. |
| | - Refill polymer TANK w/ 2 cups of NALCO polymer and 200 gal of potable water. |
| | - working on BTS SAmpling + Field Readings today |
| 0955 | - IX System performance HACH testing w/Lab split SAmples AFTer 988425 gal treated: TP-183 @ 170 ug/L; TP-174A @ 280 ug/L; TP-173A @ 4600 ug/L; TP-170 @ 5500 ug/L. |
| 1500 | - Plants operations Good. |

Influent Sources and Flow Rates: @0605
NBBW – 6.5 gpm
North End On Site- 12.3 gpm
North End Off-Site – 8.5 gpm
RWST – 0.6 gpm
NTES – 0.51 gpm(10R only)
MW38 T-540/541 – 0.27 gpm(Source well and 38 pumping wells mix)
MW38 N & S– 1.9 gpm
COND/NTES T-530- 0.0 gpm(~~6am-1pm daily~~)
MW113 Area – 2.0 gpm

Operator: **Mike Gelwick / Chris Carlson**

# LOWRY WTP OPERATIONS LOG

Date: **Wednesday, December 22, 2021**

| Time: | |
|---|---|
| 0500 | Plant operations good. Start on weekly GC maintenance and calibrations. Prepare for MW38 source well batch extraction by stopping MW38 N.'s extraction. |
| ↓ | |
| 0550 | Increase RWST influent from 0.6 gpm to 2.6 gpm. Switch MW38 from direct HMR-30 influent to T-540/541. |
| ↓ | |
| 0630 | Start MW38 source well batch extraction. |
| 0710 | Blowdown operations good. |
| 0820 | - Decant T-851 to bottom valve. wetwell activated. water is clear no color. |
| | - Clean pH-315 probe w/Acid solution. Check the HMR30 for oil or sheen; None observed. Spray down weir. |
| | - Check TP-130 for oil globules: None observed. water is very clear w/ yellow-green tint. |
| | - Setup to flush sediment tank on BTS feed piping. |
| 0910 | - Place BTS into manual Hold and begin flushing P-006/T-540/541 / sediment tank piping. Also flush BTS Reactor Feed Lines. |
| 1025 | - BTS out of Hold. Clean up Housing + Floor. |
| 1500 | - Plants operations Good. |

Influent Sources and Flow Rates: @ 0747
NBBW – 6.5 gpm
North End On Site- 12.3 gpm
North End Off-Site – 8.6 gpm
RWST – 2.6 gpm
NTES – 0.5 gpm(10R only)
MW38 T-540/541 – 0.7 gpm(Source well and 38 pumping wells mix)
MW38 N & S– 0.0 gpm
COND/NTES T-530- 0.0 gpm~~(6am-1pm daily)~~
MW113 Area – 2.0 gpm

Operator: **Mike Gelwick / Chris Carlson**

# LOWRY WTP OPERATIONS LOG

Date: **Thursday, December 23, 2021**

| Time: | |
|---|---|
| 0645 | - Plants Operations Good. |
| 0700 | - Automatic blowdown operations Good. Working on weekly/monthly Plants systems checks and calibrations. Calibrate 5.7e multimeter to 50% LEL house during LEL-740 calibration to ensure 0% LEL @ T-740. Prepare New 4+10 pH STD's house during calibrations today |
| 0915 | - Decant T-351 to bottom valve. wet well activated. water is clear No color |
| | - Clean pH-315 probe w/Acid solution. Check the HMI-30 for oil or sheen: None observed. Spray down work |
| | - Check TP-130 for oil globules: None observed. water is very clear w/ light yellow green tint. |
| | - START monthly oil moisture prevention on main compressor. Run @ max speed for ~2 Hrs |
| 0955 | - STOP pump @ MW38 source well. |
| 1040 | - RESTART MW38 N+S pumping wells to T-540/541 until @ least 600 gal Flushed thru pipeline to displace any residual source well waters. |
| 1115 | - STOP oil moisture prevention on main compressor. |
| 1210 | - Perform monthly BTS pH probes calibrations using New 4+10 pH STD's. |
| 1310 | - Begin calibration of WTP pH probes using New 4+10 pH STD's @ pH-113, 670, 310, 315 & 365. |
| 1401 | - Suspend WTP Discharge to calibrate pH-740 to New 4+10 pH STD's and LEL-740 to 49% LEL. |
| 1421 | - Plant shut down during LEL-740 calibration for High LEL @ 8% LEL. Automatic shutdown for LEL operational. |
| 1424 | - RESTART Plant process |
| 1425 | - Resume Normal Discharge. |
| 1435 | - Weekly/monthly plants systems & checks and calibrations complete. |
| 1617 | - Switch MW38 N+S pumping wells to RWST's while I switch manual valves @ the HMI-30. |
| 1620 | - Switch MW38 N+S pumping wells to HMI-30 mode. A Total of 651 gal of MW38 N+S wells Run thru Pipeline Prior to switch over. Turn RWST's flow down to 0.60 gpm. |
| 1630 | - Plants Operations Good. |

Influent Sources and Flow Rates: @ 0750
NBBW – 6.5 gpm
North End On Site- 12.2 gpm
North End Off-Site – 8.6 gpm
RWST – 2.6 gpm
NTES – 0.52 gpm(10R only)
MW38 T-540/541 – 0.20 gpm(Source well and 38 pumping wells mix)
MW38 ~~N&S~~ – 5.0 gpm ~~source well batch~~
COND/NTES T-530- 0.0 gpm(~~6am-1pm daily~~)
MW113 Area – 2.0 gpm

Operator: **Mike Gelwick**

# LOWRY WTP OPERATIONS LOG

Date: **Friday, December 24, 2021**

| Time: | |
|---|---|
| 0645 | - Plants operations Good. |
| 0700 | - Automatic blowdown operations Good. |
| 0800 | - Refill BTS phosphorus TANK w/ 4# of TSP and 40gal of potable water. weigh out media in oven. Both GC's operational within limits all Blowers ok. NO leaks observed. |
| 0825 | - Decant T-351 TO bottom valve. Wetwell activated. water IS clear NO color. |
| | - Clean pH-315 probe w/ Acid solution. Check TPE Hmp30 for oil or sheen: None observed. Spray down wet. |
| | - Check TP-130 for oil globules: None observed. water IS very clear w/ light yellow green hint. |
| | - Clean office + BATHroom. |
| 0915 | - Plants operations Good. |
| 1500 | - Log on Remotely. Allok |
| 2100 | - log on Remotely All ok |
| SATURday | December 25, 2021 |
| 0830 | - log in Remotely. Allok. |
| 1500 | - log in Remotely. Allok. Increase LWBTS flow to 1.0 gpm. T-510 Tank needs a little more water to stay at a good level. Other Influent Flows have decreased |
| 2100 | - Log in Remotely. Allok. |

Influent Sources and Flow Rates: @0645
NBBW – 6.5 gpm
North End On Site- 12.3 gpm
North End Off-Site – 8.4 gpm
RWST – 0.60 gpm
NTES – 0.52 gpm(10R only)
MW38 T-540/541 – 0.19 gpm(Source well and 38 pumping wells mix)
MW38 N & S– 2.0 gpm
COND/NTES T-530- 0.0 gpm(~~6am-1pm daily~~)
MW113 Area – 2.0 gpm

Operator: **Mike Gelwick**

# LOWRY WTP OPERATIONS LOG

Date: Sunday, December 26, 2021

| | |
|---|---|
| 0745 | - Plants operations Good. Going to check other site systems. OUT OF Automatic blowdown ok. |
| 0850 | - Decant T-351 to bottom valve. wet well activated. water is clear NO color. |
| | - Clean pH-315 probe w/Acid solution. Check TH HARJO for oil or sheen: None observed. Spray down worn |
| | - Check TP-130 for oil globules: None observed. water is very clear w/ yellow-green tint |
| | - Both GC's operational with No Limits, BTS BAG filters BACKWASH operations Good. All blowers ok. |
| 1005 | - Plants operations Good. |
| 1600 | - Remote log in. Allow |
| 2200 | - Remote log in. Allow. |

Influent Sources and Flow Rates: @ 0900
NBBW – 6.5 gpm
N. END ON-SITE – 12.0 gpm
N. END OFF-SITE – 8.5 gpm
RWST – 1.0 gpm
NTES – 0.519PM
COND/NTES T-530 – 0.0 gpm ~~(6AM-1PM daily)~~
MW38 – 1.9 gpm
T-540/541 – 0.20 gpm
MW113 Area – 1.9 gpm

OPERATOR(S) Mike Grebenik

# LOWRY WTP OPERATIONS LOG

Date: **Monday, December 27, 2021**

| Time: | |
|---|---|
| 0600 | Plant operations good. |
| 0810 | Blowdown operations good. Observe last TP3350 GC result looking normal (BTS has adjusted to Fresh Source well batch), increase ~~P-002~~ P-006 (T540/541) from 0.2 gpm to 0.3 gpm. Reduce RWST influent from 1.0 gpm to 0.6 gpm (RWST @ 27%). |
| 1030 | - Working on weekly plants systems checks and calibrations Early today due to work schedule this week. |
| | - Decant T-351 to bottom valve. Wetwell activated. Water is clear No color. |
| | - Clean pH-315 probe w/ Acid solution. Check TPE Hank 30 for oil or sheen: None observed. Spray down wash. |
| | - Check TPE 30 for oil globules: None observed. Water is very clear w/ yellow green tint. |
| 1230 | - Work w/ CC to add a New tote of Na OH to the chemical bay and top off peroxide with Remainder on tote. |
| 1340 | - CC Empty out filter press 5. 5 still Needs wash out. |
| 1351 | - Suspend Plant Discharge to calibrate pH-740 probe to 4+10 pH STD's. |
| 1359 | - Resume Normal Discharge. Continue with other WTP pH probes calibrations to 4+10 pH STD's 7 pH - 113, 670, 310, 315 & 365. |
| 1445 | - Weekly Plants Systems checks and calibrations complete. |
| 1510 | - Plants operating Good. |

Influent Sources and Flow Rates: @1030
NBBW – 6.5 gpm
North End On Site- 11.9 gpm
North End Off-Site – 8.5 gpm
RWST – 0.6 gpm
NTES – 0.5 gpm(10R only)
MW38 T-540/541 – 0.3 gpm(Source well and 38 pumping wells mix)
MW38 N & S– 1.9 gpm
COND/NTES T-530- 0.0 gpm(~~6am-1pm daily~~)
MW113 Area – 1.9 gpm

Operator: **Mike Gelwick / Chris Carlson**

# LOWRY WTP OPERATIONS LOG

Date: **Tuesday, December 28, 2021**

| Time: | |
|---|---|
| 0600 | - Plants operations Good. Prep for GC/Lab SAND sampling and TP-740+710 samplings. |
| 0630 | - Collect TP-730 GC/Lab split samples and TP-710 and TP-740 weekly Low Level 1,4-Dioxane samples. START Efficiency checks. |
| 0830 | - Decant T-351 to bottom valve. wet well activated. water is clear Noodle |
| | - Clean pH-315 probe w/Acid solution. Check the Hood 30 for oil or sheen: None observed. Spray down wash. |
| | - Check TP-130 For oil globules: None observed. water is very clear w/yellow-green hints. |
| | - working on BTS weekly sampling and Field readings today. Refill BTS phosphorus TANK w/6# OF TSP + 60 gal of potable water. |
| 1005 | - IX System Performance HACH testing w/Lab split sampling After 1,008,156 gal Treated: TP-183 ≈ 160 ug/L; TP-174A ≈ 250 ug/L; TP-173A ≈ 4900 ug/L; TP-170 ≈ 5600 ug/L. Currently the flow Rate is ≈ 1.9 gpm. |
| 1530 | Plant operations good. End. |

Influent Sources and Flow Rates: @ 0640
NBBW – 6.5 gpm
North End On Site- 11.9 gpm
North End Off-Site – 8.7 gpm
RWST – 0.6 gpm
NTES – 0.53 gpm(10R only)
MW38 T-540/541 – 0.30 gpm(Source well and 38 pumping wells mix)
MW38 N & S– 1.9 gpm
COND/NTES T-530- 0.0 gpm(~~6am-1pm daily~~)
MW113 Area – 1.9 gpm

Operator: **Mike Gelwick / Chris Carlson**

# LOWRY WTP OPERATIONS LOG

Date: **Wednesday, December 29, 2021**

| Time: 0550 | Plant operations good. Start on weekly GC maintenance & calibrations. |
|---|---|
| 0630 | Restart T-530 to BTS at 0.2 gpm (timed to run between 6AM-1PM), T-530 @ 34%. |
| 0655 ↓ | Start Filterpress on T-352 (in stage 1). Decant T-351 bottom valve, wet well did not activate. Clean HMR-30 weir and pH probe - no oil or sheen observed in the HMR-30. |
| 0710 ↓ | Blowdown operations good. Decant T-351 bottom valve again, wet well activated. |
| 0623 ↓ | Water is clear, no color. Check TP-130 for oil globules, none observed. water is very clear light yellow Place BTS in maintenance hold and flush the reactor. Feed lines with potable water / compressed air. |
| 0922 | BTS out of maintenance hold. |
| 0940 ↓ | Switch Filter press feed from T-352 to T-351. Clean decant P-352 pumps y-strainer. Begin P-381 pump rebuild. |
| 1200 | Backup plant data to Flash and DVD. Daily OneDrive backup working well. |
| 1445 | Shutdown Filterpress (in stage 4). Plant operations good. |

Influent Sources and Flow Rates: 0635
NBBW – 6.5GPM
N. END ON-SITE – 11.9GPM
N. END OFF-SITE – 8.8GPM
RWST – 0.6GPM
NTES – 0.51GPM
COND/NTES T-530 – 0.2GPM (6AM-1PM)
MW38 – 1.9GPM
T-540/541 – 0.3GPM
MW113 IX SYSTEM – 1.9GPM
OTHER – NA

OPERATOR(S) Chris Carlson / Tom Gilbert

# LOWRY WTP OPERATIONS LOG

Date: Thursday, December 30, 2021

| | |
|---|---|
| 0740 | - Plant operations good. |
| 1150 | - Decant T-351 from bottom valve, wet well activated, water is very clear |
| | - Clean ph-315 probe w/ acid solution. Check HMI330 for oil or sheens: None observed; sprayed down weir. |
| | - Checked TP-130 for oil globules: none observed. Water is very clear w/ green-yellow tint. |
| 1500 | - Plant operations good. |
| (W) 0900 | Check plant remotely - All okay. |

Influent Sources and Flow Rates: @ 1143
NBBW – 6.5 gpm
N. END ON-SITE – 11.9 gpm
N. END OFF-SITE – 8.8 gpm
RWST – 0.6 gpm
NTES – 0.52 gpm
COND/NTES T-530 – 0.22 gpm (6AM–1PM daily)
MW38 – 1.9 gpm
T-540/541 – 0.30 gpm
MW113 Area – 1.9 gpm

OPERATOR(S) Tom Gilbert

# LOWRY WTP OPERATIONS LOG

Date: Friday, December 31, 2021

| | |
|---|---|
| 0730 | - Plant operations good. |
| 0830 | - Filled phosphorus tank with 5LBS/50 gallons T.S.P. |
| 0845 | - Decant T-351 from bottom valve, wet well activated, water is very clear |
| | - Clean PH-315 probe with HCL acid solution. Checked HMR30 for oil or sheens: None observed; Sprayed down weir. |
| | - Checked TP-130 for oil globules: none observed. Water is very clear with yellow tint. |
| 0915 | - Plant operations good. |
| (W) 0935 | Check plant remotely - All Okay |

Influent Sources and Flow Rates: @0900
NBBW – 6.4 gpm
N. END ON-SITE – 11.9 gpm
N. END OFF-SITE – 8.2 gpm
RWST – 0.6 gpm
NTES – 0.54 gpm
COND/NTES T-530 – 0.20 gpm (6AM–1PM daily)
MW38 – 1.9 gpm
T-540/541 – 0.30 gpm
MW113 Area – 1.9 gpm

OPERATOR(S) Tom Gilbert

# APPENDIX A-2

# NBBW SUMP GRAPH





**FIGURE A-2**
**NORTH BOUNDARY BARRIER WALL**
**GROUNDWATER ELEVATIONS**
O&M Status Report
July through December 2021
Lowry Landfill Superfund Site

**PARSONS**
Denver, Colorado

S:\ES\MajProj\LWRYLNFL\QUARTERLY REPORTS\2ND HALF 2021\APPENDIX A-2 NBBW ELEVATIONS\
Figure A-2.xlsx

# APPENDIX A-3

# SLUDGE ANALYSIS DATA

# APPENDIX A-3
# WTP SLUDGE RESULTS
## JULY THROUGH DECEMBER 2021 OPERATIONS AND MAINTENANCE STATUS REPORT
## LOWRY LANDFILL SUPERFUND SITE

| Parameter Name | Method | Units[a/] | Regulatory Limit[b/] | WTP SLUDGE 9/28/2021 | RL/Lc[c/] | WTP SLUDGE-1[d/] 9/28/21 | Lc | WTP SLUDGE-2[d/] 9/28/21 | Lc | WTP SLUDGE-3[d/] 9/28/21 | Lc |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Radium-228 | EPA 901.1 | pCi/g | 5 | NAn | NAn | 0.94 +/- 0.29 | 0.2 | 0.37 +/- 0.48 | 0.38 | 1.19 +/- 0.37 | 0 |
| Radium-226 | EPA 901.1 | pCi/g | 5 | NAn | NAn | 0.18 +/- 0.24 | 0.17 | 0.37 +/- 0.30 | 0.22 | 0.26 +/- 0.24 | 0.18 |
| Lead-210 | EPA 901.1 | pCi/g | 5 | NAn | NAn | 0.052 +/- 0.16 | 0.13 | -0.035 +/- 0.20 | 0.14 | -0.044 +/- 0.21 | 0.15 |
| Polonium-210 | EML Po-2 | pCi/g | 5 | NAn | NAn | 0.048 +/- 0.093 | 0.031 | 0.17 +/- 0.14 | 0.0085 | 0.069 +/- 0.10 | 0.034 |
| Uranium-234 | ASTM D2907 | pCi/g | 1590 | 14.40 +/- 1.92 | 0.017 | NAn[e/] | NAn | NAn | NAn | NAn | NAn |
| Uranium-235 | ASTM D2907 | pCi/g | 1800 | 0.61 +/- 0.22 | 0.0078 | NAn | NAn | NAn | NAn | NAn | NAn |
| Uranium-238 | ASTM D2907 | pCi/g | 1940 | 10.78 +/- 1.49 | 0.024 | NAn | NAn | NAn | NAn | NAn | NAn |
| Plutonium-238 | EPA 600/7-79-081 | pCi/g | 540 | -0.0047 +/- 0.054 | 0.22 | NAn | NAn | NAn | NAn | NAn | NAn |
| Plutonium-239/240 | EPA 600/7-79-081 | pCi/g | 1090 | 0.016 +/- 0.050 | 0.0099 | NAn | NAn | NAn | NAn | NAn | NAn |
| Americium-241 | ER110 LANL | pCi/g | 646 | -0.036 +/- 0.038 | 0.038 | NAn | NAn | NAn | NAn | NAn | NAn |
| Arsenic | TCLP[f/]/6010B | mg/L | 5 | 0.5 U | 0.5 | NAn | NAn | NAn | NAn | NAn | NAn |
| Barium | TCLP/6010B | mg/L | 100 | 0.3 J | 10 | NAn | NAn | NAn | NAn | NAn | NAn |
| Cadmium | TCLP/6010B | mg/L | 1 | 0.1 U | 0.1 | NAn | NAn | NAn | NAn | NAn | NAn |
| Chromium | TCLP/6010B | mg/L | 6 | 0.5 U | 0.5 | NAn | NAn | NAn | NAn | NAn | NAn |
| Lead | TCLP/6010B | mg/L | 5 | 0.038 J | 0.5 | NAn | NAn | NAn | NAn | NAn | NAn |
| Selenium | TCLP/6010B | mg/L | 1 | 0.25 U | 0.25 | NAn | NAn | NAn | NAn | NAn | NAn |
| Silver | TCLP/6010B | mg/L | 5 | 0.5 U | 0.5 | NAn | NAn | NAn | NAn | NAn | NAn |
| Mercury | TCLP/7470A | mg/L | 0.2 | 0.0001 J | 0.002 | NAn | NAn | NAn | NAn | NAn | NAn |
| 2,4-D | TCLP/8151A | mg/L | 10 | 0.04 U | 0.04 | NAn | NAn | NAn | NAn | NAn | NAn |
| 1,1-Dichloroethene | TCLP/8260B | mg/L | 0.7 | 0.01 U | 0.01 | NAn | NAn | NAn | NAn | NAn | NAn |
| 1,2-Dichloroethane | TCLP/8260B | mg/L | 0.5 | 0.01 U | 0.01 | NAn | NAn | NAn | NAn | NAn | NAn |
| 2-Butanone (MEK) | TCLP/8260B | mg/L | 200 | 0.05 U | 0.05 | NAn | NAn | NAn | NAn | NAn | NAn |
| Benzene | TCLP/8260B | mg/L | 0.5 | 0.01 U | 0.01 | NAn | NAn | NAn | NAn | NAn | NAn |
| Carbon tetrachloride | TCLP/8260B | mg/L | 0.5 | 0.01 U | 0.01 | NAn | NAn | NAn | NAn | NAn | NAn |
| Chlorobenzene | TCLP/8260B | mg/L | 100 | 0.01 U | 0.01 | NAn | NAn | NAn | NAn | NAn | NAn |
| Chloroform | TCLP/8260B | mg/L | 6 | 0.01 U | 0.01 | NAn | NAn | NAn | NAn | NAn | NAn |
| Tetrachloroethene | TCLP/8260B | mg/L | 0.7 | 0.01 U | 0.01 | NAn | NAn | NAn | NAn | NAn | NAn |
| Trichloroethene | TCLP/8260B | mg/L | 0.5 | 0.01 U | 0.01 | NAn | NAn | NAn | NAn | NAn | NAn |
| Vinyl chloride | TCLP/8260B | mg/L | 0.2 | 0.02 U | 0.02 | NAn | NAn | NAn | NAn | NAn | NAn |
| 1,4-Dichlorobenzene | TCLP/8270C | mg/L | 7.5 | 0.02 U | 0.02 | NAn | NAn | NAn | NAn | NAn | NAn |
| 2,4,5-Trichlorophenol | TCLP/8270C | mg/L | 400 | 0.05 U | 0.05 | NAn | NAn | NAn | NAn | NAn | NAn |
| 2,4,6-Trichlorophenol | TCLP/8270C | mg/L | 2 | 0.025 U | 0.025 | NAn | NAn | NAn | NAn | NAn | NAn |
| 2,4-Dinitrotoluene | TCLP/8270C | mg/L | 0.13 | 0.05 U | 0.05 | NAn | NAn | NAn | NAn | NAn | NAn |
| 2-Methylphenol | TCLP/8270C | mg/L | 200 | 0.05 U | 0.05 | NAn | NAn | NAn | NAn | NAn | NAn |
| 3 & 4 Methylphenol | TCLP/8270C | mg/L | 200 | 0.05 U | 0.05 | NAn | NAn | NAn | NAn | NAn | NAn |
| Hexachlorobenzene | TCLP/8270C | mg/L | 0.13 | 0.05 U | 0.05 | NAn | NAn | NAn | NAn | NAn | NAn |
| Hexachlorobutadiene | TCLP/8270C | mg/L | 0.5 | 0.05 U | 0.05 | NAn | NAn | NAn | NAn | NAn | NAn |
| Hexachloroethane | TCLP/8270C | mg/L | 3 | 0.05 U | 0.05 | NAn | NAn | NAn | NAn | NAn | NAn |
| Nitrobenzene | TCLP/8270C | mg/L | 2 | 0.05 U | 0.05 | NAn | NAn | NAn | NAn | NAn | NAn |

# APPENDIX A-3
# WTP SLUDGE RESULTS
## JULY THROUGH DECEMBER 2021 OPERATIONS AND MAINTENANCE STATUS REPORT
## LOWRY LANDFILL SUPERFUND SITE

| Parameter Name | Method | Units[a/] | Regulatory Limit[b/] | WTP SLUDGE 9/28/2021 | RL/Lc[c/] | WTP SLUDGE-1[d/] 9/28/21 | Lc | WTP SLUDGE-2[d/] 9/28/21 | Lc | WTP SLUDGE-3[d/] 9/28/21 | Lc |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Pentachlorophenol | TCLP/8270C | mg/L | 100 | 0.25 U | 0.25 | NAn | NAn | NAn | NAn | NAn | NAn |
| Pyridine | TCLP/8270C | mg/L | 5 | 0.1 U | 0.1 | NAn | NAn | NAn | NAn | NAn | NAn |
| Total Cresols | TCLP/8270C | mg/L | 200 | 0.05 U | 0.05 | NAn | NAn | NAn | NAn | NAn | NAn |

a/ Units = mg/L = milligrams per liter
pCi/g = picoCuries per gram

b/ 40 CFR 261.24 Toxicity Characteristic and the Updated Waste Management Plan (EMSI/Parsons 2020)

c/ RL/Lc = Reporting Limit/Critical Value

d/ Sampled for Technologically Enhanced Naturally Occurring Radioactive Material (TENORM) Assessment

e/ Not analyzed for

f/ TCLP = Toxicity Characteristic Leaching Procedure

**Qualifiers:** U= The analyte was analyzed for and is not present above the level of the associated value.
The associated numerical value indicates the approximate concentration necessary to detect the analyte in the sample.

J= The analyte was analyzed for, and was positively identified, but the associated numerical value may not be consistent with the amount actually present in the environmental sample.

# APPENDIX A-4

# WTP WATER QUALITY DATA

# APPENDIX A-4.1

# SUMMARY OF WATER TREATMENT PLANT EFFLUENT (MP-001) WATER QUALITY

# APPENDIX A-4.1.1

# COMPLIANCE SUMMARY OF WATER TREATMENT PLANT EFFLUENT (MP-001)WATER QUALITY

# 1,4-DIOXANE

## APPENDIX A-4.1.1

## COMPLIANCE SUMMARY OF TREATMENT PLANT EFFLUENT (MP-001) WATER QUALITY
## 1,4-DIOXANE

| Date→ | 7/6/2021 | 7/6/2021 | 7/6/2021 | 7/7/2021 | 7/7/2021 | 7/7/2021 | | | | |
|---|---|---|---|---|---|---|---|---|---|---|
| Time→ | 12:00 | 16:00 | 20:00 | 0:00 | 4:00 | 8:00 | | | | |
| Compound | Conc (ug/L[a/]) | Conc (ug/L) | Conc (ug/L) | Conc (ug/L) | Conc (ug/L) | Conc (ug/L) | Average conc (ug/L) | Volume per day[b/] | Total (lbs/day[c/]) | Permit Limit (lbs/day) |
| 1,4-Dioxane[d/] | 16 | 18 | 19 | 18 | 18 | 19 | 18.00 | 51396 | 0.0077 | 0.032 |

| Date→ | 8/2/2021 | 8/2/2021 | 8/2/2021 | 8/3/2021 | 8/3/2021 | 8/3/2021 | | | | |
|---|---|---|---|---|---|---|---|---|---|---|
| Time→ | 12:00 | 16:00 | 20:00 | 0:00 | 4:00 | 8:00 | | | | |
| Compound | Conc (ug/L) | Conc (ug/L) | Conc (ug/L) | Conc (ug/L) | Conc (ug/L) | Conc (ug/L) | Average conc (ug/L) | Volume per day | Total (lbs/day) | Permit Limit (lbs/day) |
| 1,4-Dioxane[d/] | 16 | 18 | 19 | 18 | 17 | 17 | 17.50 | 50204 | 0.0073 | 0.032 |

| Date→ | 9/7/2021 | 9/7/2021 | 9/7/2021 | 9/8/2021 | 9/8/2021 | 9/8/2021 | | | | |
|---|---|---|---|---|---|---|---|---|---|---|
| Time→ | 12:00 | 16:00 | 20:00 | 0:00 | 4:00 | 8:00 | | | | |
| Compound | Conc (ug/L) | Conc (ug/L) | Conc (ug/L) | Conc (ug/L) | Conc (ug/L) | Conc (ug/L) | Average conc (ug/L) | Volume per day | Total (lbs/day) | Permit Limit (lbs/day) |
| 1,4-Dioxane[d/] | 25 | 23 | 21 | 20 | 21 | 21 | 21.83 | 48907 | 0.0089 | 0.032 |

| Date→ | 10/4/2021 | 10/4/2021 | 10/4/2021 | 10/5/2021 | 10/5/2021 | 10/5/2021 | | | | |
|---|---|---|---|---|---|---|---|---|---|---|
| Time→ | 12:00 | 16:00 | 20:00 | 0:00 | 4:00 | 8:00 | | | | |
| Compound | Conc (ug/L[a/]) | Conc (ug/L) | Conc (ug/L) | Conc (ug/L) | Conc (ug/L) | Conc (ug/L) | Average conc (ug/L) | Volume per day | Total (lbs/day) | Permit Limit (lbs/day) |
| 1,4-Dioxane[d/] | 17 | 18 | 17 | 18 | 17 | 17 | 17.33 | 51192 | 0.0074 | 0.032 |

| Date→ | 11/1/2021 | 11/1/2021 | 11/1/2021 | 11/2/2021 | 11/2/2021 | 11/2/2021 | | | | |
|---|---|---|---|---|---|---|---|---|---|---|
| Time→ | 12:00 | 16:00 | 20:00 | 0:00 | 4:00 | 8:00 | | | | |
| Compound | Conc (ug/L) | Conc (ug/L) | Conc (ug/L) | Conc (ug/L) | Conc (ug/L) | Conc (ug/L) | Average conc (ug/L) | Volume per day | Total (lbs/day) | Permit Limit (lbs/day) |
| 1,4-Dioxane[d/] | 18 | 19 | 19 | 19 | 19 | 19 | 18.83 | 50310 | 0.0079 | 0.032 |

| Date→ | 12/6/2021 | 12/6/2021 | 12/6/2021 | 12/7/2021 | 12/7/2021 | 12/7/2021 | | | | |
|---|---|---|---|---|---|---|---|---|---|---|
| Time→ | 12:00 | 16:00 | 20:00 | 0:00 | 4:00 | 8:00 | | | | |
| Compound | Conc (ug/L) | Conc (ug/L) | Conc (ug/L) | Conc (ug/L) | Conc (ug/L) | Conc (ug/L) | Average conc (ug/L) | Volume per day | Total (lbs/day) | Permit Limit (lbs/day) |
| 1,4-Dioxane[d/] | 18 | 20 | 22 | 22 | 22 | 22 | 21.00 | 47648 | 0.0084 | 0.032 |

a/ ug/L = micrograms per liter

b/ Volume per day recorded on Composite Sampling Record

c/ lbs/day = pounds per day

d/ 1,4-Dioxane analyzed by low-level method (SW8260SIM)

# APPENDIX A-4.1.2

# COMPLIANCE SUMMARY OF WATER TREATMENT PLANT EFFLUENT (MP-001)WATER QUALITY

# VOLATILE ORGANIC COMPOUNDS AND NONYLPHENOL

**APPENDIX A-4.1.2**
**COMPLIANCE SUMMARY OF TREATMENT PLANT EFFLUENT (MP-001) WATER QUALITY**
**VOLATILE ORGANIC COMPOUNDS AND NONYLPHENOL**

| Date/Time→ | 7/6/2021 12:00 | 7/6/2021 16:00 | 7/6/2021 20:00 | 7/7/2021 00:00 | 7/7/2021 04:00 | 7/7/2021 08:00 | | | |
|---|---|---|---|---|---|---|---|---|---|
| Compound | Conc (ug/L[a/]) | Conc (ug/L) | Conc (ug/L) | Conc (ug/L) | Conc (ug/L) | Conc (ug/L) | Average conc (ug/L) | Permit Limit (ug/L) | Max Value (ug/L) |
| 1,1,1,2-Tetrachloroethane | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 0 | NA [b/] | 0 |
| 1,1,1-Trichloroethane | 7 | 7.2 | 6.7 | 7 | 7.1 | 6.8 | 6.97 | NA | 7.2 |
| 1,1,2,2-Tetrachloroethane | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 0 | NA | 0 |
| 1,1,2-Trichloroethane | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 0 | NA | 0 |
| 1,1-Dichloroethane | 22 | 22 | 21 | 21 | 22 | 21 | 21.5 | NA | 22 |
| 1,1-Dichloroethene | 1.2 | 1.4 | 1.2 | 1.2 | 1.4 | 1.2 | 1.3 | NA | 1.4 |
| 1,2,3-Trichloropropane | 3 U | 3 U | 3 U | 3 U | 3 U | 3 U | 0 | NA | 0 |
| 1,2-Dibromo-3-chloropropane | 5 U | 5 U | 5 U | 5 U | 5 U | 5 U | 0 | NA | 0 |
| 1,2-Dibromoethane | 5 U | 5 U | 5 U | 5 U | 5 U | 5 U | 0 | NA | 0 |
| 1,2-Dichlorobenzene | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 0 | NA | 0 |
| 1,2-Dichloroethane | 0.81 J | 0.77 J | 0.71 J | 0.74 J | 0.72 J | 0.74 J | 0.75 J | NA | 0.81 J |
| 1,2-Dichloroethene | 5.2 | 5.3 | 4.9 | 5 | 5.1 | 4.9 | 5.07 | NA | 5.3 |
| 1,2-Dichloropropane | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 0 | NA | 0 |
| 1,3-Dichlorobenzene | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 0 | NA | 0 |
| 1,3-Dichloropropene | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 0 | NA | 0 |
| 1,4-Dichlorobenzene | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 0 | NA | 0 |
| 2-Butanone (MEK) | 20 U | 20 U | 20 U | 20 U | 20 U | 20 U | 0 | NA | 0 |
| 2-Chloroethylvinylether | 3 U | 3 U | 3 U | 3 U | 3 U | 3 U | 0 | NA | 0 |
| 2-Hexanone | 5 U | 5 U | 5 U | 5 U | 5 U | 5 U | 0 | NA | 0 |
| 4-Methyl-2-pentanone (MIBK) | 5 U | 5 U | 5 U | 5 U | 5 U | 5 U | 0 | NA | 0 |
| Acetone | 20 U | 20 U | 20 U | 20 U | 20 U | 20 U | 0 | NA | 0 |
| Acrolein | 20 U | 20 U | 20 U | 20 U | 20 U | 20 U | 0 | NA | 0 |
| Acrylonitrile | 20 U | 20 U | 20 U | 20 U | 20 U | 20 U | 0 | NA | 0 |
| Benzene | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 0 | NA | 0 |
| Bromodichloromethane | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 0 | NA | 0 |
| Bromoform | 2 U | 2 U | 2 U | 2 U | 2 U | 2 U | 0 | NA | 0 |
| Bromomethane | 2 U | 2 U | 2 U | 2 U | 2 U | 2 U | 0 | NA | 0 |
| Carbon Disulfide | 2 U | 2 U | 2 U | 2 U | 2 U | 2 U | 0 | NA | 0 |
| Carbon Tetrachloride | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 0 | NA | 0 |
| Chlorobenzene | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 0 | NA | 0 |
| Chloroethane | 4 U | 4 U | 4 U | 4 U | 4 U | 4 U | 0 | NA | 0 |
| Chloroform | 0.52 J | 0.51 J | 0.46 J | 0.5 J | 0.52 J | 0.43 J | 0.49 J | NA | 0.52 J |
| Chloromethane | 2 U | 2 U | 2 U | 2 U | 2 U | 2 U | 0 | NA | 0 |
| cis-1,2-Dichloroethene | 5.2 | 5.3 | 4.9 | 5 | 5.1 | 4.9 | 5.07 | NA | 5.3 |
| cis-1,3-Dichloropropene | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 0 | NA | 0 |
| Dibromochloromethane | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 0 | NA | 0 |
| Dibromomethane | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 0 | NA | 0 |
| Dichlorodifluoromethane | 2 U | 2 U | 2 U | 2 U | 2 U | 2 U | 0 | NA | 0 |
| Ethylbenzene | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 0 | NA | 0 |
| Hexane | 2 U | 2 U | 2 U | 2 U | 2 U | 2 U | 0 | NA | 0 |
| Methylene Chloride | 0.21 U | 5 U | 5 U | 0.22 U | 0.18 U | 5 U | 0 | NA | 0 |
| Methyl-t-butyl ether | 5 U | 5 U | 5 U | 5 U | 5 U | 5 U | 0 | NA | 0 |
| m-Xylene & p-Xylene | 2 U | 2 U | 2 U | 2 U | 2 U | 2 U | 0 | NA | 0 |
| Naphthalene | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 0 | NA | 0 |
| o-Xylene | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 0 | NA | 0 |
| Styrene | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 0 | NA | 0 |
| Tetrachloroethene | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 0 | 1500 | 0 |
| Tetrahydrofuran | 7 U | 7 U | 7 U | 7 U | 7 U | 7 U | 0 | NA | 0 |
| Toluene | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 0 | NA | 0 |
| Trans-1,2-Dichloroethene | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 0 | NA | 0 |
| Trans-1,3-Dichloropropene | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 0 | NA | 0 |
| Trichloroethene | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 0 | NA | 0 |
| Trichlorofluoromethane | 2 U | 2 U | 2 U | 2 U | 2 U | 2 U | 0 | NA | 0 |
| Vinyl Acetate | 3 U | 3 U | 3 U | 3 U | 3 U | 3 U | 0 | NA | 0 |
| Vinyl Chloride | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 0 | NA | 0 |
| Xylenes, Total | 2 U | 2 U | 2 U | 2 U | 2 U | 2 U | 0 | NA | 0 |
| Nonylphenol | 4.9 U | 5 U | 4.9 U | 4.8 U | 5 U | 5 U | 0 | NA | 0 |

| Date/Time→ | 10/4/2021 12:00 | 10/4/2021 16:00 | 10/4/2021 20:00 | 10/5/2021 00:00 | 10/5/2021 04:00 | 10/5/2021 08:00 | | | |
|---|---|---|---|---|---|---|---|---|---|
| Compound | Conc (ug/L[a/]) | Conc (ug/L) | Conc (ug/L) | Conc (ug/L) | Conc (ug/L) | Conc (ug/L) | Average conc (ug/L) | Permit Limit (ug/L) | Daily Max Value (ug/L) |
| 1,1,1,2-Tetrachloroethane | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 0 | NA [b/] | 0 |
| 1,1,1-Trichloroethane | 7.5 | 7.7 | 7.7 | 7.6 | 7.8 | 7.6 | 7.7 | NA | 7.8 |
| 1,1,2,2-Tetrachloroethane | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 0 | NA | 0 |
| 1,1,2-Trichloroethane | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 0 | NA | 0 |
| 1,1-Dichloroethane | 19 | 20 | 19 | 20 | 19 | 19 | 19.3 | NA | 20.0 |
| 1,1-Dichloroethene | 0.88 J | 1 | 1.1 | 1 | 0.98 J | 0.99 J | 1.0 | NA | 1.1 |
| 1,2,3-Trichloropropane | 3 U | 3 U | 3 U | 3 U | 3 U | 3 U | 0 | NA | 0 |
| 1,2-Dibromo-3-chloropropane | 5 U | 5 U | 5 U | 5 U | 5 U | 5 U | 0 | NA | 0 |
| 1,2-Dibromoethane | 5 U | 5 U | 5 U | 5 U | 5 U | 5 U | 0 | NA | 0 |
| 1,2-Dichlorobenzene | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 0 | NA | 0 |
| 1,2-Dichloroethane | 0.67 J | 0.65 J | 0.65 J | 0.61 J | 0.6 J | 0.62 J | 0.63 J | NA | 0.67 J |
| 1,2-Dichloroethene | 4.7 | 4.7 | 4.7 | 4.9 | 4.7 | 5 | 4.8 | NA | 5.0 |
| 1,2-Dichloropropane | 0.21 J | 0.27 J | 1 U | 1 U | 1 U | 0.23 J | 0.24 J | NA | 0.27 J |
| 1,3-Dichlorobenzene | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 0 | NA | 0 |
| 1,3-Dichloropropene | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 0 | NA | 0 |
| 1,4-Dichlorobenzene | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 0 | NA | 0 |
| 2-Butanone (MEK) | 20 U | 20 U | 20 U | 20 U | 20 U | 20 U | 0 | NA | 0 |
| 2-Chloroethylvinylether | 3 U | 3 U | 3 U | 3 U | 3 U | 3 U | 0 | NA | 0 |
| 2-Hexanone | 5 U | 5 U | 5 U | 5 U | 5 U | 5 U | 0 | NA | 0 |
| 4-Methyl-2-pentanone (MIBK) | 5 U | 5 U | 5 U | 5 U | 5 U | 5 U | 0 | NA | 0 |
| Acetone | 20 U | 20 U | 20 U | 20 U | 20 U | 20 U | 0 | NA | 0 |
| Acrolein | 20 U | 20 U | 20 U | 20 U | 20 U | 20 U | 0 | NA | 0 |
| Acrylonitrile | 20 U | 20 U | 20 U | 20 U | 20 U | 20 U | 0 | NA | 0 |
| Benzene | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 0 | NA | 0 |
| Bromodichloromethane | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 0 | NA | 0 |
| Bromoform | 2 U | 2 U | 2 U | 2 U | 2 U | 2 U | 0 | NA | 0 |
| Bromomethane | 2 U | 2 U | 2 U | 2 U | 2 U | 2 U | 0 | NA | 0 |
| Carbon Disulfide | 2 U | 2 U | 2 U | 2 U | 2 U | 2 U | 0 | NA | 0 |
| Carbon Tetrachloride | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 0 | NA | 0 |
| Chlorobenzene | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 0 | NA | 0 |
| Chloroethane | 4 U | 4 U | 4 U | 4 U | 4 U | 4 U | 0 | NA | 0 |
| Chloroform | 0.43 J | 0.39 J | 0.44 J | 0.45 J | 0.41 J | 0.43 J | 0.43 J | NA | 0.45 J |
| Chloromethane | 2 U | 2 U | 2 U | 2 U | 2 U | 2 U | 0 | NA | 0 |
| cis-1,2-Dichloroethene | 4.7 | 4.7 | 4.7 | 4.9 | 4.7 | 5 | 4.8 | NA | 5.0 |
| cis-1,3-Dichloropropene | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 0 | NA | 0 |
| Dibromochloromethane | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 0 | NA | 0 |
| Dibromomethane | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 0 | NA | 0 |
| Dichlorodifluoromethane | 2 U | 2 U | 2 U | 2 U | 2 U | 2 U | 0 | NA | 0 |
| Ethylbenzene | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 0 | NA | 0 |
| Hexane | 2 U | 2 U | 2 U | 2 U | 2 U | 2 U | 0 | NA | 0 |
| Methylene Chloride | 5 U | 5 U | 5 U | 5 U | 5 U | 5 U | 0 | NA | 0 |
| Methyl-t-butyl ether | 5 U | 5 U | 5 U | 5 U | 5 U | 5 U | 0 | NA | 0 |
| m-Xylene & p-Xylene | 2 U | 2 U | 2 U | 2 U | 2 U | 2 U | 0 | NA | 0 |
| Naphthalene | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 0 | NA | 0 |
| o-Xylene | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 0 | NA | 0 |
| Styrene | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 0 | NA | 0 |
| Tetrachloroethene | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 0 | 1500 | 0 |
| Tetrahydrofuran | 7 U | 7 U | 7 U | 7 U | 7 U | 7 U | 0 | NA | 0 |
| Toluene | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 0 | NA | 0 |
| Trans-1,2-Dichloroethene | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 0 | NA | 0 |
| Trans-1,3-Dichloropropene | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 0 | NA | 0 |
| Trichloroethene | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 0 | NA | 0 |
| Trichlorofluoromethane | 2 U | 2 U | 2 U | 2 U | 2 U | 2 U | 0 | NA | 0 |
| Vinyl Acetate | 3 U | 3 U | 3 U | 3 U | 3 U | 3 U | 0 | NA | 0 |
| Vinyl Chloride | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 0 | NA | 0 |
| Xylenes, Total | 2 U | 2 U | 2 U | 2 U | 2 U | 2 U | 0 | NA | 0 |
| Nonylphenol | 4.7 U | 4.8 U | 4.8 U | 4.8 U | 4.9 U | 4.9 U | 0 | NA | 0 |

a/ ug/L = micrograms per liter

b/ NA = Not applicable - No permit limit

Frequency: Quarterly

Methods: Volatile Organic Compounds 8260B

Nonylphenol ASTM D7065

**Qualifiers:** U= The analyte was analyzed for and is not present above the level of the associated value.

The associated numerical value indicates the approximate concentration necessary to detect the analyte in the sample.

J= The analyte was analyzed for, and was positively identified, but the associated numerical value may not be consistent with the amount actually present in the environmental sample.

# APPENDIX A-4.1.3

# COMPLIANCE SUMMARY OF WATER TREATMENT PLANT EFFLUENT (MP-001) WATER QUALITY

## METALS , pH
## AND
## SEMIVOLATILE VOLATILE ORGANIC COMPOUNDS

**APPENDIX A-4.1.3**
**SUMMARY OF TREATMENT PLANT EFFLUENT WATER QUALITY**
**METALS and SEMIVOLATILE ORGANIC COMPOUNDS**

| | | | | MP-001 Sample Date | | | | | |
|---|---|---|---|---|---|---|---|---|---|
| **Compound** | **Units** | **Permit Limit** | **Frequency** | **7/6/2021 and 7/7/2021** | **8/2/2021 and 8/3/2021** | **9/7/2021 and 9/8/2021** | **10/4/2021 and 10/5/2021** | **11/1/2021 and 11/2/2021** | **12/6/2021 and 12/7/2021** |
| 1,2,4-Trichlorobenzene | ug/L[a/] | NA[b/] | Quarterly | 1.3 J | NAn[c/] | NAn | 9.5 U | NAn | NAn |
| 2,4,6-Trichlorophenol | ug/L | NA | Quarterly | 19 U | NAn | NAn | 19 U | NAn | NAn |
| 2,4-Dichlorophenol | ug/L | NA | Quarterly | 9.6 U | NAn | NAn | 9.5 U | NAn | NAn |
| 2,4-Dimethylphenol | ug/L | NA | Quarterly | 9.6 U | NAn | NAn | 9.5 U | NAn | NAn |
| 2,4-Dinitrophenol | ug/L | NA | Quarterly | 57 U | NAn | NAn | 57 U | NAn | NAn |
| 2,4-Dinitrotoluene | ug/L | NA | Quarterly | 9.6 U | NAn | NAn | 9.5 U | NAn | NAn |
| 2,6-Dinitrotoluene | ug/L | NA | Quarterly | 9.6 U | NAn | NAn | 9.5 U | NAn | NAn |
| 2-Chloronaphthalene | ug/L | NA | Quarterly | 1.7 J | NAn | NAn | 9.5 U | NAn | NAn |
| 2-Chlorophenol | ug/L | NA | Quarterly | 9.6 U | NAn | NAn | 9.5 U | NAn | NAn |
| 2-Methylnaphthalene | ug/L | NA | Quarterly | 2.2 J | NAn | NAn | 3.8 U | NAn | NAn |
| 2-Nitrophenol | ug/L | NA | Quarterly | 19 U | NAn | NAn | 19 U | NAn | NAn |
| 3,3'-Dichlorobenzidine | ug/L | NA | Quarterly | 48 U | NAn | NAn | 47 U | NAn | NAn |
| 4,6-Dinitro-2-Methylphenol | ug/L | NA | Quarterly | 57 U | NAn | NAn | 57 U | NAn | NAn |
| 4-Bromophenyl phenyl ether | ug/L | NA | Quarterly | 9.6 U | NAn | NAn | 9.5 U | NAn | NAn |
| 4-Chloro-3-Methylphenol | ug/L | NA | Quarterly | 9.6 U | NAn | NAn | 9.5 U | NAn | NAn |
| 4-Chlorophenyl phenyl ether | ug/L | NA | Quarterly | 9.6 U | NAn | NAn | 9.5 U | NAn | NAn |
| 4-Nitrophenol | ug/L | NA | Quarterly | 48 U | NAn | NAn | 47 U | NAn | NAn |
| Acenaphthene | ug/L | NA | Quarterly | 0.55 J | NAn | NAn | 9.5 U | NAn | NAn |
| Acenaphthylene | ug/L | NA | Quarterly | 9.6 U | NAn | NAn | 9.5 U | NAn | NAn |
| Acetophenone | ug/L | NA | Quarterly | 9.6 U | NAn | NAn | 9.5 U | NAn | NAn |
| Aniline | ug/L | NA | Quarterly | 9.6 U | NAn | NAn | 9.5 U | NAn | NAn |
| Anthracene | ug/L | NA | Quarterly | 9.6 U | NAn | NAn | 9.5 U | NAn | NAn |
| Benzo(a)anthracene | ug/L | NA | Quarterly | 9.6 U | NAn | NAn | 9.5 U | NAn | NAn |
| Benzo(a)pyrene | ug/L | NA | Quarterly | 9.6 U | NAn | NAn | 9.5 U | NAn | NAn |
| Benzo(b)fluoranthene | ug/L | NA | Quarterly | 9.6 U | NAn | NAn | 9.5 U | NAn | NAn |
| Benzo(g,h,i)Perylene | ug/L | NA | Quarterly | 9.6 U | NAn | NAn | 9.5 U | NAn | NAn |
| Benzo(k)fluoranthene | ug/L | NA | Quarterly | 9.6 U | NAn | NAn | 9.5 U | NAn | NAn |
| Benzoic Acid | ug/L | NA | Quarterly | 57 U | NAn | NAn | 57 U | NAn | NAn |
| Bis(2-Chloroethoxy)methane | ug/L | NA | Quarterly | 9.6 U | NAn | NAn | 9.5 U | NAn | NAn |
| Bis(2-Chloroethyl)Ether | ug/L | NA | Quarterly | 9.6 U | NAn | NAn | 9.5 U | NAn | NAn |
| Bis(2-Chloroisopropyl) Ether | ug/L | NA | Quarterly | 9.6 U | NAn | NAn | 9.5 U | NAn | NAn |
| bis(2-Ethylhexyl)phthalate | ug/L | NA | Quarterly | 2 U | NAn | NAn | NAn | 9.5 U | NAn |
| Butyl benzyl phthalate | ug/L | NA | Quarterly | 9.6 U | NAn | NAn | 9.5 U | NAn | NAn |
| C10 | ug/L | NA | Quarterly | 9.6 U | NAn | NAn | 9.5 U | NAn | NAn |
| C18 | ug/L | NA | Quarterly | 9.5 U | NAn | NAn | 9.5 U | NAn | NAn |
| Carbazole | ug/L | NA | Quarterly | 9.6 U | NAn | NAn | 9.5 U | NAn | NAn |
| Chrysene | ug/L | NA | Quarterly | 9.6 U | NAn | NAn | 9.5 U | NAn | NAn |
| Dibenz(a,h)anthracene | ug/L | NA | Quarterly | 9.6 U | NAn | NAn | 9.5 U | NAn | NAn |
| Diethylphthalate | ug/L | NA | Quarterly | 9.6 U | NAn | NAn | 9.5 U | NAn | NAn |
| Dimethylphthalate | ug/L | NA | Quarterly | 9.6 U | NAn | NAn | 9.5 U | NAn | NAn |
| Di-N-Butylphthalate | ug/L | NA | Quarterly | 9.6 U | NAn | NAn | 9.5 U | NAn | NAn |
| Di-n-octylphthalate | ug/L | NA | Quarterly | 9.6 U | NAn | NAn | 9.5 U | NAn | NAn |
| Fluoranthene | ug/L | NA | Quarterly | 9.6 U | NAn | NAn | 9.5 U | NAn | NAn |
| Fluorene | ug/L | NA | Quarterly | 9.6 U | NAn | NAn | 9.5 U | NAn | NAn |
| Hexachlorobenzene | ug/L | NA | Quarterly | 9.6 U | NAn | NAn | 9.5 U | NAn | NAn |
| Hexachlorobutadiene | ug/L | NA | Quarterly | 9.6 U | NAn | NAn | 9.5 U | NAn | NAn |
| Hexachlorocyclopentadiene | ug/L | NA | Quarterly | 48 U | NAn | NAn | 47 U | NAn | NAn |
| Hexachloroethane | ug/L | NA | Quarterly | 9.6 U | NAn | NAn | 9.5 U | NAn | NAn |

| Compound | Units | Permit Limit | Frequency | 7/6/2021 and 7/7/2021 | 8/2/2021 and 8/3/2021 | 9/7/2021 and 9/8/2021 | 10/4/2021 and 10/5/2021 | 11/1/2021 and 11/2/2021 | 12/6/2021 and 12/7/2021 |
|---|---|---|---|---|---|---|---|---|---|
| Indeno(1,2,3-c,d)pyrene | ug/L | NA | Quarterly | 9.6 U | NAn | NAn | 9.5 U | NAn | NAn |
| Isophorone | ug/L | NA | Quarterly | 9.6 U | NAn | NAn | 9.5 U | NAn | NAn |
| Naphthalene | ug/L | NA | Quarterly | 1.1 J | NAn | NAn | 9.5 U | NAn | NAn |
| Nitrobenzene | ug/L | NA | Quarterly | 9.6 U | NAn | NAn | 9.5 U | NAn | NAn |
| N-Nitrosodimethylamine | ug/L | NA | Quarterly | 9.6 U | NAn | NAn | 9.5 U | NAn | NAn |
| N-Nitroso-Di-N-Propylamine | ug/L | NA | Quarterly | 9.6 U | NAn | NAn | 9.5 U | NAn | NAn |
| N-Nitrosodiphenylamine | ug/L | NA | Quarterly | 9.6 U | NAn | NAn | 9.5 U | NAn | NAn |
| Pentachlorophenol | ug/L | NA | Quarterly | 57 U | NAn | NAn | 57 U | NAn | NAn |
| Phenanthrene | ug/L | NA | Quarterly | 9.6 U | NAn | NAn | 9.5 U | NAn | NAn |
| Phenol | ug/L | NA | Quarterly | 9.6 U | NAn | NAn | 9.5 U | NAn | NAn |
| Pyrene | ug/L | NA | Quarterly | 9.6 U | NAn | NAn | 9.5 U | NAn | NAn |
| Pyridine | ug/L | NA | Quarterly | 19 U | NAn | NAn | 19 U | NAn | NAn |
| Molybdenum | ug/L | 430 | Monthly | 12 | 12 | 20 | 19 | 19 | 14 |
| Selenium | ug/L | 660 | Quarterly | 15 | NAn | NAn | 16 | NAn | NAn |
| Zinc | ug/L | 15600 | Quarterly | 2.6 J | NAn | NAn | 2.4 J | NAn | NAn |
| pH | pH Units | >5 | Monthly | 6.85 | 6.75 | 6.86 | 6.75 | 6.77 | 6.91 |

a/ ug/L = micrograms per liter

b/ NA = Not applicable - No permit limit

c/ Nan = Not analyzed

**Qualifiers:** U= The analyte was analyzed for and is not present above the level of the associated value.
The associated numerical value indicates the approximate concentration necessary to detect the analyte in the sample.

UJ= The analyte analyzed for was not present above the level of the associated value. The associated numerical value may not accurately represent the concentration necessary to detect the analyte in the sample.

UJ-= Same as UJ qualification but with an indication of negative bias in the sample concentration.

UJ+= Same as UJ qualification but with an indication of positive bias in the sample concentration.

J= The analyte was analyzed for, and was positively identified, but the associated numerical value may not be consistent with the amount actually present in the environmental sample.

J-= Same as J qualification but with an indication of negative bias in the sample concentration.

J+= Same as J qualification but with an indication of positive bias in the sample concentration.

# APPENDIX A-4.1.4

# COMPLIANCE SUMMARY OF WATER TREATMENT PLANT EFFLUENT (MP-001) WATER QUALITY RADIONUCLIDES

## APPENDIX A-4.1.4
## SUMMARY OF TREATMENT PLANT EFFLUENT WATER QUALITY
## RADIONUCLIDES (MP-001)

| Isotope | | Conc (pCi/L)[b/] | FINAL Q | MDC[c/] | CSU[d/] | Result minus CSU | Daily Maximum Value (pCi/L) | Permit Limit (pCi/L) |
|---|---|---|---|---|---|---|---|---|
| Americium-241 | 7/6 and 7/7/2021[a/] | 0.041 | J | 0.058 | 0.04 | -0.001 | -0.001 | NA[e/] |
| Alpha, Gross | 7/6 and 7/7/2021 | 8.22 | UJ+ | 19.1 | 5.81 | 2.41 | 2.41 | NA |
| Beta, Gross | 7/6 and 7/7/2021 | 11.3 | U | 14.8 | 4.69 | 6.61 | 6.61 | NA |
| Plutonium-238 | 7/6 and 7/7/2021 | 0.025 | UJ | 0.063 | 0.04 | -0.013 | -0.013 | NA |
| Plutonium-239/240 | 7/6 and 7/7/2021 | 0.011 | UJ | 0.071 | 0.03 | -0.022 | -0.022 | NA |
| Radium-226 | 7/6 and 7/7/2021 | -0.16 | U | 0.4 | 0.15 | -0.3 | -0.3 | NA |
| Radium-228 | 7/6 and 7/7/2021 | 0.86 | J | 0.96 | 0.53 | 0.33 | 0.33 | NA |
| Total Radium | 7/6 and 7/7/2021 | 0.23 | U | 0.25 | 0.13 | 0.096 | 0.096 | NA |
| Americium-241 | 10/4 and 10/5/2021[a/] | 0.15 | J | 0.18 | 0.14 | 0.012 | 0.012 | NA |
| Alpha, Gross | 10/4 and 10/5/2021 | 14.24 | UJ+ | 14.04 | 5.17 | 9.07 | 9.07 | NA |
| Beta, Gross | 10/4 and 10/5/2021 | 19.07 | U | 13.62 | 5.07 | 14 | 14 | NA |
| Plutonium-238 | 10/4 and 10/5/2021 | -0.016 | UJ | 0.083 | 0.03 | -0.043 | -0.043 | NA |
| Plutonium-239/240 | 10/4 and 10/5/2021 | -0.008 | UJ+ | 0.068 | 0.03 | -0.033 | -0.033 | NA |
| Radium-226 | 10/4 and 10/5/2021 | 0.17 | J | 0.413 | 0.25 | -0.074 | -0.074 | NA |
| Radium-228 | 10/4 and 10/5/2021 | 0.49 | J | 0.75 | 0.39 | 0.095 | 0.095 | NA |
| Total Radium | 10/4 and 10/5/2021 | 0.44 | U | 0.28 | 0.19 | 0.25 | 0.25 | NA |

a/ Duration of test - 24 hours beginning 08:00 a.m.and ending 08:00 a.m on the next day

b/ picoCuries per liter

c/ minimum detectable concentration

d/ Combined standard uncertainty

e/ NA = Not applicable - No permit limit

**Qualifiers:** U= The analyte was analyzed for and is not present above the level of the associated value.
The associated numerical value indicates the approximate concentration necessary to detect the analyte in the sample.

UJ= The analyte analyzed for was not present above the level of the associated value. The associated numerical value may not accurately represent the concentration necessary to detect the analyte in the sample.

UJ-= Same as UJ qualification but with an indication of negative bias in the sample concentration.

UJ+= Same as UJ qualification but with an indication of positive bias in the sample concentration.

J= The analyte was analyzed for, and was positively identified, but the associated numerical value may not be consistent with the amount actually present in the environmental sample.

J-= Same as J qualification but with an indication of negative bias in the sample concentration.

J+= Same as J qualification but with an indication of positive bias in the sample concentration.

# APPENDIX A-4.2

# SUMMARY OF TREATMENT PLANT EARLY WARNING INFLUENT WATER QUALITY

# APPENDIX A-4.2.1

# SUMMARY OF TREATMENT PLANT EARLY WARNING INFLUENT WATER QUALITY

# (VOLATILE ORGANIC COMPOUNDS)

# INDIVIDUAL AND COMPOSITE DATA

**APPENDIX A-4.2.1**
**SUMMARY OF TREATMENT PLANT EARLY WARNING INFLUENT WATER QUALITY**
**(Volatile Organic Compounds)**
**JULY THROUGH DECEMBER 2021 OPERATIONS AND MAINTENANCE STATUS REPORT**
**LOWRY LANDFILL SUPERFUND SITE**

| | Date→ | | 7/6/2021 | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|
| | | | INFLUENT SOURCE CONCENTRATIONS | | | | | | | |
| | Sample Port→ | | TP-110[a/] | TP-120[b/] | TP-140[c/] | TP-150[d/] | TP-160[e/] | TP-170[f/] | TP3310[g/] | |
| | % of Flow ► | | 1.7% | 21.5% | 6.8% | 37.6% | 24.0% | 5.6% | 2.8% | |
| **Parameter Name** | **Permit Limit[h/]** | **Units** | | | | | | | | **Composite Concentration** |
| 1,1,1,2-Tetrachloroethane | NA[i/] | ug/L[j/] | < 0.4 | < 2 | < 0.2 | < 0.2 | < 0.2 | < 0.2 | < 20 | 0 |
| 1,1,1-Trichloroethane | NA | ug/L | 12 | 57 | 0.77 | 2.1 | < 0.2 | < 0.2 | < 20 | 13.3 |
| 1,1,2,2-Tetrachloroethane | NA | ug/L | < 0.25 | < 1.2 | < 0.12 | < 0.12 | < 0.12 | < 0.12 | < 12 | 0 |
| 1,1,2-Trichloroethane | NA | ug/L | < 0.46 | < 2.3 | < 0.23 | < 0.23 | < 0.23 | < 0.23 | < 23 | 0 |
| 1,1-Dichloroethane | NA | ug/L | 41 | 190 | 12 | 4.6 | < 0.2 | 0.88 | 43 | 45.35 |
| 1,1-Dichloroethene | NA | ug/L | 11 | 54 | 0.62 | 3.2 | < 0.24 | < 0.24 | < 24 | 13.04 |
| 1,2,3-Trichloropropane | NA | ug/L | < 0.59 | < 2.9 | < 0.29 | < 0.29 | < 0.29 | < 0.29 | < 29 | 0 |
| 1,2-Dibromo-3-chloropropane | NA | ug/L | < 0.76 | < 3.8 | < 0.38 | < 0.38 | < 0.38 | < 0.38 | < 38 | 0 |
| 1,2-Dibromoethane | NA | ug/L | < 0.43 | < 2.2 | < 0.22 | < 0.22 | < 0.22 | < 0.22 | < 22 | 0 |
| 1,2-Dichlorobenzene | NA | ug/L | < 0.34 | < 1.7 | < 0.17 | < 0.17 | < 0.17 | < 0.17 | < 17 | 0 |
| 1,2-Dichloroethane | NA | ug/L | 5.3 | < 1.7 | 0.6 | < 0.17 | < 0.17 | < 0.17 | 1900 | 53.3 |
| 1,2-Dichloroethene | NA | ug/L | 150 | 730 | 4.1 | 10 | < 0.15 | 0.19 | < 15 | 163 |
| 1,2-Dichloropropane | NA | ug/L | < 0.36 | < 1.8 | < 0.18 | < 0.18 | < 0.18 | < 0.18 | < 18 | 0 |
| 1,3-Dichlorobenzene | NA | ug/L | < 0.33 | < 1.6 | < 0.16 | < 0.16 | < 0.16 | < 0.16 | < 16 | 0 |
| 1,3-Dichloropropene | NA | ug/L | < 0.28 | < 1.4 | < 0.14 | < 0.14 | < 0.14 | < 0.14 | < 14 | 0 |
| 1,4-Dichlorobenzene | NA | ug/L | < 0.31 | < 1.6 | < 0.16 | < 0.16 | < 0.16 | < 0.16 | < 16 | 0 |
| 2-Butanone (MEK) | NA | ug/L | < 2.9 | < 14 | < 1.4 | < 1.4 | < 1.4 | < 1.4 | 2100 | 58.8 |
| 2-Chloroethylvinylether | NA | ug/L | < 0.42 | < 2.1 | < 0.21 | < 0.21 | < 0.21 | < 0.21 | < 21 | 0 |
| 2-Hexanone | NA | ug/L | < 0.84 | < 4.2 | < 0.42 | < 0.42 | < 0.42 | < 0.42 | < 42 | 0 |
| 4-Methyl-2-pentanone (MIBK) | NA | ug/L | < 0.93 | < 4.6 | < 0.46 | < 0.46 | < 0.46 | < 0.46 | < 46 | 0 |
| Acetone | NA | ug/L | < 16 | < 80 | < 8 | < 8 | < 8 | < 8 | 2600 | 72.8 |
| Acrolein | NA | ug/L | < 3.6 | < 18 | < 1.8 | < 1.8 | < 1.8 | < 1.8 | < 180 | 0 |
| Acrylonitrile | NA | ug/L | < 2.2 | < 11 | < 1.1 | < 1.1 | < 1.1 | < 1.1 | < 110 | 0 |
| Benzene | NA | ug/L | < 0.36 | < 1.8 | < 0.18 | < 0.18 | < 0.18 | < 0.18 | 660 | 18.48 |
| Bromodichloromethane | NA | ug/L | < 0.31 | < 1.5 | < 0.15 | < 0.15 | < 0.15 | < 0.15 | < 15 | 0 |
| Bromoform | NA | ug/L | < 1.3 | < 6.7 | < 0.67 | < 0.67 | < 0.67 | < 0.67 | < 67 | 0 |
| Bromomethane | NA | ug/L | < 2.2 | < 11 | < 1.1 | < 1.1 | < 1.1 | < 1.1 | < 110 | 0 |
| Carbon Disulfide | NA | ug/L | < 0.64 | < 3.2 | < 0.32 | < 0.32 | < 0.32 | < 0.32 | < 32 | 0 |
| Carbon Tetrachloride | NA | ug/L | < 0.48 | < 2.4 | < 0.24 | < 0.24 | < 0.24 | < 0.24 | < 24 | 0 |
| Chlorobenzene | NA | ug/L | < 0.35 | < 1.8 | < 0.18 | < 0.18 | < 0.18 | < 0.18 | < 18 | 0 |
| Chloroethane | NA | ug/L | < 0.71 | < 3.6 | < 0.36 | < 0.36 | < 0.36 | < 0.36 | 130 | 3.64 |
| Chloroform | NA | ug/L | 0.84 | 2.8 | 5.5 | < 0.22 | < 0.22 | < 0.22 | < 22 | 0.99 |
| Chloromethane | NA | ug/L | < 1.1 | < 5.7 | < 0.57 | < 0.57 | < 0.57 | < 0.57 | < 57 | 0 |
| cis-1,2-Dichloroethene | NA | ug/L | 150 | 730 | 4.1 | 10 | < 0.15 | 0.19 | < 15 | 163 |
| cis-1,3-Dichloropropene | NA | ug/L | < 0.28 | < 1.4 | < 0.14 | < 0.14 | < 0.14 | < 0.14 | < 14 | 0 |
| Dibromochloromethane | NA | ug/L | < 0.43 | < 2.1 | < 0.21 | < 0.21 | < 0.21 | < 0.21 | < 21 | 0 |
| Dibromomethane | NA | ug/L | < 0.24 | < 1.2 | < 0.12 | < 0.12 | < 0.12 | < 0.12 | < 12 | 0 |
| Dichlorodifluoromethane | NA | ug/L | < 0.69 | < 3.5 | < 0.35 | < 0.35 | < 0.35 | < 0.35 | < 35 | 0 |
| Ethylbenzene | NA | ug/L | < 0.36 | < 1.8 | < 0.18 | < 0.18 | < 0.18 | < 0.18 | 130 | 3.64 |
| Hexane | NA | ug/L | < 0.52 | < 2.6 | < 0.26 | < 0.26 | < 0.26 | < 0.26 | < 26 | 0 |
| Methylene Chloride | NA | ug/L | < 0.35 | 1.9 | < 0.17 | < 0.17 | < 0.17 | < 0.17 | 21 | 1 |
| Methyl-t-butyl ether | NA | ug/L | 1.3 | < 1.6 | < 0.16 | < 0.16 | < 0.16 | < 0.16 | < 16 | 0.022 |
| m-Xylene & p-Xylene | NA | ug/L | < 0.41 | < 2 | < 0.2 | < 0.2 | < 0.2 | < 0.2 | 120 | 3.36 |
| Naphthalene | NA | ug/L | < 0.21 | < 1 | < 0.1 | < 0.1 | < 0.1 | < 0.1 | < 10 | 0 |
| o-Xylene | NA | ug/L | < 0.42 | < 2.1 | < 0.21 | < 0.21 | < 0.21 | < 0.21 | 62 | 1.74 |
| Styrene | NA | ug/L | < 0.43 | < 2.2 | < 0.22 | < 0.22 | < 0.22 | < 0.22 | < 22 | 0 |
| Tetrachloroethene | 1500 | ug/L | 2.5 | 9.2 | 1.3 | 1.2 | < 0.19 | < 0.19 | < 19 | 2.56 |
| Tetrahydrofuran | NA | ug/L | < 1.1 | < 5.3 | < 0.53 | < 0.53 | < 0.53 | < 0.53 | 17000 | 476 |
| Toluene | NA | ug/L | < 0.48 | < 2.4 | < 0.24 | < 0.24 | < 0.24 | < 0.24 | < 24 | 0 |
| Trans-1,2-Dichloroethene | NA | ug/L | < 0.42 | < 2.1 | < 0.21 | < 0.21 | < 0.21 | < 0.21 | < 21 | 0 |
| Trans-1,3-Dichloropropene | NA | ug/L | < 0.35 | < 1.8 | < 0.18 | < 0.18 | < 0.18 | < 0.18 | < 18 | 0 |
| Trichloroethene | NA | ug/L | 1.5 | 5.3 | 3.8 | 0.41 | < 0.18 | < 0.18 | < 18 | 1.58 |
| Trichlorofluoromethane | NA | ug/L | < 0.41 | < 2 | < 0.2 | < 0.2 | < 0.2 | < 0.2 | < 20 | 0 |
| Vinyl Acetate | NA | ug/L | < 1.9 | < 9.4 | < 0.94 | < 0.94 | < 0.94 | < 0.94 | < 94 | 0 |
| Vinyl Chloride | NA | ug/L | < 0.56 | < 2.8 | < 0.28 | < 0.28 | < 0.28 | < 0.28 | < 28 | 0 |
| Xylenes, Total | NA | ug/L | < 0.41 | < 2 | < 0.2 | < 0.2 | < 0.2 | < 0.2 | 180 | 5.04 |

**APPENDIX A-4.2.1**
**SUMMARY OF TREATMENT PLANT EARLY WARNING INFLUENT WATER QUALITY**
**(Volatile Organic Compounds)**
**JULY THROUGH DECEMBER 2021 OPERATIONS AND MAINTENANCE STATUS REPORT**
**LOWRY LANDFILL SUPERFUND SITE**

| | Date→ | | 10/4/2021 | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|
| | | | INFLUENT SOURCE CONCENTRATIONS | | | | | | | |
| | Sample Port→ | | TP-110[a/] | TP-120[b/] | TP-140[c/] | TP-150[d/] | TP-160[e/] | TP-170[f/] | TP3310[g/] | |
| | % of Flow ► | | 1.7% | 19.9% | 6.2% | 37.0% | 23.2% | 9.2% | 2.8% | |
| **Parameter Name** | **Permit Limit[h/]** | **Units** | | | | | | | | **Composite Concentration** |
| | | | | | | | | | | |
| 1,1,1,2-Tetrachloroethane | NA[i/] | ug/L[j/] | < 0.2 | < 2 | < 0.2 | < 0.2 | < 0.2 | < 0.2 | < 20 | 0 |
| 1,1,1-Trichloroethane | NA | ug/L | 13 | 80 | 0.27 | 1.7 | < 0.2 | < 0.2 | < 20 | 16.79 |
| 1,1,2,2-Tetrachloroethane | NA | ug/L | < 0.12 | < 1.2 | < 0.12 | < 0.12 | < 0.12 | < 0.12 | < 12 | 0 |
| 1,1,2-Trichloroethane | NA | ug/L | 0.25 | < 2.3 | < 0.23 | < 0.23 | < 0.23 | < 0.23 | < 23 | 0.0043 |
| 1,1-Dichloroethane | NA | ug/L | 41 | 220 | 12 | 4.1 | < 0.2 | 0.92 | 140 | 50.74 |
| 1,1-Dichloroethene | NA | ug/L | 12 | 71 | 0.33 | 3.2 | < 0.24 | < 0.24 | < 24 | 15.54 |
| 1,2,3-Trichloropropane | NA | ug/L | < 0.29 | < 2.9 | < 0.29 | < 0.29 | < 0.29 | < 0.29 | < 29 | 0 |
| 1,2-Dibromo-3-chloropropane | NA | ug/L | < 0.38 | < 3.8 | < 0.38 | < 0.38 | < 0.38 | < 0.38 | < 38 | 0 |
| 1,2-Dibromoethane | NA | ug/L | < 0.22 | < 2.2 | < 0.22 | < 0.22 | < 0.22 | < 0.22 | < 22 | 0 |
| 1,2-Dichlorobenzene | NA | ug/L | < 0.17 | < 1.7 | < 0.17 | < 0.17 | < 0.17 | < 0.17 | < 17 | 0 |
| 1,2-Dichloroethane | NA | ug/L | 3.8 | 3.3 | 0.7 | 0.17 | < 0.17 | < 0.17 | 3500 | 102 |
| 1,2-Dichloroethene | NA | ug/L | 140 | 840 | 3.8 | 9.6 | < 0.15 | 0.28 | 39 | 174 |
| 1,2-Dichloropropane | NA | ug/L | 0.56 | 3.1 | < 0.18 | < 0.18 | < 0.18 | < 0.18 | < 18 | 0.63 |
| 1,3-Dichlorobenzene | NA | ug/L | < 0.16 | < 1.6 | < 0.16 | < 0.16 | < 0.16 | < 0.16 | < 16 | 0 |
| 1,3-Dichloropropene | NA | ug/L | < 0.14 | < 1.4 | < 0.14 | < 0.14 | < 0.14 | < 0.14 | < 14 | 0 |
| 1,4-Dichlorobenzene | NA | ug/L | < 0.16 | < 1.6 | < 0.16 | < 0.16 | < 0.16 | < 0.16 | < 16 | 0 |
| 2-Butanone (MEK) | NA | ug/L | < 1.4 | < 14 | < 1.4 | < 1.4 | < 1.4 | < 1.4 | 910 | 25.48 |
| 2-Chloroethylvinylether | NA | ug/L | < 0.21 | < 2.1 | < 0.21 | < 0.21 | < 0.21 | < 0.21 | < 21 | 0 |
| 2-Hexanone | NA | ug/L | < 0.42 | < 4.2 | < 0.42 | < 0.42 | < 0.42 | < 0.42 | < 42 | 0 |
| 4-Methyl-2-pentanone (MIBK) | NA | ug/L | < 0.46 | < 4.6 | < 0.46 | < 0.46 | < 0.46 | < 0.46 | < 46 | 0 |
| Acetone | NA | ug/L | < 8 | < 80 | < 8 | < 8 | < 8 | < 8 | 1300 | 36.4 |
| Acrolein | NA | ug/L | < 1.8 | < 18 | < 1.8 | < 1.8 | < 1.8 | < 1.8 | < 180 | 0 |
| Acrylonitrile | NA | ug/L | < 1.1 | < 11 | < 1.1 | < 1.1 | < 1.1 | < 1.1 | < 110 | 0 |
| Benzene | NA | ug/L | < 0.18 | < 1.8 | < 0.18 | < 0.18 | < 0.18 | < 0.18 | 770 | 21.56 |
| Bromodichloromethane | NA | ug/L | < 0.15 | < 1.5 | < 0.15 | < 0.15 | < 0.15 | < 0.15 | < 15 | 0 |
| Bromoform | NA | ug/L | < 0.67 | < 6.7 | < 0.67 | < 0.67 | < 0.67 | < 0.67 | < 67 | 0 |
| Bromomethane | NA | ug/L | < 1.1 | < 11 | < 1.1 | < 1.1 | < 1.1 | < 1.1 | < 110 | 0 |
| Carbon Disulfide | NA | ug/L | < 0.32 | < 3.2 | < 0.32 | < 0.32 | < 0.32 | < 0.32 | < 32 | 0 |
| Carbon Tetrachloride | NA | ug/L | < 0.24 | < 2.4 | < 0.24 | < 0.24 | < 0.24 | < 0.24 | < 24 | 0 |
| Chlorobenzene | NA | ug/L | < 0.18 | < 1.8 | < 0.18 | < 0.18 | < 0.18 | < 0.18 | < 18 | 0 |
| Chloroethane | NA | ug/L | < 0.36 | < 3.6 | < 0.36 | < 0.36 | < 0.36 | < 0.36 | 140 | 3.92 |
| Chloroform | NA | ug/L | 0.62 | 2.2 | 4.8 | < 0.22 | < 0.22 | < 0.22 | < 22 | 0.75 |
| Chloromethane | NA | ug/L | < 0.57 | < 5.7 | < 0.57 | < 0.57 | < 0.57 | < 0.57 | < 57 | 0 |
| cis-1,2-Dichloroethene | NA | ug/L | 140 | 840 | 3.8 | 9.6 | < 0.15 | 0.28 | 39 | 174 |
| cis-1,3-Dichloropropene | NA | ug/L | < 0.14 | < 1.4 | < 0.14 | < 0.14 | < 0.14 | < 0.14 | < 14 | 0 |
| Dibromochloromethane | NA | ug/L | < 0.21 | < 2.1 | < 0.21 | < 0.21 | < 0.21 | < 0.21 | < 21 | 0 |
| Dibromomethane | NA | ug/L | < 0.12 | < 1.2 | < 0.12 | < 0.12 | < 0.12 | < 0.12 | < 12 | 0 |
| Dichlorodifluoromethane | NA | ug/L | 0.77 | < 3.5 | 0.46 | < 0.35 | < 0.35 | < 0.35 | < 35 | 0.041 |
| Ethylbenzene | NA | ug/L | < 0.18 | < 1.8 | < 0.18 | < 0.18 | < 0.18 | < 0.18 | 170 | 4.76 |
| Hexane | NA | ug/L | < 0.26 | < 2.6 | < 0.26 | < 0.26 | < 0.26 | < 0.26 | < 26 | 0 |
| Methylene Chloride | NA | ug/L | < 0.17 | < 1.7 | < 0.17 | < 0.17 | < 0.17 | < 0.17 | < 17 | 0 |
| Methyl-t-butyl ether | NA | ug/L | 1.5 | < 1.6 | < 0.16 | < 0.16 | < 0.16 | < 0.16 | < 16 | 0.026 |
| m-Xylene & p-Xylene | NA | ug/L | < 0.2 | < 2 | < 0.2 | < 0.2 | < 0.2 | < 0.2 | 140 | 3.92 |
| Naphthalene | NA | ug/L | < 0.1 | < 1 | < 0.1 | < 0.1 | < 0.1 | < 0.1 | < 10 | 0 |
| o-Xylene | NA | ug/L | < 0.21 | < 2.1 | < 0.21 | < 0.21 | < 0.21 | < 0.21 | 87 | 2.44 |
| Styrene | NA | ug/L | < 0.22 | < 2.2 | < 0.22 | < 0.22 | < 0.22 | < 0.22 | < 22 | 0 |
| Tetrachloroethene | 1500 | ug/L | 2.6 | 12 | 1.3 | 1.1 | < 0.19 | < 0.19 | < 19 | 2.92 |
| Tetrahydrofuran | NA | ug/L | < 0.53 | < 5.3 | < 0.53 | < 0.53 | < 0.53 | < 0.53 | 20000 | 560 |
| Toluene | NA | ug/L | < 0.24 | < 2.4 | < 0.24 | < 0.24 | < 0.24 | < 0.24 | 43 | 1.2 |
| Trans-1,2-Dichloroethene | NA | ug/L | 0.47 | 2.2 | < 0.21 | < 0.21 | < 0.21 | < 0.21 | < 21 | 0.45 |
| Trans-1,3-Dichloropropene | NA | ug/L | < 0.18 | < 1.8 | < 0.18 | < 0.18 | < 0.18 | < 0.18 | < 18 | 0 |
| Trichloroethene | NA | ug/L | 1.6 | 7 | 3.6 | 0.38 | < 0.18 | < 0.18 | < 18 | 1.78 |
| Trichlorofluoromethane | NA | ug/L | < 0.2 | < 2 | < 0.2 | < 0.2 | < 0.2 | < 0.2 | < 20 | 0 |
| Vinyl Acetate | NA | ug/L | < 0.94 | < 9.4 | < 0.94 | < 0.94 | < 0.94 | < 0.94 | < 94 | 0 |
| Vinyl Chloride | NA | ug/L | < 0.28 | < 2.8 | < 0.28 | < 0.28 | < 0.28 | < 0.28 | 42 | 1.18 |
| Xylenes, Total | NA | ug/L | < 0.2 | < 2 | < 0.2 | < 0.2 | < 0.2 | < 0.2 | 230 | 6.44 |

Footnotes:

a/ RWST - Raw Water Storage Tank water

b/ NBBW - North Boundary Barrier Wall water

c/ MW38 Area water

d/ North End On-Site water

e/ North End Off-Site water

f/ MW113 Area water

g/ BTS Tank 3310 influent is comprised of North Toe Extraction System water and Landfill Gas Condensate

h/ Permit Limit - limit in ug/L for tetrachloroethene and pounds per day for 1,4-dioxane in discharge according to Industrial Discharge Permit No. 2360-6 issued by the Metro Wastewater Reclamation District (Metro), effective January 5, 2020.

i/ NA - Not Applicable - no limit listed in the Metro permit

j/ µg/L - micrograms per liter

# APPENDIX A-4.2.2

# SUMMARY OF TREATMENT PLANT EARLY WARNING INFLUENT WATER QUALITY

# (1,4-DIOXANE)

# APPENDIX A-4.2.2.1

# SUMMARY OF TREATMENT PLANT EARLY WARNING INFLUENT WATER QUALITY

# (1,4-DIOXANE)

# INDIVIDUAL AND COMPOSITE RESULTS

# APPENDIX A-4.2.2.1
# SUMMARY OF EARLY WARNING INFLUENT WATER QUALITY
## 1,4-Dioxane
### JULY THROUGH DECEMBER 2021 OPERATIONS AND MAINTENANCE STATUS REPORT
### LOWRY LANDFILL SUPERFUND SITE

| Date→ | 7/6/2021 | 7/6/2021 | 7/6/2021 | 7/6/2021 | 7/6/2021 | 7/6/2021 | 7/6/2021 | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|
| % of Flow→ | 1.7% | 21.5% | 6.8% | 37.6% | 24.0% | 5.6% | 2.8% | | | | |
| Sample Port→ | TP-110[a/] | TP-120[b/] | TP-140[c/] | TP-150[d/] | TP-160[e/] | TP-170[f/] | TP3310[g/] | | | | |
| Compound | Conc (ug/L[h/]) | Conc (ug/L) | Conc (ug/L) | Conc (ug/L) | Conc (ug/L) | Conc (ug/L) | Conc (ug/L) | Composite Conc (ug/L) | gpm[i/] | Total (lbs/day[j/]) | Permit Limit[k/] |
| 1,4-Dioxane[l/] | 210 | 750 | 22 | 15 | 1.7 | 97 | 19000 | 710 | 35.4 | 0.30 | 0.032 |

| Date→ | 8/2/2021 | 8/2/2021 | 8/2/2021 | 8/2/2021 | 8/2/2021 | 8/2/2021 | 8/2/2021 | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|
| % of Flow→ | 1.7% | 21.8% | 6.3% | 37.9% | 23.6% | 5.7% | 2.9% | | | | |
| Sample Port→ | TP-110 | TP-120 | TP-140 | TP-150 | TP-160 | TP-170 | TP3310 | | | | |
| Compound | Conc (ug/L) | Conc (ug/L) | Conc (ug/L) | Conc (ug/L) | Conc (ug/L) | Conc (ug/L) | Conc (ug/L) | Composite Conc (ug/L) | gpm | Total (lbs/day) | Permit Limit (lbs/day) |
| 1,4-Dioxane | 290 | 750 | 23 | 23 | 1.8 | 100 | 18000 | 707.00 | 34.8 | 0.30 | 0.032 |

| Date→ | 9/7/2021 | 9/7/2021 | 9/7/2021 | 9/7/2021 | 9/7/2021 | 9/7/2021 | 9/7/2021 | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|
| % of Flow→ | 1.7% | 20.3% | 6.1% | 36.1% | 22.8% | 10.3% | 2.8% | | | | |
| Sample Port→ | TP-110 | TP-120 | TP-140 | TP-150 | TP-160 | TP-170[l/] | TP3310 | | | | |
| Compound | Conc (ug/L) | Conc (ug/L) | Conc (ug/L) | Conc (ug/L) | Conc (ug/L) | Conc (ug/L) | Conc (ug/L) | Composite Conc (ug/L) | gpm | Total (lbs/day) | Permit Limit (lbs/day) |
| 1,4-Dioxane | 230 | 700 | 21 | 14 | 0.72 | 92 | 16000 | 610.00 | 36 | 0.26 | 0.032 |

| Date→ | 10/4/2021 | 10/4/2021 | 10/4/2021 | 10/4/2021 | 10/4/2021 | 10/4/2021 | 10/4/2021 | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|
| % of Flow→ | 1.7% | 19.9% | 6.2% | 37.0% | 23.2% | 9.2% | 2.8% | | | | |
| Sample Port→ | TP-110 | TP-120 | TP-140 | TP-150 | TP-160 | TP-170 | TP3310 | | | | |
| Compound | Conc (ug/L) | Conc (ug/L) | Conc (ug/L) | Conc (ug/L) | Conc (ug/L) | Conc (ug/L) | Conc (ug/L) | Composite Conc (ug/L) | gpm | Total (lbs/day) | Permit Limit (lbs/day) |
| 1,4-Dioxane | 210 | 820 | 18 | 16 | 1.5 | 100 | 15000 | 603 | 35.7 | 0.26 | 0.032 |

## APPENDIX A-4.2.2.1
## SUMMARY OF EARLY WARNING INFLUENT WATER QUALITY
## 1,4-Dioxane

| Date→ | 11/1/2021 | 11/1/2021 | 11/1/2021 | 11/1/2021 | 11/1/2021 | 11/1/2021 | 11/1/2021 | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|
| % of Flow→ | 3.4% | 19.3% | 6.0% | 36.6% | 23.0% | 8.8% | 2.8% | | | | |
| Sample Port→ | TP-110 | TP-120 | TP-140 | TP-150 | TP-160 | TP-170 | TP3310 | | | | |
| Compound | Conc (ug/L) | Conc (ug/L) | Conc (ug/L) | Conc (ug/L) | Conc (ug/L) | Conc (ug/L) | Conc (ug/L) | Composite Conc (ug/L) | gpm | Total (lbs/day) | Permit Limit (lbs/day) |
| 1,4-Dioxane | 310 | 700 | 20 | 12 | 1.3 | 120 | 17000 | 638.00 | 35.2 | 0.27 | 0.032 |

| Date→ | 12/6/2021 | 12/6/2021 | 12/6/2021 | 12/6/2021 | 12/6/2021 | 12/6/2021 | 12/6/2021 | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|
| % of Flow→ | 1.8% | 19.7% | 6.0% | 37.6% | 25.7% | 6.3% | 3.0% | | | | |
| Sample Port→ | TP-110 | TP-120 | TP-140 | TP-150 | TP-160 | TP-170 | TP3310 | | | | |
| Compound | Conc (ug/L) | Conc (ug/L) | Conc (ug/L) | Conc (ug/L) | Conc (ug/L) | Conc (ug/L) | Conc (ug/L) | Composite Conc (ug/L) | gpm | Total (lbs/day) | Permit Limit (lbs/day) |
| 1,4-Dioxane | 320 | 860 | 18 | 13 | 1.9 | 120 | 18000 | 729 | 33.5 | 0.29 | 0.032 |

Footnotes:

a/ RWST - Raw Water Storage Tank water

b/ NBBW - North Boundary Barrier Wall water

c/ MW38 Area water

d/ North End On-Site water

e/ North End Off-Site water

f/ MW113 Area water

g/ BTS Tank 3310 influent is comprised of North Toe Extraction System water and Landfill Gas Condensate

h/ ug/L = micrograms per liter

i/ gpm = gallons per minute

j/ lbs/day = pounds per day

k/ Permit Limit - limit in ug/L for discharge according to Industrial Discharge Permit No. 2360-6 issued by the Metro Wastewater Reclamation District (Metro), effective January 5, 2020.

l/ 1,4-Dioxane analyzed by low-level method (SW8260SIM) and SW8260B


# APPENDIX A-4.2.2.2

# SUMMARY OF TREATMENT PLANT EARLY WARNING INFLUENT WATER QUALITY

# (1,4-DIOXANE)

# TREND ANALYSIS

# APPENDIX A-4.2.2.2
# 1,4-DIOXANE
# EARLY WARNING TREND ANALYSIS




**Analysis prepared using DUMPSTAT and Sen's Test for trend**

# APPENDIX A-4.2.3

# SUMMARY OF TREATMENT PLANT EARLY WARNING INFLUENT WATER QUALITY

# MOLYBDENUM

# APPENDIX A-4.2.3.1

# SUMMARY OF TREATMENT PLANT EARLY WARNING INFLUENT WATER QUALITY

# (MOLYBDENUM)

# INDIVIDUAL AND COMPOSITE RESULTS

# APPENDIX A-4.2.3.1
# SUMMARY OF EARLY WARNING INFLUENT WATER QUALITY
# MOLYBDENUM
## JULY THROUGH DECEMBER 2021 OPERATIONS AND MAINTENANCE STATUS REPORT
## LOWRY LANDFILL SUPERFUND SITE

| Date→ | 7/6/2021 | 7/6/2021 | 7/6/2021 | 7/6/2021 | 7/6/2021 | 7/6/2021 | 7/6/2021 | | |
|---|---|---|---|---|---|---|---|---|---|
| % of Flow→ | 1.7% | 21.5% | 6.8% | 37.6% | 24.0% | 5.6% | 2.8% | | |
| Sample Port→ | TP-110[a/] | TP-120[b/] | TP-140[c/] | TP-150[d/] | TP-160[e/] | TP-170[f/] | TP3310[g/] | | |
| Compound | Conc (ug/L[h/]) | Conc (ug/L) | Conc (ug/L) | Conc (ug/L) | Conc (ug/L) | Conc (ug/L) | Conc (ug/L) | Composite Conc (ug/L) | Permit Limit[i/] (ug/L) |
| Molybdenum | 1.4 | 0.51 | 1.3 | 1.7 | 2 | 7200 | 8.9 | 405 | 430 |

| Date→ | 8/2/2021 | 8/2/2021 | 8/2/2021 | 8/2/2021 | 8/2/2021 | 8/2/2021 | 8/2/2021 | | |
|---|---|---|---|---|---|---|---|---|---|
| % of Flow→ | 1.7% | 21.8% | 6.3% | 37.9% | 23.6% | 5.7% | 2.9% | | |
| Sample Port→ | TP-110 | TP-120 | TP-140 | TP-150 | TP-160 | TP-170 | TP3310 | | |
| Compound | Conc (ug/L) | Conc (ug/L) | Conc (ug/L) | Conc (ug/L) | Conc (ug/L) | Conc (ug/L) | Conc (ug/L) | Composite Conc (ug/L) | Permit Limit (ug/L) |
| Molybdenum | 1 | 0.6 | 1.4 | 1.8 | 2.1 | 6000 | 20 | 344 | 430 |

| Date→ | 9/7/2021 | 9/7/2021 | 9/7/2021 | 9/7/2021 | 9/7/2021 | 9/7/2021 | 9/7/2021 | | |
|---|---|---|---|---|---|---|---|---|---|
| % of Flow→ | 1.7% | 20.3% | 6.1% | 36.1% | 22.8% | 10.3% | 2.8% | | |
| Sample Port→ | TP-110 | TP-120 | TP-140 | TP-150 | TP-160 | TP-170[l/] | TP3310 | | |
| Compound | Conc (ug/L) | Conc (ug/L) | Conc (ug/L) | Conc (ug/L) | Conc (ug/L) | Conc (ug/L) | Conc (ug/L) | Composite Conc (ug/L) | Permit Limit (ug/L) |
| Molybdenum | 0.69 | 0.6 | 4.5 | 2.1 | 1.9 | 3700 | 36 | 384 | 430 |

# APPENDIX A-4.2.3.1
# SUMMARY OF EARLY WARNING INFLUENT WATER QUALITY
# MOLYBDENUM

| Date→ | 10/4/2021 | 10/4/2021 | 10/4/2021 | 10/4/2021 | 10/4/2021 | 10/4/2021 | 10/4/2021 | | |
|---|---|---|---|---|---|---|---|---|---|
| % of Flow→ | 1.7% | 19.9% | 6.2% | 37.0% | 23.2% | 9.2% | 2.8% | | |
| Sample Port→ | TP-110 | TP-120 | TP-140 | TP-150 | TP-160 | TP-170 | TP3310 | | |
| Compound | Conc (ug/L) | Conc (ug/L) | Conc (ug/L) | Conc (ug/L) | Conc (ug/L) | Conc (ug/L) | Conc (ug/L) | Composite Sample Conc (ug/L) | Permit Limit (ug/L) |
| Molybdenum | 1.1 | 0.89 | 1.9 | 2.6 | 2.2 | 3600 | 7.5 | 333 | 430 |

| Date→ | 11/1/2021 | 11/1/2021 | 11/1/2021 | 11/1/2021 | 11/1/2021 | 11/1/2021 | 11/1/2021 | | |
|---|---|---|---|---|---|---|---|---|---|
| % of Flow→ | 3.4% | 19.3% | 6.0% | 36.6% | 23.0% | 8.8% | 2.8% | | |
| Sample Port→ | TP-110 | TP-120 | TP-140 | TP-150 | TP-160 | TP-170 | TP3310 | | |
| Compound | Conc (ug/L) | Conc (ug/L) | Conc (ug/L) | Conc (ug/L) | Conc (ug/L) | Conc (ug/L) | Conc (ug/L) | Composite Conc (ug/L) | Permit Limit (ug/L) |
| Molybdenum | < 0.37 | < 0.37 | 0.76 | 2.3 | 2.1 | 4200 | 13 | 371 | 430 |

| Date→ | 12/6/2021 | 12/6/2021 | 12/6/2021 | 12/6/2021 | 12/6/2021 | 12/6/2021 | 12/6/2021 | | |
|---|---|---|---|---|---|---|---|---|---|
| % of Flow→ | 1.8% | 19.7% | 6.0% | 37.6% | 25.7% | 6.3% | 3.0% | | |
| Sample Port→ | TP-110 | TP-120 | TP-140 | TP-150 | TP-160 | TP-170 | TP3310 | | |
| Compound | Conc (ug/L) | Conc (ug/L) | Conc (ug/L) | Conc (ug/L) | Conc (ug/L) | Conc (ug/L) | Conc (ug/L) | Composite Conc (ug/L) | Permit Limit (ug/L) |
| Molybdenum | 0.68 | 0.57 | 3.5 | 1.7 | 2.1 | 5600 | 10 | 354 | 430 |

Footnotes:

a/ RWST - Raw Water Storage Tank wat
b/ NBBW - North Boundary Barrier Wall water
c/ MW38 Area water
d/ North End On-Site water
e/ North End Off-Site water
f/ MW113 Area water
g/ BTS Tank 3310 influent is comprised of North Toe Extraction System water and Landfill Gas Condensate
h/ ug/L = micrograms per liter
i/ Permit Limit - limit in ug/L for discharge according to Industrial Discharge Permit No. 2360-6 issued by the Metro Wastewater Reclamation District (Metro), effective January 5, 2020.


# APPENDIX A-4.2.3.2

# SUMMARY OF TREATMENT PLANT EARLY WARNING INFLUENT WATER QUALITY

# (MOLYBDENUM)

# TREND ANALYSIS

# APPENDIX A-4.2.3.2
# MOLYBDENUM
# EARLY WARNING TREND ANALYSIS




Analysis prepared using DUMPSTAT
and Sen's Test for trend

# APPENDIX A-5

# TECHNICAL MEMORANDUM – ANION EXCHANGE OPERATIONAL PERFORMANCE AT LOWRY LANDFILL SUPERFUND SITE

PARSONS
301 Plainfield Road, Suite 312, Syracuse, New York 13202
Office: +1 315.451.9560, www.parsons.com

September 24, 2021

Dave Wilmoth (City and County of Denver)
Steve Richtel (Waste Management)

**Subject: Technical Memorandum – Anion Exchange Operational Performance at Lowry Landfill Superfund Site**

Parsons Environment & Infrastructure Group (Parsons) is pleased to provide this technical memorandum presenting an evaluation of the operational performance of the anion exchange (AIEX) system for Molybdenum treatment from water generated from monitoring well MW-113 at the Lowry Landfill Superfund Site in Colorado.

The memorandum is organized into the following sections:

- Executive Summary
- Project Background and System Description
- Molybdenum AIEX Performance Curve and Observations
- Molybdenum Speciation, pH Adjustments and Observations

## Executive Summary

Based on Parsons treatability work, Parsons designed an AIEX Molybdenum treatment system, installed the system in late 2020 and started it up in January 2021. Parsons has operated this system since January 2021 as part of the Lowry treatment plant. Initial influent concentrations of Molybdenum have reduced over the operating period from levels in excess of 25,000 ug/L total Molybdenum to current levels in the approximate 7,000 ug/l range. In all cases, the treatment system has removed a significant portion of the influent Molybdenum such that the combined landfill leachate treatment process effluent is in compliance with the pretreatment limit for discharge to Metropolitan Water Reclamation District's (Metro) treatment plant. Treatment results also indicate that there is a heel of Molybdenum that is not being treated by the ion exchange system. The concentration of this heel is not significant enough to impact the overall treatment system goals of the leachate treatment process.

Treatability study testing indicated the potential for a significant improvement in ion exchange capacity if the process was conducted at a reduced pH. By operating at a reduced pH, the AIEX resin exchange capacity has been far more efficient than what was predicted by independent third-party equilibrium model predictions and was consistent with previously conducted treatability testing. The treatability study memorandum summarizing these tests has been included as Attachment 1.

## Project Background and System Description

Groundwater at the Lowry Landfill Superfund Site is currently recovered and pretreated for discharge to the Metropolitan Water Reclamation District's (Metro) treatment plant. Molybdenum is a component of the recovered groundwater generated at MW-113, one of the North End On-Site wells and is treated at AIEX Molybdenum treatment system. A brief process summary of the system is discussed below. The existing process flow diagram is shown in Figure 1.

Recovered groundwater is conveyed from MW-113 to a feed tank. To overcome the high head requirements of the system, a rotary vane positive displacement pump is used to pump the water from the feed tank into the AIEX system. In-line pH adjustment is performed prior to AIEX treatment. The AIEX system consists of a "cage" of 18 AIEX Contactors and a guard tank, each measuring 8"x44" (diameter x column height). To allow for redundancy, an identical stand-by "cage" of 18 AIEX

301 Plainfield Road, Suite 312, Syracuse, New York 13202
Office: +1 315.451.9560, www.parsons.com

Contactors is also available. Advised by isotherm studies conducted by Parsons during treatability work, the use of strong base anion resin in the chloride form was considered as the prime candidate treatment. ResinTech SPG1 strong base anion resin is currently being used for treatment. A similar resin, but not the same resin as is currently using for treatment, was used during the treatability study.

Additional resin details, including the total volume of resin in each Contactor, are shown in Table 1. For additional process details, the record process and instrumentation diagram (P&ID) of the system has been included as Attachment 2.





Figure 1-Process Flow Diagram

| AIEX Resin Details | | |
|---|---|---|
| **Item** | **Name/Value** | **Units** |
| Resin Used | ResinTech SPG1 strong base anion resin | NA |
| Resin Density | 44 | lbs/ft^3 |
| Resin Vol. in One Contactor | 1.2 | ft3 |
| Resin Weight in One Contactor | 52.8 | lbs |
| Total Resin Weight in Cage (18 Contactors) | 950 | lbs |

Table 1 – AIEX Resin Details

PARSONS
301 Plainfield Road, Suite 312, Syracuse, New York 13202
Office: +1 315.451.9560, www.parsons.com

## Molybdenum AIEX Performance Curve and Observations

This section discusses the Molybdenum AIEX performance curve in the lead Contactor (Contactor 1) of the AIEX system. Based on historical data, Molybdenum had been confirmed to primarily be present in the molybdate ($Mo^{2-}$) form. Isotherm studies also indicated that a reduction of pH to the 4.0 range prior to treatment significantly increased the anion exchange capacity and reduced the resin utilization rate (likely through the reduction of carbonate and bicarbonate anionic species which would compete for Molybdenum exchange sites.) These findings were implemented in the detailed design and operation of the existing Molybdenum Treatment System and have been validated by the operational data generated to date.

Weekly influent and effluent Molybdenum readings, treatment volumes and Molybdenum adsorbed on the resin were used to generate an AIEX performance curve for the ResinTech SPG1 strong base anion resin in Contactor 1. The operational data and calculations are tabulated in Table 2. Figure 2 shows the AIEX performance curve generated based on data from Table 2.

| | Treatment Volumes | | | | Mo. Conc. (Contactor 1) | | | | |
|---|---|---|---|---|---|---|---|---|---|
| Duration (2021) | Vol. Treated in specific duration | Vol. Treated | Cumulative Volume Treated | Cumulative Volume Treated | Influent Mo. | Contactor 1 Effluent Mo. | Mo Adsorbed on Resin-Contactor 1 for specific duration | | Cumulative Mo adsorbed on Resin in Contactor 1 |
| | gal | liters | gal | liters | ug/l | ug/l | ug | mg | mg |
| 1/27 to 1/27 | 232 | 878 | 232 | 878 | 27000 | 5 | 2.37E+07 | 2.4E+04 | 2.4E+04 |
| 1/27 to 1/28 | 650 | 2460 | 882 | 3338 | 27000 | 5 | 6.64E+07 | 6.6E+04 | 9.0E+04 |
| 1/28 to 2/2 | 3540 | 13399 | 4422 | 16737 | 26000 | 6600 | 2.60E+08 | 2.6E+05 | 3.5E+05 |
| 2/2 to 2/9 | 5250 | 19871 | 9672 | 36609 | 21000 | 4000 | 3.38E+08 | 3.4E+05 | 6.9E+05 |
| 2/9 to 2/16 | 5298 | 20053 | 14970 | 56661 | 19000 | 4500 | 2.91E+08 | 2.9E+05 | 9.8E+05 |
| 2/16 to 2/23 | 5930 | 22445 | 20900 | 79107 | 20000 | 2800 | 3.86E+08 | 3.9E+05 | 1.4E+06 |
| 2/23 to 3/2 | 9964 | 37714 | 30864 | 116820 | 18000 | 3000 | 5.66E+08 | 5.7E+05 | 1.9E+06 |
| 3/2 to 3/9 | 10201 | 38611 | 41065 | 155431 | 17000 | 2200 | 5.71E+08 | 5.7E+05 | 2.5E+06 |
| 3/9 to 3/16 | 18142 | 68667 | 59207 | 224098 | 16000 | 2700 | 9.13E+08 | 9.1E+05 | 3.4E+06 |
| 3/16 to 3/23 | 19633 | 74311 | 78840 | 298409 | 15000 | 2200 | 9.51E+08 | 9.5E+05 | 4.4E+06 |
| 3/23 to 3/30 | 19810 | 74981 | 98650 | 373390 | 14000 | 2200 | 8.85E+08 | 8.8E+05 | 5.3E+06 |
| 3/30 to 4/05 | 19768 | 74822 | 118418 | 448212 | 12000 | 1200 | 8.08E+08 | 8.1E+05 | 6.1E+06 |
| 4/05 to 4/13 | 17496 | 66222 | 133360 | 504768 | 12000 | 3000 | 5.96E+08 | 6.0E+05 | 6.7E+06 |
| 4/13 to 4/20 | 15629 | 59156 | 148989 | 563923 | 13000 | 2300 | 6.33E+08 | 6.3E+05 | 7.3E+06 |
| 4/20 to 4/29 (1) | 19836 | 75079 | 168825 | 639003 | 12700 | 2500 | 7.66E+08 | 7.7E+05 | 8.1E+06 |
| 4/29 to 5/03 (2) | 8375 | 31699 | 177200 | 670702 | 12000 | 15000 | -9.51E+07 | -9.5E+04 | 8.0E+06 |
| 5/03 to 5/11 (3) | 17346 | 65655 | 194546 | 736357 | 10000 | 9500 | 3.28E+07 | 3.3E+04 | 8.0E+06 |
| 5/11 to 5/18 (4) | 15011 | 56817 | 209557 | 793173 | 8900 | 4900 | 2.27E+08 | 2.3E+05 | 8.2E+06 |
| 5/18 to 5/25 (5) | 15129 | 57263 | 224686 | 850437 | 9900 | 3000 | 3.95E+08 | 4.0E+05 | 8.6E+06 |
| 5/25 to 6/01 | 14869 | 56279 | 239555 | 906716 | 9200 | 5900 | 1.86E+08 | 1.9E+05 | 8.8E+06 |
| 6/01 to 6/08 | 15081 | 57082 | 254636 | 963797 | 8600 | 5000 | 2.05E+08 | 2.1E+05 | 9.0E+06 |
| 6/08 to 6/15 | 20233 | 76582 | 274869 | 1040379 | 9600 | 6900 | 2.07E+08 | 2.1E+05 | 9.2E+06 |
| 6/15 to 6/21 | 16949 | 64152 | 291818 | 1104531 | 8300 | 6400 | 1.22E+08 | 1.2E+05 | 9.3E+06 |
| 6/21 to 6/29 | 21778 | 82430 | 313596 | 1186961 | 7900 | 6600 | 1.07E+08 | 1.1E+05 | 9.4E+06 |
| 6/29 to 7/06 | 19858 | 75163 | 333454 | 1262123 | 7500 | 7000 | 3.76E+07 | 3.8E+04 | 9.5E+06 |
| 7/06 to 7/13 | 19382 | 73361 | 352836 | 1335484 | 7200 | 6000 | 8.80E+07 | 8.8E+04 | 9.6E+06 |
| 7/13 to 7/20 | 19600 | 74186 | 372436 | 1409670 | 6800 | 5200 | 1.19E+08 | 1.2E+05 | 9.7E+06 |
| 7/20 to 7/27 | 19755 | 74773 | 392191 | 1484443 | 6800 | 5700 | 8.22E+07 | 8.2E+04 | 9.8E+06 |
| | | | | | | | | | |
| | | | | | | | | Total Mo Adsorbed on Resin in Contactor 1 for duration | 9.77E+06 |

| Footnotes | |
|---|---|
| 1 | 4/20 Influent data based on HACH field test result |
| 2 | pH increased to 5.0 (from 4.0) as part of Mo speciation evaluation |
| 3 | pH reduced to 4.5 (from 5.0) as part of Mo speciation evaluation |
| 4 | pH reduced to original design pH of 4.0 |
| 5 | pH adjusted to 3.7 |

Table 2-Operational Data

301 Plainfield Road, Suite 312, Syracuse, New York 13202
Office: +1 315.451.9560, www.parsons.com





Figure 2-Molybdenum AIEX Performance Curve

**Observations:**

A. **Breakthrough:** Breakthrough is defined as the first detectable concentration of note of the targeted compound to be treated in the Contactor effluent. Molybdenum demonstrated breakthrough in Contactor 1 after approximately 13,500 liters at an influent total Molybdenum concentration of >20,000 ug/l. Contactor 1 appeared to show complete breakthrough (influent concentration nearly equaling effluent concentration) in late June, but still appeared to have exchange capacity through early August, while possibly passing through a Molybdenum "heel". Molybdenum "heel" and speciation are discussed in detail later in the report under the "Molybdenum Speciation, pH Adjustments and Observations" section. Contactor 1 was deemed exhausted/spent and was taken offline in mid-August 2021.

B. **Influent pH Adjustments:** Parsons performed pH adjustments in April & May of 2021 to observe the effects on the AIEX system. These adjustments are reflected on the above curve from dates 4/20 to 5/25 and are discussed in detail later in the report under the "Molybdenum Speciation, pH Adjustments and Observations" section.

C. **Mass loading (x/m) Comparison:** Table 3 below compares the following:

1) Operational observed mass loading in Contactor 1 (x/m as mg of Molybdenum adsorbed per gram of resin, mg/g) with the loading predicted using Parsons' isotherm studies
2) Operational resin utilization (grams of resin utilized per liter of influent, g/l) in Contactor 1 with the utilization predicted using Parsons' isotherm studies and utilization predicted by Third Party Equilibrium Modeling.

The Parsons isotherm study was conducted at an initial Molybdenum concentration of 8,300 ug/L based on historic Molybdenum concentration information from the Site. Mass loading comparison has been generated by extrapolating the

PARSONS
301 Plainfield Road, Suite 312, Syracuse, New York 13202
Office: +1 315.451.9560, www.parsons.com

isotherm plot to predict adsorption capacity for the average influent concentration of 13,657 ug/l and highest influent concentration of 27,000 ug/L during the time period of this analysis.

| Mass Loading Rate (x/m) Comparison-Isotherm Data, Operational Data and Third Party Chemical Equilibrium Model | | | | | | | |
|---|---|---|---|---|---|---|---|
| | | | Loading (x/m as mg/g) | | Resin Usage (g/l) | | |
| | Mo Influent Concentration Basis | $C_0$ (ug/L) | Using Isotherm Data | Observed based on Operational Data | Using Isotherm Data (g/l) | Observed based on Operational Data (g/l) | Third Party Chemical Equilibrium Model (g/l) |
| Based on Isotherm Data | Highest Observed during Operations (for Comparison) | 27000 | 325.6 | - | 0.083 | | - |
| | Avg. Conc. Observed during Operations (for Comparison) | 13657 | 214.1 | - | 0.064 | | - |
| Based on Operational Data | Conc. Range Based on Operational Data | 6800 to 27000 | - | 411.73 | | - | - |
| | Avg. Conc. Based on Operational Data | 13657 | - | 411.73 | | 0.033 | - |
| Based on Third Party Chemical Equilibrium Model | Third Party Chemical Equilibrium Model (for comparison) | < 1000 | - | - | - | - | 1.32 |

**Table 3-Mass Loading Comparison**

The following is noted from the comparison:

- The operational observed mass loading compares favorably against the mass loading predicted during isotherm studies at the lower pH of 4.0 and has generally trended as predicted by the study. For the range of Molybdenum influent concentration (6800 ug/l to 27000 ug/l) the treatment system has been treating, the isotherm studies predicted loading of 214.1 mg/g and 325 mg/g for the average and maximum observed concentrations during operations, respectively, versus the observed operational mass loading of ~411 mg/g. In terms of resin utilization, the isotherm studies approximately predicted 0.049 to 0.083 g/l versus the observed operational resin utilization 0.033 g/l.
- Third-Party Chemical Equilibrium Model predicted ~1.32 g/l resin utilization assuming AIEX treatment at a native pH, versus the observed operational utilization of 0.033 g/l, which is forty (40) times higher than the current utilization rate. Mass loading data was not generated by the third-party chemical equilibrium model.

## Molybdenum Speciation, pH Adjustments and Observations

A. **Heel and Potential Speciation**: Based on historical discussions with the stakeholders, the AIEX treatment system was designed to treat Molybdenum species in the -II state, which the system is successfully doing and meeting permit requirements.

Based on operational data, the AIEX system appears to have a “heel” of Molybdenum associated compounds that pass at low concentrations through the 18 contactors and the guard tank. These “heel” concentrations have ranged from 160 ug/l to 1600 ug/l in the guard tank effluent, however, most recent results from June 1, 2021 onwards, have shown them to be between 160 ug/l to 290 ug/l.

Molybdenum forms chemical complexes in oxidation states from -II to +VI. Molybdenum can form several ionic species in the existing native and adjusted pH range, which was supported by performing speciation calculations using equilibrium modeling. Examples of such Molybdenum species are tetrahedral $[MoO_4]^{2-}$ ion or the heptamolybdate ion $[Mo_7O_{24}]^{6-}$ or octamolybdate ion $[Mo_8O_{26}]^{4-}$. Laboratory results are reported as Total Molybdenum. Molybdenum species cannot be separately analyzed for and reported via a standard lab analysis

301 Plainfield Road, Suite 312, Syracuse, New York 13202
Office: +1 315.451.9560, www.parsons.com

method. The "heel" is likely a Molybdenum species that does not have a -II oxidation state. Additionally, if competing Molybdenum species have an oxidation state < -II, it would be expected to outcompete a Molybdenum species in the -II oxidation state, adding to the analytical challenge and operational clarity. It should be noted that neutral or positive ionic species will not be removed by AIEX treatment.

To investigate the composition of the Molybdenum "heel", Parsons and the stakeholders worked with an external specialty lab (Brooks Applied). Their results are included as Attachment 3. Their analysis was not conclusive in terms of quantifying the different Molybdenum species. However, based on the usage of $[MoO_4]^{2-}$ molybdate as the calibration standard, the subsequent results indicated Mo (VI) as the majority of the Molybdenum component. The lab results tended to confirm the operational and design assumption that the majority of the Molybdenum component exists in the -II state, although there is a potential for other labile polymolybdates to exist, and neutral Molybdenum or non -II Molybdenum species to form and generate a low concentration "heel" that cannot be exchanged with AIEX. The operational team consistently monitors the "heel" of the system using lab and field analysis to ensure permit compliance.

B. **Adjustment of Influent pH:** The native groundwater influent is approximately at pH 7.3. As discussed previously, based on isotherm studies, during operations the influent pH is reduced to 4.0 upstream of the AIEX system. The Molybdenum Eh–pH diagram (Figure 3) is shown below to guide the discussion.





Figure 3-Molybdenum Eh-pH diagram

Based on the Eh-pH diagram, Parsons performed the following operational pH adjustments in April & May of 2021 to observe the effects on the "heel" and speciation discussed earlier:

1) Adjustment to pH 5.0 from 4.0: Based on the Eh-pH diagram, it was theorized that at a pH of 4.0, there may be neutral or -I Molybdenum species present in the influent. Neutral Molybdenum species will not be treated

PARSONS
301 Plainfield Road, Suite 312, Syracuse, New York 13202
Office: +1 315.451.9560, www.parsons.com

by AIEX and -I anions will outcompete a -II anion therefore potentially passing through the AIEX system and contributing to the heel. The Eh–pH diagram indicated that shifting the pH higher to 5.0 would potentially move most of the Molybdenum species to the -II form. To observe the impact on the "heel" and potentially mitigate it, Parsons adjusted the influent pH to 5.0. However, this adjustment in the pH resulted in some Molybdenum being desorbed from Contactor 1, increasing the Molybdenum influent concentration to Contactor 2, and increasing the effluent concentration from the guard tank. This can be observed in the spike in Molybdenum effluent concentration in Figure 2 on/around 4/29/21 through 5/5/21. The system operated as designed and permit compliance was always ensured during this adjustment.

2) Adjustment to pH 4.5 from 5.0: The pH of the system was gradually reduced to 4.5 from 5.0 as the performance of the system appeared to be better at a lower pH. Sampling results at pH 4.5 indicated improved performance in comparison to system operations at pH 5.0.

3) Adjustment to pH 4.0 from 4.5: Although the system performance improved at pH of 4.5, when compared to operations at pH 5.0, based on the sampling results the Molybdenum exchange was not as efficient as that at pH 4.0, and therefore the system pH was brought back to the design pH.

4) Impact on Molybdenum speciation and impacts on the "heel" during the pH adjustments was undetermined since the external lab was unable to quantify the individual species based on available lab methods.

5) Adjustment to pH 3.7 from 4.0: System was adjusted to pH of 3.7 from 4.0 in late May 2021. This adjustment marginally improved the Molybdenum exchange. The system is currently at pH 3.7.

### C. Field and Lab Molybdenum Data Co-Relation:

In addition to analyzing for Molybdenum in a lab, Parsons has also been analyzing Molybdenum using Hach field test kits. Due to the immediate availability of results, field analysis is particularly beneficial to the treatment system in identifying an upset condition. However, results from field test kits are not as accurate as lab results. Initial field results showed a large error. Following these initial errors, the field test methods were revised starting 3/4/21. Based on discussions and field sampling observations, potential Molybdenum concentrations >1000ug/l were field tested for by Hach Method 8036 and potential Molybdenum concentrations <1000ug/L were field tested by Hach Method 8169. Following this adjustment, the accuracy of the field sampling results improved. Table 4 below identifies the percent error for Contactor 1 effluent samples analyzed in the field and compared against the lab results. The mean absolute error of the field data has also been calculated below. It should be noted that while there is significant measurement error between the field test and partnered lab tests, the field test results are biased consistently high which means that the field results are conservative and a good real time indicator of changes in system performance. Only results following the revision of field test methods are included in this co-relation.

PARSONS
301 Plainfield Road, Suite 312, Syracuse, New York 13202
Office: +1 315.451.9560, www.parsons.com

| Molybdenum Contactor 1 Effluent Samples-Field and Lab Analysis | | | |
|---|---|---|---|
| | Mo (ug/l) | | |
| Date | Field Result | Lab Result | Error (%) |
| 1/27/2021 | 20 | 5 | See Footnote 1 |
| 1/28/2021 | 960 | 6600 | See Footnote 1 |
| 2/2/2021 | 2310 | 4000 | See Footnote 1 |
| 2/9/2021 | 1850 | 4500 | See Footnote 1 |
| 2/16/2021 | 2180 | 2800 | See Footnote 1 |
| 3/9/2021 | 2600 | 2700 | -3.7 |
| 3/16/2021 | 2300 | 2200 | 4.5 |
| 3/23/2021 | 2400 | 2200 | 9.1 |
| 3/30/2021 | 1600 | 1200 | 33.3 |
| 4/5/2021 | 3300 | 3000 | 10.0 |
| 4/13/2021 | 2600 | 2300 | 13.0 |
| 4/20/2021 | 2400 | 2500 | -4.0 |
| 4/29/2021 | 14700 | 15000 | -2.0 |
| 4/29/2021 | 15900 | 13000 | 22.3 |
| 5/3/2021 | 11400 | 9500 | 20.0 |
| 5/3/2021 | 11300 | 10000 | 13.0 |
| 5/11/2021 | 5400 | 4900 | 10.2 |
| 5/18/2021 | 3100 | 3000 | 3.3 |
| 5/25/2021 | 7100 | 5900 | 20.3 |
| 6/1/2021 | 5200 | 5000 | 4.0 |
| 6/8/2021 | 7700 | 6900 | 11.6 |
| 6/15/2021 | 7300 | 6400 | 14.1 |
| 6/21/2021 | 7000 | 6600 | 6.1 |
| 6/29/2021 | 6800 | 7000 | -2.9 |
| 7/6/2021 | 6800 | 6000 | 13.3 |
| 7/13/2021 | 6600 | 5200 | 26.9 |
| 7/20/2021 | 6900 | 5700 | 21.1 |
| | | | |
| Mean Absolute Error (%) | | 12.2 | |
| | | | |
| Footnotes | | | |
| 1 | After initial observations, field test methods were revised starting 3/4/21. Data prior to this date has not been used for error analysis. | | |

Table 4-Field and Lab Molybdenum Analysis Co-Relation

* * *

301 Plainfield Road, Suite 312, Syracuse, New York 13202
Office: +1 315.451.9560, www.parsons.com

Parsons appreciates the opportunity to be of continued service to the Lowry Landfill Site. If you have any questions or comments regarding this memorandum, please do not hesitate to contact me at 315-440-2993.

Sincerely,



Les Cordone, VP, PE
Manager-Industrial Wastewater Treatment Practice

cc: Adway Biniwale, PE (Parsons)
Chris Carlson (Parsons)
Lyn Brill (Parsons)
Dan Griffiths, PG (Parsons)

301 Plainfield Road, Suite 312, Syracuse, New York 13202
Office: +1 315.451.9560, www.parsons.com

# ATTACHMENTS

## Attachment 1: Lowry Landfill Molybdenum Treatability Study

## Attachment 2: Record P&ID

## Attachment 3: External Lab Reports on Molybdenum Speciation

Attachment 1

PARSONS

MEMORANDUM

September 23, 2021

To: Lyn Brill and Chris Carlson; Parsons

From: Les Cordone; Parsons

Subject: Lowry Landfill Molybdenum Treatability Study – Interim Results

## Summary

This summary presents the results of treatability testing for molybdenum (Mo) treatment in Lowry landfill monitoring well MW-113. It covers results of jar testing to determine molybdate removal by chemical complexation with iron at low pH (~4.0), and by precipitation / co-precipitation with iron at minimum solubility for iron hydroxide (pH 7.5 – 8.0). Additionally, results from isotherm studies with strong-base anionic exchange resins including Purolite A520E (general) and Ambersep™ 21K XLT (molybdenum-specific) are presented.

## Acid and Alkalinity Titrations

Aliquots of the MW-113 well water were titrated to endpoint 3.0 and 12.0 s.u. using 0.5N $H_2SO_4$ and 0.5N NaOH, respectively. The complete titration curves have been presented in Figure 1. These titrations were used to estimate the required quantity of acid or base require to adjust and/or re-adjust pH to target endpoints for iron complexation and isotherm tests.

## Jar Testing

### Jar Test Procedure: Complexation with Iron at Reduced pH

Jar tests were performed with aliquots of the MW-113 well water. Ferric chloride ($FeCl_3$) was used to add iron (Fe) as a complexing agent. $FeCl_3$ doses of 10 and 50 mg Fe/L were applied along with a control without Fe addition. The pH was reduced to 4.0 s.u. and allowed a reaction time of 15 minutes while stirring. The pH was readjusted to 7.5 – 8.0 s.u. using either NaOH for one set of jars or hydrated lime ($Ca(OH)_2$) for the other set. Following the reaction phase each jar was dosed with anionic polymer to achieve a concentration of 1 mg/L. Following tapered mixing at 120 and 50 RPM for 2 and 20-minute flash and slow mixing, respectively, the jars were allowed to settle for 2 hours. Supernatant was collected unfiltered and filtered through 5 µm, 1 µm and 0.45 µm pore sizes.

## Jar Test Procedure: Precipitation / Co-precipitation

Precipitation/co-precipitation of Mo with iron at minimum solubility for iron hydroxide (7.5 – 8.0) was tested following similar jar testing procedures to iron complexation. Aliquots of the MW-113 well water were dosed with $FeCl_3$ at doses of 10 and 50 mg/L along with a control without Fe addition. The pH was adjusted to 7.5 – 8.0 s.u. using NaOH for one set of jars and $(Ca(OH)_2)$ on a second set. Following the reaction phase each jar was dosed with anionic polymer to achieve a concentration of 1 mg/L. The jars were allowed to settle for 2 hours after tapered mixing after which supernatant was sampled unfiltered and filtered through at 5 µm, 1 µm and 0.45 µm pore sizes.

## Jar Test Results

All samples were screened in-house using a HACH molybdate test kit. Screening results are presented in Table 1A. Undosed controls along with samples dosed at 50 mg Fe/L (unfiltered and filtered at 0.45 µm) were submitted to Eurofins/TestAmerica (Denver, CO); results from these contract-lab analyses are presented in Table 1B. The results indicate that:

- Complexation testing achieved Mo removal by 50-60% at a dose of 50 mg Fe/L.
- Precipitation / co-precipitation at the same dose achieved a removal efficiency of 40-50%.
- Filtration did not result in noticeable improvement in Mo removal in either test series.
- There was no substantial difference in results arising from the use of NaOH versus $Ca(OH)_2$ for pH readjustment.
- The HACH test kits provided a reasonably accurate screening tool for measuring molybdenum in this test matrix.

# Isotherm Study

Two (2) ion exchange resins including a standard strong base anionic exchange resin (Purolite A520E) and Molybdenum-specific anionic exchange resin (Ambersep™ 21K XLT) were used in an isotherm study for Mo removal. For each resin, two (2) pH conditions were tested; 1) pH reduced to 4.0 s.u. (to remove carbonate / bicarbonate alkalinity); and 2) native pH. The jars were dosed with various amounts of resin and mixed for a period of 48 hours. The supernatant was filtered through 1 µm pore size to exclude any ion exchange resin particles. The results from Mo analysis of the isotherm tests are presented in Tables 2. The results indicate the following:

- Both ion exchange resins performed significantly more efficiently at lower pH (4.0) versus native pH.
- Ambersep™ 21K XLT was somewhat more efficient at removing Mo at lower pH compared to Purolite A520E especially as indicated by the lower-dosed jars.
- Ambersep™ 21K XLT did not provide better removal performance compared to Purolite A520E at native pH.

## Projected Resin Utilization: Purolite A-520E

Isotherms were generated using the data obtained from the Purolite A-520E study. The isotherms for the pH-adjusted and native pH studies are presented in Figures 2A and 2B, respectively. The isotherm results were used to project the annual amount of resin required to treat flow rates of 2 gpm and 6 gpm continuous (1.1 and 3.2 million gallons per year) reflecting minimum and maximum flows, respectively. The isotherm study parameters and associated projected utilization rates using an influent Mo concentration basis of 8.3 mg/L are presented as follows:

| pH | $K_f$ | 1/n | $x/m_{C0}$ (mg/g) | Usage Rate (g/L) | 2 gpm | 6 gpm |
|---|---|---|---|---|---|---|
| 4.0 | 42.9 | 0.615 | 157.8 | 0.053 | 460 | 1380 |
| Native | 1.03 | 0.692 | 4.45 | 1.87 | 16,400 | 49,100 |

## Projected Resin Utilization: Ambersep® 21K XLT

Isotherms were not generated for the Mo-specific Ambersep 21K XLT resin due to the near-complete removal of Mo at pH 4 even at the lowest resin dose tested; the data did not lend themselves to generation of an isotherm curve. However, based on the lowest dose test a utilization rate somewhat lower than that projected for Purolite A-520E would be estimated.

# Conclusions / Recommendations

Based on the results obtained from treatability testing, the following conclusions and recommendations were developed:

- Efficient removal to < 1 mg/L was demonstrated with ion exchange resins following adjustment of pH to 4.0. At this low pH, molybdenum-specific ion exchange resin provided more efficient removal at lower doses.
- Complexation with iron at low pH (~4.0) followed by readjustment of pH to around 7.5 – 8.0 performed slightly better than precipitation/co-precipitation of Mo with iron. Additional studies at higher doses may be warranted in the event this process is preferable to ion exchange.
- Determining the effect of adjusting the water from this location to pH 4 on the overall pH of process water at the site may be warranted.

Table 1A. Jar Test Results: HACH Test Kit Screening Mo Analyses

| Test: | Complexation (pH 4, 15 min; Adj to 7.5-8.0) | | | Precip/Co-Precip (Adj pH 7.5 – 8.0) | | | Units |
|---|---|---|---|---|---|---|---|
| $FeCl_3$ Concentration (mg/L): | 0 | 10 | 50 | 0 | 10 | 50 | |
| *pH Adjust to 7.5-8.0 with NaOH* | | | | | | | |
| Unfiltered | 9.0 | 7.9 | 4.5 | 9.5 | 9.1 | 5.9 | mg/L |
| 5um-Filtered | 9.3 | 8.2 | 4.5 | 9.9 | 9.3 | 5.7 | mg/L |
| 1um-Filtered | 9.3 | 8.3 | 4.9 | 9.9 | 8.9 | 5.5 | mg/L |
| 0.45um-Filtered | 9.1 | 8.1 | 4.4 | 9.3 | 8.7 | 5.6 | mg/L |
| *pH Adjust to 7.5-8.0 with $Ca(OH)_2$* | | | | | | | |
| Unfiltered | 9.3 | 7.4 | 4.5 | 9.3 | 9.2 | 5.1 | mg/L |
| 5um-Filtered | 9.6 | 7.6 | 4.7 | 9.3 | 9.2 | 5.3 | mg/L |
| 1um-Filtered | 9.3 | 7.8 | 4.6 | 9.0 | 8.9 | 5.2 | mg/L |
| 0.45um-Filtered | 9.3 | 7.5 | 4.2 | 9.0 | 8.9 | 5.0 | mg/L |

Table 1B. Jar Test Results: Contract Lab Mo Analyses

| Test: | Complexation (pH 4, 15 min; Adj to 7.5-8.0) | | | Precip/Co-Precip (Adj pH 7.5 – 8.0) | | | Units |
|---|---|---|---|---|---|---|---|
| $FeCl_3$ Concentration (mg/L): | 0 | 10 | 50 | 0 | 10 | 50 | |
| *pH Adjust to 7.5-8.0 with NaOH* | | | | | | | |
| Unfiltered | 7.5 | -- | 3.9 | 7.6 | -- | 4.7 | mg/L |
| 0.45um-Filtered | 7.2 | -- | 3.8 | 7.4 | -- | 4.2 | mg/L |
| *pH Adjust to 7.5-8.0 with $Ca(OH)_2$* | | | | | | | |
| Unfiltered | 7.9 | -- | 3.4 | 7.3 | -- | 4.3 | mg/L |
| 0.45um-Filtered | 7.6 | -- | 3.3 | 7.2 | -- | 4.1 | mg/L |

Table 2. Isotherm Test Results

| Sample ID | Resin Dose (g/L) | Mo Conc. (mg/L) | Sample ID | Resin Dose (g/L) | Mo Conc. (mg/L) |
|---|---|---|---|---|---|
| *pH 4* | | | | | |
| Purolite A-520E | | | Ambersep 21K XLT | | |
| ISO-Puro-Jar 1A | 0.0000 | 8.3 | ISO-Ambe-Jar 1A | 0.0000 | 8.6 |
| ISO-Puro-Jar 2A | 0.0576 | 2.0 | ISO-Ambe-Jar 2A | 0.0521 | 0.5 |
| ISO-Puro-Jar 3A | 0.1036 | 0.6 | ISO-Ambe-Jar 3A | 0.1011 | 0.4 |
| ISO-Puro-Jar 4A | 0.1756 | 0.4 | ISO-Ambe-Jar 4A | 0.1758 | 0.3 |
| ISO-Puro-Jar 5A | 0.2505 | 0.3 | ISO-Ambe-Jar 5A | 0.2517 | 0.3 |
| ISO-Puro-Jar 6A | 0.4052 | 0.3 | ISO-Ambe-Jar 6A | 0.4006 | 0.3 |
| ISO-Puro-Jar 7A | 0.7509 | 0.2 | ISO-Ambe-Jar 7A | 0.7503 | 0.3 |
| ISO-Puro-Jar 8A | 1.5011 | 0.2 | ISO-Ambe-Jar 8A | 1.5470 | 0.2 |
| *Native pH* | | | | | |
| Purolite A-520E | | | Ambersep 21K XLT | | |
| ISO-Puro-Jar 1B | 0.0000 | 8.0 | ISO-Ambe-Jar 1B | 0.0000 | 7.3 |
| ISO-Puro-Jar 2B | 0.0523 | 7.7 | ISO-Ambe-Jar 2B | 0.0516 | 8.0 |
| ISO-Puro-Jar 3B | 0.1019 | 7.1 | ISO-Ambe-Jar 3B | 0.1091 | 7.2 |
| ISO-Puro-Jar 4B | 0.1752 | 6.8 | ISO-Ambe-Jar 4B | 0.1751 | 6.9 |
| ISO-Puro-Jar 5B | 0.2538 | 6.2 | ISO-Ambe-Jar 5B | 0.2507 | 6.3 |
| ISO-Puro-Jar 6B | 0.4045 | 5.3 | ISO-Ambe-Jar 6B | 0.4018 | 5.4 |
| ISO-Puro-Jar 7B | 0.7504 | 4.0 | ISO-Ambe-Jar 7B | 0.7514 | 5.4 |
| ISO-Puro-Jar 8B | 1.5019 | 2.4 | ISO-Ambe-Jar 8B | 1.5090 | 2.1 |





Figure 1. Acid and Alkalinity Titration Curves.





Figure 2. Molybdenum removal by Iron Complexation and Precipitation/Co-Precipitation by Jar Testing (Figure based on Independent Analytical Lab Mo Analyses).





Figure 3A. Purolite A-520E Isotherm – pH 4
(Isotherm with Jars 2 – 4 presented)






Figure 3B. Purolite A-520E Isotherm – Native pH

Attachment 2




NOTES:

1. PER SITE INFORMATION, MW-113 GROUNDWATER PUMP SHUTS OFF ON IT'S OWN BASED ON PRESSURE AND THEREFORE DOES NOT NEED TO BE INTERLOCKED WITH THE FEED TANK.
2. EXISTING INFRASTRUCTURE/PROCESS EQUIPMENT & PIPING/VALVES/INSTRUMENTATION ARE OUTSIDE THE SCOPE OF CURRENT DESIGN AND HAVE BEEN DEMARCATED AS SUCH.
3. NO DUTY/STAND-BY REDUNDANCY IN CERTAIN PROCESS COMPONENTS. IT IS ASSUMED THAT THIS MOLYBDENUM TREATMENT SYSTEM, TREATING WATER FROM MW-113-EW-1, CAN BE SHUTDOWN SHORT TERM TO ALLOW O&M TASKS
4. FLOW CONTROL LOOP VIA VFD FOR P-114 BASED ON FE/FIT-0113 FLOW READING.
5. FIELD ROUTE PIPING AS REQUIRED AND ENSURE VALVE SIZES MATCH PIPE SIZES IF THERE ARE FIELD VARIATIONS.
6. MV-118 TO BE A VENTED BALL VALVE.
7. INSTRUMENTATION INSTALLATION DETAILS SHOWN ON INSTRUMENTATION INSTALLATION DETAILS (SPECIFICATION 18015)
8. ALL PRVS TO DRAIN TO A SAFE LOCATION.

INTERLOCKS:

INTERLOCK 1: FEED FORWARD PUMP, P-114, TO SHUTOFF AT LOW LEVEL CONDITION IN FEED TANK AND OPERATOR ADJUSTABLE PRESSURE SETPOINT, BASED ON PRESSURE READING FROM PI/PIT-0101.

INTERLOCK 2: ACID/CAUSTIC DOSING PUMPS TO SHUTOFF AT LOW LEVEL CONDITION IN FEED TANK

INTERLOCK 3: FV-113 TO CLOSE AT HIGH LEVEL CONDITION IN FEED TANK AND CLOSE BASED ON "PLANT RUNNING STATUS" AT PLC.

### P-113
DESC: GROUNDWATER PUMP
CAP: 0.5 - 2.0 GPM
MAT:
MFG:
HP:

### T-113
DESC: FEED TANK
CAP: 150 GAL
MAT:
MFG: SNYDER
DIM: 32" DIAM
TYPE: ATMOSPHERIC

### P-114
DESC: FEED FORWARD PUMP
CAP: 0.5 - 2.0 GPM
MAT: SS
MFG: FLUID-O-TECH
MODEL: TMSS 201
HP: PENDING MOTOR SELECTION

### BF-113
DESC: BAG FILTER
CAP: 0.5 - 8.0 GPM
MAT: STAINLESS STEEL
MFG: PENTAIR
MODEL: ES12NA415
PORE SIZE: 5 - 10µM

### T-621
DESC: ACID (28% HCl) HOLDING TANK
CAP: GAL
MAT:
MFG:
DIM:
TYPE:

### P-632
DESC: ACID PUMP
CAP: 2 - 20 GPH
MAT:
MFG: PROMINENT
MODEL: GAMMA XL_LR
TYPE: SOLENOID DRIVEN

### T-261
DESC: CAUSTIC (25% NaOH) HOLDING TANK
CAP: GAL
MAT:
MFG:
DIM:
TYPE:

### P-290
DESC: CAUSTIC PUMP
CAP: 2 - 20 GPH
MAT:
MFG: PROMINENT
MODEL: GAMMA XL_LR
TYPE: SOLENOID DRIVEN

### SM-113
DESC: IN-LINE MIXER
CAP: 55 GAL
MAT: PVC
MFG: JOHNSON SCREENS
MODEL: STM-100PVC
DIM: 1" DIA.
TYPE: INLINE MIXER

### SM-114
DESC: IN-LINE MIXER
CAP: 55 GAL
MAT: PVC
MFG: JOHNSON SCREENS
MODEL: STM-100PVC
DIM: 1" DIA.
TYPE: INLINE MIXER

### T-114
CAP: 88 GAL
MAT: POLYMER
MFG: CLEAN WATER STORE
MODEL: CWS-2165
DIAMETER: 21" HEIGHT: 74"
TYPE: PRESSURE (RATED FOR 125 PSI, MAX OPERATING PRESSURE: 150 PSI)

### SKID MOUNTED EXCHANGE SYSTEM (2 CAGES)
DESC: ION EXCHANGE SYSTEM
CAP: 0.5 - 2.0 GPM
MAT: CARBON FIBER TANKS
MFG: VEOLIA
MODEL:
TYPE: STRONG BASE ANION RESIN

| NO. | DESCRIPTION | DATE | DRAWN | CHK'D | APPV'D |
|---|---|---|---|---|---|
| C | ISSUED FOR RECORD DRAWING | 12/18/20 | PJM | AB | LC |
| B | ISSUED FOR FINAL DESIGN | 11/6/20 | PJM | AB | LC |
| A | ISSUED FOR HAZOP | 10/14/20 | PJM | AB | LC |

DRAWN BY / DATE
CHECKED BY / DATE
APPROVED BY / DATE
PROJECT MGR. / DATE
SEAL

PARSONS
OFFICE
301 PLAINFIELD ROAD
SYRACUSE, NY 13212
(315) 451-9560

JOB 452025
WBS 30010

PROJECT TITLE
MOLYBDENUM REMOVAL PROCESS TRAIN
WATER TREATMENT PLANT
LOWRY LANDFILL SUPERFUND SITE
DENVER, COLORADO

DRAWING TITLE
PROCESS
P&ID

SCALE
NO SCALE

DRAWING NO.
452025-D-101

REV.
C

FILE NAME: P:\452025 LOWRY LANDFILL MOLYBDENUM TREATABILITY\ENGR\CAD\PID\452025-D-101.DWG
A-5-18 PLOT DATE: 12/22/2020 8:25 AM PLOTTED BY: MANZARI, PAUL

BROOKS APPLIED LABS
18804 North Creek Parkway, Ste 100, Bothell, WA 98011 • USA • T: 206 632 6206 F: 206 632 6017 • info@brooksapplied.com

May 14, 2021

Parsons
Attn: Lyn Brill
1776 Lincoln Suite 600
Denver, CO 80203
Lyn.Brill@Parsons.com

RE: Lowry Environmental Protection Cleanup Trust WTP 452483.60080

Dr. Brill,

Brooks Applied Labs (BAL) received twelve field-filtered aqueous samples requesting molybdenum (Mo) speciation on either April 28 or April 30, 2021. All samples were received in acceptable condition and stored according to BAL SOPs.

*Dissolved Mo Speciation by IC-ICP-CRC-MS*
Each submitted sample was analyzed for molybdenum species using ion chromatography inductively coupled plasma collision reaction cell mass spectrometry (IC-ICP-CRC-MS) on April 30, 2021. Mo species are chromatographically separated on an ion exchange column and then quantified using inductively coupled plasma collision reaction cell mass spectrometry (ICP-CRC-MS). The instrument response was calibrated using a known molybdate [Mo(VI)] standard and any unidentified Mo species [Sum Unk. Mo] were quantified using this Mo(VI) calibration curve.

*Dissolved Mo Quantitation by ICP-QQQ-MS*
An aliquot of each submitted sample was acidified to a pH < 2 using concentrated nitric acid and allowed to digest overnight. All samples were then analyzed for dissolved Mo on May 12, 2021 by a modified EPA Method 6020 employing inductively coupled plasma triple quadrupole mass spectrometry (ICP-QQQ-MS). The ICP-QQQ-MS uses advanced interference removal techniques to ensure accuracy of the sample results.

*Analytical Issues*
No significant analytical issues were encountered with either the Mo speciation or the dissolved Mo analyses, with the exceptions noted below.

The relative percent difference (RPD) associated with the matrix spike set performed upon sample 2104257-01 for dissolved Mo (27.3%) exceeded the control limit of 20%. The RPD of the associated matrix duplicate (4.0%) was within acceptance limits and there was close agreement between the dissolved Mo and Mo(VI) results for this sample (13,400 and 12,300 µg/L, respectively). Consequently, no corrective action was taken since the elevated RPD for the matrix spike set was deemed to be unrepresentative of the performance of the applied method.


Excellent agreement between the measured dissolved Mo and molybdate concentrations was obtained for all submitted samples except for 2104287-03 (TP-174A sampled on 4/29/21) and 2104287-06 (TP-175A sampled on 4/29/21). For these latter two samples the dissolved Mo concentrations were confirmed by reanalysis. While the source of these discrepancies remains unconfirmed at this time, the fact that no unknown Mo species were detected during the speciation analyses suggests that molybdate is the

primary Mo-containing species in these samples. Upon client request BAL can further investigate the cause for the differing dissolved Mo and molybdate concentrations for samples 2104287-03 and 2104287-06.

BAL, an accredited laboratory, certifies that the reported results of all analyses for which BAL is NELAP accredited meet all NELAP requirements.

Please contact us if you have any questions regarding this report.

Sincerely,



Ben Wozniak
Technical Services
Ben@brooksapplied.com

Molybdenum Speciation for Parsons
Contact: Lyn Brill

Date: May 14, 2021
Report Generated by: Ben Wozniak
Brooks Applied Labs, LLC

Date Sampled: 04/27/2021 Date Received: 04/28/2021

**Client Sample ID**
**TP-170**

**Laboratory Sample ID**
**2104257-01**

| Analyte | Method | Concentration | MDL | MRL | Units |
|---|---|---|---|---|---|
| Diss Mo | EPA 6020 Mod. | 13400 | 34 | 100 | µg/L |
| Mo(VI) | IC-ICP-CRC-MS | 12300 | 13 | 130 | µg/L |
| Sum Unk. Mo | IC-ICP-CRC-MS | < 13 U | 13 | 130 | µg/L |

U = Sample concentration is below the MDL

J = Sample concentration is between the MDL and the MRL

Molybdenum Speciation for Parsons
Contact: Lyn Brill

Date: May 14, 2021
Report Generated by: Ben Wozniak
Brooks Applied Labs, LLC

Date Sampled: 04/27/2021 Date Received: 04/28/2021

**Client Sample ID**
**TP-173A**

**Laboratory Sample ID**
**2104257-02**

| Analyte | Method | Concentration | MDL | MRL | Units |
|---|---|---|---|---|---|
| Diss Mo | EPA 6020 Mod. | 7000 | 34 | 100 | µg/L |
| Mo(VI) | IC-ICP-CRC-MS | 7660 | 5.0 | 50 | µg/L |
| Sum Unk. Mo | IC-ICP-CRC-MS | < 5.0 U | 5.0 | 50 | µg/L |

U = Sample concentration is below the MDL

J = Sample concentration is between the MDL and the MRL

Molybdenum Speciation for Parsons
Contact: Lyn Brill

Date: May 14, 2021
Report Generated by: Ben Wozniak
Brooks Applied Labs, LLC

Date Sampled: 04/27/2021 Date Received: 04/28/2021

**Client Sample ID**
**TP-174A**

**Laboratory Sample ID**
**2104257-03**

| Analyte | Method | Concentration | MDL | MRL | Units |
|---|---|---|---|---|---|
| Diss Mo | EPA 6020 Mod. | 1500 | 34 | 100 | µg/L |
| Mo(VI) | IC-ICP-CRC-MS | 1660 | 5.0 | 50 | µg/L |
| Sum Unk. Mo | IC-ICP-CRC-MS | < 5.0 U | 5.0 | 50 | µg/L |

U = Sample concentration is below the MDL

J = Sample concentration is between the MDL and the MRL

Molybdenum Speciation for Parsons
Contact: Lyn Brill

Date: May 14, 2021
Report Generated by: Ben Wozniak
Brooks Applied Labs, LLC

Date Sampled: 04/27/2021 Date Received: 04/28/2021

**Client Sample ID**
**TP-183**

**Laboratory Sample ID**
**2104257-04**

| Analyte | Method | Concentration | MDL | MRL | Units |
|---|---|---|---|---|---|
| Diss Mo | EPA 6020 Mod. | 755 | 34 | 100 | µg/L |
| Mo(VI) | IC-ICP-CRC-MS | 807 | 5.0 | 50 | µg/L |
| Sum Unk. Mo | IC-ICP-CRC-MS | < 5.0 U | 5.0 | 50 | µg/L |

U = Sample concentration is below the MDL

J = Sample concentration is between the MDL and the MRL

Molybdenum Speciation for Parsons
Contact: Lyn Brill

Date: May 14, 2021
Report Generated by: Ben Wozniak
Brooks Applied Labs, LLC

Date Sampled: 04/27/2021 Date Received: 04/28/2021

**Client Sample ID**
**TP-193**

**Laboratory Sample ID**
**2104257-05**

| Analyte | Method | Concentration | MDL | MRL | Units |
|---|---|---|---|---|---|
| Diss Mo | EPA 6020 Mod. | 6790 | 34 | 100 | µg/L |
| Mo(VI) | IC-ICP-CRC-MS | 7420 | 5.0 | 50 | µg/L |
| Sum Unk. Mo | IC-ICP-CRC-MS | < 5.0 U | 5.0 | 50 | µg/L |

U = Sample concentration is below the MDL
J = Sample concentration is between the MDL and the MRL

Molybdenum Speciation for Parsons
Contact: Lyn Brill

Date: May 14, 2021
Report Generated by: Ben Wozniak
Brooks Applied Labs, LLC

Date Sampled: 04/27/2021 Date Received: 04/28/2021

**Client Sample ID**
**TP-172**

**Laboratory Sample ID**
**2104257-06**

| Analyte | Method | Concentration | MDL | MRL | Units |
|---|---|---|---|---|---|
| Diss Mo | EPA 6020 Mod. | 12600 | 34 | 100 | µg/L |
| Mo(VI) | IC-ICP-CRC-MS | 10000 | 13 | 130 | µg/L |
| Sum Unk. Mo | IC-ICP-CRC-MS | < 13 U | 13 | 130 | µg/L |

U = Sample concentration is below the MDL

J = Sample concentration is between the MDL and the MRL

Molybdenum Speciation for Parsons
Contact: Lyn Brill

Date: May 14, 2021
Report Generated by: Ben Wozniak
Brooks Applied Labs, LLC

Date Sampled: 04/29/2021 Date Received: 04/30/2021

**Client Sample ID**
**TP-170**

**Laboratory Sample ID**
**2104287-01**

| Analyte | Method | Concentration | MDL | MRL | Units |
|---|---|---|---|---|---|
| Diss Mo | EPA 6020 Mod. | 12800 | 34 | 100 | µg/L |
| Mo(VI) | IC-ICP-CRC-MS | 12000 | 13 | 130 | µg/L |
| Sum Unk. Mo | IC-ICP-CRC-MS | < 13 U | 13 | 130 | µg/L |

U = Sample concentration is below the MDL

J = Sample concentration is between the MDL and the MRL

Molybdenum Speciation for Parsons
Contact: Lyn Brill

Date: May 14, 2021
Report Generated by: Ben Wozniak
Brooks Applied Labs, LLC

Date Sampled: 04/29/2021 Date Received: 04/30/2021

**Client Sample ID**
**TP-173A**

**Laboratory Sample ID**
**2104287-02**

| Analyte | Method | Concentration | MDL | MRL | Units |
|---|---|---|---|---|---|
| Diss Mo | EPA 6020 Mod. | 15500 | 34 | 100 | µg/L |
| Mo(VI) | IC-ICP-CRC-MS | 15200 | 13 | 130 | µg/L |
| Sum Unk. Mo | IC-ICP-CRC-MS | < 13 U | 13 | 130 | µg/L |

U = Sample concentration is below the MDL

J = Sample concentration is between the MDL and the MRL

Molybdenum Speciation for Parsons
Contact: Lyn Brill

Date: May 14, 2021
Report Generated by: Ben Wozniak
Brooks Applied Labs, LLC

Date Sampled: 04/29/2021 Date Received: 04/30/2021

**Client Sample ID**
**TP-174A**

**Laboratory Sample ID**
**2104287-03**

| Analyte | Method | Concentration | MDL | MRL | Units |
|---|---|---|---|---|---|
| Diss Mo | EPA 6020 Mod. | 4610 | 34 | 100 | µg/L |
| Mo(VI) | IC-ICP-CRC-MS | 7520 | 5.0 | 50 | µg/L |
| Sum Unk. Mo | IC-ICP-CRC-MS | < 5.0 U | 5.0 | 50 | µg/L |

U = Sample concentration is below the MDL

J = Sample concentration is between the MDL and the MRL

Molybdenum Speciation for Parsons
Contact: Lyn Brill

Date: May 14, 2021
Report Generated by: Ben Wozniak
Brooks Applied Labs, LLC

Date Sampled: 04/29/2021 Date Received: 04/30/2021

**Client Sample ID**
**TP-183**

**Laboratory Sample ID**
**2104287-04**

| Analyte | Method | Concentration | MDL | MRL | Units |
|---|---|---|---|---|---|
| Diss Mo | EPA 6020 Mod. | 1010 | 34 | 100 | µg/L |
| Mo(VI) | IC-ICP-CRC-MS | 1010 | 2.5 | 25 | µg/L |
| Sum Unk. Mo | IC-ICP-CRC-MS | < 2.5 U | 2.5 | 25 | µg/L |

U = Sample concentration is below the MDL

J = Sample concentration is between the MDL and the MRL

Molybdenum Speciation for Parsons
Contact: Lyn Brill

Date: May 14, 2021
Report Generated by: Ben Wozniak
Brooks Applied Labs, LLC

Date Sampled: 04/29/2021 Date Received: 04/30/2021

**Client Sample ID**
**TP-172**

**Laboratory Sample ID**
**2104287-05**

| Analyte | Method | Concentration | MDL | MRL | Units |
|---|---|---|---|---|---|
| Diss Mo | EPA 6020 Mod. | 13000 | 34 | 100 | µg/L |
| Mo(VI) | IC-ICP-CRC-MS | 12100 | 13 | 130 | µg/L |
| Sum Unk. Mo | IC-ICP-CRC-MS | < 13 U | 13 | 130 | µg/L |

U = Sample concentration is below the MDL

J = Sample concentration is between the MDL and the MRL

Molybdenum Speciation for Parsons
Contact: Lyn Brill

Date: May 14, 2021
Report Generated by: Ben Wozniak
Brooks Applied Labs, LLC

Date Sampled: 04/29/2021 Date Received: 04/30/2021

**Client Sample ID**
**TP-175A**

**Laboratory Sample ID**
**2104287-06**

| Analyte | Method | Concentration | MDL | MRL | Units |
|---|---|---|---|---|---|
| Diss Mo | EPA 6020 Mod. | 1890 | 34 | 100 | µg/L |
| Mo(VI) | IC-ICP-CRC-MS | 2640 | 5.0 | 50 | µg/L |
| Sum Unk. Mo | IC-ICP-CRC-MS | < 5.0 U | 5.0 | 50 | µg/L |

U = Sample concentration is below the MDL

J = Sample concentration is between the MDL and the MRL

Molybdenum Speciation for Parsons
Contact: Lyn Brill

Date: May 14, 2021
Report Generated by: Ben Wozniak
Brooks Applied Labs, LLC

***Quality Control Summary - Method Blank Summary***

| Analyte | BLK1 | BLK2 | BLK3 | BLK4 | MDL | MRL | Units |
|---|---|---|---|---|---|---|---|
| Diss Mo | 0.009 | 0.005 | 0.003 | 0.002 | 0.034 | 0.10 | µg/L |
| Mo(VI) | 0.002 | 0.001 | -0.001 | 0.000 | 0.005 | 0.050 | µg/L |
| Sum Unk. Mo | 0.000 | 0.000 | 0.000 | 0.000 | 0.005 | 0.050 | µg/L |

Molybdenum Speciation for Parsons
Contact: Lyn Brill

Date: May 14, 2021
Report Generated by: Ben Wozniak
Brooks Applied Labs, LLC

***Quality Control Summary - Laboratory Control Sample (LCS)***

| Analyte | LCS | True Value | Result | Recovery (%) |
|---|---|---|---|---|
| Diss Mo | NIST 1643f | 115.3 | 116.3 | 100.9 |
| Mo(VI) | Blank Spike | 4.995 | 5.115 | 102.4 |

All results presented in µg/L

Molybdenum Speciation for Parsons
Contact: Lyn Brill

Date: May 14, 2021
Report Generated by: Ben Wozniak
Brooks Applied Labs, LLC

***Quality Control Summary - Matrix Duplicates***

| Analyte | Lab Sample ID | Native Result | Duplicate Result | Mean | RPD (%) |
|---|---|---|---|---|---|
| Diss Mo | 2104257-01 | 13402 | 13940 | 13402 | 4.0 |
| Diss Mo | 2104287-01 | 12811 | 10800 | 11806 | 17.0 |
| Mo(VI) | 2104257-04 | 807.3 | 812.0 | 809.7 | 0.6 |
| Mo(VI) | 2104287-06 | 2636 | 2101 | 2369 | 22.6 |
| Sum Unk. Mo | 2104257-04 | < 5.0 U | < 5.0 U | NC | NC |
| Sum Unk. Mo | 2104287-06 | < 5.0 U | < 5.0 U | NC | NC |

All results presented in µg/L
U = Sample concentration is below the MDL
J = Sample concentration is between the MDL and the MRL
NC = Not Calculated (Result < RL)

Molybdenum Speciation for Parsons
Contact: Lyn Brill

Date: May 14, 2021
Report Generated by: Ben Wozniak
Brooks Applied Labs, LLC

***Quality Control Summary - Matrix Spike/ Matrix Spike Duplicate***

| Analyte | Lab Sample ID | Native Result | MS Spike Conc. | MS Result | MS Recov. (%) | MSD Spike Conc. | MSD Result | MSD Recov. (%) | RPD (%) |
|---|---|---|---|---|---|---|---|---|---|
| Diss Mo | 2104257-01 | 13402 | 1010 | 13380 | NC | 1010 | 10170 | NC | 27.3* |
| Diss Mo | 2104287-01 | 12811 | 1010 | 13000 | NC | 1010 | 12744 | NC | 2.0 |
| Mo(VI) | 2104257-04 | 807.3 | 5000 | 6386 | 111.6 | 5000 | 6481 | 113.5 | 1.5 |
| Mo(VI) | 2104287-06 | 2636 | 5000 | 7636 | 100.0 | 5000 | 7415 | 95.6 | 2.9 |

All results presented in µg/L
NC - Not Calculated (Spike < Native Result)
* The RPD is above the established control limit of 20%; please see narrative.

# Chain of Custody

| PARSONS<br>1776 LINCOLN SUITE 600<br>DENVER, CO 80203<br>(303) 831-8100 FAX (303) 831-8208<br>CONTACT: LYN BRILL<br>LYN.BRILL@PARSONS.COM<br>PROJECT: LOWRY ENVIRONMENTAL PROTECTION/CLEANUP TRUST WTP<br>452483.60080 | CHAIN OF CUSTODY #<br>**42720215224**<br><br>LAB CONTACT: BEN WOZNIAK<br>BROOKS APPLIED LABS, BOTHELL, WA |
|---|---|

| SAMPLE ID | DATE | TIME | MATRIX |
|---|---|---|---|
| TP-170 | 4/27/21 | 1230 | AQ |
| TP-173A | 4/27/21 | 1030 | AQ |
| TP-174A | 4/27/21 | 1000 | AQ |
| TP-183 | 4/27/21 | 0930 | AQ |
| TP-193 | 4/27/21 | 1030 | AQ |
| TP-172 | 4/27/21 | 1200 | AQ |

SUITE DESCRIPTION: WTP MOLYBDENUM MONITORING

| Analysis requested for the sample points listed. | Container(s) Volume, Type & Preservatives |
|---|---|
| (IC-ICP-MS) Molybdenum Speciation | 1 x 500 ml Poly Cool ≤ 4° C<br>(.45 micron field filtered) |

Special Instructions/Conditions of Receipt:

REC'D BAL 4/28/2 @ 1015

**5-10 Day Turn Around Time**

| 1. Relinquished By | Date | Time | 1. Received By | Date | Time |
|---|---|---|---|---|---|
| Mike Gelwick | 4-27-21 | 1500 | | | |
| 2. Relinquished By | Date | Time | 2. Received By | Date | Time |
| | | | | | |
| 3. Relinquished By | Date | Time | 3. Received By | Date | Time |
| | | | | | |

Sample shipment: X UPS: **1Z 19X 705 01 9048 8530**

Comments:
IX System pH: 4.0su
IX System flow rate: ~1.5gpm
IX System Total Eff: ~164500gal

COC QC

MICHAEL GELWICK
303-356-6559
PARSONS
3500 S. GUNCLUB RD
AURORA CO 80018

35 LBS 1 OF 1

SHIP TO:
SAMPLE RECEIVING
1-206-632-6206
BROOKS APPLIED LABS
SUITE 100
18804 NORTH CREEK PARKWAY
BOTHELL WA 98011




Reference No.1: 452483/60080
Reference No.2: Lowry Landfill
XOL 21 03.15 NV45 45 0A 04/2021*

## Sample Receipt Checklist:

**Container Type:**

- [x] Cooler
- [ ] Cardboard box
- [ ] Styrofoam cooler
- [ ] Other (Specify):

- [x] Custody Seal Present?
  Custody Seal Intact? (Y)/ N
- [x] Chain of Custody Present?

**Coolant and Temperature**

Coolant Type IR#: 31

- [ ] None
- [ ] Blue Ice: °C
- [x] Ice: 2.6 °C
- [ ] Dry Ice: °C
- [ ] Temp Blank: °C

Corrected Temp: 1.6 °C

*Coolant Note:*

**Bottle Type:**

- [x] Client Provided 500mL HDPE
- [ ] Class :
  Size / Type: No plbs.
  Lot:
  Preservation:
  Preservative Lot:
- [ ] Class :
  Size / Type:
  Lot:
  Preservation:
  Preservative Lot:
- [ ] Class :
  Size / Type:
  Lot:
  Preservation:
  Preservative Lot:

**All information accurate**
Initial/date: ADN 4/28/21

# Chain of Custody

| PARSONS | CHAIN OF CUSTODY # |
|---|---|
| 1776 LINCOLN SUITE 600<br>DENVER, CO 80203<br>(303) 831-8100 FAX (303) 831-8208<br>CONTACT: LYN BRILL<br>LYN.BRILL@PARSONS.COM<br>PROJECT: LOWRY ENVIRONMENTAL PROTECTION/CLEANUP TRUST WTP<br>452483.60080 | 4292021522 5<br><br>LAB CONTACT: BEN WOZNIAK<br>BROOKS APPLIED LABS, BOTHELL, WA |

| SAMPLE ID | DATE | TIME | MATRIX |
|---|---|---|---|
| TP-170 | 4/29/21 | 1255 | AQ |
| TP-173A | 4/29/21 | 1200 | AQ |
| TP-174A | 4/29/21 | 1140 | AQ |
| TP-183 | 4/29/21 | 1155 | AQ |
| TP-172 | 4/29/21 | 1230 | AQ |
| TP-175A | 4/29/21 | 1115 | AQ |

SUITE DESCRIPTION: WTP MOLYBDENUM MONITORING

| Analysis requested for the sample points listed. | Container(s) Volume, Type & Preservatives |
|---|---|
| (IC-ICP-MS) Molybdenum Speciation | 1 x 500 ml Poly Cool ≤ 4° C (.45 micron field filtered) |

Special Instructions/Conditions of Receipt:

**5-10 Day Turn Around Time**

| 1. Relinquished By | Date | Time | 1. Received By | Date | Time |
|---|---|---|---|---|---|
| Mike Gelwick | 4-29-21 | 1345 | Shaila Priscilla | 4/30/21 | 10:17 |
| 2. Relinquished By | Date | Time | 2. Received By | Date | Time |
| 3. Relinquished By | Date | Time | 3. Received By | Date | Time |

Sample shipment: X UPS: **1Z 19X 705 01 9072 8557**

Comments:
IX System pH: 5.0su
IX System flow rate: ~1.5gpm
IX System Total Eff: ~~gal~~ 168825 gal

COC QC

MICHAEL GELWICK
303-356-6559
PARSONS
3500 S. GUNCLUB RD
AURORA CO 80018

30 LBS

1 OF 1

SHIP TO:
SAMPLE RECEIVING
1-206-632-6206
BROOKS APPLIED LABS
STE 100
18804 N CREEK PKWY
BOTHELL WA 98011-8024

WA 982 9-36

UPS NEXT DAY AIR 1

TRACKING #: 1Z 19X 705 01 9072 8557

BILLING: P/P

Reference No.1: 452483/60080
Reference No.2: Lowry Landfill
XOL 21 03.15 NV45 45 0A 04/2021*

## Sample Receipt Checklist:

**Container Type:**

- [x] Cooler
- [ ] Cardboard box
- [ ] Styrofoam cooler
- [ ] Other (Specify):

- [ ] Custody Seal Present?
- Custody Seal Intact? Y / N
- [x] Chain of Custody Present?

**Coolant and Temperature**

Coolant Type IR#: 30

- [ ] None
- [ ] Blue Ice: °C
- [x] Ice: -0.4 °C
- [ ] Dry Ice: °C
- [ ] Temp Blank: °C

Corrected Temp: °C

*Coolant Note:*

**Bottle Type:**

- [x] Client Provided
- [ ] Class :
  - Size / Type:
  - Lot:
  - Preservation:
  - Preservative Lot:
- [ ] Class :
  - Size / Type:
  - Lot:
  - Preservation:
  - Preservative Lot:
- [ ] Class :
  - Size / Type:
  - Lot:
  - Preservation:
  - Preservative Lot:

**All information accurate**

Initial/date:

SP / 4-30-21

BROOKS APPLIED LABS
18804 North Creek Parkway, Ste 100, Bothell, WA 98011 • USA • T: 206 632 6206 F: 206 632 6017 • info@brooksapplied.com

May 14, 2021

Parsons
Attn: Lyn Brill
1776 Lincoln Suite 600
Denver, CO 80203
Lyn.Brill@Parsons.com

RE: Lowry Environmental Protection Cleanup Trust WTP 452483.60080

Dr. Brill,

Brooks Applied Labs (BAL) received eight field-filtered aqueous samples requesting molybdenum (Mo) speciation on May 4, 2021. All samples were received in acceptable condition and stored according to BAL SOPs.

*Dissolved Mo Speciation by IC-ICP-CRC-MS*
Each submitted sample was analyzed for molybdenum species using ion chromatography inductively coupled plasma collision reaction cell mass spectrometry (IC-ICP-CRC-MS) on May 5, 2021. Mo species are chromatographically separated on an ion exchange column and then quantified using inductively coupled plasma collision reaction cell mass spectrometry (ICP-CRC-MS). The instrument response was calibrated using a known molybdate [Mo(VI)] standard and any unidentified Mo species [Sum Unk. Mo] were quantified using this Mo(VI) calibration curve.

*Dissolved Mo Quantitation by ICP-QQQ-MS*
An aliquot of each submitted sample was acidified to a pH < 2 using concentrated nitric acid and allowed to digest overnight. All samples were then analyzed for dissolved Mo on May 5, 2021 by a modified EPA Method 6020 employing inductively coupled plasma triple quadrupole mass spectrometry (ICP-QQQ-MS). The ICP-QQQ-MS uses advanced interference removal techniques to ensure accuracy of the sample results.

*Analytical Issues*
No significant analytical issues were encountered with either the Mo speciation or the dissolved Mo analyses.

BAL, an accredited laboratory, certifies that the reported results of all analyses for which BAL is NELAP accredited meet all NELAP requirements.

Please contact us if you have any questions regarding this report.

Sincerely,

Ben Wozniak

Ben Wozniak
Technical Services
Ben@brooksapplied.com

Molybdenum Speciation for Parsons
Contact: Lyn Brill

Date: May 14, 2021
Report Generated by: Ben Wozniak
Brooks Applied Labs, LLC

Date Sampled: 05/03/2021 Date Received: 05/04/2021

**Client Sample ID**
**TP-170**

**Laboratory Sample ID**
**2105014-01**

| Analyte | Method | Concentration | MDL | MRL | Units |
|---|---|---|---|---|---|
| Diss Mo | EPA 6020 Mod. | 10900 | 69 | 200 | µg/L |
| Mo(VI) | IC-ICP-CRC-MS | 10600 | 13 | 130 | µg/L |
| Sum Unk. Mo | IC-ICP-CRC-MS | < 13 U | 13 | 130 | µg/L |

U = Sample concentration is below the MDL

J = Sample concentration is between the MDL and the MRL

Molybdenum Speciation for Parsons
Contact: Lyn Brill

Date: May 14, 2021
Report Generated by: Ben Wozniak
Brooks Applied Labs, LLC

Date Sampled: 05/03/2021 Date Received: 05/04/2021

**Client Sample ID**
**TP-173A**

**Laboratory Sample ID**
**2105014-02**

| Analyte | Method | Concentration | MDL | MRL | Units |
|---|---|---|---|---|---|
| Diss Mo | EPA 6020 Mod. | 10500 | 69 | 200 | µg/L |
| Mo(VI) | IC-ICP-CRC-MS | 10200 | 13 | 130 | µg/L |
| Sum Unk. Mo | IC-ICP-CRC-MS | < 13 U | 13 | 130 | µg/L |

U = Sample concentration is below the MDL

J = Sample concentration is between the MDL and the MRL

Molybdenum Speciation for Parsons
Contact: Lyn Brill

Date: May 14, 2021
Report Generated by: Ben Wozniak
Brooks Applied Labs, LLC

Date Sampled: 05/03/2021 Date Received: 05/04/2021

**Client Sample ID**
**TP-174A**

**Laboratory Sample ID**
**2105014-03**

| Analyte | Method | Concentration | MDL | MRL | Units |
|---|---|---|---|---|---|
| Diss Mo | EPA 6020 Mod. | 4980 | 69 | 200 | µg/L |
| Mo(VI) | IC-ICP-CRC-MS | 5240 | 5.0 | 50 | µg/L |
| Sum Unk. Mo | IC-ICP-CRC-MS | < 5.0 U | 5.0 | 50 | µg/L |

U = Sample concentration is below the MDL

J = Sample concentration is between the MDL and the MRL

Molybdenum Speciation for Parsons
Contact: Lyn Brill

Date: May 14, 2021
Report Generated by: Ben Wozniak
Brooks Applied Labs, LLC

Date Sampled: 05/03/2021 Date Received: 05/04/2021

**Client Sample ID**
**TP-183**

**Laboratory Sample ID**
**2105014-04**

| Analyte | Method | Concentration | MDL | MRL | Units |
|---|---|---|---|---|---|
| Diss Mo | EPA 6020 Mod. | 1310 | 69 | 200 | µg/L |
| Mo(VI) | IC-ICP-CRC-MS | 1320 | 5.0 | 50 | µg/L |
| Sum Unk. Mo | IC-ICP-CRC-MS | < 5.0 U | 5.0 | 50 | µg/L |

U = Sample concentration is below the MDL

J = Sample concentration is between the MDL and the MRL

Molybdenum Speciation for Parsons
Contact: Lyn Brill

Date: May 14, 2021
Report Generated by: Ben Wozniak
Brooks Applied Labs, LLC

Date Sampled: 05/03/2021 Date Received: 05/04/2021

**Client Sample ID**
**TP-175A**

**Laboratory Sample ID**
**2105014-05**

| Analyte | Method | Concentration | MDL | MRL | Units |
|---|---|---|---|---|---|
| Diss Mo | EPA 6020 Mod. | 4600 | 69 | 200 | µg/L |
| Mo(VI) | IC-ICP-CRC-MS | 4790 | 5.0 | 50 | µg/L |
| Sum Unk. Mo | IC-ICP-CRC-MS | < 5.0 U | 5.0 | 50 | µg/L |

U = Sample concentration is below the MDL

J = Sample concentration is between the MDL and the MRL

Molybdenum Speciation for Parsons
Contact: Lyn Brill

Date: May 14, 2021
Report Generated by: Ben Wozniak
Brooks Applied Labs, LLC

Date Sampled: 05/03/2021 Date Received: 05/04/2021

**Client Sample ID**
**TP-176A**

**Laboratory Sample ID**
**2105014-06**

| Analyte | Method | Concentration | MDL | MRL | Units |
|---|---|---|---|---|---|
| Diss Mo | EPA 6020 Mod. | 3530 | 69 | 200 | µg/L |
| Mo(VI) | IC-ICP-CRC-MS | 3640 | 5.0 | 50 | µg/L |
| Sum Unk. Mo | IC-ICP-CRC-MS | < 5.0 U | 5.0 | 50 | µg/L |

U = Sample concentration is below the MDL

J = Sample concentration is between the MDL and the MRL

Molybdenum Speciation for Parsons
Contact: Lyn Brill

Date: May 14, 2021
Report Generated by: Ben Wozniak
Brooks Applied Labs, LLC

Date Sampled: 05/03/2021 Date Received: 05/04/2021

**Client Sample ID**
**TP-193**

**Laboratory Sample ID**
**2105014-07**

| Analyte | Method | Concentration | MDL | MRL | Units |
|---|---|---|---|---|---|
| Diss Mo | EPA 6020 Mod. | 10300 | 69 | 200 | µg/L |
| Mo(VI) | IC-ICP-CRC-MS | 10300 | 13 | 130 | µg/L |
| Sum Unk. Mo | IC-ICP-CRC-MS | < 13 U | 13 | 130 | µg/L |

U = Sample concentration is below the MDL

J = Sample concentration is between the MDL and the MRL

Molybdenum Speciation for Parsons
Contact: Lyn Brill

Date: May 14, 2021
Report Generated by: Ben Wozniak
Brooks Applied Labs, LLC

Date Sampled: 05/03/2021 Date Received: 05/04/2021

**Client Sample ID**
**TP-172**

**Laboratory Sample ID**
**2105014-08**

| Analyte | Method | Concentration | MDL | MRL | Units |
|---|---|---|---|---|---|
| Diss Mo | EPA 6020 Mod. | 10400 | 69 | 200 | µg/L |
| Mo(VI) | IC-ICP-CRC-MS | 10700 | 13 | 130 | µg/L |
| Sum Unk. Mo | IC-ICP-CRC-MS | < 13 U | 13 | 130 | µg/L |

U = Sample concentration is below the MDL

J = Sample concentration is between the MDL and the MRL

Molybdenum Speciation for Parsons
Contact: Lyn Brill

Date: May 14, 2021
Report Generated by: Ben Wozniak
Brooks Applied Labs, LLC

***Quality Control Summary - Method Blank Summary***

| Analyte | BLK1 | BLK2 | BLK3 | BLK4 | MDL | MRL | Units |
|---|---|---|---|---|---|---|---|
| Diss Mo | 0.000 | -0.001 | 0.000 | -0.001 | 0.034 | 0.10 | µg/L |
| Mo(VI) | 0.001 | 0.000 | 0.000 | 0.001 | 0.005 | 0.050 | µg/L |
| Sum Unk. Mo | 0.000 | 0.000 | 0.000 | 0.000 | 0.005 | 0.050 | µg/L |

Molybdenum Speciation for Parsons
Contact: Lyn Brill

Date: May 14, 2021
Report Generated by: Ben Wozniak
Brooks Applied Labs, LLC

***Quality Control Summary - Laboratory Control Sample (LCS)***

| Analyte | LCS | True Value | Result | Recovery (%) |
|---|---|---|---|---|
| Diss Mo | NIST 1643f | 115.3 | 114.4 | 99.2 |
| Mo(VI) | Blank Spike | 4.995 | 4.961 | 99.3 |

All results presented in µg/L

Molybdenum Speciation for Parsons
Contact: Lyn Brill

Date: May 14, 2021
Report Generated by: Ben Wozniak
Brooks Applied Labs, LLC

***Quality Control Summary - Matrix Duplicates***

| Analyte | Lab Sample ID | Native Result | Duplicate Result | Mean | RPD (%) |
|---|---|---|---|---|---|
| Diss Mo | Batch QC | 11298 | 11100 | 11199 | 1.8 |
| Mo(VI) | 2105014-06 | 3642 | 3839 | 3741 | 5.3 |
| Sum Unk. Mo | 2105014-06 | < 5.0 U | < 5.0 U | NC | NC |

All results presented in µg/L

U = Sample concentration is below the MDL

J = Sample concentration is between the MDL and the MRL

NC = Not Calculated (Result < RL)

Molybdenum Speciation for Parsons
Contact: Lyn Brill

Date: May 14, 2021
Report Generated by: Ben Wozniak
Brooks Applied Labs, LLC

***Quality Control Summary - Matrix Spike/ Matrix Spike Duplicate***

| Analyte | Lab Sample ID | Native Result | MS Spike Conc. | MS Result | MS Recov. (%) | MSD Spike Conc. | MSD Result | MSD Recov. (%) | RPD (%) |
|---|---|---|---|---|---|---|---|---|---|
| Diss Mo | Batch QC | 11298 | 2041 | 13090 | 87.8 | 2041 | 13050 | 85.8 | 0.3 |
| Mo(VI) | 2105014-06 | 3642 | 5000 | 8750 | 102.2 | 5000 | 8669 | 100.5 | 0.9 |

All results presented in µg/L

# Chain of Custody

| | |
|---|---|
| PARSONS<br>1776 LINCOLN SUITE 600<br>DENVER, CO 80203<br>(303) 831-8100 FAX (303) 831-8208<br>CONTACT: LYN BRILL<br>LYN.BRILL@PARSONS.COM<br>PROJECT: LOWRY ENVIRONMENTAL PROTECTION/CLEANUP TRUST WTP<br>452483.60080 | CHAIN OF CUSTODY #<br>5320215224<br><br>LAB CONTACT: BEN WOZNIAK<br>BROOKS APPLIED LABS, BOTHELL, WA |

| SAMPLE ID | DATE | TIME | MATRIX |
|---|---|---|---|
| TP-170 | 5/3/21 | 1100 | AQ |
| TP-173A | 5/3/21 | 1010 | AQ |
| TP-174A | 5/3/21 | 0945 | AQ |
| TP-183 | 5/3/21 | 0830 | AQ |
| TP-175A | 5/3/21 | 0925 | AQ |
| TP-176A | 5/3/21 | 0900 | AQ |
| TP-193 | 5/3/21 | 1010 | AQ |
| TP-172 | 5/3/21 | 1035 | AQ |

SUITE DESCRIPTION: WTP MOLYBDENUM MONITORING

| Analysis requested for the sample points listed. | Container(s) Volume, Type & Preservatives |
|---|---|
| (IC-ICP-MS) Molybdenum Speciation | 1 x 500 ml Poly Cool ≤ 4° C<br>(.45 micron field filtered) |

Special Instructions/Conditions of Receipt:

**5-10 Day Turn Around Time**

| 1. Relinquished By | Date | Time | 1. Received By | Date | Time |
|---|---|---|---|---|---|
| Mike Gelwick | 5-3-21 | 1410 | Spencer Shuleyer | 5/4/21 | 10:28 |
| 2. Relinquished By | Date | Time | 2. Received By | Date | Time |
| 3. Relinquished By | Date | Time | 3. Received By | Date | Time |

Sample shipment: X UPS: **1Z 19X 705 01 9714 6137**

Comments:
IX System pH: 4.5su
IX System flow rate: ~1.5gpm
IX System Total Eff: ~177,440gal

COC QC

MICHAEL GELWICK
303-356-6559
PARSONS
3500 S. GUNCLUB RD
AURORA CO 80018

30 LBS

1 OF 1

SHIP TO:
SAMPLE RECEIVING
BROOKS APPLIED LABS
STE 100
18804 N CREEK PKWY
BOTHELL WA 98011-8024

WA 982 9-36

UPS NEXT DAY AIR

TRACKING #: 1Z 19X 705 01 9714 6137

BILLING: P/P

Reference No.1: 452483/60080
Reference No.2: Lowry Landfill
XOL 21 03.15 NV45 45 0A 04/2021*

# Sample Receipt Checklist:

**Container Type:**

- [x] Cooler
- [ ] Cardboard box
- [ ] Styrofoam cooler
- [ ] Other (Specify):

- [x] Custody Seal Present?
- Custody Seal Intact? (Y / N)
- [x] Chain of Custody Present?

**Coolant and Temperature**

Coolant Type IR#: 30

- [ ] None
- [ ] Blue Ice: °C
- [x] Ice: 2.0 °C
- [ ] Dry Ice: °C
- [ ] Temp Blank: °C

Corrected Temp: °C

*Coolant Note:*

**Bottle Type:**

- [x] Client Provided
- [ ] Class :
  - Size / Type:
  - Lot:
  - Preservation:
  - Preservative Lot:
- [ ] Class :
  - Size / Type:
  - Lot:
  - Preservation:
  - Preservative Lot:
- [ ] Class :
  - Size / Type:
  - Lot:
  - Preservation:
  - Preservative Lot:

**All information accurate**

Initial/date: SKS 5/4/21

# APPENDIX B

# WASTE DISPOSAL RECORDS

# APPENDIX B-1

# SUMMARY OF WASTE DISPOSED

**TABLE B-1**
**SUMMARY OF WASTE DISPOSED AND TREATED OFFSITE**
**JULY THROUGH DECEMBER 2021 OPERATIONS AND MAINTENANCE STATUS REPORT**
**LOWRY LANDFILL SUPERFUND SITE**

| Date | Manifest No. | Waste Description | Quantity | Units | Facility | EPA Authorization[a/] |
|---|---|---|---|---|---|---|
| 8/23/2021 | 10722500 | WTP Sludge (Profile # 1004322) | 15 | CY[b/] | DADS[c/] | Not Required by WMP[d/] |
| 11/26/2021 | 10722501 | WTP Sludge (Profile # 1004322) | 15 | CY | DADS | Not Required by WMP |

a/ Acceptance of the treatment and disposal facility was obtained from EPA before shipment offsite.
EPA authorizations are maintained in the project files on site and are available for review.

b/ CY=cubic yards

c/ DADS=Denver Arapaho Disposal Site

d/ WMP=Waste Management Plan

# APPENDIX B-2

# WASTE MANIFESTS

WASTE MANAGEMENT

Denver Arapahoe Disposal
3500 S Gun Club , PO Box 460397
Aurora, CO, 80018
Ph: (720) 876-2620

Original
Ticket# 3860437

Customer Name JDSPROFESSIONALGROUP JDS PROF
Ticket Date 08/23/2021
Payment Type Credit Account
Manual Ticket#
Hauling Ticket#
Route
State Waste Code SW
Manifest 10722500
Destination
PO
Profile 1004322 (Spwaste Solid Oth)
Generator 125-LOWRYENVIRONMENTAL LOWRY ENVIRONMENTAL

Carrier DENVERARAP DENVER ARAPAHOE DISPOSAL
Vehicle# 1
Container
Driver
Check#
Billing # 0015317
Gen EPA ID
Grid
Volume

| | Time | Scale | Operator | Inbound | | |
|---|---|---|---|---|---|---|
| In | 08/23/2021 13:46:41 | Scale3 | dbusinge | | Gross | 56920 lb |
| Out | 08/23/2021 14:36:49 | Scale3 | dbusinge | | Tare | 32720 lb |
| | | | | | Net | 24200 lb |
| | | | | | Tons | 12.10 |

Comments

PLEASE MAKE SURE YOUR TICKET IS CORRECT BEFORE SIGNING.

| | Product | LD% | Qty | UOM | Rate | Fee | Amount | Origin |
|---|---|---|---|---|---|---|---|---|
| 1 | Spwaste Solid Oth- | 100 | 12.10 | Tons | | | | |
| 2 | RCR-P-Regulatory C | 100 | | % | | | | |
| 3 | FUEL-Fuel Surcharg | 100 | | % | | | | |
| 4 | EVF-P-Standard Env | 100 | | % | | | | |
| 5 | WWM-P650-Waste Wat | 100 | | % | | | | |

Total Fees
Total Ticket

Driver's Signature Nullmai Lalan

Nullmai Lalan

# NON-HAZARDOUS MANIFEST

WASTE MANAGEMENT

NON-HAZARDOUS MANIFEST | 1. Generator's US EPA ID No: COD980953723 | Manifest Doc No. | 2. Page 1 of: 1 | 3860437

3. Generator's Mailing Address:
LOWRY ENVIRONMENTAL PROTECTION
3500 S GUN CLUB RD
AURORA, CO 80018
4. Generator's Phone: 303-710-9419

Generator's Site Address (If different than mailing):

A. Manifest Number: WMNA 10722500

B. State Generator's ID:

5. Transporter 1 Company Name | 6. US EPA ID Number | C. State Transporter's ID | D. Transporter's Phone

7. Transporter 2 Company Name | 8. US EPA ID Number | E. State Transporter's ID | F. Transporter's Phone

9. Designated Facility Name and Site Address
DENVER ARAPAHOE DISPOSAL
3500 S GUNCLUB RD
AURORA, CO 80018

10. US EPA ID Number | G. State Facility ID | H. State Facility Phone: 720-876-2620

GENERATOR

| 11. Description of Waste Materials | 12. Containers No. | 12. Containers Type | 13. Total Quantity | 14. Unit Wt./Vol. | I. Misc. Comments |
|---|---|---|---|---|---|
| a. NON-REGULATED SOLID – WATER TREATMENT PLANT SLUDGE<br>WM Profile # 1004322 | 1 | Roll-off | 15 | yds | |
| b.<br>WM Profile # | | | | | |
| c.<br>WM Profile # | | | | | |

REGULATORY AGENCY:
**Colorado Department of Public Health and Environment**
**4300 Cherry Creek Drive South**
**Denver, CO 80222-1530**

J. Additional Descriptions for Materials Listed Above
ACCT #: D 15317 CUST NAME: JDS PROFESSIONAL GROUP

K. Disposal Location
Cell: 32 Level:
Grid:

15. Special Handling Instructions and Additional Information

Purchase Order # | EMERGENCY CONTACT / PHONE NO.: 1-800-424-9300 24HR TOLL FREE

16. GENERATOR'S CERTIFICATE:
I hereby certify that the above-described materials are not hazardous wastes as defined by CFR Part 261 or any applicable state law, have been fully and accurately described, classified and packaged and are in proper condition for transportation according to applicable regulations.

| Printed Name | Signature "On behalf of" | Month | Day | Year |
|---|---|---|---|---|
| Daniel Griffiths as agent of and on behalf of the bury trust | | 8 | 23 | 21 |

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

| Printed Name | Signature | Month | Day | Year |
|---|---|---|---|---|
| Nathaniel Lalas | | 8 | 23 | 21 |

18. Transporter 2 Acknowledgement of Receipt of Materials

| Printed Name | Signature | Month | Day | Year |
|---|---|---|---|---|
| | | | | |

FACILITY

19. Certificate of Final Treatment/Disposal
I certify, on behalf of the above listed treatment facility, that to the best of my knowledge, the above-described waste was managed in compliance with all applicable laws, regulations, permits and licenses on the dates listed above.

20. Facility Owner or Operator: Certification of receipt of non-hazardous materials covered by this manifest.

| Printed Name | Signature | Month | Day | Year |
|---|---|---|---|---|
| Dustin | | 8 | 25 | 21 |

White- TREATMENT, STORAGE, DISPOSAL FACILITY COPY
Blue- GENERATOR #2 COPY
Yellow- GENERATOR #1 COPY
Pink- FACILITY USE ONLY
Gold- TRANSPORTER #1 COPY

WASTE MANAGEMENT

# NON-HAZARDOUS MANIFEST

| NON-HAZARDOUS MANIFEST | 1. Generator's US EPA ID No. COD980953723 Manifest Doc No. | 2. Page 1 of 1 | 3922834 |
|---|---|---|---|
| 3. Generator's Mailing Address: LOWRY ENVIRONMENTAL PROTECTION 3500 S GUN CLUB RD AURORA, CO 80018 4. Generator's Phone 303-710-9419 | Generator's Site Address (if different than mailing): | A. Manifest Number WMNA | 10722501 |
| | | B. State Generator's ID | |
| 5. Transporter 1 Company Name WM NM406553 | 6. US EPA ID Number | C. State Transporter's ID | |
| 7. Transporter 2 Company Name | 8. US EPA ID Number | D. Transporter's Phone | |
| | | E. State Transporter's ID | |
| 9. Designated Facility Name and Site Address DENVER ARAPAHOE DISPOSAL 3500 S GUNCLUB RD AURORA, CO 80018 | 10. US EPA ID Number | F. Transporter's Phone | |
| | | G. State Facility ID | |
| | | H. State Facility Phone 720-876-2620 | |

| GENERATOR | 11. Description of Waste Materials | 12 Containers No. | 12 Containers Type | 13. Total Quantity | 14. Unit Wt./Vol. | I. Misc. Comments |
|---|---|---|---|---|---|---|
| | a. NON-REGULATED SOLID – WATER TREATMENT PLANT SLUDGE WM Profile # 1004322 | 1 | Roll-off | 15 | yd3 | |
| | b. WM Profile # | | | 11.57TN | | |
| | c. WM Profile # | | | | | |
| | REGULATORY AGENCY: Colorado Department of Public Health and Environment 4300 Cherry Creek Drive South Denver, CO 80222-1530 | | | | | |

J. Additional Descriptions for Materials Listed Above: ACCT #: D 15317 CUST NAME: JDS PROFESSIONAL GROUP

K. Disposal Location: 32 Cell Level Grid

15. Special Handling Instructions and Additional Information

Purchase Order # EMERGENCY CONTACT / PHONE NO.: 1-800-424-9300 24HR TOLL FREE

16. GENERATOR'S CERTIFICATE:

I hereby certify that the above-described materials are not hazardous wastes as defined by CFR Part 261 or any applicable state law, have been fully and accurately described, classified and packaged and are in proper condition for transportation according to applicable regulations.

| | Printed Name | Signature / On behalf of: | Month | Day | Year |
|---|---|---|---|---|---|
| GENERATOR | Daniel Griffiths | as agent of and on behalf of the Lowry Trust | 11 | 24 | 21 |
| TRANSPORTER | 17. Transporter 1 Acknowledgement of Receipt of Materials: Guy McMaster | | 11 | 26 | 21 |
| | 18. Transporter 2 Acknowledgement of Receipt of Materials: Printed Name | Signature | Month | Day | Year |
| FACILITY | 19. Certificate of Final Treatment/Disposal: I certify, on behalf of the above listed treatment facility, that to the best of my knowledge, the above-described waste was managed in compliance with all applicable laws, regulations, permits and licenses on the dates listed above. | | | | |
| | 20. Facility Owner or Operator: Certification of receipt of non-hazardous materials covered by this manifest. Printed Name | Signature | Month 11 | Day 26 | Year 21 |

White- TREATMENT, STORAGE, DISPOSAL FACILITY COPY Blue- GENERATOR #2 COPY Yellow- GENERATOR #1 COPY

Pink- FACILITY USE ONLY Gold- TRANSPORTER #1 COPY

WASTE MANAGEMENT

Denver Arapahoe Disposal
3500 S Gun Club , PO Box 460397
Aurora, CO, 80018
Ph: (720) 876-2620

Reprint
Ticket# 3922834

Customer Name JDSPROFESSIONALGROUP JDS PROF
Ticket Date 11/26/2021
Payment Type Credit Account
Manual Ticket#
Hauling Ticket#
Route
State Waste Code SW
Manifest 10722501
Destination
PO
Profile 1004322 (Spwaste Solid Oth)
Generator 125-LOWRYENVIRONMENTAL LOWRY ENVIRONMENTAL

Carrier WMNRO WMN - ROLLOFF
Vehicle# 406553
Container
Driver
Check#
Billing # 0015317
Gen EPA ID
Grid

Volume

| | Time | Scale | Operator | Inbound | | |
|---|---|---|---|---|---|---|
| In | 11/26/2021 12:44:56 | Scale3 | cmoran3 | | Gross | 56360 lb |
| Out | 11/26/2021 13:19:31 | Scale3 | cmoran3 | | Tare | 33220 lb |
| | | | | | Net | 23140 lb |
| | | | | | Tons | 11.57 |

Comments

PLEASE MAKE SURE YOUR TICKET IS CORRECT BEFORE SIGNING.

| | Product | LD% | Qty | UOM | Rate | Fee | Amount | Origin |
|---|---|---|---|---|---|---|---|---|
| 1 | Spwaste Solid Oth- | 100 | 11.57 | Tons | | | | |
| 2 | RCR-P-Regulatory C | 100 | | % | | | | |
| 3 | FUEL-Fuel Surcharg | 100 | | % | | | | |
| 4 | EVF-P-Standard Env | 100 | | % | | | | |
| 5 | WWM-P650-Waste Wat | 100 | | % | | | | |

Total Fees
Total Ticket

Driver`s Signature

# APPENDIX C

# GROUNDWATER

# APPENDIX C-1

# NEW MONITORING WELL LOGS

NO NEW MONITORING WELLS WERE INSTALLED FROM JULY TO DECEMBER 2021

# APPENDIX C-2

# MONITORING WELL HYDROGRAPHS

A folder containing the monitoring well hydrographs is included separately in this submittal

# APPENDIX C-3

# COMPLIANCE EVALUATION STATISTICAL TESTING AND ANALYTE STATISTICAL TREND ANALYSIS PLOTS

The material contained in this appendix represents the output of the statistical evaluations completed EPA's ProUCL Software and manual calculations for regression analysis.

# APPENDIX C-3.1

# COMPLIANCE EVALUATION STATISTICAL TESTING

## Data Summary Table

**TABLE C-3.1**
**COMPLIANCE WELL DATA FOR STATISTICS**
**JULY THROUGH DECEMBER 2021 OPERATIONS AND MAINTENANCE STATUS REPORT**
**LOWRY LANDFILL SUPERFUND SITE**

| Well ID | Constituent/Parameter | Date Sampled | Result | Qualifier[a/] | Units[b/] | Reporting Limit |
|---|---|---|---|---|---|---|
| B-313 | 1,4-Dioxane | 4/16/2019 | 14 | | ug/L | 0.9 |
| B-313 | 1,4-Dioxane | 7/16/2019 | 2.3 | | ug/l | 0.9 |
| B-313 | 1,4-Dioxane | 10/15/2019 | 7.2 | | ug/l | 0.9 |
| B-313 | 1,4-Dioxane | 1/28/2020 | 20 | | ug/L | 0.9 |
| B-313 | 1,4-Dioxane | 4/28/2020 | 21 | | ug/L | 0.9 |
| B-313 | 1,4-Dioxane | 7/28/2020 | 18 | | ug/L | 0.9 |
| B-313 | 1,4-Dioxane | 12/9/2020 | 17 | | ug/L | 0.9 |
| B-313 | 1,4-Dioxane | 2/17/2021 | 16 | | ug/L | 0.9 |
| B-313 | 1,4-Dioxane | 5/18/2021 | 15 | | ug/L | 0.9 |
| B-313 | 1,4-Dioxane | 11/16/2021 | 17 | | ug/L | 0.9 |
| B-313 | Nitrogen, Nitrate | 1/3/2019 | 21000 | | ug/L | 5000 |
| B-313 | Nitrogen, Nitrate | 4/16/2019 | 22000 | | ug/L | 10000 |
| B-313 | Nitrogen, Nitrate | 7/16/2019 | 47000 | | ug/L | 10000 |
| B-313 | Nitrogen, Nitrate | 10/17/2019 | 40000 | | ug/L | 2500 |
| B-313 | Nitrogen, Nitrate | 1/28/2020 | 30000 | | ug/L | 2500 |
| B-313 | Nitrogen, Nitrate | 4/28/2020 | 28000 | | ug/L | 10000 |
| B-313 | Nitrogen, Nitrate | 7/28/2020 | 32000 | | ug/L | 2500 |
| B-313 | Nitrogen, Nitrate | 2/17/2021 | 22000 | | ug/L | 2500 |
| B-313 | Nitrogen, Nitrate | 5/18/2021 | 39000 | J | ug/L | 500 |
| B-313 | Nitrogen, Nitrate | 8/12/2021 | 55000 | J | ug/L | 2500 |
| B-326-UD | 1,4-Dioxane | 8/26/2019 | 7 | | ug/l | 0.9 |
| B-326-UD | 1,4-Dioxane | 12/11/2019 | 7.1 | | ug/l | 0.9 |
| B-326-UD | 1,4-Dioxane | 2/12/2020 | 7.7 | | ug/L | 0.9 |
| B-326-UD | 1,4-Dioxane | 5/27/2020 | 6.9 | | ug/L | 0.9 |
| B-326-UD | 1,4-Dioxane | 9/2/2020 | 6.7 | | ug/L | 0.9 |
| B-326-UD | 1,4-Dioxane | 12/10/2020 | 6.4 | | ug/L | 0.9 |
| B-326-UD | 1,4-Dioxane | 2/4/2021 | 6.7 | | ug/L | 0.9 |
| B-326-UD | 1,4-Dioxane | 6/1/2021 | 6 | | ug/L | 0.9 |
| B-326-UD | 1,4-Dioxane | 8/30/2021 | 6.1 | | ug/L | 0.9 |
| B-326-UD | 1,4-Dioxane | 10/12/2021 | 5 | | ug/L | 0.9 |
| B-326-UD | Nitrogen, Nitrate | 4/28/2015 | 19000 | | ug/L | 2500 |
| B-326-UD | Nitrogen, Nitrate | 5/1/2017 | 40000 | | ug/L | 2500 |
| B-326-UD | Nitrogen, Nitrate | 7/31/2018 | 66000 | | ug/L | 5000 |
| B-326-UD | Nitrogen, Nitrate | 3/21/2019 | 49000 | | ug/L | 2500 |
| B-326-UD | Nitrogen, Nitrate | 6/17/2019 | 9300 | | ug/L | 500 |
| B-326-UD | Nitrogen, Nitrate | 8/26/2019 | 990 | | ug/L | 500 |
| B-326-UD | Nitrogen, Nitrate | 12/11/2019 | 700 | | ug/L | 500 |
| B-326-UD | Nitrogen, Nitrate | 2/12/2020 | 730 | | ug/L | 500 |
| B-326-UD | Nitrogen, Nitrate | 9/2/2020 | 90 | U | ug/L | 500 |
| B-326-UD | Nitrogen, Nitrate | 2/4/2021 | 90 | U | ug/L | 500 |
| B-326-WD | 1,4-Dioxane | 8/26/2019 | 10 | | ug/l | 0.9 |
| B-326-WD | 1,4-Dioxane | 12/11/2019 | 8.8 | | ug/l | 0.9 |
| B-326-WD | 1,4-Dioxane | 2/12/2020 | 10 | | ug/L | 0.9 |
| B-326-WD | 1,4-Dioxane | 5/28/2020 | 11 | | ug/L | 0.9 |
| B-326-WD | 1,4-Dioxane | 8/26/2020 | 3.5 | | ug/L | 0.9 |
| B-326-WD | 1,4-Dioxane | 11/23/2020 | 3.9 | | ug/L | 0.9 |
| B-326-WD | 1,4-Dioxane | 2/3/2021 | 17 | | ug/L | 0.9 |
| B-326-WD | 1,4-Dioxane | 6/1/2021 | 7.5 | | ug/L | 0.9 |
| B-326-WD | 1,4-Dioxane | 8/30/2021 | 0.77 | J | ug/L | 0.9 |
| B-326-WD | 1,4-Dioxane | 10/12/2021 | 1 | | ug/L | 0.9 |
| BM-11X-100N | Tetrachloroethene | 4/20/2017 | 5.1 | | ug/L | 1 |
| BM-11X-100N | Tetrachloroethene | 10/20/2017 | 4.6 | | ug/L | 1 |

**TABLE C-3.1**
**COMPLIANCE WELL DATA FOR STATISTICS**
**JULY THROUGH DECEMBER 2021 OPERATIONS AND MAINTENANCE STATUS REPORT**
**LOWRY LANDFILL SUPERFUND SITE**

| Well ID | Constituent/Parameter | Date Sampled | Result | Qualifier[a/] | Units[b/] | Reporting Limit |
|---|---|---|---|---|---|---|
| BM-11X-100N | Tetrachloroethene | 4/17/2018 | 5.9 | | ug/L | 1 |
| BM-11X-100N | Tetrachloroethene | 10/12/2018 | 6.3 | | ug/L | 1 |
| BM-11X-100N | Tetrachloroethene | 4/23/2019 | 6.5 | | ug/L | 1 |
| BM-11X-100N | Tetrachloroethene | 10/14/2019 | 6.8 | | ug/L | 1 |
| BM-11X-100N | Tetrachloroethene | 4/30/2020 | 6.9 | | ug/L | 1 |
| BM-11X-100N | Tetrachloroethene | 11/16/2020 | 7.2 | | ug/L | 1 |
| BM-11X-100N | Tetrachloroethene | 5/6/2021 | 6 | J | ug/L | 1 |
| BM-11X-100N | Tetrachloroethene | 10/28/2021 | 5.4 | | ug/L | 1 |
| BM-11X-100N | Trichloroethene | 4/20/2017 | 4.5 | | ug/L | 1 |
| BM-11X-100N | Trichloroethene | 10/20/2017 | 3.6 | | ug/L | 1 |
| BM-11X-100N | Trichloroethene | 4/17/2018 | 4.7 | | ug/L | 1 |
| BM-11X-100N | Trichloroethene | 10/12/2018 | 4.5 | | ug/L | 1 |
| BM-11X-100N | Trichloroethene | 4/23/2019 | 4.3 | | ug/L | 1 |
| BM-11X-100N | Trichloroethene | 10/14/2019 | 4.9 | | ug/L | 1 |
| BM-11X-100N | Trichloroethene | 4/30/2020 | 5 | | ug/L | 1 |
| BM-11X-100N | Trichloroethene | 11/16/2020 | 5.7 | | ug/L | 1 |
| BM-11X-100N | Trichloroethene | 5/6/2021 | 5.5 | | ug/L | 1 |
| BM-11X-100N | Trichloroethene | 10/28/2021 | 4.8 | | ug/L | 1 |
| BM-15N6 | Nitrogen, Nitrate | 4/25/2017 | 46000 | | ug/L | 5000 |
| BM-15N6 | Nitrogen, Nitrate | 10/24/2017 | 43000 | | ug/L | 2500 |
| BM-15N6 | Nitrogen, Nitrate | 4/23/2018 | 42000 | | ug/L | 5000 |
| BM-15N6 | Nitrogen, Nitrate | 10/19/2018 | 49000 | | ug/L | 10000 |
| BM-15N6 | Nitrogen, Nitrate | 4/26/2019 | 35000 | | ug/L | 10000 |
| BM-15N6 | Nitrogen, Nitrate | 12/12/2019 | 42000 | J | ug/L | 500 |
| BM-15N6 | Nitrogen, Nitrate | 5/13/2020 | 35000 | | ug/L | 2500 |
| BM-15N6 | Nitrogen, Nitrate | 2/23/2021 | 32000 | | ug/L | 5000 |
| BM-15N6 | Nitrogen, Nitrate | 4/22/2021 | 31000 | | ug/L | 2500 |
| BM-15N6 | Nitrogen, Nitrate | 10/13/2021 | 30000 | | ug/L | 5000 |
| GW-109 | 1,4-Dioxane | 5/31/2016 | 2.1 | | ug/L | 0.9 |
| GW-109 | 1,4-Dioxane | 11/2/2016 | 3.3 | | ug/L | 0.9 |
| GW-109 | 1,4-Dioxane | 5/10/2017 | 0.76 | J | ug/L | 0.9 |
| GW-109 | 1,4-Dioxane | 10/27/2017 | 0.95 | | ug/L | 0.9 |
| GW-109 | 1,4-Dioxane | 5/4/2018 | 0.54 | J | ug/L | 0.9 |
| GW-109 | 1,4-Dioxane | 7/31/2018 | 0.54 | J | ug/L | 0.9 |
| GW-109 | 1,4-Dioxane | 1/3/2019 | 0.53 | J | ug/L | 0.9 |
| GW-109 | 1,4-Dioxane | 4/16/2019 | 9.7 | | ug/L | 0.9 |
| GW-109 | 1,4-Dioxane | 3/2/2020 | 41 | | ug/L | 0.9 |
| GW-109 | 1,4-Dioxane | 6/1/2020 | 20 | | ug/L | 0.9 |
| GW-109 | Bromodichloromethane | 11/16/2015 | 2.8 | | ug/L | 1 |
| GW-109 | Bromodichloromethane | 5/31/2016 | 0.44 | J | ug/L | 1 |
| GW-109 | Bromodichloromethane | 11/2/2016 | 0.17 | U | ug/L | 1 |
| GW-109 | Bromodichloromethane | 5/10/2017 | 0.17 | U | ug/L | 1 |
| GW-109 | Bromodichloromethane | 10/27/2017 | 0.17 | U | ug/L | 1 |
| GW-109 | Bromodichloromethane | 5/4/2018 | 0.17 | U | ug/L | 1 |
| GW-109 | Bromodichloromethane | 7/31/2018 | 0.17 | U | ug/L | 1 |
| GW-109 | Bromodichloromethane | 1/3/2019 | 0.17 | U | ug/L | 1 |
| GW-109 | Bromodichloromethane | 4/16/2019 | 0.17 | U | ug/L | 1 |
| GW-109 | Bromodichloromethane | 6/1/2020 | 0.17 | U | ug/L | 1 |
| GW-109 | Chloroform | 11/16/2015 | 4.4 | | ug/L | 1 |
| GW-109 | Chloroform | 5/31/2016 | 0.81 | J | ug/L | 1 |
| GW-109 | Chloroform | 11/2/2016 | 0.3 | J | ug/L | 1 |
| GW-109 | Chloroform | 5/10/2017 | 0.16 | U | ug/L | 1 |

**TABLE C-3.1**
**COMPLIANCE WELL DATA FOR STATISTICS**
**JULY THROUGH DECEMBER 2021 OPERATIONS AND MAINTENANCE STATUS REPORT**
**LOWRY LANDFILL SUPERFUND SITE**

| Well ID | Constituent/Parameter | Date Sampled | Result | Qualifier[a/] | Units[b/] | Reporting Limit |
|---|---|---|---|---|---|---|
| GW-109 | Chloroform | 10/27/2017 | 0.16 | U | ug/L | 1 |
| GW-109 | Chloroform | 5/4/2018 | 0.16 | U | ug/L | 1 |
| GW-109 | Chloroform | 7/31/2018 | 0.16 | U | ug/L | 1 |
| GW-109 | Chloroform | 1/3/2019 | 0.16 | U | ug/L | 1 |
| GW-109 | Chloroform | 4/16/2019 | 0.16 | U | ug/L | 1 |
| GW-109 | Chloroform | 6/1/2020 | 0.16 | U | ug/L | 1 |
| MW106-UD | 1,4-Dioxane | 11/21/2006 | 0.5 | U | ug/l | 5 |
| MW106-UD | 1,4-Dioxane | 2/28/2007 | 6.5 | | ug/l | 5 |
| MW106-UD | 1,4-Dioxane | 5/25/2007 | 0.5 | U | ug/l | 5 |
| MW106-UD | 1,4-Dioxane | 8/12/2009 | 0.5 | U | ug/l | 5 |
| MW106-UD | 1,4-Dioxane | 7/26/2011 | 0.5 | U | ug/l | 5 |
| MW106-UD | 1,4-Dioxane | 8/1/2013 | 0.5 | U | ug/l | 5 |
| MW106-UD | 1,4-Dioxane | 7/13/2015 | 0.5 | U | ug/l | 5 |
| MW106-UD | 1,4-Dioxane | 7/26/2017 | 0.15 | U | ug/L | 0.9 |
| MW106-UD | 1,4-Dioxane | 8/9/2018 | 0.15 | U | ug/L | 0.9 |
| MW106-UD | 1,4-Dioxane | 8/26/2020 | 0.09 | U | ug/L | 0.9 |
| MW23-C-SD | 1,4-Dioxane | 3/15/2006 | 0.5 | U | ug/l | 5 |
| MW23-C-SD | 1,4-Dioxane | 8/21/2007 | 0.5 | UJ | ug/l | 5 |
| MW23-C-SD | 1,4-Dioxane | 8/19/2009 | 0.5 | U | ug/l | 5 |
| MW23-C-SD | 1,4-Dioxane | 8/11/2011 | 0.5 | U | ug/l | 5 |
| MW23-C-SD | 1,4-Dioxane | 8/27/2013 | 0.5 | U | ug/l | 5 |
| MW23-C-SD | 1,4-Dioxane | 9/2/2015 | 0.15 | U | ug/L | 0.9 |
| MW23-C-SD | 1,4-Dioxane | 8/1/2017 | 0.15 | U | ug/L | 0.9 |
| MW23-C-SD | 1,4-Dioxane | 7/31/2018 | 0.15 | U | ug/L | 0.9 |
| MW23-C-SD | 1,4-Dioxane | 9/15/2020 | 1.4 | | ug/L | 0.9 |
| MW23-C-SD | 1,4-Dioxane | 2/18/2021 | 0.09 | U | ug/L | 0.9 |
| MW38-830N-230E | 1,4-Dioxane | 4/26/2017 | 12 | | ug/L | 0.9 |
| MW38-830N-230E | 1,4-Dioxane | 11/1/2017 | 12 | | ug/L | 0.9 |
| MW38-830N-230E | 1,4-Dioxane | 4/26/2018 | 9.3 | | ug/L | 0.9 |
| MW38-830N-230E | 1,4-Dioxane | 8/7/2018 | 13 | | ug/L | 0.9 |
| MW38-830N-230E | 1,4-Dioxane | 5/1/2019 | 7.1 | | ug/L | 0.9 |
| MW38-830N-230E | 1,4-Dioxane | 10/22/2019 | 2.4 | | ug/l | 0.9 |
| MW38-830N-230E | 1,4-Dioxane | 1/28/2020 | 2 | | ug/L | 0.9 |
| MW38-830N-230E | 1,4-Dioxane | 11/12/2020 | 2.1 | | ug/L | 0.9 |
| MW38-830N-230E | 1,4-Dioxane | 4/15/2021 | 4.5 | | ug/L | 0.9 |
| MW38-830N-230E | 1,4-Dioxane | 10/14/2021 | 4.6 | | ug/L | 0.9 |
| MW38-830N-230E | Chloroform | 4/26/2017 | 6.4 | | ug/L | 1 |
| MW38-830N-230E | Chloroform | 11/1/2017 | 6.9 | | ug/L | 1 |
| MW38-830N-230E | Chloroform | 4/26/2018 | 6.2 | | ug/L | 1 |
| MW38-830N-230E | Chloroform | 8/7/2018 | 5.9 | | ug/L | 1 |
| MW38-830N-230E | Chloroform | 5/1/2019 | 5.4 | | ug/L | 1 |
| MW38-830N-230E | Chloroform | 10/22/2019 | 2.1 | | ug/L | 1 |
| MW38-830N-230E | Chloroform | 1/28/2020 | 2.1 | | ug/L | 1 |
| MW38-830N-230E | Chloroform | 11/12/2020 | 2.6 | | ug/L | 1 |
| MW38-830N-230E | Chloroform | 4/15/2021 | 4.3 | | ug/L | 1 |
| MW38-830N-230E | Chloroform | 10/14/2021 | 3.7 | | ug/L | 1 |
| MW62-WDR | 1,4-Dioxane | 10/13/2017 | 4.6 | | ug/L | 0.9 |
| MW62-WDR | 1,4-Dioxane | 3/7/2018 | 3.9 | | ug/L | 0.9 |
| MW62-WDR | 1,4-Dioxane | 5/10/2018 | 4.2 | | ug/L | 0.9 |
| MW62-WDR | 1,4-Dioxane | 7/31/2018 | 3.8 | | ug/L | 0.9 |
| MW62-WDR | 1,4-Dioxane | 5/14/2019 | 3.9 | | ug/L | 0.9 |
| MW62-WDR | 1,4-Dioxane | 12/17/2019 | 3.5 | | ug/l | 0.9 |

**TABLE C-3.1**
**COMPLIANCE WELL DATA FOR STATISTICS**
**JULY THROUGH DECEMBER 2021 OPERATIONS AND MAINTENANCE STATUS REPORT**
**LOWRY LANDFILL SUPERFUND SITE**

| Well ID | Constituent/Parameter | Date Sampled | Result | Qualifier[a/] | Units[b/] | Reporting Limit |
|---|---|---|---|---|---|---|
| MW62-WDR | 1,4-Dioxane | 5/14/2020 | 3.4 | | ug/L | 0.9 |
| MW62-WDR | 1,4-Dioxane | 11/11/2020 | 3.2 | | ug/L | 0.9 |
| MW62-WDR | 1,4-Dioxane | 4/27/2021 | 3.3 | | ug/L | 0.9 |
| MW62-WDR | 1,4-Dioxane | 10/27/2021 | 3.2 | | ug/L | 0.9 |
| MW62-WDR | Nitrogen, Nitrate | 10/13/2017 | 120000 | | ug/L | 10000 |
| MW62-WDR | Nitrogen, Nitrate | 3/7/2018 | 110000 | | ug/L | 10000 |
| MW62-WDR | Nitrogen, Nitrate | 5/10/2018 | 120000 | | ug/L | 25000 |
| MW62-WDR | Nitrogen, Nitrate | 7/31/2018 | 120000 | | ug/L | 10000 |
| MW62-WDR | Nitrogen, Nitrate | 5/14/2019 | 120000 | | ug/L | 10000 |
| MW62-WDR | Nitrogen, Nitrate | 12/17/2019 | 120000 | | ug/L | 10000 |
| MW62-WDR | Nitrogen, Nitrate | 5/14/2020 | 130000 | | ug/L | 10000 |
| MW62-WDR | Nitrogen, Nitrate | 11/11/2020 | 130000 | J | ug/L | 2500 |
| MW62-WDR | Nitrogen, Nitrate | 4/27/2021 | 120000 | | ug/L | 25000 |
| MW62-WDR | Nitrogen, Nitrate | 10/27/2021 | 110000 | | ug/L | 25000 |
| MW62-WDR | Nitrogen, Nitrite | 10/13/2017 | 3600 | | ug/L | 500 |
| MW62-WDR | Nitrogen, Nitrite | 3/7/2018 | 5400 | | ug/L | 1000 |
| MW62-WDR | Nitrogen, Nitrite | 5/10/2018 | 4000 | | ug/L | 500 |
| MW62-WDR | Nitrogen, Nitrite | 7/31/2018 | 2400 | | ug/L | 1000 |
| MW62-WDR | Nitrogen, Nitrite | 5/14/2019 | 1900 | | ug/L | 1000 |
| MW62-WDR | Nitrogen, Nitrite | 12/17/2019 | 980 | U | ug/L | 10000 |
| MW62-WDR | Nitrogen, Nitrite | 5/14/2020 | 1500 | J | ug/L | 10000 |
| MW62-WDR | Nitrogen, Nitrite | 11/11/2020 | 890 | | ug/L | 500 |
| MW62-WDR | Nitrogen, Nitrite | 4/27/2021 | 1800 | | ug/L | 1000 |
| MW62-WDR | Nitrogen, Nitrite | 10/27/2021 | 2200 | | ug/L | 500 |
| MW77-WD | 1,4-Dioxane | 4/24/2017 | 20 | | ug/L | 0.9 |
| MW77-WD | 1,4-Dioxane | 10/26/2017 | 5.3 | | ug/L | 0.9 |
| MW77-WD | 1,4-Dioxane | 5/3/2018 | 9 | | ug/L | 0.9 |
| MW77-WD | 1,4-Dioxane | 8/2/2018 | 2.6 | | ug/L | 0.9 |
| MW77-WD | 1,4-Dioxane | 5/2/2019 | 3 | | ug/L | 0.9 |
| MW77-WD | 1,4-Dioxane | 10/22/2019 | 12 | | ug/l | 0.9 |
| MW77-WD | 1,4-Dioxane | 5/4/2020 | 5 | | ug/L | 0.9 |
| MW77-WD | 1,4-Dioxane | 10/28/2020 | 16 | | ug/L | 0.9 |
| MW77-WD | 1,4-Dioxane | 4/21/2021 | 4.3 | | ug/L | 0.9 |
| MW77-WD | 1,4-Dioxane | 10/27/2021 | 11 | | ug/L | 0.9 |

a/ Final Q definitions: U= The analyte was analyzed for and is not present above the level of the associated value. The associated numerical value indicates the approximate concentration necessary to detect the analyte in the sample. The associated value is the method detection limit as required by the statistical procedure in the GWMP

J= The analyte was analyzed for, and was positively identified, but the associated numerical value may not be consistent with the amount actually present in the environmental sample.

b/ µg/L = micrograms per liter

# APPENDIX C-3.2

# COMPLIANCE EVALUATION STATISTICAL TESTING

## Mann-Kendall Trend Analysis

| | | |
|---|---|---|
| **Mann-Kendall Trend Test Analysis** | | |
| User Selected Options | | |
| Date/Time of Computation | ProUCL 5.11/20/2022 2:12:37 PM | |
| From File | COMPLIANCE DATA 2H2021 for MK Trend.xls | |
| Full Precision | OFF | |
| Confidence Coefficient | 0.95 | |
| Level of Significance | 0.05 | |

**1,4-Dioxane-b-313**


**General Statistics**

| | |
|---|---|
| Number of Events Reported (m) | 10 |
| Number of Missing Events | 0 |
| Number or Reported Events Used | 10 |
| Number Values Reported (n) | 10 |
| Minimum | 2.3 |
| Maximum | 21 |
| Mean | 14.75 |
| Geometric Mean | 12.84 |
| Median | 16.5 |
| Standard Deviation | 5.788 |
| Coefficient of Variation | 0.392 |

**Mann-Kendall Test**

| | |
|---|---|
| M-K Test Value (S) | 6 |
| Tabulated p-value | 0.3 |
| Standard Deviation of S | 11.14 |
| Standardized Value of S | 0.449 |
| Approximate p-value | 0.327 |

**Insufficient evidence to identify a significant trend at the specified level of significance.**


Mann-Kendall Trend Test
1,4-Dioxane-b-313
20
17
14
11
8
5
2
43551
43751
43951
44151
44351
Sample Date-b-313
Mann-Kendall Trend Analysis
n 10
Confidence Coefficient 0.9500
Level of Significance 0.0500
Standard Deviation of S 11.1355
Standardized Value of S 0.4490
M-K Test Value (S) 6
Tabulated p-value 0.3000
Approximate p-value 0.3267
OLS Regression Line (Blue)
OLS Regression Slope 0.0087
OLS Regression Intercept -368.3533
Theil-Sen Trend Line (Red)
Theil-Sen Slope 0.0032
Theil-Sen Intercept -123.1651
Insufficient statistical evidence
of a significant trend at the
specified level of significance.

| | | |
|---|---|---|
| **Mann-Kendall Trend Test Analysis** | | |
| User Selected Options | | |
| Date/Time of Computation | ProUCL 5.11/20/2022 2:24:06 PM | |
| From File | COMPLIANCE DATA 2H2021 for MK Trend_b.xls | |
| Full Precision | OFF | |
| Confidence Coefficient | 0.95 | |
| Level of Significance | 0.05 | |

**Nitrogen, Nitrate-b-313**


**General Statistics**

| | |
|---|---|
| Number of Events Reported (m) | 10 |
| Number of Missing Events | 0 |
| Number or Reported Events Used | 10 |
| Number Values Reported (n) | 10 |
| Minimum | 21000 |
| Maximum | 55000 |
| Mean | 33600 |
| Geometric Mean | 31931 |
| Median | 31000 |
| Standard Deviation | 11462 |
| Coefficient of Variation | 0.341 |

**Mann-Kendall Test**

| | |
|---|---|
| M-K Test Value (S) | 14 |
| Tabulated p-value | 0.108 |
| Standard Deviation of S | 11.14 |
| Standardized Value of S | 1.167 |
| Approximate p-value | 0.122 |

**Insufficient evidence to identify a significant trend at the specified level of significance.**




**Mann-Kendall Trend Analysis**

| | |
|---|---|
| n | 10 |
| Confidence Coefficient | 0.9500 |
| Level of Significance | 0.0500 |
| Standard Deviation of S | 11.1355 |
| Standardized Value of S | 1.1674 |
| M-K Test Value (S) | 14 |
| Tabulated p-value | 0.1080 |
| Approximate p-value | 0.1215 |

**OLS Regression Line (Blue)**

| | |
|---|---|
| OLS Regression Slope | 14.8045 |
| OLS Regression Intercept | -616,761.4886 |

**Theil-Sen Trend Line (Red)**

| | |
|---|---|
| Theil-Sen Slope | 18.9076 |
| Theil-Sen Intercept | -799,108.1933 |

Insufficient statistical evidence of a significant trend at the specified level of significance.


| | | |
|---|---|---|
| **Mann-Kendall Trend Test Analysis** | | |
| User Selected Options | | |
| Date/Time of Computation | ProUCL 5.11/20/2022 2:12:37 PM | |
| From File | COMPLIANCE DATA 2H2021 for MK Trend.xls | |
| Full Precision | OFF | |
| Confidence Coefficient | 0.95 | |
| Level of Significance | 0.05 | |

**1,4-Dioxane-b-326-ud**

| **General Statistics** | |
|---|---|
| Number of Events Reported (m) | 10 |
| Number of Missing Events | 0 |
| Number or Reported Events Used | 10 |
| Number Values Reported (n) | 10 |
| Minimum | 5 |
| Maximum | 7.7 |
| Mean | 6.56 |
| Geometric Mean | 6.52 |
| Median | 6.7 |
| Standard Deviation | 0.74 |
| Coefficient of Variation | 0.113 |

| **Mann-Kendall Test** | |
|---|---|
| M-K Test Value (S) | -34 |
| Tabulated p-value | 0 |
| Standard Deviation of S | 11.14 |
| Standardized Value of S | -2.963 |
| Approximate p-value | 0.00152 |

**Statistically significant evidence of a decreasing trend at the specified level of significance.**




**Mann-Kendall Trend Analysis**

| | |
|---|---|
| n | 10 |
| Confidence Coefficient | 0.9500 |
| Level of Significance | 0.0500 |
| Standard Deviation of S | 11.1355 |
| Standardized Value of S | -2.9635 |
| M-K Test Value (S) | -34 |
| Tabulated p-value | 0.0000 |
| Approximate p-value | 0.0015 |

**OLS Regression Line (Blue)**

| | |
|---|---|
| OLS Regression Slope | -0.0023 |
| OLS Regression Intercept | 109.3515 |

**Theil-Sen Trend Line (Red)**

| | |
|---|---|
| Theil-Sen Slope | -0.0020 |
| Theil-Sen Intercept | 96.9194 |

Statistically significant evidence of a decreasing trend at the specified level of significance.

| | | |
|---|---|---|
| **Mann-Kendall Trend Test Analysis** | | |
| User Selected Options | | |
| Date/Time of Computation | ProUCL 5.11/20/2022 2:24:06 PM | |
| From File | COMPLIANCE DATA 2H2021 for MK Trend_b.xls | |
| Full Precision | OFF | |
| Confidence Coefficient | 0.95 | |
| Level of Significance | 0.05 | |

**Nitrogen, Nitrate-b-326-ud**


**General Statistics**

| | |
|---|---|
| Number of Events Reported (m) | 10 |
| Number of Missing Events | 0 |
| Number or Reported Events Used | 10 |
| Number Values Reported (n) | 10 |
| Minimum | 45 |
| Maximum | 66000 |
| Mean | 18581 |
| Geometric Mean | 2735 |
| Median | 5145 |
| Standard Deviation | 24390 |
| Coefficient of Variation | 1.313 |

**Mann-Kendall Test**

| | |
|---|---|
| M-K Test Value (S) | -32 |
| Tabulated p-value | 0.001 |
| Standard Deviation of S | 11.14 |
| Standardized Value of S | -2.784 |
| Approximate p-value | 0.00269 |

**Statistically significant evidence of a decreasing trend at the specified level of significance.**


Mann-Kendall Trend Test
58396
48396
38396
28396
18396
8396
-1604
Nitrogen, Nitrate-b-326-ud
42078
42478
42878
43278
43678
44078
Sample Date-b-326-ud
Mann-Kendall Trend Analysis
n 10
Confidence Coefficient 0.9500
Level of Significance 0.0500
Standard Deviation of S 11.1355
Standardized Value of S -2.7839
M-K Test Value (S) -32
Tabulated p-value 0.0010
Approximate p-value 0.0027
OLS Regression Line (Blue)
OLS Regression Slope -17.9985
OLS Regression Intercept 801,804.6923
Theil-Sen Trend Line (Red)
Theil-Sen Slope -20.8916
Theil-Sen Intercept 917,441.4786
Statistically significant evidence of a decreasing trend at the specified level of significance.


| | | |
|---|---|---|
| **Mann-Kendall Trend Test Analysis** | | |
| User Selected Options | | |
| Date/Time of Computation | ProUCL 5.11/20/2022 2:12:37 PM | |
| From File | COMPLIANCE DATA 2H2021 for MK Trend.xls | |
| Full Precision | OFF | |
| Confidence Coefficient | 0.95 | |
| Level of Significance | 0.05 | |

**1,4-Dioxane-b-326-wd**

| **General Statistics** | |
|---|---|
| Number of Events Reported (m) | 10 |
| Number of Missing Events | 0 |
| Number or Reported Events Used | 10 |
| Number Values Reported (n) | 10 |
| Minimum | 0.77 |
| Maximum | 17 |
| Mean | 7.347 |
| Geometric Mean | 5.144 |
| Median | 8.15 |
| Standard Deviation | 5.088 |
| Coefficient of Variation | 0.692 |

| **Mann-Kendall Test** | |
|---|---|
| M-K Test Value (S) | -16 |
| Tabulated p-value | 0.078 |
| Standard Deviation of S | 11.14 |
| Standardized Value of S | -1.347 |
| Approximate p-value | 0.089 |

**Insufficient evidence to identify a significant trend at the specified level of significance.**




**Mann-Kendall Trend Analysis**

| | |
|---|---|
| n | 10 |
| Confidence Coefficient | 0.9500 |
| Level of Significance | 0.0500 |
| Standard Deviation of S | 11.1355 |
| Standardized Value of S | -1.3470 |
| M-K Test Value (S) | -16 |
| Tabulated p-value | 0.0780 |
| Approximate p-value | 0.0890 |

**OLS Regression Line (Blue)**

| | |
|---|---|
| OLS Regression Slope | -0.0092 |
| OLS Regression Intercept | 411.4565 |

**Theil-Sen Trend Line (Red)**

| | |
|---|---|
| Theil-Sen Slope | -0.0112 |
| Theil-Sen Intercept | 501.2759 |

Insufficient statistical evidence of a significant trend at the specified level of significance.


| | | |
|---|---|---|
| **Mann-Kendall Trend Test Analysis** | | |
| User Selected Options | | |
| Date/Time of Computation | ProUCL 5.11/20/2022 2:30:51 PM | |
| From File | COMPLIANCE DATA 2H2021 for MK Trend_d.xls | |
| Full Precision | OFF | |
| Confidence Coefficient | 0.95 | |
| Level of Significance | 0.05 | |

**Tetrachloroethene-bm-11x-100n**

| **General Statistics** | |
|---|---|
| Number of Events Reported (m) | 10 |
| Number of Missing Events | 0 |
| Number or Reported Events Used | 10 |
| Number Values Reported (n) | 10 |
| Minimum | 4.6 |
| Maximum | 7.2 |
| Mean | 6.07 |
| Geometric Mean | 6.015 |
| Median | 6.15 |
| Standard Deviation | 0.838 |
| Coefficient of Variation | 0.138 |

| **Mann-Kendall Test** | |
|---|---|
| M-K Test Value (S) | 19 |
| Tabulated p-value | 0.054 |
| Standard Deviation of S | 11.18 |
| Standardized Value of S | 1.61 |
| Approximate p-value | 0.0537 |

**Insufficient evidence to identify a significant trend at the specified level of significance.**




**Mann-Kendall Trend Analysis**

| | |
|---|---|
| n | 10 |
| Confidence Coefficient | 0.9500 |
| Level of Significance | 0.0500 |
| Standard Deviation of S | 11.1803 |
| Standardized Value of S | 1.6100 |
| M-K Test Value (S) | 19 |
| Tabulated p-value | 0.0540 |
| Approximate p-value | 0.0537 |

**OLS Regression Line (Blue)**

| | |
|---|---|
| OLS Regression Slope | 0.0007 |
| OLS Regression Intercept | -24.1667 |

**Theil-Sen Trend Line (Red)**

| | |
|---|---|
| Theil-Sen Slope | 0.0011 |
| Theil-Sen Intercept | -41.0919 |

Insufficient statistical evidence of a significant trend at the specified level of significance.


| | | |
|---|---|---|
| **Mann-Kendall Trend Test Analysis** | | |
| User Selected Options | | |
| Date/Time of Computation | ProUCL 5.11/20/2022 2:32:47 PM | |
| From File | COMPLIANCE DATA 2H2021 for MK Trend_e.xls | |
| Full Precision | OFF | |
| Confidence Coefficient | 0.95 | |
| Level of Significance | 0.05 | |

**Trichloroethene-bm-11x-100n**

| **General Statistics** | |
|---|---|
| Number of Events Reported (m) | 10 |
| Number of Missing Events | 0 |
| Number or Reported Events Used | 10 |
| Number Values Reported (n) | 10 |
| Minimum | 3.6 |
| Maximum | 5.7 |
| Mean | 4.75 |
| Geometric Mean | 4.715 |
| Median | 4.75 |
| Standard Deviation | 0.597 |
| Coefficient of Variation | 0.126 |

| **Mann-Kendall Test** | |
|---|---|
| M-K Test Value (S) | 24 |
| Tabulated p-value | 0.014 |
| Standard Deviation of S | 11.14 |
| Standardized Value of S | 2.065 |
| Approximate p-value | 0.0194 |

**Statistically significant evidence of an increasing trend at the specified level of significance.**




**Mann-Kendall Trend Analysis**

| | |
|---|---|
| n | 10 |
| Confidence Coefficient | 0.9500 |
| Level of Significance | 0.0500 |
| Standard Deviation of S | 11.1355 |
| Standardized Value of S | 2.0655 |
| M-K Test Value (S) | 24 |
| Tabulated p-value | 0.0140 |
| Approximate p-value | 0.0194 |

**OLS Regression Line (Blue)**

| | |
|---|---|
| OLS Regression Slope | 0.0008 |
| OLS Regression Intercept | -28.5146 |

**Theil-Sen Trend Line (Red)**

| | |
|---|---|
| Theil-Sen Slope | 0.0007 |
| Theil-Sen Intercept | -26.5791 |

Statistically significant evidence of an increasing trend at the specified level of significance.

| | | |
|---|---|---|
| **Mann-Kendall Trend Test Analysis** | | |
| User Selected Options | | |
| Date/Time of Computation | ProUCL 5.11/20/2022 2:24:06 PM | |
| From File | COMPLIANCE DATA 2H2021 for MK Trend_b.xls | |
| Full Precision | OFF | |
| Confidence Coefficient | 0.95 | |
| Level of Significance | 0.05 | |

**Nitrogen, Nitrate-bm-15n6**


**General Statistics**

| | |
|---|---|
| Number of Events Reported (m) | 10 |
| Number of Missing Events | 0 |
| Number or Reported Events Used | 10 |
| Number Values Reported (n) | 10 |
| Minimum | 30000 |
| Maximum | 49000 |
| Mean | 38500 |
| Geometric Mean | 37972 |
| Median | 38500 |
| Standard Deviation | 6721 |
| Coefficient of Variation | 0.175 |

**Mann-Kendall Test**

| | |
|---|---|
| M-K Test Value (S) | -35 |
| Tabulated p-value | 0 |
| Standard Deviation of S | 11.09 |
| Standardized Value of S | -3.066 |
| Approximate p-value | 0.00109 |

**Statistically significant evidence of a decreasing trend at the specified level of significance.**




**Mann-Kendall Trend Analysis**

| | |
|---|---|
| n | 10 |
| Confidence Coefficient | 0.9500 |
| Level of Significance | 0.0500 |
| Standard Deviation of S | 11.0905 |
| Standardized Value of S | -3.0657 |
| M-K Test Value (S) | -35 |
| Tabulated p-value | 0.0000 |
| Approximate p-value | 0.0011 |

**OLS Regression Line (Blue)**

| | |
|---|---|
| OLS Regression Slope | -10.1486 |
| OLS Regression Intercept | 481,876.6267 |

**Theil-Sen Trend Line (Red)**

| | |
|---|---|
| Theil-Sen Slope | -9.8039 |
| Theil-Sen Intercept | 466,892.1569 |

Statistically significant evidence of a decreasing trend at the specified level of significance.

| | | |
|---|---|---|
| | **Mann-Kendall Trend Test Analysis** | |
| User Selected Options | | |
| Date/Time of Computation | ProUCL 5.11/20/2022 2:12:37 PM | |
| From File | COMPLIANCE DATA 2H2021 for MK Trend.xls | |
| Full Precision | OFF | |
| Confidence Coefficient | 0.95 | |
| Level of Significance | 0.05 | |

**1,4-Dioxane-mw23-c-sd**


**General Statistics**

| | |
|---|---|
| Number of Events Reported (m) | 10 |
| Number of Missing Events | 0 |
| Number or Reported Events Used | 10 |
| Number Values Reported (n) | 10 |
| Minimum | 0.045 |
| Maximum | 1.4 |
| Mean | 0.292 |
| Geometric Mean | 0.174 |
| Median | 0.25 |
| Standard Deviation | 0.4 |
| Coefficient of Variation | 1.369 |

**Mann-Kendall Test**

| | |
|---|---|
| M-K Test Value (S) | -16 |
| Tabulated p-value | 0.078 |
| Standard Deviation of S | 10.23 |
| Standardized Value of S | -1.466 |
| Approximate p-value | 0.0713 |

**Insufficient evidence to identify a significant trend at the specified level of significance.**




**Mann-Kendall Trend Analysis**

| | |
|---|---|
| n | 10 |
| Confidence Coefficient | 0.9500 |
| Level of Significance | 0.0500 |
| Standard Deviation of S | 10.2307 |
| Standardized Value of S | -1.4662 |
| M-K Test Value (S) | -16 |
| Tabulated p-value | 0.0780 |
| Approximate p-value | 0.0713 |

**OLS Regression Line (Blue)**

| | |
|---|---|
| OLS Regression Slope | 0.0000 |
| OLS Regression Intercept | -1.6682 |

**Theil-Sen Trend Line (Red)**

| | |
|---|---|
| Theil-Sen Slope | 0.0000 |
| Theil-Sen Intercept | 1.2187 |

Insufficient statistical evidence of a significant trend at the specified level of significance.


| | | |
|---|---|---|
| **Mann-Kendall Trend Test Analysis** | | |
| User Selected Options | | |
| Date/Time of Computation | ProUCL 5.11/20/2022 2:12:37 PM | |
| From File | COMPLIANCE DATA 2H2021 for MK Trend.xls | |
| Full Precision | OFF | |
| Confidence Coefficient | 0.95 | |
| Level of Significance | 0.05 | |

**1,4-Dioxane-mw38-830n-230e**

| **General Statistics** | |
|---|---|
| Number of Events Reported (m) | 10 |
| Number of Missing Events | 0 |
| Number or Reported Events Used | 10 |
| Number Values Reported (n) | 10 |
| Minimum | 2 |
| Maximum | 13 |
| Mean | 6.9 |
| Geometric Mean | 5.51 |
| Median | 5.85 |
| Standard Deviation | 4.389 |
| Coefficient of Variation | 0.636 |

| **Mann-Kendall Test** | |
|---|---|
| M-K Test Value (S) | -22 |
| Tabulated p-value | 0.023 |
| Standard Deviation of S | 11.14 |
| Standardized Value of S | -1.886 |
| Approximate p-value | 0.0297 |

**Statistically significant evidence of a decreasing trend at the specified level of significance.**


Mann-Kendall Trend Test
1,4-Dioxane-mw38-830n-230e
12
10
8
6
4
2
42817
43067
43317
43567
43817
44067
44317
Sample Date-mw38-830n-230e
Mann-Kendall Trend Analysis
n 10
Confidence Coefficient 0.9500
Level of Significance 0.0500
Standard Deviation of S 11.1355
Standardized Value of S -1.8859
M-K Test Value (S) -22
Tabulated p-value 0.0230
Approximate p-value 0.0297
OLS Regression Line (Blue)
OLS Regression Slope -0.0065
OLS Regression Intercept 288.7180
Theil-Sen Trend Line (Red)
Theil-Sen Slope -0.0059
Theil-Sen Intercept 265.6022
Statistically significant evidence of a decreasing trend at the specified level of significance.

| | | |
|---|---|---|
| **Mann-Kendall Trend Test Analysis** | | |
| User Selected Options | | |
| Date/Time of Computation | ProUCL 5.11/20/2022 2:22:20 PM | |
| From File | COMPLIANCE DATA 2H2021 for MK Trend_a.xls | |
| Full Precision | OFF | |
| Confidence Coefficient | 0.95 | |
| Level of Significance | 0.05 | |

**Chloroform-mw38-830n-230e**


**General Statistics**

| | |
|---|---|
| Number of Events Reported (m) | 10 |
| Number of Missing Events | 0 |
| Number or Reported Events Used | 10 |
| Number Values Reported (n) | 10 |
| Minimum | 2.1 |
| Maximum | 6.9 |
| Mean | 4.56 |
| Geometric Mean | 4.17 |
| Median | 4.85 |
| Standard Deviation | 1.85 |
| Coefficient of Variation | 0.406 |

**Mann-Kendall Test**

| | |
|---|---|
| M-K Test Value (S) | -26 |
| Tabulated p-value | 0.008 |
| Standard Deviation of S | 11.14 |
| Standardized Value of S | -2.245 |
| Approximate p-value | 0.0124 |

**Statistically significant evidence of a decreasing trend at the specified level of significance.**


Mann-Kendall Trend Test
Chloroform-mw38-830n-230e
7
6
5
4
3
2
42817
43067
43317
43567
43817
44067
44317
Sample Date-mw38-830n-230e
Mann-Kendall Trend Analysis
n 10
Confidence Coefficient 0.9500
Level of Significance 0.0500
Standard Deviation of S 11.1355
Standardized Value of S -2.2451
M-K Test Value (S) -26
Tabulated p-value 0.0080
Approximate p-value 0.0124
OLS Regression Line (Blue)
OLS Regression Slope -0.0024
OLS Regression Intercept 111.4571
Theil-Sen Trend Line (Red)
Theil-Sen Slope -0.0020
Theil-Sen Intercept 93.4915
Statistically significant evidence of a decreasing trend at the specified level of significance.

| | | |
|---|---|---|
| | **Mann-Kendall Trend Test Analysis** | |
| User Selected Options | | |
| Date/Time of Computation | ProUCL 5.11/20/2022 2:12:37 PM | |
| From File | COMPLIANCE DATA 2H2021 for MK Trend.xls | |
| Full Precision | OFF | |
| Confidence Coefficient | 0.95 | |
| Level of Significance | 0.05 | |

**1,4-Dioxane-mw62-wdr**


**General Statistics**

| | |
|---|---|
| Number of Events Reported (m) | 10 |
| Number of Missing Events | 0 |
| Number or Reported Events Used | 10 |
| Number Values Reported (n) | 10 |
| Minimum | 3.2 |
| Maximum | 4.6 |
| Mean | 3.7 |
| Geometric Mean | 3.675 |
| Median | 3.65 |
| Standard Deviation | 0.464 |
| Coefficient of Variation | 0.125 |

**Mann-Kendall Test**

| | |
|---|---|
| M-K Test Value (S) | -37 |
| Tabulated p-value | 0 |
| Standard Deviation of S | 11.09 |
| Standardized Value of S | -3.246 |
| Approximate p-value | 5.8517E-4 |

**Statistically significant evidence of a decreasing trend at the specified level of significance.**




**Mann-Kendall Trend Analysis**

| | |
|---|---|
| n | 10 |
| Confidence Coefficient | 0.9500 |
| Level of Significance | 0.0500 |
| Standard Deviation of S | 11.0905 |
| Standardized Value of S | -3.2460 |
| M-K Test Value (S) | -37 |
| Tabulated p-value | 0.0000 |
| Approximate p-value | 0.0006 |

**OLS Regression Line (Blue)**

| | |
|---|---|
| OLS Regression Slope | -0.0008 |
| OLS Regression Intercept | 39.4829 |

**Theil-Sen Trend Line (Red)**

| | |
|---|---|
| Theil-Sen Slope | -0.0008 |
| Theil-Sen Intercept | 37.7584 |

Statistically significant evidence of a decreasing trend at the specified level of significance.


| | | |
|---|---|---|
| **Mann-Kendall Trend Test Analysis** | | |
| User Selected Options | | |
| Date/Time of Computation | ProUCL 5.11/20/2022 2:29:04 PM | |
| From File | COMPLIANCE DATA 2H2021 for MK Trend_c.xls | |
| Full Precision | OFF | |
| Confidence Coefficient | 0.95 | |
| Level of Significance | 0.05 | |

**Nitrogen, Nitrite-mw62-wdr**

| **General Statistics** | |
|---|---|
| Number of Events Reported (m) | 10 |
| Number of Missing Events | 0 |
| Number or Reported Events Used | 10 |
| Number Values Reported (n) | 10 |
| Minimum | 490 |
| Maximum | 5400 |
| Mean | 2418 |
| Geometric Mean | 1978 |
| Median | 2050 |
| Standard Deviation | 1505 |
| Coefficient of Variation | 0.622 |

| **Mann-Kendall Test** | |
|---|---|
| M-K Test Value (S) | -21 |
| Tabulated p-value | 0.036 |
| Standard Deviation of S | 11.18 |
| Standardized Value of S | -1.789 |
| Approximate p-value | 0.0368 |

**Statistically significant evidence of a decreasing trend at the specified level of significance.**


Mann-Kendall Trend Test
Nitrogen, Nitrite-mw62-wdr
5167
4367
3567
2767
1967
1167
367
42990
43190
43390
43590
43790
43990
44190
44390
Sample Date-mw62-wdr
Mann-Kendall Trend Analysis
n 10
Confidence Coefficient 0.9500
Level of Significance 0.0500
Standard Deviation of S 11.1803
Standardized Value of S -1.7889
M-K Test Value (S) -21
Tabulated p-value 0.0360
Approximate p-value 0.0368
OLS Regression Line (Blue)
OLS Regression Slope -1.9757
OLS Regression Intercept 88,767.5597
Theil-Sen Trend Line (Red)
Theil-Sen Slope -1.8464
Theil-Sen Intercept 82,753.0622
Statistically significant evidence of a decreasing trend at the specified level of significance.

| | | |
|---|---|---|
| **Mann-Kendall Trend Test Analysis** | | |
| User Selected Options | | |
| Date/Time of Computation | ProUCL 5.11/20/2022 2:24:06 PM | |
| From File | COMPLIANCE DATA 2H2021 for MK Trend_b.xls | |
| Full Precision | OFF | |
| Confidence Coefficient | 0.95 | |
| Level of Significance | 0.05 | |

**Nitrogen, Nitrate-mw62-wdr**


**General Statistics**

| | |
|---|---|
| Number of Events Reported (m) | 10 |
| Number of Missing Events | 0 |
| Number or Reported Events Used | 10 |
| Number Values Reported (n) | 10 |
| Minimum | 110000 |
| Maximum | 130000 |
| Mean | 120000 |
| Geometric Mean | 119833 |
| Median | 120000 |
| Standard Deviation | 6667 |
| Coefficient of Variation | 0.0556 |

**Mann-Kendall Test**

| | |
|---|---|
| M-K Test Value (S) | 6 |
| Tabulated p-value | 0.3 |
| Standard Deviation of S | 9.73 |
| Standardized Value of S | 0.514 |
| Approximate p-value | 0.304 |

**Insufficient evidence to identify a significant trend at the specified level of significance.**


Mann-Kendall Trend Test
Nitrogen, Nitrate-mw62-wdr
129500
125500
121500
117500
113500
109500
42990
43190
43390
43590
43790
43990
44190
44390
Sample Date-mw62-wdr
Mann-Kendall Trend Analysis
n 10
Confidence Coefficient 0.9500
Level of Significance 0.0500
Standard Deviation of S 9.7297
Standardized Value of S 0.5139
M-K Test Value (S) 6
Tabulated p-value 0.3000
Approximate p-value 0.3037
OLS Regression Line (Blue)
OLS Regression Slope 1.8558
OLS Regression Intercept 38,888.7460
Theil-Sen Trend Line (Red)
Theil-Sen Slope 0.0000
Theil-Sen Intercept 120,000.0000
Insufficient statistical evidence of a significant trend at the specified level of significance.

| | | |
|---|---|---|
| | **Mann-Kendall Trend Test Analysis** | |
| User Selected Options | | |
| Date/Time of Computation | ProUCL 5.11/20/2022 2:12:37 PM | |
| From File | COMPLIANCE DATA 2H2021 for MK Trend.xls | |
| Full Precision | OFF | |
| Confidence Coefficient | 0.95 | |
| Level of Significance | 0.05 | |

**1,4-Dioxane-mw77-wd**


**General Statistics**

| | |
|---|---|
| Number of Events Reported (m) | 10 |
| Number of Missing Events | 0 |
| Number or Reported Events Used | 10 |
| Number Values Reported (n) | 10 |
| Minimum | 2.6 |
| Maximum | 20 |
| Mean | 8.82 |
| Geometric Mean | 7.127 |
| Median | 7.15 |
| Standard Deviation | 5.882 |
| Coefficient of Variation | 0.667 |

**Mann-Kendall Test**

| | |
|---|---|
| M-K Test Value (S) | -1 |
| Tabulated p-value | 0.5 |
| Standard Deviation of S | 11.18 |
| Standardized Value of S | 0 |
| Approximate p-value | 0.5 |

**Insufficient evidence to identify a significant trend at the specified level of significance.**


Mann-Kendall Trend Test
1,4-Dioxane-mw77-wd
20
17
14
11
8
5
2
42814
43064
43314
43564
43814
44064
44314
Sample Date-mw77-wd
Mann-Kendall Trend Analysis
n 10
Confidence Coefficient 0.9500
Level of Significance 0.0500
Standard Deviation of S 11.1803
Standardized Value of S 0.0000
M-K Test Value (S) -1
Tabulated p-value 0.5000
Approximate p-value 0.5000
OLS Regression Line (Blue)
OLS Regression Slope -0.0010
OLS Regression Intercept 53.8013
Theil-Sen Trend Line (Red)
Theil-Sen Slope -0.0003
Theil-Sen Intercept 21.3759
Insufficient statistical evidence of a significant trend at the specified level of significance.


| | | |
|---|---|---|
| | **Mann-Kendall Trend Test Analysis** | |
| User Selected Options | | |
| Date/Time of Computation | ProUCL 5.11/20/2022 2:12:37 PM | |
| From File | COMPLIANCE DATA 2H2021 for MK Trend.xls | |
| Full Precision | OFF | |
| Confidence Coefficient | 0.95 | |
| Level of Significance | 0.05 | |

**1,4-Dioxane-mw106-ud**

| **General Statistics** | |
|---|---|
| Number of Events Reported (m) | 10 |
| Number of Missing Events | 0 |
| Number or Reported Events Used | 10 |
| Number Values Reported (n) | 10 |
| Minimum | 0.045 |
| Maximum | 6.5 |
| Mean | 0.82 |
| Geometric Mean | 0.229 |
| Median | 0.25 |
| Standard Deviation | 1.998 |
| Coefficient of Variation | 2.438 |

| **Mann-Kendall Test** | |
|---|---|
| M-K Test Value (S) | -27 |
| Tabulated p-value | 0.008 |
| Standard Deviation of S | 9.781 |
| Standardized Value of S | -2.658 |
| Approximate p-value | 0.00393 |

**Statistically significant evidence of a decreasing trend at the specified level of significance.**




**Mann-Kendall Trend Analysis**

| | |
|---|---|
| n | 10 |
| Confidence Coefficient | 0.9500 |
| Level of Significance | 0.0500 |
| Standard Deviation of S | 9.7809 |
| Standardized Value of S | -2.6582 |
| M-K Test Value (S) | -27 |
| Tabulated p-value | 0.0080 |
| Approximate p-value | 0.0039 |

**OLS Regression Line (Blue)**

| | |
|---|---|
| OLS Regression Slope | -0.0005 |
| OLS Regression Intercept | 19.6635 |

**Theil-Sen Trend Line (Red)**

| | |
|---|---|
| Theil-Sen Slope | 0.0000 |
| Theil-Sen Intercept | 2.0076 |

Statistically significant evidence of a decreasing trend at the specified level of significance.

# APPENDIX C-3.3

# COMPLIANCE EVALUATION STATISTICAL TESTING

## Goodness-of-Fit Testing

| | | |
|---|---|---|
| | **Goodness-of-Fit Test Statistics for Uncensored Full Data Sets without Non-Detects** | |
| **User Selected Options** | | |
| Date/Time of Computation | ProUCL 5.11/20/2022 3:43:04 PM | |
| From File | COMPLIANCE DATA 2H2021.xls | |
| Full Precision | OFF | |
| Confidence Coefficient | 0.95 | |

**1,4-Dioxane (b-313)**

**Raw Statistics**

| | |
|---|---|
| Number of Valid Observations | 10 |
| Number of Distinct Observations | 9 |
| Minimum | 2.3 |
| Maximum | 21 |
| Mean of Raw Data | 14.75 |
| Standard Deviation of Raw Data | 5.788 |
| Khat | 3.759 |
| Theta hat | 3.924 |
| Kstar | 2.698 |
| Theta star | 5.467 |
| Mean of Log Transformed Data | 2.552 |
| Standard Deviation of Log Transformed Data | 0.673 |

**Normal GOF Test Results**

| | |
|---|---|
| Correlation Coefficient R | 0.923 |
| Shapiro Wilk Test Statistic | 0.858 |
| Shapiro Wilk Critical (0.05) Value | 0.842 |
| Approximate Shapiro Wilk P Value | 0.063 |
| Lilliefors Test Statistic | 0.248 |
| Lilliefors Critical (0.05) Value | 0.262 |

**Data appear Normal at (0.05) Significance Level**

**Gamma GOF Test Results**

| | |
|---|---|
| Correlation Coefficient R | 0.834 |
| A-D Test Statistic | 1.155 |
| A-D Critical (0.05) Value | 0.73 |
| K-S Test Statistic | 0.329 |
| K-S Critical(0.05) Value | 0.268 |

**Data not Gamma Distributed at (0.05) Significance Level**

**Lognormal GOF Test Results**

| | |
|---|---|
| Correlation Coefficient R | 0.818 |
| Shapiro Wilk Test Statistic | 0.689 |
| Shapiro Wilk Critical (0.05) Value | 0.842 |
| Approximate Shapiro Wilk P Value | 5.8024E-4 |
| Lilliefors Test Statistic | 0.351 |
| Lilliefors Critical (0.05) Value | 0.262 |

**Data not Lognormal at (0.05) Significance Level**

| | | |
|---|---|---|
| | **Goodness-of-Fit Test Statistics for Uncensored Full Data Sets without Non-Detects** | |
| **User Selected Options** | | |
| Date/Time of Computation | ProUCL 5.11/20/2022 3:46:08 PM | |
| From File | COMPLIANCE DATA 2H2021_b.xls | |
| Full Precision | OFF | |
| Confidence Coefficient | 0.95 | |

**Nitrogen, Nitrate (b-313)**

**Raw Statistics**

| | |
|---|---|
| Number of Valid Observations | 10 |
| Number of Distinct Observations | 9 |
| Minimum | 21000 |
| Maximum | 55000 |
| Mean of Raw Data | 33600 |
| Standard Deviation of Raw Data | 11462 |
| Khat | 9.976 |
| Theta hat | 3368 |
| Kstar | 7.05 |
| Theta star | 4766 |
| Mean of Log Transformed Data | 10.37 |
| Standard Deviation of Log Transformed Data | 0.335 |

**Normal GOF Test Results**

| | |
|---|---|
| Correlation Coefficient R | 0.967 |
| Shapiro Wilk Test Statistic | 0.922 |
| Shapiro Wilk Critical (0.05) Value | 0.842 |
| Approximate Shapiro Wilk P Value | 0.45 |
| Lilliefors Test Statistic | 0.156 |
| Lilliefors Critical (0.05) Value | 0.262 |

**Data appear Normal at (0.05) Significance Level**

**Gamma GOF Test Results**

| | |
|---|---|
| Correlation Coefficient R | 0.985 |
| A-D Test Statistic | 0.302 |
| A-D Critical (0.05) Value | 0.725 |
| K-S Test Statistic | 0.173 |
| K-S Critical(0.05) Value | 0.267 |

**Data appear Gamma Distributed at (0.05) Significance Level**

**Lognormal GOF Test Results**

| | |
|---|---|
| Correlation Coefficient R | 0.978 |
| Shapiro Wilk Test Statistic | 0.938 |
| Shapiro Wilk Critical (0.05) Value | 0.842 |
| Approximate Shapiro Wilk P Value | 0.679 |
| Lilliefors Test Statistic | 0.167 |
| Lilliefors Critical (0.05) Value | 0.262 |

**Data appear Lognormal at (0.05) Significance Level**

| | | |
|---|---|---|
| | **Goodness-of-Fit Test Statistics for Uncensored Full Data Sets without Non-Detects** | |
| | **User Selected Options** | |
| | Date/Time of Computation | ProUCL 5.11/20/2022 3:43:04 PM |
| | From File | COMPLIANCE DATA 2H2021.xls |
| | Full Precision | OFF |
| | Confidence Coefficient | 0.95 |

**1,4-Dioxane (b-326-wd)**

**Raw Statistics**

| | |
|---|---|
| Number of Valid Observations | 10 |
| Number of Distinct Observations | 9 |
| Minimum | 0.77 |
| Maximum | 17 |
| Mean of Raw Data | 7.347 |
| Standard Deviation of Raw Data | 5.088 |
| Khat | 1.548 |
| Theta hat | 4.745 |
| Kstar | 1.15 |
| Theta star | 6.386 |
| Mean of Log Transformed Data | 1.638 |
| Standard Deviation of Log Transformed Data | 1.045 |

**Normal GOF Test Results**

| | |
|---|---|
| Correlation Coefficient R | 0.971 |
| Shapiro Wilk Test Statistic | 0.94 |
| Shapiro Wilk Critical (0.05) Value | 0.842 |
| Approximate Shapiro Wilk P Value | 0.571 |
| Lilliefors Test Statistic | 0.151 |
| Lilliefors Critical (0.05) Value | 0.262 |

**Data appear Normal at (0.05) Significance Level**

**Gamma GOF Test Results**

| | |
|---|---|
| Correlation Coefficient R | 0.949 |
| A-D Test Statistic | 0.483 |
| A-D Critical (0.05) Value | 0.739 |
| K-S Test Statistic | 0.216 |
| K-S Critical(0.05) Value | 0.271 |

**Data appear Gamma Distributed at (0.05) Significance Level**

**Lognormal GOF Test Results**

| | |
|---|---|
| Correlation Coefficient R | 0.932 |
| Shapiro Wilk Test Statistic | 0.862 |
| Shapiro Wilk Critical (0.05) Value | 0.842 |
| Approximate Shapiro Wilk P Value | 0.0895 |
| Lilliefors Test Statistic | 0.241 |
| Lilliefors Critical (0.05) Value | 0.262 |

**Data appear Lognormal at (0.05) Significance Level**

| | | |
|---|---|---|
| | **Goodness-of-Fit Test Statistics for Uncensored Full Data Sets without Non-Detects** | |
| **User Selected Options** | | |
| Date/Time of Computation | ProUCL 5.11/20/2022 3:48:40 PM | |
| From File | COMPLIANCE DATA 2H2021_d.xls | |
| Full Precision | OFF | |
| Confidence Coefficient | 0.95 | |

**Tetrachloroethene (bm-11x-100n)**

| **Raw Statistics** | |
|---|---|
| Number of Valid Observations | 10 |
| Number of Distinct Observations | 10 |
| Minimum | 4.6 |
| Maximum | 7.2 |
| Mean of Raw Data | 6.07 |
| Standard Deviation of Raw Data | 0.838 |
| Khat | 55.54 |
| Theta hat | 0.109 |
| Kstar | 38.94 |
| Theta star | 0.156 |
| Mean of Log Transformed Data | 1.794 |
| Standard Deviation of Log Transformed Data | 0.144 |

| **Normal GOF Test Results** | |
|---|---|
| Correlation Coefficient R | 0.987 |
| Shapiro Wilk Test Statistic | 0.965 |
| Shapiro Wilk Critical (0.05) Value | 0.842 |
| Approximate Shapiro Wilk P Value | 0.908 |
| Lilliefors Test Statistic | 0.12 |
| Lilliefors Critical (0.05) Value | 0.262 |

**Data appear Normal at (0.05) Significance Level**

| **Gamma GOF Test Results** | |
|---|---|
| Correlation Coefficient R | 0.978 |
| A-D Test Statistic | 0.242 |
| A-D Critical (0.05) Value | 0.724 |
| K-S Test Statistic | 0.134 |
| K-S Critical(0.05) Value | 0.266 |

**Data appear Gamma Distributed at (0.05) Significance Level**

| **Lognormal GOF Test Results** | |
|---|---|
| Correlation Coefficient R | 0.978 |
| Shapiro Wilk Test Statistic | 0.95 |
| Shapiro Wilk Critical (0.05) Value | 0.842 |
| Approximate Shapiro Wilk P Value | 0.722 |
| Lilliefors Test Statistic | 0.146 |
| Lilliefors Critical (0.05) Value | 0.262 |

**Data appear Lognormal at (0.05) Significance Level**

| | | |
|---|---|---|
| | **Goodness-of-Fit Test Statistics for Uncensored Full Data Sets without Non-Detects** | |
| | **User Selected Options** | |
| | Date/Time of Computation | ProUCL 5.11/20/2022 3:46:08 PM |
| | From File | COMPLIANCE DATA 2H2021_b.xls |
| | Full Precision | OFF |
| | Confidence Coefficient | 0.95 |

**Nitrogen, Nitrate (mw62-wdr)**

**Raw Statistics**

| | |
|---|---|
| Number of Valid Observations | 10 |
| Number of Distinct Observations | 3 |
| Minimum | 110000 |
| Maximum | 130000 |
| Mean of Raw Data | 120000 |
| Standard Deviation of Raw Data | 6667 |
| Khat | 358.9 |
| Theta hat | 334.3 |
| Kstar | 251.3 |
| Theta star | 477.5 |
| Mean of Log Transformed Data | 11.69 |
| Standard Deviation of Log Transformed Data | 0.0557 |

**Normal GOF Test Results**

| | |
|---|---|
| Correlation Coefficient R | 0.903 |
| Shapiro Wilk Test Statistic | 0.815 |
| Shapiro Wilk Critical (0.05) Value | 0.842 |
| Approximate Shapiro Wilk P Value | 0.0222 |
| Lilliefors Test Statistic | 0.3 |
| Lilliefors Critical (0.05) Value | 0.262 |

**Data not Normal at (0.05) Significance Level**

**Gamma GOF Test Results**

| | |
|---|---|
| Correlation Coefficient R | 0.904 |
| A-D Test Statistic | 1.034 |
| A-D Critical (0.05) Value | 0.724 |
| K-S Test Statistic | 0.307 |
| K-S Critical(0.05) Value | 0.266 |

**Data not Gamma Distributed at (0.05) Significance Level**

**Lognormal GOF Test Results**

| | |
|---|---|
| Correlation Coefficient R | 0.902 |
| Shapiro Wilk Test Statistic | 0.815 |
| Shapiro Wilk Critical (0.05) Value | 0.842 |
| Approximate Shapiro Wilk P Value | 0.0217 |
| Lilliefors Test Statistic | 0.31 |
| Lilliefors Critical (0.05) Value | 0.262 |

**Data not Lognormal at (0.05) Significance Level**



**Non-parametric GOF Test Results**

| | A | B | C | D | E | F | G | H | I | J | K | L |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 102 | **Data do not follow a discernible distribution at (0.05) Level of Significance** | | | | | | | | | | | |

| | A | B | C | D | E | F | G | H | I | J | K | L |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 1 | | | | Goodness-of-Fit Test Statistics for Uncensored Full Data Sets without Non-Detects | | | | | | | | |
| 2 | | | User Selected Options | | | | | | | | | |
| 3 | | | Date/Time of Computation | ProUCL 5.11/20/2022 3:43:04 PM | | | | | | | | |
| 4 | | | From File | COMPLIANCE DATA 2H2021.xls | | | | | | | | |
| 5 | | | Full Precision | OFF | | | | | | | | |
| 6 | | | Confidence Coefficient | 0.95 | | | | | | | | |
| 7 | | | | | | | | | | | | |
| 100 | 1,4-Dioxane (mw77-wd) | | | | | | | | | | | |
| 101 | | | | | | | | | | | | |
| 102 | | | Raw Statistics | | | | | | | | | |
| 103 | | | Number of Valid Observations | 10 | | | | | | | | |
| 104 | | | Number of Distinct Observations | 10 | | | | | | | | |
| 105 | | | Minimum | 2.6 | | | | | | | | |
| 106 | | | Maximum | 20 | | | | | | | | |
| 107 | | | Mean of Raw Data | 8.82 | | | | | | | | |
| 108 | | | Standard Deviation of Raw Data | 5.882 | | | | | | | | |
| 109 | | | Khat | 2.499 | | | | | | | | |
| 110 | | | Theta hat | 3.529 | | | | | | | | |
| 111 | | | Kstar | 1.816 | | | | | | | | |
| 112 | | | Theta star | 4.856 | | | | | | | | |
| 113 | | | Mean of Log Transformed Data | 1.964 | | | | | | | | |
| 114 | | | Standard Deviation of Log Transformed Data | 0.705 | | | | | | | | |
| 115 | | | | | | | | | | | | |
| 116 | | | Normal GOF Test Results | | | | | | | | | |
| 117 | | | | | | | | | | | | |
| 118 | | | Correlation Coefficient R | 0.958 | | | | | | | | |
| 119 | | | Shapiro Wilk Test Statistic | 0.906 | | | | | | | | |
| 120 | | | Shapiro Wilk Critical (0.05) Value | 0.842 | | | | | | | | |
| 121 | | | Approximate Shapiro Wilk P Value | 0.301 | | | | | | | | |
| 122 | | | Lilliefors Test Statistic | 0.225 | | | | | | | | |
| 123 | | | Lilliefors Critical (0.05) Value | 0.262 | | | | | | | | |
| 124 | Data appear Normal at (0.05) Significance Level | | | | | | | | | | | |
| 125 | | | | | | | | | | | | |
| 126 | | | Gamma GOF Test Results | | | | | | | | | |
| 127 | | | | | | | | | | | | |
| 128 | | | Correlation Coefficient R | 0.988 | | | | | | | | |
| 129 | | | A-D Test Statistic | 0.29 | | | | | | | | |
| 130 | | | A-D Critical (0.05) Value | 0.734 | | | | | | | | |
| 131 | | | K-S Test Statistic | 0.199 | | | | | | | | |
| 132 | | | K-S Critical(0.05) Value | 0.269 | | | | | | | | |
| 133 | Data appear Gamma Distributed at (0.05) Significance Level | | | | | | | | | | | |
| 134 | | | | | | | | | | | | |
| 135 | | | Lognormal GOF Test Results | | | | | | | | | |
| 136 | | | | | | | | | | | | |
| 137 | | | Correlation Coefficient R | 0.984 | | | | | | | | |
| 138 | | | Shapiro Wilk Test Statistic | 0.949 | | | | | | | | |
| 139 | | | Shapiro Wilk Critical (0.05) Value | 0.842 | | | | | | | | |
| 140 | | | Approximate Shapiro Wilk P Value | 0.809 | | | | | | | | |
| 141 | | | Lilliefors Test Statistic | 0.163 | | | | | | | | |
| 142 | | | Lilliefors Critical (0.05) Value | 0.262 | | | | | | | | |
| 143 | Data appear Lognormal at (0.05) Significance Level | | | | | | | | | | | |

# APPENDIX C-3.4

# COMPLIANCE EVALUATION STATISTICAL TESTING

## Outlier Testing

| | | |
|---|---|---|
| | **Outlier Tests for Selected Uncensored Variables** | |
| **User Selected Options** | | |
| Date/Time of Computation | ProUCL 5.11/20/2022 3:03:13 PM | |
| From File | COMPLIANCE DATA 2H2021.xls | |
| Full Precision | OFF | |

**Dixon's Outlier Test for 1,4-Dioxane (b-313)**

Number of Observations = 10

10% critical value: 0.409

5% critical value: 0.477

1% critical value: 0.597

**1. Observation Value 21 is a Potential Outlier (Upper Tail)?**

Test Statistic: 0.072

For 10% significance level, 21 is not an outlier.

For 5% significance level, 21 is not an outlier.

For 1% significance level, 21 is not an outlier.

**2. Observation Value 2.3 is a Potential Outlier (Lower Tail)?**

Test Statistic: 0.277

For 10% significance level, 2.3 is not an outlier.

For 5% significance level, 2.3 is not an outlier.

For 1% significance level, 2.3 is not an outlier.

| | A | B | C | D | E | F | G | H | I | J | K | L |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 1 | | | | | **Outlier Tests for Selected Uncensored Variables** | | | | | | | |
| 2 | | | | **User Selected Options** | | | | | | | | |
| 3 | | | | Date/Time of Computation | ProUCL 5.11/20/2022 3:11:12 PM | | | | | | | |
| 4 | | | | From File | COMPLIANCE DATA 2H2021_b.xls | | | | | | | |
| 5 | | | | Full Precision | OFF | | | | | | | |
| 6 | | | | | | | | | | | | |
| 7 | | | | | | | | | | | | |
| 8 | **Dixon's Outlier Test for Nitrogen, Nitrate (b-313)** | | | | | | | | | | | |
| 9 | | | | | | | | | | | | |
| 10 | Number of Observations = 10 | | | | | | | | | | | |
| 11 | 10% critical value: 0.409 | | | | | | | | | | | |
| 12 | 5% critical value: 0.477 | | | | | | | | | | | |
| 13 | 1% critical value: 0.597 | | | | | | | | | | | |
| 14 | | | | | | | | | | | | |
| 15 | **1. Observation Value 55000 is a Potential Outlier (Upper Tail)** | | | | | | | | | | | |
| 16 | | | | | | | | | | | | |
| 17 | Test Statistic: 0.242 | | | | | | | | | | | |
| 18 | | | | | | | | | | | | |
| 19 | For 10% significance level, 55000 is not an outlier. | | | | | | | | | | | |
| 20 | For 5% significance level, 55000 is not an outlier. | | | | | | | | | | | |
| 21 | For 1% significance level, 55000 is not an outlier. | | | | | | | | | | | |
| 22 | | | | | | | | | | | | |
| 23 | **2. Observation Value 21000 is a Potential Outlier (Lower Tail)** | | | | | | | | | | | |
| 24 | | | | | | | | | | | | |
| 25 | Test Statistic: 0.038 | | | | | | | | | | | |
| 26 | | | | | | | | | | | | |
| 27 | For 10% significance level, 21000 is not an outlier. | | | | | | | | | | | |
| 28 | For 5% significance level, 21000 is not an outlier. | | | | | | | | | | | |
| 29 | For 1% significance level, 21000 is not an outlier. | | | | | | | | | | | |
| 30 | | | | | | | | | | | | |

| | A | B | C | D | E | F | G | H | I | J | K | L |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 1 | | | | | **Outlier Tests for Selected Uncensored Variables** | | | | | | | |
| 2 | | | | **User Selected Options** | | | | | | | | |
| 3 | | | | Date/Time of Computation | ProUCL 5.11/20/2022 3:03:13 PM | | | | | | | |
| 4 | | | | From File | COMPLIANCE DATA 2H2021.xls | | | | | | | |
| 5 | | | | Full Precision | OFF | | | | | | | |
| 6 | | | | | | | | | | | | |
| 31 | | | | | | | | | | | | |
| 32 | **Dixon's Outlier Test for 1,4-Dioxane (b-326-ud)** | | | | | | | | | | | |
| 33 | | | | | | | | | | | | |
| 34 | Number of Observations = 10 | | | | | | | | | | | |
| 35 | 10% critical value: 0.409 | | | | | | | | | | | |
| 36 | 5% critical value: 0.477 | | | | | | | | | | | |
| 37 | 1% critical value: 0.597 | | | | | | | | | | | |
| 38 | | | | | | | | | | | | |
| 39 | **1. Observation Value 7.7 is a Potential Outlier (Upper Tail)?** | | | | | | | | | | | |
| 40 | | | | | | | | | | | | |
| 41 | Test Statistic: 0.353 | | | | | | | | | | | |
| 42 | | | | | | | | | | | | |
| 43 | For 10% significance level, 7.7 is not an outlier. | | | | | | | | | | | |
| 44 | For 5% significance level, 7.7 is not an outlier. | | | | | | | | | | | |
| 45 | For 1% significance level, 7.7 is not an outlier. | | | | | | | | | | | |
| 46 | | | | | | | | | | | | |
| 47 | **2. Observation Value 5 is a Potential Outlier (Lower Tail)?** | | | | | | | | | | | |
| 48 | | | | | | | | | | | | |
| 49 | Test Statistic: 0.476 | | | | | | | | | | | |
| 50 | | | | | | | | | | | | |
| 51 | For 10% significance level, 5 is an outlier. | | | | | | | | | | | |
| 52 | For 5% significance level, 5 is not an outlier. | | | | | | | | | | | |
| 53 | For 1% significance level, 5 is not an outlier. | | | | | | | | | | | |
| 54 | | | | | | | | | | | | |

| | A | B | C | D | E | F | G | H | I | J | K | L |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 1 | | | | | **Outlier Tests for Selected Variables replacing nondetects with 1/2 the Detection Limit** | | | | | | | |
| 2 | | | | **User Selected Options** | | | | | | | | |
| 3 | | | | Date/Time of Computation | ProUCL 5.11/20/2022 2:58:01 PM | | | | | | | |
| 4 | | | | From File | COMPLIANCE DATA 2H2021_b.xls | | | | | | | |
| 5 | | | | Full Precision | OFF | | | | | | | |
| 6 | | | | | | | | | | | | |
| 35 | | | | | | | | | | | | |
| 36 | **Dixon's Outlier Test for Nitrogen, Nitrate (b-326-ud)** | | | | | | | | | | | |
| 37 | | | | | | | | | | | | |
| 38 | Total N = 10 | | | | | | | | | | | |
| 39 | Number NDs = 2 | | | | | | | | | | | |
| 40 | Number Detects = 8 | | | | | | | | | | | |
| 41 | Number Data (n) = 10 | | | | | | | | | | | |
| 42 | 10% critical value: 0.409 | | | | | | | | | | | |
| 43 | 5% critical value: 0.477 | | | | | | | | | | | |
| 44 | 1% critical value: 0.597 | | | | | | | | | | | |
| 45 | Note: NDs replaced by DL/2 in Outlier Test | | | | | | | | | | | |
| 46 | | | | | | | | | | | | |
| 47 | **1. Data Value 66000 is a Potential Outlier (Upper Tail)?** | | | | | | | | | | | |
| 48 | | | | | | | | | | | | |
| 49 | Test Statistic: 0.258 | | | | | | | | | | | |
| 50 | | | | | | | | | | | | |
| 51 | For 10% significance level, 66000 is not an outlier. | | | | | | | | | | | |
| 52 | For 5% significance level, 66000 is not an outlier. | | | | | | | | | | | |
| 53 | For 1% significance level, 66000 is not an outlier. | | | | | | | | | | | |
| 54 | | | | | | | | | | | | |
| 55 | **2. Data Value 45 is a Potential Outlier (Lower Tail)?** | | | | | | | | | | | |
| 56 | | | | | | | | | | | | |
| 57 | Test Statistic: 0.000 | | | | | | | | | | | |
| 58 | | | | | | | | | | | | |
| 59 | For 10% significance level, 45 is not an outlier. | | | | | | | | | | | |
| 60 | For 5% significance level, 45 is not an outlier. | | | | | | | | | | | |
| 61 | For 1% significance level, 45 is not an outlier. | | | | | | | | | | | |
| 62 | | | | | | | | | | | | |

| | A | B | C | D | E | F | G | H | I | J | K | L |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 1 | | | | | **Outlier Tests for Selected Uncensored Variables** | | | | | | | |
| 2 | | | | **User Selected Options** | | | | | | | | |
| 3 | | | | Date/Time of Computation | ProUCL 5.11/20/2022 3:03:13 PM | | | | | | | |
| 4 | | | | From File | COMPLIANCE DATA 2H2021.xls | | | | | | | |
| 5 | | | | Full Precision | OFF | | | | | | | |
| 6 | | | | | | | | | | | | |
| 55 | | | | | | | | | | | | |
| 56 | **Dixon's Outlier Test for 1,4-Dioxane (b-326-wd)** | | | | | | | | | | | |
| 57 | | | | | | | | | | | | |
| 58 | Number of Observations = 10 | | | | | | | | | | | |
| 59 | 10% critical value: 0.409 | | | | | | | | | | | |
| 60 | 5% critical value: 0.477 | | | | | | | | | | | |
| 61 | 1% critical value: 0.597 | | | | | | | | | | | |
| 62 | | | | | | | | | | | | |
| 63 | **1. Observation Value 17 is a Potential Outlier (Upper Tail)?** | | | | | | | | | | | |
| 64 | | | | | | | | | | | | |
| 65 | Test Statistic: 0.375 | | | | | | | | | | | |
| 66 | | | | | | | | | | | | |
| 67 | For 10% significance level, 17 is not an outlier. | | | | | | | | | | | |
| 68 | For 5% significance level, 17 is not an outlier. | | | | | | | | | | | |
| 69 | For 1% significance level, 17 is not an outlier. | | | | | | | | | | | |
| 70 | | | | | | | | | | | | |
| 71 | **2. Observation Value 0.77 is a Potential Outlier (Lower Tail)?** | | | | | | | | | | | |
| 72 | | | | | | | | | | | | |
| 73 | Test Statistic: 0.022 | | | | | | | | | | | |
| 74 | | | | | | | | | | | | |
| 75 | For 10% significance level, 0.77 is not an outlier. | | | | | | | | | | | |
| 76 | For 5% significance level, 0.77 is not an outlier. | | | | | | | | | | | |
| 77 | For 1% significance level, 0.77 is not an outlier. | | | | | | | | | | | |

| | A | B | C | D | E | F | G | H | I | J | K | L |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 1 | | | | | **Outlier Tests for Selected Uncensored Variables** | | | | | | | |
| 2 | | | | **User Selected Options** | | | | | | | | |
| 3 | | | | Date/Time of Computation | ProUCL 5.11/20/2022 3:14:09 PM | | | | | | | |
| 4 | | | | From File | COMPLIANCE DATA 2H2021_d.xls | | | | | | | |
| 5 | | | | Full Precision | OFF | | | | | | | |
| 6 | | | | | | | | | | | | |
| 7 | | | | | | | | | | | | |
| 8 | **Dixon's Outlier Test for Tetrachloroethene (bm-11x-100n)** | | | | | | | | | | | |
| 9 | | | | | | | | | | | | |
| 10 | Number of Observations = 10 | | | | | | | | | | | |
| 11 | 10% critical value: 0.409 | | | | | | | | | | | |
| 12 | 5% critical value: 0.477 | | | | | | | | | | | |
| 13 | 1% critical value: 0.597 | | | | | | | | | | | |
| 14 | | | | | | | | | | | | |
| 15 | **1. Observation Value 7.2 is a Potential Outlier (Upper Tail)?** | | | | | | | | | | | |
| 16 | | | | | | | | | | | | |
| 17 | Test Statistic: 0.143 | | | | | | | | | | | |
| 18 | | | | | | | | | | | | |
| 19 | For 10% significance level, 7.2 is not an outlier. | | | | | | | | | | | |
| 20 | For 5% significance level, 7.2 is not an outlier. | | | | | | | | | | | |
| 21 | For 1% significance level, 7.2 is not an outlier. | | | | | | | | | | | |
| 22 | | | | | | | | | | | | |
| 23 | **2. Observation Value 4.6 is a Potential Outlier (Lower Tail)?** | | | | | | | | | | | |
| 24 | | | | | | | | | | | | |
| 25 | Test Statistic: 0.217 | | | | | | | | | | | |
| 26 | | | | | | | | | | | | |
| 27 | For 10% significance level, 4.6 is not an outlier. | | | | | | | | | | | |
| 28 | For 5% significance level, 4.6 is not an outlier. | | | | | | | | | | | |
| 29 | For 1% significance level, 4.6 is not an outlier. | | | | | | | | | | | |
| 30 | | | | | | | | | | | | |

| | | |
|---|---|---|
| | **Outlier Tests for Selected Uncensored Variables** | |
| **User Selected Options** | | |
| Date/Time of Computation | ProUCL 5.11/20/2022 3:15:57 PM | |
| From File | COMPLIANCE DATA 2H2021_e.xls | |
| Full Precision | OFF | |

**Dixon's Outlier Test for Trichloroethene (bm-11x-100n)**

Number of Observations = 10

10% critical value: 0.409

5% critical value: 0.477

1% critical value: 0.597

**1. Observation Value 5.7 is a Potential Outlier (Upper Tail)?**

Test Statistic: 0.143

For 10% significance level, 5.7 is not an outlier.

For 5% significance level, 5.7 is not an outlier.

For 1% significance level, 5.7 is not an outlier.

**2. Observation Value 3.6 is a Potential Outlier (Lower Tail)?**

Test Statistic: 0.368

For 10% significance level, 3.6 is not an outlier.

For 5% significance level, 3.6 is not an outlier.

For 1% significance level, 3.6 is not an outlier.

| | A | B | C | D | E | F | G | H | I | J | K | L |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 1 | | | | | **Outlier Tests for Selected Uncensored Variables** | | | | | | | |
| 2 | | | | **User Selected Options** | | | | | | | | |
| 3 | | | | Date/Time of Computation | ProUCL 5.11/20/2022 3:11:12 PM | | | | | | | |
| 4 | | | | From File | COMPLIANCE DATA 2H2021_b.xls | | | | | | | |
| 5 | | | | Full Precision | OFF | | | | | | | |
| 6 | | | | | | | | | | | | |
| 55 | | | | | | | | | | | | |
| 56 | **Dixon's Outlier Test for Nitrogen, Nitrate (bm-15n6)** | | | | | | | | | | | |
| 57 | | | | | | | | | | | | |
| 58 | Number of Observations = 10 | | | | | | | | | | | |
| 59 | 10% critical value: 0.409 | | | | | | | | | | | |
| 60 | 5% critical value: 0.477 | | | | | | | | | | | |
| 61 | 1% critical value: 0.597 | | | | | | | | | | | |
| 62 | | | | | | | | | | | | |
| 63 | **1. Observation Value 49000 is a Potential Outlier (Upper Tail)** | | | | | | | | | | | |
| 64 | | | | | | | | | | | | |
| 65 | Test Statistic: 0.167 | | | | | | | | | | | |
| 66 | | | | | | | | | | | | |
| 67 | For 10% significance level, 49000 is not an outlier. | | | | | | | | | | | |
| 68 | For 5% significance level, 49000 is not an outlier. | | | | | | | | | | | |
| 69 | For 1% significance level, 49000 is not an outlier. | | | | | | | | | | | |
| 70 | | | | | | | | | | | | |
| 71 | **2. Observation Value 30000 is a Potential Outlier (Lower Tail)** | | | | | | | | | | | |
| 72 | | | | | | | | | | | | |
| 73 | Test Statistic: 0.063 | | | | | | | | | | | |
| 74 | | | | | | | | | | | | |
| 75 | For 10% significance level, 30000 is not an outlier. | | | | | | | | | | | |
| 76 | For 5% significance level, 30000 is not an outlier. | | | | | | | | | | | |
| 77 | For 1% significance level, 30000 is not an outlier. | | | | | | | | | | | |
| 78 | | | | | | | | | | | | |

| | A | B | C | D | E | F | G | H | I | J | K | L |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 1 | | | | | Outlier Tests for Selected Variables replacing nondetects with 1/2 the Detection Limit | | | | | | | |
| 2 | | | | User Selected Options | | | | | | | | |
| 3 | | | | Date/Time of Computation | ProUCL 5.11/20/2022 2:52:53 PM | | | | | | | |
| 4 | | | | From File | COMPLIANCE DATA 2H2021.xls | | | | | | | |
| 5 | | | | Full Precision | OFF | | | | | | | |
| 6 | | | | | | | | | | | | |
| 119 | | | | | | | | | | | | |
| 120 | Dixon's Outlier Test for 1,4-Dioxane (mw23-c-sd) | | | | | | | | | | | |
| 121 | | | | | | | | | | | | |
| 122 | Total N = 10 | | | | | | | | | | | |
| 123 | Number NDs = 9 | | | | | | | | | | | |
| 124 | Number Detects = 1 | | | | | | | | | | | |
| 125 | Number Data (n) = 10 | | | | | | | | | | | |
| 126 | 10% critical value: 0.409 | | | | | | | | | | | |
| 127 | 5% critical value: 0.477 | | | | | | | | | | | |
| 128 | 1% critical value: 0.597 | | | | | | | | | | | |
| 129 | Note: NDs replaced by DL/2 in Outlier Test | | | | | | | | | | | |
| 130 | | | | | | | | | | | | |
| 131 | 1. Data Value 1.4 is a Potential Outlier (Upper Tail)? | | | | | | | | | | | |
| 132 | | | | | | | | | | | | |
| 133 | Test Statistic: 0.868 | | | | | | | | | | | |
| 134 | | | | | | | | | | | | |
| 135 | For 10% significance level, 1.4 is an outlier. | | | | | | | | | | | |
| 136 | For 5% significance level, 1.4 is an outlier. | | | | | | | | | | | |
| 137 | For 1% significance level, 1.4 is an outlier. | | | | | | | | | | | |
| 138 | | | | | | | | | | | | |
| 139 | 2. Data Value 0.045 is a Potential Outlier (Lower Tail)? | | | | | | | | | | | |
| 140 | | | | | | | | | | | | |
| 141 | Test Statistic: 0.146 | | | | | | | | | | | |
| 142 | | | | | | | | | | | | |
| 143 | For 10% significance level, 0.045 is not an outlier. | | | | | | | | | | | |
| 144 | For 5% significance level, 0.045 is not an outlier. | | | | | | | | | | | |
| 145 | For 1% significance level, 0.045 is not an outlier. | | | | | | | | | | | |
| 146 | | | | | | | | | | | | |

| | A | B | C | D | E | F | G | H | I | J | K | L |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 1 | | | | | **Outlier Tests for Selected Uncensored Variables** | | | | | | | |
| 2 | | | | **User Selected Options** | | | | | | | | |
| 3 | | | | Date/Time of Computation | ProUCL 5.11/20/2022 3:03:13 PM | | | | | | | |
| 4 | | | | From File | COMPLIANCE DATA 2H2021.xls | | | | | | | |
| 5 | | | | Full Precision | OFF | | | | | | | |
| 6 | | | | | | | | | | | | |
| 127 | | | | | | | | | | | | |
| 128 | **Dixon's Outlier Test for 1,4-Dioxane (mw38-830n-230e)** | | | | | | | | | | | |
| 129 | | | | | | | | | | | | |
| 130 | Number of Observations = 10 | | | | | | | | | | | |
| 131 | 10% critical value: 0.409 | | | | | | | | | | | |
| 132 | 5% critical value: 0.477 | | | | | | | | | | | |
| 133 | 1% critical value: 0.597 | | | | | | | | | | | |
| 134 | | | | | | | | | | | | |
| 135 | **1. Observation Value 13 is a Potential Outlier (Upper Tail)?** | | | | | | | | | | | |
| 136 | | | | | | | | | | | | |
| 137 | Test Statistic: 0.092 | | | | | | | | | | | |
| 138 | | | | | | | | | | | | |
| 139 | For 10% significance level, 13 is not an outlier. | | | | | | | | | | | |
| 140 | For 5% significance level, 13 is not an outlier. | | | | | | | | | | | |
| 141 | For 1% significance level, 13 is not an outlier. | | | | | | | | | | | |
| 142 | | | | | | | | | | | | |
| 143 | **2. Observation Value 2 is a Potential Outlier (Lower Tail)?** | | | | | | | | | | | |
| 144 | | | | | | | | | | | | |
| 145 | Test Statistic: 0.010 | | | | | | | | | | | |
| 146 | | | | | | | | | | | | |
| 147 | For 10% significance level, 2 is not an outlier. | | | | | | | | | | | |
| 148 | For 5% significance level, 2 is not an outlier. | | | | | | | | | | | |
| 149 | For 1% significance level, 2 is not an outlier. | | | | | | | | | | | |
| 150 | | | | | | | | | | | | |

| | A | B | C | D | E | F | G | H | I | J | K | L |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 1 | | | | | **Outlier Tests for Selected Uncensored Variables** | | | | | | | |
| 2 | | | | **User Selected Options** | | | | | | | | |
| 3 | | | | Date/Time of Computation | ProUCL 5.11/20/2022 3:06:31 PM | | | | | | | |
| 4 | | | | From File | COMPLIANCE DATA 2H2021_a.xls | | | | | | | |
| 5 | | | | Full Precision | OFF | | | | | | | |
| 6 | | | | | | | | | | | | |
| 7 | | | | | | | | | | | | |
| 8 | **Dixon's Outlier Test for Chloroform (mw38-830n-230e)** | | | | | | | | | | | |
| 9 | | | | | | | | | | | | |
| 10 | Number of Observations = 10 | | | | | | | | | | | |
| 11 | 10% critical value: 0.409 | | | | | | | | | | | |
| 12 | 5% critical value: 0.477 | | | | | | | | | | | |
| 13 | 1% critical value: 0.597 | | | | | | | | | | | |
| 14 | | | | | | | | | | | | |
| 15 | **1. Observation Value 6.9 is a Potential Outlier (Upper Tail)?** | | | | | | | | | | | |
| 16 | | | | | | | | | | | | |
| 17 | Test Statistic: 0.104 | | | | | | | | | | | |
| 18 | | | | | | | | | | | | |
| 19 | For 10% significance level, 6.9 is not an outlier. | | | | | | | | | | | |
| 20 | For 5% significance level, 6.9 is not an outlier. | | | | | | | | | | | |
| 21 | For 1% significance level, 6.9 is not an outlier. | | | | | | | | | | | |
| 22 | | | | | | | | | | | | |
| 23 | **2. Observation Value 2.1 is a Potential Outlier (Lower Tail)?** | | | | | | | | | | | |
| 24 | | | | | | | | | | | | |
| 25 | Test Statistic: 0.000 | | | | | | | | | | | |
| 26 | | | | | | | | | | | | |
| 27 | For 10% significance level, 2.1 is not an outlier. | | | | | | | | | | | |
| 28 | For 5% significance level, 2.1 is not an outlier. | | | | | | | | | | | |
| 29 | For 1% significance level, 2.1 is not an outlier. | | | | | | | | | | | |
| 30 | | | | | | | | | | | | |

| | A | B | C | D | E | F | G | H | I | J | K | L |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 1 | | | | | **Outlier Tests for Selected Uncensored Variables** | | | | | | | |
| 2 | | | | **User Selected Options** | | | | | | | | |
| 3 | | | | Date/Time of Computation | ProUCL 5.11/20/2022 3:03:13 PM | | | | | | | |
| 4 | | | | From File | COMPLIANCE DATA 2H2021.xls | | | | | | | |
| 5 | | | | Full Precision | OFF | | | | | | | |
| 6 | | | | | | | | | | | | |
| 151 | | | | | | | | | | | | |
| 152 | **Dixon's Outlier Test for 1,4-Dioxane (mw62-wdr)** | | | | | | | | | | | |
| 153 | | | | | | | | | | | | |
| 154 | Number of Observations = 10 | | | | | | | | | | | |
| 155 | 10% critical value: 0.409 | | | | | | | | | | | |
| 156 | 5% critical value: 0.477 | | | | | | | | | | | |
| 157 | 1% critical value: 0.597 | | | | | | | | | | | |
| 158 | | | | | | | | | | | | |
| 159 | **1. Observation Value 4.6 is a Potential Outlier (Upper Tail)?** | | | | | | | | | | | |
| 160 | | | | | | | | | | | | |
| 161 | Test Statistic: 0.286 | | | | | | | | | | | |
| 162 | | | | | | | | | | | | |
| 163 | For 10% significance level, 4.6 is not an outlier. | | | | | | | | | | | |
| 164 | For 5% significance level, 4.6 is not an outlier. | | | | | | | | | | | |
| 165 | For 1% significance level, 4.6 is not an outlier. | | | | | | | | | | | |
| 166 | | | | | | | | | | | | |
| 167 | **2. Observation Value 3.2 is a Potential Outlier (Lower Tail)?** | | | | | | | | | | | |
| 168 | | | | | | | | | | | | |
| 169 | Test Statistic: 0.000 | | | | | | | | | | | |
| 170 | | | | | | | | | | | | |
| 171 | For 10% significance level, 3.2 is not an outlier. | | | | | | | | | | | |
| 172 | For 5% significance level, 3.2 is not an outlier. | | | | | | | | | | | |
| 173 | For 1% significance level, 3.2 is not an outlier. | | | | | | | | | | | |
| 174 | | | | | | | | | | | | |

| | | |
|---|---|---|
| | **Outlier Tests for Selected Variables replacing nondetects with 1/2 the Detection Limit** | |
| **User Selected Options** | | |
| Date/Time of Computation | ProUCL 5.11/20/2022 2:56:07 PM | |
| From File | COMPLIANCE DATA 2H2021_c.xls | |
| Full Precision | OFF | |

**Dixon's Outlier Test for Nitrogen, Nitrite (mw62-wdr)**

Total N = 10

Number NDs = 1

Number Detects = 9

Number Data (n) = 10

10% critical value: 0.409

5% critical value: 0.477

1% critical value: 0.597

Note: NDs replaced by DL/2 in Outlier Test

**1. Data Value 5400 is a Potential Outlier (Upper Tail)?**

Test Statistic: 0.310

For 10% significance level, 5400 is not an outlier.

For 5% significance level, 5400 is not an outlier.

For 1% significance level, 5400 is not an outlier.

**2. Data Value 490 is a Potential Outlier (Lower Tail)?**

Test Statistic: 0.114

For 10% significance level, 490 is not an outlier.

For 5% significance level, 490 is not an outlier.

For 1% significance level, 490 is not an outlier.

| | A | B | C | D | E | F | G | H | I | J | K | L |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 1 | | | | | **Outlier Tests for Selected Uncensored Variables** | | | | | | | |
| 2 | | | | **User Selected Options** | | | | | | | | |
| 3 | | | | Date/Time of Computation | ProUCL 5.11/20/2022 3:11:12 PM | | | | | | | |
| 4 | | | | From File | COMPLIANCE DATA 2H2021_b.xls | | | | | | | |
| 5 | | | | Full Precision | OFF | | | | | | | |
| 6 | | | | | | | | | | | | |
| 79 | | | | | | | | | | | | |
| 80 | **Dixon's Outlier Test for Nitrogen, Nitrate (mw62-wdr)** | | | | | | | | | | | |
| 81 | | | | | | | | | | | | |
| 82 | Number of Observations = 10 | | | | | | | | | | | |
| 83 | 10% critical value: 0.409 | | | | | | | | | | | |
| 84 | 5% critical value: 0.477 | | | | | | | | | | | |
| 85 | 1% critical value: 0.597 | | | | | | | | | | | |
| 86 | | | | | | | | | | | | |
| 87 | **1. Observation Value 130000 is a Potential Outlier (Upper Tai** | | | | | | | | | | | |
| 88 | | | | | | | | | | | | |
| 89 | Test Statistic: 0.000 | | | | | | | | | | | |
| 90 | | | | | | | | | | | | |
| 91 | For 10% significance level, 130000 is not an outlier. | | | | | | | | | | | |
| 92 | For 5% significance level, 130000 is not an outlier. | | | | | | | | | | | |
| 93 | For 1% significance level, 130000 is not an outlier. | | | | | | | | | | | |
| 94 | | | | | | | | | | | | |
| 95 | **2. Observation Value 110000 is a Potential Outlier (Lower Tail** | | | | | | | | | | | |
| 96 | | | | | | | | | | | | |
| 97 | Test Statistic: 0.000 | | | | | | | | | | | |
| 98 | | | | | | | | | | | | |
| 99 | For 10% significance level, 110000 is not an outlier. | | | | | | | | | | | |
| 100 | For 5% significance level, 110000 is not an outlier. | | | | | | | | | | | |
| 101 | For 1% significance level, 110000 is not an outlier. | | | | | | | | | | | |
| 102 | | | | | | | | | | | | |

| | A | B | C | D | E | F | G | H | I | J | K | L |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 1 | | | | | **Outlier Tests for Selected Uncensored Variables** | | | | | | | |
| 2 | | | | **User Selected Options** | | | | | | | | |
| 3 | | | | Date/Time of Computation | ProUCL 5.11/20/2022 3:03:13 PM | | | | | | | |
| 4 | | | | From File | COMPLIANCE DATA 2H2021.xls | | | | | | | |
| 5 | | | | Full Precision | OFF | | | | | | | |
| 6 | | | | | | | | | | | | |
| 175 | | | | | | | | | | | | |
| 176 | **Dixon's Outlier Test for 1,4-Dioxane (mw77-wd)** | | | | | | | | | | | |
| 177 | | | | | | | | | | | | |
| 178 | Number of Observations = 10 | | | | | | | | | | | |
| 179 | 10% critical value: 0.409 | | | | | | | | | | | |
| 180 | 5% critical value: 0.477 | | | | | | | | | | | |
| 181 | 1% critical value: 0.597 | | | | | | | | | | | |
| 182 | | | | | | | | | | | | |
| 183 | **1. Observation Value 20 is a Potential Outlier (Upper Tail)?** | | | | | | | | | | | |
| 184 | | | | | | | | | | | | |
| 185 | Test Statistic: 0.235 | | | | | | | | | | | |
| 186 | | | | | | | | | | | | |
| 187 | For 10% significance level, 20 is not an outlier. | | | | | | | | | | | |
| 188 | For 5% significance level, 20 is not an outlier. | | | | | | | | | | | |
| 189 | For 1% significance level, 20 is not an outlier. | | | | | | | | | | | |
| 190 | | | | | | | | | | | | |
| 191 | **2. Observation Value 2.6 is a Potential Outlier (Lower Tail)?** | | | | | | | | | | | |
| 192 | | | | | | | | | | | | |
| 193 | Test Statistic: 0.030 | | | | | | | | | | | |
| 194 | | | | | | | | | | | | |
| 195 | For 10% significance level, 2.6 is not an outlier. | | | | | | | | | | | |
| 196 | For 5% significance level, 2.6 is not an outlier. | | | | | | | | | | | |
| 197 | For 1% significance level, 2.6 is not an outlier. | | | | | | | | | | | |
| 198 | | | | | | | | | | | | |

| | | |
|---|---|---|
| | **Outlier Tests for Selected Variables replacing nondetects with 1/2 the Detection Limit** | |
| | **User Selected Options** | |
| Date/Time of Computation | ProUCL 5.11/20/2022 2:52:53 PM | |
| From File | COMPLIANCE DATA 2H2021.xls | |
| Full Precision | OFF | |

**Dixon's Outlier Test for 1,4-Dioxane (mw106-ud)**

Total N = 10

Number NDs = 9

Number Detects = 1

Number Data (n) = 10

10% critical value: 0.409

5% critical value: 0.477

1% critical value: 0.597

Note: NDs replaced by DL/2 in Outlier Test

**1. Data Value 6.5 is a Potential Outlier (Upper Tail)?**

Test Statistic: 0.973

For 10% significance level, 6.5 is an outlier.

For 5% significance level, 6.5 is an outlier.

For 1% significance level, 6.5 is an outlier.

**2. Data Value 0.045 is a Potential Outlier (Lower Tail)?**

Test Statistic: 0.146

For 10% significance level, 0.045 is not an outlier.

For 5% significance level, 0.045 is not an outlier.

For 1% significance level, 0.045 is not an outlier.

# APPENDIX C-3.5

# COMPLIANCE EVALUATION STATISTICAL TESTING

## Linear Regression Analysis

# B-326-UD 1,4-DIOXANE

**Ordinary Least Squares Linear Regression Output Sheet**

| | |
|---|---|
| User Selected Options | |
| Date/Time of Computation | ProUCL 5.11/24/2022 10:08:16 AM |
| From File | COMPLIANCE DATA 2H2021.xls |
| Full Precision | OFF |
| | |
| Display Limits | True |
| Confidence Level for Intervals | 0.9 |
| Display Regresion Diagnostics | True |
| Display Regresion Tables | True |
| Title For Y vs X Plots | Classical Regression |
| Confidence Level for Regression Line | 0.9 |
| Display Confidence Band | True |
| Display Prediction Band | True |

| | |
|---|---|
| Dependendant Variable (Y-Data) | 1,4-Dioxane_b-326-ud |
| Number Reported (Y values) | 10 |
| Independent Variable (x-data) | Sample Date_b-326-ud |
| Number Reported (x-values) | 10 |

**Regression Estimates and Inference Table**

| Parameter | Estimates | Std. Error | T-values | p-values |
|---|---|---|---|---|
| intercept | 109.4 | 22.77 | 4.802 | 0.00135 |
| nple Date_b-326 | -0.00233 | 5.1626E-4 | -4.514 | 0.00197 |

**OLS ANOVA Table**

| Source of Variation | SS | DOF | MS | F-Value | P-Value |
|---|---|---|---|---|---|
| **Regression** | 3.536 | 1 | 3.536 | 20.37 | 0.0020 |
| **Error** | 1.388 | 8 | 0.174 | | |
| **Total** | 4.924 | 9 | | | |

| | |
|---|---|
| R Square | 0.718 |
| Adjusted R Square | 0.683 |
| Sqrt(MSE) = Scale | 0.417 |

**Regression Table**


| Obs | Y Vector | Yhat | Residuals | Res/Scale |
|---|---|---|---|---|
| 1 | 7 | 7.511 | -0.511 | -1.228 |
| 2 | 7.1 | 7.262 | -0.162 | -0.389 |
| 3 | 7.7 | 7.115 | 0.585 | 1.404 |
| 4 | 6.9 | 6.871 | 0.0294 | 0.0705 |
| 5 | 6.7 | 6.642 | 0.0577 | 0.139 |
| 6 | 6.4 | 6.412 | -0.0116 | -0.0278 |
| 7 | 6.7 | 6.281 | 0.419 | 1.006 |
| 8 | 6 | 6.008 | -0.00842 | -0.0202 |
| 9 | 6.1 | 5.799 | 0.301 | 0.723 |
| 10 | 5 | 5.698 | -0.698 | -1.677 |

**Summary Table for Prediction and Confidence Limits**

| Obs | X Vector | Y Vector | Yhat | s(Yhat) | s(pred) | LCL | UCL | LPL | UPL | Residuals |
|---|---|---|---|---|---|---|---|---|---|---|
| 1 | 43703 | 7 | 7.511 | 0.249 | 0.485 | 7.049 | 7.974 | 6.609 | 8.414 | -0.511 |
| 2 | 43810 | 7.1 | 7.262 | 0.204 | 0.464 | 6.883 | 7.641 | 6.4 | 8.125 | -0.162 |
| 3 | 43873 | 7.7 | 7.115 | 0.18 | 0.454 | 6.78 | 7.45 | 6.271 | 7.959 | 0.585 |
| 4 | 43978 | 6.9 | 6.871 | 0.149 | 0.442 | 6.594 | 7.147 | 6.048 | 7.693 | 0.0294 |


| | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|
| 5 | 44076 | 6.7 | 6.642 | 0.133 | 0.437 | 6.395 | 6.89 | 5.829 | 7.455 | 0.0577 |
| 6 | 44175 | 6.4 | 6.412 | 0.136 | 0.438 | 6.159 | 6.664 | 5.597 | 7.226 | -0.0116 |
| 7 | 44231 | 6.7 | 6.281 | 0.146 | 0.441 | 6.01 | 6.552 | 5.461 | 7.102 | 0.419 |
| 8 | 44348 | 6 | 6.008 | 0.18 | 0.454 | 5.674 | 6.343 | 5.165 | 6.852 | -0.00842 |
| 9 | 44438 | 6.1 | 5.799 | 0.214 | 0.468 | 5.401 | 6.197 | 4.928 | 6.67 | 0.301 |
| 10 | 44481 | 5 | 5.698 | 0.232 | 0.477 | 5.267 | 6.13 | 4.812 | 6.585 | -0.698 |

| | X Vector | Residuals |
|---|---|---|
| 8/26/2019 | 43703 | -0.511 |
| 12/11/2019 | 43810 | -0.162 |
| 2/12/2020 | 43873 | 0.585 |
| 5/27/2020 | 43978 | 0.0294 |
| 9/2/2020 | 44076 | 0.0577 |
| 12/10/2020 | 44175 | -0.0116 |
| 2/4/2021 | 44231 | 0.419 |
| 6/1/2021 | 44348 | -0.00842 |
| 8/30/2021 | 44438 | 0.301 |
| 10/12/2021 | 44481 | -0.698 |




**CONSTANT**

| | Yhat | Residuals |
|---|---|---|
| | 7.511 | -0.511 |
| | 7.262 | -0.162 |
| | 7.115 | 0.585 |
| | 6.871 | 0.0294 |
| | 6.642 | 0.0577 |
| | 6.412 | -0.0116 |
| | 6.281 | 0.419 |
| | 6.008 | -0.00842 |
| | 5.799 | 0.301 |
| | 5.698 | -0.698 |




**CONSTANT**

**Shapiro-Wilks Test for Normality**

SW= Shapiro-Wilk Statistic

| | Residuals | Residuals | Column C-l | Coeffiicien | |
|---|---|---|---|---|---|
| 1 | -0.698 | 0.585 | 1.283 | 0.5739 | 0.736314 |
| 2 | -0.511 | 0.419 | 0.93 | 0.3291 | 0.306063 |
| 3 | -0.162 | 0.301 | 0.463 | 0.2141 | 0.099128 |
| 4 | -0.0116 | 0.0577 | 0.0693 | 0.1224 | 0.008482 |
| 5 | -0.00842 | 0.0294 | 0.03782 | 0.0399 | 0.001509 |
| 6 | 0.0294 | -0.00842 | -0.03782 | b= | 1.151496 |
| 7 | 0.0577 | -0.0116 | -0.0693 | StdDev= | 0.354832 |
| 8 | 0.301 | -0.162 | -0.463 | SW= | 1.170139 |
| 9 | 0.419 | -0.511 | -0.93 | Critical pt = | 0.842 5% |
| 10 | 0.585 | -0.698 | -1.283 | | |

**Assume Normal**

# B-326-UD NITRATE

## Ordinary Least Squares Linear Regression Output Sheet

| | |
|---|---|
| User Selected Options | |
| Date/Time of Computation | ProUCL 5.11/24/2022 10:11:55 AM |
| From File | COMPLIANCE DATA 2H2021_b.xls |
| Full Precision | OFF |
| | |
| Display Limits | True |
| Confidence Level for Intervals | 0.9 |
| Display Regresion Diagnostics | True |
| Display Regresion Tables | True |
| Title For Y vs X Plots | Classical Regression |
| Confidence Level for Regression Line | 0.9 |
| Display Confidence Band | True |
| Display Prediction Band | True |

| | |
|---|---|
| Dependendant Variable (Y-Data) | Nitrogen, Nitrate_b-326-ud |
| Number Reported (Y values) | 10 |
| Independent Variable (x-data) | Sample Date_b-326-ud |
| Number Reported (x-values) | 10 |

**Regression Estimates and Inference Table**

| Parameter | Estimates | Std. Error | T-values | p-values |
|---|---|---|---|---|
| intercept | 801102 | 533370 | 1.502 | 0.172 |
| nple Date_b-326 | -17.98 | 12.26 | -1.467 | 0.18 |

**OLS ANOVA Table**

| Source of Variation | SS | DOF | MS | F-Value | P-Value |
|---|---|---|---|---|---|
| **Regression** | 1.135E+9 | 1 | 1.135E+9 | 2.153 | 0.1805 |
| **Error** | 4.216E+9 | 8 | 5.270E+8 | | |
| **Total** | 5.351E+9 | 9 | | | |

| | |
|---|---|
| R Square | 0.212 |
| Adjusted R Square | 0.114 |
| Sqrt(MSE) = Scale | 22957 |

**Regression Table**


| Obs | Y Vector | Yhat | Residuals | Res/Scale |
|---|---|---|---|---|
| 1 | 19000 | 43659 | -24659 | -1.074 |
| 2 | 40000 | 30460 | 9540 | 0.416 |
| 3 | 66000 | 22260 | 43740 | 1.905 |
| 4 | 49000 | 18070 | 30930 | 1.347 |
| 5 | 9300 | 16488 | -7188 | -0.313 |
| 6 | 990 | 15229 | -14239 | -0.62 |
| 7 | 700 | 13305 | -12605 | -0.549 |
| 8 | 730 | 12172 | -11442 | -0.498 |
| 9 | 90 | 8522 | -8432 | -0.367 |
| 10 | 90 | 5735 | -5645 | -0.246 |

**Summary Table for Prediction and Confidence Limits**

| Obs | X Vector | Y Vector | Yhat | s(Yhat) | s(pred) | LCL | UCL | LPL | UPL | Residuals |
|---|---|---|---|---|---|---|---|---|---|---|
| 1 | 42122 | 19000 | 43659 | 18564 | 29523 | 9138 | 78180 | -11241 | 98559 | -24659 |
| 2 | 42856 | 40000 | 30460 | 10870 | 25400 | 10247 | 50673 | -16772 | 77692 | 9540 |
| 3 | 43312 | 66000 | 22260 | 7678 | 24207 | 7982 | 36539 | -22753 | 67274 | 43740 |
| 4 | 43545 | 49000 | 18070 | 7268 | 24080 | 4555 | 31586 | -26707 | 62848 | 30930 |


| | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|
| 5 | 43633 | 9300 | 16488 | 7400 | 24120 | 2728 | 30248 | -28364 | 61340 | -7188 |
| 6 | 43703 | 990 | 15229 | 7612 | 24186 | 1074 | 29385 | -29746 | 60204 | -14239 |
| 7 | 43810 | 700 | 13305 | 8104 | 24345 | -1765 | 28375 | -31966 | 58576 | -12605 |
| 8 | 43873 | 730 | 12172 | 8475 | 24471 | -3588 | 27933 | -33333 | 57678 | -11442 |
| 9 | 44076 | 90 | 8522 | 9989 | 25036 | -10054 | 27098 | -38034 | 55077 | -8432 |
| 10 | 44231 | 90 | 5735 | 11378 | 25622 | -15424 | 26893 | -41910 | 53380 | -5645 |

| | X Vector | Residuals |
|---|---|---|
| 4/28/2015 | 42122 | -24659 |
| 5/1/2017 | 42856 | 9540 |
| 7/31/2018 | 43312 | 43740 |
| 3/21/2019 | 43545 | 30930 |
| 6/17/2019 | 43633 | -7188 |
| 8/26/2019 | 43703 | -14239 |
| 12/11/2019 | 43810 | -12605 |
| 2/12/2020 | 43873 | -11442 |
| 9/2/2020 | 44076 | -8432 |
| 2/4/2021 | 44231 | -5645 |




**NOT CONSTANT**

| | Yhat | Residuals |
|---|---|---|
| | 43659 | -24659 |
| | 30460 | 9540 |
| | 22260 | 43740 |
| | 18070 | 30930 |
| | 16488 | -7188 |
| | 15229 | -14239 |
| | 13305 | -12605 |
| | 12172 | -11442 |
| | 8522 | -8432 |
| | 5735 | -5645 |




**NOT CONSTANT**

**Shapiro-Wilks Test for Normality**

| | Residuals ascending | Residuals descending | Column C-I | Coeffiicient a | | |
|---|---|---|---|---|---|---|
| 1 | -24659 | 43740 | 68399 | 0.5739 | 39254.19 | |
| 2 | -14239 | 30930 | 45169 | 0.3291 | 14865.12 | |
| 3 | -12605 | 9540 | 22145 | 0.2141 | 4741.245 | |
| 4 | -11442 | -5645 | 5797 | 0.1224 | 709.5528 | |
| 5 | -8432 | -7188 | 1244 | 0.0399 | 49.6356 | |
| 6 | -7188 | -8432 | -1244 | b= | 59619.74 | |
| 7 | -5645 | -11442 | -5797 | StdDev= | 16164.59 | |
| 8 | 9540 | -12605 | -22145 | SW= | 1.511499 | |
| 9 | 30930 | -14239 | -45169 | Critical pt = | 0.842 | 5% |
| 10 | 43740 | -24659 | -68399 | | | |

SW= Shapiro-Wilk Statistic

**Assume Normal**

# BM-11X-100N TRICHLOROETHEN

**Ordinary Least Squares Linear Regression Output Sheet**

| | |
|---|---|
| User Selected Options | |
| Date/Time of Computation | ProUCL 5.11/24/2022 11:48:26 AM |
| From File | COMPLIANCE DATA 2H2021_e.xls |
| Full Precision | OFF |
| Display Limits | True |
| Confidence Level for Intervals | 0.9 |
| Display Regresion Diagnostics | True |
| Display Regresion Tables | True |
| Title For Y vs X Plots | Classical Regression |
| Confidence Level for Regression Line | 0.9 |
| Display Confidence Band | True |
| Display Prediction Band | True |

| | |
|---|---|
| Dependendant Variable (Y-Data) | Trichloroethene_bm-11x-100n |
| Number Reported (Y values) | 10 |
| Independent Variable (x-data) | Date_bm-11x-100n |
| Number Reported (x-values) | 10 |

**Regression Estimates and Inference Table**

| Parameter | Estimates | Std. Error | T-values | p-values |
|---|---|---|---|---|
| intercept | -28.51 | 11.51 | -2.478 | 0.0382 |
| Date_bm-11x-100 | 7.6170E-4 | 2.6343E-4 | 2.891 | 0.0202 |

**OLS ANOVA Table**

| Source of Variation | SS | DOF | MS | F-Value | P-Value |
|---|---|---|---|---|---|
| **Regression** | 1.638 | 1 | 1.638 | 8.36 | 0.0202 |
| **Error** | 1.567 | 8 | 0.196 | | |
| **Total** | 3.205 | 9 | | | |

| | |
|---|---|
| R Square | 0.511 |
| Adjusted R Square | 0.45 |
| Sqrt(MSE) = Scale | 0.443 |

**Regression Table**


| Obs | Y Vector | Yhat | Residuals | Res/Scale |
|---|---|---|---|---|
| 1 | 4.5 | 4.12 | 0.38 | 0.858 |
| 2 | 3.6 | 4.26 | -0.66 | -1.491 |
| 3 | 4.7 | 4.396 | 0.304 | 0.687 |
| 4 | 4.5 | 4.532 | -0.0317 | -0.0716 |
| 5 | 4.3 | 4.679 | -0.379 | -0.856 |
| 6 | 4.9 | 4.811 | 0.0888 | 0.201 |
| 7 | 5 | 4.963 | 0.0372 | 0.084 |
| 8 | 5.7 | 5.115 | 0.585 | 1.321 |
| 9 | 5.5 | 5.245 | 0.255 | 0.575 |
| 10 | 4.8 | 5.379 | -0.579 | -1.307 |

**Summary Table for Prediction and Confidence Limits**

| Obs | X Vector | Y Vector | Yhat | s(Yhat) | s(pred) | LCL | UCL | LPL | UPL | Residuals |
|---|---|---|---|---|---|---|---|---|---|---|
| 1 | 42845 | 4.5 | 4.12 | 0.259 | 0.513 | 3.639 | 4.602 | 3.167 | 5.074 | 0.38 |
| 2 | 43028 | 3.6 | 4.26 | 0.22 | 0.494 | 3.851 | 4.669 | 3.341 | 5.179 | -0.66 |
| 3 | 43207 | 4.7 | 4.396 | 0.186 | 0.48 | 4.05 | 4.742 | 3.503 | 5.289 | 0.304 |
| 4 | 43385 | 4.5 | 4.532 | 0.159 | 0.47 | 4.236 | 4.827 | 3.657 | 5.406 | -0.0317 |


| | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|
| 5 | 43578 | 4.3 | 4.679 | 0.142 | 0.465 | 4.414 | 4.943 | 3.814 | 5.543 | -0.379 |
| 6 | 43752 | 4.9 | 4.811 | 0.142 | 0.465 | 4.548 | 5.074 | 3.947 | 5.675 | 0.0888 |
| 7 | 43951 | 5 | 4.963 | 0.158 | 0.47 | 4.669 | 5.257 | 4.089 | 5.837 | 0.0372 |
| 8 | 44151 | 5.7 | 5.115 | 0.189 | 0.481 | 4.765 | 5.466 | 4.221 | 6.01 | 0.585 |
| 9 | 44322 | 5.5 | 5.245 | 0.221 | 0.495 | 4.834 | 5.657 | 4.325 | 6.166 | 0.255 |
| 10 | 44497 | 4.8 | 5.379 | 0.259 | 0.513 | 4.898 | 5.86 | 4.425 | 6.332 | -0.579 |

| | X Vector | Residuals |
|---|---|---|
| 4/20/2017 | 42845 | 0.38 |
| 10/20/2017 | 43028 | -0.66 |
| 4/17/2018 | 43207 | 0.304 |
| 10/12/2018 | 43385 | -0.0317 |
| 4/23/2019 | 43578 | -0.379 |
| 10/14/2019 | 43752 | 0.0888 |
| 4/30/2020 | 43951 | 0.0372 |
| 11/16/2020 | 44151 | 0.585 |
| 5/6/2021 | 44322 | 0.255 |
| 10/28/2021 | 44497 | -0.579 |




**CONSTANT**

| | Yhat | Residuals |
|---|---|---|
| | 4.12 | 0.38 |
| | 4.26 | -0.66 |
| | 4.396 | 0.304 |
| | 4.532 | -0.0317 |
| | 4.679 | -0.379 |
| | 4.811 | 0.0888 |
| | 4.963 | 0.0372 |
| | 5.115 | 0.585 |
| | 5.245 | 0.255 |
| | 5.379 | -0.579 |




**CONSTANT**

**Shapiro-Wilks Test for Normality**

| | Residuals ascending | Residuals descendin g | Column C-l | Coeffiicien t | |
|---|---|---|---|---|---|
| 1 | -0.66 | 0.585 | 1.245 | 0.5739 | 0.714506 |
| 2 | -0.579 | 0.38 | 0.959 | 0.3291 | 0.315607 |
| 3 | -0.379 | 0.304 | 0.683 | 0.2141 | 0.14623 |
| 4 | -0.0317 | 0.255 | 0.2867 | 0.1224 | 0.035092 |
| 5 | 0.0372 | 0.0888 | 0.0516 | 0.0399 | 0.002059 |
| 6 | 0.0888 | 0.0372 | -0.0516 | b= | 1.213494 |
| 7 | 0.255 | -0.0317 | -0.2867 | StdDev= | 0.385456 |
| 8 | 0.304 | -0.379 | -0.683 | SW= | 1.101242 |
| 9 | 0.38 | -0.579 | -0.959 | Critical pt = | 0.842 |
| 10 | 0.585 | -0.66 | -1.245 | | |

SW= Shapiro-Wilk Statistic

5%

**Assume Normal**

# BM-15N6 NITRATE

Ordinary Least Squares Linear Regression Output Sheet

| | |
|---|---|
| User Selected Options | |
| Date/Time of Computation | ProUCL 5.11/24/2022 10:11:55 AM |
| From File | COMPLIANCE DATA 2H2021_b.xls |
| Full Precision | OFF |
| Display Limits | True |
| Confidence Level for Intervals | 0.9 |
| Display Regresion Diagnostics | True |
| Display Regresion Tables | True |
| Title For Y vs X Plots | Classical Regression |
| Confidence Level for Regression Line | 0.9 |
| Display Confidence Band | True |
| Display Prediction Band | True |

| | |
|---|---|
| Dependendant Variable (Y-Data) | Nitrogen, Nitrate_bm-15n6 |
| Number Reported (Y values) | 10 |
| Independent Variable (x-data) | Sample Date_bm-15n6 |
| Number Reported (x-values) | 10 |

**Regression Estimates and Inference Table**

| Parameter | Estimates | Std. Error | T-values | p-values |
|---|---|---|---|---|
| intercept | 481877 | 95458 | 5.048 | 9.9168E-4 |
| nple Date_bm-1! | -10.15 | 2.185 | -4.645 | 0.00166 |

**OLS ANOVA Table**

| Source of Variation | SS | DOF | MS | F-Value | P-Value |
|---|---|---|---|---|---|
| **Regression** | 2.965E+8 | 1 | 2.965E+8 | 21.58 | 0.0017 |
| **Error** | 1.100E+8 | 8 | 13743975 | | |
| **Total** | 4.065E+8 | 9 | | | |

| | |
|---|---|
| R Square | 0.73 |
| Adjusted R Square | 0.696 |
| Sqrt(MSE) = Scale | 3707 |


**Regression Table**

| Obs | Y Vector | Yhat | Residuals | Res/Scale |
|---|---|---|---|---|
| 1 | 46000 | 47008 | -1008 | -0.272 |
| 2 | 43000 | 45161 | -2161 | -0.583 |
| 3 | 42000 | 43324 | -1324 | -0.357 |
| 4 | 49000 | 41507 | 7493 | 2.021 |
| 5 | 35000 | 39589 | -4589 | -1.238 |
| 6 | 42000 | 37255 | 4745 | 1.28 |
| 7 | 35000 | 35702 | -702 | -0.189 |
| 8 | 32000 | 32800 | -799.5 | -0.216 |
| 9 | 31000 | 32211 | -1211 | -0.327 |
| 10 | 30000 | 30445 | -445 | -0.12 |

**Summary Table for Prediction and Confidence Limits**


| Obs | X Vector | Y Vector | Yhat | s(Yhat) | s(pred) | LCL | UCL | LPL | UPL | Residuals |
|---|---|---|---|---|---|---|---|---|---|---|
| 1 | 42850 | 46000 | 47008 | 2175 | 4298 | 42964 | 51051 | 39015 | 55000 | -1008 |
| 2 | 43032 | 43000 | 45161 | 1852 | 4144 | 41716 | 48605 | 37454 | 52867 | -2161 |
| 3 | 43213 | 42000 | 43324 | 1566 | 4025 | 40411 | 46236 | 35840 | 50807 | -1324 |
| 4 | 43392 | 49000 | 41507 | 1339 | 3942 | 39017 | 43997 | 34177 | 48837 | 7493 |
| 5 | 43581 | 35000 | 39589 | 1196 | 3895 | 37366 | 41812 | 32345 | 46832 | -4589 |
| 6 | 43811 | 42000 | 37255 | 1203 | 3897 | 35018 | 39491 | 30007 | 44502 | 4745 |
| 7 | 43964 | 35000 | 35702 | 1318 | 3935 | 33251 | 38153 | 28385 | 43019 | -702 |
| 8 | 44250 | 32000 | 32800 | 1697 | 4077 | 29644 | 35956 | 25218 | 40381 | -799.5 |
| 9 | 44308 | 31000 | 32211 | 1791 | 4117 | 28881 | 35541 | 24555 | 39867 | -1211 |
| 10 | 44482 | 30000 | 30445 | 2093 | 4257 | 26553 | 34337 | 22528 | 38362 | -445 |

| | X Vector | Residuals |
|---|---|---|
| 4/25/2017 | 42850 | -1008 |
| 10/24/2017 | 43032 | -2161 |
| 4/23/2018 | 43213 | -1324 |
| 10/19/2018 | 43392 | 7493 |
| 4/26/2019 | 43581 | -4589 |
| 12/12/2019 | 43811 | 4745 |
| 5/13/2020 | 43964 | -702 |
| 2/23/2021 | 44250 | -799.5 |
| 4/22/2021 | 44308 | -1211 |
| 10/13/2021 | 44482 | -445 |




**NOT CONSTANT**

| | Yhat | Residuals |
|---|---|---|
| | 47008 | -1008 |
| | 45161 | -2161 |
| | 43324 | -1324 |
| | 41507 | 7493 |
| | 39589 | -4589 |
| | 37255 | 4745 |
| | 35702 | -702 |
| | 32800 | -799.5 |
| | 32211 | -1211 |
| | 30445 | -445 |




**NOT CONSTANT**

**Shapiro-Wilks Test for Normality**

| | Residuals ascending | Residuals descending | Column C-I | Coeffiicient a | | | |
|---|---|---|---|---|---|---|---|
| 1 | -4589 | 7493 | 12082 | 0.5739 | 6933.86 | | |
| 2 | -2161 | 4745 | 6906 | 0.3291 | 2272.765 | | |
| 3 | -1324 | -445 | 879 | 0.2141 | 188.1939 | | |
| 4 | -1211 | -702 | 509 | 0.1224 | 62.3016 | | |
| 5 | -1008 | -799.5 | 208.5 | 0.0399 | 8.31915 | | |
| 6 | -799.5 | -1008 | -208.5 | b= | 9465.439 | | |
| 7 | -702 | -1211 | -509 | StdDev= | 2438.458 | | |
| 8 | -445 | -1324 | -879 | SW= | 1.674204 | | |
| 9 | 4745 | -2161 | -6906 | Critical pt = | 0.842 | 5% | |
| 10 | 7493 | -4589 | -12082 | | | | |

SW= Shapiro-Wilk Statistic

**Assume Normal**

# MW38-830N-230E 1,4-DIOXANE

**Ordinary Least Squares Linear Regression Output Sheet**

| | |
|---|---|
| User Selected Options | |
| Date/Time of Computation | ProUCL 5.11/24/2022 10:08:16 AM |
| From File | COMPLIANCE DATA 2H2021.xls |
| Full Precision | OFF |
| Display Limits | True |
| Confidence Level for Intervals | 0.9 |
| Display Regresion Diagnostics | True |
| Display Regresion Tables | True |
| Title For Y vs X Plots | Classical Regression |
| Confidence Level for Regression Line | 0.9 |
| Display Confidence Band | True |
| Display Prediction Band | True |

| | |
|---|---|
| Dependendant Variable (Y-Data) | 1,4-Dioxane_mw38-830n-230e |
| Number Reported (Y values) | 10 |
| Independent Variable (x-data) | Sample Date_mw38-830n-230e |
| Number Reported (x-values) | 10 |

**Regression Estimates and Inference Table**

| Parameter | Estimates | Std. Error | T-values | p-values |
|---|---|---|---|---|
| intercept | 288.7 | 72.05 | 4.007 | 0.00391 |
| Date_mw38-83( | -0.00646 | 0.00165 | -3.912 | 0.00447 |

**OLS ANOVA Table**

| Source of Variation | SS | DOF | MS | F-Value | P-Value |
|---|---|---|---|---|---|
| **Regression** | 113.9 | 1 | 113.9 | 15.3 | 0.0045 |
| **Error** | 59.52 | 8 | 7.44 | | |
| **Total** | 173.4 | 9 | | | |

| | |
|---|---|
| R Square | 0.657 |
| Adjusted R Square | 0.614 |
| Sqrt(MSE) = Scale | 2.728 |

**Regression Table**


| Obs | Y Vector | Yhat | Residuals | Res/Scale |
|---|---|---|---|---|
| 1 | 12 | 12.1 | -0.0972 | -0.0357 |
| 2 | 12 | 10.88 | 1.123 | 0.412 |
| 3 | 9.3 | 9.741 | -0.441 | -0.162 |
| 4 | 13 | 9.076 | 3.924 | 1.439 |
| 5 | 7.1 | 7.353 | -0.253 | -0.0926 |
| 6 | 2.4 | 6.229 | -3.829 | -1.404 |
| 7 | 2 | 5.597 | -3.597 | -1.319 |
| 8 | 2.1 | 3.731 | -1.631 | -0.598 |
| 9 | 4.5 | 2.737 | 1.763 | 0.646 |
| 10 | 4.6 | 1.562 | 3.038 | 1.114 |

**Summary Table for Prediction and Confidence Limits**

| Obs | X Vector | Y Vector | Yhat | s(Yhat) | s(pred) | LCL | UCL | LPL | UPL | Residuals |
|---|---|---|---|---|---|---|---|---|---|---|
| 1 | 42851 | 12 | 12.1 | 1.584 | 3.154 | 9.152 | 15.04 | 6.232 | 17.96 | -0.0972 |
| 2 | 43040 | 12 | 10.88 | 1.333 | 3.036 | 8.398 | 13.36 | 5.231 | 16.52 | 1.123 |
| 3 | 43216 | 9.3 | 9.741 | 1.128 | 2.952 | 7.644 | 11.84 | 4.252 | 15.23 | -0.441 |
| 4 | 43319 | 13 | 9.076 | 1.026 | 2.914 | 7.167 | 10.98 | 3.657 | 14.5 | 3.924 |
| 5 | 43586 | 7.1 | 7.353 | 0.87 | 2.863 | 5.734 | 8.971 | 2.028 | 12.68 | -0.253 |


| | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|
| 6 | 43760 | 2.4 | 6.229 | 0.879 | 2.866 | 4.594 | 7.865 | 0.9 | 11.56 | -3.829 |
| 7 | 43858 | 2 | 5.597 | 0.925 | 2.88 | 3.877 | 7.316 | 0.241 | 10.95 | -3.597 |
| 8 | 44147 | 2.1 | 3.731 | 1.183 | 2.973 | 1.531 | 5.932 | -1.798 | 9.26 | -1.631 |
| 9 | 44301 | 4.5 | 2.737 | 1.37 | 3.052 | 0.19 | 5.284 | -2.939 | 8.413 | 1.763 |
| 10 | 44483 | 4.6 | 1.562 | 1.614 | 3.17 | -1.44 | 4.564 | -4.332 | 7.456 | 3.038 |

| | X Vector | Residuals |
|---|---|---|
| 4/26/2017 | 42851 | -0.0972 |
| 11/1/2017 | 43040 | 1.123 |
| 4/26/2018 | 43216 | -0.441 |
| 8/7/2018 | 43319 | 3.924 |
| 5/1/2019 | 43586 | -0.253 |
| 10/22/2019 | 43760 | -3.829 |
| 1/28/2020 | 43858 | -3.597 |
| 11/12/2020 | 44147 | -1.631 |
| 4/15/2021 | 44301 | 1.763 |
| 10/14/2021 | 44483 | 3.038 |




**NOT CONSTANT**

| | Yhat | Residuals |
|---|---|---|
| | 12.1 | -0.0972 |
| | 10.88 | 1.123 |
| | 9.741 | -0.441 |
| | 9.076 | 3.924 |
| | 7.353 | -0.253 |
| | 6.229 | -3.829 |
| | 5.597 | -3.597 |
| | 3.731 | -1.631 |
| | 2.737 | 1.763 |
| | 1.562 | 3.038 |




**NOT CONSTANT**

**Shapiro-Wilks Test for Normality**

SW= Shapiro-Wilk Statistic

| | Residuals ascending | Residuals descendin | Column C-I | Coeffiicient | |
|---|---|---|---|---|---|
| 1 | -3.829 | 3.924 | 7.753 | 0.5739 | 4.449447 |
| 2 | -3.597 | 3.038 | 6.635 | 0.3291 | 2.183579 |
| 3 | -1.631 | 1.763 | 3.394 | 0.2141 | 0.726655 |
| 4 | -0.441 | 1.123 | 1.564 | 0.1224 | 0.191434 |
| 5 | -0.253 | -0.0972 | 0.1558 | 0.0399 | 0.006216 |
| 6 | -0.0972 | -0.253 | -0.1558 | b= | 7.557331 |
| 7 | 1.123 | -0.441 | -1.564 | StdDev= | 2.302592 |
| 8 | 1.763 | -1.631 | -3.394 | SW= | 1.196906 |
| 9 | 3.038 | -3.597 | -6.635 | Critical pt = | 0.842 5% |
| 10 | 3.924 | -3.829 | -7.753 | | |

**Assume Normal**

# MW38-830N-230E CHLOROFORM

**Ordinary Least Squares Linear Regression Output Sheet**

| | |
|---|---|
| User Selected Options | |
| Date/Time of Computation | ProUCL 5.11/24/2022 10:10:48 AM |
| From File | COMPLIANCE DATA 2H2021_a.xls |
| Full Precision | OFF |
| Display Limits | True |
| Confidence Level for Intervals | 0.9 |
| Display Regresion Diagnostics | True |
| Display Regresion Tables | True |
| Title For Y vs X Plots | Classical Regression |
| Confidence Level for Regression Line | 0.9 |
| Display Confidence Band | True |
| Display Prediction Band | True |

| | |
|---|---|
| Dependendant Variable (Y-Data) | Chloroform_mw38-830n-230e |
| Number Reported (Y values) | 10 |
| Independent Variable (x-data) | Sample Date_mw38-830n-230e |
| Number Reported (x-values) | 10 |

**Regression Estimates and Inference Table**

| Parameter | Estimates | Std. Error | T-values | p-values |
|---|---|---|---|---|
| intercept | 111.5 | 35.11 | 3.175 | 0.0131 |
| Date_mw38-83( | -0.00245 | 8.0408E-4 | -3.045 | 0.0159 |

**OLS ANOVA Table**

| Source of Variation | SS | DOF | MS | F-Value | P-Value |
|---|---|---|---|---|---|
| **Regression** | 16.54 | 1 | 16.54 | 9.273 | 0.0159 |
| **Error** | 14.27 | 8 | 1.783 | | |
| **Total** | 30.8 | 9 | | | |

| | |
|---|---|
| R Square | 0.537 |
| Adjusted R Square | 0.479 |
| Sqrt(MSE) = Scale | 1.335 |


**Regression Table**

| Obs | Y Vector | Yhat | Residuals | Res/Scale |
|---|---|---|---|---|
| 1 | 6.4 | 6.536 | -0.136 | -0.102 |
| 2 | 6.9 | 6.073 | 0.827 | 0.619 |
| 3 | 6.2 | 5.642 | 0.558 | 0.417 |
| 4 | 5.9 | 5.39 | 0.51 | 0.382 |
| 5 | 5.4 | 4.737 | 0.663 | 0.497 |
| 6 | 2.1 | 4.31 | -2.21 | -1.655 |
| 7 | 2.1 | 4.071 | -1.971 | -1.476 |
| 8 | 2.6 | 3.363 | -0.763 | -0.571 |
| 9 | 4.3 | 2.937 | 1.363 | 1.021 |
| 10 | 3.7 | 2.54 | 1.16 | 0.868 |


**Summary Table for Prediction and Confidence Limits**

| Obs | X Vector | Y Vector | Yhat | s(Yhat) | s(pred) | LCL | UCL | LPL | UPL | Residuals |
|---|---|---|---|---|---|---|---|---|---|---|
| 1 | 42851 | 6.4 | 6.536 | 0.774 | 1.544 | 5.096 | 7.976 | 3.666 | 9.407 | -0.136 |
| 2 | 43040 | 6.9 | 6.073 | 0.652 | 1.486 | 4.861 | 7.286 | 3.31 | 8.837 | 0.827 |
| 3 | 43216 | 6.2 | 5.642 | 0.552 | 1.445 | 4.616 | 6.669 | 2.955 | 8.33 | 0.558 |
| 4 | 43319 | 5.9 | 5.39 | 0.503 | 1.427 | 4.456 | 6.325 | 2.737 | 8.044 | 0.51 |
| 5 | 43586 | 5.4 | 4.737 | 0.426 | 1.402 | 3.944 | 5.529 | 2.13 | 7.343 | 0.663 |
| 6 | 43760 | 2.1 | 4.31 | 0.43 | 1.403 | 3.511 | 5.11 | 1.702 | 6.919 | -2.21 |
| 7 | 43858 | 2.1 | 4.071 | 0.452 | 1.41 | 3.23 | 4.911 | 1.449 | 6.692 | -1.971 |
| 8 | 44147 | 2.6 | 3.363 | 0.577 | 1.455 | 2.29 | 4.436 | 0.658 | 6.068 | -0.763 |
| 9 | 44321 | 4.3 | 2.937 | 0.68 | 1.499 | 1.672 | 4.201 | 0.15 | 5.724 | 1.363 |
| 10 | 44483 | 3.7 | 2.54 | 0.786 | 1.55 | 1.078 | 4.002 | -0.342 | 5.422 | 1.16 |

| | X Vector | Residuals |
|---|---|---|
| 42851 | 42851 | -0.136 |




| | | |
|---|---|---|
| 43040 | 43040 | 0.827 |
| 43216 | 43216 | 0.558 |
| 43319 | 43319 | 0.51 |
| 43586 | 43586 | 0.663 |
| 43760 | 43760 | -2.21 |
| 43858 | 43858 | -1.971 |
| 44147 | 44147 | -0.763 |
| 44321 | 44321 | 1.363 |
| 44483 | 44483 | 1.16 |




ANT

**NOT CONSTANT**

| Yhat | Residuals |
|---|---|
| 6.536 | -0.136 |
| 6.073 | 0.827 |
| 5.642 | 0.558 |
| 5.39 | 0.51 |
| 4.737 | 0.663 |
| 4.31 | -2.21 |
| 4.071 | -1.971 |
| 3.363 | -0.763 |
| 2.937 | 1.363 |
| 2.54 | 1.16 |




**NOT CONSTANT**

**Shapiro-Wilks Test for Normality**

SW= Shapiro-Wilk Statistic

| | Residuals ascending | Residuals descending | Column C- a | Coeffiicient | |
|---|---|---|---|---|---|
| 1 | -2.21 | 1.363 | 3.573 | 0.5739 | 2.050545 |
| 2 | -1.971 | 1.16 | 3.131 | 0.3291 | 1.030412 |
| 3 | -0.763 | 0.827 | 1.59 | 0.2141 | 0.340419 |
| 4 | -0.136 | 0.663 | 0.799 | 0.1224 | 0.097798 |
| 5 | 0.51 | 0.558 | 0.048 | 0.0399 | 0.001915 |
| 6 | 0.558 | 0.51 | -0.048 | b= | 3.521089 |
| 7 | 0.663 | -0.136 | -0.799 | StdDev= | 1.235114 |
| 8 | 0.827 | -0.763 | -1.59 | SW= | 0.90302 |
| 9 | 1.16 | -1.971 | -3.131 | Critical pt = | 0.842 5% |
| 10 | 1.363 | -2.21 | -3.573 | | |

**Assume Normal**

# MW62-WDR 1,4-DIOXANE

**Ordinary Least Squares Linear Regression Output Sheet**

| | |
|---|---|
| User Selected Options | |
| Date/Time of Computation | ProUCL 5.11/24/2022 10:08:16 AM |
| From File | COMPLIANCE DATA 2H2021.xls |
| Full Precision | OFF |
| | |
| Display Limits | True |
| Confidence Level for Intervals | 0.9 |
| Display Regresion Diagnostics | True |
| Display Regresion Tables | True |
| Title For Y vs X Plots | Classical Regression |
| Confidence Level for Regression Line | 0.9 |
| Display Confidence Band | True |
| Display Prediction Band | True |

| | |
|---|---|
| Dependendant Variable (Y-Data) | 1,4-Dioxane_mw62-wdr |
| Number Reported (Y values) | 10 |
| Independent Variable (x-data) | Sample Date_mw62-wdr |
| Number Reported (x-values) | 10 |

**Regression Estimates and Inference Table**

| Parameter | Estimates | Std. Error | T-values | p-values |
|---|---|---|---|---|
| intercept | 39.48 | 5.605 | 7.044 | 1.0781E-4 |
| ıple Date_mw62- | -8.187E-4 | 1.2824E-4 | -6.384 | 2.1266E-4 |

**OLS ANOVA Table**

| Source of Variation | SS | DOF | MS | F-Value | P-Value |
|---|---|---|---|---|---|
| **Regression** | 1.622 | 1 | 1.622 | 40.76 | 0.0002 |
| **Error** | 0.318 | 8 | 0.0398 | | |
| **Total** | 1.94 | 9 | | | |

| | |
|---|---|
| R Square | 0.836 |
| Adjusted R Square | 0.815 |
| Sqrt(MSE) = Scale | 0.199 |

**Regression Table**


| Obs | Y Vector | Yhat | Residuals | Res/Scale |
|---|---|---|---|---|
| 1 | 4.6 | 4.261 | 0.339 | 1.699 |
| 2 | 3.9 | 4.142 | -0.242 | -1.215 |
| 3 | 4.2 | 4.09 | 0.11 | 0.551 |
| 4 | 3.8 | 4.023 | -0.223 | -1.117 |
| 5 | 3.9 | 3.788 | 0.112 | 0.562 |
| 6 | 3.5 | 3.61 | -0.11 | -0.553 |
| 7 | 3.4 | 3.488 | -0.0883 | -0.443 |
| 8 | 3.2 | 3.34 | -0.14 | -0.702 |
| 9 | 3.3 | 3.203 | 0.0966 | 0.484 |
| 10 | 3.2 | 3.054 | 0.146 | 0.734 |

**Summary Table for Prediction and Confidence Limits**

| Obs | X Vector | Y Vector | Yhat | s(Yhat) | s(pred) | LCL | UCL | LPL | UPL | Residuals |
|---|---|---|---|---|---|---|---|---|---|---|
| 1 | 43021 | 4.6 | 4.261 | 0.108 | 0.227 | 4.06 | 4.462 | 3.839 | 4.683 | 0.339 |
| 2 | 43166 | 3.9 | 4.142 | 0.0937 | 0.22 | 3.968 | 4.317 | 3.733 | 4.552 | -0.242 |
| 3 | 43230 | 4.2 | 4.09 | 0.0878 | 0.218 | 3.927 | 4.253 | 3.685 | 4.495 | 0.11 |
| 4 | 43312 | 3.8 | 4.023 | 0.0809 | 0.215 | 3.873 | 4.173 | 3.623 | 4.423 | -0.223 |


| | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|
| 5 | 43599 | 3.9 | 3.788 | 0.0646 | 0.21 | 3.668 | 3.908 | 3.398 | 4.178 | 0.112 |
| 6 | 43816 | 3.5 | 3.61 | 0.0646 | 0.21 | 3.49 | 3.73 | 3.22 | 4 | -0.11 |
| 7 | 43965 | 3.4 | 3.488 | 0.0713 | 0.212 | 3.356 | 3.621 | 3.094 | 3.882 | -0.0883 |
| 8 | 44146 | 3.2 | 3.34 | 0.0846 | 0.217 | 3.183 | 3.497 | 2.937 | 3.743 | -0.14 |
| 9 | 44313 | 3.3 | 3.203 | 0.1 | 0.223 | 3.017 | 3.39 | 2.788 | 3.618 | 0.0966 |
| 10 | 44496 | 3.2 | 3.054 | 0.119 | 0.232 | 2.832 | 3.275 | 2.621 | 3.486 | 0.146 |

| | X Vector | Residuals |
|---|---|---|
| 10/13/2017 | 43021 | 0.339 |
| 3/7/2018 | 43166 | -0.242 |
| 5/10/2018 | 43230 | 0.11 |
| 7/31/2018 | 43312 | -0.223 |
| 5/14/2019 | 43599 | 0.112 |
| 12/17/2019 | 43816 | -0.11 |
| 5/14/2020 | 43965 | -0.0883 |
| 11/11/2020 | 44146 | -0.14 |
| 4/27/2021 | 44313 | 0.0966 |
| 10/27/2021 | 44496 | 0.146 |




**CONSTANT**

| | Yhat | Residuals |
|---|---|---|
| | 4.261 | 0.339 |
| | 4.142 | -0.242 |
| | 4.09 | 0.11 |
| | 4.023 | -0.223 |
| | 3.788 | 0.112 |
| | 3.61 | -0.11 |
| | 3.488 | -0.0883 |
| | 3.34 | -0.14 |
| | 3.203 | 0.0966 |
| | 3.054 | 0.146 |




**CONSTANT**

**Shapiro-Wilks Test for Normality**

| | Residuals ascending | Residuals descendin | Column C-I | Coeffiicien t | |
|---|---|---|---|---|---|
| 1 | -0.242 | 0.339 | 0.581 | 0.5739 | 0.333436 |
| 2 | -0.223 | 0.146 | 0.369 | 0.3291 | 0.121438 |
| 3 | -0.14 | 0.112 | 0.252 | 0.2141 | 0.053953 |
| 4 | -0.11 | 0.11 | 0.22 | 0.1224 | 0.026928 |
| 5 | -0.0883 | 0.0966 | 0.1849 | 0.0399 | 0.007378 |
| 6 | 0.0966 | -0.0883 | -0.1849 | b= | 0.543133 |
| 7 | 0.11 | -0.11 | -0.22 | StdDev= | 0.154246 |
| 8 | 0.112 | -0.14 | -0.252 | SW= | 1.377655 |
| 9 | 0.146 | -0.223 | -0.369 | Critical pt = | 0.842 5% |
| 10 | 0.339 | -0.242 | -0.581 | | |

SW= Shapiro-Wilk Statistic

**Assume Normal**

# MW62-WDR NITRITE

**Ordinary Least Squares Linear Regression Output Sheet**

| | |
|---|---|
| User Selected Options | |
| Date/Time of Computation | ProUCL 5.11/24/2022 10:13:02 AM |
| From File | COMPLIANCE DATA 2H2021_c.xls |
| Full Precision | OFF |
| Display Limits | True |
| Confidence Level for Intervals | 0.9 |
| Display Regresion Diagnostics | True |
| Display Regresion Tables | True |
| Title For Y vs X Plots | Classical Regression |
| Confidence Level for Regression Line | 0.9 |
| Display Confidence Band | True |
| Display Prediction Band | True |

| | |
|---|---|
| Dependendant Variable (Y-Data) | Nitrogen, Nitrite_mw62-wdr |
| Number Reported (Y values) | 10 |
| Independent Variable (x-data) | Sample Date_mw62-wdr |
| Number Reported (x-values) | 10 |

**Regression Estimates and Inference Table**

| Parameter | Estimates | Std. Error | T-values | p-values |
|---|---|---|---|---|
| intercept | 87846 | 30588 | 2.872 | 0.0208 |
| ıple Date_mw62· | -1.953 | 0.7 | -2.791 | 0.0235 |

**OLS ANOVA Table**

| Source of Variation | SS | DOF | MS | F-Value | P-Value |
|---|---|---|---|---|---|
| **Regression** | 9232651 | 1 | 9232651 | 7.792 | 0.0235 |
| **Error** | 9478959 | 8 | 1184870 | | |
| **Total** | 18711610 | 9 | | | |

| | |
|---|---|
| R Square | 0.493 |
| Adjusted R Square | 0.43 |
| Sqrt(MSE) = Scale | 1089 |

**Regression Table**


| Obs | Y Vector | Yhat | Residuals | Res/Scale |
|---|---|---|---|---|
| 1 | 3600 | 3806 | -205.9 | -0.189 |
| 2 | 5400 | 3523 | 1877 | 1.725 |
| 3 | 4000 | 3398 | 602.4 | 0.553 |
| 4 | 2400 | 3237 | -837.5 | -0.769 |
| 5 | 1900 | 2677 | -776.8 | -0.714 |
| 6 | 980 | 2253 | -1273 | -1.169 |
| 7 | 1500 | 1962 | -461.8 | -0.424 |
| 8 | 890 | 1608 | -718.3 | -0.66 |
| 9 | 1800 | 1282 | 518 | 0.476 |
| 10 | 2200 | 924.5 | 1275 | 1.172 |

**Summary Table for Prediction and Confidence Limits**

| Obs | X Vector | Y Vector | Yhat | s(Yhat) | s(pred) | LCL | UCL | LPL | UPL | Residuals |
|---|---|---|---|---|---|---|---|---|---|---|
| 1 | 43021 | 3600 | 3806 | 590.4 | 1238 | 2708 | 4904 | 1503 | 6109 | -205.9 |
| 2 | 43166 | 5400 | 3523 | 511.4 | 1203 | 2572 | 4474 | 1286 | 5759 | 1877 |
| 3 | 43230 | 4000 | 3398 | 479.2 | 1189 | 2507 | 4289 | 1186 | 5609 | 602.4 |
| 4 | 43312 | 2400 | 3237 | 441.2 | 1175 | 2417 | 4058 | 1053 | 5422 | -837.5 |


| | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|
| 5 | 43599 | 1900 | 2677 | 352.3 | 1144 | 2022 | 3332 | 549.3 | 4804 | -776.8 |
| 6 | 43816 | 980 | 2253 | 352.7 | 1144 | 1597 | 2909 | 125.2 | 4381 | -1273 |
| 7 | 43965 | 1500 | 1962 | 388.9 | 1156 | 1239 | 2685 | -187.6 | 4111 | -461.8 |
| 8 | 44146 | 890 | 1608 | 461.7 | 1182 | 749.8 | 2467 | -590.4 | 3807 | -718.3 |
| 9 | 44313 | 1800 | 1282 | 546.5 | 1218 | 265.7 | 2298 | -982.9 | 3547 | 518 |
| 10 | 44496 | 2200 | 924.5 | 651 | 1268 | -286.1 | 2135 | -1434 | 3283 | 1275 |

| | X Vector | Residuals |
|---|---|---|
| 10/13/2017 | 43021 | -205.9 |
| 3/7/2018 | 43166 | 1877 |
| 5/10/2018 | 43230 | 602.4 |
| 7/31/2018 | 43312 | -837.5 |
| 5/14/2019 | 43599 | -776.8 |
| 12/17/2019 | 43816 | -1273 |
| 5/14/2020 | 43965 | -461.8 |
| 11/11/2020 | 44146 | -718.3 |
| 4/27/2021 | 44313 | 518 |
| 10/27/2021 | 44496 | 1275 |




**NOT CONSTANT**

| | Yhat | Residuals |
|---|---|---|
| | 3806 | -205.9 |
| | 3523 | 1877 |
| | 3398 | 602.4 |
| | 3237 | -837.5 |
| | 2677 | -776.8 |
| | 2253 | -1273 |
| | 1962 | -461.8 |
| | 1608 | -718.3 |
| | 1282 | 518 |
| | 924.5 | 1275 |




**NOT CONSTANT**

**Shapiro-Wilks Test for Normality**

| | Residuals ascending | Residuals descendin | Column C-I | Coeffiicien t | | |
|---|---|---|---|---|---|---|
| 1 | -1273 | 1877 | 3150 | 0.5739 | 1807.785 | |
| 2 | -837.5 | 1275 | 2112.5 | 0.3291 | 695.2238 | |
| 3 | -776.8 | 602.4 | 1379.2 | 0.2141 | 295.2867 | |
| 4 | -718.3 | 518 | 1236.3 | 0.1224 | 151.3231 | |
| 5 | -461.8 | -205.9 | 255.9 | 0.0399 | 10.21041 | |
| 6 | -205.9 | -461.8 | -255.9 | b= | 2959.829 | |
| 7 | 518 | -718.3 | -1236.3 | StdDev= | 833.8137 | |
| 8 | 602.4 | -776.8 | -1379.2 | SW= | 1.400079 | |
| 9 | 1275 | -837.5 | -2112.5 | Critical pt = | 0.842 | 5% |
| 10 | 1877 | -1273 | -3150 | | | |

SW= Shapiro-Wilk Statistic

**Assume Normal**

# MW106-UD 1,4-DIOXANE

**Ordinary Least Squares Linear Regression Output Sheet**

| | |
|---|---|
| User Selected Options | |
| Date/Time of Computation | ProUCL 5.11/24/2022 10:08:16 AM |
| From File | COMPLIANCE DATA 2H2021.xls |
| Full Precision | OFF |
| Display Limits | True |
| Confidence Level for Intervals | 0.9 |
| Display Regresion Diagnostics | True |
| Display Regresion Tables | True |
| Title For Y vs X Plots | Classical Regression |
| Confidence Level for Regression Line | 0.9 |
| Display Confidence Band | True |
| Display Prediction Band | True |

| | |
|---|---|
| Dependendant Variable (Y-Data) | 1,4-Dioxane_mw106-ud |
| Number Reported (Y values) | 10 |
| Independent Variable (x-data) | Sample Date_mw106-ud |
| Number Reported (x-values) | 10 |

**Regression Estimates and Inference Table**

| Parameter | Estimates | Std. Error | T-values | p-values |
|---|---|---|---|---|
| intercept | 20.8 | 13.53 | 1.538 | 0.163 |
| ıple Date_mw10 | -4.806E-4 | 3.2788E-4 | -1.466 | 0.181 |

**OLS ANOVA Table**

| Source of Variation | SS | DOF | MS | F-Value | P-Value |
|---|---|---|---|---|---|
| **Regression** | 7.203 | 1 | 7.203 | 2.149 | 0.1809 |
| **Error** | 26.82 | 8 | 3.352 | | |
| **Total** | 34.02 | 9 | | | |

| | |
|---|---|
| R Square | 0.212 |
| Adjusted R Square | 0.113 |
| Sqrt(MSE) = Scale | 1.831 |

**Regression Table**


| Obs | Y Vector | Yhat | Residuals | Res/Scale |
|---|---|---|---|---|
| 1 | 0.5 | 2.036 | -1.536 | -0.839 |
| 2 | 6.5 | 1.989 | 4.511 | 2.464 |
| 3 | 0.5 | 1.948 | -1.448 | -0.791 |
| 4 | 0.5 | 1.558 | -1.058 | -0.578 |
| 5 | 0.5 | 1.216 | -0.716 | -0.391 |
| 6 | 0.5 | 0.861 | -0.361 | -0.197 |
| 7 | 0.5 | 0.52 | -0.0196 | -0.0107 |
| 8 | 0.15 | 0.162 | -0.012 | -0.00658 |
| 9 | 0.15 | -0.0201 | 0.17 | 0.0929 |
| 10 | 0.09 | -0.38 | 0.47 | 0.256 |

**Summary Table for Prediction and Confidence Limits**

| Obs | X Vector | Y Vector | Yhat | s(Yhat) | s(pred) | LCL | UCL | LPL | UPL | Residuals |
|---|---|---|---|---|---|---|---|---|---|---|
| 1 | 39042 | 0.5 | 2.036 | 0.92 | 2.049 | 0.326 | 3.747 | -1.774 | 5.847 | -1.536 |
| 2 | 39141 | 6.5 | 1.989 | 0.895 | 2.038 | 0.325 | 3.653 | -1.801 | 5.778 | 4.511 |
| 3 | 39227 | 0.5 | 1.948 | 0.873 | 2.029 | 0.323 | 3.572 | -1.825 | 5.72 | -1.448 |
| 4 | 40037 | 0.5 | 1.558 | 0.697 | 1.959 | 0.262 | 2.855 | -2.085 | 5.201 | -1.058 |


| | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|
| 5 | 40750 | 0.5 | 1.216 | 0.599 | 1.927 | 0.101 | 2.33 | -2.367 | 4.798 | -0.716 |
| 6 | 41487 | 0.5 | 0.861 | 0.586 | 1.922 | -0.227 | 1.95 | -2.713 | 4.436 | -0.361 |
| 7 | 42198 | 0.5 | 0.52 | 0.662 | 1.947 | -0.711 | 1.75 | -3.101 | 4.14 | -0.0196 |
| 8 | 42942 | 0.15 | 0.162 | 0.808 | 2.001 | -1.341 | 1.665 | -3.56 | 3.884 | -0.012 |
| 9 | 43321 | 0.15 | -0.0201 | 0.9 | 2.04 | -1.693 | 1.653 | -3.814 | 3.773 | 0.17 |
| 10 | 44069 | 0.09 | -0.38 | 1.099 | 2.135 | -2.423 | 1.663 | -4.35 | 3.591 | 0.47 |

| | X Vector | Residuals |
|---|---|---|
| 11/21/2006 | 39042 | -1.536 |
| 2/28/2007 | 39141 | 4.511 |
| 5/25/2007 | 39227 | -1.448 |
| 8/12/2009 | 40037 | -1.058 |
| 7/26/2011 | 40750 | -0.716 |
| 8/1/2013 | 41487 | -0.361 |
| 7/13/2015 | 42198 | -0.0196 |
| 7/26/2017 | 42942 | -0.012 |
| 8/9/2018 | 43321 | 0.17 |
| 8/26/2020 | 44069 | 0.47 |




**NOT CONSTANT**

| | Yhat | Residuals |
|---|---|---|
| | 2.036 | -1.536 |
| | 1.989 | 4.511 |
| | 1.948 | -1.448 |
| | 1.558 | -1.058 |
| | 1.216 | -0.716 |
| | 0.861 | -0.361 |
| | 0.52 | -0.0196 |
| | 0.162 | -0.012 |
| | -0.0201 | 0.17 |
| | -0.38 | 0.47 |




**NOT CONSTANT**

**Shapiro-Wilks Test for Normality**

SW= Shapiro-Wilk Statistic

| | Residuals ascending | Residuals descending | Column C- | Coefficient | |
|---|---|---|---|---|---|
| 1 | -1.536 | 4.511 | 6.047 | 0.5739 | 3.470373 |
| 2 | -1.448 | 0.47 | 1.918 | 0.3291 | 0.631214 |
| 3 | -1.058 | 0.17 | 1.228 | 0.2141 | 0.262915 |
| 4 | -0.716 | -0.012 | 0.704 | 0.1224 | 0.08617 |
| 5 | -0.361 | -0.0196 | 0.3414 | 0.0399 | 0.013622 |
| 6 | -0.0196 | -0.361 | -0.3414 | b= | 4.464293 |
| 7 | -0.012 | -0.716 | -0.704 | StdDev= | 0.725263 |
| 8 | 0.17 | -1.058 | -1.228 | SW= | 4.209896 |
| 9 | 0.47 | -1.448 | -1.918 | Critical pt = | 0.842 5% |
| 10 | 4.511 | -1.536 | -6.047 | | |

**Assume Normal**

# APPENDIX C-3.6

# COMPLIANCE EVALUATION STATISTICAL TESTING

## Upper Control Limit Analysis for Data Without Trends

## Normal UCL Statistics for Uncensored Full Data Sets

| | |
|---|---|
| User Selected Options | |
| Date/Time of Computation | ProUCL 5.11/20/2022 4:04:46 PM |
| From File | COMPLIANCE DATA 2H2021.xls |
| Full Precision | OFF |
| Confidence Coefficient | 90% |

**1,4-Dioxane (b-313)**

### General Statistics

| | | | |
|---|---|---|---|
| Total Number of Observations | 10 | Number of Distinct Observations | 9 |
| | | Number of Missing Observations | 0 |
| Minimum | 2.3 | Mean | 14.75 |
| Maximum | 21 | Median | 16.5 |
| SD | 5.788 | SD of logged Data | 0.673 |
| Coefficient of Variation | 0.392 | Skewness | -1.37 |

### Normal GOF Test

| | | |
|---|---|---|
| Shapiro Wilk Test Statistic | 0.858 | **Shapiro Wilk GOF Test** |
| 5% Shapiro Wilk Critical Value | 0.842 | Data appear Normal at 5% Significance Level |
| Lilliefors Test Statistic | 0.248 | **Lilliefors GOF Test** |
| 5% Lilliefors Critical Value | 0.262 | Data appear Normal at 5% Significance Level |

**Data appear Normal at 5% Significance Level**

### Assuming Normal Distribution

| 90% Normal UCL | | 90% UCLs (Adjusted for Skewness) | |
|---|---|---|---|
| 90% Student's-t UCL | 17.28 | 90% Adjusted-CLT UCL (Chen-1995) | 16.53 |
| | | 90% Modified-t UCL (Johnson-1978) | 17.15 |

### Suggested UCL to Use

**Recommendation Provided only for 95% Confidence Coefficient**

**Note: For highly negatively-skewed data, confidence limits (e.g., Chen, Johnson, Lognormal, and Gamma) may not be reliable. Chen's and Johnson's methods provide adjustments for positvely skewed data sets.**

## Normal UCL Statistics for Uncensored Full Data Sets

| | |
|---|---|
| User Selected Options | |
| Date/Time of Computation | ProUCL 5.11/24/2022 9:06:46 AM |
| From File | COMPLIANCE DATA 2H2021_b.xls |
| Full Precision | OFF |
| Confidence Coefficient | 90% |

**Nitrogen, Nitrate (b-313)**

### General Statistics

| | | | |
|---|---|---|---|
| Total Number of Observations | 10 | Number of Distinct Observations | 9 |
| | | Number of Missing Observations | 0 |
| Minimum | 21000 | Mean | 33600 |
| Maximum | 55000 | Median | 31000 |
| SD | 11462 | SD of logged Data | 0.335 |
| Coefficient of Variation | 0.341 | Skewness | 0.671 |

### Normal GOF Test

| | | | |
|---|---|---|---|
| Shapiro Wilk Test Statistic | 0.922 | **Shapiro Wilk GOF Test** | |
| 5% Shapiro Wilk Critical Value | 0.842 | Data appear Normal at 5% Significance Level | |
| Lilliefors Test Statistic | 0.156 | **Lilliefors GOF Test** | |
| 5% Lilliefors Critical Value | 0.262 | Data appear Normal at 5% Significance Level | |

**Data appear Normal at 5% Significance Level**

### Assuming Normal Distribution

| **90% Normal UCL** | | **90% UCLs (Adjusted for Skewness)** | |
|---|---|---|---|
| 90% Student's-t UCL | 38613 | 90% Adjusted-CLT UCL (Chen-1995) | 38795 |
| | | 90% Modified-t UCL (Johnson-1978) | 38741 |

### Suggested UCL to Use

**Recommendation Provided only for 95% Confidence Coefficient**

## Normal UCL Statistics for Uncensored Full Data Sets

| | |
|---|---|
| User Selected Options | |
| Date/Time of Computation | ProUCL 5.11/20/2022 4:04:46 PM |
| From File | COMPLIANCE DATA 2H2021.xls |
| Full Precision | OFF |
| Confidence Coefficient | 90% |

**1,4-Dioxane (b-326-wd)**

### General Statistics

| | | | |
|---|---|---|---|
| Total Number of Observations | 10 | Number of Distinct Observations | 9 |
| | | Number of Missing Observations | 0 |
| Minimum | 0.77 | Mean | 7.347 |
| Maximum | 17 | Median | 8.15 |
| SD | 5.088 | SD of logged Data | 1.045 |
| Coefficient of Variation | 0.692 | Skewness | 0.37 |

### Normal GOF Test

| | | |
|---|---|---|
| Shapiro Wilk Test Statistic | 0.94 | **Shapiro Wilk GOF Test** |
| 5% Shapiro Wilk Critical Value | 0.842 | Data appear Normal at 5% Significance Level |
| Lilliefors Test Statistic | 0.151 | **Lilliefors GOF Test** |
| 5% Lilliefors Critical Value | 0.262 | Data appear Normal at 5% Significance Level |

**Data appear Normal at 5% Significance Level**

### Assuming Normal Distribution

| 90% Normal UCL | | 90% UCLs (Adjusted for Skewness) | |
|---|---|---|---|
| 90% Student's-t UCL | 9.572 | 90% Adjusted-CLT UCL (Chen-1995) | 9.543 |
| | | 90% Modified-t UCL (Johnson-1978) | 9.603 |

### Suggested UCL to Use

**Recommendation Provided only for 95% Confidence Coefficient**

## Normal UCL Statistics for Uncensored Full Data Sets

| | |
|---|---|
| User Selected Options | |
| Date/Time of Computation | ProUCL 5.11/24/2022 9:08:24 AM |
| From File | COMPLIANCE DATA 2H2021_d.xls |
| Full Precision | OFF |
| Confidence Coefficient | 90% |

**Tetrachloroethene (bm-11x-100n)**

### General Statistics

| | | | |
|---|---|---|---|
| Total Number of Observations | 10 | Number of Distinct Observations | 10 |
| | | Number of Missing Observations | 0 |
| Minimum | 4.6 | Mean | 6.07 |
| Maximum | 7.2 | Median | 6.15 |
| SD | 0.838 | SD of logged Data | 0.144 |
| Coefficient of Variation | 0.138 | Skewness | -0.448 |

### Normal GOF Test

| | | |
|---|---|---|
| Shapiro Wilk Test Statistic | 0.965 | **Shapiro Wilk GOF Test** |
| 5% Shapiro Wilk Critical Value | 0.842 | Data appear Normal at 5% Significance Level |
| Lilliefors Test Statistic | 0.12 | **Lilliefors GOF Test** |
| 5% Lilliefors Critical Value | 0.262 | Data appear Normal at 5% Significance Level |

**Data appear Normal at 5% Significance Level**

### Assuming Normal Distribution

| **90% Normal UCL** | | **90% UCLs (Adjusted for Skewness)** | |
|---|---|---|---|
| 90% Student's-t UCL | 6.437 | 90% Adjusted-CLT UCL (Chen-1995) | 6.383 |
| | | 90% Modified-t UCL (Johnson-1978) | 6.43 |

### Suggested UCL to Use

**Recommendation Provided only for 95% Confidence Coefficient**

**Note: For highly negatively-skewed data, confidence limits (e.g., Chen, Johnson, Lognormal, and Gamma) may not be reliable. Chen's and Johnson's methods provide adjustments for positvely skewed data sets.**

## Nonparametric UCL Statistics for Uncensored Full Data Sets

| | |
|---|---|
| User Selected Options | |
| Date/Time of Computation | ProUCL 5.11/24/2022 9:19:38 AM |
| From File | COMPLIANCE DATA 2H2021_b.xls |
| Full Precision | OFF |
| Confidence Coefficient | 95% |
| Number of Bootstrap Operations | 2000 |

**Nitrogen, Nitrate (mw62-wdr)**

### General Statistics

| | | | |
|---|---|---|---|
| Total Number of Observations | 10 | Number of Distinct Observations | 3 |
| | | Number of Missing Observations | 0 |
| Minimum | 110000 | Mean | 120000 |
| Maximum | 130000 | Median | 120000 |
| SD | 6667 | Std. Error of Mean | 2108 |
| Coefficient of Variation | 0.0556 | Skewness | 0 |
| Mean of logged Data | 11.69 | SD of logged Data | 0.0557 |

### Nonparametric Distribution Free UCL Statistics

**Data do not follow a Discernible Distribution (0.05)**

### Assuming Normal Distribution

| 95% Normal UCL | | 95% UCLs (Adjusted for Skewness) | |
|---|---|---|---|
| 95% Student's-t UCL | 123865 | 95% Adjusted-CLT UCL (Chen-1995) | 123468 |
| | | 95% Modified-t UCL (Johnson-1978) | 123865 |

### Nonparametric Distribution Free UCLs

| | | | |
|---|---|---|---|
| 95% CLT UCL | 123468 | 95% Jackknife UCL | 123865 |
| 95% Standard Bootstrap UCL | N/A | 95% Bootstrap-t UCL | N/A |
| 95% Hall's Bootstrap UCL | N/A | 95% Percentile Bootstrap UCL | N/A |
| 95% BCA Bootstrap UCL | N/A | | |
| 90% Chebyshev(Mean, Sd) UCL | 126325 | 95% Chebyshev(Mean, Sd) UCL | 129189 |
| 97.5% Chebyshev(Mean, Sd) UCL | 133166 | 99% Chebyshev(Mean, Sd) UCL | 140976 |

### Suggested UCL to Use

| | | | |
|---|---|---|---|
| 95% Student's-t UCL | 123865 | or 95% Modified-t UCL | 123865 |

Note: Suggestions regarding the selection of a 95% UCL are provided to help the user to select the most appropriate 95% UCL.
Recommendations are based upon data size, data distribution, and skewness.
These recommendations are based upon the results of the simulation studies summarized in Singh, Maichle, and Lee (2006).
However, simulations results will not cover all Real World data sets; for additional insight the user may want to consult a statistician.

| | | |
|---|---|---|
| **Normal UCL Statistics for Uncensored Full Data Sets** | | |
| User Selected Options | | |
| Date/Time of Computation | ProUCL 5.11/20/2022 4:04:46 PM | |
| From File | COMPLIANCE DATA 2H2021.xls | |
| Full Precision | OFF | |
| Confidence Coefficient | 90% | |

**1,4-Dioxane (mw77-wd)**

**General Statistics**

| | | | |
|---|---|---|---|
| Total Number of Observations | 10 | Number of Distinct Observations | 10 |
| | | Number of Missing Observations | 0 |
| Minimum | 2.6 | Mean | 8.82 |
| Maximum | 20 | Median | 7.15 |
| SD | 5.882 | SD of logged Data | 0.705 |
| Coefficient of Variation | 0.667 | Skewness | 0.806 |

**Normal GOF Test**

| | | |
|---|---|---|
| Shapiro Wilk Test Statistic | 0.906 | **Shapiro Wilk GOF Test** |
| 5% Shapiro Wilk Critical Value | 0.842 | Data appear Normal at 5% Significance Level |
| Lilliefors Test Statistic | 0.225 | **Lilliefors GOF Test** |
| 5% Lilliefors Critical Value | 0.262 | Data appear Normal at 5% Significance Level |

**Data appear Normal at 5% Significance Level**

**Assuming Normal Distribution**

| **90% Normal UCL** | | **90% UCLs (Adjusted for Skewness)** | |
|---|---|---|---|
| 90% Student's-t UCL | 11.39 | 90% Adjusted-CLT UCL (Chen-1995) | 11.54 |
| | | 90% Modified-t UCL (Johnson-1978) | 11.47 |

**Suggested UCL to Use**

**Recommendation Provided only for 95% Confidence Coefficient**

# APPENDIX C-4

# EFFECTIVENESS ASSESSMENT

# APPENDIX C-4.1

# EFFECTIVENESS ASSESSMENT

## Determination of Hydraulic Gradients

**(PM-1I&X through PM-15I&X)**

| MASTER LOC | Date | Water Elev | MASTER LOC | Date | Water Elev | | Difference |
|---|---|---|---|---|---|---|---|
| PM-1I | 1/16/2020 | 5772.16 | PM-1X | 1/16/2020 | 5772.79 | | -0.63 |
| PM-1I | 4/20/2020 | 5771.42 | PM-1X | 4/20/2020 | 5772.66 | | -1.24 |
| PM-1I | 7/15/2020 | 5771.40 | PM-1X | 7/15/2020 | 5772.50 | | -1.10 |
| PM-1I | 10/8/2020 | 5771.57 | PM-1X | 10/8/2020 | 5772.23 | | -0.66 |
| PM-1I | 1/11/2021 | 5771.36 | PM-1X | 1/11/2021 | 5771.72 | | -0.36 |
| PM-1I | 4/5/2021 | 5770.76 | PM-1X | 4/5/2021 | 5771.07 | | -0.31 |
| PM-1I | 7/14/2021 | 5771.24 | PM-1X | 7/14/2021 | 5774.02 | | -2.78 |
| PM-1I | 10/7/2021 | 5771.72 | PM-1X | 10/7/2021 | 5773.19 | | -1.47 |


| | | | |
|---|---|---|---|
| | | Minimum | -2.78 |
| | | Maximum | -0.31 |
| Mean Interior Water Level | 5771.45 | Avg. Diff | -1.07 |
| Mean Exterior Water Level | 5772.52 | Diff of the Means | -1.07 |
| Sum of the Squares of Deviations | | | |
| Interior | 1.12 | | |
| Exterior | 5.62 | | |
| Standard Deviation (pooled) | 0.69 | | |
| t-statistics degrees of freedom = | 7 | | |
| α = 5% | 1.89 | | |
| α = 20% | 0.90 | | |
| 80% Confidence Interval | 0.31 | 80% LCL | -1.38 |
| 95% Confidence Interval | 0.66 | 95% UCL | -0.41 |

Effectiveness Decision

Data Sufficiency

**Inward Gradient exists**

# PM-1 Well Pair Hydrographs



| MASTER LOC | Date | Water Elev | MASTER LOC | Date | Water Elev | | Difference |
|---|---|---|---|---|---|---|---|
| PM-2I | 1/9/2020 | 5770.45 | PM-2X | 1/9/2020 | 5777.48 | | -7.03 |
| PM-2I | 4/14/2020 | 5770.14 | PM-2X | 4/14/2020 | 5777.84 | | -7.70 |
| PM-2I | 7/13/2020 | 5770.20 | PM-2X | 7/13/2020 | 5777.21 | | -7.01 |
| PM-2I | 10/5/2020 | 5770.11 | PM-2X | 10/5/2020 | 5777.09 | | -6.98 |
| PM-2I | 1/6/2021 | 5770.08 | PM-2X | 1/6/2021 | 5777.06 | | -6.98 |
| PM-2I | 4/6/2021 | 5770.31 | PM-2X | 4/6/2021 | 5777.40 | | -7.09 |
| PM-2I | 7/6/2021 | 5769.95 | PM-2X | 7/6/2021 | 5776.96 | | -7.01 |
| PM-2I | 10/1/2021 | 5769.92 | PM-2X | 10/1/2021 | 5776.91 | | -6.99 |


| | | | |
|---|---|---|---|
| | | Minimum | -7.70 |
| | | Maximum | -6.98 |
| Mean Interior Water Level | 5770.15 | Avg. Diff | -7.10 |
| Mean Exterior Water Level | 5777.24 | Diff of the Means | -7.10 |
| Sum of the Squares of Deviations | | | |
| Interior | 0.22 | | |
| Exterior | 0.69 | | |
| Standard Deviation (pooled) | 0.25 | | |
| t-statistics degrees of freedom = | 7 | | |
| α = 5% | 1.89 | | |
| α = 20% | 0.90 | | |
| 80% Confidence Interval | 0.11 | 80% LCL | -7.21 |
| 95% Confidence Interval | 0.24 | 95% UCL | -6.86 |

Effectiveness Decision

Data Sufficiency

**Inward Gradient exists**

# PM-2 Well Pair Hydrographs



| MASTER LOC | Date | Water Elev | MASTER LOC | Date | Water Elev | | Difference |
|---|---|---|---|---|---|---|---|
| PM-3I | 1/9/2020 | 5779.59 | PM-3X | 1/9/2020 | 5778.81 | | 0.78 |
| PM-3I | 4/14/2020 | 5779.20 | PM-3X | 4/14/2020 | 5778.46 | | 0.74 |
| PM-3I | 7/13/2020 | 5779.12 | PM-3X | 7/13/2020 | 5778.40 | | 0.72 |
| PM-3I | 10/5/2020 | 5778.96 | PM-3X | 10/5/2020 | 5778.24 | | 0.72 |
| PM-3I | 1/6/2021 | 5778.91 | PM-3X | 1/6/2021 | 5778.18 | | 0.73 |
| PM-3I | 4/6/2021 | 5779.22 | PM-3X | 4/6/2021 | 5778.57 | | 0.65 |
| PM-3I | 7/6/2021 | 5778.64 | PM-3X | 7/6/2021 | 5778.07 | | 0.57 |
| PM-3I | 10/1/2021 | 5778.60 | PM-3X | 10/1/2021 | 5778.13 | | 0.47 |


| | | | |
|---|---|---|---|
| | | Minimum | 0.47 |
| | | Maximum | 0.78 |
| Mean Interior Water Level | 5779.03 | Avg. Diff | 0.67 |
| Mean Exterior Water Level | 5778.36 | Diff of the Means | 0.67 |
| Sum of the Squares of Deviations | | | |
| Interior | 0.74 | | |
| Exterior | 0.44 | | |
| Standard Deviation (pooled) | 0.29 | | |
| t-statistics degrees of freedom = | 7 | | |
| α = 5% | 1.89 | | |
| α = 20% | 0.90 | | |
| 80% Confidence Interval | 0.13 | 80% LCL | 0.54 |
| 95% Cpnfidence Interval | 0.28 | 95% UCL | 0.95 |

Effectiveness Decision

**Outward Gradient exists**

Data Sufficiency

# PM-3 Well Pair Hydrographs



| MASTER LOC | Date | Water Elev | MASTER LOC | Date | Water Elev | | Difference |
|---|---|---|---|---|---|---|---|
| PM-4I | 1/9/2020 | 5793.97 | PM-4X | 1/9/2020 | 5794.18 | | -0.21 |
| PM-4I | 4/15/2020 | 5793.79 | PM-4X | 4/15/2020 | 5794.06 | | -0.27 |
| PM-4I | 7/13/2020 | 5793.65 | PM-4X | 7/13/2020 | 5793.92 | | -0.27 |
| PM-4I | 10/5/2020 | 5793.41 | PM-4X | 10/5/2020 | 5793.70 | | -0.29 |
| PM-4I | 1/6/2021 | 5793.32 | PM-4X | 1/6/2021 | 5793.65 | | -0.33 |
| PM-4I | 4/6/2021 | 5793.43 | PM-4X | 4/6/2021 | 5793.77 | | -0.34 |
| PM-4I | 7/6/2021 | 5793.2 | PM-4X | 7/6/2021 | 5793.59 | | -0.39 |
| PM-4I | 10/1/2021 | 5793.14 | PM-4X | 10/1/2021 | 5793.52 | | -0.38 |


| | | | |
|---|---|---|---|
| | | Minimum | -0.39 |
| | | Maximum | -0.21 |
| Mean Interior Water Level | 5793.49 | Avg. Diff | -0.31 |
| Mean Exterior Water Level | 5793.80 | Diff of the Means | -0.31 |
| Sum of the Squares of Deviations | | | |
| Interior | 0.59 | | |
| Exterior | 0.38 | | |
| Standard Deviation (pooled) | 0.26 | | |
| t-statistics degrees of freedom = | 7 | | |
| α = 5% | 1.89 | | |
| α = 20% | 0.90 | | |
| 80% Confidence Interval | 0.1182 | 80% LCL | -0.43 |
| 95% Confidence Interval | 0.2498 | 95% UCL | -0.06 |

Effectiveness Decision

Data Sufficiency

**Inward Gradient exists**

# PM-4 Well Pair Hydrographs



| MASTER LOC | Date | Water Elev | MASTER LOC | Date | Water Elev | | Difference |
|---|---|---|---|---|---|---|---|
| PM-5I | 1/9/2020 | 5798.63 | PM-5X | 1/9/2020 | 5799.85 | | -1.22 |
| PM-5I | 4/15/2020 | 5798.26 | PM-5X | 4/15/2020 | 5799.27 | | -1.01 |
| PM-5I | 7/13/2020 | 5799.19 | PM-5X | 7/13/2020 | 5799.54 | | -0.35 |
| PM-5I | 10/5/2020 | 5798.65 | PM-5X | 10/5/2020 | 5799.71 | | -1.06 |
| PM-5I | 1/6/2021 | 5798.24 | PM-5X | 1/6/2021 | 5799.46 | | -1.22 |
| PM-5I | 4/7/2021 | 5798.07 | PM-5X | 4/7/2021 | 5799.17 | | -1.10 |
| PM-5I | 7/6/2021 | 5799.84 | PM-5X | 7/6/2021 | 5799.81 | | 0.03 |
| PM-5I | 10/1/2021 | 5799.04 | PM-5X | 10/1/2021 | 5799.93 | | -0.89 |


| | | | |
|---|---|---|---|
| | | Minimum | -1.22 |
| | | Maximum | 0.03 |
| Mean Interior Water Level | 5798.74 | Avg. Diff | -0.85 |
| Mean Exterior Water Level | 5799.59 | Diff of the Means | -0.85 |
| Sum of the Squares of Deviations | | | |
| Interior | 2.45 | | |
| Exterior | 0.54 | | |
| Standard Deviation (pooled) | 0.46 | | |
| t-statistics degrees of freedom = | 7 | | |
| α = 5% | 1.89 | | |
| α = 20% | 0.90 | | |
| 80% Confidence Interval | 0.21 | 80% LCL | -1.06 |
| 95% Confidence Interval | 0.44 | 95% UCL | -0.41 |

Effectiveness Decision

Data Sufficiency

**Inward Gradient exists**

# PM-5 Well Pair Hydrographs



| MASTER LOC | Date | Water Elev | MASTER LOC | Date | Water Elev | | Difference |
|---|---|---|---|---|---|---|---|
| PM-6I | 1/9/2020 | 5797.68 | PM-6X | 1/9/2020 | 5793.99 | | 3.69 |
| PM-6I | 4/15/2020 | 5797.63 | PM-6X | 4/15/2020 | 5793.79 | | 3.84 |
| PM-6I | 7/13/2020 | 5797.64 | PM-6X | 7/13/2020 | 5793.81 | | 3.83 |
| PM-6I | 10/5/2020 | 5797.67 | PM-6X | 10/5/2020 | 5793.70 | | 3.97 |
| PM-6I | 1/6/2021 | 5797.62 | PM-6X | 1/6/2021 | 5793.53 | | 4.09 |
| PM-6I | 4/7/2021 | 5797.73 | PM-6X | 4/7/2021 | 5793.65 | | 4.08 |
| PM-6I | 7/8/2021 | 5797.80 | PM-6X | 7/8/2021 | 5793.81 | | 3.99 |
| PM-6I | 10/1/2021 | 5797.76 | PM-6X | 10/1/2021 | 5793.76 | | 4 |


| | | | |
|---|---|---|---|
| | | Minimum | 3.69 |
| | | Maximum | 4.09 |
| Mean Interior Water Level | 5797.69 | Avg. Diff | 3.94 |
| Mean Exterior Water Level | 5793.76 | Diff of the Means | 3.94 |
| Sum of the Squares of Deviations | | | |
| Interior | 0.03 | | |
| Exterior | 0.13 | | |
| Standard Deviation (pooled) | 0.11 | | |
| t-statistics degrees of freedom = | 7 | | |
| α = 5% | 1.89 | | |
| α = 20% | 0.90 | | |
| 80% Confidence Interval | 0.05 | 80% LCL | 3.89 |
| 95% Cpnfidence Interval | 0.10 | 95% UCL | 4.04 |

Effectiveness Decision

**Outward Gradient exists**

Data Sufficiency

# PM-6 Well Pair Hydrographs



| MASTER LOC | Date | Water Elev | MASTER LOC | Date | Water Elev | | Difference |
|---|---|---|---|---|---|---|---|
| PM-7I | 1/9/2020 | 5811.43 | PM-7X | 1/9/2020 | 5818.64 | | -7.21 |
| PM-7I | 4/15/2020 | 5811.05 | PM-7X | 4/15/2020 | 5817.87 | | -6.82 |
| PM-7I | 7/13/2020 | 5811.07 | PM-7X | 7/13/2020 | 5818.49 | | -7.42 |
| PM-7I | 10/5/2020 | 5811.04 | PM-7X | 10/5/2020 | 5818.22 | | -7.18 |
| PM-7I | 1/6/2021 | 5810.84 | PM-7X | 1/6/2021 | 5817.72 | | -6.88 |
| PM-7I | 4/7/2021 | 5810.75 | PM-7X | 4/7/2021 | 5817.29 | | -6.54 |
| PM-7I | 7/8/2021 | 5810.82 | PM-7X | 7/8/2021 | 5818.26 | | -7.44 |
| PM-7I | 10/1/2021 | 5810.79 | PM-7X | 10/1/2021 | 5818.13 | | -7.34 |


| | | | |
|---|---|---|---|
| | | Minimum | -7.44 |
| | | Maximum | -6.54 |
| Mean Interior Water Level | 5810.97 | Avg. Diff | -7.10 |
| Mean Exterior Water Level | 5818.08 | Diff of the Means | -7.10 |
| Sum of the Squares of Deviations | | | |
| Interior | 0.35 | | |
| Exterior | 1.33 | | |
| Standard Deviation (pooled) | 0.35 | | |
| t-statistics degrees of freedom = | 7 | | |
| α = 5% | 1.89 | | |
| α = 20% | 0.90 | | |
| 80% Confidence Interval | 0.16 | 80% LCL | -7.26 |
| 95% Cpnfidence Interval | 0.33 | 95% UCL | -6.77 |

Effectiveness Decision

Data Sufficiency

**Inward Gradient exists**

# PM-7 well Pair Hydrographs



| MASTER LOC | Date | Water Elev | MASTER LOC | Date | Water Elev | | Difference |
|---|---|---|---|---|---|---|---|
| PM-8I | 1/9/2020 | 5817.22 | PM-8X | 1/9/2020 | 5825.73 | | -8.51 |
| PM-8I | 4/15/2020 | 5816.91 | PM-8X | 4/15/2020 | 5826.35 | | -9.44 |
| PM-8I | 7/13/2020 | 5817.07 | PM-8X | 7/13/2020 | 5826.39 | | -9.32 |
| PM-8I | 10/5/2020 | 5816.29 | PM-8X | 10/5/2020 | 5825.01 | | -8.72 |
| PM-8I | 1/6/2021 | 5815.59 | PM-8X | 1/6/2021 | 5824.34 | | -8.75 |
| PM-8I | 4/7/2021 | 5815.75 | PM-8X | 4/7/2021 | 5825.92 | | -10.17 |
| PM-8I | 7/8/2021 | 5816.84 | PM-8X | 7/8/2021 | 5826.77 | | -9.93 |
| PM-8I | 10/1/2021 | 5816.29 | PM-8X | 10/1/2021 | 5825.60 | | -9.31 |


| | | | |
|---|---|---|---|
| | | Minimum | -10.17 |
| | | Maximum | -8.51 |
| Mean Interior Water Level | 5816.50 | Avg. Diff | -9.27 |
| Mean Exterior Water Level | 5825.76 | Diff of the Means | -9.27 |
| Sum of the Squares of Deviations | | | |
| Interior | 2.61 | | |
| Exterior | 4.40 | | |
| Standard Deviation (pooled) | 0.71 | | |
| t-statistics degrees of freedom = | 7 | | |
| α = 5% | 1.89 | | |
| α = 20% | 0.90 | | |
| 80% Confidence Interval | 0.32 | 80% LCL | -9.59 |
| 95% Cpnfidence Interval | 0.67 | 95% UCL | -8.60 |

Effectiveness Decision

Data Sufficiency

**Inward Gradient exists**

# PM-8 Well Pair Hydrographs



| MASTER LOC | Date | Water Elev | MASTER LOC | Date | Water Elev | | Difference |
|---|---|---|---|---|---|---|---|
| PM-9I | 1/9/2020 | 5816.57 | PM-9X | 1/9/2020 | 5824.91 | | -8.34 |
| PM-9I | 4/15/2020 | 5816.45 | PM-9X | 4/15/2020 | 5826.55 | | -10.10 |
| PM-9I | 7/13/2020 | 5816.45 | PM-9X | 7/13/2020 | 5825.56 | | -9.11 |
| PM-9I | 10/5/2020 | 5815.96 | PM-9X | 10/5/2020 | 5824.30 | | -8.34 |
| PM-9I | 1/6/2021 | 5815.58 | PM-9X | 1/6/2021 | 5823.35 | | -7.77 |
| PM-9I | 4/7/2021 | 5815.89 | PM-9X | 4/7/2021 | 5826.79 | | -10.90 |
| PM-9I | 7/8/2021 | 5816.62 | PM-9X | 7/8/2021 | 5826.89 | | -10.27 |
| PM-9I | 10/1/2021 | 5816.02 | PM-9X | 10/1/2021 | 5824.98 | | -8.96 |


| | | | |
|---|---|---|---|
| | | Minimum | -10.90 |
| | | Maximum | -7.77 |
| Mean Interior Water Level | 5816.19 | Avg. Diff | -9.22 |
| Mean Exterior Water Level | 5825.42 | Diff of the Means | -9.22 |
| Sum of the Squares of Deviations | | | |
| Interior | 1.01 | | |
| Exterior | 11.33 | | |
| Standard Deviation (pooled) | 0.94 | | |
| t-statistics degrees of freedom = | 7 | | |
| α = 5% | 1.89 | | |
| α = 20% | 0.90 | | |
| 80% Confidence Interval | 0.42 | 80% LCL | -9.64 |
| 95% Confidence Interval | 0.89 | 95% UCL | -8.33 |

Effectiveness Decision

Data Sufficiency

**Inward Gradient exists**

# PM-9 Well Pair Hydrographs



| MASTER LOC | Date | Water Elev | MASTER LOC | Date | Water Elev | | Difference |
|---|---|---|---|---|---|---|---|
| PM-10I | 1/9/2020 | 5814.89 | PM-10X | 1/9/2020 | 5819.52 | | -4.63 |
| PM-10I | 4/15/2020 | 5814.81 | PM-10X | 4/15/2020 | 5820.47 | | -5.66 |
| PM-10I | 7/13/2020 | 5814.87 | PM-10X | 7/13/2020 | 5820.08 | | -5.21 |
| PM-10I | 10/5/2020 | 5814.27 | PM-10X | 10/5/2020 | 5818.66 | | -4.39 |
| PM-10I | 1/6/2021 | 5813.83 | PM-10X | 1/6/2021 | 5817.19 | | -3.36 |
| PM-10I | 4/7/2021 | 5813.87 | PM-10X | 4/7/2021 | 5818.60 | | -4.73 |
| PM-10I | 7/8/2021 | 5815.01 | PM-10X | 7/8/2021 | 5820.68 | | -5.67 |
| PM-10I | 10/1/2021 | 5814.28 | PM-10X | 10/1/2021 | 5818.97 | | -4.69 |


| | | | |
|---|---|---|---|
| | | Minimum | -5.67 |
| | | Maximum | -3.36 |
| Mean Interior Water Level | 5814.48 | Avg. Diff | -4.79 |
| Mean Exterior Water Level | 5819.27 | Diff of the Means | -4.79 |
| Sum of the Squares of Deviations | | | |
| Interior | 1.59 | | |
| Exterior | 9.38 | | |
| Standard Deviation (pooled) | 0.89 | | |
| t-statistics degrees of freedom = | 7 | | |
| α = 5% | 1.89 | | |
| α = 20% | 0.90 | | |
| 80% Confidence Interval | 0.40 | 80% LCL | -5.19 |
| 95% Cpnfidence Interval | 0.84 | 95% UCL | -3.95 |

Effectiveness Decision

Data Sufficiency

**Inward Gradient exists**

# PM-10 Well Pair Hydrographs



| MASTER LOC | Date | Water Elev | MASTER LOC | Date | Water Elev | | Difference |
|---|---|---|---|---|---|---|---|
| PM-11I | 1/13/2020 | 5773.71 | PM-11X | 1/13/2020 | 5795.74 | | -22.03 |
| PM-11I | 4/16/2020 | 5773.78 | PM-11X | 4/16/2020 | 5795.61 | | -21.83 |
| PM-11I | 7/8/2020 | 5773.47 | PM-11X | 7/8/2020 | 5795.36 | | -21.89 |
| PM-11I | 10/12/2020 | 5773.37 | PM-11X | 10/12/2020 | 5794.84 | | -21.47 |
| PM-11I | 1/6/2021 | 5773.40 | PM-11X | 1/7/2021 | 5794.24 | | -20.84 |
| PM-11I | 4/9/2021 | 5773.73 | PM-11X | 4/9/2021 | 5793.74 | | -20.01 |
| PM-11I | 7/9/2021 | 5773.53 | PM-11X | 7/9/2021 | 5795.56 | | -22.03 |
| PM-11I | 10/5/2021 | 5773.39 | PM-11X | 10/5/2021 | 5794.85 | | -21.46 |

| | | | |
|---|---|---|---|
| | | Minimum | -22.03 |
| | | Maximum | -20.01 |
| Mean Interior Water Level | 5773.55 | Avg. Diff | -21.45 |
| Mean Exterior Water Level | 5794.99 | Diff of the Means | -21.44 |


| | | |
|---|---|---|
| Sum of the Squares of Deviations | | |
| Interior | 0.20 | |
| Exterior | 3.58 | |
| Standard Deviation (pooled) | 0.52 | |
| t-statistics degrees of freedom = | 7 | |
| α = 5% | 1.89 | |
| α = 20% | 0.90 | |
| 80% Confidence Interval | 0.23 | 80% LCL -21.68 |
| 95% Confidence Interval | 0.49 | 95% UCL -20.95 |

Effectiveness Decision

Data Sufficiency

**Inward Gradient exists**

# PM-11 Well Pair Hydrographs



| MASTER LOC | Date | Water Elev | MASTER LOC | Date | Water Elev | | Difference |
|---|---|---|---|---|---|---|---|
| PM-12I | 1/13/2020 | 5762.93 | PM-12X | 1/13/2020 | 5769.18 | | -6.25 |
| PM-12I | 4/16/2020 | 5763.09 | PM-12X | 4/16/2020 | 5768.54 | | -5.45 |
| PM-12I | 7/8/2020 | 5763.08 | PM-12X | 7/8/2020 | 5767.99 | | -4.91 |
| PM-12I | 10/12/2020 | 5762.96 | PM-12X | 10/12/2020 | 5767.89 | | -4.93 |
| PM-12I | 1/7/2021 | 5762.91 | PM-12X | 1/7/2021 | 5768.02 | | -5.11 |
| PM-12I | 4/9/2021 | 5762.93 | PM-12X | 4/9/2021 | 5767.73 | | -4.80 |
| PM-12I | 7/9/2021 | 5762.86 | PM-12X | 7/9/2021 | 5767.15 | | -4.29 |
| PM-12I | 10/5/2021 | 5762.69 | PM-12X | 10/5/2021 | 5767.00 | | -4.31 |


| | | | |
|---|---|---|---|
| | | Minimum | -6.25 |
| | | Maximum | -4.29 |
| Mean Interior Water Level | 5762.93 | Avg. Diff | -5.01 |
| Mean Exterior Water Level | 5767.94 | Diff of the Means | -5.01 |
| Sum of the Squares of Deviations | | | |
| Interior | 0.11 | | |
| Exterior | 3.46 | | |
| Standard Deviation (pooled) | 0.51 | | |
| t-statistics degrees of freedom = | 7 | | |
| α = 5% | 1.89 | | |
| α = 20% | 0.90 | | |
| 80% Confidence Interval | 0.23 | 80% LCL | -5.23 |
| 95% Confidence Interval | 0.48 | 95% UCL | -4.53 |

Effectiveness Decision

Data Sufficiency

**Inward Gradient exists**

# PM-12 Well Pair Hydrographs




| MASTER LOC | Date | Water Elev | MASTER LOC | Date | Water Elev | | Difference |
|---|---|---|---|---|---|---|---|
| PM-13I | 1/13/2020 | dry | PM-13X | 1/13/2020 | dry | | #VALUE! |
| PM-13I | 4/16/2020 | dry | PM-13X | 4/16/2020 | 5752.30 | | #VALUE! |
| PM-13I | 7/8/2020 | dry | PM-13X | 7/8/2020 | dry | | #VALUE! |
| PM-13I | 10/12/2020 | dry | PM-13X | 10/12/2020 | dry | | #VALUE! |
| PM-13I | 1/7/2021 | dry | PM-13X | 1/7/2021 | dry | | #VALUE! |
| PM-13I | 4/9/2021 | dry | PM-13X | 4/9/2021 | 5752.16 | | #VALUE! |
| PM-13I | 7/9/2021 | dry | PM-13X | 7/9/2021 | dry | | #VALUE! |
| PM-13I | 10/5/2021 | dry | PM-13X | 10/5/2021 | 5752.11 | | #VALUE! |

| | | | |
|---|---|---|---|
| | | Minimum | #VALUE! |
| | | Maximum | #VALUE! |
| Mean Interior Water Level | #DIV/0! | Avg. Diff | #VALUE! |
| Mean Exterior Water Level | 5752.19 | Diff of the Means | #DIV/0! |
| Sum of the Squares of Deviations | | | |
| Interior | #VALUE! | | |
| Exterior | #VALUE! | | |
| Standard Deviation (pooled) | #VALUE! | | |
| t-statistics degrees of freedom = | 7 | | |
| α = 5% | 1.89 | | |
| α = 20% | 0.90 | | |
| 80% Confidence Interval | #VALUE! | 80% LCL | #DIV/0! |
| 95% Confidence Interval | #VALUE! | 95% UCL | #DIV/0! |

| Effectiveness Decision | Data Sufficiency |
|---|---|
| #VALUE! | #DIV/0! |
| #VALUE! | #DIV/0! |
| | Unable to calculate gradient |

# PM-13 Well Pair Hydrographs



| MASTER LOC | Date | Water Elev | MASTER LOC | Date | Water Elev | | Difference |
|---|---|---|---|---|---|---|---|
| PM-14I | 1/13/2020 | 5749.47 | PM-14X | 1/13/2020 | 5748.43 | | 1.04 |
| PM-14I | 4/16/2020 | 5749.21 | PM-14X | 4/16/2020 | 5748.19 | | 1.02 |
| PM-14I | 7/8/2020 | 5748.94 | PM-14X | 7/8/2020 | 5747.78 | | 1.16 |
| PM-14I | 10/12/2020 | 5748.76 | PM-14X | 10/12/2020 | 5747.69 | | 1.07 |
| PM-14I | 1/7/2021 | 5748.91 | PM-14X | 1/7/2021 | 5747.88 | | 1.03 |
| PM-14I | 4/9/2021 | 5748.96 | PM-14X | 4/9/2021 | 5747.91 | | 1.05 |
| PM-14I | 7/9/2021 | 5748.97 | PM-14X | 7/9/2021 | 5747.90 | | 1.07 |
| PM-14I | 10/5/2021 | 5749.09 | PM-14X | 10/5/2021 | 5748.11 | | 0.98 |


| | | | |
|---|---|---|---|
| | | Minimum | 0.98 |
| | | Maximum | 1.16 |
| Mean Interior Water Level | 5749.04 | Avg. Diff | 1.05 |
| Mean Exterior Water Level | 5747.99 | Diff of the Means | 1.05 |
| Sum of the Squares of Deviations | | | |
| Interior | 0.33 | | |
| Exterior | 0.41 | | |
| Standard Deviation (pooled) | 0.23 | | |
| t-statistics degrees of freedom = | 7 | | |
| α = 5% | 1.89 | | |
| α = 20% | 0.90 | | |
| 80% Confidence Interval | 0.10 | 80% LCL | 0.95 |
| 95% Cpnfidence Interval | 0.22 | 95% UCL | 1.27 |

Effectiveness Decision

**Outward Gradient exists**

Data Sufficiency

# PM-14 Well Pair Hydrographs



| MASTER LOC | Date | Water Elev | MASTER LOC | Date | Water Elev | | Difference |
|---|---|---|---|---|---|---|---|
| PM-15I | 1/13/2020 | 5723.57 | PM-15X | 1/13/2020 | 5736.52 | | -12.95 |
| PM-15I | 4/17/2020 | 5723.69 | PM-15X | 4/17/2020 | 5735.80 | | -12.11 |
| PM-15I | 7/8/2020 | 5723.59 | PM-15X | 7/9/2020 | 5735.85 | | -12.26 |
| PM-15I | 10/12/2020 | 5723.62 | PM-15X | 10/12/2020 | 5735.83 | | -12.21 |
| PM-15I | 1/6/2021 | 5723.63 | PM-15X | 1/7/2021 | 5735.76 | | -12.13 |
| PM-15I | 4/9/2021 | 5723.63 | PM-15X | 4/9/2021 | 5735.50 | | -11.87 |
| PM-15I | 7/9/2021 | 5723.61 | PM-15X | 7/9/2021 | 5736.91 | | -13.3 |
| PM-15I | 10/5/2021 | 5723.20 | PM-15X | 10/5/2021 | 5737.04 | | -13.84 |


| | | | |
|---|---|---|---|
| | | Minimum | -13.84 |
| | | Maximum | -11.87 |
| Mean Interior Water Level | 5723.57 | Avg. Diff | -12.58 |
| Mean Exterior Water Level | 5736.15 | Diff of the Means | -12.58 |
| Sum of the Squares of Deviations | | | |
| Interior | 0.16 | | |
| Exterior | 2.40 | | |
| Standard Deviation (pooled) | 0.43 | | |
| t-statistics degrees of freedom = | 7 | | |
| α = 5% | 1.89 | | |
| α = 20% | 0.90 | | |
| 80% Confidence Interval | 0.19 | 80% LCL | -12.78 |
| 95% Confidence Interval | 0.41 | 95% UCL | -12.18 |

Effectiveness Decision

Data Sufficiency

**Inward Gradient exists**

# PM-15 Well Pair Hydrographs



# APPENDIX C-4.2

# EFFECTIVENESS ASSESSMENT

## Data Summary Table for Wells with Outward Gradients

**(PM-3X, PM-6X, PM-13X, and PM-14X)**

# APPENDIX C-4.2

## Table 1

### Analytical Data Summary for PM-13X

| Dates | 1,1,1-trichloroethane (ug/L) | 1,1-dichloroethane (ug/L) | 1,4-dioxane (ug/L) | Tetrachloroethene (ug/L) | Trichloroethene (ug/L) |
|---|---|---|---|---|---|
| 9/22/2005 | 2.20 | 44 | | .82 | 1.30 |
| 12/20/2005 | 2.20 | 40 | | .94 | 1.40 |
| 3/23/2006 | 1.90 | 41 | | .90 | 1.30 |
| 6/2/2006 | .86 | 21 | | .54 | .77 |
| 7/28/2006 | 1.50 | 34 | | .79 | 1.20 |
| 11/28/2006 | 1.70 | 41 | | 1.10 | 1.40 |
| 2/6/2007 | 2.00 | 43 | | 1.70 | 1.90 |
| 6/8/2007 | .81 | 35 | | 1.30 | 1.60 |
| 11/5/2007 | 2.00 | 43 | | 2.00 | 2.30 |
| 5/16/2008 | 1.90 | 46 | | 1.20 | 1.70 |
| 12/8/2008 | .59 | 18 | | .48 | 1.10 |
| 5/12/2009 | 1.10 | 33 | | 1.00 | 1.40 |
| 11/25/2009 | 1.00 | 33 | | .83 | 1.50 |
| 6/11/2010 | 1.00 | 39 | | 1.20 | 1.70 |
| 11/19/2010 | 1.40 | 41 | | 1.60 | 1.70 |
| 6/7/2011 | 1.10 | 39 | | .93 | 1.70 |
| 12/9/2011 | 1.10 | 32 | | .87 | 1.40 |
| 6/21/2012 | .74 | 32 | | .70 | 1.00 |
| 12/10/2012 | .80 | 33 | | .48 | .99 |
| 6/18/2013 | .85 | 35 | | 1.00 | 1.40 |
| 12/19/2013 | .86 | 37 | | .82 | 1.40 |
| 6/18/2014 | .72 | 32 | | 1.20 | 1.50 |
| 12/22/2014 | .58 | 28 | | .62 | 1.00 |
| 6/2/2015 | .76 | 31 | | 1.60 | 1.70 |
| 12/21/2015 | .83 | 33 | | 1.70 | 1.90 |
| 6/21/2016 | .69 | 34 | | 1.00 | 1.40 |
| 12/20/2016 | .60 | 30 | | 1.30 | 1.60 |
| 6/29/2017 | .53 | 27 | | 1.60 | 1.70 |
| 10/17/2017 | .47 | 29 | <.15 | .59 | 1.00 |
| 6/20/2018 | .49 | 30 | <.15 | 1.00 | 1.40 |
| 10/30/2018 | .50 | 23 | <.15 | 1.60 | 1.50 |
| 6/11/2019 | .43 | 26 | <.15 | 1.60 | 1.00 |
| 12/18/2019 | .17 | 27 | <.09 | 1.30 | 1.20 |
| 6/8/2020 | .92 | 29 | .35 | 1.20 | 1.50 |
| 12/21/2020 | <.16 | 14 | <.09 | .87 | .92 |
| 6/9/2021 | <.16 | 24 | <.09 | .27 | .99 |
| 11/3/2021 | <.16 | 22 | <.09 | .30 | .66 |

# APPENDIX C-4.2

## Table 2

### Analytical Data Summary for PM-14X

| Dates | 1,1,1-trichloroethane (ug/L) | 1,1-dichloroethane (ug/L) | 1,4-dioxane (ug/L) | Tetrachloroethene (ug/L) | Trichloroethene (ug/L) |
|---|---|---|---|---|---|
| 6/15/2004 | .31 | 4.6 | | <.26 | <.16 |
| 6/8/2005 | <.16 | 3.9 | <.19 | <.20 | <.16 |
| 8/26/2005 | .23 | 3.9 | <.19 | <.20 | .17 |
| 11/21/2005 | .22 | 3.9 | <.19 | <.20 | <.16 |
| 2/21/2006 | .17 | 3.2 | <.50 | <.20 | .21 |
| 6/12/2006 | <.16 | 4.2 | | <.20 | <.16 |
| 7/26/2006 | .17 | 3.7 | <.50 | <.20 | .17 |
| 11/28/2006 | <.16 | 4.3 | | <.20 | .20 |
| 2/5/2007 | .20 | 3.7 | <.50 | <.20 | <.16 |
| 8/2/2007 | <.16 | 4.1 | <.50 | <.20 | <.16 |
| 10/17/2007 | <.16 | 4.5 | <.50 | <.20 | .22 |
| 5/5/2008 | .19 | 3.7 | <.50 | <.20 | <.16 |
| 10/29/2008 | <.16 | 3.1 | <.50 | <.20 | <.16 |
| 4/16/2009 | <.16 | 3.1 | <.50 | <.20 | <.16 |
| 11/11/2009 | <.16 | 3.9 | <.50 | <.20 | <.16 |
| 4/27/2010 | <.16 | 3.5 | <.50 | <.20 | <.16 |
| 11/2/2010 | <.16 | 3.2 | <.50 | <.20 | <.16 |
| 5/4/2011 | <.16 | 3.2 | <.50 | <.20 | .19 |
| 11/29/2011 | <.16 | 3.8 | <.50 | <.20 | .20 |
| 5/21/2012 | <.16 | 3.7 | <.50 | <.20 | <.16 |
| 10/25/2012 | <.16 | 3.8 | <.50 | <.20 | <.16 |
| 4/23/2013 | <.16 | 4.1 | <.50 | <.20 | <.16 |
| 10/15/2013 | <.16 | 3.6 | <.50 | <.20 | <.16 |
| 4/23/2014 | | | <.50 | | |
| 4/24/2014 | <.16 | 3.3 | | <.20 | <.16 |
| 10/27/2014 | <.16 | 4.0 | <.50 | <.20 | <.16 |
| 4/20/2015 | <.16 | 3.0 | <.50 | <.20 | <.16 |
| 11/2/2015 | <.16 | 2.9 | <.15 | <.20 | <.16 |
| 4/20/2016 | <.16 | 3.0 | <.15 | <.20 | .17 |
| 11/1/2016 | <.16 | 2.6 | <.15 | <.20 | <.16 |
| 4/20/2017 | <.16 | 3.0 | <.15 | <.20 | <.16 |
| 10/13/2017 | <.16 | 2.8 | <.15 | <.20 | <.16 |
| 4/18/2018 | <.16 | 2.6 | <.15 | <.20 | <.16 |
| 10/19/2018 | <.16 | 2.5 | <.15 | <.20 | <.16 |
| 4/26/2019 | <.16 | 2.5 | <.15 | <.20 | <.16 |
| 11/7/2019 | <.16 | 4.0 | <.40 | <.20 | .23 |
| 5/13/2020 | <.16 | 3.0 | <.09 | <.20 | <.16 |
| 12/15/2020 | <.16 | 3.3 | .10 | <.20 | <.16 |
| 5/20/2021 | <.16 | 3.5 | <.09 | <.20 | <.16 |
| 10/26/2021 | <.16 | 4.0 | <.09 | <.20 | <.16 |

# APPENDIX C-4.2

## Table 3

### Analytical Data Summary for PM-3X

| Dates | 1,1,1-trichloroethane (ug/L) | 1,1-dichloroethane (ug/L) | 1,4-dioxane (ug/L) | Tetrachloroethene (ug/L) | Trichloroethene (ug/L) |
|---|---|---|---|---|---|
| 6/13/2006 | <.16 | .33 | | 1.00 | .44 |
| 8/1/2006 | <.16 | .26 | | 1.30 | .39 |
| 12/12/2006 | <.16 | .28 | | 1.20 | .42 |
| 2/8/2007 | <.16 | .29 | | 1.00 | .33 |
| 6/8/2007 | <.16 | <.16 | | .46 | .24 |
| 8/10/2007 | <.16 | .34 | | .54 | .28 |
| 10/23/2007 | <.16 | .30 | | .48 | .33 |
| 2/22/2008 | <.16 | .26 | | .86 | .32 |
| 5/9/2008 | <.16 | .28 | | .99 | .34 |
| 12/11/2008 | <.16 | .35 | | .60 | .32 |
| 5/12/2009 | <.16 | .31 | | .21 | .16 |
| 11/25/2009 | <.16 | .34 | | .46 | .22 |
| 5/27/2010 | <.16 | .38 | | 1.00 | .48 |
| 11/19/2010 | <.16 | .48 | | .65 | .24 |
| 6/2/2011 | <.16 | .51 | | <.20 | <.16 |
| 12/8/2011 | <.16 | .40 | | .57 | .22 |
| 6/12/2012 | <.16 | .42 | | .82 | .33 |
| 12/5/2012 | <.16 | .47 | | .39 | .26 |
| 5/28/2013 | <.16 | .49 | | .65 | .63 |
| 12/19/2013 | <.16 | .47 | | .42 | .20 |
| 6/18/2014 | <.16 | .41 | | .38 | .16 |
| 12/29/2014 | <.16 | .32 | | .39 | .17 |
| 6/3/2015 | <.16 | .50 | | .32 | .28 |
| 12/21/2015 | <.16 | .45 | | .55 | .26 |
| 6/27/2016 | <.16 | .50 | | .63 | .27 |
| 12/29/2016 | <.16 | <.22 | | <.20 | <.16 |
| 6/29/2017 | <.16 | .33 | | .42 | .24 |
| 10/17/2017 | <.16 | .40 | <.15 | .27 | .17 |
| 6/22/2018 | .16 | .57 | <.15 | .77 | .37 |
| 11/1/2018 | <.16 | .44 | <.15 | .77 | .30 |
| 6/11/2019 | <.16 | .37 | <.15 | .33 | .17 |
| 12/18/2019 | <.16 | <.22 | <.09 | .24 | <.16 |
| 6/8/2020 | <.16 | .60 | <.09 | .73 | <.16 |
| 12/18/2020 | <.16 | .59 | <.09 | 1.10 | .38 |
| 6/8/2021 | <.16 | .73 | <.09 | .60 | .64 |
| 11/3/2021 | <.16 | .37 | <.09 | <.20 | <.16 |

# APPENDIX C-4.2

## Table 4

### Analytical Data Summary for PM-6X

| Dates | 1,1,1-trichloroethane (ug/L) | 1,1-dichloroethane (ug/L) | 1,4-dioxane (ug/L) | Tetrachloroethene (ug/L) | Trichloroethene (ug/L) |
|---|---|---|---|---|---|
| 6/15/2004 | <.16 | <.22 | | <.26 | <.16 |
| 9/22/2005 | <.16 | <.16 | | <.20 | <.16 |
| 12/20/2005 | <.16 | <.16 | | <.20 | <.16 |
| 3/23/2006 | <.16 | <.16 | | <.20 | <.16 |
| 6/2/2006 | <.16 | <.16 | | <.20 | <.16 |
| 7/28/2006 | <.16 | <.16 | | <.20 | <.16 |
| 11/28/2006 | <.16 | <.16 | | <.20 | <.16 |
| 2/6/2007 | <.16 | <.16 | | <.20 | <.16 |
| 8/10/2007 | <.16 | <.16 | | <.20 | <.16 |
| 10/23/2007 | <.16 | <.16 | | <.20 | <.16 |
| 5/9/2008 | <.16 | <.16 | | <.20 | <.16 |
| 12/8/2008 | <.16 | <.16 | | <.20 | <.16 |
| 5/5/2009 | <.16 | <.16 | | <.20 | <.16 |
| 11/25/2009 | <.16 | <.16 | | <.20 | <.16 |
| 5/27/2010 | <.16 | <.22 | | <.20 | <.16 |
| 11/19/2010 | <.16 | <.22 | | <.20 | <.16 |
| 6/2/2011 | <.16 | <.22 | | <.20 | <.16 |
| 12/7/2011 | <.16 | <.22 | | <.20 | <.16 |
| 6/21/2012 | <.16 | <.22 | | <.20 | <.16 |
| 12/5/2012 | <.16 | <.22 | | <.20 | <.16 |
| 5/28/2013 | <.16 | <.22 | | <.20 | <.16 |
| 12/16/2013 | <.16 | <.22 | | <.20 | <.16 |
| 6/17/2014 | <.16 | <.22 | | <.20 | <.16 |
| 12/22/2014 | <.16 | <.22 | | <.20 | <.16 |
| 6/2/2015 | <.16 | <.22 | | <.20 | <.16 |
| 12/23/2015 | <.16 | <.22 | | <.20 | <.16 |
| 6/21/2016 | <.16 | <.22 | | <.20 | <.16 |
| 12/20/2016 | <.16 | <.22 | | <.20 | <.16 |
| 6/29/2017 | <.16 | <.22 | | <.20 | <.16 |
| 10/17/2017 | <.16 | <.22 | <.15 | <.20 | <.16 |
| 6/21/2018 | <.16 | <.22 | <.15 | <.20 | <.16 |
| 10/16/2018 | <.16 | <.22 | <.15 | <.20 | <.16 |
| 6/12/2019 | <.16 | <.22 | <.15 | <.20 | <.16 |
| 12/18/2019 | <.16 | <.22 | <.09 | <.20 | <.16 |
| 6/8/2020 | <.16 | <.22 | <.09 | <.20 | <.16 |
| 12/18/2020 | <.16 | <.22 | <.09 | <.20 | <.16 |
| 6/8/2021 | <.16 | <.22 | <.09 | <.20 | <.16 |
| 11/3/2021 | <.16 | <.22 | <.09 | <.20 | <.16 |

< indicates resultswas not detected above the associated value.

# APPENDIX C-4.3


# EFFECTIVENESS ASSESSMENT

## Trend Analysis for Wells with Outward Gradients


**(PM-3X, PM-6X, PM-13X, and PM-14X)**

## (Baseline Data Set)


# APPENDIX C-4.3
# EFFECTIVENESS TREND ANALYSIS
## (1,1-DICHLOROETHANE)





**Graph 1**




**Graph 2**




**Graph 3**





**Graph 4**


Determined by DUMPSTAT and

Sen's Test for Trend


# APPENDIX C-4.3
# EFFECTIVENESS TREND ANALYSIS
## (1,4-DIOXANE)





**Graph 1**




**Graph 2**




**Graph 3**





**Graph 4**


Determined by DUMPSTAT and Sen's

Test for Trend


# APPENDIX C-4.3
# EFFECTIVENESS TREND ANALYSIS
## (1,1,1-TRICHLOROETHANE)





**Graph 1**




**Graph 2**





**Graph 3**





**Graph 4**

Determined by DUMPSTAT and Sen's
Test for Trend


# APPENDIX C-4.3
# EFFECTIVENESS TREND ANALYSIS
## (TETRACHLOROETHENE)





**Graph 1**




**Graph 2**




**Graph 3**





**Graph 4**


Determined by DUMPSTAT and Sen's

Test for Trend


# APPENDIX C-4.3
# EFFECTIVENESS TREND ANALYSIS
## (TRICHLOROETHENE)





**Graph 1**




**Graph 2**




**Graph 3**




**Graph 4**

Determined by DUMPSTAT and Sen's

Test for Trend

# APPENDIX C-4.4

# EFFECTIVENESS ASSESSMENT

## Shewhart-CUSUM Test for Wells with Outward Gradients

**(PM-3X, PM-6X, PM-13X, and PM-14X)**

# APPENDIX C-4.4
# SHEWHART-CUSUM CONTROL CHARTS
# 1,1-DICHLOROETHANE

## Summary Statistics and Intermediate Computations for Combined Shewhart-Cusum Control Charts


| Constituent | Units | Well | N(back) | N(mon) | N(tot) | Mean | SD | R(i-1) | R(i) | S(i-1) | S(i) |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 1,1-dichloroethane | ug/L | PM-13X | 19 | 18 | 37 | 36.2105 | 7.3905 | 24.0000 | 22.0000 | 36.2105 | 36.2105 |
| 1,1-dichloroethane | ug/L | PM-14X | 24 | 15 | 39 | 3.7500 | 0.4263 | 3.5000 | 4.0000 | 3.7500 | 3.7500 |
| 1,1-dichloroethane | ug/L | PM-3X | 12 | 24 | 36 | 0.3617 | 0.2034 | 0.7300 | 0.3700 | 0.7390 | 0.5947 |
| 1,1-dichloroethane | ug/L | PM-6X | 36 | 2 | 38 | | | 0.2200 | 0.2200 | | |

N(back) and N(mon) = Non-outlier measurements in the background and monitoring periods.
N(tot) = All independent measurements for that constituent and well.
For transformed data, mean and SD in transformed units and control limit in original units.
Conf = confidence level for passing initial test or one verification resample (nonparametric test only).
* - Insufficient Data.
** - Detection Frequency < 25%.
*** - Zero Variance.


Analysis performed using DUMPSTAT

# APPENDIX C-4.4
# SHEWHART-CUSUM CONTROL CHARTS - 1,1-DICHLOROETHANE


## Intra-Well Control Charts / Prediction Limits





**Graph 1**




**Graph 2**




**Graph 3**




**Graph 4**

# APPENDIX C-4.4
# SHEWHART-CUSUM CONTROL CHARTS
# 1,4-DIOXANE

## Summary Statistics and Intermediate Computations for Combined Shewhart-Cusum Control Charts


| Constituent | Units | Well | N(back) | N(mon) | N(tot) | Mean | SD | R(i-1) | R(i) | S(i-1) | S(i) | Limit | Type | Conf |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 1,4-dioxane | ug/L | PM-13X | 8 | 1 | 9 | | | | | | | | nonpar * | |
| 1,4-dioxane | ug/L | PM-14X | 32 | 4 | 36 | | | 0.0900 | 0.0900 | | | 0.9000 | nonpar | .99 |
| 1,4-dioxane | ug/L | PM-3X | 8 | 1 | 9 | | | | | | | | nonpar * | |
| 1,4-dioxane | ug/L | PM-6X | 8 | 1 | 9 | | | | | | | | nonpar * | |

N(back) and N(mon) = Non-outlier measurements in the background and monitoring periods.
N(tot) = All independent measurements for that constituent and well.
For transformed data, mean and SD in transformed units and control limit in original units.
Conf = confidence level for passing initial test or one verification resample (nonparametric test only).
* - Insufficient Data.
** - Detection Frequency < 25%.
*** - Zero Variance.


Analysis performed using DUMPSTAT

# APPENDIX C-4.4
# SHEWHART-CUSUM CONTROL CHARTS - 1,4-DIOXANE


## Intra-Well Control Charts / Prediction Limits





**Graph 1**




**Graph 2**




**Graph 3**




**Graph 4**

# APPENDIX C-4.4
# SHEWHART-CUSUM CONTROL CHARTS
# 1,1,1-TRICHLOROETHANE


## Summary Statistics and Intermediate Computations for Combined Shewhart-Cusum Control Charts

| Constituent | Units | Well | N(back) | N(mon) | N(tot) | Mean | SD | R(i-1) | R(i) | S(i-1) | S(i) | Limit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 1,1,1-trichloroethane | ug/L | PM-13X | 16 | 21 | 37 | 1.4538 | 0.5385 | 0.1600 | 0.1600 | 1.4538 | 1.4538 | 3.8770 |
| 1,1,1-trichloroethane | ug/L | PM-14X | 36 | 3 | 39 | | | 0.1600 | 0.1600 | | | 1.0000 |
| 1,1,1-trichloroethane | ug/L | PM-3X | 32 | 4 | 36 | | | 0.1600 | 0.1600 | | | 1.0000 |
| 1,1,1-trichloroethane | ug/L | PM-6X | 36 | 2 | 38 | | | 0.1600 | 0.1600 | | | 1.0000 |


N(back) and N(mon) = Non-outlier measurements in the background and monitoring periods.
N(tot) = All independent measurements for that constituent and well.
For transformed data, mean and SD in transformed units and control limit in original units.
Conf = confidence level for passing initial test or one verification resample (nonparametric test only).
* - Insufficient Data.
** - Detection Frequency < 25%.
*** - Zero Variance.

Analysis performed using DUMPSTAT


# APPENDIX C-4.4
# SHEWHART-CUSUM CONTROL CHARTS - 1,1,1-TRICHLOROETHANE
## Intra-Well Control Charts / Prediction Limits





**Graph 1**




**Graph 2**




**Graph 3**




**Graph 4**

# APPENDIX C-4.4
# SHEWHART-CUSUM CONTROL CHARTS
# TETRACHLOROETHENE

## Summary Statistics and Intermediate Computations for Combined Shewhart-Cusum Control Charts


| Constituent | Units | Well | N(back) | N(mon) | N(tot) | Mean | SD | R(i-1) | R(i) | S(i-1) | S(i) | Limit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Tetrachloroethene | ug/L | PM-13X | 32 | 5 | 37 | 1.0941 | 0.4070 | 0.2700 | 0.3000 | 1.0941 | 1.0941 | 2.9255 |
| Tetrachloroethene | ug/L | PM-14X | 36 | 3 | 39 | | | 0.2000 | 0.2000 | | | 1.0000 |
| Tetrachloroethene | ug/L | PM-3X | 18 | 18 | 36 | 0.7517 | 0.3069 | 0.6000 | 0.2000 | 0.7517 | 0.7517 | 2.1326 |
| Tetrachloroethene | ug/L | PM-6X | 36 | 2 | 38 | | | 0.2000 | 0.2000 | | | 1.0000 |

N(back) and N(mon) = Non-outlier measurements in the background and monitoring periods.
N(tot) = All independent measurements for that constituent and well.
For transformed data, mean and SD in transformed units and control limit in original units.
Conf = confidence level for passing initial test or one verification resample (nonparametric test only).
* - Insufficient Data.
** - Detection Frequency < 25%.
*** - Zero Variance.


Analysis performed using DUMPSTAT

# APPENDIX C-4.4
# SHEWHART-CUSUM CONTROL CHARTS - TETRACHLOROETHENE


## Intra-Well Control Charts / Prediction Limits





Graph 1




Graph 2




Graph 3




Graph 4

# APPENDIX C-4.4
# SHEWHART-CUSUM CONTROL CHARTS - TRICHLOROETHENE

## Summary Statistics and Intermediate Computations for Combined Shewhart-Cusum Control Charts


| Constituent | Units | Well | N(back) | N(mon) | N(tot) | Mean | SD | R(i-1) | R(i) | S(i-1) | S(i) | Limit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Trichloroethene | ug/L | PM-13X | 8 | 1 | 37 | 1.1888 | 0.2454 | 0.9900 | 0.6600 | | 1.1888 | 2.2930 |
| Trichloroethene | ug/L | PM-14X | 34 | 4 | 39 | 0.7871 | 0.3604 | 0.1600 | 0.1600 | 0.7871 | 0.7871 | 2.4089 |
| Trichloroethene | ug/L | PM-3X | 8 | 1 | 36 | 0.5037 | 0.3399 | 0.6400 | 0.1600 | | 0.5037 | 2.0332 |
| Trichloroethene | ug/L | PM-6X | 8 | 1 | 38 | | | | | | | |

N(back) and N(mon) = Non-outlier measurements in the background and monitoring periods.
N(tot) = All independent measurements for that constituent and well.
For transformed data, mean and SD in transformed units and control limit in original units.
Conf = confidence level for passing initial test or one verification resample (nonparametric test only).
* - Insufficient Data.
** - Detection Frequency < 25%.
*** - Zero Variance.


Analysis performed using DUMPSTAT

Prepared by: Parsons


# APPENDIX C-4.4
# SHEWHART-CUSUM CONTROL CHARTS - TRICHLOROETHENE
## Intra-Well Control Charts / Prediction Limits





**Graph 1**




**Graph 2**




**Graph 3**




**Graph 4**

# APPENDIX C-5

# VERTICAL MIGRATION ASSESSMENT

# APPENDIX C-5.1

# VERTICAL MIGRATION ASSESSMENT

## Vertical Migration Well Data

# TABLE C-5.1
# VERTICAL MIGRATION WELL DATA
## JULY THROUGH DECEMBER 2021 OPERATIONS AND MAINTENANCE STATUS
## REPORT LOWRY LANDFILL SUPERFUND SITE

| Group-ID | Sample Date | 1,1,1-Trichloroethane | 1,1,2,2-Tetrachloroetha | 1,1,2-Trichloroethane | 1,1-Dichloroethane | 1,1-Dichloroethene | 1,2-Dichloroethane | 1,2-Dichloropropane | 1,4-Dioxane | Acetone | Arsenic | Benzene | Bromodichloromethan | Bromoform | Cadmium | Carbon Tetrachloride | Chlorobenzene | Chloroform | cis-1,2-Dichloroethene | Dibromochloromethan | Ethylbenzene | Methylene Chloride | Naphthalene | Nitrogen, Nitrate | Nitrogen, Nitrite | Tetrachloroethene | Toluene | Trans-1,2-Dichloroeth | Trichloroethene | Vinyl Chloride |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| B-504A | 9/9/2002 | | | | | | | | | | 10 U | | | | 5 U | | | | | | | | | | | | | | | |
| B-504A | 5/11/2005 | | | | | | | | | | 10 U | | | | 5 U | | | | | | | | | 500 U | 500 U | | | | | |
| B-504A | 9/13/2005 | 1 U | 1 U | 1 U | 5.6 | 0.26 J | 1 U | 1 U | 0.5 U | 6.9 J | | 1 U | 1 U | 1 U | | 1 U | 1 U | 1 U | 0.24 J | 1 U | 1 U | 1 U | 1 U | 500 U | 500 U | 1 U | 0.31 J | 0.5 U | 1 U | 2 U |
| B-504A | 12/12/2005 | 1 U | 1 U | 1 U | 4.5 | 0.2 J | 1 U | 1 U | 0.5 U | 2.4 J | | 1 U | 1 U | 1 U | | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 90 J | 500 U | 1 U | 0.23 J | 0.5 U | 1 U | 2 U |
| B-504A | 3/6/2006 | 1 U | 1 U | 1 U | 4.8 | 0.19 J | 1 U | 1 U | 5 U | 10 U | 15 U | 1 U | 1 U | 1 U | 5 U | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 0.4 J | 1 U | | | 1 U | 0.21 J | 0.5 U | 1 U | 2 U |
| B-504A | 6/16/2006 | 1 U | 1 U | 1 U | 3.1 | 0.15 J | 1 U | 1 U | 5 U | 10 U | 15 U | 1 U | 1 U | 1 U | 5 U | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 0.33 J | 500 U | 500 U | 1 U | 0.18 J | 0.5 U | 1 U | 2 U |
| B-504A | 7/26/2006 | 1 U | 1 U | 1 U | 4.9 | 0.24 J | 1 U | 1 U | 5 U | 2.4 J | 15 U | 1 U | 1 U | 1 U | 5 U | 1 U | 1 U | 1 U | 0.17 J | 1 U | 1 U | 1 U | 1 U | 500 U | 500 U | 1 U | 0.22 J | 0.5 U | 1 U | 2 U |
| B-504A | 12/1/2006 | 1 U | 1 U | 1 U | 11 | 0.47 J | 1 U | 1 U | 5 U | 3.6 J | 15 U | 1 U | 1 U | 1 U | 5 U | 1 U | 1 U | 1 U | 0.37 J | 1 U | 1 U | 1 U | 1 U | 500 U | 500 U | 1 U | 0.53 J | 0.5 U | 1 U | 0.39 J |
| B-504A | 3/14/2007 | 1 U | 1 U | 1 U | 3.9 | 0.17 J | 1 U | 1 U | 5 U | 10 U | 15 U | 1 U | 1 U | 1 U | 5 U | 1 U | 1 U | 1 U | 0.17 J | 1 U | 1 U | 0.42 J | 1 U | 500 U | 500 U | 1 U | 0.19 J | 0.5 U | 1 U | 2 U |
| B-504A | 8/19/2010 | 1 U | 1 U | 1 U | 5.6 | 0.29 J | 1 U | 1 U | 5 U | 10 U | 15 U | 1 U | 1 U | 1 U | 5 U | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 500 U | 500 U | 1 U | 0.32 J | 0.5 U | 1 U | 2 U |
| B-504A | 7/30/2015 | 1 U | 1 U | 1 U | 11 | 1 U | 1 U | 1 U | 0.9 U | 10 U | 15 U | 1 U | 1 U | 1 U | 5 U | 1 U | 1 U | 1 U | 0.19 J | 1 U | 1 U | 1 U | 1 U | 500 U | 500 U | 1 U | 0.77 J | 0.5 U | 1 U | 0.28 J |
| B-504A | 8/15/2018 | 1 U | 1 U | 1 U | 1.5 | 1 U | 1 U | 1 U | 0.9 U | 10 U | 15 U | 1 U | 1 U | 1 U | 5 U | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 500 U | 500 U | 1 U | 1 U | 0.5 U | 1 U | 2 U |
| B-712-LD | 7/24/2006 | 1 U | 1 U | 1 U | 1 U | 1 U | 0.56 J | 1 U | 5 U | 10 U | 15 U | 1 U | 1 U | 1 U | 5 U | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 500 U | 500 U | 1 U | 1 U | 0.5 U | 1 U | 2 U |
| B-712-LD | 3/1/2007 | 1 U | 1 U | 1 U | 1 U | 1 U | 0.47 J | 1 U | 0.95 J | 10 U | 15 U | 1 U | 1 U | 1 U | 5 U | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 1 UJ | 1 U | 110 J | 500 U | 1 U | 1 U | 0.5 U | 1 U | 2 U |
| B-712-LD | 5/29/2007 | 1 U | 1 U | 1 U | 1 U | 1 U | 0.2 J | 1 U | 5 U | 10 U | 15 U | 1 U | 1 U | 1 U | 5 U | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 500 U | 500 U | 1 U | 1 U | 0.5 U | 1 U | 2 U |
| B-712-LD | 8/17/2009 | 1 U | 1 U | 1 U | 1 U | 1 U | 0.63 J | 1 U | 5 U | 10 U | 15 U | 1 U | 1 U | 1 U | 5 U | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 500 U | 500 U | 1 U | 1 U | 0.5 U | 1 U | 2 U |
| B-712-LD | 7/21/2011 | 1 U | 1 U | 1 U | 1 U | 1 U | 0.53 J | 1 U | 5 U | 10 U | 15 U | 1 U | 1 U | 1 U | 5 U | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 500 U | 500 U | 1 U | 1 U | 0.5 U | 1 U | 2 U |
| B-712-LD | 8/8/2013 | 1 U | 1 U | 1 U | 1 U | 1 U | 0.71 J | 1 U | 5 U | 10 U | 15 U | 1 U | 1 U | 1 U | 5 U | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 500 U | 500 U | 1 U | 1 U | 0.5 U | 1 U | 2 U |
| B-712-LD | 7/27/2015 | 1 U | 1 U | 1 U | 1 U | 1 U | 0.62 J | 1 U | 0.9 U | 10 U | 7.6 J | 1 U | 1 U | 1 U | 5 U | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 42 J | 500 U | 1 U | 1 U | 0.5 U | 1 U | 2 U |
| B-712-LD | 7/28/2017 | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 0.9 U | 10 U | 15 U | 1 U | 1 U | 1 U | 5 U | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 500 U | 500 U | 1 U | 1 U | 0.5 U | 1 U | 2 U |
| B-712-LD | 8/21/2018 | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 0.9 U | 10 U | 15 U | 1 U | 1 U | 1 U | 5 U | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 54 J | 500 U | 1 U | 1 U | 0.5 U | 1 U | 2 U |
| B-712-LD | 9/2/2020 | 1 U | 1 U | 1 U | 1 U | 1 U | 0.48 J | 1 U | 0.9 U | 10 U | 15 U | 1 U | 1 U | 1 U | 5 U | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 0.56 J | 500 U | 500 U | 1 U | 1 U | 0.5 U | 1 U | 2 U |
| C-702P3 | 9/12/2002 | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | | | 10 U | 1 U | 1 U | 1 U | 5 U | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | | | | 1 U | 1 U | 0.5 U | 1 U | 2 U |
| C-702P3 | 5/12/2005 | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | | 10 U | 10 U | 1 U | 1 U | 1 U | 5 U | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 500 U | 500 U | 1 U | 1 U | 0.5 U | 1 U | 2 U |
| C-702P3 | 9/14/2005 | | | | | | | | 0.5 U | | | | | | | | | | | | | | | 40 J | 500 U | | | | | |
| C-702P3 | 12/5/2005 | | | | | | | | 0.5 U | | | | | | | | | | | | | | | 500 U | 500 U | | | | | |
| C-702P3 | 3/8/2006 | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 5 U | 10 U | 15 U | 1 U | 1 U | 1 U | 5 U | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 0.38 J | 1 U | | | 1 U | 1 U | 0.5 U | 1 U | 2 U |
| C-702P3 | 5/24/2006 | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | | 10 U | | 1 U | 1 U | 1 U | | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | | | 1 U | 1 U | 0.5 U | 1 U | 2 U |
| C-702P3 | 6/15/2006 | | | | | | | | 5 U | | 15 U | | | | 5 U | | | | | | | | | 500 U | 500 U | | | | | |
| C-702P3 | 7/26/2006 | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 5 U | 10 U | 15 U | 1 U | 1 U | 1 U | 5 U | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 500 U | 500 U | 1 U | 1 U | 0.5 U | 1 U | 2 U |

**TABLE C-5.1**
**VERTICAL MIGRATION WELL DATA**
**JULY THROUGH DECEMBER 2021 OPERATIONS AND MAINTENANCE STATUS**
**REPORT LOWRY LANDFILL SUPERFUND SITE**

| Group-ID | Sample Date | 1,1,1-Trichloroethane | 1,1,2,2-Tetrachloroetha | 1,1,2-Trichloroethane | 1,1-Dichloroethane | 1,1-Dichloroethene | 1,2-Dichloroethane | 1,2-Dichloropropane | 1,4-Dioxane | Acetone | Arsenic | Benzene | Bromodichloromethan | Bromoform | Cadmium | Carbon Tetrachloride | Chlorobenzene | Chloroform | cis-1,2-Dichloroethene | Dibromochloromethan | Ethylbenzene | Methylene Chloride | Naphthalene | Nitrogen, Nitrate | Nitrogen, Nitrite | Tetrachloroethene | Toluene | Trans-1,2-Dichloroethe | Trichloroethene | Vinyl Chloride |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| C-702P3 | 11/27/2006 | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 5 U | 10 U | 15 U | 1 U | 1 U | 1 U | 5 U | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 500 U | 500 U | 1 U | 1 U | 0.5 U | 1 U | 2 U |
| C-702P3 | 2/28/2007 | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 5 U | 10 U | 15 U | 1 U | 1 U | 1 U | 5 U | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 1 UJ | 1 U | 500 U | 500 U | 1 U | 1 U | 0.5 U | 1 U | 2 U |
| C-702P3 | 8/19/2010 | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 5 U | 10 U | 15 U | 1 U | 1 U | 1 U | 5 U | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 500 U | 500 U | 1 U | 1 U | 0.5 U | 1 U | 2 U |
| C-702P3 | 7/14/2015 | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 5 U | 10 U | 15 U | 1 U | 1 U | 1 U | 5 U | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 87 J | 500 U | 1 U | 1 U | 0.5 U | 1 U | 2 U |
| C-702P3 | 8/15/2018 | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 0.9 U | 10 U | 15 U | 1 U | 1 U | 1 U | 5 U | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 59 J | 500 U | 1 U | 1 U | 0.5 U | 1 U | 2 U |
| GW-113 | 9/12/2002 | | | | | | | | | | 10 U | | | | 5 U | | | | | | | | | | | | | | | |
| GW-113 | 5/24/2005 | | | | | | | | | | 10 U | | | | 5 U | | | | | | | | | 500 UJ | 500 UJ | | | | | |
| GW-113 | 9/13/2005 | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 0.5 U | 10 U | 10 U | 1 U | 1 U | 1 U | 5 U | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 47 J | 500 U | 1 U | 1 U | 0.5 U | 1 U | 2 U |
| GW-113 | 12/13/2005 | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 0.5 U | 10 U | | 1 U | 1 U | 1 U | | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 140 J | 500 U | 1 U | 1 U | 0.5 U | 1 U | 2 U |
| GW-113 | 3/14/2006 | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 5 U | 10 U | | 1 U | 1 U | 1 U | | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | | | 1 U | 1 U | 0.5 U | 1 U | 2 U |
| GW-113 | 6/19/2006 | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 5 U | 10 U | 15 U | 1 U | 1 U | 1 U | 5 U | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 270 J | 500 U | 1 U | 1 U | 0.5 U | 1 U | 2 U |
| GW-113 | 7/26/2006 | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 5 U | 10 U | 15 U | 1 U | 1 U | 1 U | 5 U | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 42 J | 500 U | 1 U | 1 U | 0.5 U | 1 U | 2 U |
| GW-113 | 11/27/2006 | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 5 U | 10 U | 15 U | 1 U | 1 U | 1 U | 5 U | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 43 J | 500 U | 1 U | 1 U | 0.5 U | 1 U | 2 U |
| GW-113 | 3/1/2007 | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 5 U | 2.1 J | 15 U | 1 U | 1 U | 1 U | 5 U | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 1 UJ | 1 U | 500 U | 500 U | 1 U | 1 U | 0.5 U | 1 U | 2 U |
| GW-113 | 8/23/2010 | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 5 U | 10 U | 15 U | 1 U | 1 U | 1 U | 5 U | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 500 U | 50 J | 1 U | 1 U | 0.5 U | 1 U | 2 U |
| GW-113 | 7/27/2015 | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 0.9 U | 10 U | 15 U | 1 U | 1 U | 1 U | 5 U | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 500 U | 500 U | 1 U | 1 U | 0.5 U | 1 U | 2 U |
| GW-113 | 8/16/2018 | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 0.9 U | 10 U | 15 U | 1 U | 1 U | 1 U | 5 U | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 1 U | 57 J | 500 U | 1 U | 1 U | 0.5 U | 1 U | 2 U |

Units= µg/L

Highlighted cell indicates a detected compound

**Qualifiers:** U= The analyte was analyzed for and is not present above the level of the associated value.
The associated numerical value indicates the approximate concentration necessary to detect the analyte in the sample.

UJ= The analyte analyzed for was not present above the level of the associated value. The associated numerical value may not accurately represent the concentration necessary to detect the analyte in the sample.

UJ-= Same as UJ qualification but with an indication of negative bias in the sample concentration.

UJ+= Same as UJ qualification but with an indication of positive bias in the sample concentration.

J= The analyte was analyzed for, and was positively identified, but the associated numerical value may not be consistent with the amount actually present in the environmental sample.

J-= Same as J qualification but with an indication of negative bias in the sample concentration.

J+= Same as J qualification but with an indication of positive bias in the sample concentration.

# APPENDIX C-5.2

# VERTICAL MIGRATION ASSESSMENT

## Trend Analysis

| | | |
|---|---|---|
| **Mann-Kendall Trend Test Analysis** | | |
| User Selected Options | | |
| Date/Time of Computation | ProUCL 5.13/4/2019 9:33:53 AM | |
| From File | VERT MIG DATA.xls | |
| Full Precision | OFF | |
| Confidence Coefficient | 0.95 | |
| Level of Significance | 0.05 | |

**1,1-Dichloroethane-b-504a**


**General Statistics**

| | |
|---|---|
| Number of Events Reported (m) | 10 |
| Number of Missing Events | 0 |
| Number or Reported Events Used | 10 |
| Number Values Reported (n) | 10 |
| Minimum | 1.5 |
| Maximum | 11 |
| Mean | 5.59 |
| Geometric Mean | 4.855 |
| Median | 4.85 |
| Standard Deviation | 3.102 |
| Coefficient of Variation | 0.555 |

**Mann-Kendall Test**

| | |
|---|---|
| M-K Test Value (S) | 1 |
| Tabulated p-value | 0.5 |
| Standard Deviation of S | 11.09 |
| Standardized Value of S | 0 |
| Approximate p-value | 0.5 |

**Insufficient evidence to identify a significant trend at the specified level of significance.**


Mann-Kendall Trend Test
1,1-Dichloroethane-b-504a
9
7
5
3
1
38509
39309
40109
40909
41709
42509
43309
Sample Date-b-504a
Mann-Kendall Trend Analysis
n 10
Confidence Coefficient 0.9500
Level of Significance 0.0500
Standard Deviation of S 11.0905
Standardized Value of S 0.0000
M-K Test Value (S) 1
Tabulated p-value 0.5000
Approximate p-value 0.5000
OLS Regression Line (Blue)
OLS Regression Slope 0.0000
OLS Regression Intercept 4.6819
Theil-Sen Trend Line (Red)
Theil-Sen Slope 0.0000
Theil-Sen Intercept 4.8500
Insufficient statistical evidence of a significant trend at the specified level of significance.

| | | |
|---|---|---|
| **Mann-Kendall Trend Test Analysis** | | |
| User Selected Options | | |
| Date/Time of Computation | ProUCL 5.13/4/2019 9:30:09 AM | |
| From File | VERT MIG DATA_a.xls | |
| Full Precision | OFF | |
| Confidence Coefficient | 0.95 | |
| Level of Significance | 0.05 | |

**1,1-Dichloroethene-b-504a**

**General Statistics**

| | |
|---|---|
| Number of Events Reported (m) | 10 |
| Number of Missing Events | 0 |
| Number or Reported Events Used | 10 |
| Number Values Reported (n) | 10 |
| Minimum | 0.115 |
| Maximum | 0.47 |
| Mean | 0.22 |
| Geometric Mean | 0.201 |
| Median | 0.195 |
| Standard Deviation | 0.105 |
| Coefficient of Variation | 0.479 |

**Mann-Kendall Test**

| | |
|---|---|
| M-K Test Value (S) | -14 |
| Tabulated p-value | 0.108 |
| Standard Deviation of S | 11.14 |
| Standardized Value of S | -1.167 |
| Approximate p-value | 0.122 |

**Insufficient evidence to identify a significant trend at the specified level of significance.**


Mann-Kendall Trend Test
1,1-Dichloroethene-b-504a
0.456
0.406
0.356
0.306
0.256
0.206
0.156
0.106
38509
39309
40109
40909
41709
42509
43309
Sample Date-b-504a
Mann-Kendall Trend Analysis
n 10
Confidence Coefficient 0.9500
Level of Significance 0.0500
Standard Deviation of S 11.1355
Standardized Value of S -1.1674
M-K Test Value (S) -14
Tabulated p-value 0.1080
Approximate p-value 0.1215
OLS Regression Line (Blue)
OLS Regression Slope 0.0000
OLS Regression Intercept 1.3145
Theil-Sen Trend Line (Red)
Theil-Sen Slope 0.0000
Theil-Sen Intercept 1.0468
Insufficient statistical evidence of a significant trend at the specified level of significance.

| | | |
|---|---|---|
| **Mann-Kendall Trend Test Analysis** | | |
| User Selected Options | | |
| Date/Time of Computation | ProUCL 5.13/4/2019 9:28:31 AM | |
| From File | VERT MIG DATA_d.xls | |
| Full Precision | OFF | |
| Confidence Coefficient | 0.95 | |
| Level of Significance | 0.05 | |

**Acetone-b-504a**


**General Statistics**

| | |
|---|---|
| Number of Events Reported (m) | 10 |
| Number of Missing Events | 0 |
| Number or Reported Events Used | 10 |
| Number Values Reported (n) | 10 |
| Minimum | 0.95 |
| Maximum | 6.9 |
| Mean | 2.1 |
| Geometric Mean | 1.593 |
| Median | 0.95 |
| Standard Deviation | 1.927 |
| Coefficient of Variation | 0.917 |

**Mann-Kendall Test**

| | |
|---|---|
| M-K Test Value (S) | -17 |
| Tabulated p-value | 0.078 |
| Standard Deviation of S | 9.781 |
| Standardized Value of S | -1.636 |
| Approximate p-value | 0.0509 |

**Insufficient evidence to identify a significant trend at the specified level of significance.**


Mann-Kendall Trend Test
Acetone-b-504a
7
6
5
4
3
2
1
38509
39309
40109
40909
41709
42509
43309
Sample Date-b-504a
Mann-Kendall Trend Analysis
n 10
Confidence Coefficient 0.9500
Level of Significance 0.0500
Standard Deviation of S 9.7809
Standardized Value of S -1.6358
M-K Test Value (S) -17
Tabulated p-value 0.0780
Approximate p-value 0.0509
OLS Regression Line (Blue)
OLS Regression Slope -0.0005
OLS Regression Intercept 21.2940
Theil-Sen Trend Line (Red)
Theil-Sen Slope -0.0003
Theil-Sen Intercept 13.1627
Insufficient statistical evidence of a significant trend at the specified level of significance.

| | | |
|---|---|---|
| **Mann-Kendall Trend Test Analysis** | | |
| User Selected Options | | |
| Date/Time of Computation | ProUCL 5.13/4/2019 9:27:07 AM | |
| From File | VERT MIG DATA_f.xls | |
| Full Precision | OFF | |
| Confidence Coefficient | 0.95 | |
| Level of Significance | 0.05 | |

**cis-1,2-Dichloroethene-b-504a**


**General Statistics**

| | |
|---|---|
| Number of Events Reported (m) | 10 |
| Number of Missing Events | 0 |
| Number or Reported Events Used | 10 |
| Number Values Reported (n) | 10 |
| Minimum | 0.075 |
| Maximum | 0.37 |
| Mean | 0.152 |
| Geometric Mean | 0.128 |
| Median | 0.123 |
| Standard Deviation | 0.0983 |
| Coefficient of Variation | 0.649 |

**Mann-Kendall Test**

| | |
|---|---|
| M-K Test Value (S) | 0 |
| Tabulated p-value | 0.5 |
| Standard Deviation of S | 10.36 |
| Standardized Value of S | N/A |
| Approximate p-value | N/A |

**Insufficient evidence to identify a significant trend at the specified level of significance.**


Mann-Kendall Trend Test
cis-1,2-Dichloroethene-b-504a
0.368
0.318
0.268
0.218
0.168
0.118
0.068
38509
39309
40109
40909
41709
42509
43309
Sample Date-b-504a
Mann-Kendall Trend Analysis
n 10
Confidence Coefficient 0.9500
Level of Significance 0.0500
Standard Deviation of S 10.3602
Standardized Value of S
M-K Test Value (S) 0
Tabulated p-value 0.5000
Approximate p-value
OLS Regression Line (Blue)
OLS Regression Slope 0.0000
OLS Regression Intercept 0.6124
Theil-Sen Trend Line (Red)
Theil-Sen Slope 0.0000
Theil-Sen Intercept 0.1225
Insufficient statistical evidence of a significant trend at the specified level of significance.

| | | |
|---|---|---|
| **Mann-Kendall Trend Test Analysis** | | |
| User Selected Options | | |
| Date/Time of Computation | ProUCL 5.13/4/2019 9:26:14 AM | |
| From File | VERT MIG DATA_g.xls | |
| Full Precision | OFF | |
| Confidence Coefficient | 0.95 | |
| Level of Significance | 0.05 | |

**Methylene Chloride-b-504a**

**General Statistics**

| | |
|---|---|
| Number of Events Reported (m) | 10 |
| Number of Missing Events | 0 |
| Number or Reported Events Used | 10 |
| Number Values Reported (n) | 10 |
| Minimum | 0.16 |
| Maximum | 0.42 |
| Mean | 0.21 |
| Geometric Mean | 0.193 |
| Median | 0.16 |
| Standard Deviation | 0.106 |
| Coefficient of Variation | 0.502 |

**Mann-Kendall Test**

| | |
|---|---|
| M-K Test Value (S) | -1 |
| Tabulated p-value | 0.5 |
| Standard Deviation of S | 7.724 |
| Standardized Value of S | 0 |
| Approximate p-value | 0.5 |

**Insufficient evidence to identify a significant trend at the specified level of significance.**


Mann-Kendall Trend Test
Methylene Chloride-b-504a
0.403
0.353
0.303
0.253
0.203
0.153
38509
39309
40109
40909
41709
42509
43309
Sample Date-b-504a
Mann-Kendall Trend Analysis
n 10
Confidence Coefficient 0.9500
Level of Significance 0.0500
Standard Deviation of S 7.7244
Standardized Value of S 0.0000
M-K Test Value (S) -1
Tabulated p-value 0.5000
Approximate p-value 0.5000
OLS Regression Line (Blue)
OLS Regression Slope 0.0000
OLS Regression Intercept 0.8731
Theil-Sen Trend Line (Red)
Theil-Sen Slope 0.0000
Theil-Sen Intercept 0.1600
Insufficient statistical evidence of a significant trend at the specified level of significance.

| | | |
|---|---|---|
| **Mann-Kendall Trend Test Analysis** | | |
| User Selected Options | | |
| Date/Time of Computation | ProUCL 5.13/4/2019 9:25:41 AM | |
| From File | VERT MIG DATA_h.xls | |
| Full Precision | OFF | |
| Confidence Coefficient | 0.95 | |
| Level of Significance | 0.05 | |

**Naphthalene-b-504a**

**General Statistics**

| | |
|---|---|
| Number of Events Reported (m) | 10 |
| Number of Missing Events | 0 |
| Number or Reported Events Used | 10 |
| Number Values Reported (n) | 10 |
| Minimum | 0.11 |
| Maximum | 0.33 |
| Mean | 0.132 |
| Geometric Mean | 0.123 |
| Median | 0.11 |
| Standard Deviation | 0.0696 |
| Coefficient of Variation | 0.527 |

**Mann-Kendall Test**

| | |
|---|---|
| M-K Test Value (S) | -3 |
| Tabulated p-value | 0.431 |
| Standard Deviation of S | 5.745 |
| Standardized Value of S | -0.348 |
| Approximate p-value | 0.364 |

**Insufficient evidence to identify a significant trend at the specified level of significance.**


Mann-Kendall Trend Test
Naphthalene-b-504a
0.324
0.304
0.284
0.264
0.244
0.224
0.204
0.184
0.164
0.144
0.124
0.104
38509
39309
40109
40909
41709
42509
43309
Sample Date-b-504a
Mann-Kendall Trend Analysis
n 10
Confidence Coefficient 0.9500
Level of Significance 0.0500
Standard Deviation of S 5.7446
Standardized Value of S -0.3482
M-K Test Value (S) -3
Tabulated p-value 0.4310
Approximate p-value 0.3639
OLS Regression Line (Blue)
OLS Regression Slope 0.0000
OLS Regression Intercept 0.4561
Theil-Sen Trend Line (Red)
Theil-Sen Slope 0.0000
Theil-Sen Intercept 0.1100
Insufficient statistical evidence of a significant trend at the specified level of significance.

| | | |
|---|---|---|
| **Mann-Kendall Trend Test Analysis** | | |
| User Selected Options | | |
| Date/Time of Computation | ProUCL 5.13/4/2019 9:24:11 AM | |
| From File | VERT MIG DATA_i.xls | |
| Full Precision | OFF | |
| Confidence Coefficient | 0.95 | |
| Level of Significance | 0.05 | |

**Nitrogen, Nitrate-b-504a**


**General Statistics**

| | |
|---|---|
| Number of Events Reported (m) | 10 |
| Number of Missing Events | 0 |
| Number or Reported Events Used | 10 |
| Number Values Reported (n) | 10 |
| Minimum | 10 |
| Maximum | 90 |
| Mean | 25.7 |
| Geometric Mean | 20.94 |
| Median | 21 |
| Standard Deviation | 23.05 |
| Coefficient of Variation | 0.897 |

**Mann-Kendall Test**

| | |
|---|---|
| M-K Test Value (S) | 9 |
| Tabulated p-value | 0.242 |
| Standard Deviation of S | 8.926 |
| Standardized Value of S | 0.896 |
| Approximate p-value | 0.185 |

**Insufficient evidence to identify a significant trend at the specified level of significance.**


Mann-Kendall Trend Test
Nitrogen, Nitrate-b-504a
88
68
48
28
8
38381
39181
39981
40781
41581
42381
43181
Sample Date-b-504a
Mann-Kendall Trend Analysis
n 10
Confidence Coefficient 0.9500
Level of Significance 0.0500
Standard Deviation of S 8.9256
Standardized Value of S 0.8963
M-K Test Value (S) 9
Tabulated p-value 0.2420
Approximate p-value 0.1850
OLS Regression Line (Blue)
OLS Regression Slope -0.0018
OLS Regression Intercept 99.2049
Theil-Sen Trend Line (Red)
Theil-Sen Slope 0.0000
Theil-Sen Intercept 21.0000
Insufficient statistical evidence of a significant trend at the specified level of significance.

| | | |
|---|---|---|
| | **Mann-Kendall Trend Test Analysis** | |
| User Selected Options | | |
| Date/Time of Computation | ProUCL 5.13/4/2019 9:22:52 AM | |
| From File | VERT MIG DATA_k.xls | |
| Full Precision | OFF | |
| Confidence Coefficient | 0.95 | |
| Level of Significance | 0.05 | |

**Toluene-b-504a**


**General Statistics**

| | |
|---|---|
| Number of Events Reported (m) | 10 |
| Number of Missing Events | 0 |
| Number or Reported Events Used | 10 |
| Number Values Reported (n) | 10 |
| Minimum | 0.085 |
| Maximum | 0.77 |
| Mean | 0.305 |
| Geometric Mean | 0.257 |
| Median | 0.225 |
| Standard Deviation | 0.202 |
| Coefficient of Variation | 0.662 |

**Mann-Kendall Test**

| | |
|---|---|
| M-K Test Value (S) | -1 |
| Tabulated p-value | 0.5 |
| Standard Deviation of S | 11.18 |
| Standardized Value of S | 0 |
| Approximate p-value | 0.5 |

**Insufficient evidence to identify a significant trend at the specified level of significance.**


Mann-Kendall Trend Test
Toluene-b-504a
0.77
0.67
0.57
0.47
0.37
0.27
0.17
0.07
38509
39309
40109
40909
41709
42509
43309
Sample Date-b-504a
Mann-Kendall Trend Analysis
n 10
Confidence Coefficient 0.9500
Level of Significance 0.0500
Standard Deviation of S 11.1803
Standardized Value of S 0.0000
M-K Test Value (S) -1
Tabulated p-value 0.5000
Approximate p-value 0.5000
OLS Regression Line (Blue)
OLS Regression Slope 0.0000
OLS Regression Intercept -0.6939
Theil-Sen Trend Line (Red)
Theil-Sen Slope 0.0000
Theil-Sen Intercept 1.0586
Insufficient statistical evidence of a significant trend at the specified level of significance.

| | | |
|---|---|---|
| **Mann-Kendall Trend Test Analysis** | | |
| User Selected Options | | |
| Date/Time of Computation | ProUCL 5.13/4/2019 9:21:39 AM | |
| From File | VERT MIG DATA_I.xls | |
| Full Precision | OFF | |
| Confidence Coefficient | 0.95 | |
| Level of Significance | 0.05 | |

**Vinyl Chloride-b-504a**


**General Statistics**

| | |
|---|---|
| Number of Events Reported (m) | 10 |
| Number of Missing Events | 0 |
| Number or Reported Events Used | 10 |
| Number Values Reported (n) | 10 |
| Minimum | 0.05 |
| Maximum | 0.39 |
| Mean | 0.175 |
| Geometric Mean | 0.147 |
| Median | 0.19 |
| Standard Deviation | 0.105 |
| Coefficient of Variation | 0.599 |

**Mann-Kendall Test**

| | |
|---|---|
| M-K Test Value (S) | -3 |
| Tabulated p-value | 0.431 |
| Standard Deviation of S | 10.85 |
| Standardized Value of S | -0.184 |
| Approximate p-value | 0.427 |

**Insufficient evidence to identify a significant trend at the specified level of significance.**


Mann-Kendall Trend Test
Vinyl Chloride-b-504a
0.391
0.341
0.291
0.241
0.191
0.141
0.091
0.041
38509
39309
40109
40909
41709
42509
43309
Sample Date-b-504a
Mann-Kendall Trend Analysis
n 10
Confidence Coefficient 0.9500
Level of Significance 0.0500
Standard Deviation of S 10.8474
Standardized Value of S -0.1844
M-K Test Value (S) -3
Tabulated p-value 0.4310
Approximate p-value 0.4269
OLS Regression Line (Blue)
OLS Regression Slope 0.0000
OLS Regression Intercept 0.4355
Theil-Sen Trend Line (Red)
Theil-Sen Slope 0.0000
Theil-Sen Intercept 0.1900
Insufficient statistical evidence of a significant trend at the specified level of significance.


| | | |
|---|---|---|
| **Mann-Kendall Trend Test Analysis** | | |
| User Selected Options | | |
| Date/Time of Computation | ProUCL 5.12/19/2021 10:41:55 AM | |
| From File | VERT MIG DATA - B-712-LD ONLY.xls | |
| Full Precision | OFF | |
| Confidence Coefficient | 0.95 | |
| Level of Significance | 0.05 | |

**1,2-Dichloroethane-b-712-ld**

| **General Statistics** | |
|---|---|
| Number of Events Reported (m) | 10 |
| Number of Missing Events | 0 |
| Number or Reported Events Used | 10 |
| Number Values Reported (n) | 10 |
| Minimum | 0.065 |
| Maximum | 0.71 |
| Mean | 0.433 |
| Geometric Mean | 0.331 |
| Median | 0.505 |
| Standard Deviation | 0.237 |
| Coefficient of Variation | 0.547 |

| **Mann-Kendall Test** | |
|---|---|
| M-K Test Value (S) | -8 |
| Tabulated p-value | 0.242 |
| Standard Deviation of S | 11.14 |
| Standardized Value of S | -0.629 |
| Approximate p-value | 0.265 |

**Insufficient evidence to identify a significant trend at the specified level of significance.**




**Mann-Kendall Trend Analysis**

| | |
|---|---|
| n | 10 |
| Confidence Coefficient | 0.9500 |
| Level of Significance | 0.0500 |
| Standard Deviation of S | 11.1355 |
| Standardized Value of S | -0.6286 |
| M-K Test Value (S) | -8 |
| Tabulated p-value | 0.2420 |
| Approximate p-value | 0.2648 |

**OLS Regression Line (Blue)**

| | |
|---|---|
| OLS Regression Slope | 0.0000 |
| OLS Regression Intercept | 1.9870 |

**Theil-Sen Trend Line (Red)**

| | |
|---|---|
| Theil-Sen Slope | 0.0000 |
| Theil-Sen Intercept | 1.1817 |

Insufficient statistical evidence of a significant trend at the specified level of significance.

| | | |
|---|---|---|
| **Mann-Kendall Trend Test Analysis** | | |
| User Selected Options | | |
| Date/Time of Computation | ProUCL 5.12/19/2021 10:46:19 AM | |
| From File | VERT MIG DATA - B-712-LD ONLY_b.xls | |
| Full Precision | OFF | |
| Confidence Coefficient | 0.95 | |
| Level of Significance | 0.05 | |

**Arsenic-b-712-ld**


**General Statistics**

| | |
|---|---|
| Number of Events Reported (m) | 10 |
| Number of Missing Events | 0 |
| Number or Reported Events Used | 10 |
| Number Values Reported (n) | 10 |
| Minimum | 2.2 |
| Maximum | 7.6 |
| Mean | 2.74 |
| Geometric Mean | 2.49 |
| Median | 2.2 |
| Standard Deviation | 1.708 |
| Coefficient of Variation | 0.623 |

**Mann-Kendall Test**

| | |
|---|---|
| M-K Test Value (S) | 3 |
| Tabulated p-value | 0.431 |
| Standard Deviation of S | 5.745 |
| Standardized Value of S | 0.348 |
| Approximate p-value | 0.364 |

**Insufficient evidence to identify a significant trend at the specified level of significance.**




**Mann-Kendall Trend Analysis**

| | |
|---|---|
| n | 10 |
| Confidence Coefficient | 0.9500 |
| Level of Significance | 0.0500 |
| Standard Deviation of S | 5.7446 |
| Standardized Value of S | 0.3482 |
| M-K Test Value (S) | 3 |
| Tabulated p-value | 0.4310 |
| Approximate p-value | 0.3639 |

**OLS Regression Line (Blue)**


| | |
|---|---|
| OLS Regression Slope | 0.0002 |
| OLS Regression Intercept | -4.2394 |

**Theil-Sen Trend Line (Red)**

| | |
|---|---|
| Theil-Sen Slope | 0.0000 |
| Theil-Sen Intercept | 2.2000 |

Insufficient statistical evidence of a significant trend at the specified level of significance.

| | A | B | C | D | E | F | G | H | I | J | K | L |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 1 | | | | **Mann-Kendall Trend Test Analysis** | | | | | | | | |
| 2 | | | User Selected Options | | | | | | | | | |
| 3 | | | Date/Time of Computation | ProUCL 5.12/19/2021 10:51:27 AM | | | | | | | | |
| 4 | | | From File | VERT MIG DATA - B-712-LD ONLY_d.xls | | | | | | | | |
| 5 | | | Full Precision | OFF | | | | | | | | |
| 6 | | | Confidence Coefficient | 0.95 | | | | | | | | |
| 7 | | | Level of Significance | 0.05 | | | | | | | | |
| 8 | | | | | | | | | | | | |
| 9 | **Naphthalene-b-712-ld** | | | | | | | | | | | |
| 10 | | | | | | | | | | | | |
| 11 | **General Statistics** | | | | | | | | | | | |
| 12 | | | Number of Events Reported (m) | | 11 | | | | | | | |
| 13 | | | Number of Missing Events | | 0 | | | | | | | |
| 14 | | | Number or Reported Events Used | | 11 | | | | | | | |
| 15 | | | Number Values Reported (n) | | 11 | | | | | | | |
| 16 | | | Minimum | | 0.11 | | | | | | | |
| 17 | | | Maximum | | 0.56 | | | | | | | |
| 18 | | | Mean | | 0.151 | | | | | | | |
| 19 | | | Geometric Mean | | 0.128 | | | | | | | |
| 20 | | | Median | | 0.11 | | | | | | | |
| 21 | | | Standard Deviation | | 0.136 | | | | | | | |
| 22 | | | Coefficient of Variation | | 0.899 | | | | | | | |
| 23 | | | | | | | | | | | | |
| 24 | **Mann-Kendall Test** | | | | | | | | | | | |
| 25 | | | M-K Test Value (S) | | 10 | | | | | | | |
| 26 | | | Tabulated p-value | | 0.223 | | | | | | | |
| 27 | | | Standard Deviation of S | | 6.325 | | | | | | | |
| 28 | | | Standardized Value of S | | 1.423 | | | | | | | |
| 29 | | | Approximate p-value | | 0.0774 | | | | | | | |
| 30 | | | | | | | | | | | | |
| 31 | **Insufficient evidence to identify a significant** | | | | | | | | | | | |
| 32 | **trend at the specified level of significance.** | | | | | | | | | | | |


Mann-Kendall Trend Test
Naphthalene-b-712-Id
0.549
0.499
0.449
0.399
0.349
0.299
0.249
0.199
0.149
0.099
38778
39578
40378
41178
41978
42778
43578
Sample Date-b-712-Id
Mann-Kendall Trend Analysis
n 11
Confidence Coefficient 0.9500
Level of Significance 0.0500
Standard Deviation of S 6.3246
Standardized Value of S 1.4230
M-K Test Value (S) 10
Tabulated p-value 0.2230
Approximate p-value 0.0774
OLS Regression Line (Blue)
OLS Regression Slope 0.0000
OLS Regression Intercept -1.3924
Theil-Sen Trend Line (Red)
Theil-Sen Slope 0.0000
Theil-Sen Intercept 0.1100
Insufficient statistical evidence of a significant trend at the specified level of significance.

| | | |
|---|---|---|
| **Mann-Kendall Trend Test Analysis** | | |
| User Selected Options | | |
| Date/Time of Computation | ProUCL 5.12/19/2021 10:49:35 AM | |
| From File | VERT MIG DATA - B-712-LD ONLY_c.xls | |
| Full Precision | OFF | |
| Confidence Coefficient | 0.95 | |
| Level of Significance | 0.05 | |

**Nitrogen, Nitrate-b-712-ld**


**General Statistics**

| | |
|---|---|
| Number of Events Reported (m) | 10 |
| Number of Missing Events | 0 |
| Number or Reported Events Used | 10 |
| Number Values Reported (n) | 10 |
| Minimum | 21 |
| Maximum | 110 |
| Mean | 37.7 |
| Geometric Mean | 31.5 |
| Median | 21 |
| Standard Deviation | 28.36 |
| Coefficient of Variation | 0.752 |

**Mann-Kendall Test**

| | |
|---|---|
| M-K Test Value (S) | 10 |
| Tabulated p-value | 0.19 |
| Standard Deviation of S | 9.832 |
| Standardized Value of S | 0.915 |
| Approximate p-value | 0.18 |

**Insufficient evidence to identify a significant trend at the specified level of significance.**




**Mann-Kendall Trend Analysis**

| | |
|---|---|
| n | 10 |
| Confidence Coefficient | 0.9500 |
| Level of Significance | 0.0500 |
| Standard Deviation of S | 9.8319 |
| Standardized Value of S | 0.9154 |
| M-K Test Value (S) | 10 |
| Tabulated p-value | 0.1900 |
| Approximate p-value | 0.1800 |

**OLS Regression Line (Blue)**

| | |
|---|---|
| OLS Regression Slope | -0.0008 |
| OLS Regression Intercept | 69.8878 |

**Theil-Sen Trend Line (Red)**

| | |
|---|---|
| Theil-Sen Slope | 0.0000 |
| Theil-Sen Intercept | 21.0000 |

Insufficient statistical evidence of a significant trend at the specified level of significance.


| | | |
|---|---|---|
| **Mann-Kendall Trend Test Analysis** | | |
| User Selected Options | | |
| Date/Time of Computation | ProUCL 5.12/15/2021 12:25:59 PM | |
| From File | COMPLIANCE DATA For TREND- 1H2020.xls | |
| Full Precision | OFF | |
| Confidence Coefficient | 0.95 | |
| Level of Significance | 0.05 | |

**1,4-Dioxane-b-712-ld**

| **General Statistics** | |
|---|---|
| Number of Events Reported (m) | 10 |
| Number of Missing Events | 0 |
| Number or Reported Events Used | 10 |
| Number Values Reported (n) | 10 |
| Minimum | 0.045 |
| Maximum | 0.95 |
| Mean | 0.247 |
| Geometric Mean | 0.168 |
| Median | 0.25 |
| Standard Deviation | 0.263 |
| Coefficient of Variation | 1.066 |

| **Mann-Kendall Test** | |
|---|---|
| M-K Test Value (S) | -30 |
| Tabulated p-value | 0.002 |
| Standard Deviation of S | 10.23 |
| Standardized Value of S | -2.835 |
| Approximate p-value | 0.00229 |

**Statistically significant evidence of a decreasing trend at the specified level of significance.**




**Mann-Kendall Trend Analysis**

| | |
|---|---|
| n | 10 |
| Confidence Coefficient | 0.9500 |
| Level of Significance | 0.0500 |
| Standard Deviation of S | 10.2307 |
| Standardized Value of S | -2.8346 |
| M-K Test Value (S) | -30 |
| Tabulated p-value | 0.0020 |
| Approximate p-value | 0.0023 |

**OLS Regression Line (Blue)**

| | |
|---|---|
| OLS Regression Slope | -0.0001 |
| OLS Regression Intercept | 3.9841 |

**Theil-Sen Trend Line (Red)**

| | |
|---|---|
| Theil-Sen Slope | 0.0000 |
| Theil-Sen Intercept | 2.1880 |

Statistically significant evidence of a decreasing trend at the specified level of significance.

| | | |
|---|---|---|
| **Mann-Kendall Trend Test Analysis** | | |
| User Selected Options | | |
| Date/Time of Computation | ProUCL 5.13/4/2019 9:26:14 AM | |
| From File | VERT MIG DATA_g.xls | |
| Full Precision | OFF | |
| Confidence Coefficient | 0.95 | |
| Level of Significance | 0.05 | |

**Methylene Chloride-c-702p3**


**General Statistics**

| | |
|---|---|
| Number of Events Reported (m) | 10 |
| Number of Missing Events | 0 |
| Number or Reported Events Used | 10 |
| Number Values Reported (n) | 10 |
| Minimum | 0.16 |
| Maximum | 0.43 |
| Mean | 0.209 |
| Geometric Mean | 0.193 |
| Median | 0.16 |
| Standard Deviation | 0.104 |
| Coefficient of Variation | 0.497 |

**Mann-Kendall Test**

| | |
|---|---|
| M-K Test Value (S) | -15 |
| Tabulated p-value | 0.108 |
| Standard Deviation of S | 7.724 |
| Standardized Value of S | -1.812 |
| Approximate p-value | 0.035 |

**Insufficient evidence to identify a significant trend at the specified level of significance.**




**Mann-Kendall Trend Analysis**

| | |
|---|---|
| n | 10 |
| Confidence Coefficient | 0.9500 |
| Level of Significance | 0.0500 |
| Standard Deviation of S | 7.7244 |
| Standardized Value of S | -1.8124 |
| M-K Test Value (S) | -15 |
| Tabulated p-value | 0.1080 |
| Approximate p-value | 0.0350 |

**OLS Regression Line (Blue)**

| | |
|---|---|
| OLS Regression Slope | 0.0000 |
| OLS Regression Intercept | 1.2705 |

**Theil-Sen Trend Line (Red)**

| | |
|---|---|
| Theil-Sen Slope | 0.0000 |
| Theil-Sen Intercept | 0.1600 |

Insufficient statistical evidence of a significant trend at the specified level of significance.

| | | |
|---|---|---|
| **Mann-Kendall Trend Test Analysis** | | |
| User Selected Options | | |
| Date/Time of Computation | ProUCL 5.13/4/2019 9:24:11 AM | |
| From File | VERT MIG DATA_i.xls | |
| Full Precision | OFF | |
| Confidence Coefficient | 0.95 | |
| Level of Significance | 0.05 | |

**Nitrogen, Nitrate-c-702p3**


**General Statistics**

| | |
|---|---|
| Number of Events Reported (m) | 10 |
| Number of Missing Events | 0 |
| Number or Reported Events Used | 10 |
| Number Values Reported (n) | 10 |
| Minimum | 10 |
| Maximum | 87 |
| Mean | 32.2 |
| Geometric Mean | 26.58 |
| Median | 21 |
| Standard Deviation | 23.64 |
| Coefficient of Variation | 0.734 |

**Mann-Kendall Test**

| | |
|---|---|
| M-K Test Value (S) | 16 |
| Tabulated p-value | 0.078 |
| Standard Deviation of S | 9.832 |
| Standardized Value of S | 1.526 |
| Approximate p-value | 0.0635 |

**Insufficient evidence to identify a significant trend at the specified level of significance.**




**Mann-Kendall Trend Analysis**

| | |
|---|---|
| n | 10 |
| Confidence Coefficient | 0.9500 |
| Level of Significance | 0.0500 |
| Standard Deviation of S | 9.8319 |
| Standardized Value of S | 1.5256 |
| M-K Test Value (S) | 16 |
| Tabulated p-value | 0.0780 |
| Approximate p-value | 0.0635 |

**OLS Regression Line (Blue)**

| | |
|---|---|
| OLS Regression Slope | 0.0113 |
| OLS Regression Intercept | -415.2403 |

**Theil-Sen Trend Line (Red)**

| | |
|---|---|
| Theil-Sen Slope | 0.0040 |
| Theil-Sen Intercept | -136.0017 |

Insufficient statistical evidence of a significant trend at the specified level of significance.

| | | |
|---|---|---|
| **Mann-Kendall Trend Test Analysis** | | |
| User Selected Options | | |
| Date/Time of Computation | ProUCL 5.13/4/2019 9:28:31 AM | |
| From File | VERT MIG DATA_d.xls | |
| Full Precision | OFF | |
| Confidence Coefficient | 0.95 | |
| Level of Significance | 0.05 | |

**Acetone-gw-113**


**General Statistics**

| | |
|---|---|
| Number of Events Reported (m) | 10 |
| Number of Missing Events | 0 |
| Number or Reported Events Used | 10 |
| Number Values Reported (n) | 10 |
| Minimum | 0.95 |
| Maximum | 2.1 |
| Mean | 1.065 |
| Geometric Mean | 1.028 |
| Median | 0.95 |
| Standard Deviation | 0.364 |
| Coefficient of Variation | 0.341 |

**Mann-Kendall Test**

| | |
|---|---|
| M-K Test Value (S) | 3 |
| Tabulated p-value | 0.431 |
| Standard Deviation of S | 5.745 |
| Standardized Value of S | 0.348 |
| Approximate p-value | 0.364 |

**Insufficient evidence to identify a significant trend at the specified level of significance.**




**Mann-Kendall Trend Analysis**

| | |
|---|---|
| n | 10 |
| Confidence Coefficient | 0.9500 |
| Level of Significance | 0.0500 |
| Standard Deviation of S | 5.7446 |
| Standardized Value of S | 0.3482 |
| M-K Test Value (S) | 3 |
| Tabulated p-value | 0.4310 |
| Approximate p-value | 0.3639 |

**OLS Regression Line (Blue)**

| | |
|---|---|
| OLS Regression Slope | 0.0000 |
| OLS Regression Intercept | 2.2844 |

**Theil-Sen Trend Line (Red)**

| | |
|---|---|
| Theil-Sen Slope | 0.0000 |
| Theil-Sen Intercept | 0.9500 |

Insufficient statistical evidence of a significant trend at the specified level of significance.

| | | |
|---|---|---|
| **Mann-Kendall Trend Test Analysis** | | |
| User Selected Options | | |
| Date/Time of Computation | ProUCL 5.13/4/2019 9:23:27 AM | |
| From File | VERT MIG DATA_j.xls | |
| Full Precision | OFF | |
| Confidence Coefficient | 0.95 | |
| Level of Significance | 0.05 | |

**Nitrogen, Nitrite-gw-113**


**General Statistics**

| | |
|---|---|
| Number of Events Reported (m) | 10 |
| Number of Missing Events | 0 |
| Number or Reported Events Used | 10 |
| Number Values Reported (n) | 10 |
| Minimum | 15 |
| Maximum | 50 |
| Mean | 25.15 |
| Geometric Mean | 23.85 |
| Median | 24.5 |
| Standard Deviation | 9.583 |
| Coefficient of Variation | 0.381 |

**Mann-Kendall Test**

| | |
|---|---|
| M-K Test Value (S) | 19 |
| Tabulated p-value | 0.054 |
| Standard Deviation of S | 8.926 |
| Standardized Value of S | 2.017 |
| Approximate p-value | 0.0219 |

**Insufficient evidence to identify a significant trend at the specified level of significance.**




**Mann-Kendall Trend Analysis**

| | |
|---|---|
| n | 10 |
| Confidence Coefficient | 0.9500 |
| Level of Significance | 0.0500 |
| Standard Deviation of S | 8.9256 |
| Standardized Value of S | 2.0167 |
| M-K Test Value (S) | 19 |
| Tabulated p-value | 0.0540 |
| Approximate p-value | 0.0219 |

**OLS Regression Line (Blue)**

| | |
|---|---|
| OLS Regression Slope | 0.0015 |
| OLS Regression Intercept | -36.3034 |

**Theil-Sen Trend Line (Red)**

| | |
|---|---|
| Theil-Sen Slope | 0.0000 |
| Theil-Sen Intercept | 24.5000 |

Insufficient statistical evidence of a significant trend at the specified level of significance.

| | | |
|---|---|---|
| **Mann-Kendall Trend Test Analysis** | | |
| User Selected Options | | |
| Date/Time of Computation | ProUCL 5.13/4/2019 9:24:11 AM | |
| From File | VERT MIG DATA_i.xls | |
| Full Precision | OFF | |
| Confidence Coefficient | 0.95 | |
| Level of Significance | 0.05 | |

**Nitrogen, Nitrate-gw-113**


**General Statistics**

| | |
|---|---|
| Number of Events Reported (m) | 10 |
| Number of Missing Events | 0 |
| Number or Reported Events Used | 10 |
| Number Values Reported (n) | 10 |
| Minimum | 10 |
| Maximum | 270 |
| Mean | 67.2 |
| Geometric Mean | 41.96 |
| Median | 42.5 |
| Standard Deviation | 80.16 |
| Coefficient of Variation | 1.193 |

**Mann-Kendall Test**

| | |
|---|---|
| M-K Test Value (S) | -4 |
| Tabulated p-value | 0.364 |
| Standard Deviation of S | 11.02 |
| Standardized Value of S | -0.272 |
| Approximate p-value | 0.393 |

**Insufficient evidence to identify a significant trend at the specified level of significance.**




**Mann-Kendall Trend Analysis**

| | |
|---|---|
| n | 10 |
| Confidence Coefficient | 0.9500 |
| Level of Significance | 0.0500 |
| Standard Deviation of S | 11.0151 |
| Standardized Value of S | -0.2724 |
| M-K Test Value (S) | -4 |
| Tabulated p-value | 0.3640 |
| Approximate p-value | 0.3927 |

**OLS Regression Line (Blue)**

| | |
|---|---|
| OLS Regression Slope | -0.0106 |
| OLS Regression Intercept | 489.9055 |

**Theil-Sen Trend Line (Red)**

| | |
|---|---|
| Theil-Sen Slope | -0.0064 |
| Theil-Sen Intercept | 291.4982 |

Insufficient statistical evidence of a significant trend at the specified level of significance.

# APPENDIX C-5.3

# VERTICAL MIGRATION ASSESSMENT

## Dixon's Test for Outliers

| | | |
|---|---|---|
| | **Outlier Tests for Selected Variables replacing nondetects with 1/2 the Detection Limit** | |
| **User Selected Options** | | |
| Date/Time of Computation | ProUCL 5.12/19/2021 11:06:07 AM | |
| From File | VERT MIG DATA - B-712-LD ONLY FOR DIXON'S.xls | |
| Full Precision | OFF | |

**Dixon's Outlier Test for 1,4-Dioxane (b-712-ld)**

Total N = 10

Number NDs = 9

Number Detects = 1

Number Data (n) = 10

10% critical value: 0.409

5% critical value: 0.477

1% critical value: 0.597

Note: NDs replaced by DL/2 in Outlier Test

**1. Data Value 0.95 is a Potential Outlier (Upper Tail)?**

Test Statistic: 0.800

For 10% significance level, 0.95 is an outlier.

For 5% significance level, 0.95 is an outlier.

For 1% significance level, 0.95 is an outlier.

**2. Data Value 0.045 is a Potential Outlier (Lower Tail)?**

Test Statistic: 0.146

For 10% significance level, 0.045 is not an outlier.

For 5% significance level, 0.045 is not an outlier.

For 1% significance level, 0.045 is not an outlier.

# APPENDIX C-6

# NORTH END MONITORING AND RESPONSE ACTIONS

# APPENDIX C-6.1

# NORTH END – ALL ORGANICS AND NITRATE DATA

**APPENDIX C-6.1**
**NORTH END - ALL ORGANICS AND NITRATE**
**JULY THROUGH DECEMBER 2021 OPERATIONS AND MAINTENANCE STATUS REPORT**
**LOWRY LANDFILL SUPERFUND SITE**

| Section | Well ID | Parameter Name | Date Sampled | Result (µg/L)[a/] | Qualifier[b/] |
|---|---|---|---|---|---|
| 31 | B-313 | Nitrogen, Nitrate | 8/12/2021 | 55000 | J |
| 31 | B-313 | 1,4-Dioxane | 11/16/2021 | 17 | |
| 31 | B-314 | Nitrogen, Nitrate | 10/27/2021 | 160 | J |
| 31 | B-314 | Nitrogen, Nitrite | 10/27/2021 | 500 | U |
| 31 | B-314 | 1,4-Dioxane | 10/27/2021 | 0.9 | U |
| 31 | B-314 | 1,1,1-Trichloroethane | 10/27/2021 | 1 | U |
| 31 | B-314 | 1,1,2,2-Tetrachloroethane | 10/27/2021 | 1 | U |
| 31 | B-314 | 1,1,2-Trichloroethane | 10/27/2021 | 1 | U |
| 31 | B-314 | 1,1-Dichloroethane | 10/27/2021 | 1.5 | |
| 31 | B-314 | 1,1-Dichloroethene | 10/27/2021 | 1 | U |
| 31 | B-314 | 1,2-Dichloroethane | 10/27/2021 | 1 | U |
| 31 | B-314 | 1,2-Dichloropropane | 10/27/2021 | 1 | U |
| 31 | B-314 | 1,4-Dioxane | 10/27/2021 | 200 | U |
| 31 | B-314 | Acetone | 10/27/2021 | 10 | U |
| 31 | B-314 | Benzene | 10/27/2021 | 1 | U |
| 31 | B-314 | Bromodichloromethane | 10/27/2021 | 1 | U |
| 31 | B-314 | Bromoform | 10/27/2021 | 1 | U |
| 31 | B-314 | Carbon Tetrachloride | 10/27/2021 | 1 | U |
| 31 | B-314 | Chlorobenzene | 10/27/2021 | 1 | U |
| 31 | B-314 | Chloroform | 10/27/2021 | 1 | U |
| 31 | B-314 | cis-1,2-Dichloroethene | 10/27/2021 | 1 | U |
| 31 | B-314 | Dibromochloromethane | 10/27/2021 | 1 | U |
| 31 | B-314 | Ethylbenzene | 10/27/2021 | 1 | U |
| 31 | B-314 | Methylene Chloride | 10/27/2021 | 1 | U |
| 31 | B-314 | Naphthalene | 10/27/2021 | 1 | U |
| 31 | B-314 | Tetrachloroethene | 10/27/2021 | 1 | U |
| 31 | B-314 | Toluene | 10/27/2021 | 1 | U |
| 31 | B-314 | Trans-1,2-Dichloroethene | 10/27/2021 | 0.5 | U |
| 31 | B-314 | Trichloroethene | 10/27/2021 | 1 | U |
| 31 | B-314 | Vinyl Chloride | 10/27/2021 | 2 | U |
| 31 | B-321 | Nitrogen, Nitrate | 8/11/2021 | 43000 | |
| 31 | B-321 | 1,4-Dioxane | 8/30/2021 | 9.7 | |
| 31 | B-326-UD | 1,4-Dioxane | 8/30/2021 | 6.1 | |
| 31 | B-326-UD | 1,4-Dioxane | 10/12/2021 | 5 | |
| 31 | B-326-WD | Nitrogen, Nitrate | 10/12/2021 | 9900 | |
| 31 | B-326-WD | Nitrogen, Nitrite | 10/12/2021 | 150 | J- |
| 31 | B-326-WD | 1,4-Dioxane | 8/30/2021 | 0.77 | J |
| 31 | B-326-WD | 1,4-Dioxane | 9/27/2021 | 0.69 | J |
| 31 | B-326-WD | 1,4-Dioxane | 10/12/2021 | 1 | |
| 31 | B-326-WD | 1,1,1-Trichloroethane | 10/12/2021 | 1 | U |
| 31 | B-326-WD | 1,1,2,2-Tetrachloroethane | 10/12/2021 | 1 | U |
| 31 | B-326-WD | 1,1,2-Trichloroethane | 10/12/2021 | 1 | U |
| 31 | B-326-WD | 1,1-Dichloroethane | 10/12/2021 | 1 | U |
| 31 | B-326-WD | 1,1-Dichloroethene | 10/12/2021 | 1 | U |
| 31 | B-326-WD | 1,2-Dichloroethane | 10/12/2021 | 1 | U |
| 31 | B-326-WD | 1,2-Dichloropropane | 10/12/2021 | 1 | U |
| 31 | B-326-WD | 1,4-Dioxane | 10/12/2021 | 200 | U |
| 31 | B-326-WD | Acetone | 10/12/2021 | 10 | U |
| 31 | B-326-WD | Benzene | 10/12/2021 | 1 | U |
| 31 | B-326-WD | Bromodichloromethane | 10/12/2021 | 1 | U |
| 31 | B-326-WD | Bromoform | 10/12/2021 | 1 | U |
| 31 | B-326-WD | Carbon Tetrachloride | 10/12/2021 | 1 | U |
| 31 | B-326-WD | Chlorobenzene | 10/12/2021 | 1 | U |
| 31 | B-326-WD | Chloroform | 10/12/2021 | 1 | U |
| 31 | B-326-WD | cis-1,2-Dichloroethene | 10/12/2021 | 1 | U |

**APPENDIX C-6.1**
**NORTH END - ALL ORGANICS AND NITRATE**
**JULY THROUGH DECEMBER 2021 OPERATIONS AND MAINTENANCE STATUS REPORT**
**LOWRY LANDFILL SUPERFUND SITE**

| Section | Well ID | Parameter Name | Date Sampled | Result (µg/L)[a/] | Qualifier[b/] |
|---|---|---|---|---|---|
| 31 | B-326-WD | Dibromochloromethane | 10/12/2021 | 1 | U |
| 31 | B-326-WD | Ethylbenzene | 10/12/2021 | 1 | U |
| 31 | B-326-WD | Methylene Chloride | 10/12/2021 | 1 | U |
| 31 | B-326-WD | Naphthalene | 10/12/2021 | 1 | U |
| 31 | B-326-WD | Tetrachloroethene | 10/12/2021 | 1 | U |
| 31 | B-326-WD | Toluene | 10/12/2021 | 1 | U |
| 31 | B-326-WD | Trans-1,2-Dichloroethene | 10/12/2021 | 0.5 | U |
| 31 | B-326-WD | Trichloroethene | 10/12/2021 | 1 | U |
| 31 | B-326-WD | Vinyl Chloride | 10/12/2021 | 2 | U |
| 31 | MW05-WD | 1,4-Dioxane | 8/18/2021 | 4.4 | |
| 31 | MW113-EW-1 | Nitrogen, Nitrate | 7/29/2021 | 1100 | |
| 31 | MW113-EW-1 | Nitrogen, Nitrate | 10/19/2021 | 2000 | |
| 31 | MW113-EW-1 | 1,4-Dioxane | 7/29/2021 | 92 | |
| 31 | MW113-EW-1 | 1,4-Dioxane | 10/19/2021 | 120 | |
| 31 | MW113-UD | 1,4-Dioxane | 7/29/2021 | 120 | |
| 31 | MW113-UD | 1,4-Dioxane | 10/19/2021 | 94 | |
| 31 | MW114-WD | 1,4-Dioxane | 8/5/2021 | 0.93 | |
| 31 | MW114-WD | 1,4-Dioxane | 11/17/2021 | 0.96 | |
| 31 | MW117-WD | 1,4-Dioxane | 8/5/2021 | 1.8 | |
| 31 | MW117-WD | 1,4-Dioxane | 11/17/2021 | 1.5 | |
| 31 | MW118-WD | 1,4-Dioxane | 8/9/2021 | 0.28 | J |
| 31 | MW118-WD | 1,4-Dioxane | 11/17/2021 | 0.26 | J |
| 31 | MW121-WDR | 1,4-Dioxane | 8/18/2021 | 2 | |
| 31 | MW122-WDR | 1,4-Dioxane | 8/18/2021 | 2 | |
| 31 | MW123-WD | 1,4-Dioxane | 8/18/2021 | 1.5 | |
| 31 | MW124-WD | 1,4-Dioxane | 8/18/2021 | 0.49 | J |
| 31 | MW125-WD | 1,4-Dioxane | 8/30/2021 | 0.41 | J |
| 31 | MW129-WD | 1,4-Dioxane | 9/7/2021 | 5.3 | |
| 31 | MW132-WD | 1,4-Dioxane | 7/21/2021 | 11 | |
| 31 | MW132-WD | 1,4-Dioxane | 11/2/2021 | 14 | |
| 30 | MW135-WD | 1,4-Dioxane | 7/28/2021 | 4.5 | |
| 30 | MW141-WD | 1,4-Dioxane | 7/28/2021 | 2.3 | |
| 19 | MW142-WD | 1,4-Dioxane | 7/28/2021 | 1.7 | |
| 24 | MW144-WD | 1,4-Dioxane | 8/4/2021 | 0.9 | U |
| 31 | MW151-WD | 1,4-Dioxane | 7/19/2021 | 1.7 | |
| 31 | MW151-WD | 1,4-Dioxane | 11/11/2021 | 5.1 | |
| 31 | MW153-EW-1 | 1,4-Dioxane | 7/21/2021 | 1.5 | |
| 31 | MW153-EW-1 | 1,4-Dioxane | 11/8/2021 | 2 | |
| 31 | MW154-EW-1 | 1,4-Dioxane | 7/21/2021 | 1.2 | |
| 31 | MW154-EW-1 | 1,4-Dioxane | 11/11/2021 | 0.63 | J |
| 31 | MW155-EW-1 | 1,4-Dioxane | 7/21/2021 | 1.1 | |
| 31 | MW155-EW-1 | 1,4-Dioxane | 11/22/2021 | 0.27 | J |
| 31 | MW156-EW-1 | 1,4-Dioxane | 7/21/2021 | 1.1 | |
| 31 | MW156-EW-1 | 1,4-Dioxane | 11/22/2021 | 0.48 | J |
| 31 | MW156-WD | 1,4-Dioxane | 7/19/2021 | 0.88 | J |
| 31 | MW156-WD | 1,4-Dioxane | 11/11/2021 | 0.25 | J |
| 31 | MW157-WD | 1,4-Dioxane | 7/19/2021 | 0.19 | J |
| 31 | MW157-WD | 1,4-Dioxane | 11/11/2021 | 0.1 | J |
| 31 | MW160-WD | 1,4-Dioxane | 7/19/2021 | 2.3 | |
| 31 | MW160-WD | 1,4-Dioxane | 11/8/2021 | 3.3 | |
| 13 | MW176-DEN | 1,4-Dioxane | 8/4/2021 | 0.49 | J |
| 31 | MW179-UDEN | 1,4-Dioxane | 9/8/2021 | 0.9 | U |
| 31 | NBBW-IW-3 | 1,4-Dioxane | 8/5/2021 | 140 | |
| 31 | PTP-12 | 1,4-Dioxane | 11/4/2021 | 9.1 | |
| 31 | PTP-13 | 1,4-Dioxane | 8/25/2021 | 4.8 | |

**APPENDIX C-6.1**
**NORTH END - ALL ORGANICS AND NITRATE**
**JULY THROUGH DECEMBER 2021 OPERATIONS AND MAINTENANCE STATUS REPORT**
**LOWRY LANDFILL SUPERFUND SITE**

| Section | Well ID | Parameter Name | Date Sampled | Result (µg/L)[a/] | Qualifier[b/] |
|---|---|---|---|---|---|
| 31 | PTP-13 | 1,4-Dioxane | 11/10/2021 | 6.9 | |

a/ µg/L = micrograms per liter

b/ Final Q definitions:

**Qualifiers:** U= The analyte was analyzed for and is not present above the level of the associated value.

UJ-= Same as UJ qualification but with an indication of negative bias in the sample concentration.

UJ+= Same as UJ qualification but with an indication of positive bias in the sample concentration.

UJ= The analyte analyzed for was not present above the level of the associated value. The associated

J= The analyte was analyzed for, and was positively identified, but the associated numerical value

The associated numerical value indicates the approximate concentration necessary to detect the analyte in the sample.

J-= Same as J qualification but with an indication of negative bias in the sample concentration.

J+= Same as J qualification but with an indication of positive bias in the sample concentration.

# APPENDIX C-6.2

# MW77 AREA – ALL ORGANICS AND NITRATE DATA

# TABLE C-6.2
## MW77 AREA - ALL ORGANICS AND NITRATE
### JULY THROUGH DECEMBER 2021 OPERATIONS AND MAINTENANCE STATUS REPORT
### LOWRY LANDFILL SUPERFUND SITE

| Section | Well ID | Parameter Name | Date Sampled | Result (ug/L)[a/] | Qualifier[b/] |
|---|---|---|---|---|---|
| 31 | MW102-WD | 1,4-Dioxane | 8/31/2021 | 1.7 | |
| 31 | MW102-WD | 1,4-Dioxane | 11/18/2021 | 1.1 | |
| 31 | MW103-WD | 1,4-Dioxane | 8/5/2021 | 0.45 | J |
| 31 | MW103-WD | 1,4-Dioxane | 11/2/2021 | 0.41 | J |
| 31 | MW170-EW-1 | 1,1,1-Trichloroethane | 8/9/2021 | 1.8 | |
| 31 | MW170-EW-1 | 1,1,1-Trichloroethane | 10/27/2021 | 2 | |
| 31 | MW170-EW-1 | 1,1,2,2-Tetrachloroethane | 8/9/2021 | 1 | U |
| 31 | MW170-EW-1 | 1,1,2,2-Tetrachloroethane | 10/27/2021 | 1 | U |
| 31 | MW170-EW-1 | 1,1,2-Trichloroethane | 8/9/2021 | 1 | U |
| 31 | MW170-EW-1 | 1,1,2-Trichloroethane | 10/27/2021 | 1 | U |
| 31 | MW170-EW-1 | 1,1-Dichloroethane | 8/9/2021 | 4 | |
| 31 | MW170-EW-1 | 1,1-Dichloroethane | 10/27/2021 | 4.6 | |
| 31 | MW170-EW-1 | 1,1-Dichloroethene | 8/9/2021 | 2.8 | |
| 31 | MW170-EW-1 | 1,1-Dichloroethene | 10/27/2021 | 3.4 | |
| 31 | MW170-EW-1 | 1,2-Dichloroethane | 8/9/2021 | 1 | U |
| 31 | MW170-EW-1 | 1,2-Dichloroethane | 10/27/2021 | 1 | U |
| 31 | MW170-EW-1 | 1,2-Dichloropropane | 8/9/2021 | 1 | U |
| 31 | MW170-EW-1 | 1,2-Dichloropropane | 10/27/2021 | 1 | U |
| 31 | MW170-EW-1 | 1,4-Dioxane | 8/9/2021 | 14 | |
| 31 | MW170-EW-1 | 1,4-Dioxane | 8/9/2021 | 200 | U |
| 31 | MW170-EW-1 | 1,4-Dioxane | 10/27/2021 | 12 | |
| 31 | MW170-EW-1 | 1,4-Dioxane | 10/27/2021 | 200 | U |
| 31 | MW170-EW-1 | Acetone | 8/9/2021 | 10 | U |
| 31 | MW170-EW-1 | Acetone | 10/27/2021 | 10 | U |
| 31 | MW170-EW-1 | Benzene | 8/9/2021 | 1 | U |
| 31 | MW170-EW-1 | Benzene | 10/27/2021 | 1 | U |
| 31 | MW170-EW-1 | Bromodichloromethane | 8/9/2021 | 1 | U |
| 31 | MW170-EW-1 | Bromodichloromethane | 10/27/2021 | 1 | U |
| 31 | MW170-EW-1 | Bromoform | 8/9/2021 | 1 | U |
| 31 | MW170-EW-1 | Bromoform | 10/27/2021 | 1 | U |
| 31 | MW170-EW-1 | Carbon Tetrachloride | 8/9/2021 | 1 | U |
| 31 | MW170-EW-1 | Carbon Tetrachloride | 10/27/2021 | 1 | U |
| 31 | MW170-EW-1 | Chlorobenzene | 8/9/2021 | 1 | U |
| 31 | MW170-EW-1 | Chlorobenzene | 10/27/2021 | 1 | U |
| 31 | MW170-EW-1 | Chloroform | 8/9/2021 | 1 | U |
| 31 | MW170-EW-1 | Chloroform | 10/27/2021 | 1 | U |
| 31 | MW170-EW-1 | cis-1,2-Dichloroethene | 8/9/2021 | 9.5 | |
| 31 | MW170-EW-1 | cis-1,2-Dichloroethene | 10/27/2021 | 11 | |
| 31 | MW170-EW-1 | Dibromochloromethane | 8/9/2021 | 1 | U |
| 31 | MW170-EW-1 | Dibromochloromethane | 10/27/2021 | 1 | U |
| 31 | MW170-EW-1 | Ethylbenzene | 8/9/2021 | 1 | U |
| 31 | MW170-EW-1 | Ethylbenzene | 10/27/2021 | 1 | U |
| 31 | MW170-EW-1 | Methylene Chloride | 8/9/2021 | 1 | U |
| 31 | MW170-EW-1 | Methylene Chloride | 10/27/2021 | 1 | U |
| 31 | MW170-EW-1 | Naphthalene | 8/9/2021 | 1 | U |
| 31 | MW170-EW-1 | Naphthalene | 10/27/2021 | 1 | U |
| 31 | MW170-EW-1 | Nitrogen, Nitrate | 8/9/2021 | 9800 | |
| 31 | MW170-EW-1 | Nitrogen, Nitrate | 10/27/2021 | 9900 | |
| 31 | MW170-EW-1 | Tetrachloroethene | 8/9/2021 | 1 | |
| 31 | MW170-EW-1 | Tetrachloroethene | 10/27/2021 | 0.93 | J |
| 31 | MW170-EW-1 | Toluene | 8/9/2021 | 1 | U |

# TABLE C-6.2
## MW77 AREA - ALL ORGANICS AND NITRATE
### JULY THROUGH DECEMBER 2021 OPERATIONS AND MAINTENANCE STATUS REPORT
### LOWRY LANDFILL SUPERFUND SITE

| Section | Well ID | Parameter Name | Date Sampled | Result (ug/L)[a/] | Qualifier[b/] |
|---|---|---|---|---|---|
| 31 | MW170-EW-1 | Toluene | 10/27/2021 | 1 | U |
| 31 | MW170-EW-1 | Trans-1,2-Dichloroethene | 8/9/2021 | 0.5 | U |
| 31 | MW170-EW-1 | Trans-1,2-Dichloroethene | 10/27/2021 | 0.5 | U |
| 31 | MW170-EW-1 | Trichloroethene | 8/9/2021 | 0.45 | J |
| 31 | MW170-EW-1 | Trichloroethene | 10/27/2021 | 0.33 | J |
| 31 | MW170-EW-1 | Vinyl Chloride | 8/9/2021 | 2 | U |
| 31 | MW170-EW-1 | Vinyl Chloride | 10/27/2021 | 2 | U |
| 31 | MW23-UPPER-C | 1,1,1-Trichloroethane | 10/18/2021 | 1 | U |
| 31 | MW23-UPPER-C | 1,1,2,2-Tetrachloroethane | 10/18/2021 | 1 | U |
| 31 | MW23-UPPER-C | 1,1,2-Trichloroethane | 10/18/2021 | 1 | U |
| 31 | MW23-UPPER-C | 1,1-Dichloroethane | 10/18/2021 | 1 | U |
| 31 | MW23-UPPER-C | 1,1-Dichloroethene | 10/18/2021 | 1 | U |
| 31 | MW23-UPPER-C | 1,2-Dichloroethane | 10/18/2021 | 1 | U |
| 31 | MW23-UPPER-C | 1,2-Dichloropropane | 10/18/2021 | 1 | U |
| 31 | MW23-UPPER-C | 1,4-Dioxane | 10/18/2021 | 0.9 | U |
| 31 | MW23-UPPER-C | 1,4-Dioxane | 10/18/2021 | 200 | U |
| 31 | MW23-UPPER-C | Acetone | 10/18/2021 | 10 | U |
| 31 | MW23-UPPER-C | Benzene | 10/18/2021 | 1 | U |
| 31 | MW23-UPPER-C | Bromodichloromethane | 10/18/2021 | 1 | U |
| 31 | MW23-UPPER-C | Bromoform | 10/18/2021 | 1 | U |
| 31 | MW23-UPPER-C | Carbon Tetrachloride | 10/18/2021 | 1 | U |
| 31 | MW23-UPPER-C | Chlorobenzene | 10/18/2021 | 1 | U |
| 31 | MW23-UPPER-C | Chloroform | 10/18/2021 | 1 | U |
| 31 | MW23-UPPER-C | cis-1,2-Dichloroethene | 10/18/2021 | 1 | U |
| 31 | MW23-UPPER-C | Dibromochloromethane | 10/18/2021 | 1 | U |
| 31 | MW23-UPPER-C | Ethylbenzene | 10/18/2021 | 1 | U |
| 31 | MW23-UPPER-C | Methylene Chloride | 10/18/2021 | 1 | U |
| 31 | MW23-UPPER-C | Naphthalene | 10/18/2021 | 1 | U |
| 31 | MW23-UPPER-C | Nitrogen, Nitrate | 10/18/2021 | 100 | J |
| 31 | MW23-UPPER-C | Nitrogen, Nitrite | 10/18/2021 | 500 | U |
| 31 | MW23-UPPER-C | Tetrachloroethene | 10/18/2021 | 1 | U |
| 31 | MW23-UPPER-C | Toluene | 10/18/2021 | 1 | U |
| 31 | MW23-UPPER-C | Trans-1,2-Dichloroethene | 10/18/2021 | 0.5 | U |
| 31 | MW23-UPPER-C | Trichloroethene | 10/18/2021 | 1 | U |
| 31 | MW23-UPPER-C | Vinyl Chloride | 10/18/2021 | 2 | U |
| 31 | MW77-EW-1 | 1,4-Dioxane | 8/31/2021 | 3.7 | |
| 31 | MW77-EW-1 | 1,4-Dioxane | 11/18/2021 | 3 | |
| 31 | MW77-EW-2 | 1,4-Dioxane | 9/1/2021 | 0.12 | R |
| 31 | MW77-EW-2 | 1,4-Dioxane | 9/14/2021 | 0.13 | J |
| 31 | MW77-EW-2 | 1,4-Dioxane | 11/18/2021 | 0.12 | J |
| 31 | MW77-WD | 1,1,1-Trichloroethane | 10/27/2021 | 1 | U |
| 31 | MW77-WD | 1,1,2,2-Tetrachloroethane | 10/27/2021 | 1 | U |
| 31 | MW77-WD | 1,1,2-Trichloroethane | 10/27/2021 | 1 | U |
| 31 | MW77-WD | 1,1-Dichloroethane | 10/27/2021 | 0.99 | J |
| 31 | MW77-WD | 1,1-Dichloroethene | 10/27/2021 | 1.7 | |
| 31 | MW77-WD | 1,2-Dichloroethane | 10/27/2021 | 1 | U |
| 31 | MW77-WD | 1,2-Dichloropropane | 10/27/2021 | 1 | U |
| 31 | MW77-WD | 1,4-Dioxane | 10/27/2021 | 11 | |
| 31 | MW77-WD | 1,4-Dioxane | 10/27/2021 | 200 | U |
| 31 | MW77-WD | Acetone | 10/27/2021 | 10 | U |
| 31 | MW77-WD | Benzene | 10/27/2021 | 1 | U |

# TABLE C-6.2
## MW77 AREA - ALL ORGANICS AND NITRATE
### JULY THROUGH DECEMBER 2021 OPERATIONS AND MAINTENANCE STATUS REPORT
### LOWRY LANDFILL SUPERFUND SITE

| Section | Well ID | Parameter Name | Date Sampled | Result (ug/L)[a/] | Qualifier[b/] |
|---|---|---|---|---|---|
| 31 | MW77-WD | Bromodichloromethane | 10/27/2021 | 1 | U |
| 31 | MW77-WD | Bromoform | 10/27/2021 | 1 | U |
| 31 | MW77-WD | Carbon Tetrachloride | 10/27/2021 | 1 | U |
| 31 | MW77-WD | Chlorobenzene | 10/27/2021 | 1 | U |
| 31 | MW77-WD | Chloroform | 10/27/2021 | 1 | U |
| 31 | MW77-WD | cis-1,2-Dichloroethene | 10/27/2021 | 1 | U |
| 31 | MW77-WD | Dibromochloromethane | 10/27/2021 | 1 | U |
| 31 | MW77-WD | Ethylbenzene | 10/27/2021 | 1 | U |
| 31 | MW77-WD | Methylene Chloride | 10/27/2021 | 1 | U |
| 31 | MW77-WD | Naphthalene | 10/27/2021 | 1 | U |
| 31 | MW77-WD | Nitrogen, Nitrate | 10/27/2021 | 12000 | |
| 31 | MW77-WD | Nitrogen, Nitrite | 10/27/2021 | 500 | U |
| 31 | MW77-WD | Tetrachloroethene | 10/27/2021 | 1.1 | |
| 31 | MW77-WD | Toluene | 10/27/2021 | 1 | U |
| 31 | MW77-WD | Trans-1,2-Dichloroethene | 10/27/2021 | 0.5 | U |
| 31 | MW77-WD | Trichloroethene | 10/27/2021 | 1 | U |
| 31 | MW77-WD | Vinyl Chloride | 10/27/2021 | 2 | U |
| 31 | MW98-WD | 1,4-Dioxane | 8/31/2021 | 11 | |
| 31 | MW98-WD | 1,4-Dioxane | 11/18/2021 | 11 | |

a/ ug/L = micrograms per liter

b/ Qualifiers:

U= The analyte was analyzed for and is not present above the level of the associated value. The associated numerical value indicates the approximate concentration necessary to detect the analyte in the sample.

UJ= The analyte analyzed for was not present above the level of the associated value. The associated numerical value may not accurately represent the concentration necessary to detect the analyte in the sample.

UJ-= Same as UJ qualification but with an indication of negative bias in the sample concentration.

UJ+= Same as UJ qualification but with an indication of positive bias in the sample concentration.

J-= Same as J qualification but with an indication of negative bias in the sample concentration.

J+= Same as J qualification but with an indication of positive bias in the sample concentration.

J= The analyte was analyzed for, and was positively identified, but the associated numerical value may not be consistent with the amount actually present in the environmental sample.

# APPENDIX D

# LANDFILL GAS

# APPENDIX D-1

# LFG QUALITY AND EXTRACTION WELL PRESSURES

**APPENDIX D-1**
**LANDFILL GAS EXTRACTION WELL MONITORING**
**JULY THROUGH DECEMBER 2021 OPERATIONS AND MAINTENANCE REPORT**
**LOWRY LANDFILL SUPERFUND SITE**

| ID | Date/Time | Methane (%)[a/] | Carbon Dioxide (%) | Oxygen (%) | Balance (%) | Initial Temperature (°F)[b/] | Initial Static Pressure ("$H_2O$)[c/] | Adjusted Static Pressure ("$H_2O$) | Header Pressure ("$H_2O$) | Initial Flow (scfm)[d/] | Barometric Pressure ("Hg)[e/] | Comments |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| LOWEW30A | 7/20/21 9:44 | 42.1 | 29.2 | 0.5 | 28.2 | 82.1 | -0.12 | -0.1 | 0.086 | 6.5 | 24.43 | No Adj. Made |
| LOWEW30A | 8/31/21 7:51 | 47.4 | 33 | 0.2 | 19.4 | 78.9 | -0.34 | -0.34 | 0.132 | 8.2 | 24.04 | No Adj. Made |
| LOWEW30A | 9/14/21 9:36 | 49.7 | 33.9 | 0.1 | 16.3 | 78.5 | -0.26 | -0.26 | 0.157 | 9 | 24.3 | No Adj. Made |
| LOWEW30A | 10/31/21 10:05 | 56.7 | 34 | 0 | 9.3 | 74.3 | -0.37 | -0.37 | 0.036 | 4.4 | 24.39 | No Adj. Made |
| LOWEW30A | 11/18/21 9:16 | 59.2 | 36.4 | 0.3 | 4.1 | 77.1 | -0.07 | -0.11 | 0.034 | 4.3 | 24.44 | Inc. Flow/Vac. |
| LOWEW30A | 12/20/21 10:36 | 41.5 | 32.7 | 0.4 | 25.4 | 77.1 | -0.45 | -0.45 | 0.15 | 8.7 | 24.3 | No Adj. Made |
| LOWEW34A | 7/20/21 10:06 | 35.8 | 25.2 | 1.3 | 37.7 | 79.7 | -5.99 | -5.95 | 0.368 | 8 | 24.42 | No Adj. Made |
| LOWEW34A | 8/31/21 8:10 | 33.4 | 28 | 0.2 | 38.4 | 71.6 | -7.66 | -7.66 | 0.413 | 8.5 | 24.17 | No Adj. Made |
| LOWEW34A | 9/14/21 9:55 | 34.4 | 28.4 | 0.2 | 37 | 70 | -7.49 | -7.5 | 0.439 | 8.9 | 24.3 | No Adj. Made |
| LOWEW34A | 10/31/21 10:34 | 38.4 | 29 | 0.1 | 32.5 | 64.9 | -4.11 | -4.06 | 0.399 | 8.6 | 24.39 | No Adj. Made |
| LOWEW34A | 11/18/21 9:57 | 38.5 | 29.9 | 0.9 | 30.7 | 68.1 | -5.85 | -4.66 | 0.505 | 9.6 | 24.43 | Dec. Flow/Vac. |
| LOWEW34A | 12/21/21 9:13 | 38 | 28.5 | 0.5 | 33 | 60 | -2.28 | -2.3 | 0.068 | 3.6 | 24.2 | No Adj. Made |
| LOWEW40A | 7/19/21 10:31 | 43.9 | 33.4 | 0.8 | 21.9 | 84.2 | -1.07 | -1.06 | 2.972 | 5.5 | 24.53 | No Adj. Made |
| LOWEW40A | 8/30/21 9:49 | 41.5 | 34.4 | 0 | 24.1 | 82.4 | -1.64 | -0.13 | 0.756 | 2.7 | 24.26 | No Adj. Made |
| LOWEW40A | 9/13/21 10:06 | 43.3 | 36.6 | 0 | 20.1 | 73.6 | -1.39 | -1.38 | 1.968 | 4.5 | 24.33 | No Adj. Made |
| LOWEW40A | 10/31/21 9:01 | 48 | 37 | 0.2 | 14.8 | 54.7 | -1.29 | -1.29 | 0.957 | 3.2 | 24.4 | No Adj. Made |
| LOWEW40A | 11/17/21 9:57 | 47.3 | 40 | 0 | 12.7 | 48.4 | -2.33 | -2.32 | 1.305 | 3.7 | 24.41 | No Adj. Made |
| LOWEW40A | 12/20/21 9:43 | 46.9 | 37.1 | 0.2 | 15.8 | 55.2 | -1.04 | -1.03 | 0.743 | 2.8 | 24.31 | No Adj. Made |
| LOWREW01 | 7/20/21 11:17 | 12.7 | 24.5 | 0.4 | 62.4 | 94.9 | -0.01 | -0.01 | 0.655 | 1.6 | 24.44 | No Adj. Made |
| LOWREW01 | 8/31/21 9:14 | 12.3 | 25.3 | 0 | 62.4 | 82 | -0.19 | -0.18 | 0.728 | 1.7 | 24.2 | No Adj. Made |
| LOWREW01 | 9/14/21 10:59 | 13.1 | 26.3 | 0 | 60.6 | 77.9 | -0.09 | -0.08 | 0.843 | 1.8 | 24.33 | No Adj. Made |
| LOWREW01 | 10/31/21 12:01 | 15.4 | 27.8 | 0 | 56.8 | 54.8 | -0.05 | -0.05 | 0.446 | 1.3 | 24.41 | No Adj. Made |
| LOWREW01 | 11/19/21 10:20 | 17.1 | 29.3 | 0.4 | 53.2 | 68.1 | -0.1 | -0.09 | 1.318 | 2.3 | 24.24 | No Adj. Made |
| LOWREW01 | 12/21/21 10:07 | 13.4 | 28 | 0.3 | 58.3 | 61.9 | -0.33 | -0.33 | 0.875 | 1.9 | 24.22 | No Adj. Made |
| LOWREW02 | 7/20/21 11:15 | 6.2 | 22.9 | 0.5 | 70.4 | 92 | -0.12 | -0.11 | 1.129 | 2.1 | 24.44 | No Adj. Made |
| LOWREW02 | 8/31/21 9:11 | 5.5 | 23.8 | 0.5 | 70.2 | 82.9 | -0.08 | -0.09 | 1.439 | 2.3 | 24.2 | No Adj. Made |
| LOWREW02 | 9/14/21 10:56 | 7.3 | 24.3 | 0.2 | 68.2 | 77.7 | -0.07 | -0.07 | 1.322 | 2.2 | 24.33 | No Adj. Made |
| LOWREW02 | 10/31/21 11:58 | 8 | 25.3 | 0.1 | 66.6 | 60.7 | -0.07 | -0.06 | 0.4 | 1.3 | 24.41 | No Adj. Made |
| LOWREW02 | 11/19/21 10:13 | 8.1 | 26.6 | 0.5 | 64.8 | 73.7 | -0.06 | -0.03 | 0.902 | 1.9 | 24.23 | No Adj. Made |
| LOWREW02 | 12/21/21 10:05 | 5.1 | 24.4 | 0.7 | 69.8 | 64.8 | -0.22 | -0.22 | 0.436 | 1.3 | 24.22 | No Adj. Made |
| LOWREW03 | 7/20/21 11:12 | 21.1 | 28.1 | 0.4 | 50.4 | 94.5 | -0.07 | -0.07 | 0.211 | 0.9 | 24.44 | No Adj. Made |
| LOWREW03 | 8/31/21 9:09 | 21.8 | 28.5 | 0 | 49.7 | 82.3 | -0.2 | -0.17 | 0.397 | 1.3 | 24.2 | No Adj. Made |
| LOWREW03 | 9/14/21 10:54 | 21.6 | 28.8 | 0.1 | 49.5 | 77.9 | -0.12 | -0.11 | 0.301 | 1.1 | 24.32 | No Adj. Made |
| LOWREW03 | 10/31/21 11:54 | 24.3 | 31.1 | 0 | 44.6 | 57.6 | -0.03 | -0.01 | 0.365 | 1.2 | 24.39 | No Adj. Made |
| LOWREW03 | 11/19/21 10:05 | 26.5 | 33 | 0 | 40.5 | 65.4 | -0.02 | -0.01 | 2.128 | 2.9 | 24.23 | No Adj. Made |
| LOWREW03 | 12/21/21 10:02 | 20 | 29 | 0.5 | 50.5 | 61.2 | -3 | -0.24 | 0.655 | 1.6 | 24.22 | No Adj. Made |
| LOWREW04 | 7/20/21 11:10 | 16.5 | 27.5 | 0.4 | 55.6 | 93.4 | -0.02 | -0.01 | 0.567 | 1.5 | 24.43 | No Adj. Made |

**APPENDIX D-1**
**LANDFILL GAS EXTRACTION WELL MONITORING**
**JULY THROUGH DECEMBER 2021 OPERATIONS AND MAINTENANCE REPORT**
**LOWRY LANDFILL SUPERFUND SITE**

| ID | Date/Time | Methane (%)[a/] | Carbon Dioxide (%) | Oxygen (%) | Balance (%) | Initial Temperature (°F)[b/] | Initial Static Pressure ("$H_2O$)[c/] | Adjusted Static Pressure ("$H_2O$) | Header Pressure ("$H_2O$) | Initial Flow (scfm)[d/] | Barometric Pressure ("Hg)[e/] | Comments |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| LOWREW04 | 8/31/21 9:06 | 15 | 25.7 | 0 | 59.3 | 82.3 | -0.14 | -0.14 | 0.823 | 1.8 | 24.2 | No Adj. Made |
| LOWREW04 | 9/14/21 10:52 | 15.6 | 27 | 0 | 57.4 | 78.2 | -0.04 | -0.03 | 0.809 | 1.8 | 24.31 | No Adj. Made |
| LOWREW04 | 10/31/21 11:49 | 14 | 26.8 | 0.1 | 59.1 | 54.5 | -0.04 | -0.04 | 0.549 | 1.5 | 24.4 | No Adj. Made |
| LOWREW04 | 11/19/21 9:55 | 16.3 | 29.9 | 0.4 | 53.4 | 75.9 | -0.02 | -0.01 | 0.538 | 1.4 | 24.24 | No Adj. Made |
| LOWREW04 | 12/21/21 10:00 | 12.7 | 27.4 | 0.3 | 59.6 | 54.7 | -0.36 | -0.35 | 0.444 | 1.3 | 24.22 | No Adj. Made |
| LOWREW05 | 7/20/21 11:04 | 21.3 | 25.6 | 0.5 | 52.6 | 93.5 | -0.1 | -0.1 | 0.448 | 1.3 | 24.44 | No Adj. Made |
| LOWREW05 | 8/31/21 9:01 | 25.8 | 29.7 | 0 | 44.5 | 81.2 | -0.15 | -0.15 | 0.696 | 1.7 | 24.19 | No Adj. Made |
| LOWREW05 | 9/14/21 10:47 | 23.3 | 28.9 | 0 | 47.8 | 77.1 | -0.07 | -0.07 | 0.684 | 1.7 | 24.32 | No Adj. Made |
| LOWREW05 | 10/31/21 11:43 | 22 | 28.2 | 0 | 49.8 | 57.1 | -0.02 | -0.02 | 0.429 | 1.3 | 24.39 | No Adj. Made |
| LOWREW05 | 11/19/21 9:44 | 27.3 | 32.1 | 0 | 40.6 | 71.5 | -0.04 | -0.02 | 0.113 | 0.7 | 24.24 | Inc. Flow/Vac. |
| LOWREW05 | 12/21/21 9:56 | 21.3 | 29.3 | 0.3 | 49.1 | 58.6 | -0.44 | -0.44 | 1.432 | 2.4 | 24.22 | No Adj. Made |
| LOWREW06 | 7/20/21 11:02 | 9.4 | 21.7 | 0.5 | 68.4 | 91.5 | -0.06 | -0.05 | 0.977 | 1.9 | 24.43 | No Adj. Made |
| LOWREW06 | 8/31/21 8:57 | 9.7 | 24.2 | 0 | 66.1 | 80.4 | -0.17 | -0.16 | 1.279 | 2.2 | 24.22 | No Adj. Made |
| LOWREW06 | 9/14/21 10:44 | 11.7 | 25 | 0 | 63.3 | 78.2 | -0.02 | -0.02 | 1.276 | 2.2 | 24.31 | No Adj. Made |
| LOWREW06 | 10/31/21 11:38 | 10.4 | 24.6 | 0 | 65 | 54.7 | -0.02 | -0.01 | 0.535 | 1.5 | 24.39 | No Adj. Made |
| LOWREW06 | 11/19/21 9:28 | 12.3 | 26.8 | 0.7 | 60.2 | 71.1 | -0.04 | -0.04 | 0.861 | 1.8 | 24.24 | No Adj. Made |
| LOWREW06 | 12/21/21 9:54 | 9.2 | 25.9 | 0.4 | 64.5 | 57.1 | -0.4 | -0.4 | 0.57 | 1.5 | 24.21 | No Adj. Made |
| LOWREW07 | 7/20/21 10:59 | 31.1 | 29.1 | 0.4 | 39.4 | 87.3 | -0.19 | -0.18 | 4.067 | 4.1 | 24.43 | No Adj. Made |
| LOWREW07 | 8/31/21 8:54 | 26.9 | 29.6 | 0 | 43.5 | 73.6 | -0.76 | -0.77 | 0.615 | 1.4 | 24.19 | No Adj. Made |
| LOWREW07 | 9/14/21 10:42 | 39.1 | 35.3 | 0 | 25.6 | 79.5 | -0.18 | -0.17 | 0.021 | 0.3 | 24.32 | No Adj. Made |
| LOWREW07 | 10/31/21 11:35 | 41.3 | 34.5 | 0 | 24.2 | 53.2 | -0.04 | -0.02 | 0.215 | 1 | 24.39 | No Adj. Made |
| LOWREW07 | 11/19/21 9:22 | 43.6 | 36.5 | 0.3 | 19.6 | 67.4 | -0.08 | -0.1 | 3.822 | 4 | 24.23 | No Adj. Made |
| LOWREW07 | 12/21/21 9:51 | 33.3 | 33.3 | 0.2 | 33.2 | 54.7 | -0.41 | -0.42 | 2.295 | 3.1 | 24.22 | No Adj. Made |
| LOWREW08 | 7/20/21 10:16 | 14.7 | 23.1 | 0.5 | 61.7 | 96.3 | -0.04 | -0.04 | 0.36 | 1.2 | 24.43 | No Adj. Made |
| LOWREW08 | 8/31/21 8:16 | 15.2 | 26.5 | 0 | 58.3 | 77.3 | -0.14 | -0.14 | 0.522 | 1.4 | 24.17 | No Adj. Made |
| LOWREW08 | 9/14/21 10:03 | 15.4 | 26.9 | 0.1 | 57.6 | 72.4 | -0.01 | -0.03 | 0.516 | 1.4 | 24.3 | No Adj. Made |
| LOWREW08 | 10/31/21 10:42 | 19.5 | 29.5 | 0 | 51 | 54.1 | -0.1 | -0.09 | 0.535 | 1.5 | 24.38 | No Adj. Made |
| LOWREW08 | 11/18/21 10:09 | 21.3 | 31.6 | 0 | 47.1 | 61.4 | -0.05 | -0.04 | 0.782 | 1.8 | 24.43 | No Adj. Made |
| LOWREW08 | 12/21/21 9:18 | 16.8 | 28.6 | 0.2 | 54.4 | 52 | -0.09 | -0.08 | 0.859 | 1.8 | 24.19 | No Adj. Made |
| LOWREW09 | 7/20/21 10:10 | 0.3 | 19.2 | 3.1 | 77.4 | 91 | -0.14 | -0.14 | 1.143 | 3.2 | 24.42 | Fully Closed |
| LOWREW09 | 8/31/21 8:13 | 2.4 | 23.6 | 0.2 | 73.8 | 77.5 | -0.28 | 0 | 3.39 | 5.6 | 24.17 | Fully Closed |
| LOWREW09 | 9/14/21 9:59 | 1 | 25.2 | 0 | 73.8 | 75.4 | -0.34 | 0 | 4.803 | 6.6 | 24.3 | Fully Closed |
| LOWREW09 | 10/31/21 10:39 | 0.6 | 20.2 | 4 | 75.2 | 54.4 | -0.03 | -0.04 | 1.244 | 3.5 | 24.39 | Fully Closed |
| LOWREW09 | 11/18/21 10:01 | 0.8 | 21.8 | 3.8 | 73.6 | 63.2 | -0.11 | -0.07 | 1.196 | 3.4 | 24.43 | Fully Closed |
| LOWREW09 | 12/21/21 9:16 | 2 | 24.4 | 0.3 | 73.3 | 48.7 | -0.15 | -0.13 | 0.142 | 1.2 | 24.18 | Fully Closed |
| LOWREW10 | 7/20/21 9:22 | 6 | 19.7 | 0.5 | 73.8 | 88.1 | -0.28 | -0.21 | 3.621 | 5.9 | 24.41 | Fully Closed |
| LOWREW10 | 8/30/21 10:18 | 6.1 | 21.5 | 0.4 | 72 | 93.8 | -0.02 | -0.06 | 1.598 | 3.8 | 24.25 | Fully Closed |

**APPENDIX D-1**
**LANDFILL GAS EXTRACTION WELL MONITORING**
**JULY THROUGH DECEMBER 2021 OPERATIONS AND MAINTENANCE REPORT**
**LOWRY LANDFILL SUPERFUND SITE**

| ID | Date/Time | Methane (%)[a/] | Carbon Dioxide (%) | Oxygen (%) | Balance (%) | Initial Temperature (°F)[b/] | Initial Static Pressure ("$H_2O$)[c/] | Adjusted Static Pressure ("$H_2O$) | Header Pressure ("$H_2O$) | Initial Flow (scfm)[d/] | Barometric Pressure ("Hg)[e/] | Comments |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| LOWREW10 | 9/13/21 10:32 | 6.3 | 20.5 | 0.9 | 72.3 | 82.7 | -0.51 | -0.37 | 4.959 | 6.8 | 24.31 | Fully Closed |
| LOWREW10 | 10/31/21 9:34 | 28.8 | 25.1 | 3 | 43.1 | 51.7 | -0.19 | -0.21 | 2.422 | 5.1 | 24.39 | Fully Closed |
| LOWREW10 | 11/18/21 8:43 | 9.3 | 27.4 | 0.6 | 62.7 | 64.7 | -0.11 | -0.06 | 0.573 | 2.4 | 24.46 | Fully Closed |
| LOWREW10 | 12/20/21 10:10 | 4.2 | 19.3 | 5.6 | 70.9 | 68.5 | -0.18 | -0.03 | 0.815 | 2.8 | 24.29 | Fully Closed |
| LOWREW11 | 7/20/21 9:19 | 12.1 | 24.5 | 0.2 | 63.2 | 83.8 | -0.18 | -0.16 | 0.785 | 1.7 | 24.42 | No Adj. Made |
| LOWREW11 | 8/30/21 10:14 | 15.4 | 25 | 0 | 59.6 | 89.9 | -0.32 | -0.31 | 0.35 | 1.1 | 24.25 | No Adj. Made |
| LOWREW11 | 9/13/21 10:27 | 11.7 | 26.5 | 0.1 | 61.7 | 78.4 | -0.46 | -0.45 | 1.062 | 2 | 24.31 | No Adj. Made |
| LOWREW11 | 10/31/21 9:26 | 11.7 | 26.7 | 0 | 61.6 | 53.3 | -0.29 | -0.29 | 0.591 | 1.5 | 24.38 | No Adj. Made |
| LOWREW11 | 11/17/21 10:51 | 11.6 | 28.6 | 0 | 59.8 | 60.3 | -0.52 | -0.5 | 0.996 | 2 | 24.39 | No Adj. Made |
| LOWREW11 | 12/20/21 10:06 | 11.3 | 26.5 | 0.6 | 61.6 | 64.4 | -0.12 | -0.12 | 0.517 | 1.4 | 24.28 | No Adj. Made |
| LOWREW12 | 7/20/21 9:13 | 11.5 | 22.3 | 0.4 | 65.8 | 84.7 | -1.66 | -1.66 | 0.691 | 1.6 | 24.41 | No Adj. Made |
| LOWREW12 | 8/30/21 10:10 | 12.7 | 24.3 | 0 | 63 | 89.8 | -0.65 | -0.65 | 0.259 | 1 | 24.29 | No Adj. Made |
| LOWREW12 | 9/13/21 10:24 | 13 | 25.5 | 0.1 | 61.4 | 75.9 | -2.04 | -2.03 | 0.847 | 1.8 | 24.31 | No Adj. Made |
| LOWREW12 | 10/31/21 9:23 | 12.8 | 26.6 | 0 | 60.6 | 48.1 | -1.34 | -1.34 | 0.492 | 1.4 | 24.38 | No Adj. Made |
| LOWREW12 | 11/17/21 10:47 | 12.4 | 28.1 | 0 | 59.5 | 49.5 | -1.97 | -1.98 | 1.098 | 2.1 | 24.38 | No Adj. Made |
| LOWREW12 | 12/20/21 10:01 | 11.8 | 25.6 | 0.4 | 62.2 | 56.1 | -1.11 | -1.11 | 0.336 | 1.2 | 24.29 | No Adj. Made |
| LOWREW13 | 7/20/21 9:08 | 14.4 | 19.9 | 0.5 | 65.2 | 79.8 | -0.43 | -0.42 | 0.172 | 3 | 24.53 | No Adj. Made |
| LOWREW13 | 8/30/21 10:08 | 15.7 | 26.4 | 0 | 57.9 | 84.2 | -0.03 | -0.03 | 0.142 | 2.3 | 24.29 | No Adj. Made |
| LOWREW13 | 9/13/21 10:21 | 17.3 | 26.1 | 0.1 | 56.5 | 74.8 | -0.87 | -0.86 | 0.609 | 5.6 | 24.31 | No Adj. Made |
| LOWREW13 | 10/31/21 9:20 | 17.7 | 28.1 | 0.1 | 54.1 | 56.6 | -0.67 | -0.62 | 0.43 | 4.7 | 24.39 | No Adj. Made |
| LOWREW13 | 11/17/21 10:43 | 16.9 | 29 | 0 | 54.1 | 62.1 | -0.93 | -0.91 | 1.095 | 7.5 | 24.38 | No Adj. Made |
| LOWREW13 | 12/20/21 9:58 | 16.5 | 27.4 | 0.3 | 55.8 | 63.6 | -0.29 | -0.29 | 0.867 | 6.7 | 24.29 | No Adj. Made |
| LOWREW14 | 7/19/21 10:15 | 20.8 | 26 | 0.5 | 52.7 | 84.8 | -0.05 | -0.04 | 2.064 | 2.9 | 24.51 | No Adj. Made |
| LOWREW14 | 8/30/21 9:33 | 22 | 26.6 | 0 | 51.4 | 82.4 | -0.13 | -0.14 | 0.857 | 1.9 | 24.24 | No Adj. Made |
| LOWREW14 | 9/13/21 9:52 | 22.7 | 27.3 | 0.1 | 49.9 | 74.4 | -0.69 | -0.69 | 2.434 | 3.1 | 24.3 | No Adj. Made |
| LOWREW14 | 10/31/21 8:44 | 23 | 28.3 | 0 | 48.7 | 53.1 | -0.46 | -0.46 | 1.104 | 2.1 | 24.39 | No Adj. Made |
| LOWREW14 | 11/17/21 9:34 | 23.4 | 31.5 | 0 | 45.1 | 51.5 | -0.99 | -0.99 | 1.912 | 2.8 | 24.39 | No Adj. Made |
| LOWREW14 | 12/20/21 9:27 | 22.9 | 28.7 | 0.3 | 48.1 | 58.4 | -0.33 | -0.33 | 1.095 | 2.1 | 24.29 | No Adj. Made |
| LOWREW15 | 7/19/21 10:12 | 20.8 | 24.4 | 0.4 | 54.4 | 83.7 | -0.15 | -0.13 | 0.107 | 2.3 | 24.5 | No Adj. Made |
| LOWREW15 | 8/30/21 9:31 | 21.6 | 25.1 | 0 | 53.3 | 81.1 | -0.13 | -0.13 | 0.047 | 1.6 | 24.24 | No Adj. Made |
| LOWREW15 | 9/13/21 9:50 | 21.5 | 26.4 | 0 | 52.1 | 73.7 | -0.73 | -0.72 | 0.152 | 2.8 | 24.3 | No Adj. Made |
| LOWREW15 | 10/31/21 8:42 | 21.8 | 27.5 | 0.1 | 50.6 | 54.1 | -0.58 | -0.56 | 0.031 | 1.3 | 24.39 | No Adj. Made |
| LOWREW15 | 11/17/21 9:30 | 20.7 | 29.5 | 0 | 49.8 | 53.8 | -1.1 | -1 | 0.289 | 3.9 | 24.39 | No Adj. Made |
| LOWREW15 | 12/20/21 9:25 | 20.1 | 27.1 | 0.3 | 52.5 | 57.3 | -0.39 | -0.39 | 0.04 | 1.5 | 24.29 | No Adj. Made |
| LOWREW16 | 7/19/21 10:06 | 16.9 | 25.9 | 0.4 | 56.8 | 88.4 | -0.05 | -0.05 | 0.403 | 1.3 | 24.51 | No Adj. Made |
| LOWREW16 | 8/30/21 9:26 | 18.5 | 27.3 | 0 | 54.2 | 82.5 | -0.16 | -0.16 | 0.143 | 0.7 | 24.25 | No Adj. Made |
| LOWREW16 | 9/13/21 9:45 | 18.5 | 28.2 | 0.1 | 53.2 | 75.1 | -0.48 | -0.49 | 0.584 | 1.5 | 24.3 | No Adj. Made |

**APPENDIX D-1**
**LANDFILL GAS EXTRACTION WELL MONITORING**
**JULY THROUGH DECEMBER 2021 OPERATIONS AND MAINTENANCE REPORT**
**LOWRY LANDFILL SUPERFUND SITE**

| ID | Date/Time | Methane (%)[a/] | Carbon Dioxide (%) | Oxygen (%) | Balance (%) | Initial Temperature (°F)[b/] | Initial Static Pressure ("$H_2O$)[c/] | Adjusted Static Pressure ("$H_2O$) | Header Pressure ("$H_2O$) | Initial Flow (scfm)[d/] | Barometric Pressure ("Hg)[e/] | Comments |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| LOWREW16 | 10/31/21 8:35 | 20.5 | 29.1 | 0 | 50.4 | 50.5 | -0.46 | -0.45 | 0.769 | 1.8 | 24.39 | No Adj. Made |
| LOWREW16 | 11/17/21 9:21 | 20.1 | 31 | 0 | 48.9 | 48.9 | -0.97 | -0.97 | 1.426 | 2.4 | 24.4 | No Adj. Made |
| LOWREW16 | 12/20/21 9:18 | 20.2 | 29 | 0.3 | 50.5 | 55.6 | -0.37 | -0.37 | 0.821 | 1.8 | 24.29 | No Adj. Made |
| LOWREW17 | 7/19/21 10:01 | 7.1 | 20.3 | 0.5 | 72.1 | 87.6 | -0.02 | -0.02 | 0.05 | 1.6 | 24.52 | No Adj. Made |
| LOWREW17 | 8/30/21 9:20 | 9.9 | 23.9 | 0 | 66.2 | 80.4 | -0.11 | -0.12 | 0.02 | 1 | 24.25 | No Adj. Made |
| LOWREW17 | 9/13/21 9:40 | 9.1 | 24.2 | 0 | 66.7 | 69.5 | -0.81 | -0.8 | 0.023 | 1.1 | 24.34 | No Adj. Made |
| LOWREW17 | 10/31/21 8:29 | 5.8 | 22.7 | 0.1 | 71.4 | 57.5 | -0.42 | -0.41 | 0.349 | 4.2 | 24.4 | No Adj. Made |
| LOWREW17 | 11/17/21 9:14 | 5.3 | 24.2 | 0 | 70.5 | 55.8 | -0.46 | -0.38 | 0.738 | 6.1 | 24.26 | Dec. Flow/Vac. |
| LOWREW17 | 12/20/21 9:11 | 7.4 | 22.9 | 0.5 | 69.2 | 56 | -0.23 | -0.23 | 0.068 | 1.9 | 24.18 | No Adj. Made |
| LOWREW18 | 7/19/21 9:54 | 6.8 | 21.4 | 0.4 | 71.4 | 84.6 | -0.21 | -0.2 | 1.66 | 2.5 | 24.53 | No Adj. Made |
| LOWREW18 | 8/30/21 9:15 | 8 | 23.7 | 0 | 68.3 | 78.9 | -0.01 | -0.01 | 0.74 | 1.7 | 24.26 | No Adj. Made |
| LOWREW18 | 9/13/21 9:33 | 8.3 | 24.2 | 0.1 | 67.4 | 73 | -0.38 | -0.37 | 2.128 | 2.9 | 24.32 | No Adj. Made |
| LOWREW18 | 10/31/21 8:22 | 7.2 | 24 | 0 | 68.8 | 51.5 | -0.27 | -0.26 | 0.857 | 1.8 | 24.4 | No Adj. Made |
| LOWREW18 | 11/17/21 9:01 | 6.1 | 24.6 | 0 | 69.3 | 46.1 | -0.39 | -0.39 | 1.272 | 2.3 | 24.43 | No Adj. Made |
| LOWREW18 | 12/20/21 9:06 | 7.9 | 23.4 | 0.6 | 68.1 | 51.9 | -0.14 | -0.15 | 0.723 | 1.7 | 24.32 | No Adj. Made |
| LOWREW19 | 7/19/21 9:52 | 16.1 | 26 | 0.2 | 57.7 | 85.8 | -0.02 | -0.01 | 0.527 | 1.4 | 24.53 | No Adj. Made |
| LOWREW19 | 8/30/21 9:11 | 18.4 | 27.4 | 0 | 54.2 | 79.7 | -0.12 | -0.12 | 0.273 | 1 | 24.26 | No Adj. Made |
| LOWREW19 | 9/13/21 9:30 | 12.8 | 26 | 0.1 | 61.1 | 75.1 | -0.48 | -0.45 | 0.488 | 1.4 | 24.32 | No Adj. Made |
| LOWREW19 | 10/31/21 8:19 | 17 | 27.3 | 0.1 | 55.6 | 51 | -0.16 | -0.16 | 0.443 | 1.4 | 24.41 | No Adj. Made |
| LOWREW19 | 11/17/21 8:52 | 15.2 | 28.9 | 0 | 55.9 | 42.6 | -0.3 | -0.3 | 0.784 | 1.8 | 24.43 | No Adj. Made |
| LOWREW19 | 12/20/21 9:03 | 16.4 | 28.1 | 0.2 | 55.3 | 51.9 | -0.12 | -0.12 | 0.416 | 1.3 | 24.32 | No Adj. Made |
| LOWREW20 | 7/19/21 9:49 | 22.7 | 22.5 | 0.7 | 54.1 | 81.8 | -0.09 | -0.08 | 1.025 | 2 | 24.53 | No Adj. Made |
| LOWREW20 | 8/30/21 9:08 | 27.9 | 25 | 0.4 | 46.7 | 76 | -0.04 | -0.04 | 0.507 | 1.5 | 24.34 | No Adj. Made |
| LOWREW20 | 9/13/21 9:27 | 14.9 | 24.9 | 0.9 | 59.3 | 73.2 | -0.33 | -0.31 | 1.209 | 2.2 | 24.38 | No Adj. Made |
| LOWREW20 | 10/31/21 8:16 | 19.4 | 26.7 | 0.9 | 53 | 55.6 | -0.16 | -0.16 | 0.623 | 1.6 | 24.42 | |
| LOWREW20 | 11/17/21 8:48 | 15.5 | 28.3 | 0.4 | 55.8 | 52.4 | -0.23 | -0.21 | 1.222 | 2.2 | 24.44 | No Adj. Made |
| LOWREW20 | 12/20/21 9:00 | 18.9 | 27 | 0.8 | 53.3 | 54.2 | -0.06 | -0.06 | 0.685 | 1.7 | 24.38 | No Adj. Made |
| LOWREW21 | 7/20/21 10:35 | 21.1 | 28.6 | 0.5 | 49.8 | 94 | -0.09 | -0.1 | 0.395 | 1.2 | 24.42 | No Adj. Made |
| LOWREW21 | 8/31/21 8:36 | 20 | 29.5 | 0 | 50.5 | 79.1 | -0.15 | -0.16 | 0.481 | 1.3 | 24.18 | No Adj. Made |
| LOWREW21 | 9/14/21 10:26 | 20.5 | 29.7 | 0 | 49.8 | 74.8 | -0.07 | -0.04 | 0.504 | 1.4 | 24.3 | No Adj. Made |
| LOWREW21 | 10/31/21 11:13 | 19.5 | 28.7 | 0 | 51.8 | 55.9 | -0.06 | -0.04 | 0.646 | 1.6 | 24.39 | No Adj. Made |
| LOWREW21 | 11/18/21 11:07 | 23.1 | 32.2 | 0.3 | 44.4 | 70.5 | -0.13 | -0.08 | 2.484 | 3.1 | 24.41 | No Adj. Made |
| LOWREW21 | 12/21/21 9:38 | 18.8 | 29.4 | 0.5 | 51.3 | 57 | -0.44 | -0.44 | 1.425 | 2.4 | 24.2 | No Adj. Made |
| LOWREW22 | 7/20/21 10:38 | 21.5 | 28.1 | 0.5 | 49.9 | 90.1 | -0.01 | -0.01 | 0.122 | 2.5 | 24.43 | No Adj. Made |
| LOWREW22 | 8/31/21 8:39 | 14.6 | 28.6 | 0 | 56.8 | 77.7 | -0.33 | -0.33 | 0.182 | 3 | 24.18 | No Adj. Made |
| LOWREW22 | 9/14/21 10:30 | 18.1 | 31 | 0 | 50.9 | 73.5 | -0.05 | -0.05 | 0.235 | 3.4 | 24.31 | No Adj. Made |
| LOWREW22 | 10/31/21 11:17 | 14.6 | 27.5 | 0.5 | 57.4 | 59.2 | -0.09 | -0.1 | 0.214 | 3.3 | 24.39 | No Adj. Made |

**APPENDIX D-1**
**LANDFILL GAS EXTRACTION WELL MONITORING**
**JULY THROUGH DECEMBER 2021 OPERATIONS AND MAINTENANCE REPORT**
**LOWRY LANDFILL SUPERFUND SITE**

| ID | Date/Time | Methane (%)[a/] | Carbon Dioxide (%) | Oxygen (%) | Balance (%) | Initial Temperature (°F)[b/] | Initial Static Pressure ("$H_2O$)[c/] | Adjusted Static Pressure ("$H_2O$) | Header Pressure ("$H_2O$) | Initial Flow (scfm)[d/] | Barometric Pressure ("Hg)[e/] | Comments |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| LOWREW22 | 11/18/21 11:20 | 23.9 | 32.9 | 0.3 | 42.9 | 70 | -0.06 | -0.06 | 0.319 | 4 | 24.41 | No Adj. Made |
| LOWREW22 | 12/21/21 9:40 | 17 | 30 | 0.2 | 52.8 | 57.4 | -0.55 | -0.53 | 0.141 | 2.7 | 24.22 | No Adj. Made |
| LOWREW23 | 7/20/21 10:42 | 8.6 | 23.3 | 0.5 | 67.6 | 95.5 | -0.06 | -0.01 | 0.637 | 5.5 | 24.43 | Fully Closed |
| LOWREW23 | 8/31/21 8:42 | 8.2 | 25.3 | 0.3 | 66.2 | 92.6 | -0.32 | -0.14 | 0.786 | 6.1 | 24.19 | Fully Closed |
| LOWREW23 | 9/14/21 10:34 | 1.6 | 20.1 | 6.5 | 71.8 | 101.4 | -1.33 | -1.33 | 5.129 | 6.3 | 24.34 | Fully Closed |
| LOWREW23 | 10/31/21 11:24 | 8.1 | 16.9 | 3.3 | 71.7 | 63.3 | -0.04 | -0.04 | 0.039 | 1.4 | 24.4 | Fully Closed |
| LOWREW23 | 11/19/21 9:08 | 14.9 | 30 | 2.4 | 52.7 | 94.6 | -0.34 | -0.05 | 1.621 | 8.8 | 24.22 | Fully Closed |
| LOWREW23 | 12/21/21 9:43 | 4.1 | 25 | 3.3 | 67.6 | 91.4 | -0.41 | -0.36 | 0.939 | 6.6 | 24.21 | Fully Closed |
| LOWREW24 | 7/20/21 10:51 | 17.2 | 26.9 | 0.5 | 55.4 | 87.9 | -0.01 | -0.02 | 0.162 | 2.8 | 24.43 | No Adj. Made |
| LOWREW24 | 8/31/21 8:44 | 15.3 | 27.1 | 0 | 57.6 | 78 | -0.33 | -0.32 | 0.228 | 3.4 | 24.19 | No Adj. Made |
| LOWREW24 | 9/14/21 10:37 | 14.9 | 26.6 | 0 | 58.5 | 76.6 | -0.16 | -0.12 | 0.078 | 2 | 24.35 | No Adj. Made |
| LOWREW24 | 10/31/21 11:26 | 9.5 | 26.2 | 0.2 | 64.1 | 56.1 | -0.03 | -0.03 | 0.091 | 2.2 | 24.38 | No Adj. Made |
| LOWREW24 | 11/19/21 9:11 | 16.8 | 29.6 | 0.1 | 53.5 | 71.5 | -0.12 | -0.12 | 0.057 | 1.7 | 24.21 | No Adj. Made |
| LOWREW24 | 12/21/21 9:47 | 12 | 27 | 0.2 | 60.8 | 56.7 | -0.49 | -0.47 | 0.02 | 1 | 24.21 | No Adj. Made |
| LOWREW25 | 7/20/21 10:57 | 5.4 | 20.7 | 0.4 | 73.5 | 92.7 | -0.06 | -0.04 | 0.4 | 1.2 | 24.43 | No Adj. Made |
| LOWREW25 | 8/31/21 8:49 | 5.8 | 24.3 | 0 | 69.9 | 80.4 | -0.42 | -0.24 | -0.066 | 0 | 24.22 | No Adj. Made |
| LOWREW25 | 9/14/21 10:39 | 6.7 | 24.9 | 0 | 68.4 | 77.5 | -0.03 | -0.04 | 0.594 | 1.5 | 24.31 | No Adj. Made |
| LOWREW25 | 10/31/21 11:31 | 8.1 | 26.4 | 0 | 65.5 | 56 | -0.03 | -0.02 | 0.123 | 0.7 | 24.39 | No Adj. Made |
| LOWREW25 | 11/19/21 9:18 | 9.5 | 28.1 | 0.3 | 62.1 | 69.3 | -0.08 | -0.04 | 0.221 | 0.9 | 24.22 | Inc. Flow/Vac. |
| LOWREW25 | 12/21/21 9:49 | 6.9 | 25.9 | 0.2 | 67 | 52.3 | -0.41 | -0.41 | 0.587 | 1.5 | 24.21 | No Adj. Made |
| LOWREW26 | 7/20/21 10:33 | 24.7 | 27.3 | 0.5 | 47.5 | 88.7 | -0.14 | -0.09 | 0.14 | 2.7 | 24.42 | No Adj. Made |
| LOWREW26 | 8/31/21 8:33 | 27.8 | 30.7 | 0 | 41.5 | 74.6 | -0.39 | -0.38 | 0.126 | 2.6 | 24.17 | No Adj. Made |
| LOWREW26 | 9/14/21 10:23 | 28 | 32.2 | 0 | 39.8 | 73 | -0.12 | -0.12 | 0.04 | 1.4 | 24.29 | No Adj. Made |
| LOWREW26 | 10/31/21 11:10 | 30.1 | 30.9 | 0.8 | 38.2 | 59.4 | -0.22 | -0.19 | 0.028 | 1.2 | 24.38 | No Adj. Made |
| LOWREW26 | 11/18/21 10:59 | 28.3 | 33.2 | 0 | 38.5 | 68.5 | -0.04 | -0.02 | 0.151 | 2.8 | 24.41 | No Adj. Made |
| LOWREW26 | 12/21/21 9:35 | 25.7 | 31.5 | 0.3 | 42.5 | 60.2 | -0.45 | -0.25 | 0.061 | 1.8 | 24.19 | No Adj. Made |
| LOWREW27 | 7/20/21 10:28 | 13.2 | 24.4 | 0.5 | 61.9 | 87.7 | -8.88 | -0.02 | 0.064 | 1.8 | 24.43 | No Adj. Made |
| LOWREW27 | 8/31/21 8:27 | 15.5 | 27.8 | 0 | 56.7 | 74.9 | -0.37 | -0.38 | 0.13 | 2.5 | 24.17 | No Adj. Made |
| LOWREW27 | 9/14/21 10:17 | 14.8 | 27.9 | 0 | 57.3 | 72.4 | -0.18 | -0.17 | 0.15 | 2.7 | 24.3 | No Adj. Made |
| LOWREW27 | 10/31/21 11:01 | 15.1 | 28.1 | 0 | 56.8 | 58.4 | -0.29 | -0.28 | 0.031 | 1.3 | 24.38 | No Adj. Made |
| LOWREW27 | 11/18/21 10:50 | 14.7 | 28.9 | 0 | 56.4 | 66.8 | -0.09 | -0.09 | 0.187 | 3.1 | 24.42 | No Adj. Made |
| LOWREW27 | 12/21/21 9:30 | 13.4 | 27.2 | 0.5 | 58.9 | 59.1 | -0.32 | -0.33 | 0.148 | 2.8 | 24.19 | No Adj. Made |
| LOWREW28 | 7/20/21 10:23 | 21.1 | 25.1 | 0.4 | 53.4 | 87.7 | -0.1 | -0.1 | 0.1 | 2.2 | 24.43 | No Adj. Made |
| LOWREW28 | 8/31/21 8:23 | 15.6 | 26 | 0 | 58.4 | 75.5 | -0.49 | -0.48 | 0.092 | 2 | 24.16 | No Adj. Made |
| LOWREW28 | 9/14/21 10:11 | 18.4 | 28.6 | 0 | 53 | 72.7 | -0.22 | -0.21 | 0.105 | 2.3 | 24.3 | No Adj. Made |
| LOWREW28 | 10/31/21 10:55 | 5.6 | 25.5 | 0 | 68.9 | 58.5 | -0.4 | -0.38 | 0.012 | 0.8 | 24.38 | No Adj. Made |
| LOWREW28 | 11/18/21 10:38 | 20.7 | 29.7 | 0.1 | 49.5 | 66.8 | -0.26 | -0.2 | 0.072 | 1.9 | 24.42 | No Adj. Made |

**APPENDIX D-1**
**LANDFILL GAS EXTRACTION WELL MONITORING**
**JULY THROUGH DECEMBER 2021 OPERATIONS AND MAINTENANCE REPORT**
**LOWRY LANDFILL SUPERFUND SITE**

| ID | Date/Time | Methane (%)[a/] | Carbon Dioxide (%) | Oxygen (%) | Balance (%) | Initial Temperature (°F)[b/] | Initial Static Pressure ("$H_2O$)[c/] | Adjusted Static Pressure ("$H_2O$) | Header Pressure ("$H_2O$) | Initial Flow (scfm)[d/] | Barometric Pressure ("Hg)[e/] | Comments |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| LOWREW28 | 12/21/21 9:26 | 15.6 | 27.4 | 0.3 | 56.7 | 56.2 | -0.31 | -0.31 | 0.068 | 1.9 | 24.18 | No Adj. Made |
| LOWREW29 | 7/20/21 10:18 | 30.6 | 26.1 | 0.5 | 42.8 | 88.7 | -0.06 | -0.06 | 1.098 | 2.1 | 24.43 | No Adj. Made |
| LOWREW29 | 8/31/21 8:18 | 30.9 | 30 | 0 | 39.1 | 74.4 | -0.43 | -0.42 | 1.43 | 2.4 | 24.17 | No Adj. Made |
| LOWREW29 | 9/14/21 10:05 | 25.2 | 28.6 | 0 | 46.2 | 72 | -0.15 | -0.14 | 1.396 | 2.4 | 24.3 | No Adj. Made |
| LOWREW29 | 10/31/21 10:48 | 18.2 | 28.2 | 0 | 53.6 | 56.3 | -0.36 | -0.35 | 0.722 | 1.7 | 24.38 | No Adj. Made |
| LOWREW29 | 11/18/21 10:15 | 35.2 | 32.8 | 0 | 32 | 63.7 | -0.51 | -0.33 | 1.853 | 3.2 | 24.42 | No Adj. Made |
| LOWREW29 | 12/21/21 9:21 | 22.4 | 28.2 | 0.3 | 49.1 | 55.9 | -0.19 | -0.19 | 1.141 | 2.2 | 24.19 | No Adj. Made |
| LOWREW30 | 7/20/21 9:42 | 24.8 | 26.1 | 0.5 | 48.6 | 83.7 | -0.05 | -0.04 | 0.117 | 2.5 | 24.43 | No Adj. Made |
| LOWREW30 | 8/31/21 7:49 | 26.7 | 28 | 0.2 | 45.1 | 76.6 | -0.3 | -0.29 | 0.236 | 3.5 | 24.26 | No Adj. Made |
| LOWREW30 | 9/14/21 9:34 | 26.5 | 30.3 | 0.1 | 43.1 | 75.3 | -0.18 | -0.17 | 0.257 | 3.6 | 24.31 | No Adj. Made |
| LOWREW30 | 10/31/21 10:02 | 26.6 | 30 | 0 | 43.4 | 60.7 | -9.33 | -0.29 | 0.033 | 1.3 | 24.39 | No Adj. Made |
| LOWREW30 | 11/18/21 9:11 | 29.2 | 32 | 0.3 | 38.5 | 66.5 | -0.07 | -0.06 | 0.176 | 3.1 | 24.45 | No Adj. Made |
| LOWREW30 | 12/20/21 10:34 | 22.4 | 27.8 | 0.8 | 49 | 66.1 | -0.2 | -0.21 | 0.04 | 1.4 | 24.31 | No Adj. Made |
| LOWREW31 | 7/20/21 9:48 | 24.5 | 27.9 | 0.3 | 47.3 | 84.9 | -0.01 | -0.02 | 0.19 | 3.1 | 24.43 | No Adj. Made |
| LOWREW31 | 8/31/21 7:54 | 21.3 | 29 | 0 | 49.7 | 78.8 | -0.33 | -0.32 | 0.245 | 3.4 | 24.16 | No Adj. Made |
| LOWREW31 | 9/14/21 9:38 | 23.1 | 28 | 0.2 | 48.7 | 77 | -0.22 | -0.21 | 0.234 | 3.5 | 24.3 | No Adj. Made |
| LOWREW31 | 10/31/21 10:10 | 20.9 | 28.6 | 0 | 50.5 | 62.6 | -0.33 | -0.34 | 0.035 | 1.4 | 24.39 | No Adj. Made |
| LOWREW31 | 11/18/21 9:20 | 22.3 | 31.8 | 0 | 45.9 | 71.8 | -0.17 | -0.13 | 0.131 | 2.6 | 24.44 | No Adj. Made |
| LOWREW31 | 12/20/21 10:39 | 17.9 | 27.5 | 0.5 | 54.1 | 69.5 | -0.38 | -0.37 | 0.132 | 2.6 | 24.3 | No Adj. Made |
| LOWREW32 | 7/20/21 9:54 | 20.7 | 26.5 | 0.3 | 52.5 | 91.6 | -0.1 | -0.05 | 0.183 | 1.3 | 24.43 | No Adj. Made |
| LOWREW32 | 8/31/21 7:59 | 22.1 | 29 | 0 | 48.9 | 77.3 | -0.31 | -0.31 | 0.205 | 1.4 | 24.16 | No Adj. Made |
| LOWREW32 | 9/14/21 9:43 | 21.1 | 28.4 | 0.1 | 50.4 | 74.6 | -0.23 | -0.22 | 0.265 | 1.6 | 24.3 | No Adj. Made |
| LOWREW32 | 10/31/21 10:17 | 21 | 29 | 0 | 50 | 58.8 | -0.47 | -0.45 | 0.047 | 0.7 | 24.39 | No Adj. Made |
| LOWREW32 | 11/18/21 9:29 | 23.1 | 32 | 0 | 44.9 | 73.6 | -0.04 | -0.03 | 0.944 | 3 | 24.44 | No Adj. Made |
| LOWREW32 | 12/21/21 9:01 | 24.1 | 28.5 | 0.4 | 47 | 63.7 | -0.17 | -0.19 | 1.101 | 3.3 | 24.2 | No Adj. Made |
| LOWREW33 | 7/20/21 10:00 | 27 | 25.5 | 0.4 | 47.1 | 90 | -0.04 | -0.06 | 0.216 | 1.5 | 24.42 | No Adj. Made |
| LOWREW33 | 8/31/21 8:03 | 29 | 29.2 | 0.1 | 41.7 | 75.7 | -0.35 | -0.33 | 0.311 | 1.8 | 24.16 | No Adj. Made |
| LOWREW33 | 9/14/21 9:48 | 28.3 | 29.5 | 0.1 | 42.1 | 72.8 | -0.21 | -0.2 | 0.442 | 2.1 | 24.29 | No Adj. Made |
| LOWREW33 | 10/31/21 10:23 | 23.3 | 28.2 | 0 | 48.5 | 57.3 | -0.55 | -0.51 | 0.211 | 1.4 | 24.39 | No Adj. Made |
| LOWREW33 | 11/18/21 9:41 | 31.4 | 32.7 | 0 | 35.9 | 71.4 | -0.02 | -0.02 | 0.418 | 2.1 | 24.43 | No Adj. Made |
| LOWREW33 | 12/21/21 9:06 | 26.3 | 27.3 | 0.4 | 46 | 67.2 | -0.32 | -0.32 | 4.936 | 7.1 | 24.2 | No Adj. Made |
| LOWREW34 | 7/20/21 10:04 | 9.2 | 22.9 | 0.1 | 67.8 | 88.3 | -0.14 | -0.13 | 0.352 | 1.8 | 24.42 | No Adj. Made |
| LOWREW34 | 8/31/21 8:08 | 10.9 | 25 | 0 | 64.1 | 75.7 | -0.07 | -0.06 | 0.438 | 2.1 | 24.16 | No Adj. Made |
| LOWREW34 | 9/14/21 9:53 | 10.5 | 25.1 | 0 | 64.4 | 72.7 | -0.09 | -0.08 | 0.441 | 2.1 | 24.29 | No Adj. Made |
| LOWREW34 | 10/31/21 10:31 | 10.9 | 25.8 | 0 | 63.3 | 59.3 | -0.03 | -0.02 | 0.724 | 2.7 | 24.39 | No Adj. Made |
| LOWREW34 | 11/18/21 9:53 | 10 | 26.4 | 0.6 | 63 | 66.9 | -0.01 | -0.01 | 1.215 | 3.4 | 24.43 | No Adj. Made |
| LOWREW34 | 12/21/21 9:11 | 10.5 | 24.9 | 0.3 | 64.3 | 58.7 | -0.02 | -0.03 | 0.277 | 1.7 | 23.98 | No Adj. Made |

**APPENDIX D-1**
**LANDFILL GAS EXTRACTION WELL MONITORING**
**JULY THROUGH DECEMBER 2021 OPERATIONS AND MAINTENANCE REPORT**
**LOWRY LANDFILL SUPERFUND SITE**

| ID | Date/Time | Methane (%)[a/] | Carbon Dioxide (%) | Oxygen (%) | Balance (%) | Initial Temperature (°F)[b/] | Initial Static Pressure ("$H_2O$)[c/] | Adjusted Static Pressure ("$H_2O$) | Header Pressure ("$H_2O$) | Initial Flow (scfm)[d/] | Barometric Pressure ("Hg)[e/] | Comments |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| LOWREW35 | 7/20/21 9:25 | 13.7 | 24.7 | 0.4 | 61.2 | 82.8 | -0.08 | -0.08 | 0.082 | 2 | 24.42 | No Adj. Made |
| LOWREW35 | 8/30/21 10:20 | 17.1 | 26.2 | 0 | 56.7 | 85.4 | -0.31 | -0.31 | 0.076 | 2 | 24.28 | No Adj. Made |
| LOWREW35 | 9/13/21 10:35 | 12.1 | 26.3 | 0 | 61.6 | 75.8 | -0.67 | -0.68 | 0.132 | 2.6 | 24.32 | No Adj. Made |
| LOWREW35 | 10/31/21 9:37 | 12.5 | 26.9 | 0 | 60.6 | 57.2 | -0.54 | -0.54 | 0.019 | 1 | 24.39 | No Adj. Made |
| LOWREW35 | 11/18/21 8:48 | 15.5 | 29.6 | 0.1 | 54.8 | 61.4 | -0.13 | -0.12 | 0.067 | 1.9 | 24.45 | No Adj. Made |
| LOWREW35 | 12/20/21 10:17 | 9.9 | 23.9 | 0.6 | 65.6 | 62.2 | -0.5 | -0.48 | 0.049 | 1.6 | 24.29 | No Adj. Made |
| LOWREW36 | 7/20/21 9:39 | 32.4 | 31 | 0.3 | 36.3 | 81.4 | -0.07 | -0.08 | 1.258 | 3.6 | 24.43 | No Adj. Made |
| LOWREW36 | 8/30/21 10:32 | 35.1 | 30.1 | 0 | 34.8 | 81.8 | -0.14 | -0.11 | 0.019 | 0.4 | 24.3 | No Adj. Made |
| LOWREW36 | 9/13/21 10:46 | 31.3 | 32 | 0 | 36.7 | 76.7 | -0.91 | -0.82 | 2.057 | 4.5 | 24.32 | No Adj. Made |
| LOWREW36 | 10/31/21 9:58 | 31.6 | 30.5 | 0.1 | 37.8 | 63.1 | -0.46 | -0.45 | 0.765 | 2.8 | 24.4 | No Adj. Made |
| LOWREW36 | 11/18/21 9:05 | 36.5 | 35.6 | 0 | 27.9 | 67.3 | -0.24 | -0.23 | 1.798 | 4.3 | 24.45 | No Adj. Made |
| LOWREW36 | 12/20/21 10:32 | 29.7 | 31.2 | 0.5 | 38.6 | 67.8 | -0.35 | -0.36 | 0.963 | 3.1 | 24.31 | No Adj. Made |
| LOWREW37 | 7/20/21 9:33 | 35.4 | 30.1 | 0.3 | 34.2 | 82.5 | -0.01 | -0.01 | 3.489 | 3.8 | 24.42 | No Adj. Made |
| LOWREW37 | 8/30/21 10:28 | 37 | 29.9 | 0 | 33.1 | 86.3 | -0.3 | -0.31 | 1.424 | 2.4 | 24.26 | No Adj. Made |
| LOWREW37 | 9/13/21 10:41 | 34.7 | 31.7 | 0 | 33.6 | 75.7 | -0.76 | -0.76 | 4.089 | 4.1 | 24.32 | No Adj. Made |
| LOWREW37 | 10/31/21 9:49 | 36.2 | 33.4 | 0 | 30.4 | 58.2 | -0.45 | -0.45 | 1.662 | 2.6 | 24.4 | No Adj. Made |
| LOWREW37 | 11/18/21 8:58 | 37.4 | 36.2 | 0 | 26.4 | 64.7 | -0.12 | -0.12 | 3.421 | 3.8 | 24.46 | No Adj. Made |
| LOWREW37 | 12/20/21 10:26 | 33.7 | 32.8 | 0.1 | 33.4 | 65.3 | -0.42 | -0.42 | 1.766 | 2.7 | 24.3 | No Adj. Made |
| LOWREW38 | 7/20/21 9:28 | 42.6 | 30.8 | 0.2 | 26.4 | 82.4 | -0.05 | -0.05 | 5.517 | 4.8 | 24.42 | No Adj. Made |
| LOWREW38 | 8/30/21 10:23 | 51 | 32.5 | 0 | 16.5 | 86.1 | -0.36 | -0.37 | 2.149 | 3.1 | 24.25 | No Adj. Made |
| LOWREW38 | 9/13/21 10:37 | 26 | 28.5 | 0.2 | 45.3 | 78 | -0.61 | -0.63 | 5.606 | 4.7 | 24.32 | No Adj. Made |
| LOWREW38 | 10/31/21 9:41 | 27.7 | 30 | 0 | 42.3 | 59.8 | -0.5 | -0.51 | 2.297 | 3.1 | 24.39 | No Adj. Made |
| LOWREW38 | 11/18/21 8:51 | 41.1 | 34.3 | 0 | 24.6 | 66 | -0.04 | -0.04 | 4.924 | 4.6 | 24.45 | No Adj. Made |
| LOWREW38 | 12/20/21 10:20 | 25.7 | 28.8 | 0.6 | 44.9 | 69 | -0.41 | -0.42 | 1.931 | 2.8 | 24.29 | No Adj. Made |
| LOWREW39 | 7/20/21 9:16 | 40 | 32.3 | 0.2 | 27.5 | 80.2 | -0.26 | -0.25 | 3.725 | 6.2 | 24.41 | No Adj. Made |
| LOWREW39 | 8/30/21 10:12 | 37.4 | 31.1 | 0 | 31.5 | 84.9 | -0.27 | -0.27 | 1.496 | 3.9 | 24.25 | No Adj. Made |
| LOWREW39 | 9/13/21 10:29 | 34.3 | 31.9 | 0.1 | 33.7 | 75.3 | -0.85 | -0.86 | 3.979 | 6.2 | 24.31 | No Adj. Made |
| LOWREW39 | 10/31/21 9:29 | 38.8 | 32.7 | 0.4 | 28.1 | 60.1 | -0.56 | -0.56 | 1.543 | 4 | 24.38 | No Adj. Made |
| LOWREW39 | 11/17/21 11:04 | 39.1 | 35.1 | 0 | 25.8 | 65.7 | -0.91 | -0.91 | 3.168 | 5.7 | 24.39 | No Adj. Made |
| LOWREW39 | 12/20/21 10:03 | 38.5 | 32.7 | 0.3 | 28.5 | 65.2 | -0.46 | -0.45 | 1.541 | 4 | 24.29 | No Adj. Made |
| LOWREW40 | 7/19/21 10:29 | 14.7 | 24 | 0.7 | 60.6 | 91.1 | -0.02 | -0.03 | 0.464 | 1.3 | 24.53 | No Adj. Made |
| LOWREW40 | 8/30/21 9:48 | 22.1 | 29.3 | 0 | 48.6 | 82.5 | -0.3 | -0.29 | 0.205 | 0.9 | 24.26 | No Adj. Made |
| LOWREW40 | 9/13/21 10:05 | 21.4 | 29.8 | 0.2 | 48.6 | 74.4 | -0.5 | -0.49 | 0.509 | 1.4 | 24.32 | No Adj. Made |
| LOWREW40 | 10/31/21 9:00 | 17.9 | 28.6 | 0.3 | 53.2 | 50.6 | -0.33 | -0.34 | 0.346 | 1.2 | 24.41 | No Adj. Made |
| LOWREW40 | 11/17/21 9:54 | 19.4 | 33.2 | 0 | 47.4 | 43.2 | -0.65 | -0.65 | 0.541 | 1.5 | 24.41 | No Adj. Made |
| LOWREW40 | 12/20/21 9:40 | 18.9 | 30.3 | 0.1 | 50.7 | 55.9 | -0.2 | -0.21 | 0.376 | 1.2 | 24.3 | No Adj. Made |
| LOWREW41 | 7/19/21 10:36 | 14.5 | 23.4 | 0.7 | 61.4 | 87.4 | -0.16 | -0.16 | 1.132 | 2.1 | 24.53 | No Adj. Made |

**APPENDIX D-1**
**LANDFILL GAS EXTRACTION WELL MONITORING**
**JULY THROUGH DECEMBER 2021 OPERATIONS AND MAINTENANCE REPORT**
**LOWRY LANDFILL SUPERFUND SITE**

| ID | Date/Time | Methane (%)[a/] | Carbon Dioxide (%) | Oxygen (%) | Balance (%) | Initial Temperature (°F)[b/] | Initial Static Pressure ("$H_2O$)[c/] | Adjusted Static Pressure ("$H_2O$) | Header Pressure ("$H_2O$) | Initial Flow (scfm)[d/] | Barometric Pressure ("Hg)[e/] | Comments |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| LOWREW41 | 8/30/21 9:54 | 23.9 | 28.2 | 0 | 47.9 | 79.5 | -0.27 | -0.28 | 0.562 | 1.5 | 24.26 | No Adj. Made |
| LOWREW41 | 9/13/21 10:11 | 19.7 | 28.5 | 0 | 51.8 | 73.3 | -0.73 | -0.73 | 1.37 | 2.3 | 24.32 | No Adj. Made |
| LOWREW41 | 10/31/21 9:07 | 16.7 | 28.2 | 0.4 | 54.7 | 53.6 | -0.68 | -0.68 | 0.551 | 1.5 | 24.4 | No Adj. Made |
| LOWREW41 | 11/17/21 10:09 | 16 | 30.7 | 0 | 53.3 | 54.7 | -1.44 | -1.44 | 0.78 | 1.8 | 24.39 | No Adj. Made |
| LOWREW41 | 12/20/21 9:48 | 17.6 | 29 | 0.1 | 53.3 | 59.9 | -0.56 | -0.55 | 0.459 | 1.4 | 24.31 | No Adj. Made |
| LOWREW42 | 7/19/21 10:40 | 14.2 | 22.6 | 0.7 | 62.5 | 92.8 | -0.08 | -0.07 | 0.024 | 1.1 | 24.52 | No Adj. Made |
| LOWREW42 | 8/30/21 9:59 | 24 | 27.1 | 0 | 48.9 | 85.5 | -0.29 | -0.32 | 0.195 | 2.6 | 24.27 | No Adj. Made |
| LOWREW42 | 9/13/21 10:16 | 21.4 | 27.3 | 0.1 | 51.2 | 81.4 | -0.66 | -0.66 | 0.259 | 3.6 | 24.32 | No Adj. Made |
| LOWREW42 | 10/31/21 9:13 | 12.9 | 26.3 | 0.2 | 60.6 | 67.1 | -0.67 | -0.66 | 0.037 | 1.4 | 24.39 | No Adj. Made |
| LOWREW42 | 11/17/21 10:21 | 12.4 | 29.3 | 0 | 58.3 | 54.1 | -1.08 | -1.08 | 0.126 | 2.5 | 24.39 | No Adj. Made |
| LOWREW42 | 12/20/21 9:53 | 15.1 | 27 | 0.3 | 57.6 | 71.5 | -0.32 | -0.33 | 0.237 | 3.5 | 24.3 | No Adj. Made |
| LOWREW43 | 7/19/21 10:43 | 20.4 | 24.1 | 0.6 | 54.9 | 87.1 | -0.04 | -0.03 | 0.219 | 3.3 | 24.52 | No Adj. Made |
| LOWREW43 | 8/30/21 10:04 | 48.6 | 31.8 | 0 | 19.6 | 79.1 | -0.34 | -0.33 | 0.103 | 2.4 | 24.26 | No Adj. Made |
| LOWREW43 | 9/13/21 10:19 | 35.6 | 31 | 0.1 | 33.3 | 74.5 | -0.63 | -0.64 | 0.338 | 4.3 | 24.32 | No Adj. Made |
| LOWREW43 | 10/31/21 9:17 | 15.9 | 26.4 | 0 | 57.7 | 59.7 | -0.56 | -0.56 | 0.223 | 3.4 | 24.39 | No Adj. Made |
| LOWREW43 | 11/17/21 10:33 | 19.5 | 30.1 | 0 | 50.4 | 47.7 | -0.99 | -0.94 | 0.024 | 1.1 | 24.38 | No Adj. Made |
| LOWREW43 | 12/20/21 9:56 | 22.1 | 26.8 | 0.4 | 50.7 | 62.3 | -0.36 | -0.36 | 0.035 | 1.4 | 24.3 | No Adj. Made |
| LOWREW44 | 7/19/21 10:18 | 34.1 | 32.3 | 0.4 | 33.2 | 91.5 | -0.04 | -0.03 | 0.353 | 1.2 | 24.5 | No Adj. Made |
| LOWREW44 | 8/30/21 9:36 | 33.9 | 31.9 | 0 | 34.2 | 84.8 | -0.2 | -0.22 | 0.147 | 0.8 | 24.24 | No Adj. Made |
| LOWREW44 | 9/13/21 9:54 | 34.4 | 32.4 | 0.1 | 33.1 | 75 | -0.58 | -0.59 | 0.547 | 1.5 | 24.3 | No Adj. Made |
| LOWREW44 | 10/31/21 8:48 | 37.8 | 34.6 | 0.1 | 27.5 | 48.8 | -0.58 | -0.58 | 0.287 | 1.1 | 24.39 | No Adj. Made |
| LOWREW44 | 11/17/21 9:37 | 36.9 | 37.2 | 0 | 25.9 | 52.6 | -1.32 | -1.31 | 2.1 | 3 | 24.39 | No Adj. Made |
| LOWREW44 | 12/20/21 9:30 | 33.8 | 32.4 | 0.4 | 33.4 | 57.4 | -0.42 | -0.45 | 0.888 | 1.9 | 24.28 | No Adj. Made |
| LOWREW45 | 7/19/21 10:26 | 21.5 | 25.6 | 0.7 | 52.2 | 87.2 | -0.02 | -0.03 | 0.062 | 1.8 | 24.52 | No Adj. Made |
| LOWREW45 | 8/30/21 9:46 | 26.2 | 30.1 | 0 | 43.7 | 79.9 | -0.26 | -0.27 | 0.023 | 1.1 | 24.25 | No Adj. Made |
| LOWREW45 | 9/13/21 10:02 | 20.8 | 28.7 | 0 | 50.5 | 73.2 | -0.49 | -0.48 | 0.122 | 2.5 | 24.32 | No Adj. Made |
| LOWREW45 | 10/31/21 8:56 | 21.1 | 28.9 | 0 | 50 | 54.5 | -0.36 | -0.36 | 0.023 | 1.1 | 24.4 | No Adj. Made |
| LOWREW45 | 11/17/21 9:49 | 20.5 | 32.5 | 0 | 47 | 53.8 | -0.65 | -0.65 | 0.042 | 1.5 | 24.41 | No Adj. Made |
| LOWREW45 | 12/20/21 9:38 | 22.1 | 30 | 0.2 | 47.7 | 60 | -0.28 | -0.25 | 0.054 | 1.7 | 24.3 | No Adj. Made |
| LOWREW46 | 7/19/21 10:24 | 28.1 | 28.3 | 0.6 | 43 | 88.7 | -0.07 | -0.07 | 0.547 | 2.3 | 24.51 | No Adj. Made |
| LOWREW46 | 8/30/21 9:43 | 34.5 | 33.1 | 0 | 32.4 | 81.3 | -0.24 | -0.25 | 0.159 | 1.3 | 24.24 | No Adj. Made |
| LOWREW46 | 9/13/21 10:00 | 27.2 | 29.9 | 0.1 | 42.8 | 74.3 | -0.62 | -0.61 | 0.395 | 1.9 | 24.31 | No Adj. Made |
| LOWREW46 | 10/31/21 8:53 | 28 | 30.7 | 0 | 41.3 | 53.4 | -0.42 | -0.42 | 0.463 | 2.2 | 24.39 | No Adj. Made |
| LOWREW46 | 11/17/21 9:45 | 25.8 | 33.4 | 0 | 40.8 | 53.5 | -0.85 | -0.86 | 0.636 | 2.5 | 24.4 | No Adj. Made |
| LOWREW46 | 12/20/21 9:35 | 29.7 | 32 | 0.5 | 37.8 | 61.4 | -0.27 | -0.27 | 0.411 | 2.1 | 24.29 | No Adj. Made |
| LOWREW47 | 7/19/21 10:22 | 19.9 | 28 | 0.5 | 51.6 | 93.2 | -0.03 | -0.04 | 0.04 | 0.6 | 24.51 | No Adj. Made |
| LOWREW47 | 8/30/21 9:38 | 22.2 | 29.4 | 0 | 48.4 | 83.7 | -0.23 | -0.24 | 0.066 | 0.8 | 24.24 | No Adj. Made |

**APPENDIX D-1**
**LANDFILL GAS EXTRACTION WELL MONITORING**
**JULY THROUGH DECEMBER 2021 OPERATIONS AND MAINTENANCE REPORT**
**LOWRY LANDFILL SUPERFUND SITE**

| ID | Date/Time | Methane (%)[a/] | Carbon Dioxide (%) | Oxygen (%) | Balance (%) | Initial Temperature (°F)[b/] | Initial Static Pressure ("$H_2O$)[c/] | Adjusted Static Pressure ("$H_2O$) | Header Pressure ("$H_2O$) | Initial Flow (scfm)[d/] | Barometric Pressure ("Hg)[e/] | Comments |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| LOWREW47 | 9/13/21 9:58 | 22.2 | 28.9 | 0.8 | 48.1 | 73.9 | -0.7 | -0.67 | 0.383 | 1.9 | 24.3 | No Adj. Made |
| LOWREW47 | 10/31/21 8:51 | 20.6 | 28.6 | 0 | 50.8 | 46.6 | -0.61 | -0.59 | 0.316 | 1.8 | 24.39 | No Adj. Made |
| LOWREW47 | 11/17/21 9:42 | 19.3 | 31.8 | 0.2 | 48.7 | 35 | -0.97 | -0.96 | 0.326 | 1.8 | 24.39 | No Adj. Made |
| LOWREW47 | 12/20/21 9:32 | 20.1 | 29.4 | 0.2 | 50.3 | 53.8 | -0.32 | -0.32 | 0.14 | 1.2 | 24.29 | No Adj. Made |
| LOWREW48 | 7/19/21 9:58 | 9.8 | 23.6 | 0.4 | 66.2 | 88.2 | -0.01 | -0.01 | 0.613 | 1.5 | 24.53 | No Adj. Made |
| LOWREW48 | 8/30/21 9:18 | 28 | 31.4 | 0 | 40.6 | 79.7 | -0.18 | -0.18 | 0.367 | 1.2 | 24.25 | No Adj. Made |
| LOWREW48 | 9/13/21 9:36 | 25.4 | 31.5 | 0 | 43.1 | 74 | -0.44 | -0.44 | 0.012 | 0.2 | 24.31 | No Adj. Made |
| LOWREW48 | 10/31/21 8:26 | 9.6 | 27 | 0 | 63.4 | 56.6 | -0.31 | -0.3 | 0.776 | 1.8 | 24.4 | No Adj. Made |
| LOWREW48 | 11/17/21 9:05 | 10.4 | 29.8 | 0 | 59.8 | 57.9 | -0.57 | -0.56 | 1.468 | 2.4 | 24.42 | No Adj. Made |
| LOWREW48 | 12/20/21 9:08 | 12 | 27 | 0.4 | 60.6 | 57.9 | -0.24 | -0.23 | 0.961 | 2 | 24.31 | No Adj. Made |
| LOWREW49 | 7/19/21 10:04 | 17.3 | 26.3 | 0.3 | 56.1 | 83.4 | -0.08 | -0.07 | 0.088 | 2.1 | 24.52 | No Adj. Made |
| LOWREW49 | 8/30/21 9:23 | 24.8 | 29.8 | 0 | 45.4 | 80.1 | -0.14 | -0.14 | 0.037 | 1.4 | 24.25 | No Adj. Made |
| LOWREW49 | 9/13/21 9:43 | 16.7 | 27.8 | 0 | 55.5 | 74.1 | -0.6 | -0.59 | 0.171 | 2.9 | 24.33 | No Adj. Made |
| LOWREW49 | 10/31/21 8:32 | 14.3 | 26.8 | 0.1 | 58.8 | 55.4 | -0.47 | -0.46 | 0.025 | 1.1 | 24.39 | No Adj. Made |
| LOWREW49 | 11/17/21 9:17 | 14.1 | 29.8 | 0 | 56.1 | 53.9 | -0.83 | -0.84 | 0.084 | 2.1 | 24.4 | No Adj. Made |
| LOWREW49 | 12/20/21 9:14 | 14.6 | 27.3 | 0.3 | 57.8 | 57.8 | -0.33 | -0.34 | 0.062 | 1.8 | 24.31 | No Adj. Made |
| LOWREW50 | 7/19/21 10:09 | 27.8 | 26.9 | 0.4 | 44.9 | 84 | -0.3 | -0.29 | 0.137 | 2.6 | 24.5 | No Adj. Made |
| LOWREW50 | 8/30/21 9:28 | 33 | 30.2 | 0 | 36.8 | 79 | -0.01 | -0.01 | 0.076 | 2 | 24.25 | No Adj. Made |
| LOWREW50 | 9/13/21 9:48 | 25.2 | 29 | 0 | 45.8 | 74.4 | -0.82 | -0.82 | 0.212 | 3.3 | 24.3 | No Adj. Made |
| LOWREW50 | 10/31/21 8:38 | 20.3 | 26.8 | 0.4 | 52.5 | 56.3 | -0.71 | -0.69 | 0.302 | 4 | 24.39 | No Adj. Made |
| LOWREW50 | 11/17/21 9:25 | 15 | 29 | 0.2 | 55.8 | 57.8 | -1.14 | -1.14 | 0.109 | 2.4 | 24.39 | No Adj. Made |
| LOWREW50 | 12/20/21 9:22 | 22 | 29 | 0.6 | 48.4 | 63.7 | -0.57 | -0.6 | 0.113 | 2.4 | 24.29 | No Adj. Made |
| LOWREW55 | 7/19/21 10:33 | 42.7 | 32 | 1 | 24.3 | 83.1 | -1.56 | -1.55 | 0.169 | 9.2 | 24.53 | No Adj. Made |
| LOWREW55 | 8/30/21 9:52 | 45.6 | 34.6 | 0 | 19.8 | 79.4 | -0.49 | -0.48 | 0.094 | 6.9 | 24.26 | No Adj. Made |
| LOWREW55 | 9/13/21 10:09 | 46.6 | 36.9 | 0 | 16.5 | 73.9 | -2.12 | -2.13 | 0.213 | 10.4 | 24.32 | No Adj. Made |
| LOWREW55 | 10/31/21 9:04 | 49.6 | 36.6 | 0 | 13.8 | 66.2 | -1.73 | -1.73 | 0.032 | 4.1 | 24.41 | No Adj. Made |
| LOWREW55 | 11/17/21 10:01 | 48.9 | 38.7 | 0 | 12.4 | 67.5 | -3.32 | -3.32 | 0.194 | 10 | 24.4 | No Adj. Made |
| LOWREW55 | 12/20/21 9:45 | 46.1 | 35.7 | 0.5 | 17.7 | 68.7 | -1.57 | -1.57 | 0.017 | 3 | 24.31 | No Adj. Made |
| LOWREW56 | 7/19/21 10:38 | 32.1 | 28 | 0.8 | 39.1 | 85.2 | -0.26 | -0.26 | 0.175 | 3 | 24.53 | No Adj. Made |
| LOWREW56 | 8/30/21 9:56 | 40.1 | 32.6 | 0 | 27.3 | 82.5 | -0.25 | -0.26 | 0.069 | 1.9 | 24.26 | No Adj. Made |
| LOWREW56 | 9/13/21 10:14 | 36.2 | 32.1 | 0.1 | 31.6 | 77.5 | -0.88 | -0.87 | 0.295 | 4 | 24.32 | No Adj. Made, scheduled repairs |
| LOWREW56 | 10/31/21 9:10 | 28.1 | 29.4 | 0.1 | 42.4 | 63.2 | -0.88 | -0.88 | 0.045 | 1.5 | 24.28 | No Adj. Made |
| LOWREW56 | 11/17/21 10:13 | 27.2 | 32.3 | 0 | 40.5 | 65.5 | -1.76 | -1.76 | 0.289 | 3.9 | 24.39 | No Adj. Made |
| LOWREW56 | 12/20/21 9:50 | 26.7 | 28.7 | 0.6 | 44 | 65.5 | -0.68 | -0.67 | 0.079 | 2 | 24.3 | No Adj. Made |
| LOWREW57 | 7/20/21 9:36 | 42.1 | 31.8 | 0.4 | 25.7 | 83.3 | -0.94 | -0.94 | 0.482 | 5.1 | 24.43 | No Adj. Made |
| LOWREW57 | 8/30/21 10:30 | 42.9 | 31.5 | 0 | 25.6 | 84.8 | -0.26 | -0.23 | 0.284 | 3.9 | 24.28 | No Adj. Made |

**APPENDIX D-1**
**LANDFILL GAS EXTRACTION WELL MONITORING**
**JULY THROUGH DECEMBER 2021 OPERATIONS AND MAINTENANCE REPORT**
**LOWRY LANDFILL SUPERFUND SITE**

| ID | Date/Time | Methane (%)[a/] | Carbon Dioxide (%) | Oxygen (%) | Balance (%) | Initial Temperature (°F)[b/] | Initial Static Pressure ("$H_2O$)[c/] | Adjusted Static Pressure ("$H_2O$) | Header Pressure ("$H_2O$) | Initial Flow (scfm)[d/] | Barometric Pressure ("Hg)[e/] | Comments |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| LOWREW57 | 9/13/21 10:44 | 43.7 | 33.8 | 0 | 22.5 | 81.7 | -1.71 | -1.65 | 0.571 | 5.5 | 24.32 | No Adj. Made |
| LOWREW57 | 10/31/21 9:54 | 48.2 | 34 | 0.1 | 17.7 | 70.8 | -1.21 | -1.21 | 0.269 | 3.9 | 24.4 | No Adj. Made |
| LOWREW57 | 11/18/21 9:02 | 50.2 | 37.8 | 0 | 12 | 73.6 | -1.04 | -1.04 | 0.545 | 5.5 | 24.46 | No Adj. Made |
| LOWREW57 | 12/20/21 10:28 | 42.9 | 32.1 | 0.7 | 24.3 | 74.2 | -1.14 | -1.15 | 0.341 | 4.3 | 24.31 | No Adj. Made |
| LOWREW58 | 7/20/21 9:31 | 30.3 | 26.5 | 0.3 | 42.9 | 84 | -0.13 | -0.11 | 0.223 | 3.4 | 24.42 | No Adj. Made |
| LOWREW58 | 8/30/21 10:26 | 33.6 | 27.9 | 0 | 38.5 | 86.5 | -0.35 | -0.38 | 0.114 | 2.5 | 24.26 | No Adj. Made |
| LOWREW58 | 9/13/21 10:39 | 30.7 | 28.3 | 0.1 | 40.9 | 77.1 | -0.64 | -0.65 | 0.317 | 4 | 24.32 | No Adj. Made |
| LOWREW58 | 10/31/21 9:45 | 30 | 27.9 | 0.6 | 41.5 | 60.4 | -0.52 | -0.49 | 0.143 | 2.8 | 24.4 | No Adj. Made |
| LOWREW58 | 11/18/21 8:54 | 32 | 31 | 0.1 | 36.9 | 67.2 | -0.07 | -0.07 | 0.355 | 4.4 | 24.45 | No Adj. Made |
| LOWREW58 | 12/20/21 10:23 | 26.8 | 27.6 | 0.2 | 45.4 | 68.4 | -0.43 | -0.42 | 0.114 | 2.5 | 24.3 | No Adj. Made |
| LOWREW59 | 7/20/21 9:57 | 35.6 | 28.2 | 0.4 | 35.8 | 85.1 | -0.06 | -0.05 | 0.297 | 4 | 24.42 | No Adj. Made |
| LOWREW59 | 8/31/21 8:01 | 38.7 | 31.4 | 0 | 29.9 | 74.2 | -0.3 | -0.3 | 0.414 | 4.7 | 24.16 | No Adj. Made |
| LOWREW59 | 9/14/21 9:46 | 38.5 | 30.2 | 0.1 | 31.2 | 71.7 | -0.24 | -0.24 | 0.421 | 4.8 | 24.3 | No Adj. Made |
| LOWREW59 | 10/31/21 10:20 | 42.9 | 31 | 0 | 26.1 | 63.4 | -0.38 | -0.38 | 0.165 | 3.1 | 24.3 | No Adj. Made |
| LOWREW59 | 11/18/21 9:33 | 43.6 | 33.8 | 0 | 22.6 | 69.1 | -0.08 | -0.07 | 0.475 | 5.1 | 24.43 | No Adj. Made |
| LOWREW59 | 12/21/21 9:03 | 35.4 | 29.3 | 0.4 | 34.9 | 62.8 | -0.31 | -0.31 | 0.257 | 3.8 | 24.2 | |
| LOWREW5A | 7/20/21 11:06 | 25 | 27 | 0.4 | 47.6 | 92.2 | -0.03 | -0.02 | 0.453 | 1.3 | 24.43 | No Adj. Made |
| LOWREW5A | 8/31/21 9:03 | 27.3 | 30.4 | 0 | 42.3 | 81.8 | -0.44 | -0.43 | 0.716 | 1.7 | 24.2 | No Adj. Made |
| LOWREW5A | 9/14/21 10:49 | 26.7 | 29.6 | 0 | 43.7 | 78.1 | -0.24 | -0.2 | 0.755 | 1.7 | 24.31 | No Adj. Made |
| LOWREW5A | 10/31/21 11:46 | 28.9 | 31.1 | 0 | 40 | 51.2 | -0.06 | -0.06 | 0.446 | 1.4 | 24.39 | No Adj. Made |
| LOWREW5A | 11/19/21 9:49 | 30.9 | 33.1 | 0.1 | 35.9 | 67.5 | -0.06 | -0.11 | 0.629 | 1.6 | 24.24 | No Adj. Made |
| LOWREW5A | 12/21/21 9:58 | 25.5 | 28.2 | 0.3 | 46 | 53.6 | -0.52 | -0.51 | 0.472 | 1.4 | 24.23 | No Adj. Made |
| LOWREW60 | 7/20/21 9:51 | 44.6 | 32.6 | 0.2 | 22.6 | 83.9 | -0.02 | -0.03 | 0.123 | 2.6 | 24.43 | No Adj. Made |
| LOWREW60 | 8/31/21 7:56 | 45.1 | 33.2 | 0 | 21.7 | 74.6 | -0.35 | -0.32 | 0.355 | 4.4 | 24.16 | No Adj. Made |
| LOWREW60 | 9/14/21 9:41 | 44 | 32.5 | 0.2 | 23.3 | 73 | -0.23 | -0.23 | 0.348 | 4.4 | 24.3 | No Adj. Made |
| LOWREW60 | 10/31/21 10:13 | 45.9 | 33.2 | 0 | 20.9 | 61.5 | -0.43 | -0.43 | 0.077 | 2.1 | 24.39 | No Adj. Made |
| LOWREW60 | 11/18/21 9:24 | 47.4 | 36.3 | 0 | 16.3 | 70.8 | -0.06 | -0.04 | 0.436 | 4.9 | 24.44 | No Adj. Made |
| LOWREW60 | 12/21/21 8:58 | 47.6 | 33 | 0.3 | 19.1 | 62.4 | -0.29 | -0.28 | 0.313 | 4.2 | 24.3 | No Adj. Made |
| LOWREW61 | 7/20/21 10:21 | 36.5 | 28.5 | 0.3 | 34.7 | 85.3 | -0.04 | -0.04 | 0.283 | 3.9 | 24.43 | No Adj. Made |
| LOWREW61 | 8/31/21 8:20 | 38.7 | 30.7 | 0 | 30.6 | 76 | -0.42 | -0.42 | 0.348 | 4.3 | 24.17 | No Adj. Made |
| LOWREW61 | 9/14/21 10:08 | 36.8 | 30.3 | 0.1 | 32.8 | 72.7 | -0.1 | -0.11 | 0.375 | 4.5 | 24.3 | No Adj. Made |
| LOWREW61 | 10/31/21 10:51 | 39.3 | 31.5 | 0 | 29.2 | 61.5 | -0.25 | -0.26 | 0.155 | 2.9 | 24.38 | No Adj. Made |
| LOWREW61 | 11/18/21 10:24 | 43.3 | 34 | 0 | 22.7 | 69.5 | -0.06 | -0.04 | 0.486 | 5.2 | 24.42 | No Adj. Made |
| LOWREW61 | 12/21/21 9:23 | 39.3 | 31.3 | 0.4 | 29 | 63.1 | -0.2 | -0.21 | 0.406 | 4.7 | 24.19 | No Adj. Made |
| LOWREW62 | 7/20/21 10:02 | 35.5 | 27.1 | 0.4 | 37 | 87.5 | -0.41 | -0.4 | 0.293 | 4 | 24.42 | No Adj. Made |
| LOWREW62 | 8/31/21 8:06 | 36.6 | 29.4 | 0.1 | 33.9 | 77.4 | -0.87 | -0.85 | 0.436 | 4.8 | 24.16 | No Adj. Made |
| LOWREW62 | 9/14/21 9:51 | 37.8 | 30.3 | 0 | 31.9 | 74.3 | -0.62 | -0.64 | 0.5 | 5.2 | 24.3 | No Adj. Made |

**APPENDIX D-1**
**LANDFILL GAS EXTRACTION WELL MONITORING**
**JULY THROUGH DECEMBER 2021 OPERATIONS AND MAINTENANCE REPORT**
**LOWRY LANDFILL SUPERFUND SITE**

| ID | Date/Time | Methane (%)[a/] | Carbon Dioxide (%) | Oxygen (%) | Balance (%) | Initial Temperature (°F)[b/] | Initial Static Pressure ("$H_2O$)[c/] | Adjusted Static Pressure ("$H_2O$) | Header Pressure ("$H_2O$) | Initial Flow (scfm)[d/] | Barometric Pressure ("Hg)[e/] | Comments |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| LOWREW62 | 10/31/21 10:27 | 40.6 | 30.2 | 0 | 29.2 | 64 | -0.69 | -0.68 | 0.185 | 3.2 | 24.38 | No Adj. Made |
| LOWREW62 | 11/18/21 9:46 | 41.7 | 32.8 | 0 | 25.5 | 69.7 | -0.29 | -0.29 | 0.319 | 4.2 | 24.43 | No Adj. Made |
| LOWREW62 | 12/21/21 9:09 | 37.5 | 29.3 | 0.2 | 33 | 61.7 | -0.45 | -0.47 | 0.145 | 2.8 | 24.2 | No Adj. Made |
| LOWREW63 | 7/20/21 10:30 | 33.1 | 31.9 | 0.4 | 34.6 | 84.4 | -0.24 | -0.24 | 0.166 | 2.9 | 24.42 | No Adj. Made |
| LOWREW63 | 8/31/21 8:30 | 34.3 | 34.6 | 0 | 31.1 | 73 | -0.72 | -0.72 | 0.17 | 3 | 24.17 | No Adj. Made |
| LOWREW63 | 9/14/21 10:20 | 33.3 | 34.1 | 0 | 32.6 | 71 | -0.4 | -0.22 | 0.189 | 3.2 | 24.3 | No Adj. Made |
| LOWREW63 | 10/31/21 11:06 | 34.4 | 33.8 | 0 | 31.8 | 56.7 | -0.57 | -0.56 | 0.043 | 1.5 | 24.38 | No Adj. Made |
| LOWREW63 | 11/18/21 10:55 | 43.7 | 39.6 | 0 | 16.7 | 66.5 | -0.07 | -0.02 | 0.422 | 4.8 | 24.41 | No Adj. Made |
| LOWREW63 | 12/21/21 9:32 | 33.7 | 34.9 | 0.3 | 31.1 | 57.3 | -0.68 | -0.7 | 0.198 | 3.3 | 24.19 | No Adj. Made |
| LOWREW64 | 7/20/21 10:26 | 37.2 | 35.1 | 0.6 | 27.1 | 85.5 | -1.58 | -1.57 | 0.176 | 3 | 24.42 | No Adj. Made |
| LOWREW64 | 8/31/21 8:25 | 36.7 | 35 | 0 | 28.3 | 75.4 | -2.38 | -2.37 | 0.209 | 3.3 | 24.16 | No Adj. Made |
| LOWREW64 | 9/14/21 10:14 | 36.6 | 35.4 | 0 | 28 | 71.7 | -2.1 | -2.11 | 0.246 | 3.6 | 24.29 | No Adj. Made |
| LOWREW64 | 10/31/21 10:57 | 40 | 35.6 | 0.6 | 23.8 | 57.5 | -1.54 | -1.53 | 0.123 | 2.6 | 24.38 | No Adj. Made |
| LOWREW64 | 11/18/21 10:42 | 43.3 | 39.3 | 0 | 17.4 | 65.7 | -1.13 | -1.13 | 0.21 | 3.4 | 24.42 | No Adj. Made |
| LOWREW64 | 12/21/21 9:28 | 35.5 | 34.9 | 0.3 | 29.3 | 54.8 | -1.48 | -1.46 | 0.044 | 1.5 | 24.19 | No Adj. Made |

a/ % = Percent
b/ Deg F = Degrees Fahrenheit
c/ " H2O = Inches of water
d/ scfm = Standard cubic feet per minute
e/ " Hg = Inches of mercury

# APPENDIX D-2

# FLARE/GAS-TO-ENERGY PLANT STATION MONITORING

# APPENDIX D-2.1

# FLARE STATION MONITORING

# LOWRY INLET

**APPENDIX D-2.1**
**FLARE STATION MONITORING**
**JULY THROUGH DECEMBER 2021 OPERATIONS AND MAINTENANCE REPORT**
**LOWRY LANDFILL SUPERFUND SITE**

**Lowry Inlet**

| Sample Point | Date and Time | % Methane | % Carbon Dioxide | % Oxygen | % Balance Gas | Static Pressure ("$H_2O$)[a/] | Temp (°F)[b/] | Flow (scfm)[c/] | Current * Power (BTU/h)[d/] | Comments |
|---|---|---|---|---|---|---|---|---|---|---|
| LOWRINLT | 7/2/2021 14:25 | 30.9 | 28.1 | 2.1 | 38.9 | -35.17 | 59 | 197 | 3696.21 | |
| LOWRINLT | 7/8/2021 14:55 | 28.1 | 25.8 | 2.2 | 43.9 | -33.06 | 60 | 191 | 3258.9 | |
| LOWRINLT | 7/15/2021 14:54 | 28.8 | 27.6 | 2 | 41.6 | -34.92 | 60.1 | 199 | 3479.98 | |
| LOWRINLT | 7/16/2021 13:43 | 27.5 | 26.4 | 2.1 | 44 | -35.48 | 60.3 | 202 | 3373 | |
| LOWRINLT | 7/23/2021 13:08 | 27 | 26.4 | 2.2 | 44.4 | -36.52 | 61.1 | 195 | 3196.91 | |
| LOWRINLT | 7/29/2021 14:27 | 26.8 | 27.5 | 2.2 | 43.5 | -34.38 | 62 | 193 | 3140.68 | |
| LOWRINLT | 7/30/2021 10:07 | 23.9 | 26.6 | 2.5 | 47 | -33.79 | 62 | 189 | 2742.78 | |
| LOWRINLT | 8/5/2021 14:14 | 28.9 | 27.8 | 2.1 | 41.2 | -32.85 | 63.4 | 196 | 3439.42 | |
| LOWRINLT | 8/5/2021 14:22 | 39.4 | 32.2 | 0.8 | 27.6 | 8.37 | 143 | 498 | 11913.99 | |
| LOWRINLT | 8/6/2021 14:55 | 30.6 | 26.3 | 2.2 | 40.9 | -32.34 | 63 | 194 | 3604.58 | |
| LOWRINLT | 8/13/2021 12:19 | 24.3 | 25.8 | 2.5 | 47.4 | -31.59 | 63.8 | 185 | 2729.67 | |
| LOWRINLT | 8/19/2021 13:37 | 27.8 | 26.6 | 2.1 | 43.5 | -34.52 | 64 | 209 | 3527.95 | |
| LOWRINLT | 8/20/2021 16:46 | 26.4 | 25.7 | 2.6 | 45.3 | -35.7 | 64.5 | 205 | 3286.17 | |
| LOWRINLT | 8/27/2021 13:19 | 30.3 | 25.9 | 2.2 | 41.6 | -34.72 | 64 | 204 | 3753.22 | |
| LOWRINLT | 9/1/2021 13:35 | 28.1 | 26.8 | 2 | 43.1 | -35.21 | 65 | 205 | 3497.78 | |
| LOWRINLT | 9/2/2021 14:39 | 27.1 | 26.4 | 2.1 | 44.4 | -36.41 | 65 | 204 | 3356.84 | |
| LOWRINLT | 9/10/2021 14:38 | 28.5 | 28.4 | 2.2 | 40.9 | -35.3 | 65 | 204 | 3530.26 | |
| LOWRINLT | 9/15/2021 14:58 | 29.7 | 28.3 | 1.9 | 40.1 | -34.7 | 65 | 206 | 3714.97 | |
| LOWRINLT | 9/17/2021 15:41 | 25.2 | 28 | 1.7 | 45.1 | -34.1 | 65 | 205 | 3136.8 | |
| LOWRINLT | 9/24/2021 15:10 | 26 | 28.1 | 2.1 | 43.8 | -30.65 | 65 | 198 | 3125.87 | |
| LOWRINLT | 9/30/2021 15:05 | 25 | 27.2 | 1.9 | 45.9 | -29.31 | 64 | 196 | 2975.28 | |
| LOWRINLT | 10/1/2021 14:25 | 28.2 | 28.8 | 1.8 | 41.2 | -28.27 | 64 | 192 | 3287.62 | |
| LOWRINLT | 10/13/2021 15:15 | 25.4 | 27.6 | 2.4 | 44.6 | -34.63 | 209 | 63 | 971.64 | |
| LOWRINLT | 10/14/2021 14:22 | 26.1 | 25.6 | 2.3 | 46 | -34.35 | 63 | 210 | 3328.06 | |
| LOWRINLT | 10/22/2021 13:12 | 28.7 | 28.1 | 1.9 | 41.3 | -32.56 | 61 | 186 | 3241.36 | |
| LOWRINLT | 10/28/2021 16:38 | 24.2 | 26.8 | 2.5 | 46.5 | -34.55 | 60 | 192 | 2821.29 | |
| LOWRINLT | 10/29/2021 14:04 | 29.5 | 28.4 | 1.7 | 40.4 | -37.62 | 60 | 208 | 3725.78 | |
| LOWRINLT | 11/5/2021 14:00 | 24.9 | 27.3 | 1.9 | 45.9 | -33.81 | 59 | 218 | 3296 | |
| LOWRINLT | 11/11/2021 14:06 | 27.9 | 29.3 | 2 | 40.8 | -32.27 | 58 | 217 | 3676.17 | |
| LOWRINLT | 11/12/2021 13:42 | 25.6 | 25.3 | 2.4 | 46.7 | -31.85 | 58 | 216 | 3357.57 | |
| LOWRINLT | 11/18/2021 14:48 | 29.4 | 29.8 | 1.6 | 39.2 | -29.15 | 57 | 213 | 3802.41 | |
| LOWRINLT | 11/19/2021 13:06 | 32.5 | 29.7 | 1.5 | 36.3 | -29.43 | 57 | 213 | 4203.34 | |
| LOWRINLT | 11/24/2021 13:13 | 26.3 | 27.3 | 3.1 | 43.3 | -28.98 | 56 | 211 | 3366.9 | |
| LOWRINLT | 11/26/2021 10:20 | 32.7 | 28.2 | 2.9 | 36.2 | -28.47 | 56 | 213 | 4229.3 | |

**APPENDIX D-2.1**
**FLARE STATION MONITORING**
**JULY THROUGH DECEMBER 2021 OPERATIONS AND MAINTENANCE REPORT**
**LOWRY LANDFILL SUPERFUND SITE**

## Lowry Inlet

| Sample Point | Date and Time | % Methane | % Carbon Dioxide | % Oxygen | % Balance Gas | Static Pressure ("$H_2O$)[a/] | Temp (°F)[b/] | Flow (scfm)[c/] | Current * Power (BTU/h)[d/] | Comments |
|---|---|---|---|---|---|---|---|---|---|---|
| LOWRINLT | 12/2/2021 14:47 | 35.2 | 27.8 | 3.5 | 33.5 | -27.55 | 55 | 200 | 4272.6 | |
| LOWRINLT | 12/3/2021 13:22 | 33.4 | 28.1 | 3 | 35.5 | -25.59 | 55 | 201 | 4072.8 | |
| LOWRINLT | 12/7/2021 12:50 | 33 | 29.9 | 2.2 | 34.9 | -24.77 | 55 | 188 | 3767.5 | |
| LOWRINLT | 12/16/2021 14:27 | 27.8 | 28 | 1.9 | 42.3 | -17.51 | 53 | 191 | 3224.11 | |
| LOWRINLT | 12/17/2021 14:36 | 25.1 | 27.8 | 3.1 | 44 | -17.36 | 53 | 186 | 2834.77 | |
| LOWRINLT | 12/29/2021 15:11 | 26.4 | 27.6 | 3.2 | 42.8 | -13.83 | 51 | 193 | 3093.81 | |
| LOWRINLT | 12/30/2021 14:44 | 31.3 | 29.4 | 1.8 | 37.5 | -11.28 | 51 | 126 | 2394.68 | |

***** Note: The BTU calculation is based upon a methane value of **1009.7** BTU/scf at standard conditions. This data is taken from the petroleum industry book "Gas Processors Association Engineering Data Book", Ninth Edition, Tulsa OK, 1972.

a/ "$H_2O$=inches of water

b/ °F= Degrees Fahrenheit

c/ scfm= standard cubic feet per minute

d/ BTU/h= British Thermal Unit per hour

# APPENDIX D-2.2

# FLARE STATION MONITORING

# DADS BLOWER FLARE

**APPENDIX D-2.2**
**GAS-TO-ENERGY PLANT MONITORING**
**JULY THROUGH DECEMBER 2021 OPERATIONS AND MAINTENANCE REPORT**
**LOWRY LANDFILL SUPERFUND SITE**

## DADS Blower Flare

| Location | Sample Point | Date and Time | Methane (%) | Carbon Dioxide (%) | Oxygen (%) | Balance Gas (%) | Initial Static Pressure (" H2O)[a/] | Initial Temperature (° F)[b/] | Initial Flow (scfm)[c/] | Initial Power (BTU/h)[d/] | Comments |
|---|---|---|---|---|---|---|---|---|---|---|---|
| DADS Blower Flare | DASPFLR1 | 7/2/2021 14:32 | 41.1 | 33 | 0.6 | 25.3 | 7.76 | 135 | 497 | 12403.09 | |
| DADS Blower Flare | DASPFLR1 | 7/8/2021 15:02 | 38.3 | 32.2 | 0.6 | 28.9 | 8.3 | 143 | 500 | 11627.88 | |
| DADS Blower Flare | DASPFLR1 | 7/16/2021 13:51 | 37.3 | 32 | 0.6 | 30.1 | 8.25 | 143 | 500 | 11324.28 | |
| DADS Blower Flare | DASPFLR1 | 7/23/2021 13:15 | 36.8 | 32 | 0.7 | 30.5 | 7.21 | 146 | 503 | 11239.51 | |
| DADS Blower Flare | DASPFLR1 | 7/29/2021 14:37 | 35.3 | 32.7 | 0.7 | 31.3 | 8.32 | 146 | 499 | 10695.65 | |
| DADS Blower Flare | DASPFLR1 | 8/6/2021 15:02 | 41.4 | 31.3 | 0.6 | 26.7 | 8.33 | 141 | 506 | 12719.87 | |
| DADS Blower Flare | DASPFLR1 | 8/13/2021 12:29 | 32.6 | 31.4 | 0.8 | 35.2 | 8.37 | 140 | 502 | 9936.95 | |
| DADS Blower Flare | DASPFLR1 | 8/20/2021 16:52 | 35.9 | 32.4 | 0.7 | 31 | 8.3 | 144 | 500 | 10899.24 | |
| DADS Blower Flare | DASPFLR1 | 8/27/2021 13:28 | 43.3 | 32.9 | 0.4 | 23.4 | 8.36 | 151 | 496 | 13040.71 | |
| DADS Blower Flare | DASPFLR1 | 9/1/2021 13:46 | 39.9 | 31.9 | 0.5 | 27.7 | 8.17 | 148 | 500 | 12113.64 | |
| DADS Blower Flare | DASPFLR1 | 9/2/2021 14:51 | 36.5 | 31.9 | 0.6 | 31 | 8.13 | 147 | 496 | 10992.75 | |
| DADS Blower Flare | DASPFLR1 | 9/10/2021 14:46 | 40.1 | 33.8 | 0.6 | 25.5 | 8.05 | 129 | 497 | 12101.31 | |
| DADS Blower Flare | DASPFLR1 | 9/15/2021 15:07 | 42.1 | 34.2 | 0.6 | 23.1 | 8.12 | 128 | 501 | 12807.12 | |
| DADS Blower Flare | DASPFLR1 | 9/24/2021 15:17 | 36.6 | 33.1 | 0.6 | 29.7 | 8.41 | 143 | 497 | 11045.09 | |
| DADS Blower Flare | DASPFLR1 | 10/1/2021 14:32 | 39.2 | 33 | 0.5 | 27.3 | 8.28 | 137 | 504 | 11996.33 | |
| DADS Blower Flare | DASPFLR1 | 10/13/2021 15:26 | 36.2 | 32.9 | 0.8 | 30.1 | 7.98 | 126 | 502 | 11034.28 | |
| DADS Blower Flare | DASPFLR1 | 10/22/2021 13:22 | 41.7 | 34.7 | 0.4 | 23.2 | 7.56 | 120 | 503 | 12736.08 | |
| DADS Blower Flare | DASPFLR1 | 10/28/2021 16:46 | 33.5 | 30.4 | 1.2 | 34.9 | 7.61 | 117 | 508 | 10333.33 | |
| DADS Blower Flare | DASPFLR1 | 11/5/2021 14:08 | 35.7 | 32.2 | 0.6 | 31.5 | 8.19 | 118 | 497 | 10773.49 | |
| DADS Blower Flare | DASPFLR1 | 11/11/2021 14:16 | 40.2 | 34.9 | 0.6 | 24.3 | 7.73 | 111 | 499 | 12180.31 | |
| DADS Blower Flare | DASPFLR1 | 11/12/2021 13:53 | 36.9 | 30.5 | 0.7 | 31.9 | 7.62 | 112 | 498 | 11158.03 | |
| DADS Blower Flare | DASPFLR1 | 11/19/2021 13:19 | 42.5 | 34.5 | 0.4 | 22.6 | 7.99 | 109 | 500 | 12903 | |
| DADS Blower Flare | DASPFLR1 | 11/24/2021 13:21 | 36 | 33.4 | 1.2 | 29.4 | 7.53 | 102 | 503 | 10994.8 | |
| DADS Blower Flare | DASPFLR1 | 11/26/2021 10:29 | 45.2 | 35 | 0.7 | 19.1 | 7.87 | 110 | 505 | 13869.6 | |
| DADS Blower Flare | DASPFLR1 | 12/2/2021 15:00 | 47.6 | 35.1 | 0.8 | 16.5 | 7.61 | 99 | 507 | 14657 | |
| DADS Blower Flare | DASPFLR1 | 12/3/2021 13:33 | 48.4 | 35.4 | 0.6 | 15.6 | 7.76 | 105 | 499 | 14670.4 | |
| DADS Blower Flare | DASPFLR1 | 12/7/2021 12:58 | 44.5 | 35.9 | 0.7 | 18.9 | 7.63 | 99 | 501 | 13550.7 | |
| DADS Blower Flare | DASPFLR1 | 12/17/2021 14:42 | 35.1 | 33.4 | 1 | 30.5 | 7.02 | 85 | 501 | 10677.67 | |
| DADS Blower Flare | DASPFLR1 | 12/29/2021 15:18 | 37.3 | 34.9 | 0.7 | 27.1 | 7.13 | 79 | 500 | 11324.28 | |

***** Note: The BTU calculation is based upon a methane value of **1009.7** BTU/scf at standard conditions. This data is taken from the petroleum industry book "Gas Processors Association Engineering Data Book", Ninth Edition, Tulsa OK, 1972.

a/ "$H_2O$= inches water

b/ ° F= Degrees Fahrenheit

c/ scfm= standard cubic feet per minute

d/ BTU/h= British Thermal Unit per hour

# APPENDIX D-2.3

# FLARE STATION MONITORING

# FLARE STATION 3

**APPENDIX D-2.3**
**GAS-TO-ENERGY PLANT MONITORING**
**JULY THROUGH DECEMBER 2021 OPERATIONS AND MAINTENANCE REPORT**
**LOWRY LANDFILL SUPERFUND SITE**

## Flare Station 3 - Candlestick Flare

| Location | Sample Point | Date Time | Methane (%) | Carbon Dioxide (%) | Oxygen (%) | Balance Gas (%) | Initial Static Pressure (" H2O)[a/] | Initial Temperature (° F)[b/] | Initial Flow (scfm)[c/] | Initial Power (BTU/h)[d/] | Comments |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Flare Station 3 | DASPFLR3 | 7/2/2021 14:41 | 49.4 | 36.7 | 0.7 | 13.2 | 5.42 | 102 | 1095 | 32845.27 | |
| Flare Station 3 | DASPFLR3 | 7/8/2021 15:10 | 47.8 | 35.9 | 0.9 | 15.4 | 8.73 | 109 | 1327 | 38515.06 | |
| Flare Station 3 | DASPFLR3 | 7/16/2021 14:01 | 49.3 | 37.6 | 0.4 | 12.7 | 8.77 | 110 | 1343 | 40202.65 | |
| Flare Station 3 | DASPFLR3 | 7/23/2021 13:26 | 48 | 36.7 | 0.3 | 15 | 4.31 | 109 | 911 | 26551.64 | |
| Flare Station 3 | DASPFLR3 | 7/29/2021 14:49 | 49.2 | 37.9 | 0.4 | 12.5 | 5.34 | 108 | 1015 | 30322.35 | |
| Flare Station 3 | DASPFLR3 | 8/5/2021 14:34 | 50.7 | 36.7 | 0.6 | 12 | 4.68 | 109 | 1016 | 31277.6 | |
| Flare Station 3 | DASPFLR3 | 8/6/2021 15:11 | 50 | 36.3 | 0.3 | 13.4 | 5.25 | 106 | 1117 | 33912.12 | |
| Flare Station 3 | DASPFLR3 | 8/13/2021 12:45 | 47.4 | 36.9 | 0.5 | 15.2 | 3.08 | 106 | 917 | 26392.43 | |
| Flare Station 3 | DASPFLR3 | 8/20/2021 16:59 | 46.2 | 36.3 | 0.4 | 17.1 | 2.72 | 102 | 857 | 24041.11 | |
| Flare Station 3 | DASPFLR3 | 8/27/2021 13:37 | 52.3 | 36.2 | 0.2 | 11.3 | 5.65 | 111 | 1053 | 33439.66 | |
| Flare Station 3 | DASPFLR3 | 9/1/2021 14:01 | 52.3 | 36.1 | 0.4 | 11.2 | 6.4 | 110 | 1118 | 35503.83 | |
| Flare Station 3 | DASPFLR3 | 9/2/2021 15:02 | 50.5 | 37.2 | 0.3 | 12 | 6.1 | 108 | 1068 | 32748.72 | |
| Flare Station 3 | DASPFLR3 | 9/10/2021 15:02 | 51.3 | 37.8 | 0.4 | 10.5 | 10.61 | 117 | 1472 | 45851.86 | |
| Flare Station 3 | DASPFLR3 | 9/15/2021 15:16 | 51.3 | 38.1 | 0.4 | 10.2 | 10.68 | 117 | 1416 | 44107.49 | |
| Flare Station 3 | DASPFLR3 | 9/24/2021 15:26 | 49.5 | 38.5 | 0.3 | 11.7 | 9.02 | 109 | 1391 | 41808.45 | |
| Flare Station 3 | DASPFLR3 | 10/1/2021 14:41 | 49 | 37.6 | 0.3 | 13.1 | 8.37 | 107 | 1297 | 38589.38 | |
| Flare Station 3 | DASPFLR3 | 10/13/2021 15:37 | 48.2 | 38 | 0.4 | 13.4 | 11.32 | 110 | 1558 | 45598.05 | |
| Flare Station 3 | DASPFLR3 | 10/22/2021 13:38 | 50.9 | 38.4 | 0.1 | 10.6 | 6.15 | 105 | 1199 | 37056.87 | |
| Flare Station 3 | DASPFLR3 | 10/28/2021 17:00 | 46.7 | 37.3 | 0.6 | 15.4 | 10.16 | 103 | 1547 | 43867.1 | |
| Flare Station 3 | DASPFLR3 | 11/5/2021 14:21 | 47.7 | 36.5 | 0.3 | 15.5 | 7.48 | 104 | 1222 | 35393.32 | |
| Flare Station 3 | DASPFLR3 | 11/11/2021 14:26 | 49 | 38.4 | 0.4 | 12.2 | 6.88 | 95 | 1168 | 34751.27 | |
| Flare Station 3 | DASPFLR3 | 11/12/2021 14:04 | 47.3 | 34.1 | 0.4 | 18.2 | 5.84 | 95 | 1124 | 32281.91 | |
| Flare Station 3 | DASPFLR3 | 11/19/2021 13:34 | 50 | 38.7 | 0.5 | 10.8 | 6.3 | 100 | 1160 | 35217.6 | |
| Flare Station 3 | DASPFLR3 | 11/24/2021 13:34 | 48.9 | 39.5 | 0.8 | 10.8 | 4.45 | 84 | 1002 | 29765.4 | |
| Flare Station 3 | DASPFLR3 | 11/26/2021 10:40 | 55.3 | 38.7 | 0.5 | 5.5 | 5.64 | 96 | 1105 | 34140.8 | |
| Flare Station 3 | DASPFLR3 | 12/2/2021 15:15 | 53.6 | 38.9 | 0.6 | 6.9 | 6.37 | 99 | 1171 | 34140.8 | |
| Flare Station 3 | DASPFLR3 | 12/3/2021 13:46 | 55.7 | 39.2 | 0.5 | 4.6 | 5.92 | 82 | 1197 | 34140.8 | |
| Flare Station 3 | DASPFLR3 | 12/7/2021 13:13 | 53.3 | 39.1 | 0.7 | 6.9 | 3.55 | 91 | 910 | 29468.7 | |
| Flare Station 3 | DASPFLR3 | 12/17/2021 14:54 | 45.7 | 38.3 | 0.7 | 15.3 | 4.78 | 84 | 1088 | 30190.96 | |
| Flare Station 3 | DASPFLR3 | 12/29/2021 15:31 | 47.4 | 38.7 | 0.5 | 13.4 | 4.52 | 79 | 1036 | 29817.41 | |

***** Note: The BTU calculation is based upon a methane value of **1009.7** BTU/scf at standard conditions. This data is taken from the petroleum industry book "Gas Processors Association Engineering Data Book", Ninth Edition, Tulsa OK, 1972

a/ "$H_2O$= inches water

b/ ° F= Degrees Fahrenheit

c/ scfm= standard cubic feet per minute

d/ BTU/h= British Thermal Unit per hour

# APPENDIX D-2.4

# FLARE STATION MONITORING

# COMBINED SOURCES AT GAS-TO-ENERGY PLANT

**APPENDIX D-2.4**
**GAS-TO-ENERGY PLANT MONITORING**
**JULY THROUGH DECEMBER 2021 OPERATIONS AND MAINTENANCE REPORT**
**LOWRY LANDFILL SUPERFUND SITE**

## Gas-to-Energy Plant

| Location | Sample Point | Date and Time | Methane (%) | Carbon Dioxide (%) | Oxygen (%) | Balance Gas (%) | Initial Static Pressure (" $H_2O$)[a/] | Initial Temperature (° F)[b/] | Initial Flow (scfm)[c/] | Initial Power (BTU/h)[d/] | Comments |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Gas Plant | DASPGAP1 | 7/2/2021 14:47 | 52.2 | 38.9 | 0.7 | 8.2 | 66.08 | 86 | 1020.2 | 32336.1 | |
| Gas Plant | DASPGAP1 | 7/8/2021 15:16 | 50.9 | 38.2 | 0.9 | 10 | 68.89 | 96 | 736.5 | 22762.62 | |
| Gas Plant | DASPGAP1 | 7/16/2021 14:17 | 52.9 | 39.2 | 0.3 | 7.6 | 72.47 | 89 | 716.1 | 23001.76 | |
| Gas Plant | DASPGAP1 | 7/23/2021 13:42 | 52.3 | 39.1 | 0.2 | 8.4 | 65.87 | 93 | 990.3 | 31448.52 | |
| Gas Plant | DASPGAP1 | 7/29/2021 15:02 | 53 | 40 | 0.3 | 6.7 | 67.07 | 91 | 980.7 | 31560.5 | |
| Gas Plant | DASPGAP1 | 8/5/2021 14:44 | 54.1 | 39.3 | 0.4 | 6.2 | 67.54 | 91 | 955.8 | 31397.57 | |
| Gas Plant | DASPGAP1 | 8/6/2021 15:16 | 54.9 | 39.1 | 0.2 | 5.8 | 65.98 | 89 | 973.6 | 32455.23 | |
| Gas Plant | DASPGAP1 | 8/13/2021 13:04 | 53.7 | 39.8 | 0.4 | 6.1 | 66.68 | 82 | 990.4 | 32293.62 | |
| Gas Plant | DASPGAP1 | 8/20/2021 17:09 | 54.2 | 39.8 | 0.3 | 5.7 | 66.81 | 78 | 950.3 | 31274.6 | |
| Gas Plant | DASPGAP1 | 8/27/2021 14:34 | 56.9 | 39.6 | 0.2 | 3.3 | 78.8 | 93 | 675.9 | 23352.13 | |
| Gas Plant | DASPGAP1 | 9/1/2021 14:09 | 56 | 40 | 0.2 | 3.8 | 81.39 | 88 | 491.5 | 16712.57 | |
| Gas Plant | DASPGAP1 | 9/2/2021 15:13 | 55.4 | 39.7 | 0.2 | 4.7 | 81 | 79 | 492 | 16550.33 | |
| Gas Plant | DASPGAP1 | 9/10/2021 15:10 | 54.8 | 39.7 | 0.3 | 5.2 | 68.55 | 96 | 924.4 | 30759 | |
| Gas Plant | DASPGAP1 | 9/15/2021 15:25 | 54.3 | 39.4 | 0.3 | 6 | 67.29 | 89 | 968.2 | 31922.48 | |
| Gas Plant | DASPGAP1 | 9/24/2021 15:33 | 52.3 | 40.3 | 0.3 | 7.1 | 68.99 | 76 | 993.3 | 31543.79 | |
| Gas Plant | DASPGAP1 | 10/1/2021 14:46 | 52.5 | 39.3 | 0.2 | 8 | 64.36 | 85 | 992.6 | 31642.1 | |
| Gas Plant | DASPGAP1 | 10/13/2021 15:49 | 51.6 | 39.9 | 0.2 | 8.3 | 68.71 | 83 | 775.8 | 24306.99 | |
| Gas Plant | DASPGAP1 | 10/22/2021 13:45 | 51.7 | 38.8 | 0.1 | 9.4 | 69.89 | 75 | 1010.3 | 31715.58 | |
| Gas Plant | DASPGAP1 | 10/28/2021 17:08 | 51.4 | 38.8 | 0.3 | 9.5 | 80.11 | 77 | 605.4 | 18894.58 | |
| Gas Plant | DASPGAP1 | 11/5/2021 14:28 | 52.1 | 38.6 | 0.2 | 9.1 | 69.98 | 74 | 1073 | 33944.48 | |
| Gas Plant | DASPGAP1 | 11/11/2021 14:36 | 53.5 | 40 | 0.3 | 6.2 | 68.06 | 78 | 1065.6 | 34616.23 | |
| Gas Plant | DASPGAP1 | 11/12/2021 14:14 | 52.8 | 35.8 | 0.4 | 11 | 69.27 | 80 | 1089.2 | 34919.93 | |
| Gas Plant | DASPGAP1 | 11/19/2021 13:42 | 53.5 | 39 | 0.4 | 7.1 | 69.87 | 80 | 1083.1 | 35184.72 | |
| Gas Plant | DASPGAP1 | 11/24/2021 13:42 | 53.1 | 40.4 | 0.8 | 5.7 | 69.02 | 81 | 1145.5 | 34140.8 | |
| Gas Plant | DASPGAP1 | 11/26/2021 10:52 | 54.6 | 39.7 | 0.6 | 5.1 | 69.04 | 70 | 1108.5 | 34140.8 | |
| Gas Plant | DASPGAP1 | 12/2/2021 15:22 | 56.7 | 39.7 | 0.5 | 3.1 | 69.5 | 71 | 1036.5 | 34140.8 | |
| Gas Plant | DASPGAP1 | 12/3/2021 13:53 | 57.4 | 40 | 0.5 | 2.1 | 68.87 | 70 | 1031.1 | 34140.8 | |
| Gas Plant | DASPGAP1 | 12/7/2021 13:22 | 55.1 | 40.3 | 0.6 | 4 | 68.7 | 79 | 1053.3 | 34140.8 | |
| Gas Plant | DASPGAP1 | 12/17/2021 15:00 | 50.8 | 39.2 | 0.7 | 9.3 | 68.9 | 62 | 808.8 | 24948.05 | |
| Gas Plant | DASPGAP1 | 12/29/2021 15:38 | 50.9 | 39.4 | 0.5 | 9.2 | 69.72 | 63 | 790.8 | 24440.84 | |

* Note: The BTU calculation is based upon a methane value of 1009.7 BTU/scf at standard conditions. This data is taken from the petroleum industry book "Gas Processors Association Engineering Data Book", Ninth Edition, Tulsa OK, 1972.

a/ "$H_2O$= inches water

b/ ° F= Degrees Fahrenheit

c/ scfm= standard cubic feet per minute

d/ BTU/h= British Thermal Unit per hour

# APPENDIX D-2.5

# FLARE STATION MONITORING

# DAILY FIELD NOTES

# Collection and Control System Monitoring

| Day of Week | Monday | Tuesday | Wednesday | Thursday | Friday |
|---|---|---|---|---|---|
| Date (mm/dd/yy) | | | | 07/08/21 | |
| **Lowry Header - Monitoring** | | | | | |
| Time (hh:mm) | | | | 1451 | |
| Technician (initials) | | | | CL | |
| ***Control Panel - Digital Recorder*** | | | | | |
| Flow Rate (SCFM) | | | | 191 | |
| Gas Temperature (F) | | | | 60.0 | |
| **Flare 2 - Monitoring** | | | | | |
| Time (hh:mm) | | | | 1457 | |
| Technician (initials) | | | | CL | |
| ***Control Panel*** | | | | | |
| *Indicator Lights OK (Check for Yes) | ☐ | ☐ | ☐ | ✓ | ☐ |
| Heating/Cooling OK (Check for Yes) | ☐ | ☐ | ☐ | ✓ | ☐ |
| ***Control Panel - Digital Recorder*** | | | | | |
| Local Recorder On (Check for Yes) | ☐ | ☐ | ☐ | ✓ | ☐ |
| ***Control Panel - Touchscreen - Process Overview*** | | | | | |
| *Gas Handling Skid Inlet Pressure (inWC) | | | | 39.8 | |
| *Flare DP (inWC) | | | | 5.5 | |
| *Flare Flame Temperature (F) | | | | 1274 | |
| ***Control Panel - Touchscreen*** *(Press Next)* | | | | | |
| Panel Temperature (F) | | | | 79 | |
| *Gas Handling Skid Inlet Temperature (F) | | | | 64 | |
| *Recirculation Valve Position (%Closed) | | | | 70 | |
| ***Control Panel - Touchscreen - Flare Flow Data*** *(Press Back 2x, Flare Flow Data)* | | | | | |
| *Flow Rate (SCFM) | | | | 500 | |
| *Total Flow (MMSCF) | | | | 934.05 | |
| *Flow Pressure (inWC) | | | | 7.0 | |
| *Flow Temperature (F) | | | | 143 | |
| ***Control Panel - Touchscreen*** *(Press Resettable Flow History, Analog Data Menu, Blower Data)* | | | | | |
| *Resettable Total Flow (MMSCF) | | | | 340.39 | |
| *Reset Date/Time (mm/dd/yy hh:mm:ss) | | | | | |
| ***Control Panel - Touchscreen - Blower Data*** *(Press Main)* | | | | | |
| *Blower 301 Runtime (Hours) | | | | 35406 | |
| *Blower 301 Vibration (in/Sec) | | | | 0.24 | |
| *Blower 301 Speed (%Max) | | | | 91 | |
| *Blower 301 Inlet Bearing Temp (F) | | | | 112 | |
| *Blower 301 Outlet Bearing Temp (F) | | | | 142 | |
| ***Control Panel - Blower Keypad*** | | | | | |
| *Blower 301 Current (Amps) | | | | 14.1 | |
| ***Gas Handling Skid*** | | | | | |
| *Demister Inlet Pressure (inWC) | | | | -40.3 | |
| *Demister Outlet Pressure (inWC) | | | | -43.0 | |
| *Demister DP (inWC) | | | | +2.7 | |
| *Flame Arrester Inlet Pressure (inWC) | | | | +8.1 | |
| *Flame Arrester Outlet Pressure (inWC) | | | | +5.0 | |
| *Flame Arrester DP (inWC) | | | | +3.1 | |
| ***Flare*** | | | | | |
| *Visible Emissions (Yes/No, If yes explain) | | | | NO | |
| *Spiralator Position (%Open) | | | | 50 | |
| *Manual Louver 1 Position (%Open) | | | | 50 | |
| *Manual Louver 2 Position (%Open) | | | | 50 | |
| ***Other*** | | | | | |
| Heat Trace OK (Check for Yes) | ☐ | ☐ | ☐ | ✓ | ☐ |
| *Propane Tank Level OK (T1 \| T2 (Check for Yes)) | ☐ ☐ | ☐ ☐ | ☐ ☐ | ✓ ✓ | ☐ ☐ |
| **Flare 3 - Monitoring** | | | | | |
| Time (hh:mm) | | | | 1504 | |
| Technician (initials) | | | | CL | |
| ***Control Panel*** | | | | | |
| *Indicator Lights OK (Check for Yes) | ☐ | ☐ | ☐ | ✓ | ☐ |
| *Heating/Cooling OK (Check for Yes) | ☐ | ☐ | ☐ | ✓ | ☐ |
| ***Control Panel - Digital Recorder*** | | | | | |
| *Remote Recorder On (Check for Yes) | ☐ | ☐ | ☐ | ✓ | ☐ |

# Collection and Control System Monitoring

| Day of Week | Monday | Tuesday | Wednesday | Thursday | Friday |
|---|---|---|---|---|---|
| ***Control Panel - Touchscreen - Analog Data Menu - Process Overview*** | | | | | |
| *Gas Handling Skid Inlet Vacuum (inWC) | | | | 40.0 | |
| *Gas Handling Skid Inlet Temperature (F) | | | | 69 | |
| *Panel Temperature (F) | | | | 125 | |
| *Recirculation Valve Position (%Closed) | | | | 100 | |
| *Flare Flame Temperature (F) | | | | 1312 | |
| *Flame Arrestor Temperature (F) | | | | 109 | |
| ***Control Panel - Touchscreen - Blower Data*** *(Press Back, Blower Menu, Select Current Blower)* | | | | | |
| *Blower Runtime (Blower \| Runtime (Hours)) | | | | 30( 1413 | |
| *Blower Speed (Blower \| Speed (%Max)) | | | | 72 | |
| *Blower Vibration (Blower \| Vibration (in/Sec)) | | | | 0.05 | |
| *Blower Current (Blower \| Current (Amps)) | | | | 37.5 | |
| ***Control Panel - Touchscreen - Flare Flow Data*** *(Press Back X2, Flare Flow Data)* | | | | | |
| *Flow Rate (SCFM) | | | | 1327 | |
| *Total Flow (MMSCF) | | | | 60.94 | |
| *Flow Pressure (inWC) | | | | 7.4 | |
| *Flow Temperature (F) | | | | 109 | |
| *Flow DP (inWC) | | | | 4.46 | |
| ***Control Panel - Touchscreen*** *(Press Resettable)* | | | | | |
| *Resettable Total Flow (MMSCF) | | | | 60.94 | |
| *Reset Date/Time (mm/dd/yy hh:mm ss) | | | | | |
| ***Control Panel - Touchscreen - Alarm History*** *(Press Main)* | | | | | |
| *Alarm History (Check box if no alarm) | ☐ | ☐ | ☐ | ✓ | ☐ |
| ***Gas Handling Skid*** | | | | | |
| *Demister Inlet Pressure (inWC) | | | | -39.7 | |
| *Demister Outlet Pressure (inWC) | | | | -41.2 | |
| *Demister DP (inWC) | | | | +1.5 | |
| *Flame Arrester Inlet Pressure (inWC) | | | | +8.4 | |
| *Flame Arrester Outlet Pressure (inWC) | | | | +7.7 | |
| *Flame Arrester DP (inWC) | | | | +0.7 | |
| *Fail-Close Valve Air Pressure (psi) | | | | 105 | |
| ***Flare*** | | | | | |
| *Visible Emissions (Yes/No, If yes explain) | | | | NO | |
| *Spiralator Position (%Open) | | | | 50 | |
| *Manual Louver 1 Position (%Open) | | | | 50 | |
| *Manual Louver 2 Position (%Open) | | | | 50 | |
| ***Other*** | | | | | |
| *Heat Trace OK (Check for Yes) | ☐ | ☐ | ☐ | ✓ | ☐ |
| *Propane Tank Level OK (T1 \| T2 (Check for Yes)) | ☐ | ☐ | ☐ | ✓ | ☐ |
| ***Engine Plant 1 - Monitoring*** | | | | | |
| Time (hh mm) | | | | 0811 | |
| Technician (Initials) | | | | AM | |
| ***Engine Control Panel*** | | | | | |
| *Power Setpoint (kWh) (Engine #4 \| #3) | | | | 633 652 | |
| *Power Setpoint (kWh) (Engine #2 \| #1) | | | | 710 | |
| ***Control Room - Laptop*** | | | | | |
| *Flow Total (MSCF) | | | | 2626.11.6 | |
| *Flow Rate (SCFM) | | | | 734.5 | |
| *Discharge Gas Temperature (F) | | | | 960 | |
| ***Engine Bay/Control Room Window*** | | | | | |
| *Inlet Gas Pressure (inWC) | | | | -43.9 | |
| ***Other*** | | | | | |
| *Visible Emissions (Yes/No, If yes explain) | | | | NO | |

***Note * Collect during device operation only***

**Remarks**

07/08 - Engine #2 Down

# Collection and Control System Monitoring

| Day of Week | Monday | Tuesday | Wednesday | Thursday | Friday |
|---|---|---|---|---|---|
| Date (mm/dd/yy) | | | | | 07/23/21 |
| ***Lowry Header - Monitoring*** | | | | | |
| Time (hh:mm) | | | | | 1305 |
| Technician (Initials) | | | | | CS |
| ***Control Panel - Digital Recorder*** | | | | | |
| Flow Rate (SCFM) | | | | | 195 |
| Gas Temperature (F) | | | | | 61.1 |
| ***Flare 2 - Monitoring*** | | | | | |
| Time (hh:mm) | | | | | 1310 |
| Technician (Initials) | | | | | CS |
| ***Control Panel*** | | | | | |
| *Indicator Lights OK (Check for Yes) | ☐ | ☐ | ☐ | ☐ | ✓ |
| Heating/Cooling OK (Check for Yes) | ☐ | ☐ | ☐ | ☐ | ✓ |
| ***Control Panel - Digital Recorder*** | | | | | |
| Local Recorder On (Check for Yes) | ☐ | ☐ | ☐ | ☐ | ✓ |
| ***Control Panel - Touchscreen - Process Overview*** | | | | | |
| *Gas Handling Skid Inlet Pressure (inWC) | | | | | 42.7 |
| *Flare DP (inWC) | | | | | 5.55 |
| *Flare Flame Temperature (F) | | | | | 1304 |
| ***Control Panel - Touchscreen*** *(Press Next)* | | | | | |
| Panel Temperature (F) | | | | | 84 |
| *Gas Handling Skid Inlet Temperature (F) | | | | | 64 |
| *Recirculation Valve Position (%Closed) | | | | | 90 |
| ***Control Panel - Touchscreen - Flare Flow Data*** *(Press Back 2x, Flare Flow Data)* | | | | | |
| *Flow Rate (SCFM) | | | | | 503 |
| *Total Flow (MMSCF) | | | | | 444.851 |
| *Flow Pressure (inWC) | | | | | 7.0 |
| *Flow Temperature (F) | | | | | 146 |
| ***Control Panel - Touchscreen*** *(Press Resettable Flow History, Analog Data Menu, Blower Data)* | | | | | |
| *Resettable Total Flow (MMSCF) | | | | | 601.14 |
| *Reset Date/Time (mm/dd/yy hh:mm:ss) | | | | | |
| ***Control Panel - Touchscreen - Blower Data*** *(Press Main)* | | | | | |
| *Blower 301 Runtime (Hours) | | | | | 35764 |
| *Blower 301 Vibration (in/Sec) | | | | | 0.26 |
| *Blower 301 Speed (%Max) | | | | | 92 |
| *Blower 301 Inlet Bearing Temp (F) | | | | | 99 |
| *Blower 301 Outlet Bearing Temp (F) | | | | | 143 |
| ***Control Panel - Blower Keypad*** | | | | | |
| *Blower 301 Current (Amps) | | | | | 14.3 |
| ***Gas Handling Skid*** | | | | | |
| *Demister Inlet Pressure (inWC) | | | | | -43.6 |
| *Demister Outlet Pressure (inWC) | | | | | -46.3 |
| *Demister DP (inWC) | | | | | +2.7 |
| *Flame Arrester Inlet Pressure (inWC) | | | | | +7.5 |
| *Flame Arrester Outlet Pressure (inWC) | | | | | +4.8 |
| *Flame Arrester DP (inWC) | | | | | +2.7 |
| ***Flare*** | | | | | |
| *Visible Emissions (Yes/No, If yes explain) | | | | | NO |
| *Spiralator Position (%Open) | | | | | 50 |
| *Manual Louver 1 Position (%Open) | | | | | 50 |
| *Manual Louver 2 Position (%Open) | | | | | 50 |
| ***Other*** | | | | | |
| Heat Trace OK (Check for Yes) | ☐ | ☐ | ☐ | ☐ | ✓ |
| *Propane Tank Level OK (T1 \| T2 (Check for Yes)) | ☐ ☐ | ☐ ☐ | ☐ ☐ | ☐ ☐ | ✓ ✓ |
| ***Flare 3 - Monitoring*** | | | | | |
| Time (hh:mm) | | | | | 1319 |
| Technician (Initials) | | | | | CS |
| ***Control Panel*** | | | | | |
| *Indicator Lights OK (Check for Yes) | ☐ | ☐ | ☐ | ☐ | ✓ |
| *Heating/Cooling OK (Check for Yes) | ☐ | ☐ | ☐ | ☐ | ✓ |
| ***Control Panel - Digital Recorder*** | | | | | |
| *Remote Recorder On (Check for Yes) | ☐ | ☐ | ☐ | ☐ | ✓ |

# Collection and Control System Monitoring

| Day of Week | Monday | Tuesday | Wednesday | Thursday | Friday |
|---|---|---|---|---|---|
| ***Control Panel - Touchscreen - Analog Data Menu - Process Overview*** | | | | | |
| *Gas Handling Skid Inlet Vacuum (inWC) | | | | | 39.8 |
| *Gas Handling Skid Inlet Temperature (F) | | | | | 72 |
| *Panel Temperature (F) | | | | | 113 |
| *Recirculation Valve Position (%Closed) | | | | | 100 |
| *Flare Flame Temperature (F) | | | | | 1320 |
| *Flame Arrestor Temperature (F) | | | | | 108 |
| ***Control Panel - Touchscreen - Blower Data*** *(Press Back, Blower Menu, Select Current Blower)* | | | | | |
| *Blower Runtime (Blower \| Runtime (Hours)) | | | | | 30 1278 |
| *Blower Speed (Blower \| Speed (%Max)) | | | | | 65 |
| *Blower Vibration (Blower \| Vibration (in/Sec)) | | | | | 0.02 |
| *Blower Current (Blower \| Current (Amps)) | | | | | 29.4 |
| ***Control Panel - Touchscreen - Flare Flow Data*** *(Press Back X2, Flare Flow Data)* | | | | | |
| *Flow Rate (SCFM) | | | | | 911 |
| *Total Flow (MMSCF) | | | | | 185.94 |
| *Flow Pressure (inWC) | | | | | 3.7 |
| *Flow Temperature (F) | | | | | 109 |
| *Flow DP (inWC) | | | | | 2.34 |
| ***Control Panel - Touchscreen*** *(Press Resettable)* | | | | | |
| *Resettable Total Flow (MMSCF) | | | | | 185.94 |
| *Reset Date/Time (mm/dd/yy hh:mm ss) | | | | | |
| ***Control Panel - Touchscreen - Alarm History*** *(Press Main)* | | | | | |
| *Alarm History (Check box if no alarm) | ☐ | ☐ | ☐ | ☐ | ☑ |
| ***Gas Handling Skid*** | | | | | |
| *Demister Inlet Pressure (inWC) | | | | | -40.5 |
| *Demister Outlet Pressure (inWC) | | | | | -41.5 |
| *Demister DP (inWC) | | | | | +1.0 |
| *Flame Arrester Inlet Pressure (inWC) | | | | | +4.1 |
| *Flame Arrester Outlet Pressure (inWC) | | | | | +3.7 |
| *Flame Arrester DP (inWC) | | | | | +0.4 |
| *Fail-Close Valve Air Pressure (psi) | | | | | 105 |
| ***Flare*** | | | | | |
| *Visible Emissions (Yes/No, If yes explain) | | | | | NO |
| *Spiralator Position (%Open) | | | | | 50 |
| *Manual Louver 1 Position (%Open) | | | | | 50 |
| *Manual Louver 2 Position (%Open) | | | | | 50 |
| ***Other*** | | | | | |
| *Heat Trace OK (Check for Yes) | ☐ | ☐ | ☐ | ☐ | ☑ |
| *Propane Tank Level OK (T1 \| T2 (Check for Yes)) | ☐ ☐ | ☐ ☐ | ☐ ☐ | ☐ ☐ | ☑ ☐ |
| ***Engine Plant 1 - Monitoring*** | | | | | |
| Time (hh mm) | | | | | 1332 |
| Technician (Initials) | | | | | CL |
| ***Engine Control Panel*** | | | | | |
| *Power Setpoint (kWh) (Engine #4 \| #3) | | | | | 695 C10 |
| *Power Setpoint (kWh) (Engine #2 \| #1) | | | | | C13 C13 |
| ***Control Room - Laptop*** | | | | | |
| *Flow Total (MSCF) | | | | | 28G547.5 |
| *Flow Rate (SCFM) | | | | | 990.5 |
| *Discharge Gas Temperature (F) | | | | | 93.0 |
| ***Engine Bay/Control Room Window*** | | | | | |
| *Inlet Gas Pressure (inWC) | | | | | -44.8 |
| ***Other*** | | | | | |
| *Visible Emissions (Yes/No, If yes explain) | | | | | NO |

***Note * Collect during device operation only***

**Remarks**

# Collection and Control System Monitoring

| Day of Week | Monday | Tuesday | Wednesday | Thursday | Friday |
|---|---|---|---|---|---|
| Date (mm/dd/yy) | | | | 07/29/21 | 07/30/21 |
| ***Lowry Header - Monitoring*** | | | | | |
| Time (hh mm) | | | | 1424 | 1084 |
| Technician (Initials) | | | | CS | CS |
| ***Control Panel - Digital Recorder*** | | | | | |
| Flow Rate (SCFM) | | | | 193 | 189 |
| Gas Temperature (F) | | | | 62.0 | 62.0 |
| ***Flare 2 - Monitoring*** | | | | | |
| Time (hh:mm) | | | | 1429 | 1011 |
| Technician (Initials) | | | | CS | CS |
| ***Control Panel*** | | | | | |
| *Indicator Lights OK (Check for Yes) | ☐ | ☐ | ☐ | ☑ | ☑ |
| Heating/Cooling OK (Check for Yes) | ☐ | ☐ | ☐ | ☑ | ☑ |
| ***Control Panel - Digital Recorder*** | | | | | |
| Local Recorder On (Check for Yes) | ☐ | ☐ | ☐ | ☑ | ☑ |
| ***Control Panel - Touchscreen - Process Overview*** | | | | | |
| *Gas Handling Skid Inlet Pressure (InWC) | | | | 41.3 | 40.4 |
| *Flare DP (InWC) | | | | 5.55 | 5.37 |
| *Flare Flame Temperature (F) | | | | 1154 | 1128 |
| ***Control Panel - Touchscreen*** *(Press Next)* | | | | | |
| Panel Temperature (F) | | | | 81 | 79 |
| *Gas Handling Skid Inlet Temperature (F) | | | | 70 | 70 |
| *Recirculation Valve Position (%Closed) | | | | 70 | 70 |
| ***Control Panel - Touchscreen - Flare Flow Data*** *(Press Back 2x, Flare Flow Data)* | | | | | |
| *Flow Rate (SCFM) | | | | 499 | 497 |
| *Total Flow (MMSCF) | | | | 949.17 | 949.77 |
| *Flow Pressure (InWC) | | | | 7.1 | 6.9 |
| *Flow Temperature (F) | | | | 146 | 140 |
| ***Control Panel - Touchscreen*** *(Press Resettable Flow History, Analog Data Menu, Blower Data)* | | | | | |
| *Resettable Total Flow (MMSCF) | | | | 605.51 | 606.10 |
| *Reset Date/Time (mm/dd/yy hh.mm.ss) | | | | | |
| ***Control Panel - Touchscreen - Blower Data*** *(Press Main)* | | | | | |
| *Blower 301 Runtime (Hours) | | | | 35909 | 35929 |
| *Blower 301 Vibration (In/Sec) | | | | 0.23 | 0.28 |
| *Blower 301 Speed (%Max) | | | | 91 | 90 |
| *Blower 301 Inlet Bearing Temp (F) | | | | 96 | 93 |
| *Blower 301 Outlet Bearing Temp (F) | | | | 145 | 130 |
| ***Control Panel - Blower Keypad*** | | | | | |
| *Blower 301 Current (Amps) | | | | 14.4 | 13.9 |
| ***Gas Handling Skid*** | | | | | |
| *Demister Inlet Pressure (InWC) | | | | -41.4 | -41.5 |
| *Demister Outlet Pressure (InWC) | | | | -44.5 | -43.7 |
| *Demister DP (InWC) | | | | +3.1 | +2.2 |
| *Flame Arrester Inlet Pressure (InWC) | | | | +8.2 | +8.3 |
| *Flame Arrester Outlet Pressure (InWC) | | | | +5.0 | +4.9 |
| *Flame Arrester DP (InWC) | | | | +3.2 | +3.4 |
| ***Flare*** | | | | | |
| *Visible Emissions (Yes/No, If yes explain) | | | | ND | ND |
| *Spiralator Position (%Open) | | | | 50 | 50 |
| *Manual Louver 1 Position (%Open) | | | | 50 | 50 |
| *Manual Louver 2 Position (%Open) | | | | 50 | 50 |
| ***Other*** | | | | | |
| Heat Trace OK (Check for Yes) | ☐ | ☐ | ☐ | ☑ | ☑ |
| *Propane Tank Level OK (T1 \| T2 (Check for Yes)) | ☐ ☐ | ☐ ☐ | ☐ ☐ | ☑ ☑ | ☑ ☑ |
| ***Flare 3 - Monitoring*** | | | | | |
| Time (hh.mm) | | | | 1441 | 1136 |
| Technician (Initials) | | | | CS | CS |
| ***Control Panel*** | | | | | |
| *Indicator Lights OK (Check for Yes) | ☐ | ☐ | ☐ | ☑ | ☑ |
| *Heating/Cooling OK (Check for Yes) | ☐ | ☐ | ☐ | ☑ | ☑ |
| ***Control Panel - Digital Recorder*** | | | | | |
| *Remote Recorder On (Check for Yes) | ☐ | ☐ | ☐ | ☑ | ☑ |

# Collection and Control System Monitoring

| Day of Week | Monday | Tuesday | Wednesday | Thursday | Friday |
|---|---|---|---|---|---|
| ***Control Panel - Touchscreen - Analog Data Menu - Process Overview*** | | | | | |
| *Gas Handling Skid Inlet Vacuum (inWC) | | | | 40.1 | 39.9 |
| *Gas Handling Skid Inlet Temperature (F) | | | | 72 | 73 |
| *Panel Temperature (F) | | | | 114 | 102 |
| *Recirculation Valve Position (%Closed) | | | | 100 | 100 |
| *Flare Flame Temperature (F) | | | | 1267 | 1306 |
| *Flame Arrestor Temperature (F) | | | | 108 | 106 |
| ***Control Panel - Touchscreen - Blower Data*** *(Press Back, Blower Menu, Select Current Blower)* | | | | | |
| *Blower Runtime (Blower \| Runtime (Hours)) | | | | 302-1424 | 302-1445 |
| *Blower Speed (Blower \| Speed (%Max)) | | | | C6 | C6 |
| *Blower Vibration (Blower \| Vibration (in/Sec)) | | | | 0.02 | 0.01 |
| *Blower Current (Blower \| Current (Amps)) | | | | 27.8 | 26.6 |
| ***Control Panel - Touchscreen - Flare Flow Data*** *(Press Back X2, Flare Flow Data)* | | | | | |
| *Flow Rate (SCFM) | | | | 1015 | 1013 |
| *Total Flow (MMSCF) | | | | 194.26 | 195.56 |
| *Flow Pressure (inWC) | | | | 3.9 | 4.1 |
| *Flow Temperature (F) | | | | 108 | 107 |
| *Flow DP (inWC) | | | | 2.84 | 2.51 |
| ***Control Panel - Touchscreen*** *(Press Resettable)* | | | | | |
| *Resettable Total Flow (MMSCF) | | | | 194.26 | 195.56 |
| *Reset Date/Time (mm/dd/yy hh:mm ss) | | | | | |
| ***Control Panel - Touchscreen - Alarm History*** *(Press Main)* | | | | | |
| *Alarm History (Check box if no alarm) | ☐ | ☐ | ☐ | ☑ | ☑ |
| ***Gas Handling Skid*** | | | | | |
| *Demister Inlet Pressure (inWC) | | | | -39.2 | -39.6 |
| *Demister Outlet Pressure (inWC) | | | | -41.2 | -40.6 |
| *Demister DP (inWC) | | | | +2.0 | +1.0 |
| *Flame Arrester Inlet Pressure (inWC) | | | | +5.2 | +4.8 |
| *Flame Arrester Outlet Pressure (inWC) | | | | +4.4 | +4.1 |
| *Flame Arrester DP (inWC) | | | | +0.8 | +0.7 |
| *Fail-Close Valve Air Pressure (psi) | | | | 105 | 105 |
| ***Flare*** | | | | | |
| *Visible Emissions (Yes/No, If yes explain) | | | | NO | NO |
| *Spiralator Position (%Open) | | | | 50 | 50 |
| *Manual Louver 1 Position (%Open) | | | | 50 | 50 |
| *Manual Louver 2 Position (%Open) | | | | 50 | 50 |
| ***Other*** | | | | | |
| *Heat Trace OK (Check for Yes) | ☐ | ☐ | ☐ | ☑ | ☑ |
| *Propane Tank Level OK (T1 \| T2 (Check for Yes)) | ☐ ☐ | ☐ ☐ | ☐ ☐ | ☑ ☑ | ☑ ☑ |
| ***Engine Plant 1 - Monitoring*** | | | | | |
| Time (hh mm) | | | | 1451 | 1147 |
| Technician (Initials) | | | | CB | CB |
| ***Engine Control Panel*** | | | | | |
| *Power Setpoint (kWh) (Engine #4 \| #3) | | | | C76 C69 | C81 C68 |
| *Power Setpoint (kWh) (Engine #2 \| #1) | | | | C79 C83 | C74 C79 |
| ***Control Room - Laptop*** | | | | | |
| *Flow Total (MSCF) | | | | 295163.3 | 296384.3 |
| *Flow Rate (SCFM) | | | | 980.7 | 966.5 |
| *Discharge Gas Temperature (F) | | | | 91.0 | 86.0 |
| ***Engine Bay/Control Room Window*** | | | | | |
| *Inlet Gas Pressure (inWC) | | | | -42.5 | -42.7 |
| ***Other*** | | | | | |
| *Visible Emissions (Yes/No, If yes explain) | | | | NO | NO |

***Note * Collect during device operation only***

**Remarks**

# Collection and Control System Monitoring

| Day of Week | Monday | Tuesday | Wednesday | Thursday | Friday |
|---|---|---|---|---|---|
| Date (mm/dd/yy) | | | | 08/05/21 | 08/06/21 |
| **Lowry Header - Monitoring** | | | | | |
| Time (hh:mm) | | | | 1410 | 1453 |
| Technician (Initials) | | | | CS | CS |
| ***Control Panel - Digital Recorder*** | | | | | |
| Flow Rate (SCFM) | | | | 194 | 194 |
| Gas Temperature (F) | | | | 63.4 | 63.0 |
| **Flare 2 - Monitoring** | | | | | |
| Time (hh:mm) | | | | 1414 | 1458 |
| Technician (Initials) | | | | CS | CS |
| ***Control Panel*** | | | | | |
| *Indicator Lights OK (Check for Yes) | ☐ | ☐ | ☐ | ✓ | ✓ |
| Heating/Cooling OK (Check for Yes) | ☐ | ☐ | ☐ | ✓ | ✓ |
| ***Control Panel - Digital Recorder*** | | | | | |
| Local Recorder On (Check for Yes) | ☐ | ☐ | ☐ | ✓ | ✓ |
| ***Control Panel - Touchscreen - Process Overview*** | | | | | |
| *Gas Handling Skid Inlet Pressure (inWC) | | | | 39.5 | 39.3 |
| *Flare DP (inWC) | | | | 5.42 | 5.47 |
| *Flare Flame Temperature (F) | | | | 1275 | 1281 |
| ***Control Panel - Touchscreen*** *(Press Next)* | | | | | |
| Panel Temperature (F) | | | | 82 | 80 |
| *Gas Handling Skid Inlet Temperature (F) | | | | 70 | 70 |
| *Recirculation Valve Position (%Closed) | | | | 70 | 70 |
| ***Control Panel - Touchscreen - Flare Flow Data*** *(Press Back 2x, Flare Flow Data)* | | | | | |
| *Flow Rate (SCFM) | | | | 498 | 506 |
| *Total Flow (MMSCF) | | | | 953.91 | 954.64 |
| *Flow Pressure (inWC) | | | | 7.1 | 7.3 |
| *Flow Temperature (F) | | | | 143 | 141 |
| ***Control Panel - Touchscreen*** *(Press Resettable Flow History, Analog Data Menu, Blower Data)* | | | | | |
| *Resettable Total Flow (MMSCF) | | | | C10.24 | C10.98 |
| *Reset Date/Time (mm/dd/yy hh:mm:ss) | | | | | |
| ***Control Panel - Touchscreen - Blower Data*** *(Press Main)* | | | | | |
| *Blower 301 Runtime (Hours) | | | | 36067 | 36091 |
| *Blower 301 Vibration (in/Sec) | | | | 0.26 | 0.27 |
| *Blower 301 Speed (%Max) | | | | 40 | 40 |
| *Blower 301 Inlet Bearing Temp (F) | | | | 106 | 105 |
| *Blower 301 Outlet Bearing Temp (F) | | | | 147 | 137 |
| ***Control Panel - Blower Keypad*** | | | | | |
| *Blower 301 Current (Amps) | | | | 14.0 | 13.9 |
| ***Gas Handling Skid*** | | | | | |
| *Demister Inlet Pressure (inWC) | | | | -39.5 | -39.3 |
| *Demister Outlet Pressure (inWC) | | | | -42.2 | -40.8 |
| *Demister DP (inWC) | | | | +2.7 | +1.5 |
| *Flame Arrester Inlet Pressure (inWC) | | | | +8.6 | +6.2 |
| *Flame Arrester Outlet Pressure (inWC) | | | | +4.9 | +4.8 |
| *Flame Arrester DP (inWC) | | | | +3.7 | +3.4 |
| ***Flare*** | | | | | |
| *Visible Emissions (Yes/No, If yes explain) | | | | No | No |
| *Spiralator Position (%Open) | | | | 50 | 50 |
| *Manual Louver 1 Position (%Open) | | | | 50 | 50 |
| *Manual Louver 2 Position (%Open) | | | | 50 | 50 |
| ***Other*** | | | | | |
| Heat Trace OK (Check for Yes) | ☐ | ☐ | ☐ | ✓ | ✓ |
| *Propane Tank Level OK (T1 \| T2 (Check for Yes)) | ☐ ☐ | ☐ ☐ | ☐ ☐ | ✓ ✓ | ✓ ✓ |
| **Flare 3 - Monitoring** | | | | | |
| Time (hh:mm) | | | | 1428 | 1505 |
| Technician (Initials) | | | | CS | CS |
| ***Control Panel*** | | | | | |
| *Indicator Lights OK (Check for Yes) | ☐ | ☐ | ☐ | ✓ | ✓ |
| *Heating/Cooling OK (Check for Yes) | ☐ | ☐ | ☐ | ✓ | ✓ |
| ***Control Panel - Digital Recorder*** | | | | | |
| *Remote Recorder On (Check for Yes) | ☐ | ☐ | ☐ | ✓ | ✓ |

# Collection and Control System Monitoring

| Day of Week | Monday | Tuesday | Wednesday | Thursday | Friday |
|---|---|---|---|---|---|
| ***Control Panel - Touchscreen - Analog Data Menu - Process Overview*** | | | | | |
| *Gas Handling Skid Inlet Vacuum (inWC) | | | | 39.6 | 42.0 |
| *Gas Handling Skid Inlet Temperature (F) | | | | 73 | 72 |
| *Panel Temperature (F) | | | | 114 | 112 |
| *Recirculation Valve Position (%Closed) | | | | 1295 | 1297 |
| *Flare Flame Temperature (F) | | | | 109 | 106 |
| *Flame Arrestor Temperature (F) | | | | | |
| ***Control Panel - Touchscreen - Blower Data*** *(Press Back, Blower Menu, Select Current Blower)* | | | | | |
| *Blower Runtime (Blower \| Runtime (Hours)) | | | | 302 1582 | 301 1506 |
| *Blower Speed (Blower \| Speed (%Max)) | | | | 66 | 67 |
| *Blower Vibration (Blower \| Vibration (in/Sec)) | | | | 0.01 | 0.02 |
| *Blower Current (Blower \| Current (Amps)) | | | | 29.3 | 31.6 |
| ***Control Panel - Touchscreen - Flare Flow Data*** *(Press Back X2, Flare Flow Data)* | | | | | |
| *Flow Rate (SCFM) | | | | 1016 | 1117 |
| *Total Flow (MMSCF) | | | | 203.76 | 205.23 |
| *Flow Pressure (inWC) | | | | 4.5 | 4.4 |
| *Flow Temperature (F) | | | | 109 | 106 |
| *Flow DP (inWC) | | | | 2.50 | 2.32 |
| ***Control Panel - Touchscreen*** *(Press Resettable)* | | | | | |
| *Resettable Total Flow (MMSCF) | | | | 203.76 | 205.23 |
| *Reset Date/Time (mm/dd/yy hh:mm:ss) | | | | | |
| ***Control Panel - Touchscreen - Alarm History*** *(Press Main)* | | | | | |
| *Alarm History (Check box if no alarm) | ☐ | ☐ | ☐ | ✓ | ✓ |
| ***Gas Handling Skid*** | | | | | |
| *Demister Inlet Pressure (inWC) | | | | -40.2 | -40.5 |
| *Demister Outlet Pressure (inWC) | | | | -41.2 | -41.5 |
| *Demister DP (inWC) | | | | +1.0 | +1.0 |
| *Flame Arrester Inlet Pressure (inWC) | | | | +5.5 | +4.9 |
| *Flame Arrester Outlet Pressure (inWC) | | | | +4.2 | +4.0 |
| *Flame Arrester DP (inWC) | | | | +1.3 | +0.9 |
| *Fail-Close Valve Air Pressure (psi) | | | | 105 | 105 |
| ***Flare*** | | | | | |
| *Visible Emissions (Yes/No, If yes explain) | | | | NO | NO |
| *Spiralator Position (%Open) | | | | 50 | 50 |
| *Manual Louver 1 Position (%Open) | | | | 50 | 50 |
| *Manual Louver 2 Position (%Open) | | | | 50 | 50 |
| ***Other*** | | | | | |
| *Heat Trace OK (Check for Yes) | ☐ | ☐ | ☐ | ✓ | ✓ |
| *Propane Tank Level OK (T1 \| T2 (Check for Yes)) | ☐ ☐ | ☐ ☐ | ☐ ☐ | ✓ ✓ | ✓ ✓ |
| ***Engine Plant 1 - Monitoring*** | | | | | |
| Time (hh:mm) | | | | 1436 | 1512 |
| Technician (Initials) | | | | CS | CS |
| ***Engine Control Panel*** | | | | | |
| *Power Setpoint (kWh) (Engine #4 \| #3) | | | | 626 711 | 755 669 |
| *Power Setpoint (kWh) (Engine #2 \| #1) | | | | 691 670 | 673 650 |
| ***Control Room - Laptop*** | | | | | |
| *Flow Total (MSCF) | | | | 304809.5 | 306205.2 |
| *Flow Rate (SCFM) | | | | 955.8 | 973.6 |
| *Discharge Gas Temperature (F) | | | | 91.0 | 89.0 |
| ***Engine Bay/Control Room Window*** | | | | | |
| *Inlet Gas Pressure (inWC) | | | | -44.3 | -46.1 |
| ***Other*** | | | | | |
| *Visible Emissions (Yes/No, If yes explain) | | | | NO | NO |

***Note * Collect during device operation only***

**Remarks**

# Collection and Control System Monitoring

| Day of Week | Monday | Tuesday | Wednesday | Thursday | Friday |
|---|---|---|---|---|---|
| Date (mm/dd/yy) | | | | 05/19/21 | 05/20/21 |
| **Lowry Header - Monitoring** | | | | | |
| Time (hh mm) | | | | 1333 | 1645 |
| Technician (initials) | | | | CS | CS |
| ***Control Panel - Digital Recorder*** | | | | | |
| Flow Rate (SCFM) | | | | 209 | 205 |
| Gas Temperature (F) | | | | 64.0 | 64.5 |
| **Flare 2 - Monitoring** | | | | | |
| Time (hh:mm) | | | | 1343 | 1648 |
| Technician (initials) | | | | CS | CS |
| ***Control Panel*** | | | | | |
| *Indicator Lights OK (Check for Yes) | ☐ | ☐ | ☐ | ☑ | ☑ |
| Heating/Cooling OK (Check for Yes) | ☐ | ☐ | ☐ | ☑ | ☑ |
| ***Control Panel - Digital Recorder*** | | | | | |
| Local Recorder On (Check for Yes) | ☐ | ☐ | ☐ | ☑ | ☑ |
| ***Control Panel - Touchscreen - Process Overview*** | | | | | |
| *Gas Handling Skid Inlet Pressure (inWC) | | | | 42.5 | 43.4 |
| *Flare DP (inWC) | | | | 5.51 | 5.48 |
| *Flare Flame Temperature (F) | | | | 1229 | 1167 |
| ***Control Panel - Touchscreen*** *(Press Next)* | | | | | |
| Panel Temperature (F) | | | | 80 | 78 |
| *Gas Handling Skid Inlet Temperature (F) | | | | 72 | 74 |
| *Recirculation Valve Position (%Closed) | | | | 70 | 70 |
| ***Control Panel - Touchscreen - Flare Flow Data*** *(Press Back 2x, Flare Flow Data)* | | | | | |
| *Flow Rate (SCFM) | | | | 500 | 500 |
| *Total Flow (MMSCF) | | | | 963.91 | 964.72 |
| *Flow Pressure (inWC) | | | | 7.0 | 7.0 |
| *Flow Temperature (F) | | | | 146 | 144 |
| ***Control Panel - Touchscreen*** *(Press Resettable Flow History, Analog Data Menu, Blower Data)* | | | | | |
| *Resettable Total Flow (MMSCF) | | | | 020.25 | 021.06 |
| *Reset Date/Time (mm/dd/yy hh.mm.ss) | | | | | |
| ***Control Panel - Touchscreen - Blower Data*** *(Press Main)* | | | | | |
| *Blower 301 Runtime (Hours) | | | | 30400 | 30427 |
| *Blower 301 Vibration (in/Sec) | | | | 0.29 | 0.26 |
| *Blower 301 Speed (%Max) | | | | 93 | 93 |
| *Blower 301 Inlet Bearing Temp (F) | | | | 98 | 89 |
| *Blower 301 Outlet Bearing Temp (F) | | | | 143 | 141 |
| ***Control Panel - Blower Keypad*** | | | | | |
| *Blower 301 Current (Amps) | | | | 14.6 | 14.3 |
| ***Gas Handling Skid*** | | | | | |
| *Demister Inlet Pressure (inWC) | | | | -43.6 | -43.6 |
| *Demister Outlet Pressure (inWC) | | | | -44.9 | -46.1 |
| *Demister DP (inWC) | | | | +1.3 | +2.5 |
| *Flame Arrester Inlet Pressure (inWC) | | | | +8.6 | +8.1 |
| *Flame Arrester Outlet Pressure (inWC) | | | | +5.4 | +4.9 |
| *Flame Arrester DP (inWC) | | | | +3.2 | +3.2 |
| ***Flare*** | | | | | |
| *Visible Emissions (Yes/No, If yes explain) | | | | NO | NO |
| *Spiralator Position (%Open) | | | | 50 | 50 |
| *Manual Louver 1 Position (%Open) | | | | 50 | 50 |
| *Manual Louver 2 Position (%Open) | | | | 50 | 50 |
| ***Other*** | | | | | |
| Heat Trace OK (Check for Yes) | ☐ | ☐ | ☐ | ☑ | ☑ |
| *Propane Tank Level OK (T1 \| T2 (Check for Yes)) | ☐ ☐ | ☐ ☐ | ☐ ☐ | ☑ ☑ | ☑ ☑ |
| **Flare 3 - Monitoring** | | | | | |
| Time (hh.mm) | | | | 1354 | 1654 |
| Technician (initials) | | | | CS | CS |
| ***Control Panel*** | | | | | |
| *Indicator Lights OK (Check for Yes) | ☐ | ☐ | ☐ | ☑ | ☑ |
| *Heating/Cooling OK (Check for Yes) | ☐ | ☐ | ☐ | ☑ | ☑ |
| ***Control Panel - Digital Recorder*** | | | | | |
| *Remote Recorder On (Check for Yes) | ☐ | ☐ | ☐ | ☑ | ☑ |

# Collection and Control System Monitoring

| Day of Week | Monday | Tuesday | Wednesday | Thursday | Friday |
|---|---|---|---|---|---|
| ***Control Panel - Touchscreen - Analog Data Menu - Process Overview*** | | | | | |
| *Gas Handling Skid Inlet Vacuum (inWC) | | | | 40.2 | 37.4 |
| *Gas Handling Skid Inlet Temperature (F) | | | | 74 | 72 |
| *Panel Temperature (F) | | | | 99 | 105 |
| *Recirculation Valve Position (%Closed) | | | | 100 | 100 |
| *Flare Flame Temperature (F) | | | | 1315 | 1278 |
| *Flame Arrestor Temperature (F) | | | | 100 | 105 |
| ***Control Panel - Touchscreen - Blower Data*** *(Press Back, Blower Menu, Select Current Blower)* | | | | | |
| *Blower Runtime (Blower \| Runtime (Hours)) | | | | 301 1639 | 301 1812 |
| *Blower Speed (Blower \| Speed (%Max)) | | | | 63 | 68 |
| *Blower Vibration (Blower \| Vibration (in/Sec)) | | | | 0.01 | 0.02 |
| *Blower Current (Blower \| Current (Amps)) | | | | 27.0 | 33.7 |
| ***Control Panel - Touchscreen - Flare Flow Data*** *(Press Back X2, Flare Flow Data)* | | | | | |
| *Flow Rate (SCFM) | | | | 857 | 1099 |
| *Total Flow (MMSCF) | | | | 223.52 | 221.90 |
| *Flow Pressure (inWC) | | | | 3.0 | 4.5 |
| *Flow Temperature (F) | | | | 102 | 102 |
| *Flow DP (inWC) | | | | 1.58 | 3.35 |
| ***Control Panel - Touchscreen*** *(Press Resettable)* | | | | | |
| *Resettable Total Flow (MMSCF) | | | | 223.52 | 221.90 |
| *Reset Date/Time (mm/dd/yy hh:mm ss) | | | | | |
| ***Control Panel - Touchscreen - Alarm History*** *(Press Main)* | | | | | |
| *Alarm History (Check box if no alarm) | ☐ | ☐ | ☐ | ☑ | ☑ |
| ***Gas Handling Skid*** | | | | | |
| *Demister Inlet Pressure (inWC) | | | | -39.7 | -39.2 |
| *Demister Outlet Pressure (inWC) | | | | -41.0 | -40.5 |
| *Demister DP (inWC) | | | | +1.3 | +1.3 |
| *Flame Arrester Inlet Pressure (inWC) | | | | +3.0 | +5.8 |
| *Flame Arrester Outlet Pressure (inWC) | | | | +2.1 | +4.7 |
| *Flame Arrester DP (inWC) | | | | +0.9 | +1.1 |
| *Fail-Close Valve Air Pressure (psi) | | | | 105 | 105 |
| ***Flare*** | | | | | |
| *Visible Emissions (Yes/No, If yes explain) | | | | NO | NO |
| *Spiralator Position (%Open) | | | | 50 | 50 |
| *Manual Louver 1 Position (%Open) | | | | 50 | 50 |
| *Manual Louver 2 Position (%Open) | | | | 50 | 50 |
| ***Other*** | | | | | |
| *Heat Trace OK (Check for Yes) | ☐ | ☐ | ☐ | ☑ | ☑ |
| *Propane Tank Level OK (T1 \| T2 (Check for Yes)) | ☐ ☐ | ☐ ☐ | ☐ ☐ | ☑ ☑ | ☑ ☑ |
| ***Engine Plant 1 - Monitoring*** | | | | | |
| Time (hh mm) | | | | 1701 | 1401 |
| Technician (Initials) | | | | CS | CS |
| ***Engine Control Panel*** | | | | | |
| *Power Setpoint (kWh) (Engine #4 \| #3) | | | | 695 662 | — 670 |
| *Power Setpoint (kWh) (Engine #2 \| #1) | | | | 661 669 | 666 671 |
| ***Control Room - Laptop*** | | | | | |
| *Flow Total (MSCF) | | | | 324741.8 | 323473.8 |
| *Flow Rate (SCFM) | | | | 950.3 | 710.9 |
| *Discharge Gas Temperature (F) | | | | 78.0 | 80.0 |
| ***Engine Bay/Control Room Window*** | | | | | |
| *Inlet Gas Pressure (inWC) | | | | -43.7 | -44.1 |
| ***Other*** | | | | | |
| *Visible Emissions (Yes/No, If yes explain) | | | | NO | NO |

***Note * Collect during device operation only***

**Remarks**

08/19 – Engine #4 Down

# Collection and Control System Monitoring

| Day of Week | Monday | Tuesday | Wednesday | Thursday | Friday |
|---|---|---|---|---|---|
| Date (mm/dd/yy) | | | | | 08/27/21 |
| ***Lowry Header - Monitoring*** | | | | | |
| Time (hh mm) | | | | | 1316 |
| Technician (initials) | | | | | CS |
| ***Control Panel - Digital Recorder*** | | | | | |
| Flow Rate (SCFM) | | | | | 204 |
| Gas Temperature (F) | | | | | 84.0 |
| ***Flare 2 - Monitoring*** | | | | | |
| Time (hh:mm) | | | | | 1329 |
| Technician (initials) | | | | | CS |
| ***Control Panel*** | | | | | |
| *Indicator Lights OK (Check for Yes) | ☐ | ☐ | ☐ | ☐ | ✓ |
| Heating/Cooling OK (Check for Yes) | ☐ | ☐ | ☐ | ☐ | ✓ |
| ***Control Panel - Digital Recorder*** | | | | | |
| Local Recorder On (Check for Yes) | ☐ | ☐ | ☐ | ☐ | ✓ |
| ***Control Panel - Touchscreen - Process Overview*** | | | | | |
| *Gas Handling Skid Inlet Pressure (InWC) | | | | | 42.3 |
| *Flare DP (InWC) | | | | | 5.61 |
| *Flare Flame Temperature (F) | | | | | 1260 |
| ***Control Panel - Touchscreen*** (Press Next) | | | | | |
| Panel Temperature (F) | | | | | 82 |
| *Gas Handling Skid Inlet Temperature (F) | | | | | 72 |
| *Recirculation Valve Position (%Closed) | | | | | 20 |
| ***Control Panel - Touchscreen - Flare Flow Data*** (Press Back 2x, Flare Flow Data) | | | | | |
| *Flow Rate (SCFM) | | | | | 496 |
| *Total Flow (MMSCF) | | | | | 909.89 |
| *Flow Pressure (InWC) | | | | | 7.0 |
| *Flow Temperature (F) | | | | | 151 |
| ***Control Panel - Touchscreen*** (Press Resettable Flow History, Analog Data Menu, Blower Data) | | | | | |
| *Resettable Total Flow (MMSCF) | | | | | 625.92 |
| *Reset Date/Time (mm/dd/yy hh.mm.ss) | | | | | |
| ***Control Panel - Touchscreen - Blower Data*** (Press Main) | | | | | |
| *Blower 301 Runtime (Hours) | | | | | 36589 |
| *Blower 301 Vibration (In/Sec) | | | | | 0.31 |
| *Blower 301 Speed (%Max) | | | | | 94 |
| *Blower 301 Inlet Bearing Temp (F) | | | | | 104 |
| *Blower 301 Outlet Bearing Temp (F) | | | | | 220 |
| ***Control Panel - Blower Keypad*** | | | | | |
| *Blower 301 Current (Amps) | | | | | 14.3 |
| ***Gas Handling Skid*** | | | | | |
| *Demister Inlet Pressure (InWC) | | | | | -43.1 |
| *Demister Outlet Pressure (InWC) | | | | | -45.3 |
| *Demister DP (InWC) | | | | | +2.2 |
| *Flame Arrester Inlet Pressure (InWC) | | | | | +8.2 |
| *Flame Arrester Outlet Pressure (InWC) | | | | | +4.9 |
| *Flame Arrester DP (InWC) | | | | | +3.3 |
| ***Flare*** | | | | | |
| *Visible Emissions (Yes/No, If yes explain) | | | | | NO |
| *Spiralator Position (%Open) | | | | | 55 |
| *Manual Louver 1 Position (%Open) | | | | | 30 |
| *Manual Louver 2 Position (%Open) | | | | | 80 |
| ***Other*** | | | | | ✓ |
| Heat Trace OK (Check for Yes) | ☐ | ☐ | ☐ | ☐ | ✓ |
| *Propane Tank Level OK (T1 \| T2 (Check for Yes)) | ☐ | ☐ | ☐ | ☐ | ✓ ✓ |
| ***Flare 3 - Monitoring*** | | | | | |
| Time (hh mm) | | | | | 1339 |
| Technician (initials) | | | | | CS |
| ***Control Panel*** | | | | | |
| *Indicator Lights OK (Check for Yes) | ☐ | ☐ | ☐ | ☐ | ✓ |
| *Heating/Cooling OK (Check for Yes) | ☐ | ☐ | ☐ | ☐ | ✓ |
| ***Control Panel - Digital Recorder*** | | | | | |
| *Remote Recorder On (Check for Yes) | ☐ | ☐ | ☐ | ☐ | ✓ |

# Collection and Control System Monitoring

| Day of Week | Monday | Tuesday | Wednesday | Thursday | Friday |
|---|---|---|---|---|---|
| ***Control Panel - Touchscreen - Analog Data Menu - Process Overview*** | | | | | |
| *Gas Handling Skid Inlet Vacuum (inWC) | | | | | 41.6 |
| *Gas Handling Skid Inlet Temperature (F) | | | | | 74 |
| *Panel Temperature (F) | | | | | 114 |
| *Recirculation Valve Position (%Closed) | | | | | 100 |
| *Flare Flame Temperature (F) | | | | | 1287 |
| *Flame Arrestor Temperature (F) | | | | | 111 |
| ***Control Panel - Touchscreen - Blower Data*** *(Press Back, Blower Menu, Select Current Blower)* | | | | | |
| *Blower Runtime (Blower \| Runtime (Hours)) | | | | | 302-1606 |
| *Blower Speed (Blower \| Speed (%Max)) | | | | | C7 |
| *Blower Vibration (Blower \| Vibration (In/Sec)) | | | | | 0.02 |
| *Blower Current (Blower \| Current (Amps)) | | | | | 30.5 |
| ***Control Panel - Touchscreen - Flare Flow Data*** *(Press Back X2, Flare Flow Data)* | | | | | |
| *Flow Rate (SCFM) | | | | | 1053 |
| *Total Flow (MMSCF) | | | | | 228.08 |
| *Flow Pressure (inWC) | | | | | 3.9 |
| *Flow Temperature (F) | | | | | 111 |
| *Flow DP (inWC) | | | | | 277 |
| ***Control Panel - Touchscreen*** *(Press Resettable)* | | | | | |
| *Resettable Total Flow (MMSCF) | | | | | 228.08 |
| *Reset Date/Time (mm/dd/yy hh:mm:ss) | | | | | |
| ***Control Panel - Touchscreen - Alarm History*** *(Press Main)* | | | | | |
| *Alarm History (Check box if no alarm) | ☐ | ☐ | ☐ | ☐ | ☑ |
| ***Gas Handling Skid*** | | | | | |
| *Demister Inlet Pressure (inWC) | | | | | -40.8 |
| *Demister Outlet Pressure (inWC) | | | | | -42.0 |
| *Demister DP (inWC) | | | | | +1.2 |
| *Flame Arrester Inlet Pressure (inWC) | | | | | +4.6 |
| *Flame Arrester Outlet Pressure (inWC) | | | | | +4.3 |
| *Flame Arrester DP (inWC) | | | | | +1.3 |
| *Fail-Close Valve Air Pressure (psi) | | | | | 105 |
| ***Flare*** | | | | | |
| *Visible Emissions (Yes/No, If yes explain) | | | | | NO |
| *Spiralator Position (%Open) | | | | | 50 |
| *Manual Louver 1 Position (%Open) | | | | | 50 |
| *Manual Louver 2 Position (%Open) | | | | | 50 |
| ***Other*** | | | | | |
| *Heat Trace OK (Check for Yes) | ☐ | ☐ | ☐ | ☐ | ☑ |
| *Propane Tank Level OK (T1 \| T2 (Check for Yes)) | ☐ ☐ | ☐ ☐ | ☐ ☐ | ☐ ☐ | ☑ ☑ |

## *Engine Plant 1 - Monitoring*

| | | | | | |
|---|---|---|---|---|---|
| Time (hh mm) | | | | | 1427 |
| Technician (Initials) | | | | | CB |
| ***Engine Control Panel*** | | | | | |
| *Power Setpoint (kWh) (Engine #4 \| #3) | | | | | — 857 |
| *Power Setpoint (kWh) (Engine #2 \| #1) | | | | | 677 682 |
| ***Control Room - Laptop*** | | | | | |
| *Flow Total (MSCF) | | | | | 333760.8 |
| *Flow Rate (SCFM) | | | | | 1259 |
| *Discharge Gas Temperature (F) | | | | | 93.0 |
| ***Engine Bay/Control Room Window*** | | | | | |
| *Inlet Gas Pressure (inWC) | | | | | -44.8 |
| ***Other*** | | | | | |
| *Visible Emissions (Yes/No, If yes explain) | | | | | NO |

***Note * Collect during device operation only***

**Remarks**

08/27 - Engine #4 Down

# Collection and Control System Monitoring

| Day of Week | Monday | Tuesday | Wednesday | Thursday | Friday |
|---|---|---|---|---|---|
| Date (mm/dd/yy) | | 09/01/21 | 09/02/21 | | |
| **Lowry Header - Monitoring** | | | | | |
| Time (hh mm) | | 1330 | 1438 | | |
| Technician (Initials) | | CS | CS | | |
| ***Control Panel - Digital Recorder*** | | | | | |
| Flow Rate (SCFM) | | 205 | 204 | | |
| Gas Temperature (F) | | CS | CS | | |
| **Flare 2 - Monitoring** | | | | | |
| Time (hh:mm) | | 1338 | 1441 | | |
| Technician (Initials) | | CS | CS | | |
| ***Control Panel*** | | | | | |
| *Indicator Lights OK (Check for Yes) | ☐ | ☑ | ☑ | ☐ | ☐ |
| Heating/Cooling OK (Check for Yes) | ☐ | ☑ | ☑ | ☐ | ☐ |
| ***Control Panel - Digital Recorder*** | | | | | |
| Local Recorder On (Check for Yes) | ☐ | ☑ | ☑ | ☐ | ☐ |
| ***Control Panel - Touchscreen - Process Overview*** | | | | | |
| *Gas Handling Skid Inlet Pressure (inWC) | | 42.3 | 43.0 | | |
| *Flare DP (inWC) | | 5.44 | 5.66 | | |
| *Flare Flame Temperature (F) | | 1224 | 1177 | | |
| ***Control Panel - Touchscreen*** *(Press Next)* | | | | | |
| Panel Temperature (F) | | 82 | 81 | | |
| *Gas Handling Skid Inlet Temperature (F) | | 72 | 72 | | |
| *Recirculation Valve Position (%Closed) | | 70 | 70 | | |
| ***Control Panel - Touchscreen - Flare Flow Data*** *(Press Back 2x, Flare Flow Data)* | | | | | |
| *Flow Rate (SCFM) | | 500 | 496 | | |
| *Total Flow (MMSCF) | | 973.10 | 973.85 | | |
| *Flow Pressure (inWC) | | 7.0 | 7.3 | | |
| *Flow Temperature (F) | | 148 | 147 | | |
| ***Control Panel - Touchscreen*** *(Press Resettable Flow History, Analog Data Menu, Blower Data)* | | | | | |
| *Resettable Total Flow (MMSCF) | | C29.43 | C30.18 | | |
| *Reset Date/Time (mm/dd/yy hh.mm.ss) | | | | | |
| ***Control Panel - Touchscreen - Blower Data*** *(Press Main)* | | | | | |
| *Blower 301 Runtime (Hours) | | 36706 | 36731 | | |
| *Blower 301 Vibration (in/Sec) | | 0.32 | 0.28 | | |
| *Blower 301 Speed (%Max) | | 94 | 93 | | |
| *Blower 301 Inlet Bearing Temp (F) | | 99 | 92 | | |
| *Blower 301 Outlet Bearing Temp (F) | | 148 | 146 | | |
| ***Control Panel - Blower Keypad*** | | | | | |
| *Blower 301 Current (Amps) | | 14.2 | 14.3 | | |
| ***Gas Handling Skid*** | | | | | |
| *Demister Inlet Pressure (inWC) | | -43.6 | -43.4 | | |
| *Demister Outlet Pressure (inWC) | | -46.2 | -46.6 | | |
| *Demister DP (inWC) | | +2.6 | +3.2 | | |
| *Flame Arrester Inlet Pressure (inWC) | | +8.1 | +8.2 | | |
| *Flame Arrester Outlet Pressure (inWC) | | +4.9 | +4.9 | | |
| *Flame Arrester DP (inWC) | | +3.2 | +3.3 | | |
| ***Flare*** | | | | | |
| *Visible Emissions (Yes/No, If yes explain) | | NO | NO | | |
| *Spiralator Position (%Open) | | 50 | 50 | | |
| *Manual Louver 1 Position (%Open) | | 50 | 50 | | |
| *Manual Louver 2 Position (%Open) | | 50 | 50 | | |
| ***Other*** | | | | | |
| Heat Trace OK (Check for Yes) | ☐ | ☑ | ☑ | ☐ | ☐ |
| *Propane Tank Level OK (T1 \| T2 (Check for Yes)) | ☐ ☐ | ☑ ☑ | ☑ ☑ | ☐ ☐ | ☐ ☐ |
| **Flare 3 - Monitoring** | | | | | |
| Time (hh.mm) | | 1353 | 1455 | | |
| Technician (Initials) | | CS | CS | | |
| ***Control Panel*** | | | | | |
| *Indicator Lights OK (Check for Yes) | ☐ | ☑ | ☑ | ☐ | ☐ |
| *Heating/Cooling OK (Check for Yes) | ☐ | ☑ | ☑ | ☐ | ☐ |
| ***Control Panel - Digital Recorder*** | | | | | |
| *Remote Recorder On (Check for Yes) | ☐ | ☑ | ☑ | ☐ | ☐ |

# Collection and Control System Monitoring

| Day of Week | Monday | Tuesday | Wednesday | Thursday | Friday |
|---|---|---|---|---|---|
| ***Control Panel - Touchscreen - Analog Data Menu - Process Overview*** | | | | | |
| *Gas Handling Skid Inlet Vacuum (inWC) | | 40.4 | 41.5 | | |
| *Gas Handling Skid Inlet Temperature (F) | | 73 | 72 | | |
| *Panel Temperature (F) | | 114 | 108 | | |
| *Recirculation Valve Position (%Closed) | | 100 | 100 | | |
| *Flare Flame Temperature (F) | | 1320 | 1269 | | |
| *Flame Arrestor Temperature (F) | | 109 | 107 | | |
| ***Control Panel - Touchscreen - Blower Data*** *(Press Back, Blower Menu, Select Current Blower)* | | | | | |
| *Blower Runtime (Blower \| Runtime (Hours)) | | 302 1722 | 302 1747 | | |
| *Blower Speed (Blower \| Speed (%Max)) | | 71 | 70 | | |
| *Blower Vibration (Blower \| Vibration (in/Sec)) | | 0.03 | 0.02 | | |
| *Blower Current (Blower \| Current (Amps)) | | 32.8 | 32.2 | | |
| ***Control Panel - Touchscreen - Flare Flow Data*** *(Press Back X2, Flare Flow Data)* | | | | | |
| *Flow Rate (SCFM) | | 111.8 | 1068 | | |
| *Total Flow (MMSCF) | | 235536 | 237.00 | | |
| *Flow Pressure (inWC) | | 5.4 | 5.1 | | |
| *Flow Temperature (F) | | 110 | 108 | | |
| *Flow DP (inWC) | | 3.13 | 3.53 | | |
| ***Control Panel - Touchscreen*** *(Press Resettable)* | | | | | |
| *Resettable Total Flow (MMSCF) | | 235.36 | 237.00 | | |
| *Reset Date/Time (mm/dd/yy hh:mm:ss) | | | | | |
| ***Control Panel - Touchscreen - Alarm History*** *(Press Main)* | | | | | |
| *Alarm History (Check box if no alarm) | ☐ | ☑ | ☑ | ☐ | ☐ |
| ***Gas Handling Skid*** | | | | | |
| *Demister Inlet Pressure (inWC) | | -39.0 | -39.6 | | |
| *Demister Outlet Pressure (inWC) | | -41.1 | -40.9 | | |
| *Demister DP (inWC) | | +2.1 | +1.3 | | |
| *Flame Arrester Inlet Pressure (inWC) | | +6.2 | +6.4 | | |
| *Flame Arrester Outlet Pressure (inWC) | | +5.7 | +5.7 | | |
| *Flame Arrester DP (inWC) | | +0.5 | +0.7 | | |
| *Fail-Close Valve Air Pressure (psi) | | 105 | 105 | | |
| ***Flare*** | | | | | |
| *Visible Emissions (Yes/No, If yes explain) | | NO | NO | | |
| *Spiralator Position (%Open) | | 50 | 50 | | |
| *Manual Louver 1 Position (%Open) | | 50 | 50 | | |
| *Manual Louver 2 Position (%Open) | | 50 | 50 | | |
| ***Other*** | | | | | |
| *Heat Trace OK (Check for Yes) | ☐ | ☑ | ☑ | ☐ | ☐ |
| *Propane Tank Level OK (T1 \| T2 (Check for Yes)) | ☐ ☐ | ☑ ☑ | ☑ ☑ | ☐ ☐ | ☐ ☐ |
| ***Engine Plant 1 - Monitoring*** | | | | | |
| Time (hh mm) | | 1404 | 1504 | | |
| Technician (Initials) | | CS | CS | | |
| ***Engine Control Panel*** | | | | | |
| *Power Setpoint (kWh) (Engine #4 \| #3) | | 711 — | 711 — | | |
| *Power Setpoint (kWh) (Engine #2 \| #1) | | 692 — | 687 — | | |
| ***Control Room - Laptop*** | | | | | |
| *Flow Total (MSCF) | | 338060.9 | 338807.0 | | |
| *Flow Rate (SCFM) | | 491.5 | 492.0 | | |
| *Discharge Gas Temperature (F) | | 88.0 | 79.0 | | |
| ***Engine Bay/Control Room Window*** | | | | | |
| *Inlet Gas Pressure (inWC) | | -45.5 | -44.1 | | |
| ***Other*** | | | | | |
| *Visible Emissions (Yes/No, If yes explain) | | NO | NO | | |

***Note * Collect during device operation only***

**Remarks**

# Collection and Control System Monitoring

| Day of Week | Monday | Tuesday | Wednesday | Thursday | Friday |
|---|---|---|---|---|---|
| Date (mm/dd/yy) | | | | | 09/10/21 |
| ***Lowry Header - Monitoring*** | | | | | |
| Time (hh mm) | | | | | 1437 |
| Technician (initials) | | | | | CS |
| ***Control Panel - Digital Recorder*** | | | | | |
| Flow Rate (SCFM) | | | | | 204 |
| Gas Temperature (F) | | | | | 65.0 |
| ***Flare 2 - Monitoring*** | | | | | |
| Time (hh:mm) | | | | | 1440 |
| Technician (initials) | | | | | CS |
| ***Control Panel*** | | | | | |
| *Indicator Lights OK (Check for Yes) | ☐ | ☐ | ☐ | ☐ | ☑ |
| Heating/Cooling OK (Check for Yes) | ☐ | ☐ | ☐ | ☐ | ☑ |
| ***Control Panel - Digital Recorder*** | | | | | |
| Local Recorder On (Check for Yes) | ☐ | ☐ | ☐ | ☐ | ☑ |
| ***Control Panel - Touchscreen - Process Overview*** | | | | | |
| *Gas Handling Skid Inlet Pressure (inWC) | | | | | 42.2 |
| *Flare DP (inWC) | | | | | 5.38 |
| *Flare Flame Temperature (F) | | | | | 1338 |
| ***Control Panel - Touchscreen*** *(Press Next)* | | | | | |
| Panel Temperature (F) | | | | | 118 |
| *Gas Handling Skid Inlet Temperature (F) | | | | | 49 |
| *Recirculation Valve Position (%Closed) | | | | | 20 |
| ***Control Panel - Touchscreen - Flare Flow Data*** *(Press Back 2x, Flare Flow Data)* | | | | | |
| *Flow Rate (SCFM) | | | | | 497 |
| *Total Flow (MMSCF) | | | | | 979.4 |
| *Flow Pressure (inWC) | | | | | 6.9 |
| *Flow Temperature (F) | | | | | 129 |
| ***Control Panel - Touchscreen*** *(Press Resettable Flow History, Analog Data Menu, Blower Data)* | | | | | |
| *Resettable Total Flow (MMSCF) | | | | | 635.48 |
| *Reset Date/Time (mm/dd/yy hh.mm:ss) | | | | | |
| ***Control Panel - Touchscreen - Blower Data*** *(Press Main)* | | | | | |
| *Blower 301 Runtime (Hours) | | | | | 36107 |
| *Blower 301 Vibration (in/Sec) | | | | | 0.24 |
| *Blower 301 Speed (%Max) | | | | | 92 |
| *Blower 301 Inlet Bearing Temp (F) | | | | | 98 |
| *Blower 301 Outlet Bearing Temp (F) | | | | | 139 |
| ***Control Panel - Blower Keypad*** | | | | | |
| *Blower 301 Current (Amps) | | | | | 141 |
| ***Gas Handling Skid*** | | | | | |
| *Demister Inlet Pressure (inWC) | | | | | -42.7 |
| *Demister Outlet Pressure (inWC) | | | | | -45.6 |
| *Demister DP (inWC) | | | | | +2.9 |
| *Flame Arrester Inlet Pressure (inWC) | | | | | +8.0 |
| *Flame Arrester Outlet Pressure (inWC) | | | | | +4.9 |
| *Flame Arrester DP (inWC) | | | | | +3.1 |
| ***Flare*** | | | | | |
| *Visible Emissions (Yes/No, If yes explain) | | | | | No |
| *Spiralator Position (%Open) | | | | | 50 |
| *Manual Louver 1 Position (%Open) | | | | | 50 |
| *Manual Louver 2 Position (%Open) | | | | | 50 |
| ***Other*** | | | | | |
| Heat Trace OK (Check for Yes) | ☐ | ☐ | ☐ | ☐ | ☑ |
| *Propane Tank Level OK (T1 \| T2 (Check for Yes)) | ☐ ☐ | ☐ ☐ | ☐ ☐ | ☐ ☐ | ☑ ☑ |
| ***Flare 3 - Monitoring*** | | | | | |
| Time (hh:mm) | | | | | 1455 |
| Technician (initials) | | | | | CS |
| ***Control Panel*** | | | | | |
| *Indicator Lights OK (Check for Yes) | ☐ | ☐ | ☐ | ☐ | ☑ |
| *Heating/Cooling OK (Check for Yes) | ☐ | ☐ | ☐ | ☐ | ☑ |
| ***Control Panel - Digital Recorder*** | | | | | |
| *Remote Recorder On (Check for Yes) | ☐ | ☐ | ☐ | ☐ | ☑ |

# Collection and Control System Monitoring

| Day of Week | Monday | Tuesday | Wednesday | Thursday | Friday |
|---|---|---|---|---|---|
| ***Control Panel - Touchscreen - Analog Data Menu - Process Overview*** | | | | | |
| *Gas Handling Skid Inlet Vacuum (inWC) | | | | | 40.1 |
| *Gas Handling Skid Inlet Temperature (F) | | | | | 73 |
| *Panel Temperature (F) | | | | | 128 |
| *Recirculation Valve Position (%Closed) | | | | | 100 |
| *Flare Flame Temperature (F) | | | | | 1312 |
| *Flame Arrestor Temperature (F) | | | | | 117 |
| ***Control Panel - Touchscreen - Blower Data*** *(Press Back, Blower Menu, Select Current Blower)* | | | | | |
| *Blower Runtime (Blower \| Runtime (Hours)) | | | | | 302 1896 |
| *Blower Speed (Blower \| Speed (%Max)) | | | | | 77 |
| *Blower Vibration (Blower \| Vibration (in/Sec)) | | | | | 0.07 |
| *Blower Current (Blower \| Current (Amps)) | | | | | 41.5 |
| ***Control Panel - Touchscreen - Flare Flow Data*** *(Press Back X2, Flare Flow Data)* | | | | | |
| *Flow Rate (SCFM) | | | | | 1472 |
| *Total Flow (MMSCF) | | | | | 248.68 |
| *Flow Pressure (inWC) | | | | | 9.3 |
| *Flow Temperature (F) | | | | | 117 |
| *Flow DP (inWC) | | | | | 5.58 |
| ***Control Panel - Touchscreen*** *(Press Resettable)* | | | | | |
| *Resettable Total Flow (MMSCF) | | | | | 248.68 |
| *Reset Date/Time (mm/dd/yy hh:mm ss) | | | | | |
| ***Control Panel - Touchscreen - Alarm History*** *(Press Main)* | | | | | |
| *Alarm History (Check box if no alarm) | ☐ | ☐ | ☐ | ☐ | ☑ |
| ***Gas Handling Skid*** | | | | | |
| *Demister Inlet Pressure (inWC) | | | | | -40.1 |
| *Demister Outlet Pressure (inWC) | | | | | -42.2 |
| *Demister DP (inWC) | | | | | +2.1 |
| *Flame Arrester Inlet Pressure (inWC) | | | | | +10.6 |
| *Flame Arrester Outlet Pressure (inWC) | | | | | +9.8 |
| *Flame Arrester DP (inWC) | | | | | +0.8 |
| *Fail-Close Valve Air Pressure (psi) | | | | | 105 |
| ***Flare*** | | | | | |
| *Visible Emissions (Yes/No, If yes explain) | | | | | NO |
| *Spiralator Position (%Open) | | | | | 0 |
| *Manual Louver 1 Position (%Open) | | | | | 0 |
| *Manual Louver 2 Position (%Open) | | | | | 0 |
| ***Other*** | | | | | |
| *Heat Trace OK (Check for Yes) | ☐ | ☐ | ☐ | ☐ | ☑ |
| *Propane Tank Level OK (T1 \| T2 (Check for Yes)) | ☐ ☐ | ☐ ☐ | ☐ ☐ | ☐ ☐ | ☑ ☑ |
| ***Engine Plant 1 - Monitoring*** | | | | | |
| Time (hh mm) | | | | | 1504 |
| Technician (Initials) | | | | | CS |
| ***Engine Control Panel*** | | | | | |
| *Power Setpoint (kWh) (Engine #4 \| #3) | | | | | 711 707 |
| *Power Setpoint (kWh) (Engine #2 \| #1) | | | | | C52C87 |
| ***Control Room - Laptop*** | | | | | |
| *Flow Total (MSCF) | | | | | 342090.2 |
| *Flow Rate (SCFM) | | | | | 924.4 |
| *Discharge Gas Temperature (F) | | | | | 96.0 |
| ***Engine Bay/Control Room Window*** | | | | | |
| *Inlet Gas Pressure (inWC) | | | | | -44.0 |
| ***Other*** | | | | | |
| *Visible Emissions (Yes/No, If yes explain) | | | | | NO |

***Note * Collect during device operation only***

**Remarks**

# Collection and Control System Monitoring

| Day of Week | Monday | Tuesday | Wednesday | Thursday | Friday |
|---|---|---|---|---|---|
| Date (mm/dd/yy) | | | 09/15/21 | | 09/17/21 |
| **Lowry Header - Monitoring** | | | | | |
| Time (hh mm) | | | 1456 | | 1539 |
| Technician (initials) | | | CS | | CS |
| ***Control Panel - Digital Recorder*** | | | | | |
| Flow Rate (SCFM) | | | 206 | | 205 |
| Gas Temperature (F) | | | 65.0 | | 65 |
| **Flare 2 - Monitoring** | | | | | |
| Time (hh:mm) | | | 1502 | | 1542 |
| Technician (initials) | | | CS | | CS |
| ***Control Panel*** | | | | | |
| *Indicator Lights OK (Check for Yes) | ☐ | ☐ | ☑ | ☐ | ☑ |
| Heating/Cooling OK (Check for Yes) | ☐ | ☐ | ☑ | ☐ | ☑ |
| ***Control Panel - Digital Recorder*** | | | | | |
| Local Recorder On (Check for Yes) | ☐ | ☐ | ☑ | ☐ | ☑ |
| ***Control Panel - Touchscreen - Process Overview*** | | | | | |
| *Gas Handling Skid Inlet Pressure (inWC) | | | 41.8 | | 41.6 |
| *Flare DP (inWC) | | | 5.48 | | 5.50 |
| *Flare Flame Temperature (F) | | | 1247 | | 1275 |
| ***Control Panel - Touchscreen*** *(Press Next)* | | | | | |
| Panel Temperature (F) | | | 111 | | 62 |
| *Gas Handling Skid Inlet Temperature (F) | | | 51 | | 79 |
| *Recirculation Valve Position (%Closed) | | | 70 | | 70 |
| ***Control Panel - Touchscreen - Flare Flow Data*** *(Press Back 2x, Flare Flow Data)* | | | | | |
| *Flow Rate (SCFM) | | | 501 | | 498 |
| *Total Flow (MMSCF) | | | 982.29 | | 983.75 |
| *Flow Pressure (inWC) | | | 7.0 | | 7.0 |
| *Flow Temperature (F) | | | 128 | | 146 |
| ***Control Panel - Touchscreen*** *(Press Resettable Flow History, Analog Data Menu, Blower Data)* | | | | | |
| *Resettable Total Flow (MMSCF) | | | C38.63 | | C40.09 |
| *Reset Date/Time (mm/dd/yy hh.mm ss) | | | | | |
| ***Control Panel - Touchscreen - Blower Data*** *(Press Main)* | | | | | |
| *Blower 301 Runtime (Hours) | | | 37012 | | 37061 |
| *Blower 301 Vibration (in/Sec) | | | 0.26 | | 0.24 |
| *Blower 301 Speed (%Max) | | | 93 | | 91 |
| *Blower 301 Inlet Bearing Temp (F) | | | 90 | | 86 |
| *Blower 301 Outlet Bearing Temp (F) | | | 138 | | 135 |
| ***Control Panel - Blower Keypad*** | | | | | |
| *Blower 301 Current (Amps) | | | 13.9 | | 14.0 |
| ***Gas Handling Skid*** | | | | | |
| *Demister Inlet Pressure (inWC) | | | -42.0 | | -42.3 |
| *Demister Outlet Pressure (inWC) | | | -44.8 | | -45.1 |
| *Demister DP (inWC) | | | +2.8 | | +2.8 |
| *Flame Arrester Inlet Pressure (inWC) | | | -18.0 | | +7.8 |
| *Flame Arrester Outlet Pressure (inWC) | | | +4.9 | | +4.9 |
| *Flame Arrester DP (inWC) | | | +3.1 | | +2.9 |
| ***Flare*** | | | | | |
| *Visible Emissions (Yes/No, If yes explain) | | | NO | | NO |
| *Spiralator Position (%Open) | | | 50 | | 50 |
| *Manual Louver 1 Position (%Open) | | | 50 | | 50 |
| *Manual Louver 2 Position (%Open) | | | 50 | | 50 |
| ***Other*** | | | | | |
| Heat Trace OK (Check for Yes) | ☐ | ☐ | ☑ | ☐ | ☑ |
| *Propane Tank Level OK (T1 \| T2 (Check for Yes)) | ☐ ☐ | ☐ ☐ | ☑ ☑ | ☐ ☐ | ☑ ☑ |
| **Flare 3 - Monitoring** | | | | | |
| Time (hh.mm) | | | 1511 | | 1550 |
| Technician (initials) | | | CS | | CS |
| ***Control Panel*** | | | | | |
| *Indicator Lights OK (Check for Yes) | ☐ | ☐ | ☑ | ☐ | ☑ |
| *Heating/Cooling OK (Check for Yes) | ☐ | ☐ | ☑ | ☐ | ☑ |
| ***Control Panel - Digital Recorder*** | | | | | |
| *Remote Recorder On (Check for Yes) | ☐ | ☐ | ☑ | ☐ | ☑ |

# Collection and Control System Monitoring

| Day of Week | Monday | Tuesday | Wednesday | Thursday | Friday |
|---|---|---|---|---|---|
| ***Control Panel - Touchscreen - Analog Data Menu - Process Overview*** | | | | | |
| *Gas Handling Skid Inlet Vacuum (inWC) | | | 39.7 | | 39.6 |
| *Gas Handling Skid Inlet Temperature (F) | | | 74 | | 73 |
| *Panel Temperature (F) | | | 119 | | 98 |
| *Recirculation Valve Position (%Closed) | | | 100 | | 100 |
| *Flare Flame Temperature (F) | | | 1299 | | 1121 |
| *Flame Arrestor Temperature (F) | | | 116 | | 107 |
| ***Control Panel - Touchscreen - Blower Data*** *(Press Back, Blower Menu, Select Current Blower)* | | | | | |
| *Blower Runtime (Blower \| Runtime (Hours)) | | | 302 1793 | | 302 2042 |
| *Blower Speed (Blower \| Speed (%Max)) | | | 79 | | 76 |
| *Blower Vibration (Blower \| Vibration (in/Sec)) | | | 0.06 | | 0.05 |
| *Blower Current (Blower \| Current (Amps)) | | | 42.1 | | 39.3 |
| ***Control Panel - Touchscreen - Flare Flow Data*** *(Press Back X2, Flare Flow Data)* | | | | | |
| *Flow Rate (SCFM) | | | 1416 | | 1376 |
| *Total Flow (MMSCF) | | | 257.66 | | 261.66 |
| *Flow Pressure (inWC) | | | 9.0 | | 7.9 |
| *Flow Temperature (F) | | | 117 | | 108 |
| *Flow DP (inWC) | | | 5.29 | | 4.73 |
| ***Control Panel - Touchscreen*** *(Press Resettable)* | | | | | |
| *Resettable Total Flow (MMSCF) | | | 257.66 | | 261.66 |
| *Reset Date/Time (mm/dd/yy hh:mm ss) | | | | | |
| ***Control Panel - Touchscreen - Alarm History*** *(Press Main)* | | | | | |
| *Alarm History (Check box if no alarm) | ☐ | ☐ | ☑ | ☐ | ☑ |
| ***Gas Handling Skid*** | | | | | |
| *Demister Inlet Pressure (inWC) | | | -39.6 | | -40.0 |
| *Demister Outlet Pressure (inWC) | | | -41.7 | | -41.9 |
| *Demister DP (inWC) | | | +2.1 | | +1.9 |
| *Flame Arrester Inlet Pressure (inWC) | | | +10.7 | | +9.3 |
| *Flame Arrester Outlet Pressure (inWC) | | | +9.8 | | +8.4 |
| *Flame Arrester DP (inWC) | | | +0.9 | | +0.9 |
| *Fail-Close Valve Air Pressure (psi) | | | 105 | | 105 |
| ***Flare*** | | | | | |
| *Visible Emissions (Yes/No, If yes explain) | | | NO | | NO |
| *Spiralator Position (%Open) | | | 50 | | 50 |
| *Manual Louver 1 Position (%Open) | | | 50 | | 50 |
| *Manual Louver 2 Position (%Open) | | | 50 | | 50 |
| ***Other*** | | | | | |
| *Heat Trace OK (Check for Yes) | ☐ | ☐ | ☑ | ☐ | ☑ |
| *Propane Tank Level OK (T1 \| T2 (Check for Yes)) | ☐ ☐ | ☐ ☐ | ☑ ☑ | ☐ ☐ | ☑ ☑ |
| ***Engine Plant 1 - Monitoring*** | | | | | |
| Time (hh mm) | | | 1518 | | 1554 |
| Technician (Initials) | | | CS | | CS |
| ***Engine Control Panel*** | | | | | |
| *Power Setpoint (kWh) (Engine #4 \| #3) | | | 648 680 | | 645 647 |
| *Power Setpoint (kWh) (Engine #2 \| #1) | | | 682 697 | | 682 683 |
| ***Control Room - Laptop*** | | | | | |
| *Flow Total (MSCF) | | | 3489247 | | 3512661 |
| *Flow Rate (SCFM) | | | 968.2 | | 961.3 |
| *Discharge Gas Temperature (F) | | | 89.0 | | 72.0 |
| ***Engine Bay/Control Room Window*** | | | | | |
| *Inlet Gas Pressure (inWC) | | | -43.1 | | -41.4 |
| ***Other*** | | | | | |
| *Visible Emissions (Yes/No, If yes explain) | | | NO | | NO |

***Note * Collect during device operation only***

**Remarks**

# Collection and Control System Monitoring

| Day of Week | Monday | Tuesday | Wednesday | Thursday | Friday |
|---|---|---|---|---|---|
| Date (mm/dd/yy) | | | | | 09/24/21 |
| ***Lowry Header - Monitoring*** | | | | | |
| Time (hh:mm) | | | | | 1507 |
| Technician (Initials) | | | | | CS |
| ***Control Panel - Digital Recorder*** | | | | | |
| Flow Rate (SCFM) | | | | | 198 |
| Gas Temperature (F) | | | | | 65 |
| ***Flare 2 - Monitoring*** | | | | | |
| Time (hh:mm) | | | | | 1513 |
| Technician (Initials) | | | | | CS |
| ***Control Panel*** | | | | | |
| *Indicator Lights OK (Check for Yes) | ☐ | ☐ | ☐ | ☐ | ☑ |
| Heating/Cooling OK (Check for Yes) | ☐ | ☐ | ☐ | ☐ | ☑ |
| ***Control Panel - Digital Recorder*** | | | | | |
| Local Recorder On (Check for Yes) | ☐ | ☐ | ☐ | ☐ | ☑ |
| ***Control Panel - Touchscreen - Process Overview*** | | | | | |
| *Gas Handling Skid Inlet Pressure (inWC) | | | | | 37.9 |
| *Flare DP (inWC) | | | | | 5.04 |
| *Flare Flame Temperature (F) | | | | | 1172 |
| ***Control Panel - Touchscreen*** *(Press Next)* | | | | | |
| Panel Temperature (F) | | | | | 64 |
| *Gas Handling Skid Inlet Temperature (F) | | | | | 78 |
| *Recirculation Valve Position (%Closed) | | | | | 0 |
| ***Control Panel - Touchscreen - Flare Flow Data*** *(Press Back 2x, Flare Flow Data)* | | | | | |
| *Flow Rate (SCFM) | | | | | 497 |
| *Total Flow (MMSCF) | | | | | 98878 |
| *Flow Pressure (inWC) | | | | | 7.1 |
| *Flow Temperature (F) | | | | | 143 |
| ***Control Panel - Touchscreen*** *(Press Resettable Flow History, Analog Data Menu, Blower Data)* | | | | | |
| *Resettable Total Flow (MMSCF) | | | | | 6.45.12 |
| *Reset Date/Time (mm/dd/yy hh.mm.ss) | | | | | |
| ***Control Panel - Touchscreen - Blower Data*** *(Press Main)* | | | | | |
| *Blower 301 Runtime (Hours) | | | | | 37228 |
| *Blower 301 Vibration (in/Sec) | | | | | 0.22 |
| *Blower 301 Speed (%Max) | | | | | 89 |
| *Blower 301 Inlet Bearing Temp (F) | | | | | 88 |
| *Blower 301 Outlet Bearing Temp (F) | | | | | 145 |
| ***Control Panel - Blower Keypad*** | | | | | |
| *Blower 301 Current (Amps) | | | | | 13.5 |
| ***Gas Handling Skid*** | | | | | |
| *Demister Inlet Pressure (inWC) | | | | | -38.1 |
| *Demister Outlet Pressure (inWC) | | | | | -41.3 |
| *Demister DP (inWC) | | | | | +3.2 |
| *Flame Arrester Inlet Pressure (inWC) | | | | | +8.4 |
| *Flame Arrester Outlet Pressure (inWC) | | | | | +4.9 |
| *Flame Arrester DP (inWC) | | | | | +3.5 |
| ***Flare*** | | | | | |
| *Visible Emissions (Yes/No, If yes explain) | | | | | NO |
| *Spiralator Position (%Open) | | | | | 50 |
| *Manual Louver 1 Position (%Open) | | | | | 50 |
| *Manual Louver 2 Position (%Open) | | | | | 50 |
| ***Other*** | | | | | |
| Heat Trace OK (Check for Yes) | ☐ | ☐ | ☐ | ☐ | ☑ |
| *Propane Tank Level OK (T1 \| T2 (Check for Yes)) | ☐ ☐ | ☐ ☐ | ☐ ☐ | ☐ ☐ | ☑ ☑ |
| ***Flare 3 - Monitoring*** | | | | | |
| Time (hh:mm) | | | | | 1530 |
| Technician (Initials) | | | | | CS |
| ***Control Panel*** | | | | | |
| *Indicator Lights OK (Check for Yes) | ☐ | ☐ | ☐ | ☐ | ☑ |
| *Heating/Cooling OK (Check for Yes) | ☐ | ☐ | ☐ | ☐ | ☑ |
| ***Control Panel - Digital Recorder*** | | | | | |
| *Remote Recorder On (Check for Yes) | ☐ | ☐ | ☐ | ☐ | ☑ |

# Collection and Control System Monitoring

| Day of Week | Monday | Tuesday | Wednesday | Thursday | Friday |
|---|---|---|---|---|---|
| ***Control Panel - Touchscreen - Analog Data Menu - Process Overview*** | | | | | |
| *Gas Handling Skid Inlet Vacuum (inWC) | | | | | 39.6 |
| *Gas Handling Skid Inlet Temperature (F) | | | | | 74 |
| *Panel Temperature (F) | | | | | 103 |
| *Recirculation Valve Position (%Closed) | | | | | 100 |
| *Flare Flame Temperature (F) | | | | | 1279 |
| *Flame Arrestor Temperature (F) | | | | | 109 |
| ***Control Panel - Touchscreen - Blower Data*** *(Press Back, Blower Menu, Select Current Blower)* | | | | | |
| *Blower Runtime (Blower \| Runtime (Hours)) | | | | | 302 → 2207 |
| *Blower Speed (Blower \| Speed (%Max)) | | | | | 74 |
| *Blower Vibration (Blower \| Vibration (in/Sec)) | | | | | 0.04 |
| *Blower Current (Blower \| Current (Amps)) | | | | | 36.9 |
| ***Control Panel - Touchscreen - Flare Flow Data*** *(Press Back X2, Flare Flow Data)* | | | | | |
| *Flow Rate (SCFM) | | | | | 1391 |
| *Total Flow (MMSCF) | | | | | 275.25 |
| *Flow Pressure (inWC) | | | | | 7.5 |
| *Flow Temperature (F) | | | | | 109 |
| *Flow DP (inWC) | | | | | 4.68 |
| ***Control Panel - Touchscreen*** *(Press Resettable)* | | | | | |
| *Resettable Total Flow (MMSCF) | | | | | 275.25 |
| *Reset Date/Time (mm/dd/yy hh:mm ss) | | | | | |
| ***Control Panel - Touchscreen - Alarm History*** *(Press Main)* | | | | | |
| *Alarm History (Check box if no alarm) | ☐ | ☐ | ☐ | ☐ | ✓ |
| ***Gas Handling Skid*** | | | | | |
| *Demister Inlet Pressure (inWC) | | | | | -39.7 |
| *Demister Outlet Pressure (inWC) | | | | | -41.5 |
| *Demister DP (inWC) | | | | | +1.8 |
| *Flame Arrester Inlet Pressure (inWC) | | | | | +9.0 |
| *Flame Arrester Outlet Pressure (inWC) | | | | | +8.3 |
| *Flame Arrester DP (inWC) | | | | | +0.7 |
| *Fail-Close Valve Air Pressure (psi) | | | | | 105 |
| ***Flare*** | | | | | |
| *Visible Emissions (Yes/No, If yes explain) | | | | | NO |
| *Spiralator Position (%Open) | | | | | 50 |
| *Manual Louver 1 Position (%Open) | | | | | 50 |
| *Manual Louver 2 Position (%Open) | | | | | 50 |
| ***Other*** | | | | | |
| *Heat Trace OK (Check for Yes) | ☐ | ☐ | ☐ | ☐ | ✓ |
| *Propane Tank Level OK (T1 \| T2 (Check for Yes)) | ☐ ☐ | ☐ ☐ | ☐ ☐ | ☐ ☐ | ✓ ✓ |
| ***Engine Plant 1 - Monitoring*** | | | | | |
| Time (hh mm) | | | | | 1528 |
| Technician (Initials) | | | | | CS |
| ***Engine Control Panel*** | | | | | |
| *Power Setpoint (kWh) (Engine #4 \| #3) | | | | | 695 686 |
| *Power Setpoint (kWh) (Engine #2 \| #1) | | | | | 694 681 |
| ***Control Room - Laptop*** | | | | | |
| *Flow Total (MSCF) | | | | | 3611175.7 |
| *Flow Rate (SCFM) | | | | | 993.3 |
| *Discharge Gas Temperature (F) | | | | | 760 |
| ***Engine Bay/Control Room Window*** | | | | | |
| *Inlet Gas Pressure (inWC) | | | | | -42.3 |
| ***Other*** | | | | | |
| *Visible Emissions (Yes/No, If yes explain) | | | | | NO |

***Note * Collect during device operation only***

**Remarks**

# Collection and Control System Monitoring

| Day of Week | Monday | Tuesday | Wednesday | Thursday | Friday |
|---|---|---|---|---|---|
| Date (mm/dd/yy) | | | | 09/30/21 | 10/01/21 |
| ***Lowry Header - Monitoring*** | | | | | |
| Time (hh:mm) | | | | 1502 | 1422 |
| Technician (Initials) | | | | CS | CS |
| ***Control Panel - Digital Recorder*** | | | | | |
| Flow Rate (SCFM) | | | | 196 | 192 |
| Gas Temperature (F) | | | | 64.0 | 64.0 |
| ***Flare 2 - Monitoring*** | | | | | |
| Time (hh:mm) | | | | 1505 | 1424 |
| Technician (Initials) | | | | CS | CS |
| ***Control Panel*** | | | | | |
| *Indicator Lights OK (Check for Yes) | ☐ | ☐ | ☐ | ✓ | ✓ |
| Heating/Cooling OK (Check for Yes) | ☐ | ☐ | ☐ | ✓ | ✓ |
| ***Control Panel - Digital Recorder*** | | | | | |
| Local Recorder On (Check for Yes) | ☐ | ☐ | ☐ | ✓ | ✓ |
| ***Control Panel - Touchscreen - Process Overview*** | | | | | |
| *Gas Handling Skid Inlet Pressure (inWC) | | | | 35.8 | 35.6 |
| *Flare DP (inWC) | | | | 5.17 | 5.44 |
| *Flare Flame Temperature (F) | | | | 1160 | 1174 |
| ***Control Panel - Touchscreen*** *(Press Next)* | | | | | |
| Panel Temperature (F) | | | | 56 | 65 |
| *Gas Handling Skid Inlet Temperature (F) | | | | 78 | 75 |
| *Recirculation Valve Position (%Closed) | | | | 70 | 70 |
| ***Control Panel - Touchscreen - Flare Flow Data*** *(Press Back 2x, Flare Flow Data)* | | | | | |
| *Flow Rate (SCFM) | | | | 500 | 504 |
| *Total Flow (MMSCF) | | | | 993.11 | 993.81 |
| *Flow Pressure (inWC) | | | | 6.9 | 6.8 |
| *Flow Temperature (F) | | | | 134 | 137 |
| ***Control Panel - Touchscreen*** *(Press Resettable Flow History, Analog Data Menu, Blower Data)* | | | | | |
| *Resettable Total Flow (MMSCF) | | | | 649.44 | 650.14 |
| *Reset Date/Time (mm/dd/yy hh:mm:ss) | | | | | |
| ***Control Panel - Touchscreen - Blower Data*** *(Press Main)* | | | | | |
| *Blower 301 Runtime (Hours) | | | | 37377 | 37395 |
| *Blower 301 Vibration (In/Sec) | | | | 0.29 | 0.28 |
| *Blower 301 Speed (%Max) | | | | 86 | 87 |
| *Blower 301 Inlet Bearing Temp (F) | | | | 77 | 85 |
| *Blower 301 Outlet Bearing Temp (F) | | | | 134 | 137 |
| ***Control Panel - Blower Keypad*** | | | | | |
| *Blower 301 Current (Amps) | | | | 13.2 | 13.0 |
| ***Gas Handling Skid*** | | | | | |
| *Demister Inlet Pressure (inWC) | | | | -36.1 | -36.0 |
| *Demister Outlet Pressure (inWC) | | | | -39.0 | -38.9 |
| *Demister DP (inWC) | | | | +2.9 | +2.9 |
| *Flame Arrester Inlet Pressure (inWC) | | | | +8.3 | +8.2 |
| *Flame Arrester Outlet Pressure (inWC) | | | | +4.8 | +4.9 |
| *Flame Arrester DP (inWC) | | | | +3.5 | +3.3 |
| ***Flare*** | | | | | |
| *Visible Emissions (Yes/No, If yes explain) | | | | NO | NO |
| *Spiralator Position (%Open) | | | | 50 | 50 |
| *Manual Louver 1 Position (%Open) | | | | 50 | 50 |
| *Manual Louver 2 Position (%Open) | | | | 50 | 50 |
| ***Other*** | | | | | |
| Heat Trace OK (Check for Yes) | ☐ | ☐ | ☐ | ✓ | ✓ |
| *Propane Tank Level OK (T1 \| T2 (Check for Yes)) | ☐ ☐ | ☐ ☐ | ☐ ☐ | ✓ ✓ | ✓ ✓ |
| ***Flare 3 - Monitoring*** | | | | | |
| Time (hh:mm) | | | | 1516 | 1435 |
| Technician (Initials) | | | | CS | CS |
| ***Control Panel*** | | | | | |
| *Indicator Lights OK (Check for Yes) | ☐ | ☐ | ☐ | ✓ | ✓ |
| *Heating/Cooling OK (Check for Yes) | ☐ | ☐ | ☐ | ✓ | ✓ |
| ***Control Panel - Digital Recorder*** | | | | | |
| *Remote Recorder On (Check for Yes) | ☐ | ☐ | ☐ | ✓ | ✓ |

# Collection and Control System Monitoring

| Day of Week | Monday | Tuesday | Wednesday | Thursday | Friday |
|---|---|---|---|---|---|
| ***Control Panel - Touchscreen - Analog Data Menu - Process Overview*** | | | | | |
| *Gas Handling Skid Inlet Vacuum (inWC) | | | | 40.3 | 40.0 |
| *Gas Handling Skid Inlet Temperature (F) | | | | 71 | 73 |
| *Panel Temperature (F) | | | | 87 | 100 |
| *Recirculation Valve Position (%Closed) | | | | 100 | 100 |
| *Flare Flame Temperature (F) | | | | 1285 | 1183 |
| *Flame Arrestor Temperature (F) | | | | 99 | 104 |
| ***Control Panel - Touchscreen - Blower Data*** *(Press Back, Blower Menu, Select Current Blower)* | | | | | |
| *Blower Runtime (Blower \| Runtime (Hours)) | | | | 302 2357 | 302 2374 |
| *Blower Speed (Blower \| Speed (%Max)) | | | | 70 | 72 |
| *Blower Vibration (Blower \| Vibration (in/Sec)) | | | | 0.02 | 0.03 |
| *Blower Current (Blower \| Current (Amps)) | | | | 36.2 | 36.5 |
| ***Control Panel - Touchscreen - Flare Flow Data*** *(Press Back X2, Flare Flow Data)* | | | | | |
| *Flow Rate (SCFM) | | | | 1262 | 1297 |
| *Total Flow (MMSCF) | | | | 286.65 | 288.44 |
| *Flow Pressure (inWC) | | | | 6.2 | 6.8 |
| *Flow Temperature (F) | | | | 101 | 107 |
| *Flow DP (inWC) | | | | 4.08 | 4.10 |
| ***Control Panel - Touchscreen*** *(Press Resettable)* | | | | | |
| *Resettable Total Flow (MMSCF) | | | | 286.65 | 288.44 |
| *Reset Date/Time (mm/dd/yy hh:mm ss) | | | | | |
| ***Control Panel - Touchscreen - Alarm History*** *(Press Main)* | | | | | |
| *Alarm History (Check box if no alarm) | ☐ | ☐ | ☐ | ☑ | ☑ |
| ***Gas Handling Skid*** | | | | | |
| *Demister Inlet Pressure (inWC) | | | | -40.1 | -39.7 |
| *Demister Outlet Pressure (inWC) | | | | -41.5 | -41.7 |
| *Demister DP (inWC) | | | | +1.4 | +2.0 |
| *Flame Arrester Inlet Pressure (inWC) | | | | +7.5 | +8.5 |
| *Flame Arrester Outlet Pressure (inWC) | | | | +7.0 | +7.6 |
| *Flame Arrester DP (inWC) | | | | +0.5 | +0.9 |
| *Fail-Close Valve Air Pressure (psi) | | | | 105 | 105 |
| ***Flare*** | | | | | |
| *Visible Emissions (Yes/No, If yes explain) | | | | NO | NO |
| *Spiralator Position (%Open) | | | | 50 | 50 |
| *Manual Louver 1 Position (%Open) | | | | 50 | 50 |
| *Manual Louver 2 Position (%Open) | | | | 50 | 50 |
| ***Other*** | | | | | |
| *Heat Trace OK (Check for Yes) | ☐ | ☐ | ☐ | ☑ | ☑ |
| *Propane Tank Level OK (T1 \| T2 (Check for Yes)) | ☐ ☐ | ☐ ☐ | ☐ ☐ | ☑ ☑ | ☑ ☑ |
| ***Engine Plant 1 - Monitoring*** | | | | | |
| Time (hh mm) | | | | 1524 | 1443 |
| Technician (Initials) | | | | CS | |
| ***Engine Control Panel*** | | | | | |
| *Power Setpoint (kWh) (Engine #4 \| #3) | | | | 692 698 | 717 744 |
| *Power Setpoint (kWh) (Engine #2 \| #1) | | | | 635 651 | 688 697 |
| ***Control Room - Laptop*** | | | | | |
| *Flow Total (MSCF) | | | | 36,984.5 | 37,273.6 |
| *Flow Rate (SCFM) | | | | 913.7 | 942.4 |
| *Discharge Gas Temperature (F) | | | | 63.0 | 65.0 |
| ***Engine Bay/Control Room Window*** | | | | | |
| *Inlet Gas Pressure (inWC) | | | | -42.1 | -43.6 |
| ***Other*** | | | | | |
| *Visible Emissions (Yes/No, If yes explain) | | | | NO | NO |

***Note * Collect during device operation only***

**Remarks**

# Collection and Control System Monitoring

| Day of Week | Monday | Tuesday | Wednesday | Thursday | Friday |
|---|---|---|---|---|---|
| Date (mm/dd/yy) | | | 10/13/21 | 10/14/21 | |
| **Lowry Header - Monitoring** | | | | | |
| Time (hh:mm) | | | 1513 | 1420 | |
| Technician (Initials) | | | CB | CB | |
| ***Control Panel - Digital Recorder*** | | | | | |
| Flow Rate (SCFM) | | | 209 | 218 | |
| Gas Temperature (F) | | | 93.0 | 93 | |
| **Flare 2 - Monitoring** | | | | | |
| Time (hh:mm) | | | 1517 | 1424 | |
| Technician (Initials) | | | CB | CB | |
| ***Control Panel*** | | | | | |
| *Indicator Lights OK (Check for Yes) | ☐ | ☐ | ☑ | ☑ | ☐ |
| Heating/Cooling OK (Check for Yes) | ☐ | ☐ | ☑ | ☑ | ☐ |
| ***Control Panel - Digital Recorder*** | | | | | |
| Local Recorder On (Check for Yes) | ☐ | ☐ | ☑ | ☑ | ☐ |
| ***Control Panel - Touchscreen - Process Overview*** | | | | | |
| *Gas Handling Skid Inlet Pressure (InWC) | | | 42.5 | 41.7 | |
| *Flare DP (InWC) | | | 5.49 | 5.38 | |
| *Flare Flame Temperature (F) | | | 1168 | 1145 | |
| ***Control Panel - Touchscreen*** (Press Next) | | | | | |
| Panel Temperature (F) | | | 83 | 79 | |
| *Gas Handling Skid Inlet Temperature (F) | | | 59 | 61 | |
| *Recirculation Valve Position (%Closed) | | | 70 | 70 | |
| ***Control Panel - Touchscreen - Flare Flow Data*** (Press Back 2x, Flare Flow Data) | | | | | |
| *Flow Rate (SCFM) | | | 502 | 499 | |
| *Total Flow (MMSCF) | | | 1002.41 | 1003.10 | |
| *Flow Pressure (InWC) | | | 6.8 | 6.7 | |
| *Flow Temperature (F) | | | 126 | 122 | |
| ***Control Panel - Touchscreen*** (Press Resettable Flow History, Analog Data Menu, Blower Data) | | | | | |
| *Resettable Total Flow (MMSCF) | | | 058.74 | 059.44 | |
| *Reset Date/Time (mm/dd/yy hh.mm.ss) | | | | | |
| ***Control Panel - Touchscreen - Blower Data*** (Press Main) | | | | | |
| *Blower 301 Runtime (Hours) | | | 37052 | 37105 | |
| *Blower 301 Vibration (in/Sec) | | | 0.27 | 0.25 | |
| *Blower 301 Speed (%Max) | | | 92 | 91 | |
| *Blower 301 Inlet Bearing Temp (F) | | | 61 | 60 | |
| *Blower 301 Outlet Bearing Temp (F) | | | 127 | 121 | |
| ***Control Panel - Blower Keypad*** | | | | | |
| *Blower 301 Current (Amps) | | | 14.0 | 13.7 | |
| ***Gas Handling Skid*** | | | | | |
| *Demister Inlet Pressure (InWC) | | | -42.8 | -42.7 | |
| *Demister Outlet Pressure (InWC) | | | -45.6 | -45.5 | |
| *Demister DP (InWC) | | | +2.8 | +2.8 | |
| *Flame Arrester Inlet Pressure (InWC) | | | +8.0 | +7.6 | |
| *Flame Arrester Outlet Pressure (InWC) | | | +4.8 | +4.6 | |
| *Flame Arrester DP (InWC) | | | +3.2 | +3.0 | |
| ***Flare*** | | | | | |
| *Visible Emissions (Yes/No, If yes explain) | | | NO | NO | |
| *Spiralator Position (%Open) | | | 50 | 50 | |
| *Manual Louver 1 Position (%Open) | | | 50 | 50 | |
| *Manual Louver 2 Position (%Open) | | | 50 | 50 | |
| ***Other*** | | | | | |
| Heat Trace OK (Check for Yes) | ☐ | ☐ | ☑ | ☑ | ☐ |
| *Propane Tank Level OK (T1 \| T2 (Check for Yes)) | ☐ ☐ | ☐ ☐ | ☑ ☑ | ☑ ☑ | ☐ ☐ |
| **Flare 3 - Monitoring** | | | | | |
| Time (hh:mm) | | | 1538 | 1431 | |
| Technician (Initials) | | | CB | CB | |
| ***Control Panel*** | | | | | |
| *Indicator Lights OK (Check for Yes) | ☐ | ☐ | ☑ | ☑ | ☐ |
| *Heating/Cooling OK (Check for Yes) | ☐ | ☐ | ☑ | ☑ | ☐ |
| ***Control Panel - Digital Recorder*** | | | | | |
| *Remote Recorder On (Check for Yes) | ☐ | ☐ | ☑ | ☑ | ☐ |

# Collection and Control System Monitoring

| Day of Week | Monday | Tuesday | Wednesday | Thursday | Friday |
|---|---|---|---|---|---|
| ***Control Panel - Touchscreen - Analog Data Menu - Process Overview*** | | | | | |
| *Gas Handling Skid Inlet Vacuum (inWC) | | | 40.4 | 39.9 | |
| *Gas Handling Skid Inlet Temperature (F) | | | 71 | 70 | |
| *Panel Temperature (F) | | | 92 | 85 | |
| *Recirculation Valve Position (%Closed) | | | 100 | 100 | |
| *Flare Flame Temperature (F) | | | 1265 | 1368 | |
| *Flame Arrestor Temperature (F) | | | 105 | 100 | |
| ***Control Panel - Touchscreen - Blower Data*** *(Press Back, Blower Menu, Select Current Blower)* | | | | | |
| *Blower Runtime (Blower \| Runtime (Hours)) | | | 301 2153 | 301 2176 | |
| *Blower Speed (Blower \| Speed (%Max)) | | | 78 | 77 | |
| *Blower Vibration (Blower \| Vibration (In/Sec)) | | | 0.07 | 0.05 | |
| *Blower Current (Blower \| Current (Amps)) | | | 43.1 | 42.4 | |
| ***Control Panel - Touchscreen - Flare Flow Data*** *(Press Back X2, Flare Flow Data)* | | | | | |
| *Flow Rate (SCFM) | | | 1558 | 1534 | |
| *Total Flow (MMSCF) | | | 313.92 | 316.03 | |
| *Flow Pressure (inWC) | | | 9.7 | 9.4 | |
| *Flow Temperature (F) | | | 110 | 104 | |
| *Flow DP (inWC) | | | 6.18 | 5.99 | |
| ***Control Panel - Touchscreen*** *(Press Resettable)* | | | | | |
| *Resettable Total Flow (MMSCF) | | | 313.92 | 316.03 | |
| *Reset Date/Time (mm/dd/yy hh mm ss) | | | | | |
| ***Control Panel - Touchscreen - Alarm History*** *(Press Main)* | | | | | |
| *Alarm History (Check box if no alarm) | ☐ | ☐ | ☑ | ☑ | ☐ |
| ***Gas Handling Skid*** | | | | | |
| *Demister Inlet Pressure (inWC) | | | -40.4 | -40.2 | |
| *Demister Outlet Pressure (inWC) | | | -42.8 | -42.7 | |
| *Demister DP (inWC) | | | +2.4 | +2.5 | |
| *Flame Arrester Inlet Pressure (inWC) | | | +11.6 | +10.4 | |
| *Flame Arrester Outlet Pressure (inWC) | | | +10.6 | +9.7 | |
| *Flame Arrester DP (inWC) | | | +1.8 | +0.7 | |
| *Fail-Close Valve Air Pressure (psi) | | | 105 | 103 | |
| ***Flare*** | | | | | |
| *Visible Emissions (Yes/No, If yes explain) | | | NO | NO | |
| *Spiralator Position (%Open) | | | 50 | 50 | |
| *Manual Louver 1 Position (%Open) | | | 50 | 50 | |
| *Manual Louver 2 Position (%Open) | | | 50 | 50 | |
| ***Other*** | | | | | |
| *Heat Trace OK (Check for Yes) | ☐ | ☐ | ☑ | ☑ | ☐ |
| *Propane Tank Level OK (T1 \| T2 (Check for Yes)) | ☐ ☐ | ☐ ☐ | ☑ ☑ | ☑ ☑ | ☐ ☐ |
| ***Engine Plant 1 - Monitoring*** | | | | | |
| Time (hh mm) | | | 1540 | 1441 | |
| Technician (Initials) | | | CS | CS | |
| ***Engine Control Panel*** | | | | | |
| *Power Setpoint (kWh) (Engine #4 \| #3) | | | 700 664 | 688 690 | |
| *Power Setpoint (kWh) (Engine #2 \| #1) | | | 687 | 697 | |
| ***Control Room - Laptop*** | | | | | |
| *Flow Total (MSCF) | | | 384073.3 | 384909.2 | |
| *Flow Rate (SCFM) | | | 775.8 | 787.8 | |
| *Discharge Gas Temperature (F) | | | 83.0 | 76.0 | |
| ***Engine Bay/Control Room Window*** | | | | | |
| *Inlet Gas Pressure (inWC) | | | -41.7 | -40.5 | |
| ***Other*** | | | | | |
| *Visible Emissions (Yes/No, If yes explain) | | | NO | NO | |

***Note * Collect during device operation only***

**Remarks**

10/13 - Engine #2 Down
10/14 - Engine #2 Down

# Collection and Control System Monitoring

| Day of Week | Monday | Tuesday | Wednesday | Thursday | Friday |
|---|---|---|---|---|---|
| Date (mm/dd/yy) | | | | | 10/22/21 |
| ***Lowry Header - Monitoring*** | | | | | |
| Time (hh:mm) | | | | | 1310 |
| Technician (initials) | | | | | CB |
| ***Control Panel - Digital Recorder*** | | | | | |
| Flow Rate (SCFM) | | | | | 186 |
| Gas Temperature (F) | | | | | 61.0 |
| ***Flare 2 - Monitoring*** | | | | | |
| Time (hh:mm) | | | | | 1314 |
| Technician (initials) | | | | | CB |
| ***Control Panel*** | | | | | |
| *Indicator Lights OK (Check for Yes) | ☐ | ☐ | ☐ | ☐ | ☑ |
| Heating/Cooling OK (Check for Yes) | ☐ | ☐ | ☐ | ☐ | ☑ |
| ***Control Panel - Digital Recorder*** | | | | | |
| Local Recorder On (Check for Yes) | ☐ | ☐ | ☐ | ☐ | ☑ |
| ***Control Panel - Touchscreen - Process Overview*** | | | | | |
| *Gas Handling Skid Inlet Pressure (inWC) | | | | | 40.5 |
| *Flare DP (inWC) | | | | | 5.53 |
| *Flare Flame Temperature (F) | | | | | 1172 |
| ***Control Panel - Touchscreen*** *(Press Next)* | | | | | |
| Panel Temperature (F) | | | | | 100 |
| *Gas Handling Skid Inlet Temperature (F) | | | | | 49 |
| *Recirculation Valve Position (%Closed) | | | | | 0 |
| ***Control Panel - Touchscreen - Flare Flow Data*** *(Press Back 2x, Flare Flow Data)* | | | | | |
| *Flow Rate (SCFM) | | | | | 503 |
| *Total Flow (MMSCF) | | | | | 1008.84 |
| *Flow Pressure (inWC) | | | | | 6.4 |
| *Flow Temperature (F) | | | | | 120 |
| ***Control Panel - Touchscreen*** *(Press Resettable Flow History, Analog Data Menu, Blower Data)* | | | | | |
| *Resettable Total Flow (MMSCF) | | | | | 665.17 |
| *Reset Date/Time (mm/dd/yy hh:mm:ss) | | | | | |
| ***Control Panel - Touchscreen - Blower Data*** *(Press Main)* | | | | | |
| *Blower 301 Runtime (Hours) | | | | | 37896 |
| *Blower 301 Vibration (in/Sec) | | | | | 0.27 |
| *Blower 301 Speed (%Max) | | | | | 88 |
| *Blower 301 Inlet Bearing Temp (F) | | | | | 71 |
| *Blower 301 Outlet Bearing Temp (F) | | | | | 127 |
| ***Control Panel - Blower Keypad*** | | | | | |
| *Blower 301 Current (Amps) | | | | | 13.7 |
| ***Gas Handling Skid*** | | | | | |
| *Demister Inlet Pressure (inWC) | | | | | -37.2 |
| *Demister Outlet Pressure (inWC) | | | | | -44.4 |
| *Demister DP (inWC) | | | | | +7.2 |
| *Flame Arrester Inlet Pressure (inWC) | | | | | +7.4 |
| *Flame Arrester Outlet Pressure (inWC) | | | | | +4.8 |
| *Flame Arrester DP (inWC) | | | | | +2.6 |
| ***Flare*** | | | | | |
| *Visible Emissions (Yes/No, If yes explain) | | | | | NO |
| *Spiralator Position (%Open) | | | | | 50 |
| *Manual Louver 1 Position (%Open) | | | | | 50 |
| *Manual Louver 2 Position (%Open) | | | | | 50 |
| ***Other*** | | | | | |
| Heat Trace OK (Check for Yes) | ☐ | ☐ | ☐ | ☐ | ☑ |
| *Propane Tank Level OK (T1 \| T2 (Check for Yes)) | ☐ ☐ | ☐ ☐ | ☐ ☐ | ☐ ☐ | ☑ ☑ |
| ***Flare 3 - Monitoring*** | | | | | |
| Time (hh:mm) | | | | | 1332 |
| Technician (initials) | | | | | CB |
| ***Control Panel*** | | | | | |
| *Indicator Lights OK (Check for Yes) | ☐ | ☐ | ☐ | ☐ | ☑ |
| *Heating/Cooling OK (Check for Yes) | ☐ | ☐ | ☐ | ☐ | ☑ |
| ***Control Panel - Digital Recorder*** | | | | | |
| *Remote Recorder On (Check for Yes) | ☐ | ☐ | ☐ | ☐ | ☑ |

# Collection and Control System Monitoring

| Day of Week | Monday | Tuesday | Wednesday | Thursday | Friday |
|---|---|---|---|---|---|
| ***Control Panel - Touchscreen - Analog Data Menu - Process Overview*** | | | | | |
| *Gas Handling Skid Inlet Vacuum (InWC) | | | | | 40.9 |
| *Gas Handling Skid Inlet Temperature (F) | | | | | 70 |
| *Panel Temperature (F) | | | | | 104 |
| *Recirculation Valve Position (%Closed) | | | | | 100 |
| *Flare Flame Temperature (F) | | | | | 1248 |
| *Flame Arrestor Temperature (F) | | | | | 104 |
| ***Control Panel - Touchscreen - Blower Data*** *(Press Back, Blower Menu, Select Current Blower)* | | | | | |
| *Blower Runtime (Blower 1 \| Runtime (Hours)) | | | | | 301 2367 |
| *Blower Speed (Blower 1 \| Speed (%Max)) | | | | | 70 |
| *Blower Vibration (Blower 1 \| Vibration (in/Sec)) | | | | | 0.03 |
| *Blower Current (Blower 1 \| Current (Amps)) | | | | | 32.2 |
| ***Control Panel - Touchscreen - Flare Flow Data*** *(Press Back X2, Flare Flow Data)* | | | | | |
| *Flow Rate (SCFM) | | | | | 1199 |
| *Total Flow (MMSCF) | | | | | 331.52 |
| *Flow Pressure (InWC) | | | | | 6.7 |
| *Flow Temperature (F) | | | | | 105 |
| *Flow DP (InWC) | | | | | 4.45 |
| ***Control Panel - Touchscreen*** *(Press Resettable)* | | | | | |
| *Resettable Total Flow (MMSCF) | | | | | 331.52 |
| *Reset Date/Time (mm/dd/yy hh:mm:ss) | | | | | |
| ***Control Panel - Touchscreen - Alarm History*** *(Press Main)* | | | | | |
| *Alarm History (Check box if no alarm) | ☐ | ☐ | ☐ | ☐ | ☑ |
| ***Gas Handling Skid*** | | | | | |
| *Demister Inlet Pressure (InWC) | | | | | -36.8 |
| *Demister Outlet Pressure (InWC) | | | | | -42.2 |
| *Demister DP (InWC) | | | | | +5.4 |
| *Flame Arrester Inlet Pressure (InWC) | | | | | +6.5 |
| *Flame Arrester Outlet Pressure (InWC) | | | | | +41.5 |
| *Flame Arrester DP (InWC) | | | | | +2.0 |
| *Fail-Close Valve Air Pressure (psi) | | | | | 105 |
| ***Flare*** | | | | | |
| *Visible Emissions (Yes/No, If yes explain) | | | | | NO |
| *Spiralator Position (%Open) | | | | | 50 |
| *Manual Louver 1 Position (%Open) | | | | | 50 |
| *Manual Louver 2 Position (%Open) | | | | | 50 |
| ***Other*** | | | | | |
| *Heat Trace OK (Check for Yes) | ☐ | ☐ | ☐ | ☐ | ☑ |
| *Propane Tank Level OK (T1 \| T2 (Check for Yes)) | ☐ ☐ | ☐ ☐ | ☐ ☐ | ☐ ☐ | ☑ ☑ |
| ***Engine Plant 1 - Monitoring*** | | | | | |
| Time (hh mm) | | | | | 1345 |
| Technician (Initials) | | | | | CS |
| ***Engine Control Panel*** | | | | | |
| *Power Setpoint (kWh) (Engine #4 \| #3) | | | | | 699 699 |
| *Power Setpoint (kWh) (Engine #2 \| #1) | | | | | 710 681 |
| ***Control Room - Laptop*** | | | | | |
| *Flow Total (MSCF) | | | | | 3955341.8 |
| *Flow Rate (SCFM) | | | | | 1010.3 |
| *Discharge Gas Temperature (F) | | | | | 75.0 |
| ***Engine Bay/Control Room Window*** | | | | | |
| *Inlet Gas Pressure (InWC) | | | | | -42.5 |
| ***Other*** | | | | | |
| *Visible Emissions (Yes/No, If yes explain) | | | | | NO |
| ***Note * Collect during device operation only*** | | | | | |

**Remarks**

# Collection and Control System Monitoring

| Day of Week | Monday | Tuesday | Wednesday | Thursday | Friday |
|---|---|---|---|---|---|
| Date (mm/dd/yy) | | | | 10/28/21 | 10/29/21 |
| ***Lowry Header - Monitoring*** | | | | | |
| Time (hh mm) | | | | 10/28/21 | CS |
| Technician (initials) | | | | 1136 | 1402 |
| ***Control Panel - Digital Recorder*** | | | | | |
| Flow Rate (SCFM) | | | | 192 | 208 |
| Gas Temperature (F) | | | | 60.0 | 60.0 |
| ***Flare 2 - Monitoring*** | | | | | |
| Time (hh:mm) | | | | 1640 | 1406 |
| Technician (initials) | | | | CS | CS |
| ***Control Panel*** | | | | | |
| *Indicator Lights OK (Check for Yes) | ☐ | ☐ | ☐ | ☑ | ☑ |
| Heating/Cooling OK (Check for Yes) | ☐ | ☐ | ☐ | ☑ | ☑ |
| ***Control Panel - Digital Recorder*** | | | | | |
| Local Recorder On (Check for Yes) | ☐ | ☐ | ☐ | ☑ | ☑ |
| ***Control Panel - Touchscreen - Process Overview*** | | | | | |
| *Gas Handling Skid Inlet Pressure (inWC) | | | | 42.4 | 43.9 |
| *Flare DP (inWC) | | | | 5.12 | 5.44 |
| *Flare Flame Temperature (F) | | | | 1216 | 1200 |
| ***Control Panel - Touchscreen*** *(Press Next)* | | | | | |
| Panel Temperature (F) | | | | 84 | 100 |
| *Gas Handling Skid Inlet Temperature (F) | | | | 54 | 47 |
| *Recirculation Valve Position (%Closed) | | | | 70 | 70 |
| ***Control Panel - Touchscreen - Flare Flow Data*** *(Press Back 2x, Flare Flow Data)* | | | | | |
| *Flow Rate (SCFM) | | | | 508 | 489 |
| *Total Flow (MMSCF) | | | | 1012.90 | 1013.55 |
| *Flow Pressure (inWC) | | | | 6.4 | 7.1 |
| *Flow Temperature (F) | | | | 117 | 121 |
| ***Control Panel - Touchscreen*** *(Press Resettable Flow History, Analog Data Menu, Blower Data)* | | | | | |
| *Resettable Total Flow (MMSCF) | | | | 669.24 | 669.88 |
| *Reset Date/Time (mm/dd/yy hh.mm.ss) | | | | | |
| ***Control Panel - Touchscreen - Blower Data*** *(Press Main)* | | | | | |
| *Blower 301 Runtime (Hours) | | | | 38031 | 38053 |
| *Blower 301 Vibration (in/Sec) | | | | 0.24 | 0.24 |
| *Blower 301 Speed (%Max) | | | | 89 | 90 |
| *Blower 301 Inlet Bearing Temp (F) | | | | 56 | 68 |
| *Blower 301 Outlet Bearing Temp (F) | | | | 114 | 120 |
| ***Control Panel - Blower Keypad*** | | | | | |
| *Blower 301 Current (Amps) | | | | 14.6 | 14.3 |
| ***Gas Handling Skid*** | | | | | |
| *Demister Inlet Pressure (inWC) | | | | -44.6 | -43.3 |
| *Demister Outlet Pressure (inWC) | | | | -46.7 | -48.3 |
| *Demister DP (inWC) | | | | +2.1 | +5.0 |
| *Flame Arrester Inlet Pressure (inWC) | | | | +7.5 | +8.3 |
| *Flame Arrester Outlet Pressure (inWC) | | | | +4.5 | +4.5 |
| *Flame Arrester DP (inWC) | | | | +3.0 | +3.8 |
| ***Flare*** | | | | | |
| *Visible Emissions (Yes/No, If yes explain) | | | | NO | NO |
| *Spiralator Position (%Open) | | | | 50 | 50 |
| *Manual Louver 1 Position (%Open) | | | | 50 | 50 |
| *Manual Louver 2 Position (%Open) | | | | 50 | 50 |
| ***Other*** | | | | | |
| Heat Trace OK (Check for Yes) | ☐ | ☐ | ☐ | ☑ | ☑ |
| *Propane Tank Level OK (T1 \| T2 (Check for Yes)) | ☐ ☐ | ☐ ☐ | ☐ ☐ | ☑ ☑ | ☑ ☑ |
| ***Flare 3 - Monitoring*** | | | | | |
| Time (hh:mm) | | | | 1652 | 1417 |
| Technician (initials) | | | | CS | CS |
| ***Control Panel*** | | | | | |
| *Indicator Lights OK (Check for Yes) | ☐ | ☐ | ☐ | ☑ | ☑ |
| *Heating/Cooling OK (Check for Yes) | ☐ | ☐ | ☐ | ☑ | ☑ |
| ***Control Panel - Digital Recorder*** | | | | | |
| *Remote Recorder On (Check for Yes) | ☐ | ☐ | ☐ | ☑ | ☑ |

# Collection and Control System Monitoring

| Day of Week | Monday | Tuesday | Wednesday | Thursday | Friday |
|---|---|---|---|---|---|
| ***Control Panel - Touchscreen - Analog Data Menu - Process Overview*** | | | | | |
| *Gas Handling Skid Inlet Vacuum (inWC) | | | | 40.5 | 40.9 |
| *Gas Handling Skid Inlet Temperature (F) | | | | 65 | 69 |
| *Panel Temperature (F) | | | | 89 | 101 |
| *Recirculation Valve Position (%Closed) | | | | 100 | 100 |
| *Flare Flame Temperature (F) | | | | 1284 | 1105 |
| *Flame Arrestor Temperature (F) | | | | 102 | 100 |
| ***Control Panel - Touchscreen - Blower Data*** *(Press Back, Blower Menu, Select Current Blower)* | | | | | |
| *Blower Runtime (Blower \| Runtime (Hours)) | | | | 301 2494 | 301 2515 |
| *Blower Speed (Blower \| Speed (%Max)) | | | | 77 | 67 |
| *Blower Vibration (Blower \| Vibration (in/Sec)) | | | | 0.05 | 0.02 |
| *Blower Current (Blower \| Current (Amps)) | | | | 46.0 | 31.6 |
| ***Control Panel - Touchscreen - Flare Flow Data*** *(Press Back X2, Flare Flow Data)* | | | | | |
| *Flow Rate (SCFM) | | | | 1547 | 1096 |
| *Total Flow (MMSCF) | | | | 340.09 | 341.85 |
| *Flow Pressure (inWC) | | | | 8.6 | 5.8 |
| *Flow Temperature (F) | | | | 103 | 101 |
| *Flow DP (inWC) | | | | 0.93 | 3.58 |
| ***Control Panel - Touchscreen*** *(Press Resettable)* | | | | | |
| *Resettable Total Flow (MMSCF) | | | | 340.09 | 341.85 |
| *Reset Date/Time (mm/dd/yy hh:mm:ss) | | | | | |
| ***Control Panel - Touchscreen - Alarm History*** *(Press Main)* | | | | | |
| *Alarm History (Check box if no alarm) | ☐ | ☐ | ☐ | ☑ | ☑ |
| ***Gas Handling Skid*** | | | | | |
| *Demister Inlet Pressure (inWC) | | | | -43.3 | -42.0 |
| *Demister Outlet Pressure (inWC) | | | | -45.3 | -43.2 |
| *Demister DP (inWC) | | | | +2.0 | +1.2 |
| *Flame Arrester Inlet Pressure (inWC) | | | | +10.6 | -5.8 |
| *Flame Arrester Outlet Pressure (inWC) | | | | +9.7 | +4.8 |
| *Flame Arrester DP (inWC) | | | | +0.9 | +1.0 |
| *Fail-Close Valve Air Pressure (psi) | | | | 105 | 105 |
| ***Flare*** | | | | | |
| *Visible Emissions (Yes/No, If yes explain) | | | | NO | NO |
| *Spiralator Position (%Open) | | | | 50 | 50 |
| *Manual Louver 1 Position (%Open) | | | | 50 | 50 |
| *Manual Louver 2 Position (%Open) | | | | 50 | 50 |
| ***Other*** | | | | | |
| *Heat Trace OK (Check for Yes) | ☐ | ☐ | ☐ | ☑ | ☑ |
| *Propane Tank Level OK (T1 \| T2 (Check for Yes)) | ☐ ☐ | ☐ ☐ | ☐ ☐ | ☑ ☑ | ☑ ☑ |
| ***Engine Plant 1 - Monitoring*** | | | | | |
| Time (hh:mm) | | | | 1704 | 1480 |
| Technician (Initials) | | | | CS | CS |
| ***Engine Control Panel*** | | | | | |
| *Power Setpoint (kWh) (Engine #4 \| #3) | | | | 672 — | 703 666 |
| *Power Setpoint (kWh) (Engine #2 \| #1) | | | | — 688 | 691 673 |
| ***Control Room - Laptop*** | | | | | |
| *Flow Total (MSCF) | | | | 4037605 | 4047553 |
| *Flow Rate (SCFM) | | | | 605.4 | 996.3 |
| *Discharge Gas Temperature (F) | | | | 77.0 | 74.0 |
| ***Engine Bay/Control Room Window*** | | | | | |
| *Inlet Gas Pressure (inWC) | | | | -41.7 | -45.2 |
| ***Other*** | | | | | |
| *Visible Emissions (Yes/No, If yes explain) | | | | NO | NO |

***Note * Collect during device operation only***

**Remarks**

10/28 - Engine #4 & #2 Down

# Collection and Control System Monitoring

| Day of Week | Monday | Tuesday | Wednesday | Thursday | Friday |
|---|---|---|---|---|---|
| Date (mm/dd/yy) | | | | | 11/05/21 |
| ***Lowry Header - Monitoring*** | | | | | |
| Time (hh:mm) | | | | | 1355 |
| Technician (Initials) | | | | | DS |
| ***Control Panel - Digital Recorder*** | | | | | |
| Flow Rate (SCFM) | | | | | 218 |
| Gas Temperature (F) | | | | | 59.0 |
| ***Flare 2 - Monitoring*** | | | | | |
| Time (hh:mm) | | | | | 1402 |
| Technician (Initials) | | | | | DS |
| ***Control Panel*** | | | | | |
| *Indicator Lights OK (Check for Yes) | ☐ | ☐ | ☐ | ☐ | ☑ |
| Heating/Cooling OK (Check for Yes) | ☐ | ☐ | ☐ | ☐ | ☑ |
| ***Control Panel - Digital Recorder*** | | | | | |
| Local Recorder On (Check for Yes) | ☐ | ☐ | ☐ | ☐ | ☑ |
| ***Control Panel - Touchscreen - Process Overview*** | | | | | |
| *Gas Handling Skid Inlet Pressure (InWC) | | | | | 41.6 |
| *Flare DP (InWC) | | | | | 5.32 |
| *Flare Flame Temperature (F) | | | | | 1230 |
| ***Control Panel - Touchscreen*** *(Press Next)* | | | | | |
| Panel Temperature (F) | | | | | 100 |
| *Gas Handling Skid Inlet Temperature (F) | | | | | 43 |
| *Recirculation Valve Position (%Closed) | | | | | 70 |
| ***Control Panel - Touchscreen - Flare Flow Data*** *(Press Back 2x, Flare Flow Data)* | | | | | |
| *Flow Rate (SCFM) | | | | | 497 |
| *Total Flow (MMSCF) | | | | | 1018.59 |
| *Flow Pressure (InWC) | | | | | 6.7 |
| *Flow Temperature (F) | | | | | 118 |
| ***Control Panel - Touchscreen*** *(Press Resettable Flow History, Analog Data Menu, Blower Data)* | | | | | |
| *Resettable Total Flow (MMSCF) | | | | | 674.93 |
| *Reset Date/Time (mm/dd/yy hh.mm.ss) | | | | | |
| ***Control Panel - Touchscreen - Blower Data*** *(Press Main)* | | | | | |
| *Blower 301 Runtime (Hours) | | | | | 38221 |
| *Blower 301 Vibration (in/Sec) | | | | | 0.25 |
| *Blower 301 Speed (%Max) | | | | | 90 |
| *Blower 301 Inlet Bearing Temp (F) | | | | | 67 |
| *Blower 301 Outlet Bearing Temp (F) | | | | | 121 |
| ***Control Panel - Blower Keypad*** | | | | | |
| *Blower 301 Current (Amps) | | | | | 3.8 |
| ***Gas Handling Skid*** | | | | | |
| *Demister Inlet Pressure (InWC) | | | | | -41.6 |
| *Demister Outlet Pressure (InWC) | | | | | -44.2 |
| *Demister DP (InWC) | | | | | +2.6 |
| *Flame Arrester Inlet Pressure (InWC) | | | | | +8.1 |
| *Flame Arrester Outlet Pressure (InWC) | | | | | +4.7 |
| *Flame Arrester DP (InWC) | | | | | +3.4 |
| ***Flare*** | | | | | |
| *Visible Emissions (Yes/No, If yes explain) | | | | | No |
| *Spiralator Position (%Open) | | | | | 50 |
| *Manual Louver 1 Position (%Open) | | | | | 50 |
| *Manual Louver 2 Position (%Open) | | | | | 50 |
| ***Other*** | | | | | |
| Heat Trace OK (Check for Yes) | ☐ | ☐ | ☐ | ☐ | ☑ |
| *Propane Tank Level OK (T1 & T2 (Check for Yes)) | ☐ ☐ | ☐ ☐ | ☐ ☐ | ☐ ☐ | ☑ ☑ |
| ***Flare 3 - Monitoring*** | | | | | |
| Time (hh:mm) | | | | | 1415 |
| Technician (Initials) | | | | | DS |
| ***Control Panel*** | | | | | |
| *Indicator Lights OK (Check for Yes) | ☐ | ☐ | ☐ | ☐ | ☑ |
| *Heating/Cooling OK (Check for Yes) | ☐ | ☐ | ☐ | ☐ | ☑ |
| ***Control Panel - Digital Recorder*** | | | | | |
| *Remote Recorder On (Check for Yes) | ☐ | ☐ | ☐ | ☐ | ☑ |

# Collection and Control System Monitoring

| Day of Week | Monday | Tuesday | Wednesday | Thursday | Friday |
|---|---|---|---|---|---|
| ***Control Panel - Touchscreen - Analog Data Menu - Process Overview*** | | | | | |
| *Gas Handling Skid Inlet Vacuum (inWC) | | | | | 40.1 |
| *Gas Handling Skid Inlet Temperature (F) | | | | | 68 |
| *Panel Temperature (F) | | | | | 101 |
| *Recirculation Valve Position (%Closed) | | | | | 100 |
| *Flare Flame Temperature (F) | | | | | 1264 |
| *Flame Arrestor Temperature (F) | | | | | 102 |
| ***Control Panel - Touchscreen - Blower Data*** *(Press Back, Blower Menu, Select Current Blower)* | | | | | |
| *Blower Runtime (Blower 1 Runtime (Hours)) | | | | | 302 2582 |
| *Blower Speed (Blower 1 Speed (%Max)) | | | | | 69 |
| *Blower Vibration (Blower 1 Vibration (in/Sec)) | | | | | 6.02 |
| *Blower Current (Blower 1 Current (Amps)) | | | | | 34.0 |
| ***Control Panel - Touchscreen - Flare Flow Data*** *(Press Back X2, Flare Flow Data)* | | | | | |
| *Flow Rate (SCFM) | | | | | 1222 |
| *Total Flow (MMSCF) | | | | | 353.37 |
| *Flow Pressure (inWC) | | | | | 6.1 |
| *Flow Temperature (F) | | | | | 104 |
| *Flow DP (inWC) | | | | | 3.78 |
| ***Control Panel - Touchscreen*** *(Press Resettable)* | | | | | |
| *Resettable Total Flow (MMSCF) | | | | | 353.37 |
| *Reset Date/Time (mm/dd/yy hh:mm ss) | | | | | |
| ***Control Panel - Touchscreen - Alarm History*** *(Press Main)* | | | | | |
| *Alarm History (Check box if no alarm) | ☐ | ☐ | ☐ | ☐ | ☑ |
| ***Gas Handling Skid*** | | | | | |
| *Demister Inlet Pressure (inWC) | | | | | -39.4 |
| *Demister Outlet Pressure (inWC) | | | | | -40.6 |
| *Demister DP (inWC) | | | | | +1.2 |
| *Flame Arrester Inlet Pressure (inWC) | | | | | +7.8 |
| *Flame Arrester Outlet Pressure (inWC) | | | | | +7.1 |
| *Flame Arrester DP (inWC) | | | | | +0.7 |
| *Fail-Close Valve Air Pressure (psi) | | | | | 105 |
| ***Flare*** | | | | | |
| *Visible Emissions (Yes/No, If yes explain) | | | | | NO |
| *Spiralator Position (%Open) | | | | | 50 |
| *Manual Louver 1 Position (%Open) | | | | | 50 |
| *Manual Louver 2 Position (%Open) | | | | | 50 |
| ***Other*** | | | | | |
| *Heat Trace OK (Check for Yes) | ☐ | ☐ | ☐ | ☐ | ☑ |
| *Propane Tank Level OK (T1 \| T2 (Check for Yes)) | ☐ ☐ | ☐ ☐ | ☐ ☐ | ☐ ☐ | ☑ ☑ |
| ***Engine Plant 1 - Monitoring*** | | | | | |
| Time (hh mm) | | | | | 1424 |
| Technician (Initials) | | | | | CS |
| ***Engine Control Panel*** | | | | | |
| *Power Setpoint (kWh) (Engine #4 \| #3) | | | | | 681 687 |
| *Power Setpoint (kWh) (Engine #2 \| #1) | | | | | 689 686 |
| ***Control Room - Laptop*** | | | | | |
| *Flow Total (MSCF) | | | | | 415190.6 |
| *Flow Rate (SCFM) | | | | | 1073.0 |
| *Discharge Gas Temperature (F) | | | | | 74.0 |
| ***Engine Bay/Control Room Window*** | | | | | |
| *Inlet Gas Pressure (inWC) | | | | | -43.9 |
| ***Other*** | | | | | |
| *Visible Emissions (Yes/No, If yes explain) | | | | | NO |
| ***Note * Collect during device operation only*** | | | | | |

**Remarks**

# Collection and Control System Monitoring

| Day of Week | Monday | Tuesday | Wednesday | Thursday | Friday |
|---|---|---|---|---|---|
| Date (mm/dd/yy) | | | | 11/11/21 | 11/12/21 |
| **Lowry Header - Monitoring** | | | | | |
| Time (hh mm) | | | | 1402 | 1340 |
| Technician (Initials) | | | | CS | CS |
| ***Control Panel - Digital Recorder*** | | | | | |
| Flow Rate (SCFM) | | | | 217 | 216 |
| Gas Temperature (F) | | | | 58 | 58 |
| **Flare 2 - Monitoring** | | | | | |
| Time (hh:mm) | | | | 1408 | 1343 |
| Technician (Initials) | | | | CS | CS |
| ***Control Panel*** | | | | | |
| *Indicator Lights OK (Check for Yes) | ☐ | ☐ | ☐ | ✓ | ✓ |
| Heating/Cooling OK (Check for Yes) | ☐ | ☐ | ☐ | ✓ | ✓ |
| ***Control Panel - Digital Recorder*** | | | | | |
| Local Recorder On (Check for Yes) | ☐ | ☐ | ☐ | ✓ | ✓ |
| ***Control Panel - Touchscreen - Process Overview*** | | | | | |
| *Gas Handling Skid Inlet Pressure (InWC) | | | | 38.5 | 38.9 |
| *Flare DP (InWC) | | | | 5.24 | 5.24 |
| *Flare Flame Temperature (F) | | | | 1024 | 1230 |
| ***Control Panel - Touchscreen*** *(Press Next)* | | | | | |
| Panel Temperature (F) | | | | 75 | 83 |
| *Gas Handling Skid Inlet Temperature (F) | | | | 54 | 49 |
| *Recirculation Valve Position (%Closed) | | | | 70 | 70 |
| ***Control Panel - Touchscreen - Flare Flow Data*** *(Press Back 2x, Flare Flow Data)* | | | | | |
| *Flow Rate (SCFM) | | | | 499 | 498 |
| *Total Flow (MMSCF) | | | | 1022.43 | 1023.1 |
| *Flow Pressure (InWC) | | | | 6.5 | 6.6 |
| *Flow Temperature (F) | | | | 111 | 112 |
| ***Control Panel - Touchscreen*** *(Press Resettable Flow History, Analog Data Menu, Blower Data)* | | | | | |
| *Resettable Total Flow (MMSCF) | | | | 678.8 | 679.5 |
| *Reset Date/Time (mm/dd/yy hh.mm ss) | | | | | |
| ***Control Panel - Touchscreen - Blower Data*** *(Press Main)* | | | | | |
| *Blower 301 Runtime (Hours) | | | | 35349 | 35372 |
| *Blower 301 Vibration (In/Sec) | | | | 0.22 | 0.24 |
| *Blower 301 Speed (%Max) | | | | 85 | 86 |
| *Blower 301 Inlet Bearing Temp (F) | | | | 57 | 55 |
| *Blower 301 Outlet Bearing Temp (F) | | | | 105 | 119 |
| ***Control Panel - Blower Keypad*** | | | | | |
| *Blower 301 Current (Amps) | | | | 13.4 | 13.3 |
| ***Gas Handling Skid*** | | | | | |
| *Demister Inlet Pressure (InWC) | | | | -40.0 | -39.2 |
| *Demister Outlet Pressure (InWC) | | | | -42.4 | -42.1 |
| *Demister DP (InWC) | | | | +2.4 | +2.9 |
| *Flame Arrester Inlet Pressure (InWC) | | | | +7.8 | +7.8 |
| *Flame Arrester Outlet Pressure (InWC) | | | | +4.7 | +4.6 |
| *Flame Arrester DP (InWC) | | | | +3.1 | +3.2 |
| ***Flare*** | | | | | |
| *Visible Emissions (Yes/No, If yes explain) | | | | NO | NO |
| *Spiralator Position (%Open) | | | | 50 | 50 |
| *Manual Louver 1 Position (%Open) | | | | 50 | 50 |
| *Manual Louver 2 Position (%Open) | | | | 50 | 50 |
| ***Other*** | | | | ✓ | ✓ |
| Heat Trace OK (Check for Yes) | ☐ | ☐ | ☐ | ✓ | ✓ |
| *Propane Tank Level OK (T1 \| T2 (Check for Yes)) | ☐ ☐ | ☐ ☐ | ☐ ☐ | ✓ ✓ | ✓ ✓ |
| **Flare 3 - Monitoring** | | | | | |
| Time (hh.mm) | | | | 1419 | 1355 |
| Technician (Initials) | | | | CS | CS |
| ***Control Panel*** | | | | | |
| *Indicator Lights OK (Check for Yes) | ☐ | ☐ | ☐ | ✓ | ✓ |
| *Heating/Cooling OK (Check for Yes) | ☐ | ☐ | ☐ | ✓ | ✓ |
| ***Control Panel - Digital Recorder*** | | | | | |
| *Remote Recorder On (Check for Yes) | ☐ | ☐ | ☐ | ✓ | ✓ |

# Collection and Control System Monitoring

| Day of Week | Monday | Tuesday | Wednesday | Thursday | Friday |
|---|---|---|---|---|---|
| ***Control Panel - Touchscreen - Analog Data Menu - Process Overview*** | | | | | |
| *Gas Handling Skid Inlet Vacuum (inWC) | | | | 39.6 | 39.8 |
| *Gas Handling Skid Inlet Temperature (F) | | | | ~~69~~ 65 | 65 |
| *Panel Temperature (F) | | | | 73 | 72 |
| *Recirculation Valve Position (%Closed) | | | | 100 | 100 |
| *Flare Flame Temperature (F) | | | | 1412 | 1376 |
| *Flame Arrestor Temperature (F) | | | | 92 | 94 |
| ***Control Panel - Touchscreen - Blower Data*** *(Press Back, Blower Menu, Select Current Blower)* | | | | | |
| *Blower Runtime (Blower \| Runtime (Hours)) | | | | 302 2690 | 302 2714 |
| *Blower Speed (Blower \| Speed (%Max)) | | | | 69 | 67 |
| *Blower Vibration (Blower \| Vibration (in/Sec)) | | | | 0.01 | 0.01 |
| *Blower Current (Blower \| Current (Amps)) | | | | 32.3 | 31.8 |
| ***Control Panel - Touchscreen - Flare Flow Data*** *(Press Back X2, Flare Flow Data)* | | | | | |
| *Flow Rate (SCFM) | | | | 1168 | 1124 |
| *Total Flow (MMSCF) | | | | 342.75 | 344.33 |
| *Flow Pressure (inWC) | | | | 5.9 | 4.6 |
| *Flow Temperature (F) | | | | 95 | 95 |
| *Flow DP (inWC) | | | | 3.44 | 3.21 |
| ***Control Panel - Touchscreen*** *(Press Resettable)* | | | | | |
| *Resettable Total Flow (MMSCF) | | | | 342.7 | 344.55 |
| *Reset Date/Time (mm/dd/yy hh:mm:ss) | | | | | |
| ***Control Panel - Touchscreen - Alarm History*** *(Press Main)* | | | | | |
| *Alarm History (Check box if no alarm) | ☐ | ☐ | ☐ | ✓ | ✓ |
| ***Gas Handling Skid*** | | | | | |
| *Demister Inlet Pressure (inWC) | | | | -40.0 | -40.0 |
| *Demister Outlet Pressure (inWC) | | | | -41.5 | -41.2 |
| *Demister DP (inWC) | | | | +1.5 | +1.2 |
| *Flame Arrester Inlet Pressure (inWC) | | | | +7.0 | +5.6 |
| *Flame Arrester Outlet Pressure (inWC) | | | | +6.4 | +4.4 |
| *Flame Arrester DP (inWC) | | | | +0.6 | +0.7 |
| *Fail-Close Valve Air Pressure (psi) | | | | 105 | 105 |
| ***Flare*** | | | | | |
| *Visible Emissions (Yes/No, If yes explain) | | | | NO | NO |
| *Spiralator Position (%Open) | | | | ~~50~~ 50 | 50 |
| *Manual Louver 1 Position (%Open) | | | | 50 | 50 |
| *Manual Louver 2 Position (%Open) | | | | 50 | 50 |
| ***Other*** | | | | | |
| *Heat Trace OK (Check for Yes) | ☐ | ☐ | ☐ | ✓ | ✓ |
| *Propane Tank Level OK (T1 \| T2 (Check for Yes)) | ☐ ☐ | ☐ ☐ | ☐ ☐ | ✓ ✓ | ✓ ✓ |
| ***Engine Plant 1 - Monitoring*** | | | | | |
| Time (hh:mm) | | | | 1430 | 1426 |
| Technician (Initials) | | | | CS | CS |
| ***Engine Control Panel*** | | | | | |
| *Power Setpoint (kWh) (Engine #4 \| #3) | | | | 700 670 | 714 684 |
| *Power Setpoint (kWh) (Engine #2 \| #1) | | | | 699 677 | 705 705 |
| ***Control Room - Laptop*** | | | | | |
| *Flow Total (MSCF) | | | | 424595.9 | 426150.9 |
| *Flow Rate (SCFM) | | | | 1065.6 | 1089.2 |
| *Discharge Gas Temperature (F) | | | | 78.0 | 80.0 |
| ***Engine Bay/Control Room Window*** | | | | | |
| *Inlet Gas Pressure (inWC) | | | | -42.1 | -42.4 |
| ***Other*** | | | | | |
| *Visible Emissions (Yes/No, If yes explain) | | | | NO | NO |

***Note * Collect during device operation only***

**Remarks**

# Collection and Control System Monitoring

| Day of Week | Monday | Tuesday | Wednesday | Thursday | Friday |
|---|---|---|---|---|---|
| Date (mm/dd/yy) | | | | 11/18/21 | 11/19/21 |
| ***Lowry Header - Monitoring*** | | | | | |
| Time (hh:mm) | | | | 1443 | 1305 |
| Technician (Initials) | | | | CS | CS |
| ***Control Panel - Digital Recorder*** | | | | | |
| Flow Rate (SCFM) | | | | 213 | 213 |
| Gas Temperature (F) | | | | 57.0 | 57.0 |
| ***Flare 2 - Monitoring*** | | | | | |
| Time (hh:mm) | | | | 1450 | 1305 |
| Technician (Initials) | | | | CS | CS |
| ***Control Panel*** | | | | | |
| *Indicator Lights OK (Check for Yes) | ☐ | ☐ | ☐ | ☑ | ☑ |
| Heating/Cooling OK (Check for Yes) | ☐ | ☐ | ☐ | ☑ | ☑ |
| ***Control Panel - Digital Recorder*** | | | | | |
| Local Recorder On (Check for Yes) | ☐ | ☐ | ☐ | ☑ | ☑ |
| ***Control Panel - Touchscreen - Process Overview*** | | | | | |
| *Gas Handling Skid Inlet Pressure (inWC) | | | | 36.4 | 36.3 |
| *Flare DP (inWC) | | | | 5.38 | 5.21 |
| *Flare Flame Temperature (F) | | | | 1111 | 1128 |
| ***Control Panel - Touchscreen*** *(Press Next)* | | | | | |
| Panel Temperature (F) | | | | 79 | 95 |
| *Gas Handling Skid Inlet Temperature (F) | | | | 50 | 42 |
| *Recirculation Valve Position (%Closed) | | | | 70 | 70 |
| ***Control Panel - Touchscreen - Flare Flow Data*** *(Press Back 2x, Flare Flow Data)* | | | | | |
| *Flow Rate (SCFM) | | | | 496 | 500 |
| *Total Flow (MMSCF) | | | | 1027.5 | 1028.17 |
| *Flow Pressure (inWC) | | | | 6.5 | 6.5 |
| *Flow Temperature (F) | | | | 108 | 109 |
| ***Control Panel - Touchscreen*** *(Press Resettable Flow History, Analog Data Menu, Blower Data)* | | | | | |
| *Resettable Total Flow (MMSCF) | | | | 683.83 | 684.51 |
| *Reset Date/Time (mm/dd/yy hh.mm.ss) | | | | | |
| ***Control Panel - Touchscreen - Blower Data*** *(Press Main)* | | | | | |
| *Blower 301 Runtime (Hours) | | | | 38518 | 38540 |
| *Blower 301 Vibration (in/Sec) | | | | 0.25 | 0.24 |
| *Blower 301 Speed (%Max) | | | | 85 | 84 |
| *Blower 301 Inlet Bearing Temp (F) | | | | 55 | 63 |
| *Blower 301 Outlet Bearing Temp (F) | | | | 105 | 117 |
| ***Control Panel - Blower Keypad*** | | | | | |
| *Blower 301 Current (Amps) | | | | 13.0 | 13.5 |
| ***Gas Handling Skid*** | | | | | |
| *Demister Inlet Pressure (inWC) | | | | -36.4 | -36.8 |
| *Demister Outlet Pressure (inWC) | | | | -39.3 | -39.5 |
| *Demister DP (inWC) | | | | +2.9 | +2.7 |
| *Flame Arrester Inlet Pressure (inWC) | | | | +7.6 | +7.9 |
| *Flame Arrester Outlet Pressure (inWC) | | | | +4.6 | +4.6 |
| *Flame Arrester DP (inWC) | | | | +3.0 | +3.3 |
| ***Flare*** | | | | | |
| *Visible Emissions (Yes/No, If yes explain) | | | | NO | NO |
| *Spiralator Position (%Open) | | | | 50 | 50 |
| *Manual Louver 1 Position (%Open) | | | | 50 | 50 |
| *Manual Louver 2 Position (%Open) | | | | 50 | 50 |
| ***Other*** | | | | | |
| Heat Trace OK (Check for Yes) | ☐ | ☐ | ☐ | ☑ | ☑ |
| *Propane Tank Level OK (T1 \| T2 (Check for Yes)) | ☐ ☐ | ☐ ☐ | ☐ ☐ | ☑ ☑ | ☑ ☑ |
| ***Flare 3 - Monitoring*** | | | | | |
| Time (hh:mm) | | | | 1500 | 1325 |
| Technician (Initials) | | | | CS | CS |
| ***Control Panel*** | | | | | |
| *Indicator Lights OK (Check for Yes) | ☐ | ☐ | ☐ | ☑ | ☑ |
| *Heating/Cooling OK (Check for Yes) | ☐ | ☐ | ☐ | ☑ | ☑ |
| ***Control Panel - Digital Recorder*** | | | | | |
| *Remote Recorder On (Check for Yes) | ☐ | ☐ | ☐ | ☑ | ☑ |

# Collection and Control System Monitoring

| Day of Week | Monday | Tuesday | Wednesday | Thursday | Friday |
|---|---|---|---|---|---|
| ***Control Panel - Touchscreen - Analog Data Menu - Process Overview*** | | | | | |
| *Gas Handling Skid Inlet Vacuum (inWC) | | | | 40.4 | 39.4 |
| *Gas Handling Skid Inlet Temperature (F) | | | | 64 | 65 |
| *Panel Temperature (F) | | | | 85 | 103 |
| *Recirculation Valve Position (%Closed) | | | | 100 | 100 |
| *Flare Flame Temperature (F) | | | | 1296 | 1285 |
| *Flame Arrestor Temperature (F) | | | | 92 | 99 |
| ***Control Panel - Touchscreen - Blower Data*** *(Press Back, Blower Menu, Select Current Blower)* | | | | | |
| *Blower Runtime (Blower \| Runtime (Hours)) | | | | 302 2859 | 302 2881 |
| *Blower Speed (Blower \| Speed (%Max)) | | | | 67 | 68 |
| *Blower Vibration (Blower \| Vibration (in/Sec)) | | | | 0.01 | 0.02 |
| *Blower Current (Blower \| Current (Amps)) | | | | 31.4 | 32.2 |
| ***Control Panel - Touchscreen - Flare Flow Data*** *(Press Back X2, Flare Flow Data)* | | | | | |
| *Flow Rate (SCFM) | | | | 1145 | 1160 |
| *Total Flow (MMSCF) | | | | 374.15 | 375.66 |
| *Flow Pressure (inWC) | | | | 4.8 | 4.9 |
| *Flow Temperature (F) | | | | 94 | 100 |
| *Flow DP (inWC) | | | | 3.23 | 3.39 |
| ***Control Panel - Touchscreen*** *(Press Resettable)* | | | | | |
| *Resettable Total Flow (MMSCF) | | | | 374.15 | 375.66 |
| *Reset Date/Time (mm/dd/yy hh:mm:ss) | | | | | |
| ***Control Panel - Touchscreen - Alarm History*** *(Press Main)* | | | | | |
| *Alarm History (Check box if no alarm) | ☐ | ☐ | ☐ | ☑ | ☑ |
| ***Gas Handling Skid*** | | | | | |
| *Demister Inlet Pressure (inWC) | | | | -40.2 | -39.6 |
| *Demister Outlet Pressure (inWC) | | | | -41.4 | -41.3 |
| *Demister DP (inWC) | | | | +1.2 | +1.7 |
| *Flame Arrester Inlet Pressure (inWC) | | | | +5.7 | -1.4 |
| *Flame Arrester Outlet Pressure (inWC) | | | | +5.6 | +5.8 |
| *Flame Arrester DP (inWC) | | | | +0.7 | +0.6 |
| *Fail-Close Valve Air Pressure (psi) | | | | 105 | 105 |
| ***Flare*** | | | | | |
| *Visible Emissions (Yes/No, If yes explain) | | | | NO | NO |
| *Spiralator Position (%Open) | | | | 50 | 50 |
| *Manual Louver 1 Position (%Open) | | | | 50 | 50 |
| *Manual Louver 2 Position (%Open) | | | | 50 | 50 |
| ***Other*** | | | | | |
| *Heat Trace OK (Check for Yes) | ☐ | ☐ | ☒ | ☑ | ☑ |
| *Propane Tank Level OK (T1 \| T2 (Check for Yes)) | ☐ ☐ | ☐ ☐ | ☐ ☐ | ☑ ☑ | ☑ ☑ |
| ***Engine Plant 1 - Monitoring*** | | | | | |
| Time (hh:mm) | | | | 1513 | 1339 |
| Technician (Initials) | | | | CS | CS |
| ***Engine Control Panel*** | | | | | |
| *Power Setpoint (kWh) (Engine #4 \| #3) | | | | 685 690 | 699 700 |
| *Power Setpoint (kWh) (Engine #2 \| #1) | | | | 700 688 | 685 671 |
| ***Control Room - Laptop*** | | | | | |
| *Flow Total (MSCF) | | | | 4354720 | 4371267 |
| *Flow Rate (SCFM) | | | | 1080.3 | 1083.1 |
| *Discharge Gas Temperature (F) | | | | 93.0 | 800 |
| ***Engine Bay/Control Room Window*** | | | | | |
| *Inlet Gas Pressure (inWC) | | | | -42.2 | -43.0 |
| ***Other*** | | | | | |
| *Visible Emissions (Yes/No, If yes explain) | | | | NO | NO |
| ***Note * Collect during device operation only*** | | | | | |

**Remarks**

# Collection and Control System Monitoring

| Day of Week | Monday | Tuesday | Wednesday | Thursday | Friday |
|---|---|---|---|---|---|
| Date (mm/dd/yy) | | | 11/24/21 | | 11/26/21 |
| ***Lowry Header - Monitoring*** | | | | | |
| Time (hh:mm) | | | 1312 | | 1020 |
| Technician (Initials) | | | CS | | CS |
| ***Control Panel - Digital Recorder*** | | | | | |
| Flow Rate (SCFM) | | | 211 | | 213 |
| Gas Temperature (F) | | | 56.0 | | 56.0 |
| ***Flare 2 - Monitoring*** | | | | | |
| Time (hh:mm) | | | 1314 | | 1024 |
| Technician (Initials) | | | CS | | CS |
| ***Control Panel*** | | | | | |
| *Indicator Lights OK (Check for Yes) | ☐ | ☐ | ☑ | ☐ | ☑ |
| Heating/Cooling OK (Check for Yes) | ☐ | ☐ | ☑ | ☐ | ☑ |
| ***Control Panel - Digital Recorder*** | | | | | |
| Local Recorder On (Check for Yes) | ☐ | ☐ | ☑ | ☐ | ☑ |
| ***Control Panel - Touchscreen - Process Overview*** | | | | | |
| *Gas Handling Skid Inlet Pressure (InWC) | | | 34.2 | | 35.7 |
| *Flare DP (InWC) | | | 4.95 | | 5.44 |
| *Flare Flame Temperature (F) | | | 1054 | | 1245 |
| ***Control Panel - Touchscreen*** *(Press Next)* | | | | | |
| Panel Temperature (F) | | | 68 | | 83 |
| *Gas Handling Skid Inlet Temperature (F) | | | 52 | | 47 |
| *Recirculation Valve Position (%Closed) | | | 70 | | 70 |
| ***Control Panel - Touchscreen - Flare Flow Data*** *(Press Back 2x, Flare Flow Data)* | | | | | |
| *Flow Rate (SCFM) | | | 503 | | 505 |
| *Total Flow (MMSCF) | | | 1031.78 | | 1033.14 |
| *Flow Pressure (InWC) | | | 4.5 | | 4.7 |
| *Flow Temperature (F) | | | 102 | | 110 |
| ***Control Panel - Touchscreen*** *(Press Resettable Flow History, Analog Data Menu, Blower Data)* | | | | | |
| *Resettable Total Flow (MMSCF) | | | 685.11 | | 689.47 |
| *Reset Date/Time (mm/dd/yy hh:mm:ss) | | | | | |
| ***Control Panel - Touchscreen - Blower Data*** *(Press Main)* | | | | | |
| *Blower 301 Runtime (Hours) | | | 35760 | | 38705 |
| *Blower 301 Vibration (in/Sec) | | | 0.24 | | 0.24 |
| *Blower 301 Speed (%Max) | | | 84 | | 84 |
| *Blower 301 Inlet Bearing Temp (F) | | | 46 | | 63 |
| *Blower 301 Outlet Bearing Temp (F) | | | 89 | | 103 |
| ***Control Panel - Blower Keypad*** | | | | | |
| *Blower 301 Current (Amps) | | | 13.1 | | 13.2 |
| ***Gas Handling Skid*** | | | | | |
| *Demister Inlet Pressure (InWC) | | | -36.3 | | -36.1 |
| *Demister Outlet Pressure (InWC) | | | -36.7 | | -38.6 |
| *Demister DP (InWC) | | | +2.4 | | +2.5 |
| *Flame Arrester Inlet Pressure (InWC) | | | +7.16 | | +7.6 |
| *Flame Arrester Outlet Pressure (InWC) | | | +4.21 | | +4.8 |
| *Flame Arrester DP (InWC) | | | +3.2 | | +2.8 |
| ***Flare*** | | | | | |
| *Visible Emissions (Yes/No, If yes explain) | | | No | | No |
| *Spiralator Position (%Open) | | | 50 | | 50 |
| *Manual Louver 1 Position (%Open) | | | 50 | | 50 |
| *Manual Louver 2 Position (%Open) | | | 50 | | 50 |
| ***Other*** | | | | | |
| Heat Trace OK (Check for Yes) | ☐ | ☐ | ☑ | ☐ | ☑ |
| *Propane Tank Level OK (T1 \| T2 (Check for Yes)) | ☐ ☐ | ☐ ☐ | ☑ ☑ | ☐ ☐ | ☑ ☑ |
| ***Flare 3 - Monitoring*** | | | | | |
| Time (hh:mm) | | | 1324 | | 1023 |
| Technician (Initials) | | | CS | | CS |
| ***Control Panel*** | | | | | |
| *Indicator Lights OK (Check for Yes) | ☐ | ☐ | ☑ | ☐ | ☑ |
| *Heating/Cooling OK (Check for Yes) | ☐ | ☐ | ☑ | ☐ | ☑ |
| ***Control Panel - Digital Recorder*** | | | | | |
| *Remote Recorder On (Check for Yes) | ☐ | ☐ | ☑ | ☐ | ☑ |

# Collection and Control System Monitoring

| Day of Week | Monday | Tuesday | Wednesday | Thursday | Friday |
|---|---|---|---|---|---|
| ***Control Panel - Touchscreen - Analog Data Menu - Process Overview*** | | | | | |
| *Gas Handling Skid Inlet Vacuum (inWC) | | | 40.1 | | 40.2 |
| *Gas Handling Skid Inlet Temperature (F) | | | 63 | | 63 |
| *Panel Temperature (F) | | | 71 | | 90 |
| *Recirculation Valve Position (%Closed) | | | 100 | | 100 |
| *Flare Flame Temperature (F) | | | 1303 | | 1271 |
| *Flame Arrestor Temperature (F) | | | 52 | | 95 |
| ***Control Panel - Touchscreen - Blower Data*** *(Press Back, Blower Menu, Select Current Blower)* | | | | | |
| *Blower Runtime (Blower \| Runtime (Hours)) | | | 302 30.1 | | 302 304.6 |
| *Blower Speed (Blower \| Speed (%Max)) | | | 64 | | 66 |
| *Blower Vibration (Blower \| Vibration (in/Sec)) | | | 0.01 | | 0.01 |
| *Blower Current (Blower \| Current (Amps)) | | | 25.2 | | 30.7 |
| ***Control Panel - Touchscreen - Flare Flow Data*** *(Press Back X2, Flare Flow Data)* | | | | | |
| *Flow Rate (SCFM) | | | 1062 | | 1105 |
| *Total Flow (MMSCF) | | | 38[illegible] | | 386.44 |
| *Flow Pressure (inWC) | | | 4.7 | | 4.4 |
| *Flow Temperature (F) | | | 84 | | 96 |
| *Flow DP (inWC) | | | 2.47 | | 2.91 |
| ***Control Panel - Touchscreen*** *(Press Resettable)* | | | | | |
| *Resettable Total Flow (MMSCF) | | | 353.64 | | 386.44 |
| *Reset Date/Time (mm/dd/yy hh:mm ss) | | | | | |
| ***Control Panel - Touchscreen - Alarm History*** *(Press Main)* | | | | | |
| *Alarm History (Check box if no alarm) | ☐ | ☐ | ☑ | ☐ | ☑ |
| ***Gas Handling Skid*** | | | | | |
| *Demister Inlet Pressure (inWC) | | | -40.4 | | -40.1 |
| *Demister Outlet Pressure (inWC) | | | -41.2 | | -41.7 |
| *Demister DP (inWC) | | | +0.8 | | +1.6 |
| *Flame Arrester Inlet Pressure (inWC) | | | +4.2 | | +5.1 |
| *Flame Arrester Outlet Pressure (inWC) | | | +4.6 | | +4.7 |
| *Flame Arrester DP (inWC) | | | +0.4 | | +0.4 |
| *Fail-Close Valve Air Pressure (psi) | | | 105 | | 105 |
| ***Flare*** | | | | | |
| *Visible Emissions (Yes/No, If yes explain) | | | NO | | NO |
| *Spiralator Position (%Open) | | | 50 | | 50 |
| *Manual Louver 1 Position (%Open) | | | 50 | | 50 |
| *Manual Louver 2 Position (%Open) | | | 50 | | 50 |
| ***Other*** | | | | | |
| *Heat Trace OK (Check for Yes) | ☐ | ☐ | ☑ | ☐ | ☑ |
| *Propane Tank Level OK (T1 \| T2 (Check for Yes)) | ☐ ☐ | ☐ ☐ | ☑ ☑ | ☐ ☐ | ☑ ☑ |
| ***Engine Plant 1 - Monitoring*** | | | | | |
| Time (hh:mm) | | | 1337 | | 1045 |
| Technician (Initials) | | | CS | | CS |
| ***Engine Control Panel*** | | | | | |
| *Power Setpoint (kWh) (Engine #4 \| #3) | | | 705 697 | | 700 692 |
| *Power Setpoint (kWh) (Engine #2 \| #1) | | | 704 694 | | 697 710 |
| ***Control Room - Laptop*** | | | | | |
| *Flow Total (MSCF) | | | 445071.9 | | 448135.4 |
| *Flow Rate (SCFM) | | | 1145.5 | | 1128.5 |
| *Discharge Gas Temperature (F) | | | 81.0 | | 70.0 |
| ***Engine Bay/Control Room Window*** | | | | | |
| *Inlet Gas Pressure (inWC) | | | -40.5 | | -42.8 |
| ***Other*** | | | | | |
| *Visible Emissions (Yes/No, If yes explain) | | | NO | | NO |

***Note * Collect during device operation only***

**Remarks**

# Collection and Control System Monitoring

| Day of Week | Monday | Tuesday | Wednesday | Thursday | Friday |
|---|---|---|---|---|---|
| Date (mm/dd/yy) | | | | 12/02/21 | 12/03/21 |
| **Lowry Header - Monitoring** | | | | | |
| Time (hh:mm) | | | | 1445 | 1319 |
| Technician (Initials) | | | | DS | DS |
| ***Control Panel - Digital Recorder*** | | | | | |
| Flow Rate (SCFM) | | | | 200 | 201 |
| Gas Temperature (F) | | | | 55.0 | 55.0 |
| **Flare 2 - Monitoring** | | | | | |
| Time (hh:mm) | | | | 1450 | 1329 |
| Technician (Initials) | | | | DS | DS |
| ***Control Panel*** | | | | | |
| *Indicator Lights OK (Check for Yes) | ☐ | ☐ | ☐ | ✓ | ✓ |
| Heating/Cooling OK (Check for Yes) | ☐ | ☐ | ☐ | ✓ | ✓ |
| ***Control Panel - Digital Recorder*** | | | | | |
| Local Recorder On (Check for Yes) | ☐ | ☐ | ☐ | ✓ | ✓ |
| ***Control Panel - Touchscreen - Process Overview*** | | | | | |
| *Gas Handling Skid Inlet Pressure (inWC) | | | | 31.7 | 31.9 |
| *Flare DP (inWC) | | | | 5.22 | 5.24 |
| *Flare Flame Temperature (F) | | | | 1250 | 1203 |
| ***Control Panel - Touchscreen*** *(Press Next)* | | | | | |
| Panel Temperature (F) | | | | 102 | 79 |
| *Gas Handling Skid Inlet Temperature (F) | | | | 56 | 48 |
| *Recirculation Valve Position (%Closed) | | | | 70 | 70 |
| ***Control Panel - Touchscreen - Flare Flow Data*** *(Press Back 2x, Flare Flow Data)* | | | | | |
| *Flow Rate (SCFM) | | | | 507 | 499 |
| *Total Flow (MMSCF) | | | | 1037.59 | 1038.27 |
| *Flow Pressure (inWC) | | | | 6.4 | 6.4 |
| *Flow Temperature (F) | | | | 99 | 105 |
| ***Control Panel - Touchscreen*** *(Press Resettable Flow History, Analog Data Menu, Blower Data)* | | | | | |
| *Resettable Total Flow (MMSCF) | | | | 693.92 | 694.20 |
| *Reset Date/Time (mm/dd/yy hh.mm.ss) | | | | | |
| ***Control Panel - Touchscreen - Blower Data*** *(Press Main)* | | | | | |
| *Blower 301 Runtime (Hours) | | | | 38854 | 38876 |
| *Blower 301 Vibration (in/Sec) | | | | 0.18 | 0.21 |
| *Blower 301 Speed (%Max) | | | | 82 | 81 |
| *Blower 301 Inlet Bearing Temp (F) | | | | 58 | 59 |
| *Blower 301 Outlet Bearing Temp (F) | | | | 116 | 108 |
| ***Control Panel - Blower Keypad*** | | | | | |
| *Blower 301 Current (Amps) | | | | 12.2 | 12.2 |
| ***Gas Handling Skid*** | | | | | |
| *Demister Inlet Pressure (inWC) | | | | -32.2 | -32.5 |
| *Demister Outlet Pressure (inWC) | | | | -35.0 | -34.3 |
| *Demister DP (inWC) | | | | +2.8 | +1.8 |
| *Flame Arrester Inlet Pressure (inWC) | | | | +7.6 | +7.7 |
| *Flame Arrester Outlet Pressure (inWC) | | | | +4.7 | +4.7 |
| *Flame Arrester DP (inWC) | | | | +2.9 | +3.0 |
| ***Flare*** | | | | | |
| *Visible Emissions (Yes/No, If yes explain) | | | | No | No |
| *Spiralator Position (%Open) | | | | 50 | 50 |
| *Manual Louver 1 Position (%Open) | | | | 50 | 50 |
| *Manual Louver 2 Position (%Open) | | | | 50 | 50 |
| ***Other*** | | | | | |
| Heat Trace OK (Check for Yes) | ☐ | ☐ | ☐ | ✓ | ✓ |
| *Propane Tank Level OK (T1 \| T2 (Check for Yes)) | ☐ ☐ | ☐ ☐ | ☐ ☐ | ✓ ✓ | ✓ ✓ |
| **Flare 3 - Monitoring** | | | | | |
| Time (hh:mm) | | | | 1508 | 1339 |
| Technician (Initials) | | | | DS | DS |
| ***Control Panel*** | | | | | |
| *Indicator Lights OK (Check for Yes) | ☐ | ■ | ☐ | ✓ | ✓ |
| *Heating/Cooling OK (Check for Yes) | ☐ | ☐ | ☐ | ✓ | ✓ |
| ***Control Panel - Digital Recorder*** | | | | | |
| *Remote Recorder On (Check for Yes) | ☐ | ☐ | ☐ | ✓ | ✓ |

# Collection and Control System Monitoring

| Day of Week | Monday | Tuesday | Wednesday | Thursday | Friday |
|---|---|---|---|---|---|
| ***Control Panel - Touchscreen - Analog Data Menu - Process Overview*** | | | | | |
| *Gas Handling Skid Inlet Vacuum (inWC) | | | | 40.3 | 40.2 |
| *Gas Handling Skid Inlet Temperature (F) | | | | 65 | 63 |
| *Panel Temperature (F) | | | | 110 | 93 |
| *Recirculation Valve Position (%Closed) | | | | 100 | 100 |
| *Flare Flame Temperature (F) | | | | 1294 | 1073 |
| *Flame Arrestor Temperature (F) | | | | 98 | 82 |
| ***Control Panel - Touchscreen - Blower Data*** *(Press Back, Blower Menu, Select Current Blower)* | | | | | |
| *Blower Runtime (Blower \| Runtime (Hours)) | | | | 302 3195 | 301 2946 |
| *Blower Speed (Blower \| Speed (%Max)) | | | | 68 | 67 |
| *Blower Vibration (Blower \| Vibration (in/Sec)) | | | | 0.02 | 0.02 |
| *Blower Current (Blower \| Current (Amps)) | | | | 32.6 | 33.1 |
| ***Control Panel - Touchscreen - Flare Flow Data*** *(Press Back X2, Flare Flow Data)* | | | | | |
| *Flow Rate (SCFM) | | | | 1171 | 1197 |
| *Total Flow (MMSCF) | | | | 396.85 | 398.33 |
| *Flow Pressure (inWC) | | | | 5.3 | 5.2 |
| *Flow Temperature (F) | | | | 99 | 82 |
| *Flow DP (inWC) | | | | 3.48 | 3.34 |
| ***Control Panel - Touchscreen*** *(Press Resettable)* | | | | | |
| *Resettable Total Flow (MMSCF) | | | | 396.85 | 398.33 |
| *Reset Date/Time (mm/dd/yy hh:mm ss) | | | | | |
| ***Control Panel - Touchscreen - Alarm History*** *(Press Main)* | | | | | |
| *Alarm History (Check box if no alarm) | ☐ | ☐ | ☐ | ✓ | ✓ |
| ***Gas Handling Skid*** | | | | | |
| *Demister Inlet Pressure (inWC) | | | | -39.7 | -39.3 |
| *Demister Outlet Pressure (inWC) | | | | -40.0 | -41.8 |
| *Demister DP (inWC) | | | | +0.3 | +2.5 |
| *Flame Arrester Inlet Pressure (inWC) | | | | +6.4 | +6.4 |
| *Flame Arrester Outlet Pressure (inWC) | | | | +5.7 | +5.4 |
| *Flame Arrester DP (inWC) | | | | +0.9 | +1.0 |
| *Fail-Close Valve Air Pressure (psi) | | | | 105 | 105 |
| ***Flare*** | | | | | |
| *Visible Emissions (Yes/No, If yes explain) | | | | NO | NO |
| *Spiralator Position (%Open) | | | | 50 | 50 |
| *Manual Louver 1 Position (%Open) | | | | 50 | 50 |
| *Manual Louver 2 Position (%Open) | | | | 50 | 50 |
| ***Other*** | | | | | |
| *Heat Trace OK (Check for Yes) | ☐ | ☐ | ☐ | ✓ | ✓ |
| *Propane Tank Level OK (T1 \| T2 (Check for Yes)) | ☐ ☐ | ☐ ☐ | ☐ ☐ | ✓ ✓ | ✓ ✓ |
| ***Engine Plant 1 - Monitoring*** | | | | | |
| Time (hh mm) | | | | 1519 | 1349 |
| Technician (Initials) | | | | CS | CS |
| ***Engine Control Panel*** | | | | | |
| *Power Setpoint (kWh) (Engine #4 \| #3) | | | | 704 700 | 693 694 |
| *Power Setpoint (kWh) (Engine #2 \| #1) | | | | 700 687 | 680 695 |
| ***Control Room - Laptop*** | | | | | |
| *Flow Total (MSCF) | | | | 457119.5 | 458557.9 |
| *Flow Rate (SCFM) | | | | 1036.5 | 1031.1 |
| *Discharge Gas Temperature (F) | | | | 71.0 | 70.0 |
| ***Engine Bay/Control Room Window*** | | | | | |
| *Inlet Gas Pressure (inWC) | | | | -44.5 | -42.7 |
| ***Other*** | | | | | |
| *Visible Emissions (Yes/No, If yes explain) | | | | NO | NO |

***Note * Collect during device operation only***

**Remarks**

# Collection and Control System Monitoring

| Day of Week | Monday | Tuesday | Wednesday | Thursday | Friday |
|---|---|---|---|---|---|
| Date (mm/dd/yy) | | 12/07/21 | | | |
| **Lowry Header - Monitoring** | | | | | |
| Time (hh:mm) | | 1249 | | | |
| Technician (Initials) | | CS | | | |
| ***Control Panel - Digital Recorder*** | | | | | |
| Flow Rate (SCFM) | | 148 | | | |
| Gas Temperature (F) | | 53.0 | | | |
| **Flare 2 - Monitoring** | | | | | |
| Time (hh:mm) | | 1253 | | | |
| Technician (Initials) | | CS | | | |
| ***Control Panel*** | | | | | |
| *Indicator Lights OK (Check for Yes) | ☐ | ☑ | ☐ | ☐ | ☐ |
| Heating/Cooling OK (Check for Yes) | ☐ | ☑ | ☐ | ☐ | ☐ |
| ***Control Panel - Digital Recorder*** | | | | | |
| Local Recorder On (Check for Yes) | ☐ | ☑ | ☐ | ☐ | ☐ |
| ***Control Panel - Touchscreen - Process Overview*** | | | | | |
| *Gas Handling Skid Inlet Pressure (InWC) | | 29.1 | | | |
| *Flare DP (InWC) | | 5.27 | | | |
| *Flare Flame Temperature (F) | | 1121 | | | |
| ***Control Panel - Touchscreen*** *(Press Next)* | | | | | |
| Panel Temperature (F) | | 78 | | | |
| *Gas Handling Skid Inlet Temperature (F) | | 46 | | | |
| *Recirculation Valve Position (%Closed) | | 70 | | | |
| ***Control Panel - Touchscreen - Flare Flow Data*** *(Press Back 2x, Flare Flow Data)* | | | | | |
| *Flow Rate (SCFM) | | 501 | | | |
| *Total Flow (MMSCF) | | 1041.14 | | | |
| *Flow Pressure (InWC) | | 6.4 | | | |
| *Flow Temperature (F) | | 49 | | | |
| ***Control Panel - Touchscreen*** *(Press Resettable Flow History, Analog Data Menu, Blower Data)* | | | | | |
| *Resettable Total Flow (MMSCF) | | 697.47 | | | |
| *Reset Date/Time (mm/dd/yy hh.mm.ss) | | | | | |
| ***Control Panel - Touchscreen - Blower Data*** *(Press Main)* | | | | | |
| *Blower 301 Runtime (Hours) | | 38972 | | | |
| *Blower 301 Vibration (In/Sec) | | 0.19 | | | |
| *Blower 301 Speed (%Max) | | 79 | | | |
| *Blower 301 Inlet Bearing Temp (F) | | 53 | | | |
| *Blower 301 Outlet Bearing Temp (F) | | 104 | | | |
| ***Control Panel - Blower Keypad*** | | | | | |
| *Blower 301 Current (Amps) | | 11.7 | | | |
| ***Gas Handling Skid*** | | | | | |
| *Demister Inlet Pressure (InWC) | | -29.6 | | | |
| *Demister Outlet Pressure (InWC) | | -33.0 | | | |
| *Demister DP (InWC) | | +3.4 | | | |
| *Flame Arrester Inlet Pressure (InWC) | | +7.4 | | | |
| *Flame Arrester Outlet Pressure (InWC) | | +4.5 | | | |
| *Flame Arrester DP (InWC) | | +2.9 | | | |
| ***Flare*** | | | | | |
| *Visible Emissions (Yes/No, If yes explain) | | NO | | | |
| *Spiralator Position (%Open) | | 50 | | | |
| *Manual Louver 1 Position (%Open) | | 50 | | | |
| *Manual Louver 2 Position (%Open) | | 50 | | | |
| ***Other*** | | | | | |
| Heat Trace OK (Check for Yes) | ☐ | ☑ | ☐ | ☐ | ☐ |
| *Propane Tank Level OK (T1 \| T2 (Check for Yes)) | ☐ ☐ | ☑ ☑ | ☐ ☐ | ☐ ☐ | ☐ ☐ |
| **Flare 3 - Monitoring** | | | | | |
| Time (hh:mm) | | 1305 | | | |
| Technician (Initials) | | CS | | | |
| ***Control Panel*** | | | | | |
| *Indicator Lights OK (Check for Yes) | ☐ | ☑ | ☐ | ☐ | ☐ |
| *Heating/Cooling OK (Check for Yes) | ☐ | ☑ | ☐ | ☐ | ☐ |
| ***Control Panel - Digital Recorder*** | | | | | |
| *Remote Recorder On (Check for Yes) | ☐ | ☑ | ☐ | ☐ | ☐ |

# Collection and Control System Monitoring

| Day of Week | Monday | Tuesday | Wednesday | Thursday | Friday |
|---|---|---|---|---|---|
| ***Control Panel - Touchscreen - Analog Data Menu - Process Overview*** | | | | | |
| *Gas Handling Skid Inlet Vacuum (inWC) | | 40.2 | | | |
| *Gas Handling Skid Inlet Temperature (F) | | 61 | | | |
| *Panel Temperature (F) | | 88 | | | |
| *Recirculation Valve Position (%Closed) | | 100 | | | |
| *Flare Flame Temperature (F) | | 1267 | | | |
| *Flame Arrestor Temperature (F) | | 809 | | | |
| ***Control Panel - Touchscreen - Blower Data*** *(Press Back, Blower Menu, Select Current Blower)* | | | | | |
| *Blower Runtime (Blower \| Runtime (Hours)) | | 301 2641 | | | |
| *Blower Speed (Blower \| Speed (%Max)) | | 63 | | | |
| *Blower Vibration (Blower \| Vibration (in/Sec)) | | 0.01 | | | |
| *Blower Current (Blower \| Current (Amps)) | | 27.9 | | | |
| ***Control Panel - Touchscreen - Flare Flow Data*** *(Press Back X2, Flare Flow Data)* | | | | | |
| *Flow Rate (SCFM) | | 910 | | | |
| *Total Flow (MMSCF) | | 409.78 | | | |
| *Flow Pressure (inWC) | | 2.9 | | | |
| *Flow Temperature (F) | | 91 | | | |
| *Flow DP (inWC) | | 2.04 | | | |
| ***Control Panel - Touchscreen*** *(Press Resettable)* | | | | | |
| *Resettable Total Flow (MMSCF) | | 409.78 | | | |
| *Reset Date/Time (mm/dd/yy hh:mm:ss) | | | | | |
| ***Control Panel - Touchscreen - Alarm History*** *(Press Main)* | | | | | |
| *Alarm History (Check box if no alarm) | ☐ | ☑ | ☐ | ☐ | ☐ |
| ***Gas Handling Skid*** | | | | | |
| *Demister Inlet Pressure (inWC) | | -39.9 | | | |
| *Demister Outlet Pressure (inWC) | | -40.8 | | | |
| *Demister DP (inWC) | | +0.9 | | | |
| *Flame Arrester Inlet Pressure (inWC) | | +3.4 | | | |
| *Flame Arrester Outlet Pressure (inWC) | | +3.1 | | | |
| *Flame Arrester DP (inWC) | | +0.5 | | | |
| *Fail-Close Valve Air Pressure (psi) | | 105 | | | |
| ***Flare*** | | | | | |
| *Visible Emissions (Yes/No, If yes explain) | | NO | | | |
| *Spiralator Position (%Open) | | 50 | | | |
| *Manual Louver 1 Position (%Open) | | 50 | | | |
| *Manual Louver 2 Position (%Open) | | 50 | | | |
| ***Other*** | | | | | |
| *Heat Trace OK (Check for Yes) | ☐ | ☑ | ☐ | ☐ | ☐ |
| *Propane Tank Level OK (T1 \| T2 (Check for Yes)) | ☐ ☐ | ☑ ☑ | ☐ ☐ | ☐ ☐ | ☐ ☐ |
| ***Engine Plant 1 - Monitoring*** | | | | | |
| Time (hh mm) | | 1367 | | | |
| Technician (Initials) | | CB | | | |
| ***Engine Control Panel*** | | | | | |
| *Power Setpoint (kWh) (Engine #4 \| #3) | | 711 694 | | | |
| *Power Setpoint (kWh) (Engine #2 \| #1) | | 716 710 | | | |
| ***Control Room - Laptop*** | | | | | |
| *Flow Total (MSCF) | | 4644506.0 | | | |
| *Flow Rate (SCFM) | | 1053.3 | | | |
| *Discharge Gas Temperature (F) | | 709.0 | | | |
| ***Engine Bay/Control Room Window*** | | | | | |
| *Inlet Gas Pressure (inWC) | | -41.0 | | | |
| ***Other*** | | | | | |
| *Visible Emissions (Yes/No, If yes explain) | | NO | | | |

***Note * Collect during device operation only***

**Remarks**

# Collection and Control System Monitoring

| Day of Week | Monday | Tuesday | Wednesday | Thursday | Friday |
|---|---|---|---|---|---|
| Date (mm/dd/yy) | | | | 12/16/21 | 12/17/21 |
| **Lowry Header - Monitoring** | | | | | |
| Time (hh:mm) | | | | 1434 | 1453 |
| Technician (Initials) | | | | CS | CS |
| ***Control Panel - Digital Recorder*** | | | | | |
| Flow Rate (SCFM) | | | | 191 | 186 |
| Gas Temperature (F) | | | | 53.0 | 53.0 |
| **Flare 2 - Monitoring** | | | | | |
| Time (hh:mm) | | | | 1429 | 1437 |
| Technician (Initials) | | | | CS | CS |
| ***Control Panel*** | | | | | |
| *Indicator Lights OK (Check for Yes) | ☐ | ☐ | ☐ | ✓ | ✓ |
| Heating/Cooling OK (Check for Yes) | ☐ | ☐ | ☐ | ✓ | ✓ |
| ***Control Panel - Digital Recorder*** | | | | | |
| Local Recorder On (Check for Yes) | ☐ | ☐ | ☐ | ✓ | ✓ |
| ***Control Panel - Touchscreen - Process Overview*** | | | | | |
| *Gas Handling Skid Inlet Pressure (inWC) | | | | 23.6 | 22.8 |
| *Flare DP (inWC) | | | | 5.18 | 5.12 |
| *Flare Flame Temperature (F) | | | | 1073 | 1114 |
| ***Control Panel - Touchscreen*** *(Press Next)* | | | | | |
| Panel Temperature (F) | | | | 85 | 71 |
| *Gas Handling Skid Inlet Temperature (F) | | | | 41 | 47 |
| *Recirculation Valve Position (%Closed) | | | | 70 | 70 |
| ***Control Panel - Touchscreen - Flare Flow Data*** *(Press Back 2x, Flare Flow Data)* | | | | | |
| *Flow Rate (SCFM) | | | | 499 | 501 |
| *Total Flow (MMSCF) | | | | 1047.7 | 1048.4 |
| *Flow Pressure (inWC) | | | | 6.6 | 6.2 |
| *Flow Temperature (F) | | | | 88 | 55 |
| ***Control Panel - Touchscreen*** *(Press Resettable Flow History, Analog Data Menu, Blower Data)* | | | | | |
| *Resettable Total Flow (MMSCF) | | | | 704.0 | 704.7 |
| *Reset Date/Time (mm/dd/yy hh:mm:ss) | | | | | |
| ***Control Panel - Touchscreen - Blower Data*** *(Press Main)* | | | | | |
| *Blower 301 Runtime (Hours) | | | | 39189 | 39213 |
| *Blower 301 Vibration (In/Sec) | | | | 0.18 | 0.33 |
| *Blower 301 Speed (%Max) | | | | 74 | 73 |
| *Blower 301 Inlet Bearing Temp (F) | | | | 92 | 42 |
| *Blower 301 Outlet Bearing Temp (F) | | | | 95 | 95 |
| ***Control Panel - Blower Keypad*** | | | | | |
| *Blower 301 Current (Amps) | | | | 11.1 | 11.1 |
| ***Gas Handling Skid*** | | | | | |
| *Demister Inlet Pressure (inWC) | | | | -24.2 | -24.0 |
| *Demister Outlet Pressure (inWC) | | | | -26.5 | -26.1 |
| *Demister DP (inWC) | | | | +2.3 | +2.1 |
| *Flame Arrester Inlet Pressure (inWC) | | | | +7.7 | +7.5 |
| *Flame Arrester Outlet Pressure (inWC) | | | | +4.4 | +4.4 |
| *Flame Arrester DP (inWC) | | | | +3.3 | +2.9 |
| ***Flare*** | | | | | |
| *Visible Emissions (Yes/No, If yes explain) | | | | NO | NO |
| *Spiralator Position (%Open) | | | | 50 | 50 |
| *Manual Louver 1 Position (%Open) | | | | 50 | 50 |
| *Manual Louver 2 Position (%Open) | | | | 50 | 50 |
| ***Other*** | | | | | |
| Heat Trace OK (Check for Yes) | ☐ | ☐ | ☐ | ✓ | ✓ |
| *Propane Tank Level OK (T1 \| T2 (Check for Yes)) | ☐ ☐ | ☐ ☐ | ☐ ☐ | ✓ ✓ | ✓ ✓ |
| **Flare 3 - Monitoring** | | | | | |
| Time (hh:mm) | | | | 1441 | 1445 |
| Technician (Initials) | | | | CS | CS |
| ***Control Panel*** | | | | | |
| *Indicator Lights OK (Check for Yes) | ☐ | ☐ | ☐ | ✓ | ✓ |
| *Heating/Cooling OK (Check for Yes) | ☐ | ☐ | ☐ | ✓ | ✓ |
| ***Control Panel - Digital Recorder*** | | | | | |
| *Remote Recorder On (Check for Yes) | ☐ | ☐ | ☐ | ✓ | ✓ |

# Collection and Control System Monitoring

| Day of Week | Monday | Tuesday | Wednesday | Thursday | Friday |
|---|---|---|---|---|---|
| ***Control Panel - Touchscreen - Analog Data Menu - Process Overview*** | | | | | |
| *Gas Handling Skid Inlet Vacuum (inWC) | | | | 40.4 | 40.3 |
| *Gas Handling Skid Inlet Temperature (F) | | | | 54 | 61 |
| *Panel Temperature (F) | | | | 87 | 85 |
| *Recirculation Valve Position (%Closed) | | | | 100 | 100 |
| *Flare Flame Temperature (F) | | | | 1327 | 1355 |
| *Flame Arrestor Temperature (F) | | | | 84 | 80 |
| ***Control Panel - Touchscreen - Blower Data*** *(Press Back, Blower Menu, Select Current Blower)* | | | | | |
| *Blower Runtime (Blower \| Runtime (Hours)) | | | | 301 2859 | 301 2883 |
| *Blower Speed (Blower \| Speed (%Max)) | | | | 62 | 66 |
| *Blower Vibration (Blower \| Vibration (in/Sec)) | | | | 0.01 | 0.01 |
| *Blower Current (Blower \| Current (Amps)) | | | | 27.1 | 31.2 |
| ***Control Panel - Touchscreen - Flare Flow Data*** *(Press Back X2, Flare Flow Data)* | | | | | |
| *Flow Rate (SCFM) | | | | 878 | 1058 |
| *Total Flow (MMSCF) | | | | 417.52 | 418.05 |
| *Flow Pressure (inWC) | | | | 2.4 | 5.3 |
| *Flow Temperature (F) | | | | 84 | 84 |
| *Flow DP (inWC) | | | | 1.68 | 2.14 |
| ***Control Panel - Touchscreen*** *(Press Resettable)* | | | | | |
| *Resettable Total Flow (MMSCF) | | | | 417.52 | 418.05 |
| *Reset Date/Time (mm/dd/yy hh:mm:ss) | | | | | |
| ***Control Panel - Touchscreen - Alarm History*** *(Press Main)* | | | | | |
| *Alarm History (Check box if no alarm) | ☐ | ☐ | ☐ | ✓ | ✓ |
| ***Gas Handling Skid*** | | | | | |
| *Demister Inlet Pressure (inWC) | | | | -40.0 | -40.5 |
| *Demister Outlet Pressure (inWC) | | | | -40.7 | -41.5 |
| *Demister DP (inWC) | | | | +0.7 | +1.0 |
| *Flame Arrester Inlet Pressure (inWC) | | | | +3.2 | +5.5 |
| *Flame Arrester Outlet Pressure (inWC) | | | | +2.9 | +5.3 |
| *Flame Arrester DP (inWC) | | | | +0.3 | +0.2 |
| *Fail-Close Valve Air Pressure (psi) | | | | 105 | 105 |
| ***Flare*** | | | | | |
| *Visible Emissions (Yes/No, If yes explain) | | | | No | No |
| *Spiralator Position (%Open) | | | | 50 | 50 |
| *Manual Louver 1 Position (%Open) | | | | 50 | 50 |
| *Manual Louver 2 Position (%Open) | | | | 50 | 50 |
| ***Other*** | | | | | |
| *Heat Trace OK (Check for Yes) | ☐ | ☐ | ☐ | ✓ | ✓ |
| *Propane Tank Level OK (T1 \| T2 (Check for Yes)) | ☐ ☐ | ☐ ☐ | ☐ ☐ | ✓ ✓ | ✓ ✓ |
| ***Engine Plant 1 - Monitoring*** | | | | | |
| Time (hh:mm) | | | | 1450 | 1457 |
| Technician (Initials) | | | | CS | CS |
| ***Engine Control Panel*** | | | | | |
| *Power Setpoint (kWh) (Engine #4 \| #3) | | | | 700 699 | 698 702 |
| *Power Setpoint (kWh) (Engine #2 \| #1) | | | | 707 709 | — 688 |
| ***Control Room - Laptop*** | | | | | |
| *Flow Total (MSCF) | | | | 472413.7 | 472975.2 |
| *Flow Rate (SCFM) | | | | 1069.2 | 808.8 |
| *Discharge Gas Temperature (F) | | | | 100.0 | 62.0 |
| ***Engine Bay/Control Room Window*** | | | | | |
| *Inlet Gas Pressure (inWC) | | | | -43.5 | -42.5 |
| ***Other*** | | | | | |
| *Visible Emissions (Yes/No, If yes explain) | | | | NO | NO |
| ***Note * Collect during device operation only*** | | | | | |

**Remarks**

12/17 - Engine #2 Down

# Collection and Control System Monitoring

| Day of Week | Monday | Tuesday | Wednesday | Thursday | Friday |
|---|---|---|---|---|---|
| Date (mm/dd/yy) | | | 12/29/21 | 12/30/21 | |
| **Lowry Header - Monitoring** | | | | | |
| Time (hh mm) | | | 1506 | 1442 | |
| Technician (initials) | | | CS | CS | |
| ***Control Panel - Digital Recorder*** | | | | | |
| Flow Rate (SCFM) | | | 193 | 126 | |
| Gas Temperature (F) | | | 51.0 | 51.0 | |
| **Flare 2 - Monitoring** | | | | | |
| Time (hh:mm) | | | 1512 | 1426 | |
| Technician (initials) | | | CS | CS | |
| ***Control Panel*** | | | | | |
| *Indicator Lights OK (Check for Yes) | ☐ | ☐ | ✓ | ✓ | ☐ |
| Heating/Cooling OK (Check for Yes) | ☐ | ☐ | ✓ | ✓ | ☐ |
| ***Control Panel - Digital Recorder*** | | | | | |
| Local Recorder On (Check for Yes) | ☐ | ☐ | ✓ | ✓ | ☐ |
| ***Control Panel - Touchscreen - Process Overview*** | | | | | |
| *Gas Handling Skid Inlet Pressure (inWC) | | | 19.4 | 17.2 | |
| *Flare DP (inWC) | | | 5.03 | 5.04 | |
| *Flare Flame Temperature (F) | | | 1270 | 1112 | |
| ***Control Panel - Touchscreen*** *(Press Next)* | | | | | |
| Panel Temperature (F) | | | 76 | 72 | |
| *Gas Handling Skid Inlet Temperature (F) | | | 43 | 42 | |
| *Recirculation Valve Position (%Closed) | | | 70 | 70 | |
| ***Control Panel - Touchscreen - Flare Flow Data*** *(Press Back 2x, Flare Flow Data)* | | | | | |
| *Flow Rate (SCFM) | | | 500 | 503 | |
| *Total Flow (MMSCF) | | | 1057.07 | 1057.54 | |
| *Flow Pressure (inWC) | | | 6.1 | 6.4 | |
| *Flow Temperature (F) | | | 79 | 80 | |
| ***Control Panel - Touchscreen*** *(Press Resettable Flow History, Analog Data Menu, Blower Data)* | | | | | |
| *Resettable Total Flow (MMSCF) | | | 713.4 | 713.9 | |
| *Reset Date/Time (mm/dd/yy hh.mm.ss) | | | | | |
| ***Control Panel - Touchscreen - Blower Data*** *(Press Main)* | | | | | |
| *Blower 301 Runtime (Hours) | | | 39502 | 39520 | |
| *Blower 301 Vibration (in/Sec) | | | 0.21 | 0.21 | |
| *Blower 301 Speed (%Max) | | | 76 | 81 | |
| *Blower 301 Inlet Bearing Temp (F) | | | 32 | 81 | |
| *Blower 301 Outlet Bearing Temp (F) | | | 51 | 80 | |
| ***Control Panel - Blower Keypad*** | | | | | |
| *Blower 301 Current (Amps) | | | 10.3 | 10.3 | |
| ***Gas Handling Skid*** | | | | | |
| *Demister Inlet Pressure (inWC) | | | -19.9 | -16.8 | |
| *Demister Outlet Pressure (inWC) | | | -22.3 | -18.9 | |
| *Demister DP (inWC) | | | +2.4 | +2.1 | |
| *Flame Arrester Inlet Pressure (inWC) | | | +7.2 | +7.4 | |
| *Flame Arrester Outlet Pressure (inWC) | | | +4.3 | +4.6 | |
| *Flame Arrester DP (inWC) | | | +2.9 | +2.8 | |
| ***Flare*** | | | | | |
| *Visible Emissions (Yes/No, If yes explain) | | | No | No | |
| *Spiralator Position (%Open) | | | 50 | 50 | |
| *Manual Louver 1 Position (%Open) | | | 50 | 50 | |
| *Manual Louver 2 Position (%Open) | | | 50 | 50 | |
| ***Other*** | | | | | |
| Heat Trace OK (Check for Yes) | ☐ | ☐ | ✓ | ✓ | ☐ |
| *Propane Tank Level OK (T1 \| T2 (Check for Yes)) | ☐ ☐ | ☐ ☐ | ✓ ✓ | ✓ ✓ | ☐ ☐ |
| **Flare 3 - Monitoring** | | | | | |
| Time (hh:mm) | | | 1523 | 1459 | |
| Technician (initials) | | | CS | CS | |
| ***Control Panel*** | | | | | |
| *Indicator Lights OK (Check for Yes) | ☐ | ☐ | ✓ | ✓ | ☐ |
| *Heating/Cooling OK (Check for Yes) | ☐ | ☐ | ✓ | ✓ | ☐ |
| ***Control Panel - Digital Recorder*** | | | | | |
| *Remote Recorder On (Check for Yes) | ☐ | ☐ | ✓ | ✓ | ☐ |

# Collection and Control System Monitoring

| Day of Week | Monday | Tuesday | Wednesday | Thursday | Friday |
|---|---|---|---|---|---|
| ***Control Panel - Touchscreen - Analog Data Menu - Process Overview*** | | | | | |
| *Gas Handling Skid Inlet Vacuum (inWC) | | | 40.0 | 39.1 | |
| *Gas Handling Skid Inlet Temperature (F) | | | 54 | 57 | |
| *Panel Temperature (F) | | | 69 | 75 | |
| *Recirculation Valve Position (%Closed) | | | 100 | 100 | |
| *Flare Flame Temperature (F) | | | 1159 | 1400 | |
| *Flame Arrestor Temperature (F) | | | 75 | 82 | |
| ***Control Panel - Touchscreen - Blower Data*** *(Press Back, Blower Menu, Select Current Blower)* | | | | | |
| *Blower Runtime (Blower 1 Runtime (Hours)) | | | 301 3171 | 501 3194 | |
| *Blower Speed (Blower 1 Speed (%Max)) | | | 64 | 64 | |
| *Blower Vibration (Blower 1 Vibration (In/Sec)) | | | 0.01 | 0.01 | |
| *Blower Current (Blower 1 Current (Amps)) | | | 29.4 | 28.3 | |
| ***Control Panel - Touchscreen - Flare Flow Data*** *(Press Back X2, Flare Flow Data)* | | | | | |
| *Flow Rate (SCFM) | | | 1036 | 434 | |
| *Total Flow (MMSCF) | | | 435.81 | 437.24 | |
| *Flow Pressure (inWC) | | | 3.8 | 4.2 | |
| *Flow Temperature (F) | | | 79 | 86 | |
| *Flow DP (inWC) | | | 2.73 | 2.14 | |
| ***Control Panel - Touchscreen*** *(Press Resettable)* | | | | | |
| *Resettable Total Flow (MMSCF) | | | 435.81 | 437.24 | |
| *Reset Date/Time (mm/dd/yy hh:mm ss) | | | | | |
| ***Control Panel - Touchscreen - Alarm History*** *(Press Main)* | | | | | |
| *Alarm History (Check box if no alarm) | ☐ | ☐ | ☑ | ☑ | ☐ |
| ***Gas Handling Skid*** | | | | | |
| *Demister Inlet Pressure (inWC) | | | -40.2 | -40.4 | |
| *Demister Outlet Pressure (inWC) | | | -41.8 | -41.3 | |
| *Demister DP (inWC) | | | +1.6 | +0.9 | |
| *Flame Arrester Inlet Pressure (inWC) | | | +4.6 | +4.2 | |
| *Flame Arrester Outlet Pressure (inWC) | | | +3.9 | +3.6 | |
| *Flame Arrester DP (inWC) | | | +0.7 | +0.6 | |
| *Fail-Close Valve Air Pressure (psi) | | | 105 | 105 | |
| ***Flare*** | | | | | |
| *Visible Emissions (Yes/No, If yes explain) | | | No | No | |
| *Spiralator Position (%Open) | | | 50 | 50 | |
| *Manual Louver 1 Position (%Open) | | | 50 | 50 | |
| *Manual Louver 2 Position (%Open) | | | 50 | 50 | |
| ***Other*** | | | | | |
| *Heat Trace OK (Check for Yes) | ☐ | ☐ | ☑ | ☑ | ☐ |
| *Propane Tank Level OK (T1 \| T2 (Check for Yes)) | ☐ ☐ | ☐ ☐ | ☑ ☑ | ☑ ☑ | ☐ ☐ |
| ***Engine Plant 1 - Monitoring*** | | | | | |
| Time (hh mm) | | | 1534 | 1510 | |
| Technician (Initials) | | | CS | CS | |
| ***Engine Control Panel*** | | | | | |
| *Power Setpoint (kWh) (Engine #4 \| #3) | | | 707 707 | 689 699 | |
| *Power Setpoint (kWh) (Engine #2 \| #1) | | | 704 | 689 | |
| ***Control Room - Laptop*** | | | | | |
| *Flow Total (MSCF) | | | 4944825 | 4955648.6 | |
| *Flow Rate (SCFM) | | | 790.8 | 832.0 | |
| *Discharge Gas Temperature (F) | | | 63.0 | 70.0 | |
| ***Engine Bay/Control Room Window*** | | | | | |
| *Inlet Gas Pressure (inWC) | | | -41.6 | -38.5 | |
| ***Other*** | | | | | |
| *Visible Emissions (Yes/No, If yes explain) | | | NO | NO | |

***Note * Collect during device operation only***

**Remarks**

12/29 - Engine #1 Down
12/30 - Engine #1 Down

# APPENDIX D-3

# LANDFILL GAS MONITORING PROBES

# (METHANE)

**APPENDIX D-3**
**LFG GAS PROBE RESULTS (METHANE)**
**JULY THROUGH DECEMBER 2021 OPERATIONS AND MAINTENANCE STATUS REPORT**
**LOWRY LANDFILL SUPERFUND SITE**

| Date | MP-1 Pressure (in. of $H_2O$)[a/] | MP-1 Methane (%)[b/] | MP-2 Pressure (in. of $H_2O$) | MP-2 Methane (%) | MP-3 Pressure (in. of $H_2O$) | MP-3 Methane (%) | MP-4 Pressure (in. of $H_2O$) | MP-4 Methane (%) | MP-5 Pressure (in. of $H_2O$) | MP-5 Methane (%) | MP-6B Pressure (in. of $H_2O$) | MP-6B Methane (%) | MP-7 Pressure (in. of $H_2O$) | MP-7 Methane (%) | MP-8 Pressure (in. of $H_2O$) | MP-8 Methane (%) | MP-8BH[c/] Pressure (in. of $H_2O$) | MP-8BH Methane (%) |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 8/23/2021 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | NA[d/] | NA |
| 11/17/2021 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | NA | NA |
| | | | | | | | | | | | | | | | | | | |
| | MP-9 Pressure (in. of $H_2O$) | MP-9 Methane (%) | MP-10 Pressure (in. of $H_2O$) | MP-10 Methane (%) | MP-11 Pressure (in. of $H_2O$) | MP-11 Methane (%) | MP-12 Pressure (in. of $H_2O$) | MP-12 Methane (%) | MP-13 Pressure (in. of $H_2O$) | MP-13 Methane (%) | MP-14 Pressure (in. of $H_2O$) | MP-14 Methane (%) | MP-15 Pressure (in. of $H_2O$) | MP-15 Methane (%) | MP-16 Pressure (in. of $H_2O$) | MP-16 Methane (%) | MP-17 Pressure (in. of $H_2O$) | MP-17 Methane (%) |
| 8/23/2021 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 11/17/2021 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | |
| | MP-18 Pressure (in. of $H_2O$) | MP-18 Methane (%) | MP-19 Pressure (in. of $H_2O$) | MP-19 Methane (%) | MP-20 Pressure (in. of $H_2O$) | MP-20 Methane (%) | MP-21 Pressure (in. of $H_2O$) | MP-21 Methane (%) | | | | | | | | | Barometric Pressure (Start) (in. of Hg)[e/] | Barometric Pressure (Finish) (in. of Hg) |
| 8/23/2021 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | | | | | | | | | 30.11 | 30.05 |
| 11/17/2021 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | | | | | | | | | 30.26 | 30.24 |
| | | | | | | | | | | | | | | | | | | |

a/ (in. of $H_2O$) = Pressure measured in inches of water measurement taken in well casing before cap is removed.

b/ (%) = Percent of Methane measured

c/ MP-8BH is sampled if the water level was above the top of screen at MP-8. Six foot deep borehole probe (MP-8 BH) installed and sampled next to MP-8.

d/ NA = Not applicable

e/ (in. of Hg) = Barometric Pressure measured in inches of Mercury

# APPENDIX E

# COVER MONITORING

# FIELD INSPECTION AND MAINTENANCE REPORTS

# APPENDIX E-1

# SITE AND LANDFILL COVER INSPECTIONS

No cover inspections performed this reporting period.

# APPENDIX E-2

# BUFFER ZONE INSPECTIONS

# APPENDIX E-2.1

# AUGUST 2021 BUFFER ZONE INSPECTION

# BUFFER ZONE FIELD INSPECTION AND MAINTENANCE FORM

Inspector: **Chris Carlson** Organization: **Parsons**

Date: **8/17/21**

Instructions: Complete checklist of visual evaluation items and then complete specific data items. Field measurements should be made with a cloth tape and noted on the attached site plan. Estimated measurements shall be so noted. Attach photographs or hand sketches of areas indicating fence damage, erosion, sedimentation, settlement, animal burrows, weeds etc. to further define conditions or problems.

***1. Visual Evaluation Items***

| | | CONDITION: (Check One) | | | | |
|---|---|---|---|---|---|---|
| | Map ID | Acceptable | Not Acceptable | Action Required? Yes | No | REMARKS |
| 1) E. ¼ Section 6 | | | | | | |
| a) Fencing / Security | | | | | | |
| Locking Gates | | X | | | X | |
| Barbwire | | X | | | X | |
| Braces | | X | | | X | |
| Other (litter, disposal) | | X | | | X | |

# BUFFER ZONE FIELD INSPECTION AND MAINTENANCE FORM

| | Map ID | Acceptable | Not Acceptable | Action Required? Yes | No | REMARKS |
|---|---|---|---|---|---|---|
| b) Terrain | | | | | | |
| Settlement | _____ | X | _____ | ___ | X | _____ |
| Animal Burrows | _____ | X | _____ | ___ | X | _____ |
| Erosion | _____ | X | _____ | ___ | X | _____ |
| Sediment Accumulation | _____ | X | _____ | ___ | X | _____ |
| Obstruction of Culverts | _____ | X | _____ | ___ | X | _____ |
| c) Vegetation | | | | | | |
| Weeds | _____ | X | _____ | ___ | X | _____ |
| Ground Cover | _____ | X | _____ | ___ | X | _____ |

# BUFFER ZONE FIELD INSPECTION AND MAINTENANCE FORM

***Specific Items*** *(Write N.A. if not applicable)*

a) Fence / Security
- Map ID: _NA_
- Area: _____feet by _____feet

- Map ID: _NA_
- Area: _____feet by _____feet

b) Terrain
- Map ID: _NA_
- Area: _____feet by _____feet
- Depth: _____feet

- Map ID: _NA_
- Area: _____feet by _____feet
- Depth: _____feet

c) Vegetation
- Map ID: _NA_
- Area: _____feet by _____feet

- Map ID: _NA_
- Area: _____feet by _____feet

- Map ID: _NA_
- Area: _____feet by _____feet

# BUFFER ZONE FIELD INSPECTION AND MAINTENANCE FORM

| | | CONDITION: (Check One) | | | | |
|---|---|---|---|---|---|---|
| | Map | | Not | Action Required? | | |
| | ID | Acceptable | Acceptable | Yes | No | REMARKS |
| 2) N. ½ Section 7 | | | | | | |
| a) Fencing / Security | | | | | | |
| Locking Gates | _____ | __X__ | _____ | ___ | _X_ | _____ |
| Barbwire | _____ | __X__ | _____ | ___ | _X_ | _____ |
| Barbwire | _____ | __X__ | _____ | ___ | _X_ | _____ |
| Braces | _____ | __X__ | _____ | ___ | _X_ | _____ |
| Other (litter, disposal) | _____ | __X__ | _____ | ___ | _X_ | _____ |

# BUFFER ZONE FIELD INSPECTION AND MAINTENANCE FORM (Continued)

| | Map ID | Acceptable | Not Acceptable | Action Required? Yes | No | REMARKS |
|---|---|---|---|---|---|---|
| b) Terrain | | | | | | |
| Settlement | _____ | X | _____ | ___ | X | _____ |
| Animal Burrows | _____ | X | _____ | ___ | X | Approximately 4 Active Burrows |
| Erosion | _____ | X | _____ | ___ | X | _____ |
| Sediment Accumulation | _____ | X | _____ | ___ | X | _____ |
| Obstruction of Culverts | _____ | X | _____ | ___ | X | _____ |
| c) Vegetation | | | | | | |
| Weeds | _____ | X | _____ | ___ | X | _____ |
| Ground Cover | _____ | X | _____ | ___ | X | _____ |

# BUFFER ZONE FIELD INSPECTION AND MAINTENANCE FORM (Continued)

***Specific Items*** *(Write N.A. if not applicable)*

a) Fence / Security
- Map ID: _NA_
- Area: _____feet by _____feet

- Map ID: _NA_
- Area: _____feet by _____feet

- Map ID: _NA_
- Area: _____feet by _____feet

- Map ID: _NA_
- Area: _____feet by _____feet

b) Terrain
- Map ID: _NA_
- Area: _____feet by _____feet
- Depth: _____feet

c) Vegetation
- Map ID: _NA_
- Area: _____feet by _____feet
-

# BUFFER ZONE FIELD INSPECTION AND MAINTENANCE FORM (Continued)

| | | CONDITION: (Check One) | | | | |
|---|---|---|---|---|---|---|
| | Map ID | Acceptable | Not Acceptable | Action Required? Yes | No | REMARKS |
| 3) E. ½ Section 1 | | | | | | |
| a) Fencing / Security | | | | | | |
| Locking Gates | _____ | __X__ | _____ | ___ | _X_ | _____ |
| Barbwire | _____ | __X__ | _____ | ___ | _X_ | _____ |
| Braces | _____ | __X__ | _____ | ___ | _X_ | _____ |
| Other (litter, disposal) | _____ | __X__ | _____ | ___ | _X_ | _____ |

# BUFFER ZONE FIELD INSPECTION AND MAINTENANCE FORM (Continued)

| | Map ID | Acceptable | Not Acceptable | Action Required? Yes | No | REMARKS |
|---|---|---|---|---|---|---|
| b) Terrain | | | | | | |
| Settlement | _____ | X | _____ | ___ | X | _____ |
| Animal Burrows | _____ | X | _____ | | X | Approximately 10 Active Burrows |
| Erosion | _____ | X | _____ | ___ | X | _____ |
| Sediment Accumulation | _____ | X | _____ | ___ | X | _____ |
| Obstruction of Culverts | _____ | X | _____ | ___ | X | _____ |
| c) Vegetation | | | | | | |
| Weeds | _____ | X | _____ | ___ | X | _____ |
| Ground Cover | _____ | X | _____ | ___ | X | _____ |

# BUFFER ZONE FIELD INSPECTION AND MAINTENANCE FORM (Continued)

***Specific Items*** *(Write N.A. if not applicable)*

a) Fence / Security

- Map ID: _NA_
- Area: _____linier feet

- Map ID: _NA_
- Area: _____linier feet

b) Terrain

- Map ID: _NA_
- Area: _____feet by _____feet
- Depth: _____feet

- Map ID: _NA_
- Area: _____feet by _____feet
- Depth: _____feet

c) Vegetation

- Map ID: _NA_
- Area: _____feet by _____feet

- Map ID: _NA_
- Area: _____feet by _____feet

# BUFFER ZONE FIELD INSPECTION AND MAINTENANCE FORM (Continued)

| | | CONDITION: (Check One) | | | | |
|---|---|---|---|---|---|---|
| | Map ID | Acceptable | Not Acceptable | Action Required? Yes | No | REMARKS |
| 4) E. ½ Section 36 | | | | | | |
| a) Fencing / Security | | | | | | |
| Locking Gates | A | | X | X | | Gate found open/unlocked. Locked now. |
| Barbwire | | X | | | X | |
| Barbwire | | X | | | X | |
| Barbwire | | X | | | X | |
| Barbwire | | X | | | X | |
| Barbwire | | X | | | X | |
| Braces | | X | | | X | |
| Other (litter, disposal) | | X | | | X | |

# BUFFER ZONE FIELD INSPECTION AND MAINTENANCE FORM (Continued)

| | Map ID | Acceptable | Not Acceptable | Action Required? Yes | No | REMARKS |
|---|---|---|---|---|---|---|
| b) Terrain | | | | | | |
| Settlement | _____ | X | _____ | ___ | X | _____ |
| Animal Burrows | _____ | X | _____ | ___ | X | _____ |
| Erosion | _____ | X | _____ | ___ | X | _____ |
| Sediment Accumulation | _____ | X | _____ | ___ | X | _____ |
| Obstruction of Culverts | _____ | X | _____ | ___ | X | _____ |
| c) Vegetation | | | | | | |
| Weeds | _____ | X | _____ | ___ | X | _____ |
| Ground Cover | _____ | X | _____ | ___ | X | _____ |

# BUFFER ZONE FIELD INSPECTION AND MAINTENANCE FORM (Continued)

***Specific Items*** *(Write N.A. if not applicable)*

a) Fence / Security
- Map ID: **_A_**
- Area: **NA** linier feet (Gate left open and unlocked by harvest crew)

- Map ID: **NA**
- Area: **NA** linier feet

- Map ID: **NA**
- Area: **NA** linier feet

- Map ID: **NA**
- Area: **NA** linier feet

- Map ID: **NA**
- Area: **NA** linier feet

b) Terrain
- Map ID: **_NA_**
- Area: **_NA_** feet by **_NA_** feet
- Depth: **_NA_** feet


- Map ID: **_NA_**
- Area: **_NA_** feet by **_NA_** feet
- Depth: **_NA_** feet

c) Vegetation
- Map ID: **_NA_**
- Area: _____feet by _____feet

# BUFFER ZONE FIELD INSPECTION AND MAINTENANCE FORM (Continued)

Signature of Inspector:

**Attachments**



__**X**__ Yes ____ No


If yes, list attachments:

__**August 2021 Buffer Property Map.pdf**_____

__**Buffer Zone Pictures (8-17-21).pdf**_____

Date: __**8/17/21**_____

**Actions taken:** Gate found open on Section 36 by harvest crew, closed and locked. Prairie dog burrows to be addressed with mitigation, in the Spring of 2022, sooner if numbers multiply quickly.




Legend

- Lowry Landfill Site Boundary
- Lowry Trust Buffer Property
- Active Prairie Dog Burrows
- Weeds

# August 17, 2021
# Buffer Zone Inspection



E ½ Section 36 (MAP ID A) Gate Found Open. Closed and Locked at Time of Inspection



E ½ Section 1 New Fencing Along Newly Constructed S Gun Club Road and E Quincy Ave Intersection Installed by SEMA Construction in July



E ½ Section 1 New Fencing Along Newly Constructed S Gun Club Road and E Quincy Ave Intersection
Installed by SEMA Construction in July



E ½ Section 1 New Fencing Along Newly Constructed S Gun Club Road and E Quincy Ave Intersection
Installed by SEMA Construction in July



E ½ Section 1 MAP ID D). Prairie Dog Burrows Present 10 Active.

# APPENDIX E-2.2

# NOVEMBER 2021 BUFFER ZONE INSPECTION

# BUFFER ZONE FIELD INSPECTION AND MAINTENANCE FORM

Inspector: **Chris Carlson** Organization: **Parsons**

Date: **11/8/21 and 12/20/21**

Instructions: Complete checklist of visual evaluation items and then complete specific data items. Field measurements should be made with a cloth tape and noted on the attached site plan. Estimated measurements shall be so noted. Attach photographs or hand sketches of areas indicating fence damage, erosion, sedimentation, settlement, animal burrows, weeds etc. to further define conditions or problems.

***1. Visual Evaluation Items***

| | | CONDITION: (Check One) | | | | |
|---|---|---|---|---|---|---|
| | Map ID | Acceptable | Not Acceptable | Action Required? Yes | No | REMARKS |
| 1) E. ¼ Section 6 | | | | | | |
| a) Fencing / Security | | | | | | |
| Locking Gates | | X | | | X | |
| Barbwire | | X | | | X | |
| Braces | | X | | | X | |
| Other (litter, disposal) | | X | | | X | |

# BUFFER ZONE FIELD INSPECTION AND MAINTENANCE FORM

| | Map ID | Acceptable | Not Acceptable | Action Required? Yes | No | REMARKS |
|---|---|---|---|---|---|---|
| b) Terrain | | | | | | |
| Settlement | _____ | __X__ | _____ | ___ | _X_ | _____ |
| Animal Burrows | _____ | __X__ | _____ | ___ | _X_ | _____ |
| Erosion | _____ | __X__ | _____ | ___ | _X_ | _____ |
| Sediment Accumulation | _____ | __X__ | _____ | ___ | _X_ | _____ |
| Obstruction of Culverts | _____ | __X__ | _____ | ___ | _X_ | _____ |
| c) Vegetation | | | | | | |
| Weeds | _____ | __X__ | _____ | ___ | _X_ | _____ |
| Ground Cover | _____ | __X__ | _____ | ___ | _X_ | _____ |

# BUFFER ZONE FIELD INSPECTION AND MAINTENANCE FORM

***Specific Items*** *(Write N.A. if not applicable)*

a) Fence / Security
- Map ID: _NA_
- Area: _____feet by _____feet

- Map ID: _NA_
- Area: _____feet by _____feet

b) Terrain
- Map ID: _NA_
- Area: _____feet by _____feet
- Depth: _____feet

- Map ID: _NA_
- Area: _____feet by _____feet
- Depth: _____feet

c) Vegetation
- Map ID: _NA_
- Area: _____feet by _____feet

- Map ID: _NA_
- Area: _____feet by _____feet

- Map ID: _NA_
- Area: _____feet by _____feet

# BUFFER ZONE FIELD INSPECTION AND MAINTENANCE FORM

| | | CONDITION: (Check One) | | | | |
|---|---|---|---|---|---|---|
| | Map | | Not | Action Required? | | |
| | ID | Acceptable | Acceptable | Yes | No | REMARKS |
| 2) N. ½ Section 7 | | | | | | |
| a) Fencing / Security | | | | | | |
| Locking Gates | _____ | __X__ | _____ | ___ | _X_ | _____ |
| Barbwire | __A__ | _____ | __X__ | _X_ | ___ | Approx. 100 LF of barbwire damaged. |
| Barbwire | _____ | __X__ | _____ | ___ | _X_ | _____ |
| Braces | _____ | __X__ | _____ | ___ | _X_ | _____ |
| Other (litter, disposal) | _____ | __X__ | _____ | ___ | _X_ | _____ |

# BUFFER ZONE FIELD INSPECTION AND MAINTENANCE FORM (Continued)

| | Map ID | Acceptable | Not Acceptable | Action Required? Yes | No | REMARKS |
|---|---|---|---|---|---|---|
| b) Terrain | | | | | | |
| Settlement | | X | | | X | |
| Animal Burrows | | X | | | X | Approximately 4 Active Burrows |
| Erosion | | X | | | X | |
| Sediment Accumulation | | X | | | X | |
| Obstruction of Culverts | | X | | | X | |
| c) Vegetation | | | | | | |
| Weeds | | X | | | X | |
| Ground Cover | | X | | | X | |

# BUFFER ZONE FIELD INSPECTION AND MAINTENANCE FORM (Continued)

***Specific Items*** *(Write N.A. if not applicable)*

a) Fence / Security
- Map ID: **_A_**
- Area: **100** linier feet (Barbwire fencing near E Quincy Ave. damaged by vehicle)

- Map ID: _NA_
- Area: _____feet by _____feet

- Map ID: _NA_
- Area: _____feet by _____feet

- Map ID: _NA_
- Area: _____feet by _____feet

b) Terrain
- Map ID: _NA_
- Area: _____feet by _____feet
- Depth: _____feet

c) Vegetation
- Map ID: _NA_
- Area: _____feet by _____feet
-

# BUFFER ZONE FIELD INSPECTION AND MAINTENANCE FORM (Continued)

| | | CONDITION: (Check One) | | | | |
|---|---|---|---|---|---|---|
| | **Map ID** | **Acceptable** | **Not Acceptable** | **Action Required? Yes** | **No** | **REMARKS** |
| 3) E. ½ Section 1 | | | | | | |
| a) Fencing / Security | | | | | | |
| Locking Gates | | X | | | X | |
| Barbwire | | X | | | X | |
| Braces | | X | | | X | |
| Other (litter, disposal) | | X | | | X | |

# BUFFER ZONE FIELD INSPECTION AND MAINTENANCE FORM (Continued)

| | Map ID | Acceptable | Not Acceptable | Action Required? Yes | No | REMARKS |
|---|---|---|---|---|---|---|
| b) Terrain | | | | | | |
| Settlement | _____ | X | _____ | ___ | X | _____ |
| Animal Burrows | _____ | X | _____ | | X | Approximately 13 Active Burrows |
| Erosion | _____ | X | _____ | ___ | X | _____ |
| Sediment Accumulation | _____ | X | _____ | ___ | X | _____ |
| Obstruction of Culverts | _____ | X | _____ | ___ | X | _____ |
| c) Vegetation | | | | | | |
| Weeds | _____ | X | _____ | ___ | X | _____ |
| Ground Cover | _____ | X | _____ | ___ | X | _____ |

# BUFFER ZONE FIELD INSPECTION AND MAINTENANCE FORM (Continued)

***Specific Items*** *(Write N.A. if not applicable)*

a) Fence / Security

- Map ID: _NA_
- Area: _____linier feet

- Map ID: _NA_
- Area: _____linier feet

b) Terrain

- Map ID: _NA_
- Area: _____feet by _____feet
- Depth: _____feet

- Map ID: _NA_
- Area: _____feet by _____feet
- Depth: _____feet

c) Vegetation

- Map ID: _NA_
- Area: _____feet by _____feet

- Map ID: _NA_
- Area: _____feet by _____feet

# BUFFER ZONE FIELD INSPECTION AND MAINTENANCE FORM (Continued)

| | | CONDITION: (Check One) | | | | |
|---|---|---|---|---|---|---|
| | Map ID | Acceptable | Not Acceptable | Action Required? Yes | No | REMARKS |
| 4) E. ½ Section 36 | | | | | | |
| a) Fencing / Security | | | | | | |
| Locking Gates | | X | | | X | |
| Barbwire | | X | | | X | |
| Barbwire | | X | | | X | |
| Barbwire | | X | | | X | |
| Barbwire | | X | | | X | |
| Barbwire | | X | | | X | |
| Braces | | X | | | X | |
| Other (litter, disposal) | | X | | | X | |

# BUFFER ZONE FIELD INSPECTION AND MAINTENANCE FORM (Continued)

| | Map ID | Acceptable | Not Acceptable | Action Required? Yes | No | REMARKS |
|---|---|---|---|---|---|---|
| b) Terrain | | | | | | |
| Settlement | | X | | | X | |
| Animal Burrows | | X | | | X | Approximately 20 Active Burrows |
| Erosion | | X | | | X | |
| Sediment Accumulation | | X | | | X | |
| Obstruction of Culverts | | X | | | X | |
| c) Vegetation | | | | | | |
| Weeds | | X | | | X | |
| Ground Cover | | X | | | X | |

# BUFFER ZONE FIELD INSPECTION AND MAINTENANCE FORM (Continued)

***Specific Items*** *(Write N.A. if not applicable)*

a) Fence / Security
- Map ID: **NA**
- Area: **NA** linier feet

- Map ID: **NA**
- Area: **NA** linier feet

- Map ID: **NA**
- Area: **NA** linier feet

- Map ID: **NA**
- Area: **NA** linier feet

- Map ID: **NA**
- Area: **NA** linier feet

b) Terrain
- Map ID: **_NA_**
- Area: **_NA_** feet by **_NA_** feet
- Depth: **_NA_** feet


- Map ID: **_NA_**
- Area: **_NA_** feet by **_NA_** feet
- Depth: **_NA_** feet

c) Vegetation
- Map ID: **_NA_**
- Area: _____feet by _____feet

# BUFFER ZONE FIELD INSPECTION AND MAINTENANCE FORM (Continued)

Signature of Inspector:

**Attachments**



__**X**__ Yes ____ No


If yes, list attachments:

__**November 2021 Buffer Property Map.pdf**_____

__**Buffer Zone Pictures (11-8-21 and 12-20-21)).pdf**_____

Date: __**12/20/21**_____

**Actions taken:** Fence damaged on Section 7 near E Quincy Avenue found and repaired during informal monthly inspection on December 20, 2021. Prairie dog burrows to be addressed with mitigation, in the Spring of 2022, sooner if numbers multiply quickly.




Legend

- Lowry Landfill Site Boundary
- Lowry Trust Buffer Property
- Active Prairie Dog Burrows
- Weeds

# November 8, 2021
# Buffer Zone Inspection




N ½ Section 7 (MAP ID A) Approximately 100 LF of Barbwire Fence Found Damaged 12/20/21



N ½ Section 7 (MAP ID A) Approximately 100 LF of Barbwire Fence Found Damaged 12/20/21



N ½ Section 7 (MAP ID A) Approximately 100 LF of Barbwire Fence Found Damaged 12/20/21. Repaired 12/20/21.



E ½ Section 1 Approximately 10 Active Prairie Dog Burrows Present 11/8/21.



E ¼ Section 6 Fencing Good and No Active Prairie Dog Burrows 11/8/21



E ¼ Section 6 Fencing Good and No Active Prairie Dog Burrows 11/8/21




E ¼ Section 6 Fencing Good and No Active Prairie Dog Burrows 11/8/21



N ½ Section 7 Active Prairie Dog Burrows 11/8/21



N ½ Section 7 Active Prairie Dog Burrows 11/8/21



E ½ Section 36 Active Prairie Dog Burrows 11/8/21



E ½ Section 36 Active Prairie Dog Burrows 11/8/21



E ½ Section 36 Active Prairie Dog Burrows 11/8/21



E ½ Section 36 Active Prairie Dog Burrows 11/8/21

# APPENDIX F

# ANALYTICAL DATA PACKAGES, DATA VALIDATION REPORTS, AND DATA QUALITY ASSESSMENT

# APPENDIX F-1

# SAMPLE LOCATION CROSS REFERENCE TABLE

**APPENDIX F-1**
**SAMPLE LOCATION CROSS-REFERENCE TABLE**
**JULY THROUGH DECEMBER 2021 OPERATIONS AND MAINTENANCE STATUS REPORT**
**LOWRY LANDFILL SUPERFUND SITE**

| Data Type | Sample Location | Sample Date | Project Number | Lab | Validated?[a/] |
|---|---|---|---|---|---|
| GW[b/] - Compliance/Effectiveness/B-326-UD & B-313 RAWP[c/] | B-313 | 8/12/2021 | 280-151819-1 | EUROFINS | NR |
| GW - Compliance/Effectiveness/B-326-UD & B-313 RAWP | B-313 | 11/16/2021 | A214611 | PACE | NR |
| GW - Compliance/Effectiveness | B-314 | 10/27/2021 | 280-154753-1 | EUROFINS | X |
| GW - Compliance/Effectiveness | B-314 | 10/27/2021 | A214317 | PACE | X |
| GW - B-326-UD & B-313 RAWP | B-321 | 8/11/2021 | 280-151744-1 | EUROFINS | NR |
| GW - B-326-UD & B-313 RAWP | B-321 | 8/30/2021 | A213505 | PACE | NR |
| GW - Molybdenum Investigation | B-326-UD | 8/12/2021 | 280-151836-1 | EUROFINS | NR |
| GW - North End Monitoring | B-326-UD | 8/30/2021 | A213505 | PACE | NR |
| GW - Molybdenum Investigation | B-326-UD | 10/12/2021 | 280-154070-1 | EUROFINS | NR |
| GW - North End Monitoring | B-326-UD | 10/12/2021 | A214120 | PACE | X |
| GW - Molybdenum Investigation | B-326-WD | 8/12/2021 | 280-151836-1 | EUROFINS | NR |
| GW - North End Monitoring | B-326-WD | 8/30/2021 | A213505 | PACE | NR |
| GW - Confirmation Sample | B-326-WD | 9/27/2021 | A213905 | PACE | NR |
| GW - Compliance/Effectiveness/Molybdenum Investigation | B-326-WD | 10/12/2021 | 280-154071-1 | EUROFINS | X |
| GW - Compliance/Effectiveness | B-326-WD | 10/12/2021 | A214120 | PACE | X |
| GW - Performance Evaluation | BKGD-3WD | 8/16/2021 | 280-151930-1 | EUROFINS | X |
| GW - Performance Evaluation | BKGD-3WD | 8/16/2021 | A213302 | PACE | X |
| GW - Compliance/Effectiveness | BM-11X-100N | 10/28/2021 | 280-154815-1 | EUROFINS | NR |
| GW - Compliance/Effectiveness | BM-11X-100N | 10/28/2021 | A214330 | PACE | NR |
| GW - Compliance/Effectiveness | BM-11X-100S | 10/28/2021 | 280-154815-1 | EUROFINS | NR |
| GW - Compliance/Effectiveness | BM-11X-100S | 10/28/2021 | A214330 | PACE | NR |
| GW - Compliance | BM-15E2 | 11/16/2021 | 280-155721-1 | EUROFINS | NR |
| GW - Compliance | BM-15E2 | 11/16/2021 | A214611 | PACE | NR |
| GW - Compliance/Effectiveness | BM-15N6 | 10/13/2021 | 280-154169-1 | EUROFINS | NR |
| GW - Compliance/Effectiveness | BM-15N6 | 10/13/2021 | A214121 | PACE | NR |
| GW - Compliance | GW-106 | 10/13/2021 | 280-154115-1 | EUROFINS | NR |
| GW - Compliance | GW-106 | 10/13/2021 | A214121 | PACE | NR |
| GW - Effectiveness | MNA-01 | 11/23/2021 | 280-156069-1 | EUROFINS | NR |
| GW - Effectiveness | MNA-03 | 11/23/2021 | 280-156069-1 | EUROFINS | NR |
| WTP[d/] - Compliance | MP-001 | 7/6/2021 | 280-150534-1 | EUROFINS | X |
| WTP - Compliance | MP-001 | 7/7/2021 | 21-07031 | EBS[e/] | X |
| WTP - Compliance | MP-001 | 7/7/2021 | 280-150532-1 | EUROFINS | X |
| WTP - Compliance | MP-001 | 7/7/2021 | 280-150534-1 | EUROFINS | X |
| WTP - Compliance | MP-001 | 8/2/2021 | 280-151434-1 | EUROFINS | X |
| WTP - Compliance | MP-001 | 8/3/2021 | 280-151431-1 | EUROFINS | X |
| WTP - Compliance | MP-001 | 8/3/2021 | 280-151434-1 | EUROFINS | X |
| WTP - Compliance | MP-001 | 9/7/2021 | 280-152738-1 | EUROFINS | X |

**APPENDIX F-1**
**SAMPLE LOCATION CROSS-REFERENCE TABLE**
**JULY THROUGH DECEMBER 2021 OPERATIONS AND MAINTENANCE STATUS REPORT**
**LOWRY LANDFILL SUPERFUND SITE**

| Data Type | Sample Location | Sample Date | Project Number | Lab | Validated?[a/] |
|---|---|---|---|---|---|
| WTP - Compliance | MP-001 | 9/8/2021 | 280-152738-1 | EUROFINS | X |
| WTP - Compliance | MP-001 | 9/8/2021 | 280-152739-1 | EUROFINS | X |
| WTP - Compliance | MP-001 | 10/4/2021 | 280-153738-1 | EUROFINS | X |
| WTP - Compliance | MP-001 | 10/5/2021 | 21-10013 | EBS | X |
| WTP - Compliance | MP-001 | 10/5/2021 | 280-153738-1 | EUROFINS | X |
| WTP - Compliance | MP-001 | 10/5/2021 | 280-153741-1 | EUROFINS | X |
| WTP - Compliance | MP-001 | 11/1/2021 | 280-155031-1 | EUROFINS | X |
| WTP - Compliance | MP-001 | 11/2/2021 | 280-155028-1 | EUROFINS | X |
| WTP - Compliance | MP-001 | 11/2/2021 | 280-155029-1 | EUROFINS | X |
| WTP - Compliance | MP-001 | 11/2/2021 | 280-155031-1 | EUROFINS | X |
| WTP - Compliance | MP-001 | 12/6/2021 | 280-156498-1 | EUROFINS | X |
| WTP - Compliance | MP-001 | 12/7/2021 | 280-156498-1 | EUROFINS | X |
| WTP - Compliance | MP-001 | 12/7/2021 | 280-156500-1 | EUROFINS | X |
| GW - North End Monitoring | MW05-WD | 8/18/2021 | A213314 | PACE | NR |
| GW - North End Monitoring | MW102-WD | 8/31/2021 | A213506 | PACE | NR |
| GW - North End Monitoring | MW102-WD | 11/18/2021 | A214617 | PACE | NR |
| GW - North End Monitoring | MW103-WD | 8/5/2021 | A213109 | PACE | NR |
| GW - North End Monitoring | MW103-WD | 11/2/2021 | A214421 | PACE | NR |
| GW - Compliance | MW105-WD | 10/19/2021 | 280-154402-1 | EUROFINS | NR |
| GW - Compliance | MW105-WD | 10/19/2021 | A214210 | PACE | NR |
| GW - Compliance | MW108-WD | 11/1/2021 | 280-154968-1 | EUROFINS | NR |
| GW - Compliance | MW108-WD | 11/1/2021 | A214417 | PACE | NR |
| GW -Molybdenum Investigation | MW113-EW-1 | 7/29/2021 | 280-151315-1 | EUROFINS | NR |
| GW - North End Monitoring | MW113-EW-1 | 7/29/2021 | A213022 | PACE | X |
| GW -Molybdenum Investigation | MW113-EW-1 | 10/19/2021 | 280-154399-1 | EUROFINS | NR |
| GW -Molybdenum Investigation | MW113-EW-1 | 10/19/2021 | 280-154405-1 | EUROFINS | NR |
| GW - North End Monitoring | MW113-EW-1 | 10/19/2021 | A214210 | PACE | NR |
| GW -Molybdenum Investigation | MW113-UD | 7/29/2021 | 280-151317-1 | EUROFINS | NR |
| GW - North End Monitoring | MW113-UD | 7/29/2021 | A213022 | PACE | X |
| GW -Molybdenum Investigation | MW113-UD | 8/25/2021 | 280-152231-1 | EUROFINS | NR |
| GW -Molybdenum Investigation | MW113-UD | 9/9/2021 | 280-152782-1 | EUROFINS | NR |
| GW -Molybdenum Investigation | MW113-UD | 10/19/2021 | 280-154405-1 | EUROFINS | NR |
| GW - North End Monitoring | MW113-UD | 10/19/2021 | A214210 | PACE | NR |
| GW -Molybdenum Investigation | MW113-UD | 11/17/2021 | 280-155787-1 | EUROFINS | NR |
| GW -Molybdenum Investigation | MW113-UD | 12/15/2021 | 280-156887-1 | EUROFINS | NR |
| GW -Molybdenum Investigation | MW113-WD | 7/13/2021 | 280-150730-1 | EUROFINS | NR |
| GW -Molybdenum Investigation | MW113-WD | 7/29/2021 | 280-151317-1 | EUROFINS | NR |
| GW -Molybdenum Investigation | MW113-WD | 8/11/2021 | 280-151746-1 | EUROFINS | NR |
| GW -Molybdenum Investigation | MW113-WD | 8/25/2021 | 280-152231-1 | EUROFINS | NR |

**APPENDIX F-1**
**SAMPLE LOCATION CROSS-REFERENCE TABLE**
**JULY THROUGH DECEMBER 2021 OPERATIONS AND MAINTENANCE STATUS REPORT**
**LOWRY LANDFILL SUPERFUND SITE**

| Data Type | Sample Location | Sample Date | Project Number | Lab | Validated?[a/] |
|---|---|---|---|---|---|
| GW -Molybdenum Investigation | MW113-WD | 9/8/2021 | 280-152740-1 | EUROFINS | NR |
| GW -Molybdenum Investigation | MW113-WD | 9/23/2021 | 280-153333-1 | EUROFINS | NR |
| GW -Molybdenum Investigation | MW113-WD | 10/5/2021 | 280-153751-1 | EUROFINS | NR |
| GW -Molybdenum Investigation | MW113-WD | 10/19/2021 | 280-154405-1 | EUROFINS | NR |
| GW -Molybdenum Investigation | MW113-WD | 11/2/2021 | 280-155030-1 | EUROFINS | NR |
| GW -Molybdenum Investigation | MW113-WD | 11/17/2021 | 280-155787-1 | EUROFINS | NR |
| GW -Molybdenum Investigation | MW113-WD | 11/30/2021 | 280-156216-1 | EUROFINS | NR |
| GW -Molybdenum Investigation | MW113-WD | 12/15/2021 | 280-156887-1 | EUROFINS | NR |
| GW -Molybdenum Investigation | MW113-WD | 12/28/2021 | 280-157266-1 | EUROFINS | NR |
| GW - North End Monitoring | MW114-WD | 8/5/2021 | A213109 | PACE | NR |
| GW - North End Monitoring | MW114-WD | 11/17/2021 | A214618 | PACE | NR |
| GW - North End Monitoring | MW117-WD | 8/5/2021 | A213109 | PACE | NR |
| GW - North End Monitoring | MW117-WD | 11/17/2021 | A214618 | PACE | NR |
| GW - North End Monitoring | MW118-WD | 8/9/2021 | A213210 | PACE | NR |
| GW - North End Monitoring | MW118-WD | 11/17/2021 | A214618 | PACE | NR |
| GW - North End Monitoring | MW121-WDR | 8/18/2021 | A213314 | PACE | NR |
| GW - North End Monitoring | MW122-WDR | 8/18/2021 | A213314 | PACE | NR |
| GW - North End Monitoring | MW123-WD | 8/18/2021 | A213314 | PACE | NR |
| GW - North End Monitoring | MW124-WD | 8/18/2021 | A213314 | PACE | NR |
| GW - North End Monitoring | MW125-WD | 8/30/2021 | A213505 | PACE | NR |
| GW - North End Monitoring | MW129-WD | 9/7/2021 | A213606 | PACE | X |
| GW - North End Monitoring | MW132-WD | 7/21/2021 | A212910 | PACE | NR |
| GW - North End Monitoring | MW132-WD | 11/2/2021 | A214421 | PACE | NR |
| GW - North End Monitoring | MW135-WD | 7/28/2021 | A213020 | PACE | NR |
| GW - North End Monitoring | MW141-WD | 7/28/2021 | A213020 | PACE | NR |
| GW - North End Monitoring | MW142-WD | 7/28/2021 | A213020 | PACE | NR |
| GW - North End Monitoring | MW144-WD | 8/4/2021 | A213106 | PACE | NR |
| GW - North End Monitoring | MW151-WD | 7/19/2021 | A212904 | PACE | NR |
| GW - North End Monitoring | MW151-WD | 11/11/2021 | A214602 | PACE | NR |
| GW - North End Monitoring | MW153-EW-1 | 7/21/2021 | A212910 | PACE | NR |
| GW - North End Monitoring | MW153-EW-1 | 11/8/2021 | A214504 | PACE | NR |
| GW - North End Monitoring | MW154-EW-1 | 7/21/2021 | A212910 | PACE | NR |
| GW - North End Monitoring | MW154-EW-1 | 11/11/2021 | A214602 | PACE | NR |
| GW - North End Monitoring | MW155-EW-1 | 7/21/2021 | A212910 | PACE | NR |
| GW - North End Monitoring | MW155-EW-1 | 11/22/2021 | A214701 | PACE | NR |
| GW - North End Monitoring | MW156-EW-1 | 7/21/2021 | A212910 | PACE | NR |
| GW - North End Monitoring | MW156-EW-1 | 11/22/2021 | A214701 | PACE | NR |
| GW - North End Monitoring | MW156-WD | 7/19/2021 | A212904 | PACE | NR |
| GW - North End Monitoring | MW156-WD | 11/11/2021 | A214602 | PACE | NR |

**APPENDIX F-1**
**SAMPLE LOCATION CROSS-REFERENCE TABLE**
**JULY THROUGH DECEMBER 2021 OPERATIONS AND MAINTENANCE STATUS REPORT**
**LOWRY LANDFILL SUPERFUND SITE**

| Data Type | Sample Location | Sample Date | Project Number | Lab | Validated?[a/] |
|---|---|---|---|---|---|
| GW - North End Monitoring | MW157-WD | 7/19/2021 | A212904 | PACE | NR |
| GW - North End Monitoring | MW157-WD | 11/11/2021 | A214602 | PACE | NR |
| GW - North End Monitoring | MW160-WD | 7/19/2021 | A212904 | PACE | NR |
| GW - North End Monitoring | MW160-WD | 11/8/2021 | A214504 | PACE | NR |
| GW - RAWP/MW77 Response Action/Molybdenum Investigation | MW170-EW-1 | 8/9/2021 | 280-151705-1 | EUROFINS | NR |
| GW - RAWP/MW77 Response Action | MW170-EW-1 | 8/9/2021 | A213210 | PACE | NR |
| GW - RAWP/MW77 Response Action/Molybdenum Investigation | MW170-EW-1 | 10/27/2021 | 280-154754-1 | EUROFINS | NR |
| GW - RAWP/MW77 Response Action | MW170-EW-1 | 10/27/2021 | A214317 | PACE | X |
| GW - North End Monitoring | MW176-DEN | 8/4/2021 | A213106 | PACE | NR |
| GW - North End Monitoring | MW179-UDEN | 9/8/2021 | A213606 | PACE | X |
| GW - Compliance | MW23-UPPER-C | 10/18/2021 | 280-154346-1 | EUROFINS | NR |
| GW - Compliance | MW23-UPPER-C | 10/18/2021 | A214204 | PACE | NR |
| GW - Compliance | MW36-WDR | 11/2/2021 | 280-155019-1 | EUROFINS | NR |
| GW - Compliance | MW36-WDR | 11/2/2021 | A214421 | PACE | NR |
| GW - MW38 Source Control | MW38-1028N-256E | 11/10/2021 | 280-155451-1 | EUROFINS | NR |
| GW - MW38 Source Control | MW38-1028N-256E | 11/10/2021 | A214510 | PACE | NR |
| GW - MW38 Source Control | MW38-170S-140W | 11/9/2021 | 280-155385-1 | EUROFINS | NR |
| GW - MW38 Source Control | MW38-170S-140W | 11/9/2021 | A214510 | PACE | NR |
| GW - MW38 Source Control | MW38-825S-445E | 11/8/2021 | 280-155385-1 | EUROFINS | NR |
| GW - MW38 Source Control | MW38-825S-445E | 11/8/2021 | A214504 | PACE | NR |
| GW - Compliance | MW38-830N-230E | 10/14/2021 | 280-154169-1 | EUROFINS | NR |
| GW - Compliance | MW38-830N-230E | 10/14/2021 | A214134 | PACE | NR |
| GW - Compliance | MW43-WD | 11/16/2021 | 280-155721-1 | EUROFINS | NR |
| GW - Compliance | MW43-WD | 11/16/2021 | A214611 | PACE | NR |
| GW - Compliance | MW54-WD | 10/14/2021 | 280-154169-1 | EUROFINS | NR |
| GW - Compliance | MW54-WD | 10/14/2021 | A214134 | PACE | NR |
| GW - Compliance | MW60-WD | 10/28/2021 | 280-154815-1 | EUROFINS | NR |
| GW - Compliance | MW60-WD | 10/28/2021 | A214330 | PACE | NR |
| GW - Compliance/Effectiveness | MW62-WDR | 10/27/2021 | 280-154752-1 | EUROFINS | X |
| GW - Compliance/Effectiveness | MW62-WDR | 10/27/2021 | A214317 | PACE | X |
| GW - VES[f/] Performance | MW70-WD | 11/9/2021 | 280-155383-1 | EUROFINS | NR |
| GW - Compliance | MW71-WD | 11/1/2021 | 280-154968-1 | EUROFINS | NR |
| GW - Compliance | MW71-WD | 11/1/2021 | A214417 | PACE | NR |
| GW - Compliance | MW74-WD | 10/14/2021 | 280-154169-1 | EUROFINS | NR |
| GW - Compliance | MW74-WD | 10/14/2021 | A214134 | PACE | NR |
| GW - North End Monitoring | MW77-EW-1 | 8/31/2021 | A213506 | PACE | NR |

**APPENDIX F-1**
**SAMPLE LOCATION CROSS-REFERENCE TABLE**
**JULY THROUGH DECEMBER 2021 OPERATIONS AND MAINTENANCE STATUS REPORT**
**LOWRY LANDFILL SUPERFUND SITE**

| Data Type | Sample Location | Sample Date | Project Number | Lab | Validated?[a/] |
|---|---|---|---|---|---|
| GW - North End Monitoring | MW77-EW-1 | 11/18/2021 | A214617 | PACE | NR |
| GW - North End Monitoring | MW77-EW-2 | 9/1/2021 | A213508 | PACE | NR |
| GW - North End Monitoring | MW77-EW-2 | 9/14/2021 | A213709 | PACE | NR |
| GW - North End Monitoring | MW77-EW-2 | 11/18/2021 | A214617 | PACE | NR |
| GW - Compliance | MW77-WD | 10/27/2021 | 280-154752-1 | EUROFINS | X |
| GW - Compliance | MW77-WD | 10/27/2021 | A214317 | PACE | X |
| GW - Compliance | MW78-WD | 11/1/2021 | 280-154968-1 | EUROFINS | NR |
| GW - Compliance | MW78-WD | 11/1/2021 | A214417 | PACE | NR |
| GW - Compliance | MW90-WD | 10/13/2021 | 280-154115-1 | EUROFINS | NR |
| GW - Compliance | MW90-WD | 10/13/2021 | A214121 | PACE | NR |
| GW - Compliance | MW91-WD | 10/18/2021 | 280-154346-1 | EUROFINS | NR |
| GW - Compliance | MW91-WD | 10/18/2021 | A214204 | PACE | NR |
| GW - North End Monitoring | MW98-WD | 8/31/2021 | A213506 | PACE | NR |
| GW - North End Monitoring | MW98-WD | 11/18/2021 | A214617 | PACE | NR |
| GW - NBBW-IW-3 Response Action | NBBW-IW-3 | 8/5/2021 | 280-151558-1 | EUROFINS | NR |
| GW - Effectiveness | PM-13X | 11/3/2021 | 280-155266-1 | EUROFINS | NR |
| GW - Effectiveness | PM-13X | 11/3/2021 | A214429 | PACE | NR |
| GW - Compliance/Effectiveness | PM-14X | 10/26/2021 | 280-154710-1 | EUROFINS | NR |
| GW - Compliance/Effectiveness | PM-14X | 10/26/2021 | A214308 | PACE | NR |
| GW - Effectiveness | PM-3X | 11/3/2021 | 280-155095-1 | EUROFINS | NR |
| GW - Effectiveness | PM-3X | 11/3/2021 | A214426 | PACE | NR |
| GW - Effectiveness | PM-6X | 11/3/2021 | 280-155095-1 | EUROFINS | NR |
| GW - Effectiveness | PM-6X | 11/3/2021 | A214426 | PACE | NR |
| GW - Molybdenum Investigation | PTP-11 | 8/26/2021 | 280-152303-1 | EUROFINS | NR |
| GW - Molybdenum Investigation | PTP-11 | 11/4/2021 | 280-155264-1 | EUROFINS | NR |
| GW - Molybdenum Investigation | PTP-12 | 8/26/2021 | 280-152303-1 | EUROFINS | NR |
| GW - Molybdenum Investigation | PTP-12 | 11/4/2021 | 280-155264-1 | EUROFINS | NR |
| GW - North End Monitoring | PTP-12 | 11/4/2021 | A214429 | PACE | NR |
| GW - Molybdenum Investigation | PTP-13 | 8/25/2021 | 280-152231-1 | EUROFINS | NR |
| GW - North End Monitoring | PTP-13 | 8/25/2021 | A213408 | PACE | NR |
| GW - Molybdenum Investigation | PTP-13 | 11/10/2021 | 280-155455-1 | EUROFINS | NR |
| GW - North End Monitoring | PTP-13 | 11/10/2021 | A214510 | PACE | NR |
| WTP - Early Warning | TP-110 | 7/6/2021 | 280-150497-1 | EUROFINS | NR |
| WTP - Early Warning | TP-110 | 8/2/2021 | 280-151437-1 | EUROFINS | NR |
| WTP - Early Warning | TP-110 | 9/7/2021 | 280-152675-1 | EUROFINS | NR |
| WTP - Early Warning | TP-110 | 10/4/2021 | 280-153737-1 | EUROFINS | NR |
| WTP - Early Warning | TP-110 | 11/1/2021 | 280-154978-1 | EUROFINS | NR |
| WTP - Early Warning | TP-110 | 12/6/2021 | 280-156501-1 | EUROFINS | NR |
| WTP - Early Warning | TP-120 | 7/6/2021 | 280-150497-1 | EUROFINS | NR |

**APPENDIX F-1**
**SAMPLE LOCATION CROSS-REFERENCE TABLE**
**JULY THROUGH DECEMBER 2021 OPERATIONS AND MAINTENANCE STATUS REPORT**
**LOWRY LANDFILL SUPERFUND SITE**

| Data Type | Sample Location | Sample Date | Project Number | Lab | Validated?[a/] |
|---|---|---|---|---|---|
| WTP - Early Warning | TP-120 | 8/2/2021 | 280-151437-1 | EUROFINS | NR |
| WTP - Early Warning | TP-120 | 9/7/2021 | 280-152675-1 | EUROFINS | NR |
| WTP - Early Warning | TP-120 | 10/4/2021 | 280-153737-1 | EUROFINS | NR |
| WTP - Early Warning | TP-120 | 11/1/2021 | 280-154978-1 | EUROFINS | NR |
| WTP - Early Warning | TP-120 | 12/6/2021 | 280-156501-1 | EUROFINS | NR |
| WTP - Early Warning | TP-140 | 7/6/2021 | 280-150497-1 | EUROFINS | NR |
| WTP - Early Warning | TP-140 | 8/2/2021 | 280-151437-1 | EUROFINS | NR |
| WTP - Early Warning | TP-140 | 9/7/2021 | 280-152675-1 | EUROFINS | NR |
| WTP - Early Warning | TP-140 | 10/4/2021 | 280-153737-1 | EUROFINS | NR |
| WTP - Early Warning | TP-140 | 11/1/2021 | 280-154978-1 | EUROFINS | NR |
| WTP - Early Warning | TP-140 | 12/6/2021 | 280-156501-1 | EUROFINS | NR |
| WTP - Early Warning | TP-150 | 7/6/2021 | 280-150497-1 | EUROFINS | NR |
| WTP - Early Warning | TP-150 | 8/2/2021 | 280-151437-1 | EUROFINS | NR |
| WTP - Early Warning | TP-150 | 9/7/2021 | 280-152675-1 | EUROFINS | NR |
| WTP - Early Warning | TP-150 | 10/4/2021 | 280-153737-1 | EUROFINS | NR |
| WTP - Early Warning | TP-150 | 11/1/2021 | 280-154978-1 | EUROFINS | NR |
| WTP - Early Warning | TP-150 | 12/6/2021 | 280-156501-1 | EUROFINS | NR |
| WTP - Early Warning | TP-160 | 7/6/2021 | 280-150497-1 | EUROFINS | NR |
| WTP - Early Warning | TP-160 | 8/2/2021 | 280-151437-1 | EUROFINS | NR |
| WTP - Early Warning | TP-160 | 9/7/2021 | 280-152675-1 | EUROFINS | NR |
| WTP - Early Warning | TP-160 | 10/4/2021 | 280-153737-1 | EUROFINS | NR |
| WTP - Early Warning | TP-160 | 11/1/2021 | 280-154978-1 | EUROFINS | NR |
| WTP - Early Warning | TP-160 | 12/6/2021 | 280-156501-1 | EUROFINS | NR |
| WTP - Early Warning | TP-170 | 7/6/2021 | 280-150497-1 | EUROFINS | NR |
| WTP - Molybdenum Performance | TP-170 | 7/6/2021 | 280-150501-1 | EUROFINS | NR |
| WTP - Molybdenum Performance | TP-170 | 7/13/2021 | 280-150720-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-170 | 7/13/2021 | 280-150721-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-170 | 7/20/2021 | 280-150951-1 | EUROFINS | NR |
| WTP - Molybdenum Performance | TP-170 | 7/20/2021 | 280-150952-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-170 | 7/27/2021 | 280-151191-1 | EUROFINS | NR |
| WTP - Molybdenum Performance | TP-170 | 7/27/2021 | 280-151192-1 | EUROFINS | NR |
| WTP - Early Warning | TP-170 | 8/2/2021 | 280-151437-1 | EUROFINS | NR |
| WTP - Molybdenum Performance | TP-170 | 8/2/2021 | 280-151452-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-170 | 8/10/2021 | 280-151712-1 | EUROFINS | NR |
| WTP - Molybdenum Performance | TP-170 | 8/10/2021 | 280-151714-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-170 | 8/17/2021 | 280-151954-1 | EUROFINS | NR |
| WTP - Molybdenum Performance | TP-170 | 8/17/2021 | 280-151955-1 | EUROFINS | NR |
| WTP - Molybdenum Performance | TP-170 | 8/24/2021 | 280-152189-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-170 | 8/24/2021 | 280-152190-1 | EUROFINS | NR |

**APPENDIX F-1**
**SAMPLE LOCATION CROSS-REFERENCE TABLE**
**JULY THROUGH DECEMBER 2021 OPERATIONS AND MAINTENANCE STATUS REPORT**
**LOWRY LANDFILL SUPERFUND SITE**

| Data Type | Sample Location | Sample Date | Project Number | Lab | Validated?[a/] |
|---|---|---|---|---|---|
| WTP - Molybdenum Performance | TP-170 | 8/31/2021 | 280-152445-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-170 | 8/31/2021 | 280-152446-1 | EUROFINS | NR |
| WTP - Molybdenum Performance | TP-170 | 9/7/2021 | 280-152673-1 | EUROFINS | NR |
| WTP - Early Warning | TP-170 | 9/7/2021 | 280-152675-1 | EUROFINS | NR |
| WTP - Molybdenum Performance | TP-170 | 9/14/2021 | 280-152941-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-170 | 9/21/2021 | 280-153216-1 | EUROFINS | NR |
| WTP - Molybdenum Performance | TP-170 | 9/21/2021 | 280-153217-1 | EUROFINS | NR |
| WTP - Molybdenum Performance | TP-170 | 9/28/2021 | 280-153488-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-170 | 9/28/2021 | 280-153489-1 | EUROFINS | NR |
| WTP - Early Warning | TP-170 | 10/4/2021 | 280-153737-1 | EUROFINS | NR |
| WTP - Molybdenum Performance | TP-170 | 10/4/2021 | 280-153739-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-170 | 10/12/2021 | 280-154064-1 | EUROFINS | NR |
| WTP - Molybdenum Performance | TP-170 | 10/12/2021 | 280-154068-1 | EUROFINS | NR |
| WTP - Molybdenum Performance | TP-170 | 10/19/2021 | 280-154400-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-170 | 10/19/2021 | 280-154401-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-170 | 10/26/2021 | 280-154712-1 | EUROFINS | NR |
| WTP - Molybdenum Performance | TP-170 | 10/26/2021 | 280-154713-1 | EUROFINS | NR |
| WTP - Molybdenum Performance | TP-170 | 11/1/2021 | 280-154971-1 | EUROFINS | NR |
| WTP - Early Warning | TP-170 | 11/1/2021 | 280-154978-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-170 | 11/9/2021 | 280-155384-1 | EUROFINS | NR |
| WTP - Molybdenum Performance | TP-170 | 11/9/2021 | 280-155387-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-170 | 11/16/2021 | 280-155724-1 | EUROFINS | NR |
| WTP - Molybdenum Performance | TP-170 | 11/16/2021 | 280-155726-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-170 | 11/23/2021 | 280-156071-1 | EUROFINS | NR |
| WTP - Molybdenum Performance | TP-170 | 11/23/2021 | 280-156073-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-170 | 11/30/2021 | 280-156207-1 | EUROFINS | NR |
| WTP - Molybdenum Performance | TP-170 | 11/30/2021 | 280-156210-1 | EUROFINS | NR |
| WTP - Early Warning | TP-170 | 12/6/2021 | 280-156501-1 | EUROFINS | NR |
| WTP - Molybdenum Performance | TP-170 | 12/6/2021 | 280-156505-1 | EUROFINS | NR |
| WTP - Molybdenum Performance | TP-170 | 12/14/2021 | 280-156803-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-170 | 12/14/2021 | 280-156804-1 | EUROFINS | NR |
| WTP - Molybdenum Performance | TP-170 | 12/21/2021 | 280-157113-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-170 | 12/21/2021 | 280-157116-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-170 | 12/28/2021 | 280-157265-1 | EUROFINS | NR |
| WTP - Molybdenum Performance | TP-170 | 12/28/2021 | 280-157267-1 | EUROFINS | NR |
| WTP - Molybdenum Performance | TP-173A | 7/6/2021 | 280-150501-1 | EUROFINS | NR |
| WTP - Molybdenum Performance | TP-173A | 7/13/2021 | 280-150720-1 | EUROFINS | NR |
| WTP - Molybdenum Performance | TP-173A | 7/20/2021 | 280-150952-1 | EUROFINS | NR |
| WTP - Molybdenum Performance | TP-173A | 7/27/2021 | 280-151192-1 | EUROFINS | NR |

**APPENDIX F-1**
**SAMPLE LOCATION CROSS-REFERENCE TABLE**
**JULY THROUGH DECEMBER 2021 OPERATIONS AND MAINTENANCE STATUS REPORT**
**LOWRY LANDFILL SUPERFUND SITE**

| Data Type | Sample Location | Sample Date | Project Number | Lab | Validated?[a/] |
|---|---|---|---|---|---|
| WTP - Molybdenum Performance | TP-173A | 8/2/2021 | 280-151452-1 | EUROFINS | NR |
| WTP - Molybdenum Performance | TP-173A | 8/10/2021 | 280-151714-1 | EUROFINS | NR |
| WTP - Molybdenum Performance | TP-173A | 8/17/2021 | 280-151955-1 | EUROFINS | NR |
| WTP - Molybdenum Performance | TP-173A | 8/24/2021 | 280-152189-1 | EUROFINS | NR |
| WTP - Molybdenum Performance | TP-173A | 8/31/2021 | 280-152445-1 | EUROFINS | NR |
| WTP - Molybdenum Performance | TP-173A | 9/7/2021 | 280-152673-1 | EUROFINS | NR |
| WTP - Molybdenum Performance | TP-173A | 9/14/2021 | 280-152941-1 | EUROFINS | NR |
| WTP - Molybdenum Performance | TP-173A | 9/21/2021 | 280-153217-1 | EUROFINS | NR |
| WTP - Molybdenum Performance | TP-173A | 9/28/2021 | 280-153488-1 | EUROFINS | NR |
| WTP - Molybdenum Performance | TP-173A | 10/4/2021 | 280-153739-1 | EUROFINS | NR |
| WTP - Molybdenum Performance | TP-173A | 10/12/2021 | 280-154068-1 | EUROFINS | NR |
| WTP - Molybdenum Performance | TP-173A | 10/19/2021 | 280-154400-1 | EUROFINS | NR |
| WTP - Molybdenum Performance | TP-173A | 10/26/2021 | 280-154713-1 | EUROFINS | NR |
| WTP - Molybdenum Performance | TP-173A | 11/1/2021 | 280-154971-1 | EUROFINS | NR |
| WTP - Molybdenum Performance | TP-173A | 11/9/2021 | 280-155387-1 | EUROFINS | NR |
| WTP - Molybdenum Performance | TP-173A | 11/16/2021 | 280-155726-1 | EUROFINS | NR |
| WTP - Molybdenum Performance | TP-173A | 11/23/2021 | 280-156073-1 | EUROFINS | NR |
| WTP - Molybdenum Performance | TP-173A | 11/30/2021 | 280-156210-1 | EUROFINS | NR |
| WTP - Molybdenum Performance | TP-173A | 12/6/2021 | 280-156505-1 | EUROFINS | NR |
| WTP - Molybdenum Performance | TP-173A | 12/14/2021 | 280-156803-1 | EUROFINS | NR |
| WTP - Molybdenum Performance | TP-173A | 12/21/2021 | 280-157113-1 | EUROFINS | NR |
| WTP - Molybdenum Performance | TP-173A | 12/28/2021 | 280-157267-1 | EUROFINS | NR |
| WTP - Molybdenum Performance | TP-174A | 7/6/2021 | 280-150501-1 | EUROFINS | NR |
| WTP - Molybdenum Performance | TP-174A | 7/13/2021 | 280-150720-1 | EUROFINS | NR |
| WTP - Molybdenum Performance | TP-174A | 7/20/2021 | 280-150952-1 | EUROFINS | NR |
| WTP - Molybdenum Performance | TP-174A | 7/27/2021 | 280-151192-1 | EUROFINS | NR |
| WTP - Molybdenum Performance | TP-174A | 8/2/2021 | 280-151452-1 | EUROFINS | NR |
| WTP - Molybdenum Performance | TP-174A | 8/10/2021 | 280-151714-1 | EUROFINS | NR |
| WTP - Molybdenum Performance | TP-174A | 8/17/2021 | 280-151955-1 | EUROFINS | NR |
| WTP - Molybdenum Performance | TP-174A | 8/24/2021 | 280-152189-1 | EUROFINS | NR |
| WTP - Molybdenum Performance | TP-174A | 8/31/2021 | 280-152445-1 | EUROFINS | NR |
| WTP - Molybdenum Performance | TP-174A | 9/7/2021 | 280-152673-1 | EUROFINS | NR |
| WTP - Molybdenum Performance | TP-174A | 9/14/2021 | 280-152941-1 | EUROFINS | NR |
| WTP - Molybdenum Performance | TP-174A | 9/21/2021 | 280-153217-1 | EUROFINS | NR |
| WTP - Molybdenum Performance | TP-174A | 9/28/2021 | 280-153488-1 | EUROFINS | NR |
| WTP - Molybdenum Performance | TP-174A | 10/4/2021 | 280-153739-1 | EUROFINS | NR |
| WTP - Molybdenum Performance | TP-174A | 10/12/2021 | 280-154068-1 | EUROFINS | NR |
| WTP - Molybdenum Performance | TP-174A | 10/19/2021 | 280-154400-1 | EUROFINS | NR |
| WTP - Molybdenum Performance | TP-174A | 10/26/2021 | 280-154713-1 | EUROFINS | NR |

**APPENDIX F-1**
**SAMPLE LOCATION CROSS-REFERENCE TABLE**
**JULY THROUGH DECEMBER 2021 OPERATIONS AND MAINTENANCE STATUS REPORT**
**LOWRY LANDFILL SUPERFUND SITE**

| Data Type | Sample Location | Sample Date | Project Number | Lab | Validated?[a/] |
|---|---|---|---|---|---|
| WTP - Molybdenum Performance | TP-174A | 11/1/2021 | 280-154971-1 | EUROFINS | NR |
| WTP - Molybdenum Performance | TP-174A | 11/9/2021 | 280-155387-1 | EUROFINS | NR |
| WTP - Molybdenum Performance | TP-174A | 11/16/2021 | 280-155726-1 | EUROFINS | NR |
| WTP - Molybdenum Performance | TP-174A | 11/23/2021 | 280-156073-1 | EUROFINS | NR |
| WTP - Molybdenum Performance | TP-174A | 11/30/2021 | 280-156210-1 | EUROFINS | NR |
| WTP - Molybdenum Performance | TP-174A | 12/6/2021 | 280-156505-1 | EUROFINS | NR |
| WTP - Molybdenum Performance | TP-174A | 12/14/2021 | 280-156803-1 | EUROFINS | NR |
| WTP - Molybdenum Performance | TP-174A | 12/21/2021 | 280-157113-1 | EUROFINS | NR |
| WTP - Molybdenum Performance | TP-174A | 12/28/2021 | 280-157267-1 | EUROFINS | NR |
| WTP - Molybdenum Performance | TP-183 | 7/6/2021 | 280-150501-1 | EUROFINS | NR |
| WTP - Molybdenum Performance | TP-183 | 7/13/2021 | 280-150720-1 | EUROFINS | NR |
| WTP - Molybdenum Performance | TP-183 | 7/20/2021 | 280-150952-1 | EUROFINS | NR |
| WTP - Molybdenum Performance | TP-183 | 7/27/2021 | 280-151192-1 | EUROFINS | NR |
| WTP - Molybdenum Performance | TP-183 | 8/2/2021 | 280-151452-1 | EUROFINS | NR |
| WTP - Molybdenum Performance | TP-183 | 8/10/2021 | 280-151714-1 | EUROFINS | NR |
| WTP - Molybdenum Performance | TP-183 | 8/17/2021 | 280-151955-1 | EUROFINS | NR |
| WTP - Molybdenum Performance | TP-183 | 8/24/2021 | 280-152189-1 | EUROFINS | NR |
| WTP - Molybdenum Performance | TP-183 | 8/31/2021 | 280-152445-1 | EUROFINS | NR |
| WTP - Molybdenum Performance | TP-183 | 9/7/2021 | 280-152673-1 | EUROFINS | NR |
| WTP - Molybdenum Performance | TP-183 | 9/14/2021 | 280-152941-1 | EUROFINS | NR |
| WTP - Molybdenum Performance | TP-183 | 9/21/2021 | 280-153217-1 | EUROFINS | NR |
| WTP - Molybdenum Performance | TP-183 | 9/28/2021 | 280-153488-1 | EUROFINS | NR |
| WTP - Molybdenum Performance | TP-183 | 10/4/2021 | 280-153739-1 | EUROFINS | NR |
| WTP - Molybdenum Performance | TP-183 | 10/12/2021 | 280-154068-1 | EUROFINS | NR |
| WTP - Molybdenum Performance | TP-183 | 10/19/2021 | 280-154400-1 | EUROFINS | NR |
| WTP - Molybdenum Performance | TP-183 | 10/26/2021 | 280-154713-1 | EUROFINS | NR |
| WTP - Molybdenum Performance | TP-183 | 11/1/2021 | 280-154971-1 | EUROFINS | NR |
| WTP - Molybdenum Performance | TP-183 | 11/9/2021 | 280-155387-1 | EUROFINS | NR |
| WTP - Molybdenum Performance | TP-183 | 11/16/2021 | 280-155726-1 | EUROFINS | NR |
| WTP - Molybdenum Performance | TP-183 | 11/23/2021 | 280-156073-1 | EUROFINS | NR |
| WTP - Molybdenum Performance | TP-183 | 11/30/2021 | 280-156210-1 | EUROFINS | NR |
| WTP - Molybdenum Performance | TP-183 | 12/6/2021 | 280-156505-1 | EUROFINS | NR |
| WTP - Molybdenum Performance | TP-183 | 12/14/2021 | 280-156803-1 | EUROFINS | NR |
| WTP - Molybdenum Performance | TP-183 | 12/21/2021 | 280-157113-1 | EUROFINS | NR |
| WTP - Molybdenum Performance | TP-183 | 12/28/2021 | 280-157267-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3300 | 7/6/2021 | 280-150498-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3300 | 7/6/2021 | 280-150500-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3300 | 7/13/2021 | 280-150719-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3300 | 7/13/2021 | 280-150721-1 | EUROFINS | NR |

**APPENDIX F-1**
**SAMPLE LOCATION CROSS-REFERENCE TABLE**
**JULY THROUGH DECEMBER 2021 OPERATIONS AND MAINTENANCE STATUS REPORT**
**LOWRY LANDFILL SUPERFUND SITE**

| Data Type | Sample Location | Sample Date | Project Number | Lab | Validated?[a/] |
|---|---|---|---|---|---|
| WTP - Biotreatment System | TP-3300 | 7/20/2021 | 280-150947-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3300 | 7/20/2021 | 280-150951-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3300 | 7/27/2021 | 280-151190-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3300 | 7/27/2021 | 280-151191-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3300 | 8/3/2021 | 280-151428-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3300 | 8/3/2021 | 280-151451-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3300 | 8/10/2021 | 280-151706-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3300 | 8/10/2021 | 280-151712-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3300 | 8/17/2021 | 280-151952-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3300 | 8/17/2021 | 280-151954-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3300 | 8/24/2021 | 280-152186-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3300 | 8/24/2021 | 280-152190-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3300 | 8/31/2021 | 280-152444-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3300 | 8/31/2021 | 280-152446-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3300 | 9/7/2021 | 280-152672-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3300 | 9/7/2021 | 280-152674-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3300 | 9/14/2021 | 280-152937-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3300 | 9/14/2021 | 280-152940-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3300 | 9/21/2021 | 280-153216-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3300 | 9/21/2021 | 280-153218-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3300 | 9/28/2021 | 280-153489-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3300 | 9/28/2021 | 280-153491-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3300 | 10/5/2021 | 280-153736-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3300 | 10/5/2021 | 280-153740-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3300 | 10/12/2021 | 280-154064-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3300 | 10/12/2021 | 280-154066-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3300 | 10/19/2021 | 280-154398-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3300 | 10/19/2021 | 280-154401-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3300 | 10/26/2021 | 280-154711-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3300 | 10/26/2021 | 280-154712-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3300 | 11/2/2021 | 280-155026-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3300 | 11/2/2021 | 280-155027-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3300 | 11/9/2021 | 280-155380-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3300 | 11/9/2021 | 280-155384-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3300 | 11/16/2021 | 280-155723-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3300 | 11/16/2021 | 280-155724-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3300 | 11/23/2021 | 280-156070-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3300 | 11/23/2021 | 280-156071-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3300 | 11/30/2021 | 280-156205-1 | EUROFINS | NR |

**APPENDIX F-1**
**SAMPLE LOCATION CROSS-REFERENCE TABLE**
**JULY THROUGH DECEMBER 2021 OPERATIONS AND MAINTENANCE STATUS REPORT**
**LOWRY LANDFILL SUPERFUND SITE**

| Data Type | Sample Location | Sample Date | Project Number | Lab | Validated?[a/] |
|---|---|---|---|---|---|
| WTP - Biotreatment System | TP-3300 | 11/30/2021 | 280-156207-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3300 | 12/7/2021 | 280-156495-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3300 | 12/7/2021 | 280-156511-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3300 | 12/14/2021 | 280-156800-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3300 | 12/14/2021 | 280-156804-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3300 | 12/21/2021 | 280-157111-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3300 | 12/21/2021 | 280-157116-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3300 | 12/28/2021 | 280-157261-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3300 | 12/28/2021 | 280-157265-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3310 | 7/6/2021 | 280-150497-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3310 | 7/13/2021 | 280-150719-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3310 | 7/13/2021 | 280-150721-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3310 | 7/20/2021 | 280-150947-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3310 | 7/20/2021 | 280-150951-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3310 | 7/27/2021 | 280-151190-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3310 | 7/27/2021 | 280-151191-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3310 | 8/2/2021 | 280-151437-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3310 | 8/3/2021 | 280-151428-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3310 | 8/3/2021 | 280-151451-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3310 | 8/10/2021 | 280-151706-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3310 | 8/10/2021 | 280-151712-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3310 | 8/17/2021 | 280-151952-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3310 | 8/17/2021 | 280-151954-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3310 | 8/24/2021 | 280-152186-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3310 | 8/24/2021 | 280-152190-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3310 | 8/31/2021 | 280-152444-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3310 | 8/31/2021 | 280-152446-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3310 | 9/7/2021 | 280-152675-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3310 | 9/7/2021 | 280-152672-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3310 | 9/7/2021 | 280-152674-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3310 | 9/14/2021 | 280-152937-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3310 | 9/14/2021 | 280-152940-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3310 | 9/21/2021 | 280-153216-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3310 | 9/21/2021 | 280-153218-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3310 | 9/28/2021 | 280-153489-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3310 | 9/28/2021 | 280-153491-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3310 | 10/4/2021 | 280-153737-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3310 | 10/5/2021 | 280-153736-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3310 | 10/5/2021 | 280-153740-1 | EUROFINS | NR |

**APPENDIX F-1**
**SAMPLE LOCATION CROSS-REFERENCE TABLE**
**JULY THROUGH DECEMBER 2021 OPERATIONS AND MAINTENANCE STATUS REPORT**
**LOWRY LANDFILL SUPERFUND SITE**

| Data Type | Sample Location | Sample Date | Project Number | Lab | Validated?[a/] |
|---|---|---|---|---|---|
| WTP - Biotreatment System | TP-3310 | 10/12/2021 | 280-154064-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3310 | 10/12/2021 | 280-154066-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3310 | 10/19/2021 | 280-154398-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3310 | 10/19/2021 | 280-154401-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3310 | 10/26/2021 | 280-154711-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3310 | 10/26/2021 | 280-154712-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3310 | 11/1/2021 | 280-154978-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3310 | 11/2/2021 | 280-155026-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3310 | 11/2/2021 | 280-155027-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3310 | 11/9/2021 | 280-155380-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3310 | 11/9/2021 | 280-155384-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3310 | 11/16/2021 | 280-155723-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3310 | 11/16/2021 | 280-155724-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3310 | 11/23/2021 | 280-156070-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3310 | 11/23/2021 | 280-156071-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3310 | 11/30/2021 | 280-156205-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3310 | 11/30/2021 | 280-156207-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3310 | 12/6/2021 | 280-156501-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3310 | 12/7/2021 | 280-156495-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3310 | 12/7/2021 | 280-156511-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3310 | 12/14/2021 | 280-156800-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3310 | 12/14/2021 | 280-156804-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3310 | 12/21/2021 | 280-157111-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3310 | 12/21/2021 | 280-157116-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3310 | 12/28/2021 | 280-157261-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3310 | 12/28/2021 | 280-157265-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3320 | 7/6/2021 | 280-150498-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3320 | 7/6/2021 | 280-150500-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3320 | 7/13/2021 | 280-150719-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3320 | 7/13/2021 | 280-150721-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3320 | 7/20/2021 | 280-150947-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3320 | 7/20/2021 | 280-150951-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3320 | 7/27/2021 | 280-151190-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3320 | 7/27/2021 | 280-151191-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3320 | 8/3/2021 | 280-151451-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3320 | 8/3/2021 | 280-151428-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3320 | 8/10/2021 | 280-151706-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3320 | 8/10/2021 | 280-151712-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3320 | 8/17/2021 | 280-151952-1 | EUROFINS | NR |

**APPENDIX F-1**
**SAMPLE LOCATION CROSS-REFERENCE TABLE**
**JULY THROUGH DECEMBER 2021 OPERATIONS AND MAINTENANCE STATUS REPORT**
**LOWRY LANDFILL SUPERFUND SITE**

| Data Type | Sample Location | Sample Date | Project Number | Lab | Validated?[a/] |
|---|---|---|---|---|---|
| WTP - Biotreatment System | TP-3320 | 8/17/2021 | 280-151954-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3320 | 8/24/2021 | 280-152186-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3320 | 8/24/2021 | 280-152190-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3320 | 8/31/2021 | 280-152444-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3320 | 8/31/2021 | 280-152446-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3320 | 9/7/2021 | 280-152672-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3320 | 9/7/2021 | 280-152674-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3320 | 9/14/2021 | 280-152937-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3320 | 9/14/2021 | 280-152940-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3320 | 9/21/2021 | 280-153216-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3320 | 9/21/2021 | 280-153218-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3320 | 9/28/2021 | 280-153489-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3320 | 9/28/2021 | 280-153491-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3320 | 10/5/2021 | 280-153736-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3320 | 10/5/2021 | 280-153740-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3320 | 10/12/2021 | 280-154064-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3320 | 10/12/2021 | 280-154066-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3320 | 10/19/2021 | 280-154398-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3320 | 10/19/2021 | 280-154401-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3320 | 10/26/2021 | 280-154711-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3320 | 10/26/2021 | 280-154712-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3320 | 11/2/2021 | 280-155026-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3320 | 11/2/2021 | 280-155027-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3320 | 11/9/2021 | 280-155380-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3320 | 11/9/2021 | 280-155384-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3320 | 11/16/2021 | 280-155723-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3320 | 11/16/2021 | 280-155724-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3320 | 11/23/2021 | 280-156070-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3320 | 11/23/2021 | 280-156071-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3320 | 11/30/2021 | 280-156205-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3320 | 11/30/2021 | 280-156207-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3320 | 12/7/2021 | 280-156495-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3320 | 12/7/2021 | 280-156511-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3320 | 12/14/2021 | 280-156800-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3320 | 12/14/2021 | 280-156804-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3320 | 12/21/2021 | 280-157111-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3320 | 12/21/2021 | 280-157116-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3320 | 12/28/2021 | 280-157261-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3320 | 12/28/2021 | 280-157265-1 | EUROFINS | NR |

**APPENDIX F-1**
**SAMPLE LOCATION CROSS-REFERENCE TABLE**
**JULY THROUGH DECEMBER 2021 OPERATIONS AND MAINTENANCE STATUS REPORT**
**LOWRY LANDFILL SUPERFUND SITE**

| Data Type | Sample Location | Sample Date | Project Number | Lab | Validated?[a/] |
|---|---|---|---|---|---|
| WTP - Biotreatment System | TP-3331 | 7/6/2021 | 280-150498-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3331 | 7/13/2021 | 280-150719-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3331 | 7/20/2021 | 280-150947-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3331 | 7/27/2021 | 280-151190-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3331 | 8/3/2021 | 280-151428-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3331 | 8/10/2021 | 280-151706-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3331 | 8/17/2021 | 280-151952-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3331 | 8/24/2021 | 280-152186-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3331 | 8/31/2021 | 280-152444-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3331 | 9/7/2021 | 280-152672-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3331 | 9/14/2021 | 280-152937-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3331 | 9/21/2021 | 280-153218-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3331 | 9/28/2021 | 280-153491-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3331 | 10/5/2021 | 280-153736-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3331 | 10/12/2021 | 280-154066-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3331 | 10/19/2021 | 280-154398-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3331 | 10/26/2021 | 280-154711-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3331 | 11/2/2021 | 280-155026-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3331 | 11/9/2021 | 280-155380-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3331 | 11/16/2021 | 280-155723-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3331 | 11/23/2021 | 280-156070-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3331 | 11/30/2021 | 280-156205-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3331 | 12/7/2021 | 280-156495-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3331 | 12/14/2021 | 280-156800-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3331 | 12/21/2021 | 280-157111-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3331 | 12/28/2021 | 280-157261-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3332 | 7/6/2021 | 280-150498-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3332 | 7/13/2021 | 280-150719-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3332 | 7/20/2021 | 280-150947-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3332 | 7/27/2021 | 280-151190-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3332 | 8/3/2021 | 280-151428-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3332 | 8/10/2021 | 280-151706-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3332 | 8/17/2021 | 280-151952-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3332 | 8/24/2021 | 280-152186-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3332 | 8/31/2021 | 280-152444-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3332 | 9/7/2021 | 280-152672-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3332 | 9/14/2021 | 280-152937-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3332 | 9/21/2021 | 280-153218-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3332 | 9/28/2021 | 280-153491-1 | EUROFINS | NR |

**APPENDIX F-1**
**SAMPLE LOCATION CROSS-REFERENCE TABLE**
**JULY THROUGH DECEMBER 2021 OPERATIONS AND MAINTENANCE STATUS REPORT**
**LOWRY LANDFILL SUPERFUND SITE**

| Data Type | Sample Location | Sample Date | Project Number | Lab | Validated?[a/] |
|---|---|---|---|---|---|
| WTP - Biotreatment System | TP-3332 | 10/5/2021 | 280-153736-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3332 | 10/12/2021 | 280-154066-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3332 | 10/19/2021 | 280-154398-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3332 | 10/26/2021 | 280-154711-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3332 | 11/2/2021 | 280-155026-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3332 | 11/9/2021 | 280-155380-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3332 | 11/16/2021 | 280-155723-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3332 | 11/23/2021 | 280-156070-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3332 | 11/30/2021 | 280-156205-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3332 | 12/7/2021 | 280-156495-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3332 | 12/14/2021 | 280-156800-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3332 | 12/21/2021 | 280-157111-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3332 | 12/28/2021 | 280-157261-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3333 | 7/6/2021 | 280-150498-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3333 | 7/13/2021 | 280-150719-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3333 | 7/20/2021 | 280-150947-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3333 | 7/27/2021 | 280-151190-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3333 | 8/3/2021 | 280-151428-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3333 | 8/10/2021 | 280-151706-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3333 | 8/17/2021 | 280-151952-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3333 | 8/24/2021 | 280-152186-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3333 | 8/31/2021 | 280-152444-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3333 | 9/7/2021 | 280-152672-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3333 | 9/14/2021 | 280-152937-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3333 | 9/21/2021 | 280-153218-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3333 | 9/28/2021 | 280-153491-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3333 | 10/5/2021 | 280-153736-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3333 | 10/12/2021 | 280-154066-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3333 | 10/19/2021 | 280-154398-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3333 | 10/26/2021 | 280-154711-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3333 | 11/2/2021 | 280-155026-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3333 | 11/9/2021 | 280-155380-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3333 | 11/16/2021 | 280-155723-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3333 | 11/23/2021 | 280-156070-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3333 | 11/30/2021 | 280-156205-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3333 | 12/7/2021 | 280-156495-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3333 | 12/14/2021 | 280-156800-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3333 | 12/21/2021 | 280-157111-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3333 | 12/28/2021 | 280-157261-1 | EUROFINS | NR |

**APPENDIX F-1**
**SAMPLE LOCATION CROSS-REFERENCE TABLE**
**JULY THROUGH DECEMBER 2021 OPERATIONS AND MAINTENANCE STATUS REPORT**
**LOWRY LANDFILL SUPERFUND SITE**

| Data Type | Sample Location | Sample Date | Project Number | Lab | Validated?[a/] |
|---|---|---|---|---|---|
| WTP - Biotreatment System | TP-3340 | 7/6/2021 | 280-150498-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3340 | 7/6/2021 | 280-150500-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3340 | 7/13/2021 | 280-150719-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3340 | 7/13/2021 | 280-150721-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3340 | 7/20/2021 | 280-150947-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3340 | 7/20/2021 | 280-150951-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3340 | 7/27/2021 | 280-151190-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3340 | 7/27/2021 | 280-151191-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3340 | 8/3/2021 | 280-151428-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3340 | 8/3/2021 | 280-151451-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3340 | 8/10/2021 | 280-151706-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3340 | 8/10/2021 | 280-151712-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3340 | 8/17/2021 | 280-151952-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3340 | 8/17/2021 | 280-151954-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3340 | 8/24/2021 | 280-152186-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3340 | 8/24/2021 | 280-152190-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3340 | 8/31/2021 | 280-152444-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3340 | 8/31/2021 | 280-152446-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3340 | 9/7/2021 | 280-152672-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3340 | 9/7/2021 | 280-152674-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3340 | 9/14/2021 | 280-152937-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3340 | 9/14/2021 | 280-152940-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3340 | 9/21/2021 | 280-153216-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3340 | 9/21/2021 | 280-153218-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3340 | 9/28/2021 | 280-153489-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3340 | 9/28/2021 | 280-153491-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3340 | 10/5/2021 | 280-153736-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3340 | 10/5/2021 | 280-153740-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3340 | 10/12/2021 | 280-154064-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3340 | 10/12/2021 | 280-154066-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3340 | 10/19/2021 | 280-154398-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3340 | 10/19/2021 | 280-154401-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3340 | 10/26/2021 | 280-154711-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3340 | 10/26/2021 | 280-154712-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3340 | 11/2/2021 | 280-155026-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3340 | 11/2/2021 | 280-155027-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3340 | 11/9/2021 | 280-155380-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3340 | 11/9/2021 | 280-155384-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3340 | 11/16/2021 | 280-155723-1 | EUROFINS | NR |

**APPENDIX F-1**
**SAMPLE LOCATION CROSS-REFERENCE TABLE**
**JULY THROUGH DECEMBER 2021 OPERATIONS AND MAINTENANCE STATUS REPORT**
**LOWRY LANDFILL SUPERFUND SITE**

| Data Type | Sample Location | Sample Date | Project Number | Lab | Validated?[a/] |
|---|---|---|---|---|---|
| WTP - Biotreatment System | TP-3340 | 11/16/2021 | 280-155724-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3340 | 11/23/2021 | 280-156070-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3340 | 11/23/2021 | 280-156071-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3340 | 11/30/2021 | 280-156205-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3340 | 11/30/2021 | 280-156207-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3340 | 12/7/2021 | 280-156495-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3340 | 12/7/2021 | 280-156511-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3340 | 12/14/2021 | 280-156800-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3340 | 12/14/2021 | 280-156804-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3340 | 12/21/2021 | 280-157111-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3340 | 12/21/2021 | 280-157116-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3340 | 12/28/2021 | 280-157261-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-3340 | 12/28/2021 | 280-157265-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-710 | 7/6/2021 | 280-150500-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-710 | 7/13/2021 | 280-150721-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-710 | 7/20/2021 | 280-150951-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-710 | 7/27/2021 | 280-151191-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-710 | 8/3/2021 | 280-151451-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-710 | 8/10/2021 | 280-151712-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-710 | 8/17/2021 | 280-151954-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-710 | 8/24/2021 | 280-152190-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-710 | 8/31/2021 | 280-152446-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-710 | 9/7/2021 | 280-152674-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-710 | 9/14/2021 | 280-152940-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-710 | 9/21/2021 | 280-153216-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-710 | 9/28/2021 | 280-153489-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-710 | 10/5/2021 | 280-153740-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-710 | 10/12/2021 | 280-154064-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-710 | 10/19/2021 | 280-154401-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-710 | 10/26/2021 | 280-154712-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-710 | 11/2/2021 | 280-155027-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-710 | 11/9/2021 | 280-155384-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-710 | 11/16/2021 | 280-155724-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-710 | 11/23/2021 | 280-156071-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-710 | 11/30/2021 | 280-156207-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-710 | 12/7/2021 | 280-156511-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-710 | 12/14/2021 | 280-156804-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-710 | 12/21/2021 | 280-157116-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-710 | 12/28/2021 | 280-157265-1 | EUROFINS | NR |

**APPENDIX F-1**
**SAMPLE LOCATION CROSS-REFERENCE TABLE**
**JULY THROUGH DECEMBER 2021 OPERATIONS AND MAINTENANCE STATUS REPORT**
**LOWRY LANDFILL SUPERFUND SITE**

| Data Type | Sample Location | Sample Date | Project Number | Lab | Validated?[a/] |
|---|---|---|---|---|---|
| WTP - Biotreatment System | TP-730 | 7/6/2021 | 280-150498-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-730 | 7/6/2021 | 280-150500-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-730 | 7/13/2021 | 280-150719-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-730 | 7/13/2021 | 280-150721-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-730 | 7/20/2021 | 280-150947-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-730 | 7/20/2021 | 280-150951-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-730 | 7/27/2021 | 280-151190-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-730 | 7/27/2021 | 280-151191-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-730 | 8/3/2021 | 280-151428-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-730 | 8/3/2021 | 280-151451-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-730 | 8/10/2021 | 280-151706-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-730 | 8/10/2021 | 280-151712-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-730 | 8/17/2021 | 280-151952-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-730 | 8/17/2021 | 280-151954-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-730 | 8/24/2021 | 280-152186-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-730 | 8/24/2021 | 280-152190-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-730 | 8/31/2021 | 280-152444-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-730 | 8/31/2021 | 280-152446-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-730 | 9/7/2021 | 280-152672-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-730 | 9/7/2021 | 280-152674-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-730 | 9/14/2021 | 280-152937-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-730 | 9/14/2021 | 280-152940-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-730 | 9/21/2021 | 280-153216-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-730 | 9/21/2021 | 280-153218-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-730 | 9/28/2021 | 280-153489-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-730 | 9/28/2021 | 280-153491-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-730 | 10/5/2021 | 280-153736-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-730 | 10/5/2021 | 280-153740-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-730 | 10/12/2021 | 280-154064-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-730 | 10/12/2021 | 280-154066-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-730 | 10/19/2021 | 280-154398-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-730 | 10/19/2021 | 280-154401-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-730 | 10/26/2021 | 280-154711-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-730 | 10/26/2021 | 280-154712-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-730 | 11/2/2021 | 280-155026-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-730 | 11/2/2021 | 280-155027-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-730 | 11/9/2021 | 280-155380-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-730 | 11/9/2021 | 280-155384-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-730 | 11/16/2021 | 280-155723-1 | EUROFINS | NR |

**APPENDIX F-1**
**SAMPLE LOCATION CROSS-REFERENCE TABLE**
**JULY THROUGH DECEMBER 2021 OPERATIONS AND MAINTENANCE STATUS REPORT**
**LOWRY LANDFILL SUPERFUND SITE**

| Data Type | Sample Location | Sample Date | Project Number | Lab | Validated?[a/] |
|---|---|---|---|---|---|
| WTP - Biotreatment System | TP-730 | 11/16/2021 | 280-155724-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-730 | 11/23/2021 | 280-156070-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-730 | 11/23/2021 | 280-156071-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-730 | 11/30/2021 | 280-156205-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-730 | 11/30/2021 | 280-156207-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-730 | 12/7/2021 | 280-156495-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-730 | 12/7/2021 | 280-156511-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-730 | 12/14/2021 | 280-156800-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-730 | 12/14/2021 | 280-156804-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-730 | 12/21/2021 | 280-157111-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-730 | 12/21/2021 | 280-157116-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-730 | 12/28/2021 | 280-157261-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-730 | 12/28/2021 | 280-157265-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-740 | 7/6/2021 | 280-150500-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-740 | 7/13/2021 | 280-150721-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-740 | 7/20/2021 | 280-150951-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-740 | 7/27/2021 | 280-151191-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-740 | 8/3/2021 | 280-151451-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-740 | 8/10/2021 | 280-151712-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-740 | 8/17/2021 | 280-151954-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-740 | 8/24/2021 | 280-152190-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-740 | 8/31/2021 | 280-152446-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-740 | 9/7/2021 | 280-152674-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-740 | 9/14/2021 | 280-152940-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-740 | 9/21/2021 | 280-153216-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-740 | 9/28/2021 | 280-153489-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-740 | 10/5/2021 | 280-153740-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-740 | 10/12/2021 | 280-154064-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-740 | 10/19/2021 | 280-154401-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-740 | 10/26/2021 | 280-154712-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-740 | 11/2/2021 | 280-155027-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-740 | 11/9/2021 | 280-155384-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-740 | 11/16/2021 | 280-155724-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-740 | 11/23/2021 | 280-156071-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-740 | 11/30/2021 | 280-156207-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-740 | 12/7/2021 | 280-156511-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-740 | 12/14/2021 | 280-156804-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-740 | 12/21/2021 | 280-157116-1 | EUROFINS | NR |
| WTP - Biotreatment System | TP-740 | 12/28/2021 | 280-157265-1 | EUROFINS | NR |

**APPENDIX F-1**
**SAMPLE LOCATION CROSS-REFERENCE TABLE**
**JULY THROUGH DECEMBER 2021 OPERATIONS AND MAINTENANCE STATUS REPORT**
**LOWRY LANDFILL SUPERFUND SITE**

| Data Type | Sample Location | Sample Date | Project Number | Lab | Validated?[a/] |
|---|---|---|---|---|---|
| GW - Compliance | U-518R-WD | 10/26/2021 | 280-154710-1 | EUROFINS | NR |
| GW - Compliance | U-518R-WD | 10/26/2021 | A214308 | PACE | NR |
| WTP - Sludge Analysis | WTP SLUDGE | 9/28/2021 | 21-09091 | EBS | NR |
| WTP - Sludge Analysis | WTP SLUDGE | 9/28/2021 | 280-153533-1 | EUROFINS | NR |
| WTP - Sludge Analysis (TENORM[g/]) | WTP SLUDGE-1 | 9/28/2021 | 21-09090 | EBS | NR |
| WTP - Sludge Analysis (TENORM) | WTP SLUDGE-2 | 9/28/2021 | 21-09090 | EBS | NR |
| WTP - Sludge Analysis (TENORM) | WTP SLUDGE-3 | 9/28/2021 | 21-09090 | EBS | NR |

a/ Validated:
X = Level III validation
NR = Not required
b/ GW = groundwater
c/ RAWP = Response Action Work Plan
d/ WTP = Water Treatment Plant
e/ EBS - Eberline Services
f/ VES = Vapor Extraction System
g/ TENORM = Technologically Enhanced Naturally Occurring Radioactive Material

# APPENDIX F-2

# ANALYTICAL DATA PACKAGES

# AND

# DATA VALIDATION REPORTS

The data packages and DVRs are included in the Appendix F-2 folder in this submittal

# APPENDIX F-3

# DATA QUALITY ASSESSMENT

# APPENDIX F-3

## DATA QUALITY ASSESSMENT

## JULY THROUGH DECEMBER 2021
## OPERATIONS AND MAINTENANCE STATUS REPORT
## LOWRY LANDFILL SUPERFUND SITE

Based on the project or task requirements, a data evaluation process was performed on project analytical data. The data evaluation process provides an evaluation of the data quality in relation to specific project data quality criteria and with reference to the sampling and analysis requirements of the Quality Assurance Project Plan (QAPP).

The overall quality assurance objective for all measurement data is to maximize the probability that the data generated are of documented quality and are defensible for the intended data uses. To meet these objectives, data shall be: (1) representative of actual site physical and chemical conditions; (2) comparable to previous and subsequent data and other studies; (3) complete to the extent that necessary conclusions may be reached; and (4) of known quantitative statistical significance in terms of precision and accuracy, at levels appropriate for each stated data use for the project.

The data review process is performed in two phases. The initial phase, data verification, involves inspecting the laboratory data deliverables to determine if project requirements were met. The second phase, data validation, includes a review of data to assess data usability and application of data qualifiers to the analytical results based on adherence to method protocols and laboratory-specific quality assurance/quality control (QA/QC) limits.

### F-3.1 DATA VERIFICATION

Data verification is the process of evaluating the completeness, correctness, and conformance/compliance of a specific data set against the method, procedural, or contractual requirements. Data verification is the review of sample data deliverables for completeness and compliance with project requirements. A checklist was completed for each data package to ensure that all documentation was provided. If deficiencies were revealed, resubmissions of the missing or incorrect data were requested and the data deliverable was updated. In addition, transcription checks of 100% of the compliance, effectiveness, vertical migration, Response Action, and North End groundwater results, Water Treatment Plant (WTP) Early Warning, molybdenum testing, and WTP effluent (MP-001) samples were performed to ensure the data reported in the database and the hardcopy data packages were the same. The following problems were noted during sample verification:

The following SDGs were missing raw metals data and required resubmission by the laboratory:

- 280-154710-1
- 280-154752-1
- 280-155030-1
- 280-155264-1

The following additional problems were identified:

The following wells were resampled when the coolers shipped overnight to PACE laboratory in Wisconsin were delayed. The delay caused the temperature of the samples to increase to an unacceptable level (>6°C) making them unusable for analysis. For part of the reporting period, corrective action involved shipping the VOC vials in our largest coolers filled to the maximum with extra ice and frozen plastic bottles. In that way the temperature in the coolers is maintained for a greater amount of time depending on the weather. Corrective action shifted to a more economical solution of collecting duplicate VOC vials from each well and storing them on-Site. The 14-day holding time allows enough time to resend the vials if a cooler is lost or delayed. This option saves on the cost of shipping the larger, heavier coolers.

- MW121-WDR
- MW122-WDR
- MW123-WD
- MW124-WD
- MW05-WD
- MW125-WD
- B-326-UD
- B-326-WD
- B-313 – not enough water in the well to resample
- B-321
- MW117-WD
- MW114-WD
- MW103-WD
- Second resampling event - B-326-UD, B-326-WD, MW125-WD

Additional problems encountered are described below.

280-151819 B-313 Nitrate – the laboratory analyzed the sample within the holding time but the result exceeded the calibration curve (55000 E µg/L). The reanalysis was performed out of holding time (55000 H µg/L). The first analysis result was reported with a J qualifier to indicate an estimated concentration.

280-154071 B-326-WD Nitrite – the laboratory analyzed the sample within the holding time (0.15 J- µg/L) but the associated Continuing Calibration Verification (CCV) sample was below the lower control limit. The reanalysis was performed out of holding time (not detected). The first analysis result is reported with a J- qualifier for an estimated concentration with a low bias. This SDG was also revised to include the Wet Chemistry raw data that was omitted from the original report.

280-151434 MP-001 – The laboratory miscalculated the LCS recovery for WTP compliance 8260B compounds. A check of the calculation revealed the wrong spike concentration was used to calculate the recovery of each compound. The data package was revised and resubmitted.

Two wells were resampled to confirm anomalous data. B-326-WD (A213505) was reported as a trace detect (0.77 J µg/L, 8/30/21). Because the previous sample result from June 2021 was 7.5 µg/L a confirmation sample was collected on 9/27/21. The result for the confirmation sample B-326-WD was 0.69 J µg/L confirming the original result.

MW77-EW-2 (SDG A213508) (9/1/21) was reported as 20 µg/L which was inconsistent with historical data (2 µg/L or less). The laboratory reran the sample out of holding time and reported 0.12 J µg/L. This result was rejected for the holding time violation. The well was resampled on 9/14/21 resulting in a reported value of 0.13 J µg/L (SDG A213709). The laboratory believes the sample was accidentally spiked with the matrix spiking solution.

No other problems were encountered from data verification of the analytical data.

## F-3.2 DATA VALIDATION

Data validation was performed on the following selected locations during the reporting period.

- 10% of the 31 compliance and effectiveness groundwater (GW) samples. Samples for validation were chosen at random:
- A representative set of the investigation wells (Molybdenum testing and North End Monitoring) were also validated.
- All MP-00l (WTP effluent) samples.

A Level III validation (summary quality control review) was performed consisting of manually examining data deliverables to determine data quality. Data validation included application of data qualifiers to the analytical results based on adherence to method protocols and project-specific QA/QC limits. Method protocols reviewed included:

- Analytical holding times,
- Method blanks (MB),
- Trip blanks (TB),
- Equipment blanks (EBs),
- Ambient blanks (AB),
- Matrix spikes/matrix spike duplicates (MS/MSDs),
- Laboratory control samples (LCSs),
- Shipping cooler temperatures,
- Laboratory duplicates,
- Internal Standards (ISs),
- Surrogates,
- Chemical recovery (radionuclides), or
- An out-of-control QC parameter that is mentioned in the case narrative.

Data qualifiers were applied to analytical results during the data validation process. All data were validated using method applicable guidelines and in accordance with the requirements of the National Functional Guidelines for Organic and Inorganic Data Review (EPA, 1994a & b, as amended) and by SW-846 guidelines specific to the method or as directed by EPA. All

radionuc1ide results that were less than the critical value (Lc) were qualified as not detected (U). Radionuc1ides were validated according to the guidelines and criteria specified in the Multi-Agency Radiological Laboratory Analytical Protocols (MARLAP) Manual (EPA, 2004, as amended).

The following definitions provide explanations of the USEPA qualifiers that may be assigned to analytical results during data validation.

U = The analyte was analyzed for and is not present above the level of the associated value. The associated numerical value indicates the approximate concentration necessary to detect the analyte in the sample.

UJ = The analyte analyzed for was not present above the level of the associated value. The associated numerical value may not accurately represent the concentration necessary to detect the analyte in the sample.

UJ- = Same as UJ qualification but with an indication of negative bias in the associated numerical value.

UJ+ = Same as UJ qualification but with an indication of positive bias in the associated numerical value.

NJ = The analysis indicates that the analyte is "tentatively identified" and the associated numerical value may not be consistent with the amount actually present in the sample.

J = The analyte was analyzed for, and was positively identified, but the associated numerical value may not be consistent with the amount actually present in the environmental sample.

J- = Same as J qualification but with an indication of negative bias in the sample concentration.

J+ = Same as J qualification but with an indication of positive bias in the sample concentration.

Data quality is summarized below only where problems were noted during the validation. Frequency requirements for field sample collection of QC samples (MS/MSDs, field duplicates, and blanks) were reviewed and meet project requirements. The frequency requirements for laboratory specific method QC were met overall.

### F -3.2.1 Groundwater

Eleven samples associated with the 33 compliance and effectiveness wells plus 16 samples associated with investigation and North End groundwater monitoring were validated. Locations of wells sampled during the reporting period are shown on Figures 4.9 and 4.10. Data validation reports (DVRs), included in Appendix F-2, are cross-referenced by location and SDG number in Table F-l. Raw data packages and DVRs are presented in Appendix F-2.

The following methods were validated as required:

- SW8260B (VOCs),
- SW8260_SIM (low-level 1,4-Dioxane),
- SW6010B (Metals),
- E300.0A (Nitrate and Nitrite).

The following groundwater samples were validated as indicated for each method:

| Location | Sample Date | 300.0A | 6010B | 8260_SIM | 8260B |
|---|---|---|---|---|---|
| B-314 | 10/27/2021 | X | X | X | X |
| B-326-UD | 10/12/2021 | | | X | |
| B-326-WD | 10/12/2021 | X | X | X | X |
| BKGD-3WD | 8/16/2021 | X | X | X | X |
| MW113-EW-1 | 7/29/2021 | | | X | |
| MW113-UD | 7/29/2021 | | | X | |
| MW129-WD | 9/7/2021 | | | X | |
| MW170-EW-1 | 10/27/2021 | | | X | |
| MW179-UDEN | 9/8/2021 | | | X | |
| MW62-WDR | 10/27/2021 | X | X | X | X |
| MW77-WD | 10/27/2021 | X | X | X | X |

The results listed in the table below were qualified for exceeding the linear range (LR) of the calibration curve or exceeding the holding time. No other qualifiers were necessary for groundwater samples after validation.

**Data Qualifications – Groundwater**

| Location | Parameter Name | Sample Date | Result | Units | Final Q | HT | LR | CCV %D |
|---|---|---|---|---|---|---|---|---|
| B-313 | Nitrogen, Nitrate | 8/12/2021 | 55000 | µg/L | J | | J | |
| B-326-WD | Nitrogen, Nitrite | 10/12/2021 | 150 | µg/L | J- | | | J- |
| MW77-EW-2 | 1,4-Dioxane | 9/1/2021 | 0.12 | µg/L | R | R | | |

HT = Holding Time LR = Linear Range CCV %D = Continuing Calibration Verification % Difference

## Holding Time

Holding times for sample extraction and/or analysis as required by the methods is calculated from the date and time of sample collection to the time of sample preparation and/or analysis. 1,4-Dioxane in one sample was qualified as rejected for exceeding holding time (14 days).

## Linear Range

One samples nitrate concentration exceeded the linear range of the calibration curve. The dilution reanalysis was performed after the holding time expired so could not be used. The results exceeding the linear range were reported and qualified as J, estimated.

**Continuing Calibration Verification Standard**

The CCV standard verifies that instrument response and accuracy are consistent with the initial calibration curve and includes all target compounds. One nitrite sample was qualified as J- (estimated with a low bias) because the associated CCV was below the control limit.

### F-3.2.2 WTP Effluent (MP-00l)

The WTP effluent sample (MP-001) was validated for the following methods:

- E200.8 and E200.7 – Metals,
- E624 – VOCs,
- E625 –SVOCs,
- SW8260SIM – 1,4-Dioxane,
- E900.0 - Gross alpha/beta,
- EPA 60017-79-08 - Plutonium-238, -239, -240,
- ER110 LANL - Americium-241,
- SM 7500-RA-B – Radium-226 and Total Radium, and
- EPA-RA-05 – Radium-228.

Data validation reports included in Appendix F are cross-referenced by location and SDG number in Appendix F-l. DVRs and raw data packages are presented in Appendix F-2.

The results listed in the table below were qualified because out-of-control chemical recovery, uncertainty, LCS recovery, MS recovery, trip blanks, and method blanks.

**Data Qualifications – WTP Effluent**

| Sample ID | Sample Date | Parameter Name | Result | CE | Units | Q | Unc | MS Rec | Chem Rec | MB | TB | LCS Rec |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| MP-001_ 070621_1200 | 7/6/2021 | Methylene Chloride | 0.21 | | µg/L | U | | | | | U | |
| MP-001 | 7/7/2021 | Alpha, Gross | 8.22 | 5.8 | pCi/l | UJ+ | | S+ | | B+ | | |
| MP-001 | 7/7/2021 | Americium -241 | 0.041 | 0.042 | pCi/l | J | Q | | | | | |
| MP-001 | 7/7/2021 | Benzidine | 95 | | µg/L | R | | R | | | | |
| MP-001 | 7/7/2021 | bis(2-Ethylhexyl) phthalate | 2 | | µg/L | U | | | | U | | |
| MP-001_ 070721_0000 | 7/7/2021 | Methylene Chloride | 0.22 | | µg/L | U | | | | | U | |
| MP-001_ 070721_0400 | 7/7/2021 | Methylene Chloride | 0.18 | | µg/L | U | | | | | U | |
| MP-001 | 7/7/2021 | Plutonium-238 | 0.025 | 0.038 | pCi/l | UJ | | | J | | | |
| MP-001 | 7/7/2021 | Plutonium-239/240 | 0.011 | 0.033 | pCi/l | UJ | | | J | | | |
| MP-001 | 7/7/2021 | Radium-228 | 0.86 | 0.53 | pCi/l | J | Q | | | | | |

| Sample ID | Sample Date | Parameter Name | Result | CE | Units | Q | Unc | MS Rec | Chem Rec | MB | TB | LCS Rec |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| MP-001 | 10/5/2021 | Alpha, Gross | 14.24 | 5.17 | pCi/l | UJ+ | | S+ | | | | |
| MP-001 | 10/5/2021 | Americium -241 | 0.15 | 0.14 | pCi/l | J | Q | | J | | | |
| MP-001 | 10/5/2021 | Benzidine | 95 | | µg/L | R | | R | | | | |
| MP-001 | 10/5/2021 | bis(2-Ethylhexyl) phthalate | 3.2 | | µg/L | R | | | | R | | |
| MP-001 | 10/5/2021 | Plutonium-238 | -0.016 | 0.028 | pCi/l | UJ | | | J | | | |
| MP-001 | 10/5/2021 | Plutonium-239/240 | -0.008 | 0.025 | pCi/l | UJ+ | | | J | | | S+ |
| MP-001 | 10/5/2021 | Radium-226 | 0.17 | 0.24503 | pCi/l | J | Q | | J | | | |
| MP-001 | 10/5/2021 | Radium-228 | 0.49 | 0.39 | pCi/l | J | Q | | J | | | |

CE = Counting Error MS Rec = Matrix Spike Recovery Chem Rec = Chemical Recovery (RADs) Unc = Uncertainty
LCS Rec = Laboratory Control Sample Recovery MB = Method Blank

### Uncertainty

Samples for americium-241 and radium-228 were qualified because of a high counting error in relation to the sample result (uncertainty). This indicates that the uncertainty of a measured value is too large compared to the result value. This usually occurs when the result value is just above the critical value. The final result is qualified as estimated (J).

### Matrix Spike Recovery

Benzidine in two samples was rejected due to low matrix spike recoveries. Benzidine was extracted and analyzed in duplicate for each sample collected because of this problem. Benzidine experiences oxidative losses during extraction inhibiting recovery of matrix spikes. Because benzidine has never been detected at Lowry, Metro has allowed a variance for the method. The lab must analyze it twice and if the spikes fail twice, we do not have to resample. LCS recoveries will still need to be in control plus all other QC.

Gross alpha in two samples were out of control for matrix spike recoveries. Gross alpha may be biased high in the associated samples as indicated by matrix spike recoveries that were above the upper control limits. Qualifications resulting from matrix spike recoveries are most likely matrix-related because the associated LCSs were in control.

### Chemical Recovery

Americium-241, radium-226, and radium-228 in one sample and plutonium-238 and plutonium-239/240, n two samples were qualified as estimated for chemical recovery. Chemical recovery measures the yield of a radioactive isotope of the analyte added to the sample to measure any losses of the analyte during the chemical separations or other processes employed in the analysis. Sample concentrations are corrected for chemical recovery but the lower the yield the greater the variance in the result. Therefore, the sample results were qualified as estimated (J).

### Method Blanks

The method blank measures possible contamination by the laboratory. Two bis(2-ethyhexyl) phthalate sample were qualified for method blank contamination (U or R). One gross alpha sample was qualified as B+ (estimated with a high bias, final Q = J+). This indicates contamination originating from lab processes.

### Trip Blanks

The trip blank is used to indicate potential contamination by VOCs during sample shipping and handling. Methylene chloride in three sample was qualified as U for trip blank contamination. Methylene chloride is also a common lab contaminant.

### Laboratory Control Samples

LCSs are designed to check the accuracy of the analytical procedure by measuring a known concentration of the analyte of interest. Plutonium-239/240 in one sample was out of control for LCS spike recoveries (S+). Plutonium-239/240 may be biased high as indicated by LCS spike recovery that was above the upper control limits.

## F-3.3 DATA ASSESSMENT

Data quality assessment (DQA) criteria were used to evaluate the quality of the field sampling efforts, field screening results, and laboratory results for compliance with project data quality objectives (DQOs). The DQA criteria are expressed in terms of analytical precision, accuracy, representativeness, completeness, and comparability (PARCC). Procedures used to assess data accuracy and precision are in accordance with the respective analytical methods and QAPP requirements.

### F-3.3.1 Precision

Precision is the measure of variability between individual sample measurements under prescribed conditions. The relative percent difference (RPD) for field duplicate, MS/MSD, and laboratory duplicate analyses demonstrates the precision of the analytical methods and, in the case of field duplicates, sampling methods. An RPD within the method-specific control limit indicates satisfactory precision in a measurement system. Methods (matrix specific) were considered out of control when greater than 50 percent of all precision data exceeded criteria. Out-of-control methods are evaluated for trends in bias. If a specific bias is evident, it is discussed below.

Precision results (i.e., MS/MSD, laboratory replicates, and field duplicates) for all methods and matrices were in control overall. The tables below present field duplicate precision for groundwater, WTP effluent, and landfill gas where at least one of the duplicate results was detected. Field duplicates have an RPD control limit for sample concentrations exceeding the RL by 5 times of 35% and a range limit equal to the two times the RL is applied to sample values less than 5 times the RL. The field duplicate results were in control.

**Field Duplicate Results**

| Sample ID | Analyte | Sample Date | RL | Sample Conc (µg/L) | Dupe Conc (µg/L) | Range | RPD |
|---|---|---|---|---|---|---|---|
| MW113-EW-1 | 1,4-Dioxane | 7/29/2021 | 0.9 | 92 | 97 | 5 | 5% |
| MW156-WD | 1,4-Dioxane | 11/11/2021 | 0.9 | 0.25 | 0.25 | 0 | 0% |
| MW113-EW-1 | Molybdenum, Dissolved | 7/29/2021 | 20 | 6600 | 6400 | 200 | 3% |
| MW113-EW-1 | Nitrate as N | 7/29/2021 | 500 | 1120 | 1100 | 20 | 2% |
| MW113-EW-1 | Molybdenum, Total | 7/29/2021 | 20 | 6600 | 6400 | 200 | 3% |
| B-314 | Nitrate as N | 10/27/2021 | 500 | 160 | 150 | 10 | 6% |
| B-314 | 1,1-Dichloroethane | 10/27/2021 | 1 | 1.5 | 1.5 | 0 | 0% |
| MP-001_070721_0800 | 1,1,1-Trichloroethane | 7/7/2021 | 1 | 6.8 | 6.7 | 0.1 | 1% |
| MP-001_100521_0800 | 1,1,1-Trichloroethane | 10/5/2021 | 1 | 7.6 | 7.4 | 0.2 | 3% |
| MP-001_070721_0800 | 1,1-Dichloroethane | 7/7/2021 | 1 | 21 | 21 | 0 | 0% |
| MP-001_100521_0800 | 1,1-Dichloroethane | 10/5/2021 | 1 | 19 | 19 | 0 | 0% |
| MP-001_070721_0800 | 1,1-Dichloroethene | 7/7/2021 | 1 | 1.2 | 1.2 | 0 | 0% |
| MP-001_100521_0800 | 1,1-Dichloroethene | 10/5/2021 | 1 | 0.99 | 0.91 | 0.08 | 8% |
| MP-001_070721_0800 | 1,2-Dichloroethane | 7/7/2021 | 1 | 0.74 | 0.61 | 0.13 | 19% |
| MP-001_100521_0800 | 1,2-Dichloroethane | 10/5/2021 | 1 | 0.62 | 0.63 | 0.01 | 2% |
| MP-001_070721_0800 | 1,2-Dichloroethene, Total | 7/7/2021 | 1 | 4.9 | 5.1 | 0.2 | 4% |
| MP-001_100521_0800 | 1,2-Dichloroethene, Total | 10/5/2021 | 1 | 5 | 4.4 | 0.6 | 13% |
| MP-001_100521_0800 | 1,2-Dichloropropane | 10/5/2021 | 1 | 0.23 | 0 | 0.23 | |
| MP-001_070721_0800 | 1,4-Dioxane | 7/7/2021 | 1.4 | 19 | 17 | 2 | 11% |
| MP-001_100521_0800 | 1,4-Dioxane | 10/5/2021 | 20 | 19 | 15 | 4 | 24% |
| MP-001_100521_0800 | 1,4-Dioxane | 10/5/2021 | 1.4 | 17 | 17 | 0 | 0% |
| MP-001 | Bis(2-ethylhexyl) phthalate | 10/5/2021 | 9.5 | 3.2 | 3.2 | 0 | 0% |
| MP-001_070721_0800 | Chloroform | 7/7/2021 | 1 | 0.43 | 0.44 | 0.01 | 2% |
| MP-001_100521_0800 | Chloroform | 10/5/2021 | 1 | 0.43 | 0.37 | 0.06 | 15% |
| MP-001_070721_0800 | cis-1,2-Dichloroethene | 7/7/2021 | 1 | 4.9 | 5.1 | 0.2 | 4% |
| MP-001_100521_0800 | cis-1,2-Dichloroethene | 10/5/2021 | 1 | 5 | 4.4 | 0.6 | 13% |
| MP-001_070721_0800 DUPE | Methylene Chloride | 7/7/2021 | 5 | 0.2 | 0 | 0.2 | |
| MP-001 | Molybdenum | 7/7/2021 | 5 | 12 | 12 | 0 | 0% |
| MP-001 | Molybdenum | 10/5/2021 | 5 | 19 | 17 | 2 | 11% |
| MP-001 | Naphthalene | 7/7/2021 | 9.6 | 1.1 | 0.29 | 0.81 | |
| MP-001 | Selenium | 7/7/2021 | 2.5 | 15 | 14 | 1 | 7% |
| MP-001 | Selenium | 10/5/2021 | 2.5 | 16 | 16 | 0 | 0% |
| MP-001 | Zinc | 7/7/2021 | 10 | 2.6 | 3.2 | 0.6 | 21% |
| MP-001 | Zinc | 10/5/2021 | 10 | 2.4 | 3.5 | 1.1 | 37% |

No qualifiers are applied based on field duplicate results unless resampling is indicated. Field duplicates are used as a measure of field sampling reproducibility and may be used to judge the representativeness of the samples collected.

### F-3.3.2 Accuracy

#### F-3.3.2.1 Accuracy of Laboratory QC Samples

Accuracy is the degree of agreement of a measurement with an accepted reference or true value. The results of surrogate, MS/MSD, and LCS analyses, when expressed in terms of percent recovery, demonstrate the accuracy of the method. Surrogate and MS/MSD spike recoveries indicate accuracy relevant to a unique sample matrix. LCS spike recoveries indicate accuracy relevant to an analytical batch lot and are strictly a measure of laboratory analytical accuracy conditions independent of samples and matrices. As with precision determinations, methods (matrix specific) were considered systematically out of control when greater than 50 percent of all accuracy data exceeded criteria. Out-of-control methods are evaluated for trends in bias. If a specific bias is evident, it is discussed below. If insufficient data are available (i.e., fewer than 20 occurrences) to represent a viable sample population, then statistical certainty in an out-of-control condition cannot be assumed. Control charts were developed to demonstrate if a change in the lab analysis process is occurring over time. The most current analyses were compared against the control limits and mean of the previous twenty analyses. By comparing current data to the control limits and mean of the previous set, you can determine whether the process variation is consistent (in control) or is unpredictable (out of control, affected by special causes of variation).

Control charts were developed for groundwater for the LCS/LCSD and MS/MSD spike recoveries for cadmium (representing SW6010B, Figures F-3.1, F-3.2, F-3.3, and F-3.4), trichloroethene (TCE) (representing SW8260B, Figures F-3.5, F-3.6, F-3.7, and F-3.8), and 1,4-dioxane by method SW8260 SIM (Figures F-3.9, F-3.10, and F-3.11). LCSs and MSs never exceeded the upper or lower control limit during the reporting period except for one 1,4-dioxane LCS which was 89% just under the control limit of 90%.

Control charts or plots were developed for WTP effluent for the LCS/LCSD and MS/MSD spike recoveries for TCE (representing SW8260B, Figures F-3.12, F-3.13, F-3.14 and F-3.15), selenium (representing SW6010B, Figures, F-3.16, F-3.17, 3.18, and F-3.19), and pyridine by method SW8270 (Figures F-3.20, F-3.21, F-3.22 and F-3.23). LCS, LCSD, MS and MSD results were in control for the reporting period.

Accuracy results (i.e., MS/MSD, LCS, surrogate spikes, and post digestion spikes) for all methods and matrices are predominantly in control except where noted. MP-001 was resampled for out-of-control matrix spike recoveries for benzidine. Benzidine experiences oxidative losses during the extraction inhibiting recovery of matrix spikes. The accuracy results which were out-of-control are not significant for any one compound, method, or matrix (except benzidine) and do not represent a negative impact to data quality. Therefore, overall accuracy was acceptable.

One PE sample concentration was prepared in duplicate for all groundwater compounds of concern. The laboratory received an unspiked BKGD-3WD sample also. This was a double-blind study in which the laboratory did not know the samples were performance evaluation samples of known concentration. The following table lists the results for each compound. The concentrations were chosen to fall within the linear range of the analysis at the low end of the concentration range or near the performance standard. Bromodichloromethane, bromoform and

dibromochloromethane were below the acceptable range and cadmium was slightly above the acceptable range.

**Performance Evaluation Sample Results**

| Compound | BKGD -3WD Result | BKGD-3WD Matrix Spike 1 | % Rec | BKGD-3WD Matrix Spike 2 | % Rec | RPD | ERA Cert Value | ERA Acceptable Range (estimated 95% confidence interval) | GWPS |
|---|---|---|---|---|---|---|---|---|---|
| 1,1,1-Trichloroethane | 0 | 4.4 | 87% | 5.2 | 103% | 17% | 5.03 | 3.62-6.13 | 200 |
| 1,1,2,2-Tetrachloroethane | 0 | 4.3 | 85% | 4.8 | 95% | 11% | 5.04 | 3.94-6.39 | 1 |
| 1,1,2-Trichloroethane | 0 | 4.5 | 90% | 4.8 | 96% | 6% | 5.01 | 4.09-6.07 | 5 |
| 1,1-Dichloroethane | 0 | 4.6 | 93% | 5 | 101% | 8% | 4.95 | 3.9-6.08 | 990 |
| 1,1-Dichloroethene | 0 | 6.8 | 97% | 8.1 | 116% | 17% | 7 | 4.89-9.41 | 7 |
| 1,2-Dichloroethane | 0 | 4.8 | 97% | 5 | 101% | 4% | 4.97 | 3.97-6.14 | 5 |
| 1,2-Dichloropropane | 0 | 4.6 | 92% | 4.9 | 98% | 6% | 4.99 | 3.98-6.02 | 5 |
| 1,4-Dioxane (low-level) | 0 | 3.8 | 95% | 3.7 | 93% | 3% | 4 | 2.80-5.20 | 0.9 |
| Acetone | 0 | 46 | 92% | 48 | 96% | 4% | 49.9 | 22.6-68.5 | 1600 |
| Arsenic | 0 | 56 | 102% | 56 | 102% | 0% | 55 | 48.1-60.5 | 52.18 |
| Benzene | 0 | 4.9 | 97% | 5.4 | 107% | 10% | 5.04 | 3.95-6.01 | 5 |
| Bromodichloromethane | 0 | 3.9 | 78% | 4.2 | 84% | 7% | 5 | 4.06-6.25 | 1 |
| Bromoform | 0 | 2.9 | 73% | 3 | 75% | 3% | 4 | 2.99-5.09 | 4 |
| Cadmium | 0 | 6.4 | 107% | 6.5 | 108% | 2% | 6 | 5.33-6.40 | 5.48 |
| Carbon Tetrachloride | 0 | 3.8 | 76% | 4.4 | 89% | 15% | 4.97 | 3.25-6.22 | 5 |
| Chlorobenzene | 0 | 4.7 | 94% | 5 | 100% | 6% | 5.02 | 3.99-5.95 | 100 |
| Chloroform | 0 | 3.1 | 90% | 3.4 | 98% | 9% | 3.46 | 2.74-4.23 | 3.5 |
| cis-1,2-Dichloroethene | 0 | 4.8 | 96% | 5.1 | 102% | 6% | 5 | 3.92-6.13 | 70 |
| Dibromochloromethane | 0 | 10 | 71% | 11 | 78% | 10% | 14.1 | 11.1-17.4 | 14 |
| Ethylbenzene | 0 | 4.6 | 92% | 5.1 | 102% | 10% | 5 | 3.69-6.08 | 700 |
| Methylene chloride | 0 | 4.5 | 91% | 4.7 | 95% | 4% | 4.97 | 3.65-6.24 | 5 |
| Naphthalene | 0 | 3.5 | 71% | 3.9 | 79% | 11% | 4.96 | 3.11-6.27 | 140 |
| Nitrogen, Nitrate | 660 | 2500 | 92% | 2500 | 92% | 0% | 2000 | 1760-2220 | 28000 |
| Nitrogen, Nitrite | 0 | 2000 | 100% | 2000 | 100% | 0% | 2000 | 1780-2210 | 1000 |
| Tetrachloroethene | 0 | 4.7 | 93% | 5.3 | 105% | 12% | 5.03 | 3.18-6.02 | 5 |
| Toluene | 0 | 4.8 | 96% | 5.3 | 106% | 10% | 5 | 3.87-5.94 | 1000 |
| trans-1,2-Dichloroethene | 0 | 1.9 | 96% | 2.2 | 112% | 15% | 1.97 | 1.5-2.48 | 100 |
| Trichloroethene | 0 | 4.6 | 93% | 5.3 | 107% | 14% | 4.96 | 3.69-5.94 | 5 |
| Vinyl chloride | 0 | 5.8 | 116% | 6.7 | 134% | 14% | 5 | 3.03-7.47 | 2 |

%Rec = percent recovery

RPD = Relative percent difference

ERA Cert value = Environmental Resource Associates Certified Value

GWPS – Groundwater performance standard

### F-3.4.3 Representativeness

Compliance sample data are believed to be representative of the site conditions prevailing at the time of sample collection because samples were properly collected, stored, and preserved. Although blank contamination did occur, sample data quality was not adversely affected. Holding times were met for all compliance samples other than specified above. Samples that exceeded holding times were resampled.

### F-3.4.4 Comparability

All samples were reported in industry-standard units. Water reporting units were micrograms per liter (µg/L) or picoCuries per liter (pCi/L) (adjusted in the database if mg/L). Landfill gas units were in ug/$m^3$. Analytical protocols for the methods were adhered to and analytical results are considered comparable.

### F-3.4.5 Completeness

Completeness is defined as the percentage of laboratory measurements judged to be valid on a method-by-method basis. Valid data are defined as all data and/or qualified data which meet the DQOs for this project. Data completeness is expressed as percent complete (PC), which is (1-(the number of rejected samples per compound ÷ total number of samples per compound) X 100. Completeness for the reporting period was 100%, understanding that all results qualified with U, UJ* or J* are usable to meet project objectives. Benzidine results were 0% complete but are not included in the calculation. The method required by the Metro permit is inadequate to analyze for this compound and does not provide a usable result. The goal for meeting analytical holding times was l00% and was met for all reported compliance samples except benzidine. The nitrate samples that were out of holding time were replaced with usable but estimated values or resampled.

### F-3.4.6 Conclusion

The groundwater, landfill gas, and WTP data for the reporting period are of acceptable quality and are considered usable to support project objectives. Samples are representative of the Site and comparable with previous and future investigations (when used in accordance with the validation qualifiers).





**Figure F-3.1**
**Cadmium Control Chart**
**LCS Spike Recovery in Groundwater**
**O&M Status Report**
**July through December 2021**
**Lowry Landfill Superfund Site**





**Figure F-3.2**
**Cadmium Control Chart**
**LCSD Spike Recovery in Groundwater**
**O&*M* Status Report**
**July through December 2021**
**Lowry Landfill Superfund Site**





**Figure F-3.3**
**Cadmium Control Chart**
**Matrix Spike Recovery in Groundwater**
**O&M Status Report**
**July through December 2021**
**Lowry Landfill Superfund Site**





**Figure F-3.4**
**Cadmium Control Chart**
**Matrix Spike Duplicate Recovery in Groundwater**
**O&M Status Report**
**July through December 2021**
**Lowry Landfill Superfund Site**





**Figure F-3.5**
**Trichloroethene Control Chart**
**LCS Spike Recovery in Groundwater**
**O&M Status Report**
**July through December 2021**
**Lowry Landfill Superfund Site**





**Figure F-3.6**
**Trichloroethene Control Chart**
**LCSD Spike Recovery in Groundwater**
**O&M Status Report**
**July through December 2021**
**Lowry Landfill Superfund Site**





**Figure F-3.7**
**Trichloroethene Control Chart**
**Matrix Spike Recovery in Groundwater**
**O&M Status Report**
**July through December 2021**
**Lowry Landfill Superfund Site**





**Figure F-3.8**
**Trichloroethene Control Chart**
**Matrix Spike Duplicate Recovery in Groundwater**
**O&M Status Report**
**July through December 2021**
**Lowry Landfill Superfund Site**





**Figure F-3.9**
**1,4-Dioxane Control Chart**
**LCS Spike Recovery in Groundwater**
**O&M Status Report**
**July through December 2021**
**Lowry Landfill Superfund Site**





**Figure F-3.10**
**1,4-Dioxane Control Chart**
**MS Spike Recovery in Groundwater**
**O&M Status Report**
**July through December 2021**
**Lowry Landfill Superfund Site**





**Figure F-3.11**
**1,4-Dioxane Control Chart**
**MSD Spike Recovery in Groundwater**
**O&M Status Report -**
**July through December 2021**
**Lowry Landfill Superfund Site**





**Figure F-3.12**
**Trichloroethene Control Chart**
**LCS Spike Recovery in WTP Effluent**
**O&M Status Report**
**July through December 2021**
**Lowry Landfill Superfund Site**





**Figure F-3.13**
**Trichloroethene Control Chart**
**LCSD Spike Recovery in WTP Effluent**
**O&M Status Report**
**July through December 2021**
**Lowry Landfill Superfund Site**





**Figure F-3.14**
**Trichloroethene Control Chart**
**MS Spike Recovery in WTP Effluent**
**O&M Status Report**
**July through December 2021**
**Lowry Landfill Superfund Site**

WTP





**Figure F-3.15**
**Trichloroethene Control Chart**
**MSD Spike Recovery in WTP Effluent**
**O&M Status Report**
**July through December 2021**
**Lowry Landfill Superfund Site**





**Figure F-3.16**
**Selenium Control Chart**
**LCS Spike Recovery in WTP Effluent**
**O&M Status Report**
**July through December 2021**
**Lowry Landfill Superfund Site**





**Figure F-3.17**
**Selenium Control Chart**
**LCSD Spike Recovery in WTP Effluent**
**O&M Status Report**
**July through December 2021**
**Lowry Landfill Superfund Site**





**Figure F-3.18**
**Selenium Control Chart**
**MS Spike Recovery in WTP Effluent**
**O&M Status Report**
**July through December 2021**
**Lowry Landfill Superfund Site**





**Figure F-3.19**
**Selenium Control Chart**
**MSD Spike Recovery in WTP Effluent**
**O&M Status Report**
**July through December 2021**
**Lowry Landfill Superfund Site**





**Figure F-3.20**
**Pyridine Control Chart**
**LCS Spike Recovery in WTP Effluent**
**O&M Status Report**
**July through December 2021**
**Lowry Landfill Superfund Site**





**Figure F-3.21**
**Pyridine Control Chart**
**LCSD Spike Recovery in WTP Effluent**
**O&M Status Report**
**July through December 2021**
**Lowry Landfill Superfund Site**





**Figure F-3.22**
**Pyridine Control Chart**
**MS Spike Recovery in WTP Effluent**
**O&M Status Report**
**July through December 2021**
**Lowry Landfill Superfund Site**



S:\ES\MajProj\LWRYLNFL\QUARTERLY REPORTS\2ND HALF 2021
\APPENDIX F-3 DQA\Figures F-3.1 thru F-3.21 2H2021.xlsx





**Figure F-3.23**
**Pyridine Control Chart**
**MSD Spike Recovery in WTP Effluent**
**O&M Status Report**
**July through December 2021**
**Lowry Landfill Superfund Site**

# APPENDIX G

# ELECTRONIC DATABASE

The analytical data is presented in the access database  in this submittal.